## KARNATAKA LOKAYUKTA

No. COMPT/LOK/BCD-1668/2020/ARE-1 Multi-storeyed Building, Dr. B.R. Ambedkar Veedhi, Bengaluru, Dated: 24.01.2022.

## "REPORT U/S 12(3) OF THE KARNTAKA LOKAYUKTA ACT 1984"

Sub:-

Proceedings against: Respondent-1 Sri. Doddaiah, Engineer, T.V.C.C Cell, BBMP Head Office, N.R Square, Bengaluru Respondent-2 Sri. Sathish, Assistant Executive Engineer, T.V.C.C BBMP Office. Head N.R Square, Bengaluru Respondent-7 Basavaraj, Sri. Executive Engineer, In-charge Assistant Executive Engineer, Rajarajeshwari Nagara Sub-Division, BBMP, Bengaluru Respondent-8 Sri. Siddaramaiah, Assistant Engineer, Ward No. 129 and Rajarajeshwari Nagara Division, BBMP, Bengaluru Respondent-9 Sri. Umesh, Assistant Executive Engineer, I/c Assistant Engineer, Ward No. 73, Laggere Sub Division, BBMP, Bengaluru Respondent-12 Sri. Chandranath, Assistant Executive Engineer, KRIDL, Ananda Rao Circle, Bengaluru Respondent-13 Sri. Srinivas, Executive Engineer, KRIDL, Ananda Rao Circle, Bengaluru Respondent-14 Smt. Venkatalakshmi, Assistant Executive Engineer, T.V.C.C Cell, BBMP, Bengaluru Respondent-15 Sri. Shreetej, Assistant Executive Engineer, T.V.C.C

This complaint is filed by Sri. D.K Suresh who is the Member of Parliament representing Bengaluru Rural Parliamentary constituency (hereinafter referred to as complainant in short) against the 1st respondent Sri. Doddaiah who is working as Chief Engineer, TVCC d Mah darmon, Cell, Bruhath Bengaluru Mahanagara Palike (in short, "BBMP") Head

BBMP, Bengaluru-reg.

Office, Bengaluru, against the 2nd respondent Sri. Sathish who is working as Assistant Executive Engineer, TVCC Cell, BBMP Head Office, Bengaluru, against the 3rd respondent Sri. Vijayakumar who is working as Chief Engineer, Rajarajeshwari Nagara Zonal Office, BBMP, Bengaluru, against the 4th respondent Smt. Shilpa who is working as Assistant Engineer and Technical Assistant, Office of the Engineer, BBMP, Rajarajeshwari Nagara Bengaluru, against the 5th respondent Sri. Mohan who is working as Executive Engineer, Rajarajeshwari Nagara Project, BBMP, Bengaluru, against the 6th respondent Smt. Bharathi who is working as Assistant Executive Engineer and Technical Assistant attached to the office of the Executive Engineer, Rajarajeshwari Nagara Project, BBMP, Bengaluru, against the 7th respondent by name Sri. Basavaraj who is working as Executive Engineer and in-charge Assistant Executive Engineer, Rajarajeshwari Nagara Division and Rajarajeshwari Nagara Sub-Division, Bengaluru, against 8th respondent Sri. Siddaramaiah who is working as Assistant Engineer Ward numbers 129 and 160, Rajarajeshwari Ñagara Sub-Division, BBMP, Bengaluru, against the 9th respondent Sri. Umesh who is working as Assistant Executive Engineer and in-charge Assistant Engineer, Ward number '73, Laggere Sub-Division, BBMP, Bengaluru, against the 10th respondent Smt. Anitha who is working as Superintendent and Cashier, Rajarajeshwari Nagara Division, BBMP, Bengaluru and against the 11th respondent Sri. Guli Gowda who is working as Deputy Manager, Rajarajeshwari Nagara Division, BBMP, Bengaluru.

2. The allegations in the complaint is that, the public of Rajarajeshwari Nagara Assembly constituency which comes under the jurisdiction of Bengaluru Rural Loka Sabha constituency have given the complaints to the complainant who is the Member of Lokasabha of Bengaluru Rural Lokasabha constituency to the effect that funds have



been allotted from the State Government and the Central Government for various developmental works for the year 2019-20 and in November/ December-2019 the work orders have been obtained and without executing the work in January-2020 the bills have been submitted and through KRIDL the amount has been paid to the contractors. Even though the complainant wrote letters to the Joint Commissioner and to the Chief Engineer of BBMP not to pass the bills as there is substandard work or no work at all but even then the payments have been made. In the complaint respondents 1 to 11 are mentioned as the persons responsible for the above said lapses. In the complaint it is also alleged that there is lot of difference between the estimates and the works done and there is misappropriation of the Government funds to the tune of Rs. 250 Crores. Along with the complaint the complainant has enclosed the list signed by Sri. A. Rangaswamy and Sri. H.C Shivakumar in which the details of the civil works and the volume of misappropriation is mentioned as follows:

- 2.01. Estimated cost for improvement of roads at 9<sup>th</sup> main road, 10<sup>th</sup> main road and Nanjappa Garden surrounding cross roads in Ward Number 73, BBMP, Kottigepalya was at Rs. 1,95,99,826/-. The said work was entrusted to KRIDL which has carried out substandard work to the extent of 30% and submitted bill for Rs. 1,70,53,540/-.
- 2.02. Estimated cost for improvement of roads at 13th main road and surrounding cross roads in Vinayaka Layout, Wurd Number 73, Kottigepalya was at Rs. 1,95,99,402/-. The said work was entrusted to KRIDL which has carried out substandard work to the extent of 30% and submitted bill for Rs. 1,71,55,596/-.
- 2.03. Estimated cost for improvement of roads at roads at 2<sup>nd</sup> main road, 2A, 2B, 2C, 2D, 2E, 2F, 2G cross roads and surrounding areas in Ward Number 73, BBMP, Kottigepalya was at Rs.

- 1,95,99,420/-. The said work was entrusted to KRIDL which, without executing the above work drawn Rs. 1,71,99,035/- by placing fake bill.
- 2.04. Estimated cost for improvement of roads at roads at Nagarabhavi 5<sup>th</sup> Block and BDA complex surrounding cross roads in Ward Number 73, BBMP, Kottigepalya was at Rs. 1,95,99,049/-. The said work was entrusted to KRIDL which without executing the above work submitted the bill for Rs. 1,71,47,495/- towards the work earlier executed in BDA.
- 2.05. Estimated cost for improvement of roads at Marilinganapalya extention, Nagarabhavi, 5<sup>th</sup> Block and other surrounding cross roads in Ward Number 73, BBMP, Kottigepalya was at Rs. 1,95,99,619/-. The said work was entrusted to KRIDL which has carried out substandard work to the extent of 25% and submitted bill for Rs. 1,71,12,776/-.
- 2.06. Estimated cost for improvement and maintenance of drains in Gattigere extention, Basaveshwara Badavane and surrounding areas in Rajarajeshwari Nagara Ward Number 160 was at Rs. 1,95,99,300/-. The said work was entrusted to KRIDL which without executing the said work submitted bill for Rs. 1,74,00,536/-.
- 2.07. Estimated cost for improvement and maintenance of drains at 2<sup>nd</sup> main road and 60 feet road in Dwaraka Layout, BEML Layout and surrounding area in Rajarajeshwari Nagara Ward Number 160 at Rs. 1,95,99,884/-. The said work was entrusted to KRIDL which, without applying cement over the drain has provided in the estimate put up hollow bricks raising force over the drain and submitted bill for Rs. 1,74,00,536/-.
- 2.08. Estimated cost for improvement and maintenance of drains in Ideal Homes Township in Rajarajeshieri Nagara Ward Number 160

was at Rs. 1,95,96,002/-. The said work was entrusted to KRIDL which, without applying concrete over the drain put up hollow bricks raising course over the said drain and submitted bill for Rs. 1,71,66,466/-.

- 2.09. Estimated cost for improvement and maintenance of drains in Ideal Homes Township and Kenchenahalli surroundings in Rajarajeshwari Nagara Ward Number 160 was at Rs. 1,95,98,045/-. The said work was entrusted to KRIDL which without applying cement concrete over the drain as provided in the estimate put up hollow bricks raising course and submitted bill for Rs. 1,74,18,140/-.
- 2.10. Estimated cost for improvement and maintenance of drains at 7<sup>th</sup> main road and 9<sup>th</sup> main road in Daraka Layout, BEML Layout and surrounding areas in Rajarajeshwari Nagara Ward Number 160 was at Rs. 1,95,99,172/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up hollow bricks raising course to the extent of 25% and submitted bill for Rs. 1,74,62,137/-.
- 2.11. Estimated cost for improvement of roads in 10th main, 11th main and Mavina thoupu surrounding roads at BEML 5th Stage in Rajarajeshwari Nagara Ward Number 160 was at Rs. 1,95,99,948/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain put up hollow bricks raising course and without applying pointing on the covering slab executed the work to the extent of 25% and submitted bill for Rs. 1,61,97,683/-.
- 2.12. Estimated cost for improvement of roads at New Horizonal School road and surrounding areas at BEMI. 5th slage in Rajarajeshwari Nagara Ward Number 160 was at Rs. 1,95,99,370/-. The said work was entrusted to KRIDL which, without applying cement concrete over





the drain put up raising course and without pointing the stone covering slab executed the said work and submitted bill for Rs. 1,33,44,791/-.

- 2.13. Estimated cost for improvement of roads in Kempegowda Jowdi road and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,99,526/-. The said work was entrusted to KRIDL which, without executing the said work submitted for Rs. 1,64,94,580/-.
- 2.14. Estimated cost for improvement and maintenance of drains at 5<sup>th</sup> main road, 6<sup>th</sup> main road and surrounding areas of BEML 5<sup>th</sup> stage in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,98,079/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up hollow bricks raising course over the drain and without applying pointing on the stone covering slab executed work to the extent of 25% and submitted bill for Rs. 1,71,79,475/-.
- 2.15. Estimated cost for improvement and maintenance of drains in Krishnappa Layout and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,98,246/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up hollow bricks raising course over the drain and without applying pointing over the stone covering slab executed the said work to the extent of 25% and submitted bill for Rs. 1,73,89,050/-.
- 2.16. Estimated cost for improvements and maintenance of drains and footpath in Dr. R. Arunachalam road in BEML layout and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,98,325/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up hollow bricks raising source over the drain and without

ने जा के प्रकृति


A STATE OF THE STA

applying pointing over the stone covering slab executed the said work to the extent of 25% and submitted bill for Rs. 1,74,16,840/-.

- 2.17. Estimated cost for improvement and maintenance of drains in 1<sup>st</sup> cross and 2<sup>nd</sup> cross in Dwaraka Layout, BEML Layout and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,99,179/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up hollow bricks raising course over the drain executed the said work to the extent of 25% and submitted bill for Rs. 1,71,87,681/-.
- 2.18. Estimated cost for improvement and maintenance of drains in Gattigere Badavan and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,99,534/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided under the estimate put up hollow bricks raising course over the drain and carried out the work to an extent of 25% and submitted bill for Rs. 1,74,16,718/-.
- 2.19. Estimated cost for improvement and maintenance of drains in BEML extention, Sreenivasa Blocka and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,98,659/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided under the estimate put up hollow bricks raising course over the drain and carried out the work to an extent of 25% and submitted bill for Rs. 1,74,04,360/-.
- 2.20. Estimated cost for improvement and maintenance of roads in 9th cross road and surrounding areas at BEMI. 5th stage in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,99,110/-. The said work was entrusted to KRIDL which, carried out the work to an extent of 20% and prepared fake bill and submitted hill for Rs.

1,71,01,816/-

- 2.21. Estimated cost for improvement and maintenance of drains in 9th cross road and surrounding areas in BEML 5th stage in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,99,742/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain put up hollow bricks raising course over the drain and carried out the work to an extent of 25% and submitted bill for Rs. 1,45,96,411/-.
- 2.22. Estimated cost for improvement and maintenance of drains in 1st main road, 8th main road and surrounding areas at BEML 5th stage in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,99,181/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain put up hollow bricks raising course over the drain and carried out the work to an extent of 25% and submitted bill for Rs. 1,73,64,966/-.
- 2.23. Estimated cost for improvement and maintenance of drains in Pramod Layout, Raghavanswamy Temple and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,96,658/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided under the estimate put up hollow bricks raising course over the drain and carried out the work to an extent of 25% and submitted bill for Rs. 1,73,59,639/-.
- 2.24. Estimated cost for improvement and maintenance of drains near Raghavendra Swamy Temple and surrounding areas at BEML 5<sup>th</sup> stage in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,98,840/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided under the estimate put up hollow bricks raising course over the drain and carried out the work to an extent of 25% and submitted bill for Rs. 1,74,01,435/-.



- 2.25. Estimated cost for improvement and maintenance of 1<sup>st</sup> main road, RNS College by the side of Sai Lotus Layout and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,97,316/-. The said work was entrusted to KRIDL which, without executing the work as specified in the estimate executed the work to an extent of 20% and prepared fake bill and submitted bill for Rs. 1,73,80,026/-.
- 2.26. Estimated cost for improvement and maintenance of BEML 2<sup>nd</sup> and 3<sup>rd</sup> cross road and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,97,773/-. The said work was entrusted to KRIDL which, without executing the work as specified in the estimate executed the work to an extent of 20% and prepared fake bill and submitted bill for Rs. 1,73,45,473/-.
- 2.27. Estimated cost for improvement and maintenance of K.K Mahesh P.U College road, Tiruchi Mahaswamy 80 feet main road and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,95,610/-. The said work was entrusted to KRIDL which, without executing the work as specified in the estimate executed the work to an extent of 20% and prepared fake bill and submitted bill for Rs. 1,74,40,482/-.
- 2.28. Estimated cost for improvement and maintenance of 1<sup>st</sup> main road, 4<sup>th</sup> main road in Kalegowda Layout and Kampada Badavane and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,98,157/-. The said work was entrusted to KRIDL which, without executing the work as specified in the estimate executed the work to an extent of 20% and prepared fake bill and submitted bill for Rs. 1,74,05,822/-.
- 2.29. Estimated cost for improvement and maintenance of Shaneshwara Swamy Temples made, Subhash Chandra Nagara, BEML

Layout and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,95,738/-. The said work was entrusted to KRIDL which, without executing the work as specified in the estimate executed the work to an extent of 20% and prepared fake bill and submitted bill for Rs. 1,67,77,155/-.

- 2.30. Estimated cost for improvement and maintenance of drains in Giridhama Layout, Krishnappa Layout, Hanumanthappa Layout and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,95,342/-. The said work was entrusted to KRIDL which, without executing the work as specified in the estimate executed the work to an extent of 20% and prepared fake bill and submitted bill for Rs. 1,74,37,077/-.
- 2.31. Estimated cost for improvement and maintenance of drains in Panchasheela Nagara, Basaveshwara Badavane and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,99,623/-. The said work was entrusted to KRIDL which, without executing the work prepared fake hill and submitted bill for Rs. 1,74,32,269/-.
- 2.32. Estimated cost for improvement and maintenance of drains at 7<sup>th</sup> and 9<sup>th</sup> main road in Dwaraka Layout, BEML Layout and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,99,172/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,73,46,836/-.
- 2.33. Estimated cost for improvement and maintenance of roads in Dwaraka East Layout and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,99,057/-. The said work was entrusted to KRIDL which, without executing the quality work executed the work to an extent of 30% and submitted bill for Rs. 1,63,83,415/-.

- 2.34. Estimated cost for improvement and maintenance of roads of Dr. Arunachalam Road in Dwaraka Layouta, BEML 4<sup>th</sup> stage and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,99,641/-. The said work was entrusted to KRIDL which, without executing quality work executed the work to an extent of 30% and submitted bill for Rs. 1,47,17,273/-.
- 2.35. Estimated cost for improvement and maintenance of roads in Jawaharlal main road in Dwaraka Layout, BEML 4th stage and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,97,987/-. The said work was entrusted to KRIDL which, without executing quality work executed the work to an extent of 30% and submitted bill for Rs. 1,73,11,721/-.
- 2.36. Estimated cost for improvement and maintenance of roads Giridhama Layout, Panchasheela Nagara and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,99,562/-. The said work was entrusted to KRIDL which, without executing quality work executed the work to an extent of 30% and submitted bill for Rs. 1,72,57,315/-.
- 2.37. Estimated cost for improvement and maintenance of roads in Sudharshana Badavane, Chandrashekara Block, Gattigere extention, Gattigere Badavane and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,99,959/-. The said work was entrusted to KRIDL which, without executing quality work executed the work to an extent of 30% and submitted bill for Rs. 1,12,04,261/-.
- 2.38. Estimated cost for improvement and maintenance of roads in Basaveshwara Badavane, Gattigere Extention and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,99,157/-. The said work was entrusted to KRIDL which, without





executing quality work executed the work to an extent of 30% and submitted bill for Rs. 1,72,51,502/-.

- 2.39. Estimated cost for improvement and maintenance of roads in 4th main road, 5th main road, 6th main road at BEML Layout and surrounding areas in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,98,306/-. The said work was entrusted to KRIDL which, without executing quality work executed the work to an extent of 30% and submitted bill for Rs. 1,71,50,197/-.
- 2.40. Estimated cost for improvement and maintenance of drains in 10<sup>th</sup> main road, 11<sup>th</sup> main road and Mavinathopu surrounding areas at BEML 5<sup>th</sup> stage in Rajarajeshwari Nagara in Ward Number 160 was at Rs. 1,95,98,107/-. The said work was entrusted to KRIDL which, had not fully executed the said work and submitted bill for Rs. 1,73,76,505/-.
- 2.41. Estimated cost for improvement and maintenance of drains at Pramod layout, Reddy Layout and surrounding areas in Rujurajeshwari Nagara in Ward Number 160 was at Rs. 1,95,97,521/-. The said work was entrusted to KRIDL which, had not fully executed the said work and submitted bill for Rs. 1,73,58,110/-.
- 2.42. Estimated cost for removal and debris and overburden of earth in D. Devaraja Urs Truck Terminal Limited of Ward number 42 in Rajarajeshwari Nagara was at Rs. 1,95,96,185/-. The said work was entrusted to KRIDL which, without executing quality work executed the work to an extent of 30% and submitted bill for Rs. 1,74,96,593/-.
- 2.43. Estimated cost for drilling of borewells and providing water supply through pipeline in ward number 17, 38 and 42 within the limits of Rajarajeshwari Nagara Assembly Constituency was at, Rs. 1,43,24,517/-. The said work was entrysted to KRIDL which, without

صه الم

cercifole Was Entered to

executing quality work executed the work to an extent of 30% and submitted bill for Rs. 23,434/-.

- 2.44. Estimated cost for comprehensive development of roads and drains in Kempegowda Layout and surrounding areas in Ward Number 69, Laggere was at Rs. 1,95,95,928/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up raised hollow bricks raising course over the drain and carried out the work to an extent of 25% and submitted bill for Rs. 1,75,64,922/-.
- 2.45. Estimated cost for improvement and maintenance of drain and footpath from Laggere Bus Stand to Rajiv Gandhi Circle was at Rs. 1,95,96,441/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up raised hollow bricks raising course over the drain and carried out the work to an extent of 25% and submitted bill for Rs. 1,21,10,854/-.
- 2.46. Estimated cost for comprehensive development of roads and drains in Vidhansoudha Layout and surrounding areas in Ward Number 69, Laggere was at Rs. 1,95,98,967/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up raised hollow bricks raising course over the drain to an extent of 25% and submitted bill for Rs. 1,31,17,172/-.
- 2.17. Estimated cost comprehensive development of roads and drains from Aladamara circle to Rajiv Gandhi Circle in Ward Number 69 Laggere was at Rs. 1,95,98,598/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up raised hollow bricks raising course over the drain and carried out the work to an extent of 25% and submitted bill for Rs. 1,75,69,957/-

ಸ್ಯಾದ

- 2.48. Estimated cost comprehensive development of roads and drains in Muneshwara Layout and surrounding areas in Ward Number 69, Laggere was at Rs. 1,95,96,359/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up raised hollow bricks raising course over the drain and carried out the work to an extent of 25% and submitted bill for Rs. 1,28,40,337/-.
- 2.49. Estimated cost for improvement and maintenance of drains at Chandrashekara Badavane, 2<sup>nd</sup> main, 1<sup>st</sup> main and surrounding areas in Jnanabharathi, Ward Number 129 Rs. 1,95,27,846/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up raised hollow bricks raising course over the drain and carried out the work to an extent of 25% and submitted bill for Rs: 1,74,87,436/-.
- 2.50. Estimated cost for improvement of raods in NGEF Layout 2<sup>nd</sup> main, 3<sup>rd</sup> main and other surrounding cross roads in Jnanabharathi Ward Number 129 Rs. 1,95,96,812/-. The said work was entrusted to KRIDI. which, has not executed the said work and submitted bill for Rs. 1,69,53,080/-.
- 2.51. Estimated cost for improvement of raods in Mallathahalli and other surrounding cross roads in Jnanabharathi Ward Number 129 Rs. 1,95,98,254/-. The said work was entrusted to KRIDL which, without executing the work as per the estimate executed work to the extent of 20% and submitted bill for Rs. 1,08,85,845/-.
- 2.52. Estimated cost for improvement and maintenance of drains at RHCS Layout, 2<sup>nd</sup> stage, A Block and other surrounding areas in Jnanabharathi, Ward Number 129 Rs. 1,95,99,242/-. The said work was entrusted to KRIDL which, without executing the work as per the



estimate executed work to the extent of 20% and submitted bill for Rs. 17,49,007/-.

- 2.53. Estimated cost for improvement and maintenance of drains in 1<sup>st</sup> main, 2<sup>nd</sup> main, Aladamara main road, Jubilee Internation school and cross roads in Annapurneshwari Nagara and other surrounding areas in Jnanabharathi, Ward Number 129 was at Rs. 1,95,96,395/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up hollow bricks raising course over the drain and executed work to the extent of 25% and submitted bill for Rs. 1,74,14,333/-.
- 2.54. Estimated cost for improvement and maintenance of drains in Muneshwara Nagara 8th cross, 12th cross and other surrounding areas in Jnanabharathi, Ward Number 129 was at Rs. 1,95,98,145/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up hollow bricks raising course over the drain and executed work to the extent of 25% and submitted bill for Rs. 1,74,51,037/-.
- 2.55. Estimated cost for improvement and maintenance of drains at 9th cross and 9th D road in Jnanajyothi Nagara and other surrounding areas in Jnanabharathi, Ward Number 129 was at Rs. 1,95,95,595/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up hollow bricks raising course over the drain and executed work to the extent of 25% and submitted bill for Rs. 1,74,09,584/-.
- 2.56. Estimated cost for improvement and maintenance of drains at Inanajyothi Nagar 7th main and other surrounding areas in Inanabharathi, Ward Number 129 was at Rs. 1,95,95,418/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up hollow bricks raising

course over the drain and executed work to the extent of 25% and submitted bill for Rs. 1,74,72,497/-.

- 2.57. Estimated cost for improvement and maintenance of drains at Health Layout, 3rd main, RHCS Layout 1st main and other surrounding areas in Jnanabharathi, Ward Number 129 was at Rs. 1,95,98,915/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,91,69,018/-.
- 2.58. Estimated cost for improvement and maintenance of drains in 4th main, 3rd main and cross road in Annapurneshwari Layout and RHCS Layout and surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,96,232/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,74,72,915/-.
- 2.59. Estimated cost for improvement and maintenance of drains Jnanajyotht Nagara 7th main and surrounding areas Jnanabharathi Ward Number 129 was at Rs. 1,95,96,154/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up hollow bricks raising course over the drain and executed work to the extent of 25% and submitted bill for Rs. 1,74,06,369/-.
- 2.60. Estimated cost for improvement and maintenance of drains at 34th main road, 35th main road, 36th main road and cross road in RHCS Layout and surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,98,228/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up hollow bricks raising course over the drain and executed work to the extent of 25% and submitted bill for Rs. The state of

1,74,69,147/-

- 2.61. Estimated cost for improvement and maintenance of drains at Jnanajyothi Nagara 10<sup>th</sup> cross and surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,99,240/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up hollow bricks raising course over the drain and executed work to the extent of 25% and submitted bill for Rs. 1,73,94,148/-.
- 2.62. Estimated cost for improvement and maintenance of drains at 2<sup>nd</sup> main road, 35<sup>th</sup> main road and cross road in Iranapalya, RHCS Layout and surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,96,159/-. The said work was entrusted to KRIDL which, without executing the said work prepared fake bill and submitted bill for Rs. 1,72,26,942/-.
- 2.63. Estimated cost for improvement and maintenance of drains at Government Press Layout and other surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,978,790/-. The said work was entrusted to KRIDL which, without executing the said work prepared fake bill and submitted bill for Rs. 1,59,49,405/-.
- 2.64. Estimated cost for improvement and maintenance of drains at 5<sup>th</sup> main 1<sup>st</sup> stage and cross road in Annapurneshwari Layout and RHCS Layout and surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,98,199/-. The said work was entrusted to KRIDL which, without executing the said work prepared fake bill and submitted bill for Rs. 1,74,16,050/-.
- 2.65. Estimated cost for improvement and maintenance of drains at 5th main, 6th main, 7th main and cross road in HCS Layout and surrounding area in Jnanabharathi Ward Number 129 was at Rs. 1,95,96,860/-. The said work was entrusted to KRIDL which, without applying cement concrete overstanding as provided in the estimate put

Dest

up hollow bricks raising course executed the work to an extent of 25% and and submitted bill for Rs. 1,74,23,728/-.

- 2.66. Estimated cost for improvement and maintenance of drains at Health Layout 4th main and surrounding area in Jnanabharathi Ward Number 129 was at Rs. 1,95,98,902/-. The said work was entrusted to KRIDL which, without executing the above work prepared fake bill and submitted bill for Rs. 1,68,32,913/-.
- 2.67. Estimated cost for improvement and maintenance of drains at 1<sup>st</sup> main, 3<sup>rd</sup> main, 6<sup>th</sup> main, 4<sup>th</sup> main and cross road in RHCS Layout and Srigandhada Kavalu and surrounding area in Jnanabharathi Ward Number 129 was at Rs. 1,95,98,214/-. The said work was entrusted to KRIDL which, without executing the above work prepared fake bill and submitted bill for Rs. 1,74,97,442/-.
- 2.68. Estimated cost for improvement and maintenance of drains at 28th main road, 29th main road, 5th main road and cross road in Poornachandra Layout and surrounding area in Jnanabharathi Ward Number 129 was at Rs. 1,95,99,309/-. The said work was entrusted to KRIDL which, without executing the above work prepared fake bill and submitted bill for Rs. 1,71,82,637/-.
- 2.69. Estimated cost for improvement and maintenance of roads in Muneshwaranagara, Ullala Main road and other surrounding cross roads in Jnanabharathi Ward Number 129 was at Rs. 1,95,95,034/-. The said work was entrusted to KRIDL which, without executing the work as provided in the estimate executed the work to an extent of 20% and prepared fake bill and submitted bill for Rs. 1,02,82,339/-.
- 2.70. Estimated cost for improvement and maintenance of roads in Sir. M. Vishweshwaraiah Layout and other surrounding cross roads in Jnanabharathi Ward Number 12304 at Rs. 1,95,96,121/-. The said

ude i saarakaassa siin d

work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,10,99,151/-.

- 2.71. Estimated cost for improvement and maintenance of drains at 2<sup>nd</sup> main, Mallathahalli and Sunkadakatte cross roads and surrounding cross roads in Jnanabharathi Ward Number 129 was at Rs. 1,95,98,044/-. The said work was entrusted to KRIDL which, without executing the work and prepared fake bill and submitted bill for Rs. 1,67,50,414/-.
- 2.72. Estimated cost for improvement and maintenance of drains at 11th cross, 12th cross and surrounding cross roads in Papareddy Palya, Jnanabharathi Ward Number 129 was at Rs. 1,95,95,842/-. The said work was entrusted to KRIDL which, without executing the work as provided in the estimate executed the work to an extent of 25% and prepared fake bill and submitted bill for Rs. 1,74,38,489/-.
- 2.73. Estimated cost for improvement and maintenance of 1<sup>st</sup> main road, Paryaya Acadamey, BEML Layout and ther surrounding cross roads in Rajarajeshwari nagar Ward Number 160 was at Rs. 1,95,99,723/-. The said work was entrusted to KRIDL which, without executing the work as provided in the estimate executed the work to an extent of 25% and prepared fake bill and submitted bill for Rs. 1,70,49,531/-.
- 2.74. Estimated cost for improvement and maintenance of drains and footpath in Dr. R. Arunachalam Road in BEML Layout and the surrounding area in Rajarajeshwari Nagar Ward Number 160 was at Rs. 1,95,98,325/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,74,16,840/-.



- 2.75. Estimated cost for improvement and maintenance of drains and footpath in Dr. R. Arunachalam road in BEML Layout and the surrounding area in Rajarajeshwari nagar Ward Number 160 was at Rs. 1,95,98,325/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,74,16,840/-.
- 2.76. Estimated cost for improvement and maintenance of drains in BEML extention Srinivasa Block and the surrounding area in Rajarajeshwari nagar Ward Number 160 was at Rs. 1,95,98,659/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,74,04,360/-.
- 2.77. Estimated cost for improvement and maintenance of drains in 6<sup>th</sup> main, 1<sup>st</sup> main and 8<sup>th</sup> main road in BEML Layout and the surrounding area in Rajarajeshwari nagar Ward Number 160 was at Rs. 1,95,98,829/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,73,49,836/-.
- 2.78. Estimated cost for improvement and maintenance of Aiyappa Garden 1st main road in Kampada Badavane and the surrounding area in Rajarajeshwari nagar Ward Number 160 was at Rs. 1,95,97,333/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,73,00,844/-.

- 2.80. Estimated cost for improvement and maintenance of drains at Muneshwara Nagara 1st cross and Ullal Main road and the surrounding area in Jnanabharathi Ward Number 129 was at Rs. 1,95,98,326/-. The said work was entrusted to KRIDL which, without applying cement concrete over the drain as provided in the estimate put up hollow bricks raising course over the drain to an extent of 25% and submitted bill for Rs. 1,90,47,302/-.
- 2.81. Estimated cost for improvement and maintenance of drains at 4th cross and 7th main in Adarsha Layout and the surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,94,232/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,74,18,549/-.
- 2.82. Estimated cost for improvement and maintenance of drains at 2<sup>nd</sup> cross and 9<sup>th</sup> cros road in NGEF Layout and the surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,98,010/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,74,17,156/-.
- 2.83. Estimated cost for improvement and maintenance of drains at 2<sup>nd</sup> main, 3<sup>rd</sup> main and cross roads in NGEF Layout and surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,63,67,281/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill.
- 2.84. Estimated cost for improvement and maintenance of drains at 10<sup>th</sup> main, 7<sup>th</sup> main, 8<sup>th</sup> main and cross roads in NGEF Layout and the surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,95,991/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,63,91,333/-.


\* ADF UF

- 2.85. Estimated cost for improvement and maintenance of drains at 5<sup>th</sup> main and 6<sup>th</sup> cross in Bhavani Nagara and surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,96,154/-. The said work was entrusted to KRIDL which, without executing the work as provided in the estimate executed the work to an extent of 25% and prepared fake bill and submitted bill for Rs. 1,73,92,030/-.
- 2.86. Estimated cost for improvement and maintenance of drains at 10<sup>th</sup> cross and 6<sup>th</sup> main road and cross roads in Gurukrupa Badavane and surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,99,648/-. The said work was entrusted to KRIDL which, without executing the work as provided in the estimate executed the work to an extent of 25%.
- 2.87. Estimated cost for improvement and maintenance of drains at 12<sup>th</sup> main road, 11<sup>th</sup> main road, 1st main road and cross road in Honnappa Layout and surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,95,618/-. The said work was entrusted to KRIDL which, without executing the work as provided in the estimate executed the work to an extent of 25% and submitted bill for Rs. 1.74, 70,409/-.
- 2.88. Estimated cost for improvement and maintenance of drains at 30<sup>th</sup> main road, 21<sup>st</sup> main road, 32<sup>nd</sup> main road and cross road in RHCS Layout and surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,96,099/-. The said work was entrusted to KRIDL which, without executing the work as provided in the estimate executed the work to an extent of 25% and and submitted bill for Rs. 1,74,14,410/-.
- 2.89. Estimated cost for improvement and maintenance of drains at Inanajyothi Nagara, 10th cross, 15th cross and other surrounding areas in Inanabharathi Ward Number 129 was at Rs. 1,95,94,175/-



The said work was entrusted to KRIDL which, without executing the work has prepared fake bill and submitted bill for Rs. 1,74,41,696/-.

- 2.90. Estimated cost for improvement and maintenance of drains at Jnanajyothi nagara 9th main and other surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,96,154/-. The said work was entrusted to KRIDL which, without executing the work has prepared fake bill and submitted bill for Rs. 1,75,67,004/-.
- 2.91. Estimated cost for improvement and maintenance of drains at Government Press Layout and other surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,96,154 /-. The said work was entrusted to KRIDL which, without executing the work has prepared fake bill and submitted bill for Rs. 1,72,61,625/-.
- 2.92. Estimated cost for improvement and maintenance of drains at Gavipuram Badavane and other surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,94,594/-. The said work was entrusted to KRIDL which, without executing the work has prepared fake bill and submitted bill for Rs. 1,71,28,670/-.
- 2.93. Estimated cost for improvement and maintenance of drains at Inanajyothi nagara 9th main and other surrounding areas in Inanabharathi Ward Number 129 was at Rs. 1,95,96,154/-. The said work was entrusted to KRIDL which, without executing the work as provided in the estimate executed the work to an extent of 25% and submitted bill for Rs. 1,74,20,106/-
- 2.94. Estimated cost for improvement and maintenance of drains at Inanajyothi nagara 14th cross and 15th cross and other surrounding areas in Inanabharathi Ward Number 129 was at Rs. 1,95,96,154/-. The said work was entrusted to KRIDL which, without executing the work has prepared fake bill and submitted bill for Rs. 1,68,24,393/-.



- 2.95. Estimated cost for improvement and maintenance of drains at 10<sup>th</sup> main and 10<sup>th</sup> cross in Jnanajyothi Nagara and other surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,95,066/-. The said work was entrusted to KRIDL which, without executing the work has prepared fake bill and submitted bill for Rs. 1,75,65,342/-.
- 2.96. Estimated cost for improvement and maintenance of drains at 5<sup>th</sup> main and 6<sup>th</sup> cross at Bhavani Nagara and other surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,96,678/-. The said work was entrusted to KRIDL which, without executing the work has prepared fake bill and submitted bill for Rs. 1,75,65,399/-.
- 2.97. Estimated cost for improvement and maintenance of drains at Papareddy Palya main road and other surrounding cross road in Jnanabharathi Ward Number 129 was at Rs. 1,95,99,364/-. The said work was entrusted to KRIDL which, without executing the work has prepared fake bill and submitted bill for Rs. 1,73,89,959/-.
- 2.98. Estimated cost for improvement and maintenance of drains at 3<sup>rd</sup> main, 4<sup>th</sup> main and cross roads in NGEF Layout and surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,97,579/-. The said work was entrusted to KRIDL which, without executing the work has prepared fake bill and submitted bill for Rs. 1,65,14,246/-.
- 2.99. Estimated cost for improvement and maintenance of drains at 6<sup>th</sup> main road, 6<sup>th</sup> cross road in ITI Layout and surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,95,367/-. The said work was entrusted to KRIDL which, without executing the work has prepared fake bill and submitted bill for Rs. 1,14,64,326/-.
- 2.100. Estimated cost for improvement and maintenance of drains at 1sr main and 2<sup>nd</sup> main road in Sir. M. Vishweshwaraiah Layout, 9<sup>th</sup>





Secretary of the second of the

Block and surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,98,816/-. The said work was entrusted to KRIDL which, without executing the work has prepared fake bill and submitted bill for Rs. 1,74,69,846/-.

- 2.101. Estimated cost for improvement and maintenance of drains at 2<sup>nd</sup> main, 11<sup>th</sup> cross and cross roads in NGEF Layout and surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,98,435/-. The said work was entrusted to KRIDL which, without executing the work has prepared fake bill and submitted bill for Rs. 1,69,13;855/-.
- 2.102. Estimated cost for improvement and maintenance of drains at 9th cross, 1st main road and cross roads in Mallathahalli Layout and surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,94,070/-. The said work was entrusted to KRIDL which, without executing the work as provided in the estimate executed the work to an extent of 25% and submitted bill for Rs. 1,74,34,338/-.
- 2.103. Estimated cost for improvement and maintenance of drains at 11<sup>th</sup> main and 9<sup>th</sup> main in Bhavani Nagara and surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,96,234/-. The said work was entrusted to KRIDL which, without executing the work has prepared fake bill and submitted bill for Rs. 1,74,27,723/-.
- ° 2.104. Estimated cost for improvement and maintenance of drains at Muneshwara Nagara 8<sup>th</sup> cross and 12<sup>th</sup> cross and also surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,98,709/-. The said work was entrusted to KRIDL which, without executing the work has prepared fake bill and submitted bill for Rs. 1,70,20,785/-.
- 2.105. Estimated cost for improvement and maintenance of drains at Muneshwara Nagara 1st cross Ullal Main road and also surrounding

areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,96,154/-. The said work was entrusted to KRIDL which, without executing the work as provided in the estimate executed the work to an extent of 25% and submitted bill for Rs. 1,70,55,606/-.

- 2.106. Estimated cost for improvement and maintenance of drains at 10<sup>th</sup> cross and 1<sup>st</sup> cross of K.K Layout and surrounding cross road in Jnanabharathi Ward Number 129 was at Rs. 1,95,96,863/-. The said work was entrusted to KRIDL which, without executing the work as provided in the estimate executed the work to an extent of 25% and submitted bill for Rs. 1,74,82,160/-.
- 2.107. Estimated cost for improvement and maintenance of drains of 16th main, 15th main and cross road in Deepa Complex and surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,96,948/-. The said work was entrusted to KRIDL which, without executing the work as provided in the estimate executed the work to an extent of 25% and submitted bill for Rs. 1,74,68,325/-.
- 2.108. Estimated cost for improvement and maintenance of drains 4th main, 5th main, 6th main and cross road in III Layout and surrounding areas in Jnanabharathi Ward Number 129 was at Rs. 1,95,98,496/-. The said work was entrusted to KRIDL which, without executing the work as provided in the estimate executed the work to an extent of 25% and submitted bill for Rs. 1,74,68,067/-.
- 2.109. Estimated cost for improvement and maintenance of road at 13<sup>th</sup> main and surrounding cross roads in Vinayaka Layout in Ward Number 73, Kottigepalya was at Rs. 1,95,99,402/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,71,55,596/.





- 2.110. Estimated cost for improvement and maintenance of drains in Srigandhada Kaval Industrial Estate and surrounding areas in Ward Number 73, Kottigepalya was at Rs. 1,95,95,272/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,69,09,754/-.
- 2.111. Estimated cost for improvement and maintenance of drains in BDA Layout, Mahathma Gandhi Park, Bramhagiri Apartment and surrounding ares in Ward Number 73, Kottigepalya was at Rs. 1,95,98,375/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,68,93,644/-.
- 2.112. Estimated cost for improvement and maintenance drains in Gangamma Garden, Krishnananda Nagara, Malagala and surrounding areas in Ward Number 73, Kottigepalya was at Rs. 1,95,98,604/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,69,11,336/-.
- 2.113. Estimated cost for improvement and maintenance of drains in Marilingappa Extention, Nagarabhavi 7th block and surrounding areas in Ward Number 73, Kottigepalya was at Rs. 1,95,99,827/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,60,10,097/-.
- 2.114. Estimated cost for improvement and maintenance of drains in Vinayaka Layout, BDA Layout, Bandemaramma Park and surrounding areas in Kottigepalya Ward Number 73, was at Rs. 1,95,99,560/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,73,89,017/-.

क्रिन्ध स

- 2.115. Estimated cost for improvement and maintenance of drains in Vinayaka Layout, Nanjappa Garden and surrounding areas in Kottigepalya Ward Number 73 was at Rs. 1,95,98,628/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,60,06,867/-.
- 2.116. Estimated cost for improvement of roads at 10th main road, 9th main road and Nanjappa Garden surrounding cross roads in Kottigepalya Ward Number 73 was at Rs. 1,95,99,826/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,70,53,540/-.
- 2.117. Estimated cost for improvement of roads at 2<sup>nd</sup> main road, 2A, 2B, 2C, 2D, 2E, 2F, 2G cross roads and surrounding area roads in Kottigepalya Ward Number 73 was at Rs. 1,95,99,420/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,71,99,035/-.
- 2.118. Estimated cost for improvement and maintenance of drains in Malagala Layout, Malagala Village, Ramakrishna Layout and surrounding area roads in Ward Number 73 Kottigepalya was at Rs. 1,95,99,792/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,70,38,559/-.
- 2.119. Estimated cost for improvement of roads in 3<sup>rd</sup> main road, Sofia High School road and H. Main road and surrounding area roads in Ward Number 73 Kottigepalya was at Rs. 1,95,99,524/-. The said work was entrusted to KRIDL which, without fully executing the work and without applying line on the Tar Road prepared fake bill and submitted bill for Rs. 1.72,70,651/-.





- 2.120. Estimated cost for improvement of roads at Nagarabhavi 5th Block and BDA complex surrounding cross roads in Kottigepalya Ward Number 73 was at Rs. 1,95,99,049/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,71,47,494/-.
- 2.121. Estimated cost for improvement of roads at Marilingappa extention, Nagarabhavi 5<sup>th</sup> block and surrounding cross roads in Kottigepalya Ward Number 73 was at Rs. 1,95,99,691/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,74,12,776/-.
- 2.122. Estimated cost for improvement and maintenance of drains in Nagarabhavi 2<sup>nd</sup> Block, Nagarabhavi 3<sup>rd</sup> block and surrounding areas in Kottigepalya Ward Number 73 was at Rs. 1,95,98,737/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill.
- 2.123. Estimated cost for improvement and maintenance of drains in Prema Nagara, Pramod Nagara and surrounding areas in Kottigepalya Ward Number 73 was at Rs. 1,95,98,873/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,68,68,141/-.
- 2.124. Estimated cost for improvement and maintenance of drains in Sollapuradamma Layout, Sreenivasa Nagara and surrounding areas in Kottigepalya Ward Number 73 was at Rs. 1,95,93,878/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,66,48,689/-.
- 2.125. Estimated cost for improvement and maintenance of drains in Rudreshwara Nagara, Ashwatha Nagara and surrounding areas in Ward Number 73 Kottigepalya was at Rs. 1,95,96,811/-. The said work

was entrusted to KRIDL which, without executing the work as provided in the estimate executed the work to an extent of 25% and submitted bill for Rs. 1,68,92,277/-.

- 2.126. Estimated cost for improvement and maintenance of drains in Telephone Employees' Layout, Sollapuradamma Layout, Srigandhadha Kaval Industrial Estate and surrounding areas in Ward Number 73 Kottigepalya was at Rs. 1,95,93,173/-. The said work was entrusted to KRIDL which, without executing the work prepared fake bill and submitted bill for Rs. 1,73,48,095/-.
- 3. The comments of respondents 1 to 12 was called and in the meantime the file was entrusted to the Chief Engineer attached to Technical Audit Cell, Karnataka Lokayukta for investigation and report. The Managing Director attached to Karnataka Rural Infrastructure Development Limited was also directed to furnish documents which are in his custody to the investigation team and also to submit his report touching the allegations levelled in the complaint.
- 4. Respondent No. 1 Sri. Doddaiah, Chief Engineer, T.V.C.C Cell, BBMP has contended that the bills have to be submitted for payment along with work completion certificate issued by the concerned Engineers, Quality control report, estimate, Administrative and technical approval and M.B books online to the concerned Accounts Superintendent and the Accounts Superintendent has to verify the file and should deduct the statutory deductions and submit the bill for payment online through the concerned Executive Engineers to T.V.C.C Cell and in that cell the file will be verified, the quality of the work done will be examined and through online the further steps will be taken. In case the bills are not in accordance with rules and the work is not done properly the same will be sent back. The concerned field

area y leggi burde in Julya Aya

engineers of Rajarajeshwari Nagara division ward have certified that all the 126 works mentioned in the complaint have been completed and the Accounts Superintendent has verified the files and had put up the bills for payment and the files were sent to the Chief Accountant through the Chief Engineer of T.V.C.C and T.V.C.C has no power to release the amount. There is no irregularity by the 1st respondent or by T.V.C.C in respect of the 126 works mentioned in the complaint. It is further stated that the payments have been made in respect of the 126 works in question as per above said procedure and the 1st respondent has not committed any misconduct. The allegations made against the 1st respondent are all false. For each work separate estimate has been prepared and the sketch has also been prepared to the estimate and the approval has been obtained for all the 126 works (Administrative and Technical) and all the 126 works have been executed through M/s. KRIDL. The concerned Executive Engineer of Rajarajeshwari Nagara Division has entered into agreement with the contractors and the copies of the same are produced. In respect of all the 126 works the field engineers have given the photos of the works for having completed the works and quality control reports have also been obtained. The concerned engineers have also noted the measurements of the work done in the M.B books. The concerned engineers have also reported that out of 126 works the works at sl. nos. 42, 90, 95, 96 are completed and remaining 122 works are in progress. The 1st respondent is not concerned with the allegation that in respect of the 126 works stated above the payment has been made without executing the works. The concerned Executive Engineer has to submit the documents online and only in respect of 10% of the works to T.V.C.C office and in respect of the remaining works the file has to be sent to the Chief Accountant online and T.V.C.C will examine only the 10% of the works submitted to their office online. He has also

CO CO CO

stated that he is not concerned with the allegations made in respect of 126 works enclosed to the complaint.

- 5. The 2<sup>nd</sup> respondent Sri. Sathish, Assistant Executive Engineer, T.V.C.C Cell, BBMP has filed his comments which is similar to the comments filed by the 1<sup>st</sup> respondent stated above.
- Sri. Vijayakumar, Chief . Engineer, respondent 6. The Rajarajeshwari Nagara Zonal Office, BBMP has contended that the execution of the works, examination of quality is the duty of the concerned Assistant Engineer and Assistant Executive Engineer of the concerned divisions and the Executive Engineer has to examine the bills submitted by the Assistant Executive Engineer and recommend for payment. The allegations made in the complaint comes within the purview of Assistant Engineer, Assistant Executive Engineer and Executive Engineer of the concerned sub division and the same does not come within the jurisdiction of Chief Engineer. The Chief Engineer gives only the technical sanction to the works and the works have to be executed as per the estimates and it is the duty of the concerned Assistant Engineer, Assistant Executive Engineer and the Executive Engineer to see that the works are done as per the estimates.
- 7. The Respondent number 4 Smt. Shilpa, Assistant Engineer, Office of Chief Engineer, BBMP in her comments has contended that execution of the works, examining the quality of the works is the duty of the concerned Assistant Engineer and Assistant Executive Engineer of the concerned ward. The works have to be examined by the Assistant Engineer and he has to write the measurements of the works and it has to be verified by the Assistant Executive Engineer and afterwards it is the duty of the concerned Executive Engineer to certify the same. None of the above said responsibility was with the 4th

The second of the second

respondent as she is working as Assistant Engineer (T.A) in the office of the Chief Engineer, Rajarajeshwari Nagara zone.

- 8. The 5th respondent Sri. Mohan, Executive Engineer, Rajarajeshwari Nagara Project Division, BBMP has contended that none of the works mentioned in the complaint have been undertaken through 5th respondent and he has not executed or supervised any of the works.
- 9. Respondent number 6 Smt. Bharathi, Assistant Executive Engineer and T.A, Executive Engineer office, Rajarajeshwari Nagara Project Division has filed her comments contending that she has not done any of the works mentioned in the complaint and she is not at all concerned with the allegations made in the complaint.
- 10. Respondent number 7 Sri. Basavaraj, Executive Engineer, Incharge Assistant Executive Engineer, Rajarajeshwari Nagara Division has contended that, from BBMP the works in question were entrusted to KRIDL which is a company. Earlier it was called as Karnataka Land Army Corporation. The works entrusted to KRIDL have to be executed as per the rules and circulars issued by the Government of Karnataka from time to time. The Engineers of KRIDL have supervised the works and after completion of the works the bills have been submitted and after examining the bills recommendation has been made to clear the bills and except for KRIDL no amount is paid to the contractors in respect of the works in question. The 7th respondent has not executed the works in question. The quality of the works has been certified by the M/s Civil Square consultants (3rd party). There is Quality Control Engineer in KRIDL also. The KRIDL has executed the works as per the estimates and the 7th respondent has not committed any misconduct.
- 11. Respondent number 8 Sri. Siddaramaiah, Assistant Engineer, Rajarajeshwari Nagara sub division, BBMP has filed his comments which is similar to the comments of respondent 7 stated above. It is

further contended that the KRIDL has completed the works as per the agreement by the Engineers of KRIDL. After completion of the work the bills have been submitted and after examining the bills and the works the recommendation has been made to pay the amount to KRIDL.

- 12. Respondent number 9 Sri. Umesh, Assistant Executive Engineer, In-charge Assistant Engineer ward number 73 has filed his comments which is similar to the comments of Respondent number 7.
- 13. Respondent number 10 Smt. Anitha, Superintendent and Cashier, Rajarajeshwari Nagara, BBMP has filed her comments contending that her name is Anitha Gowda.T and she is working as First Division Account Assistant. As the post of Accounts Superintendent was vacant she was directed to be in-charge Accounts Superintendent and accordingly she took charge as in-charge Accounts Superintendent on 01.02.2020. Her duty is only to examine the bills, deduct the statutory deductions from the bill amount and credit the remaining amount concerned section through online and after the payment is made to the contractor to mention the same in the Accounts book. She is not concerned regarding whether the works have been done as per the specifications nor she is concerned with the measurement of the works etc., The above said duty is on the concerned Assistant Engineer and the Assistant Executive Engineer. When she was working as in-charge Accounts Superintendent she has received the bills certified by the Assistant Engineer, Assistant Executive Engineer and the Executive Engineer along with the photos of work done and the quality control reports and as per PWD accounts code after deducting the statutory deductions the recommendation will be made for payment of the amount and she has not committed misconduct.

14. Respondent number 11 Sri. Gooligowda Deputy Manager, Rajarajeshwari Nagara, BRMP has contended that he is working as

MON AND

Assistant Engineer/Draft man in the office of Executive Engineer, Rajarajeshwari Nagara Division the execution of the examination of the quality is the duty of the concerned Assistant Engineer and Assistant Executive Engineer. The measurement will be written by the Assistant Engineer of the ward and the same has to be certified by the Assistant Executive Engineer of the sub-division and the bills certified by the Assistant Engineer and Assistant Executive Engineer will be submitted to the Accounts section. The allegations made in the complaint pertains to non-execution of the work as per the specification which is the duty of the Assistant Engineer and the Assistant Executive Engineer and the 11th respondent nothing to do with the same.

15. Superintending Engineer, KRIDL, BBMP Range, Bengaluru has given the report dated 11.10.2020 as follows:

In the list of 126 works mentioned in the complaint 11 works are repeated, one work is not entrusted to KRIDL and in respect of another work the job code is not correctly mentioned and in respect of the remaining 113 works agreements have been executed between BBMP and KRIDL and after obtaining the agreement and the work order the 113 works have been executed and the details of the same is as follows:

1	ಲೋಕಾಯುಕ್ತ ವರದಿಯ ಪ್ರಕಾರ ದೂರು ಸಲ್ಲಿಸಿರುವ ಕಾಮಗಾರಿಗಳು (2.01 ರಿಂದ 2.126)	ಒಟ್ಟು ಕಾಮಗಾರಿಗಳ ಸಂಖ್ಯೆ: 126
2	ರಿಪಿಟಿಷನ್ ಆಗಿರುವ ಕಾಮಗಾರಿಗಳು: 2.32(2.10), 2.74 (2.16), 2.75 (2.16), 2.76(2.19), 2.79 (2.29), 2.109(2.02) 2.110(2.108), 2.116 (2.01), 2.117 (2.03), 2.120 (2.04), 2.121 (2.05)	120
3 4	ಕಾಮಗಾರಿ ಸಂಖ್ಯೆ: 2.43 (ಮಟ ಸಂಖ್ಯೆ:17) ಕೆಆರ್ಐಡಿಎಲ್ ಸಂಸ್ಥೆಗೆ ವಹಿಸಿರುವುದಿಲ್ಲ ಕಾಮಗಾರಿ ಸಂಖ್ಯೆ: 2.59 (ಮಟ ಸಂಖ್ಯೆ: 23) ಜಾಬ್ ಕೋಡ್ ಸರಿಯಾಗಿ ನಮೂದಿಸಿರುವುದಿಲ್ಲ	1
5	ಬಿಬಿಎಂಪಿ ವತಿಯಿಂದ ಕೆಆರ್ಐಡಿಎಲ್ ಸಂಸ್ಥೆಗೆ, ಕಾಮಗಾರಿ ಸಂಪ್ಯೆ: 2.06, 2.08 ರಿಂದ 2.10 (03), 2.14, 2.16, 2.18, 2.25 ರಿಂದ 2.27 (03) 2.30, 2.31, 2.40, 2.42, ರಿಂದ 2.49 (06) 2.52, 2.53, 2.58, 2.63, 2.64, 2.91, 2.97, 2.126. ಸದರಿ ಕಾಯಮಗಾರಿಗಳನ್ನು ಬಿಬಿಎಂಪಿ ನೀಡಿರುವ ಕಾರ್ಯಾದೇಶ ಹಾಗೂ ಕರಾರು ಪತ್ರದನ್ವಯ ನಿರ್ವಹಿಸಲಾಗಿರುತ್ತದೆ, ಆದರೇ ಸದರಿ ಕಾಮಗಾರಿಗಳಿಗೆ ಬಿಬಿಎಂಪಿ ವತಿಯಿಂದ ಅನುದಾನ ಬಿಡುಗಡೆಯಾಗಿರುವುದಿಲ್ಲ.	28



6	ಕಾಮಗಾರಿ ಸಂಖ್ಯೆ: 2.39, 2.55, 2.123, 2.124, 2.125, ಸದರಿ ಕಾಮಗಾರಿಗಳಿಗೆ ಬಿಬಿಎಂಪಿ	
	ವತಿಯಿಂದ ಅನುದಾನ ಬಿಡುಗಡೆಯಾಗಿರುತ್ತದೆ. ಆದರೇ, ಮಾನ್ಯ ಆಯುಕ್ತರು, ಬೃಹತ್	0.0
	ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ ರವರ ಪತ್ರ ಸಂಖ್ಯೆ: 130 ದಿನಾಂಕ: 06.07.2020ರ ಪ್ರಕಾರ	05
	(ಪ್ರತಿಯನ್ನು ಲಗತ್ತಿಸಿದೆ), ಪಾವತಿ ಮಾಡದಿರಲು ಸೂಚಿಸಿರುತ್ತಾರೆ. ಅದರಂತೆ ಈ	
	ಕಾಮಗಾರಿಗಳಿಗೆ ಹಣವನ್ನು ಪಾವತಿಸಿರುವುದಿಲ್ಲ.	
7	ಹಣವನ್ನು ಪಾವತಿಸಿದ ಒಟ್ಟು ಕಾಮಗಾರಿ ಸಂಖ್ಯೆಗಳು. ಈ 80 ಕಾಮಗಾರಿಗಳಲ್ಲಿ 17	
	ಕಾಮಗಾರಿಗಳಿಗೆ ಫೆಬ್ರವರಿ-2020 ಹಾಗೂ ಮಾರ್ಚ್-2020ರಲ್ಲಿ ಬಿಬಿಎಂಪಿ ಟಿವಿಸಿಸಿ	
	ವತಿಯಿಂದ ಅನುಮೋದನೆ ಪಡೆದು ಗ್ರೂಪ್ ಲೀಡರ್ಗಳಿಗೆ ಹಣವನ್ನು ಪಾವತಿಸಿದೆ. 17	
	ಕಾಮಗಾರಿಗಳಿಗೆ ಟಿವಿಸಿಸಿ ಅನುಮೋದಿಸಿದ ಪ್ರತಿಯನ್ನು ಲಗತ್ತಿಸಿದೆ ಹಾಗೂ ಕ್ರಮ ಸಂಖ್ಯೆಗಳು	· ·
	ಹೀಗಿರುತ್ತವೆ: 2.57, 2.66, 2.71, 2.80, 2.83, 2.84, 2.86, 2.92, 2.98, 2.101, 2.111,	
	2.112, 2.113, 2.114, 2.115, 2.118, 2.122.	
) )	ಈ ಪೈಕಿ ಉಳಿದ 63 ಕಾಮಗಾರಿಗಳಿಗೆ ಮಾನ್ಯ ಆಯುಕ್ತರು, ಬಿಬಿಎಂಪಿ ಇವರ ಆದೇಶ ಪತ್ರ	80
	ಸಂರ್ಖಯ: 130 ದಿನಾಂಕ: 06.07.2020ರಂತೆ ಟಿವಿಸಿಸಿ-ಬಿಬಿಎಂಪಿ ರವರಿಂದ	
	ಅನುಮೋದನೆ ಪಡೆದು ಗ್ರೂಪ್ ಲೀಡರ್ಗಳಿಗೆ ಜುಲೈ-2020 ಹಾಗೂ ಆಗಸ್ಟ್-2020 ರಲ್ಲಿ	
	ಪಾವತಿಸಲಾಗಿರುತ್ತದೆ. ಕಾಮಗಾರಿಗಳ ಸಂಖ್ಯೆ ಈ ರೀತಿ ಇರುತ್ತವೆ: 2.01 ರಿಂದ 2.05(5),	
	2.07, 2.11 ರಿಂದ 2.13 (3) 2.15, 2.17, 2.19 ರಿಂದ 2.24 (6) , 2.28, 2.29, 2.33	
	ರಿಂದ 2.38 (6), 2.41, 2.50, 2.51, 2.54, 2.56, 2.60 ರಿಂದ 2.68 (8) 2.65, 2.67	
	ರಿಂದ 2.70 (4), 2.93 ರಿಂದ 2.96 (4), 2.99, 1.100, 2.102 ರಿಂದ 2.108 (7), 2.119	

The total estimated amount of the above said 80 works is Rs. 154.97 crores. Out of the same Rs. 6.98 crores has been deducted as FSD and the remaining amount of Rs. 133.95 crores has been released to KRIDL and it has been paid to the group leaders. Out of the 80 works stated above for 3 works (2.90, 2.95, 2.96) the BBMP has paid the final bills and in respect of the remaining 77 works BBMP has paid the first and part bill as per the letters of Executive Engineer and Assistant Executive Engineer, KRIDL. No amount has been misappropriated in respect of any work and 113 files are also produced for perusal.

16. According to the investigation reports the works at serial numbers 2.32, 2.74, 2.75, 2.76, 2.79, 2.109, 2.116, 2.117, 2.120 and 2.121 are repetitions and only 116 files were given to Investigating Officers by the Rajarajeshwari Nagara ward BBMP officials.

17. As 116 works had to be inspected totally 5 Engineers of Technical Audit Cell have conducted the investigation and given the reports by distributing the above said [16] works among themselves. Sri. R. Ravishankar, Assistant Executive Engineer-5 has inspected 24 works.

COURTO !

Sri. Chandrappa.M, Assistant Executive Engineer-3 has inspected 23 works, Smt. M. Nagarathna, Assistant Executive Engineer-2 has inspected 24 works, Sri. Guruprasad J.D, Assistant Engineer-6 has inspected 23 works and Sri. Ashok.N, Assistant Engineer-1 has inspected 22 works and all of them given their reports separately in respect of the works inspected by them.

- 18. All the Investigating Officers have given their reports to the effect that out of 116 works inspected, some of the works have not been executed at all and the remaining works have not been executed as per the tender specifications and thereby there is misuse and misappropriation of the Government funds as mentioned in their reports.
- 19. As per the report of Sri. R. Ravishankar, Assistant Executive Engineer-5 there is misappropriation of Rs. 23,68,20,263/- in respect of the 24 works inspected by him.
- 20. As per the report of Sri. Guruprasad J.D, Assistant Engineer-6 there is misappropriation of Rs. 20,76,53,469/- in respect of the 21 works out of 23 works inspected by him.
- 21. As per the report of Sri. Chandrappa.M, Assistant Executive Engineer-3, there is misappropriation of Rs. 32,60,43,419/- in respect of the 23 works inspected by him.
- 22. As per the report of Sri. Ashok.N, Assistant Engineer-1 there is misappropriation of Rs. 12,00,07,909/- in respect of the 22 works inspected by him.
- 23. As per the report of Smt. M. Nagarathna, Assistant Executive Engineer-2 there is misappropriation of Rs. 29,20,54,737/- in respect of the 24 works inspected by her.

24. As per the letter of Sri. R. Ravishankar, Assistant Executive Engineer-5 dated 15.11.2021 it is stated that he had written the letter on 02.11.2021 to the Superintending Engineer, KRIDL to give othe particulars called for and no reply is received but over phone the Superintending Engineer has told that Sri. Chandranath was working as Assistant Executive Engineer, and Sri. Srinivas was working as Executive Engineer and at present they are working in KRIDL and regarding third party inspection team the name of the third party is Civil Square Consultants but other details is not given. In the above said letter it is further stated that 1st respondent has written the letter dated 12.11.2021 to the Chief Engineer of Technical Audit Cell, Karnataka Lokayukta wherein it is mentioned that Sri. Shreetej was working as Assistant Engineer and Smt. Venkatalakshmi was working as Assistant Executive Engineer in TVCC Cell and they have given their reports in respect of most of the work in question. In view of the same the respondents 12 to 15 have been impleaded.

- 25. Copies of the reports of the Investigating Officers have been sent to respondents 1 to 15 for their reply to the investigation reports.
- 26. Respondent number 1 has filed the reply reiterating the comments already filed and the 1st respondent is not responsible for the deficiencies in the work etc., alleged in the complaint.
- 27. Respondent number 2 has filed the reply reiterating the averments made in the comments already filed and the 2<sup>nd</sup> respondent is nowhere concerned with the misappropriation of the amount alleged in the complaint.
- 28. Respondent number 3 has filed the reply contending that in respect of number of works part payment part payment has been made at the level of Executive Engineer and the third respondent has not certified the measurement of the levels and he is not concerned

with the payment of the bills. In the report of Sri. R. Ravishankar, Assistant Executive Engineer-5 there is mention about providing ruled pointing to coursed stone masonry with cement mortar-for flagging course item but for flagging course of concrete solid blocks ruled pointing item has been considered as ruled pointing to coursed stone masonry is wrong and the estimate is wrong. In the reply it is stated as follows:

"ಆದರೆ, ಸಾಲಿಡ್ ಬ್ಲಾಕ್ ಗಳಿಂದ ನಿರ್ಮಿಸಿರುವ ಪ್ಲಾಂಗಿಂಗ್ ಕೋರ್ಸ್ ಗೆ ಅವಶ್ಯವಿರುವ ಪಾಯಿಂಟಿಂಗ್ ಅಂಶವು ಯಾವುದೇ ಇಲಾಖೆಯ ದರಪಟ್ಟಿಯಲ್ಲಿ ಲಭ್ಯವಿಲ್ಲದೇ ಇರುವುದರಿಂದ ಅನುಗುಣವಾಗಿ ಪಾಯಿಂಟಿಂಗ್ ಅಂಶವನ್ನು ಅಳವಡಿಸಿಕೊಳ್ಳುವುದು ಅವಶ್ಯವಾಗಿದ್ದ ಕಾರಣ ಯೋಜನಾ ಹಾಗೂ ಸಮಾಲೋಚಕರು ಸಾಲಿಡ್ ಕಾಂಕ್ರೀಟ್ ಬ್ಲಾಕ್ ಗೋಡೆಯಂತೆಯೇ ನಿರ್ಮಿಸಲಾಗುವ ಕೋರ್ಸ್ಡ್ ಸ್ಟೋನ್ ಮೇಸನ್ರಿಗೆ ಸಂಬಂಧಿಸಿದ ಸಮಾನಾಂತರ ಪಾಯಿಂಟಿಂಗ್ ಅಂಶವನ್ನು (Equivilant pointing item) ಅವಳಡಿಸಿಕೊಂಡು ಅಂದಾಜುಪಟ್ಟಿಯನ್ನು ತಯಾರಿಸಿದ್ದು, ಸದರಿ ಅಂದಾಜುಪಟ್ಟಿಗಳನ್ನು ಅಭಿಯಂತರರು, ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು ಅಭಿಯಂತರರು ದೃಢೀಕರಿಸಿ ತಾಂತ್ರಿಕ ಮಂಜೂರಾತಿಗಾಗಿ ಸಲ್ಲಿಸಿರುತ್ತಾರೆ. ಸಹಾಯಕ ಅಭಿಯಂತರರು, ಮತ್ತು ಕಾರ್ಯಪಾಲಕ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ ದೃಢೀಕರಣ ಮತ್ತು ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ ಶಿಫಾರಸ್ಸಿನಂತೆ ಸದರಿ ಅಂದಾಜುಪಟ್ಟಿಗಳಿಗೆ ತಾಂತ್ರಿಕ ಮಂಜೂರಾತಿ ನೀಡಲಾಗಿರುತ್ತದೆ. ಆದುದರಿಂದ ತಾಂತ್ರಿಕ ಮಂಜೂರಾತಿ ನೀಡಿರುವಲ್ಲಿ ಯಾವುದೇ ರೀತಿಯ ಕರ್ತವ್ಯಲೋಪವಾಗಿರುವುದಿಲ್ಲ." Respondent number 3 has not committed lapses by giving technical sanction to the estimates.

- 29. Respondent number 4 has filed the reply stating that in the investigating reports there is no mention about her and she has prayed to close the complaint against her.
- 30. Respondent number 5 has filed the reply reiterating the comments already filed and that he has not executed or supervised any of the works mentioned in the reports and his name is wrongly included in



- 31. Respondent number 6 has filed his reply stating that she has not executed or supervised any of the works mentioned in the report and his name is wrongly included in the complaint.
- 32. Respondent number 10 has filed the reply that she was kept in charge of the post of Accounts Superintendent from 01.02.2020. The duty of the Accounts Superintendent is only to verify the bills and to deduct the amount towards IT, CGST, SGST and labour Cess etc., and credit the amount to the concerned Departments and uploading the bills online for mentioning B.R and after payment of the bill to mention about the same in the cash book. It is the duty of the concerned field engineers to take the measurement and verify the works and 25% of the work has to be certified by the Executive Engineer and she has not committed any misconduct.
  - 33. Respondent number 11 has filed the reply reiterating the comments already filed by him. The name of 11th respondent is Chikkaguligowda J.G and not Guligowda as mentioned in the cause title of the complaint. He has only worked as Draft man and he is not concerned with the lapses mentioned in the investigation reports.
  - 34. Respondent number 12 Sri. Chandranath, Assistant Executive Engineer, KRIDL has filed the reply to the investigation report as follows:-

The complainant has not named the 12th respondent in the complaint. In otherwords there is no complaint against respondent number 12 by the complainant. The report given by the Investigating Officer Guruprasad J.D has to be rejected as he has not considered the name and designation of respondent number 12 while giving his report in respect of sl. no. 1 to 10 and 14 and the said report is not correct. In the report of the Investigating Officer G.D Guruprasad in respect of works at sl. no. 1 to 23 no dereliction of duty is attributed to

the 12th respondent and the 12th respondent has to be left out from this complaint. In respect of the works done regarding quality the 3rd party inspection report has also been obtained. The bills submitted have been scrutinised by the Accounts section of the BBMP and the Assistant Engineer, Assistant Executive Engineer, and Executive Engineer after making entries in the measurement books and after satisfying that the works have been executed satisfactorily the amounts have been paid to KRIDL. The 12th respondent has not committed any misconduct in executing the works.

35. The 13th respondent Sri. Srinivas, Executive Engineer, KRIDL has filed the reply to the investigation report as follows:

In the complaint no allegations are made against the 13th respondent. In respect of work number 1 to 23 the Investigating Officer has not conducted the mahazar nor enquired any officers who were present at the time of inspection (as per para 4.01 to 4.23). In page number 157 to 166 of the report what are the deficiencies in the work is not mentioned clearly. Likewise in respect of page number 161 to 238 also. The Investigating Officer J.D Guruprasad has not made any allegations of misconduct or dereliction of duty against respondent number 13. The works have been supervised as per the orders of higher officer of respondent number 13 as the works were entrusted to KRIDL from BBMP. After execution of the work the amount has been related by BBMP in favour of KRIDL. The respondent number 13 have not caused any loss to the Government.

Respondent number 14 Smt. Venkatalakshmi, Assistant Executive Engineer, TVCC Cell, BBMP, Bengaluru has filed the lengthy reply and the gist of the same is as follows:

The Commissioner BBMP orally instructed the Chief Engineer, TVCC to inspect the works undertaker under "Chief Minister's Nava Nagarothana Scheme" and to give report and the Chief Engineer, TVCC instructed the concerned Engineers to inspect the works and to give the report and accordingly 73 works pertaining to Rajarajeshwari Nagara Assembly constituency were verified and the details of those 73 works are mentioned in the reply. She has given report after prima facie inspecting the works as per the oral instructions in respect of 35 works out of 73 works and in respect of the remaining 38 works respondent number-15 has given the inspection report. As only part payment is made in case of dislocation of slabs put to the drains the difference amount can be recovered. She has given the report as per the situation that existed at the time of her inspection. The payment in respect of 5 works has been withheld as per the reports given. Out of the 35 works inspected by her in respect of one work the concerned Assistant Engineer, Assistant Executive Engineer did not show the place of that work. She has given the report mentioning the facts and situation she noticed prima facie at the time of inspection in respect of 34 works. The defect liability period has not yet started and in case there are any lapses it can be set right in the defect liability period also. She has not committed any misconduct as alleged in the investigation reports.

37. Respondent number 15 Sri. Sreetej, the then Assistant Executive Engineer, T.V.C.C. Cell and Additional Charge of Technical Assistant, Office of Engineer-in-Chief, BBMP, Bengaluru has given the reply to the investigation report which is similar to the reply given by respondent number 14. Out of the works mentioned in the investigation reports, he has only inspected 38 works as per the oral instructions of the 1st respondent and given his report.

38. As stated above the complaint was referred to the Chief Engineer, Technical Audit Cell for investigation and report. The Chief Engineer

has got the inspection done through his 5 Engineers by distributing the works in dispute among them. All the 5 Engineers have given their reports in respect of the works inspected by them separately. The inspection has been done after issuing notice to both the parties and even spot mahazars have been drawn to show that the inspection has been done in the presence of the parties present. The Engineers have taken the measurements of the works inspected by them. In respect of roads (asphalted) core samples have been taken in the presence of the parties present and the same was sent to the Lab for report and the reports have also been obtained from the lab. By considering the tender specifications and the work done in the spots all the Engineers have come to the conclusion that the works are not in accordance with the tender specifications and thereby there is misappropriation of the Government funds in respect of 114 works out of 116 works inspected. According to the investigation reports the work has not been done as per the measurements mentioned in the estimate. In the investigation reports it is clearly stated that the work done is less than the measurements mentioned in the estimate in respect of most of the works in question and thereby there is misuse and misappropriation of the Government funds.

39. In the list annexed to the complaint the complainant has mentioned that in respect of 126 works (2.01 to 2.126) there is misappropriation. As per the investigation reports 116 works have been verified with reference to job code number and the area where the work has to be done and 10 works are repetitions and hence the complaint has to be considered in respect of 116 works in respect of which the Investigating Officers have given their reports.

40. In the investigation reports it is mentioned that some of the works are not at all executed, regarding some works excess measurements



are recorded and some works are not executed in accordance with the tender specifications and the details of the same and the amount misappropriated in respect of each work is clearly mentioned in the investigation reports. Annexure—A is annexed to this report which contains the name of the Investigating Officer, the name of the work, date of inspection, findings of the Investigating Officer, amount misappropriated and officers/officials responsible for the misappropriation (as per the Investigation Officers) and it forms part of this 12(3) report.

- 41. The investigation reports prima facie discloses that some of the works are not at all executed, some of the works were of substandard quality (asphalt work) and some works have not been executed as per the tender specifications and there was mention of excess measurements in the M.B books and there is misappropriation of Government funds as mentioned in Annexure-A stated above. The investigation reports are also supported by the lab reports regarding the core samples taken from the spots and sent to the lab for report (in respect of asphalt work). The Investigating Officers have also produced the mahazars for having done the spot inspection of the works in question.
- 42. In the investigation reports given by Sri. Chandrappa, Assistant Executive Engineer-3, Technical Audit Cell, Karnataka Lokayukta it is clearly mentioned that some of the works inspected by him were not at all executed and the BBMP Engineers present were not able to substantiate the execution of the works and in those places the works which were done 3 or 4 years earlier were found. The investigation reports clearly discloses that the works are not executed as per the estimate/tender specifications, excess measurements have been mentioned in the M.B Books which has resulted in payment for the

work not done and there was substandard asphalt work etc., due to which crores of rupees has been misappropriated in respect of the 114 out of 116 works which were inspected. The investigation reports clearly discloses that the concerned Engineers of the BBMP and KRIDL who have inspected/ dealt with the works in question have made false entries in the concerned registers and bills as if the works have been executed as per tender specifications and allowed the payment to be made and thereby they have caused huge loss to the Government. As stated above some works have not been executed at all and the concerned engineers have not shown the place of work which clearly shows that those works have not been executed at all. As per the reports of the Investigating Officers 10 works alleged in the complaint are repetitions and only 116 works have to be considered in respect of which the payment either in part or full has been released.

- 43. By going through the comments and the documents the following facts are not in dispute:
- i) In respect of 116 works in question the Chief Engineer, TVCC has scrutinised the estimate and the Chief Engineer, R.R. Nagar Zone BBMP has given the technical sanction to the estimates and the officer authorised by BBMP Commissioner has given the Administrative approval and job code numbers are given separately for each work. The Executive Engineer, R.R. Nagar Division, BBMP and Executive Engineer, KRIDL, Bengaluru have entered into agreement regarding entrusting the works in question to KRIDL for execution. The Executive Engineer, R.R. Nagar Division, BBMP has also issued the work order to the Technical Manager, KRIDL to execute the work as per the agreement. The amount of each work is nearly two crores. In the work order the estimate amount is mentioned and it is also stated that it includes GST, KRIDL charges and Cess. The KRIDL

(Government Agency) Engineers have to execute the works and raise the bill and submit the bill to BBMP for payment. The record discloses that the bills have been signed by Respondent number 12 Sri. Chandranath, Assistant Executive Engineer, KRIDL along with the officer in charge of the work. Afterwards the concerned BBMP R.R Nagar Division engineers have inspected the works done to ascertain whether the works have been done as per the estimates or not and also verify the M.B Books written by KRIDL engineers to ascertain whether the works have been done as per the measurements recorded in the M.B Books or not. The bills given by the KRIDL engineers have been verified by the concerned BBMP Engineers. If the work has been done as per the estimates and measurement recorded in the MB books then the bills have to be sent to the Accounts section for payment. The Executive Engineer of KRIDL and Executive Engineer of concerned BBMP division have to check 25% of each work and sign the M.B books in that respect. 10% of the work to be investigated by Chief Engineer, T.V.C.C Cell according to the comments of Respondent number 1 who is the Chief Engineer, T.V.C.C Cell, BBMP Head Office. In the accounts section the statutory deductions have been deducted and the cheques have been issued for the balance amount to the KRIDL to whom the works were entrusted for execution.

44. As per the report given by Superintending Engineer, KRIDL, BBMP 11 works are repetition but as per the investigation reports only 10 works are repetitions. In the said report it is contended that the work mentioned in para 2.43 was not entrusted to KRIDL and Sri. J.D Guruprasad, Assistant Engineer of TAC has also given the report that the said work had not been entrusted to KRIDL. In the report it is stated that in respect of 80 works only the payment has been made but the Investigating Officers have collected the copies of documents to show that in respect of 116 works mentioned in the complaint the

payments have been made either in part or full and hence the contention of KRIDL to the effect that in respect of 80 works only the payment has been made to KRIDL cannot be accepted.

45. The KRIDL has produced the 113 files which contains the copies of the agreement, job number certificate, administrative approval, technical approval, work order, photographs of the work, 3<sup>rd</sup> party reports (Civil Square Consultants), copies of M.B books etc., The Investigating officers have given the xerox copies of the documents in respect of the each of the work inspected by them which contains the copies of contract certificate (bill) which shows the amount including GST, IT etc., paid, measurement sheets signed by the concerned officers including the signature of the engineer who has verified the same, copy of the estimate, copies of the photographs of the work, etc.,

46. As per the investigation reports out of 116 works only two works have been executed as per the tender specification—and in respect of remaining 114 works there is misappropriation of the Government funds. As per the investigation reports in respect of 114 works payment has been made for the works not done and some works have not been executed at all and there is total loss of **Rs. 118,25,79,797/-** to the Government.

47. It is not in dispute that Respondent-7, Sri. Basavaraju, Assistant Executive Engineer Rajarajeshwari Nagara Division, BBMP, Respondent-8 Sri. Siddaramaiah, Assistant Engineer Ward number 129 and 116, Rajarajeshwari Nagara, Respondent-9 Sri. Umcsh, Assistant Engineer and in charge Assistant Executive Engineer, Ward number 83, Laggere Sub Division, BBMP have verified/inspected the works of their respective wards/jurisdiction in respect of the 114 works in question stated above and they have signed the measurement books and the bills fare-having verified/checked the

works done by KRIDL. As per the comments of Respondent no.9 Sri. Umesh has verified the works mentioned in paras 2.01 to 2.05, 2.44 to 2.48, 2.109 to 2.115, 2.118 to 2.126 as Assistant Engineer and also as incharge Assistant Executive Engineer. As per the comments of Respondent no.7 Sri. Basavaraj as Assistant Executive Engineer and Respondent no. 8 Sri. Siddaramaiah as Assistant Engineer have verified all the remaining the works in question namely works mentioned at paras 2.06 to 2.15, 2.17 to 2.31, 2.33 to 2.42, 2.49 to 2.74, 2.77, 2.78, 2.80 to 2.108 and they have signed the measurement books and the bills for having verified and checked the works done by KRIDL. In view of the same it has to be said that they have signed the measurement books and the bills even after knowing that the works are not done as per the estimates and allowed the amount to be paid for the works not done and thereby they are responsible for the excess payment. In their comments the respondents 7 to 9 have contended that the Engineers of KRIDL had supervised the works and after completion of the works bills have been submitted and the quality of the works has been certified by M/s. Civil Square Consultants (3rd party) and KRIDI, had executed the works as per the estimates and they have not committed any misconduct. As stated above even after the works are executed by the KRIDL the respondents 7 to 9 have checked/verified the works done by KRIDL on the basis of the measurement books written by the KRIDL engineers and they have certified that the works have been done as per estimates and that the measurements mentioned in the M.B books are correct which is contrary to the reports of the Investigating Officers. In view of the reports of the Investigating Officers the above said 114 works have not been executed as per the estimates and excess measurements have been recorded in the M.B book ctc., it has to be said that prima facie the respondents 7 to 9 have desired misconduct by falsely

certifying that the works have been done as per the estimates and thereby allowed the payment to be made for the works not done.

48. In the investigation report of Sri. R. Ravishankar, Assistant Executive Engineer-5 it is stated that the concerned Executive Engineer of Rajarajeshwari Nagara Division, BBMP who had also checked the measurements mentioned in the M.B books in respect of the works in question by name Sri. M. Srinivas is dead and hence he is not included in the investigation report.

49. The Respondent number 1 is Sri. Doddaiah, Chief Engineer, T.V.C.C Cell, BBMP Head office and Respondent number 2 is Sri. Satish, Assistant Executive Engineer, T.V.C.C Cell and they have filed their comments contending that the bill for payment online will be made by the concerned Executive Engineers to T.V.C.C Cell and the said cell will verify the files, the quality of the work done and through online further steps will be taken. It is also admitted by them that through the above said cell the files will be put up for payment by sending the same to the Chief Accountant. In another breath they have stated in their comments that the concerned Executive Engineers have to submit the documents online and only in respect of 10% of the works to T.V.C.C office and in respect of the remaining works the file has to be send to the Chief Accountant online and T.V.C.C. will examine only 10% of the works submitted to their office online. Thus respondents 1 and 2 admits that the bills along with other relevant documents to show that work has been done will be submitted to T.V.C.C cell and they have to verify 10% of the works to ascertain whether the works have been done as per the estimates and as per the measurements recorded in the MB books or not. As stated above the estimated amount of each of the work in question is almost two crores and out of 116 works in question in respect of 114 works the payment

has been made for the works not at all done which prima facie shows that respondent 1 and 2 have not at all checked/verified 10% of the work which they have to verify even according to their comments and thereby caused huge loss to the Government. Respondent 1 and 2 contends that the concerned field engineers of KRIDL and the concerned engineers of BBMP wards had certified the measurements and hence the payment has been made. As stated above the investigation reports clearly shows that the measurements entered in the M.B books are not in accordance with the actual work done in the spot and false measurements had been recorded in the M.B books and respondent 1 and 2 have not even cared to inspect 10% of the works out of 114 works stated above to ascertain whether the works have been done as per the measurements recorded in the M.B books or not and thereby there is prima facie dereliction of duty on their part even assuming that they have to verify and inspect 10% of the work as contended by them. Apart from the same the files submitted by the KRIDL contains the copy of the letter written by Commissioner, BBMP to the Managing Director, KRIDL, Bengaluru dated 06.07.2020 wherein it is stated as follows:

" ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಉಲ್ಲೇಖದಲ್ಲಿನ ಟಿಪ್ಪಣಿಯನ್ವಯ ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆಯ ಮೆ ಕೆ.ಆರ್.ಐ.ಡಿ.ಎಲ್ ಸಂಸ್ಥೆಯಿಂದ ಕೈಗೊಳ್ಳಲಾದ ಕಾಮಗಾರಿಗಳ ಭಿಲ್ಲುಗಳ ಪಾವತಿಯನ್ನು ತಡೆಹಿಡಿಯಲಾಗಿತ್ತು, ಮುಂದುವರೆದು ಮೆ ಕೆ.ಆರ್.ಐ.ಡಿ.ಎಲ್ ಸಂಸ್ಥೆಯಿಂದ ಕೈಗೊಳ್ಳಲಾದ ಕಾಮಗಾರಿಗಳ ಪೈಕಿ ಮಾನ್ಯ ಮುಖ್ಯ ಮಂತ್ರಿಗಳ ನವನಗರೋತ್ಥಾನ ಅನುದಾನದಡಿಯಲ್ಲಿ ಅನುಷ್ಠಾನಗೊಳಿಸಲಾಗುತ್ತಿರುವ/ಅನುಷ್ಠಾನಗೊಳಿಸಿರುವ 269 ಕಾಮಗಾರಿಗಳ, ಸ್ಥಳ ತಪಾಸಣೆ ನಡೆಸಿ ವರದಿ ನೀಡಲು ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆಯ ತಾಂತ್ರಿಕ ಮತ್ತು ಜಾಗೃತ ಕೋಶಕ್ಕೆ ವಹಿಸಿ, ವರದಿ ಪಡೆಯಲಾಗಿರುತ್ತದೆ."

Thus, the KRIDL also admits that the works in question are included in the above said 269 works and hence it can be said that T.V.C.C cell of BBMP had also inspected the works in question and

given the report to the effect that the works are done even though the works have not been done as per the measurements mentioned in the M.B books and some works are not executed at all and there is prima facie material to show that the false report has been given by T.V.C.C and thereby Respondents 1 and 2 have committed misconduct. Respondent 1 is the Chief Engineer and respondent number 2 is the Assistant Executive Engineer of Technical Vigilance Cell under Commissioner, BBMP head office. The said cell has been established to expose the financial scams/irregularities in BBMP but they have failed in their duty by allowing the payment to be made for the works not done by KRIDL as stated above. In other words the said cell has been established to see that the amount of BBMP is not misused but the said cell has also allowed the payment to be made to the KRIDL for the works not at all done.

50. Respondent-3 is Sri. Vijayakumar, Chief Engineer, R.R. Nagar Zonal office, BBMP, Bengaluru. He has contended in his comments that the execution of works and examination of quality is the duty of the concerned Assistant Engineer and Assistant Executive Engineer and the Executive Engineer has to examine the bills submitted by the Assistant Executive Engineer and recommend for payment. It is further contended that the Chief Engineer gives only the technical sanction to the works and the works have to be executed as per the estimates and it is the duty of the concerned Engineers to see that the works are done as per the estimate and he has not committed any misconduct. Only one of the Investigating Officer by name Sri. R. Ravishankar, Assistant Executive Engineer-5 has taken the name of the 3<sup>rd</sup> respondent as one of the officer responsible for the loss caused to the Government in respect of some of the works inspected by him (drain works) whereas the other four engineers of Technical Audit Cell have not named the 3rd respondent in their report. Sri. R. Ravishankar

has stated in his report in respect of work stated in para 2.06 as follows:

"....ಆರೋಪಿಸಿರುವಂತೆ ಎದುರುದಾರರು ಅಂದಾಜು ಪಟ್ಟಿಯಲ್ಲಿ item no.5 ರಲ್ಲಿ Poviding ruled pointing to coursed stone masonry with cement mortar--- for flagging course ಎಂಬ item ಅನ್ನು ಅಳವಡಿಸಿಕೊಂಡಿರುತ್ತಾರೆ. Item no. 4ರಲ್ಲಿ Providing and constructing load bearing wall with concrete solid blocks---for flagging course ಎಂಬ item ಅನ್ನು ಅಳವಡಿಸಿಕೊಂಡಿರುತ್ತಾರೆ. ಆದರೆ concrete solid blocks ಗಳಿಂದ ನಿರ್ಮಿಸಿರುವ flagging course ಗಳಿಗೆ ಮಾಡಬೇಕಾಗಿರುವ ruled pointing item ಅನ್ನು ruled pointing to coursed stone masonry ಎಂಬ item ನಲ್ಲಿ ಪರಿಗಣಿಸಿರುವುದು ತಪ್ಪಾಗಿರುತ್ತದೆ ಎಂದು ಅಭಿಪ್ರಾಯ ಪಡಲಾಗಿದೆ. ಹಾಗಾಗಿ ಸದರಿ ನ್ನು ಅಂದಾಜು ಪಟ್ಟಿಯಲ್ಲಿ ಅಳವಡಿಸಿಕೊಂಡು ಮತ್ತು ಸದರಿ item ಗೆ ತಾಂತ್ರಿಕ ಅನುಮೋದನೆ ನೀಡಿರುವುದು ಶ್ರೀ ವಿಜಯ್ಕಮಾರ್, ಮುಖ್ಯ ಅಭಿಯಂತರರು, ರಾಜರಾಜೇಶ್ವರಿ ನಗರ ವಲಯ ಕಛೇರಿ, ಬಿ.ಬಿ.ಎಂ.ಪಿ ಬೆಂಗಳೂರು ರವರ ಕರ್ತವ್ಯ ಲೋಪವಾಗಿರುತ್ತದೆ ಎಂದು ಸಹ ಅಭಿಪ್ರಾಯ ಪಡಲಾಗಿದೆ.

The 3<sup>rd</sup> respondent in his reply to the investigation report has given his reply as follows:

"…ಆದರೆ, ಸಾಲಿಡ್ ಬ್ಲಾಕ್ಗಳಿಂದ ನಿರ್ಮಿಸಿರುವ ಪ್ಲಾಂಗಿಂಗ್ ಕೋರ್ಸ್ಗೆ ಅವಶ್ಯವಿರುವ ಪಾಯಿಂಟಿಂಗ್ ಅಂಶದ ಯಾವುದೇ ಇಲಾಖೆಯ ದರಪಟ್ಟಿಯಲ್ಲಿ ಲಭ್ಯವಿಲ್ಲದೇ ಇರುವುದರಿಂದ ಹಾಗೂ ಸ್ಥಳದ ಪರಿಸ್ಥಿತಿಗೆ ಅನುಗುಣವಾಗಿ ಪಾಯಿಂಟಿಂಗ್ ಅಂಶವನ್ನು ಅಳವಡಿಸಿಕೊಳ್ಳುವುದು ಅವಶ್ಯವಾಗಿದ್ದ ಕಾರಣ ಯೋಜನಾ ಸಮಾಲೋಚಕರು ಸಾಲಿಡ್ ಕಾಂಕ್ರೀಟ್ ಬ್ಲಾಕ್ ನಗೋಡೆಯಂತೆಯೇ ನಿರ್ಮಿಸಲಾಗುವು ಕೋರ್ಸ್ಡ್ ಸ್ಟೋನ್ ಮೇಸ್ಪರಿಗೆ ಸಂಬಂಧಿಸಿದ ಸಮಾನಾಂತರ ಪಾಯಿಂಟಿಂಗ್ ಅಂಶವನ್ನು (Equivalent pointing item) ಅಳವಡಿಸಿಕೊಂಡು ಅಂದಾಜುಪಟ್ಟಿಯನ್ನು ತಯಾರಿಸಿದ್ದು, ಸದರಿ ಅಂದಾಜುಪಟ್ಟಿಗಳನ್ನು ಸಂಬಂಧಿಸಿದ ಸಹಾಯಕ ಅಭಿಯಂತರರು, ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು ಮತ್ತು ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು ದೃಢೀಕರಿಸಿ ತಾಂತ್ರಿಕ ಮಂಜೂರಾತಿಗಾಗಿ ಸಲ್ಲಿಸಿರುತ್ತಾರೆ. ಸಹಾಯಕ ಅಭಿಯಂತರರು, ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ ಶಿಫಾರಸ್ಸಿನಂತೆ ಸದರಿ ಅಂದಾಜುಪಟ್ಟಿಗಳಿಗೆ ತಾಂತ್ರಿಕ ಮಂಜೂರಾತಿ ನೀಡಲಾಗಿರುತ್ತದೆ. ಆದುದರಿಂದ ತಾಂತ್ರಿಕ ಮಂಜೂರಾತಿ ನೀಡಲಾದಿರುತ್ತದೆ. ಆದುದರಿಂದ ತಾಂತ್ರಿಕ ಮಂಜೂರಾತಿ ನೀಡಿರುವಲ್ಲಿ ಯಾವುದೇ ರೀತಿಯ ಕರ್ವವಲೋಪತ್ಪಾಗಿರುತ್ತದೆ.

30

There is no allegation in the complaint that there was defect in the tenders in respect of the drain works in question and the 3rd respondent is responsible for the same. It is also not stated in the investigation report of Sri. R. Ravishankar that there is any loss caused to the Government in view of the technical approval given by the respondent 3 to the estimates regarding the drain works. As already stated above there is no complaint also to the effect that Respondent 3 has committed misconduct while giving technical sanction to the estimates regarding drain works. Hence, there is no prima facie material to proceed against Respondent 3.

51. Respondent number 4 Smt. Shilpa, Assistant Engineer office of Chief Engineer, BBMP, respondent number 5 is Sri. Mohan, Executive Engineer Rajarajeshwari Nagara Project Division, BBMP respondent number 6 is Smt. Bharathi Assistant Executive Engineer and T.A Executive Engineer office, Rajarajeshwari Nagara Project Division, have filed their comments contending that they have not at all executed nor supervised any of the works in question. As stated above respondent 4 has contended that she is working as Assistant Engineer (T.A) in the office of CE, Rajarajeshwari Nagara zone, and she has not verified or supervised any of the works in question. There is no document to show that respondent number 4 has signed the M.B book or the bill. There is no document to show that she has given any report after verifying any of the work in question. As stated above respondent 5 and 6 are working in project division and they have not supervised nor executed any of the work in question. Hence, there is no prima facie material so far as respondents 4 to 6 are concerned in respect of the loss caused to the Government and there is no prima facie material to proceed against them further.



52. Respondent number 10 is Smt. Anitha, Superintendent and Cashier and Respondent number 11 is Sri. Guligowda, Deputy Manager, Rajarajeshwari Nagara division, BBMP. Respondent 10 has contended that she is working as First Division Account Assistant and in charge Accounts Superintendent from 01.02.2020 and her duty is only to examine the bills, deduct the statutory deductions from the bill amount and credit the remaining amount to the concerned section online and after the payment is made to the contractor to mention the same in the accounts book and she is nowhere concerned with the execution of the works in question. Respondent 11 has contended that he is also not concerned with the execution or supervision of the works concerned and he is working as Draft man/Assistant Engineer in the office of the Executive Engineer and he is in nowhere concerned to the works in question. In the complaint it is not contended that respondent number 10 and 11 have not scrutinised the bills as per rules and that they have made excess payment or not deducted the statutory deductions. When the bills are signed by all the concerned Engineers and the same is submitted along with all the required documents like copies of M.B Books, 3rd party inspection report etc., the respondents 10 and 11 have to pass the bills and no misconduct can be attributed to them. Hence, it has to be said that no prima facie case of misconduct is made out in respect of respondents 10 and 11.

53. Respondent number 12 is Sri. Chandranath, Assistant Executive Engineer, KRIDL and respondent number 13 is Sri. Srinivas Executive Engineer KRIDL. The records produced by KRIDL discloses that the agreement is signed by the Executive Engineer-3 on behalf of KRIDL as second party. The record further discloses that the contract certificate/bill has been signed by Sri. Chandranath as Assistant Executive Engineer, KRIDL in the place of the contractor. Even the measurement sheet is signed by the above said Sri. Chandranath. The

מסא ארסני.

respondent 12 and 13 have contended in their reply to the investigation reports that all the works in question have been executed satisfactorily as per tender specification but the Investigation reports prima facie shows that the respondents 12 and 13 have not executed the works as per the tender specifications and even then submitted the bills as if the works have been carried out as per tender specifications and received the amount for the work not done and thereby there is prima facie material against them for misconduct in causing loss to the Government.

54. Respondent number 14 is Smt. Venkatalakshmi and respondent number 15 is Sri. Sreetej, Assistant Executive Engineer and Assistant Engineer respectively of T.V.C.C and they admits in their reply to the investigation reports that they have inspected some of the works in question separately as per the instructions of Chief Engineer, T.V.C.C and given their reports. As per their reply respondent number 14 has given her report in respect of the works mentioned in paras 2.50, 2.51, 2.54, 2.55, 2.56, 2.60, 2.61, 2.62, 2.65, 2.67 to 2.70, 2.72, 2.81, 2.85, 2.89, 2.93 to 2.95, 2.102, 2.108 and respondent number 15 has given his report in respect of the works mentioned in paras 2.01 to 2.05, 2.06, 2.11, 2.12, 2.13, 2.15, 2.17, 2.19 to 2.24, 2.28, 2.29, 2.33 to 2.39, 2.41, 2.73, 2.77, 2.78, 2.110, 2.119, 2.123 to 2.125 to the effect that the works have been executed as mentioned in the M.B book and payment can be made. As already stated above the investigation reports discloses that the works have not been done as per the measurements mentioned in the M.B book and excess amount has been paid to KRIDL. When the works are not in accordance with measurements recorded in the M.B books it has to be said that respondent 14 and 15 have prima facie given false reports as if the works have been completed as per the measurements mentioned in the M.B books and as per the troubs specification which amounts to

misconduct which has resulted in excess payment to KRIDL for the works not at all done. The respondents 14 and 15 have contended that the defect liability period is not yet started and in case there are lapses it can be set right in the defect liability period. The above said contention of the respondents 14 and 15 cannot be given any weight and the same does not give any authority for respondents 14 and 15 to give the report to the effect that the works have been done as per the measurements recorded in the M.B books and as per the estimates which has resulted in loss of crores of rupees to the Government.

55. In the files submitted by KRIDL copies of some photographs are produced to show that those photographs are taken when the works were being carried out and that all the works have been carried out. Only on the basis of the photographs it cannot be said that the works have been executed as per the estimates and as per the measurements mentioned in the M.B book. In the report given by Superintending Engineer, KRIDL, BBMP range, Bengaluru it is stated that in respect of 28 works the amount is not released from BBMP. The KRIDL has not produced any documents to show that no payment is made in respect of the 28 works in question (either first bill or full amount). On the other hand the Investigating Officers have collected the copies of the bills in respect of all the 116 works in question to show that the payment either in part or full has been released already and calculated the loss caused to the Government on that basis only. Hence, the contention of the KRIDL to the effect that in respect of 28 works mentioned in their report the amount has not been released cannot be accepted at this stage.

56. The files produced by KRIDL discloses that Civil Square Consultants have given the test reports as if all the works in question have been done in accordance with the tender specification (quality)

which is false in view of the investigation reports and the lab reports produced along with the investigation reports. Hence, it has to be said that Civil Square Consultants has blindly given the 3<sup>rd</sup> party inspection report without verifying the quality of any of the work in question in respect of any aspect either concrete cubes or reinforcement of steel, etc., Hence, BBMP and KRIDL should take steps to immediately black list Civil Square Consultants (Civil Engineering Consultants, 3<sup>rd</sup> party inspection, PMC, Material testing laboratory) and remove the said name from the approval list of 3<sup>rd</sup> party inspection in respect of BBMP and KRIDL works and also in respect of any civil works of the State of Karnataka.

57. The reports of the Investigating Officers discloses that 10 works mentioned in the complaint are repetitions and those works are mentioned in paras 2.32, 2.74, 2.75, 2.76, 2.79, 2.109, 2.116, 2.117, 2.118, 2.121. In respect of the remaining 116 works the investigation officers have given their reports. Sri. Guruprasad J.D Investigating Officer has given the report that there are no lapses in respect of execution of the works at para 2.42 and 2.43. The investigation reports shows that the remaining 114 works have not been executed as per the estimates and excess measurements are noted in the M.B books and there is substandard asphalt work due to which totally the Government has sustained loss of Rs.118,25,79,797/- and the said amount is the excess payment made to KRIDL for the works not done and for the reasons stated above the respondents 1, 2, respondents 7 to 9 and respondents 12 to 15 are prima facie liable for the excess payment and there is no material to proceed further in respect of respondent 3 to 6 and 10 and 11.

58. The investigation reports highlights the connivance the public servants referred to above in raising the bills and allowing the





payments also for the works not executed and also regarding substandard works which is a matter of serious concern.

- 59. Since detailed discussion of the investigation reports with reference to the culpability of each of the respondents referred to above is likely to cause prejudice to them in the course of regular enquiry I desist from discussing at greater details the misconduct committed by each of the respondents referred to above.
- 60. Since the above facts and materials on record prima facie show that Respondent-1 Sri. Doddaiah, Chief Engineer, T.V.C.C Cell, BBMP Head Office, N.R Square, Bengaluru Respondent-2 Sri. Sathish, Assistant Executive Engineer, T.V.C.C Cell, BBMP Head Office, N.R Square, Bengaluru Respondent-7 Sri. Basavaraj, Executive Engineer, In-charge Assistant Executive Engineer, Rajarajeshwari Nagara Sub-Division, BBMP, Bengaluru Respondent-8 Sri. Siddaramaiah, Assistant Engineer, Ward No. 129 and 160, Rajarajeshwari Nagara Sub-Division, BBMP, Bengaluru Respondent-9 Sri. Umesh, Assistant Executive Engineer, I/c Assistant Engineer, Ward No. 73, Laggere Sub Division, BBMP, Bengaluru Respondent-12 Sri. Chandranath, Assistant Executive Engineer, KRIDL, Ananda Rao Circle, Bengaluru Respondent-13 Sri. Srinivas, Executive Engineer, KRIDL. Ananda Rao Circle, Bengaluru, Respondent-14 Smt. Venkatalakshmi, Assistant Executive Engineer, T.V.C.C Cell, BBMP, Bengaluru, Respondent-15 Sri. Shreetej, Assistant Executive Engineer, T.V.C.C Cell, BBMP, Bengaluru being public/Government servants have committed misconduct as per rule 3 (1) (i) to (iii) of the KCS (Conduct) Rules, 1966 and now, acting under section 12(3) of the Karnataka Lokayukta Act, 1984, recommendation is made to the Competent Authority to initiate disciplinary proceedings against the above said respondents 1, 2, 7, 8, 9, 12 to 15 and to entrust the inquiry to this Authority under Rule 14-A of the Karnataka Civil Services (Classification, Control and Appeal) Rules, 1957.
- 61. Having regard to the facts and electron stances of the case in addition to the recommendation made at paragraph 60 above and prima-facie serious

TU!

lapse committed in execution of the work entrusted to KRIDL by BBMP and also in monitoring the said work by the concerned public servants of the BBMP, I am of the view it is desirable to make a recommendation to the Government and BBMP with a view to prevent pilferage misappropriation of public funds and also to provide quality execution of the work which is intended to be executed for the benefit of the public to consider the following:-

- Desirability of not entrusting any infrastructural development work/other works required to be executed by the BBMP to KRIDL.
- 2. To consider constituting special committee of experts with a high ranking public servant as its Chairman to make a sample survey of 10% of the work executed or being executed by the KRIDL which has been entrusted to it for the last two years by BBMP or in the alternative to consider making a reference by the Government in exercise of its power under Section 7(2A) of Karnataka Lokayukta Act, 1984 to the Lokayukta to get all the works entrusted to KRIDL by BBMP which are already executed within a period of two years or in the process of execution investigated in the interest of justice.
- 62. Further, as prescribed in section 12(4) of Karnataka Lokayukta Act 1984, the Competent Authority to intimate this authority within two months from the date of receipt of this report, about the action taken or proposed to be taken on this report against the persons referred above as respondents 1, 2, 7, 8, 9, 12 to 15.

Annexure-A is also enclosed and it forms part of this report.

Connected records are enclosed.

VISHWANATHA SHETTY

Lokavukta,

State of Karnataka.

			ANNEXURE-A	Amount	Officers/Officials
Name of the work		Date of inspection	Findings of the I.O	misappropriated in Rs.	responsible
Investigation Officer: Sr	er: Sri f	R. Ravishanke	i R. Ravishankar, Assistant Executive Engineer-5, T	AC, Karnataka Lo	TAC, Karnataka Lokayukta, Bengaluru
Improvements and maintenance to drains in Gattigere Extension, Basaveshwara Badavane, Gattigere Badavane and surrounding areas in Rajarajashwari nagara ward	aintenance Extension, Badavane, ne and as in	24.11.2020	Bills were prepared and payments made for the works which were not executed. Excess measurements were found to have been recorded in the M.B. book and excess amount being paid by the	85,33,498.00 *	1. Sri Vijaykumar, Chief Engineer, Rajarajeshwarinagar Zonal Office, B.B.M.P.,
90 pg	06 of		concerned officers are held responsible.  (Details of excess measurements and excess payment are shown in the investigation report)		2. Sri M. Siddaramaiah, Assistant Engineer, Ward No. 160, Rajarajeshwarinagar Sub- division, B.B.M.P.,
1)	8	) )		1 V	3. Sri Basavaraj, Assistant Executive Engineer, Rajarajeshwarinagar Sub-
				X	division, B.B.M.P. Bengaluru. 4. Officers of K.R.I.D.L.
Improvements and maintenance to drains 2 <sup>rd</sup> main and 60 feet roac in Dwaraka Layout BEML	nance ) feet SEML	30.11.2020	Bills were prepared and payments made for the works which were not executed. Excess measurements were found to have	1,12,32,667.00	1. Sri Vijaykumar, Chief Engineer, Rajarajeshwarinagar Zonal Office,
Rajarajeshwarinagar in No. 160. J.C.No. 160-20-000046	Ward	: p	been recorded in the M.B. book and excess amount being paid by the concerned officers are held responsible.	9 9	B.B.M.P.; Bengaluru. 2. Sri M. Siddaramaiah,
(Work mentioned in para 2.07 this note)	0 70.	ol	(Details of excess measurements and excess payment are shown in	.,	Ward No.160, Rajarajeshwarinagar Sub-

LOU AND /

39

	4.				ω				No.	
main, 11 main road & mavintopu surrounding roads at BEML 5th stage in Rajarajeshwarinagara in Ward No.160  J.C.No.160-20-000060	Improvements to roads in 10 <sup>th</sup>		(Work mentioned in para 2.13 of this note)	Kempegowda Jowdi Road and surrounding area in Rajarajeshwari nagara in Ward No.160.  J.C. No.160-20-000044	Improvements to roads in			8	Name of the work	
	22.12.2020				24.12.2020	:			Date of inspection	
excess in the I ount paid a k carried c	Bills were prepared and powerate	inconganon report)	(Details of the same mentioned in the		Bills were prepared and parents			the investigation report)	Findings of the I.O	AMME AORE: A
1,30,32,911.00				1,04,70,004,00			•		Amount misappropriated in Rs.	
Assistant Engineer, Ward No. 160, Rajarajeshwarinagar Subdivision, B.B.M.P, Bengaluru. 2. Sri Basavaraj, Assistant Executive Engineer		2. Sri Basavaraj, Assistant Executive Engineer, Rajarajeshwarinagar Sub-	Bengaluru	1. Sri M. Siddaramaiah, Assistant Engineer Ward No 160, Rajarajeshwarinagar Sub- division, B.B.M.P.	4 Chicers of R. R. I.D. C		3. Sri Basavaraj,	division, B.B.M.P Bengaluru	Officers/Officials responsible	



tong not

		Data at			Amount	Official Official
Name of the work inspection		Date o inspection	- on	Findings of the I.O	misappropriated in Rs	Oncers/Onicials responsible
			ΠÍ			
(Work mentioned in para 2.11 of this note)	n para 2.11 of			investigation report)		Rajarajeshwarinagar Subdivision, B.B.M.P., Bengaluru, 3. Officers of K.R.I.D.L
Improvements and maintenance 01.12.2020 to drains in ideal homes township in Rajarajeshwarinagar in ward No.160. J.C.No.160-20-000079. (Work mentioned in para 2.08 of this note)		01.12.2020		Bills were prepared and payments made for the works which were not executed, excess measurements mentioned in the M.B book and excess amount paid and substandard asphalt work carried out.  (Details of the same mentioned in the investigation report)	89,70,590.00	1.Sri Vijayakumar, Chief Engineer, Rajarajeshwarinagar Zonal Office, B.B.M.P., Bengaluru. 2.Sri M.Siddaramaiah, AE 3.Sri Basavaraj, AEE, RR Nagar Division, BBMP, Bengaluru.
Improvements and maintenance to drains 7 <sup>th</sup> Main and 9 <sup>th</sup> Main road in Dwaraka layout, BEML Layout and surrounding area in Rajarajeshwarinagar in Ward No.160.  J.C.No.163-20-000047.  (Work mentioned in para 2.10 of this note)		02.12.2020		Bills were prepared and payments made for the works which were not executed, excess measurements mentioned in the M.B book and excess amount paid and substandard asphalt work carried out.  (Details of the same mentioned in the investigation report)	81,13,677.00	1.Sri Wjayakumar, Chief Engineer, Rajarajeshwarinagar Zonal Office, B.B.M.P., Bengaluru, 2.Sri M.Siddaramaiah, AE 3.Sri Basavaraj, AEE, RR Nagar Division, BBMP, Bengaluru.
Improvements and maintenance 04.12.2020 B to drains in Gattigere Badavane and surrounding area in Rajarajeshwari nagara Ward No. 60.  J.C.:No.160-20-000054.	enance 04.12.2020 davane sa in Ward			Bills were prepared and payments made for the works which were not executed, excess measurements mentioned in the M.B book and excess amount paid and substandard asphalt work carried out.	1,01,89,813.00	1.Sri Vijayakumar, Chief Engineer, Rajarajeshwarinagar Zonal Office, B.B.M.P., Bengaluru, 2.Sri M.Siddaramaiah, AE

ANNEXURE-A

3

	ā	5	Ċ			ω .	No.	
	with overments and maintenance to drains in BEML Extension, Srinivasa block and surrounding areas in Rajarajeshwarinagara Ward No.160.  J.C.No.160-20-000055  (Work mentioned in para 2.19 of this note)	(Work mentioned in para 2.20 of this note)	cross road and surrounding areas at BEML 5 <sup>th</sup> stage in ward No. 160.  J.C.No.160-20-000059.		Horizon School road and surrounding areas at BEML 5 <sup>th</sup> Stage in Ward No.160 J.C.No.160-20-000058. (Work mentioned in para 2.12 of this note)	(Work mentioned in para 2.18 of this note)	Name of the work	
	05.12.2020	# 10 mm	24.12.2020		rv. 1c.7020	23 12 20 20 1	Date of inspection	
	Bills were prepared and payments made for the works which were not executed. Excess measurements were found to have been recorded in the M.B. book and excess amount being paid by the concerned officers are held responsible.  (Details of excess measurements and excess payment are shown in	Substandard asphalt work carried out.  (Details of the same mentioned in the investigation report)		(Details of the same mentioned in the investigation report)	payments made for the works which were not executed, excess measurements mentioned in the M.B. book and excess amount paid and substandard asphalt work carried out.	Bi of	Findings of the I.O	ANNEXURE-A
	85,83,312.00		1,15,47,370.00		1,02,17,634.00		Amount misappropriated in Rs.	
Bengaluru.	1.Sri Vijayakumar, Chief Engineer, Rajarajeshwarinagar Zonal Office, B.B.M.P., Bengaluru. 2.Sri M.Siddaramaiah, AE 3.Sri Basavaraj, AEE, RR Nagar Division, BBMP.		1.Sri M.Siddaramaiah, AE 2.Sri Basavaraj, AEE 3.Officers of K.R.I.D.L		1.Sri M.Siddaramaiah, AE 2.Sri Basavaraj, AEE 3.Officers of K.R.I.D.L	3. Sri Basavaraj, AEE, RR Nagar Division. BBMP, Bengaluru.	Officers/Officia's responsible	

# Corocood

1			ANNEXURE-A			1
No.	Name of the work	Date of inspection	Findings of the I.O	Amount misappropriated in Rs.	Officers/Officials responsible	350
			the investigation report)		4. Officers of K.R.I.D.L	1 1
	¥.	y				
7	12		Bills were prepared and payments made for the works which were not	1,02,42,555.00	1.Sri Vijayakumar,	l.
	BEML Layout and surrounding area in Rajarajeshwarinagara Ward No.160.	10.12.2020	executed. Excess measurements were found to have been recorded in the M.B. book and excess amount being paid by the concerned officers are held responsible.	1	Cnief Engineer, Rajarajeshwarinagar Zonal Office, B.B.M.P., Bengaluru.	m
	(Work mentioned in para 2.16 of this note)		(Details of excess measurements and excess payment are shown in the investigation report)		<ul><li>2.5ri M. Siddaramalah, AE</li><li>3.Sri Basavaraj, AEE, RR</li><li>Nagar Division, BBMP,</li><li>Bengaluru.</li><li>4. Officers of K.R.I.D.L</li></ul>	
12.	mprovements and maintenance	10 19 2020				
	to drains 1st and 2nd cross in Dwarka Layout BEML Layout and surrounding area in Rajarajeshwarinagara Ward No.160.	11.12.2020	Bills were prepared and payments made for the works which were not executed. Excess measurements were found to have been recorded in the M.B. book and excess amount being paid by the concerned officers	99,10,655.00	1.Sri Vijayakumar, Chief Engineer, Rajarajeshwarinagar Zonal Office, B.B.M.P., Bengaluru.	
	(Work mentioned in para 2.17 of		are held responsible.		3.Sri Basavaraj, AEE, RR	
	rnis note)		(Details of excess measurements and excess payment are shown in the investigation report)		Nagar DINISION, BBMP, Bengaluru. 4. Officers of K.R.I.D.L	
Soco						
oar,					5	1

				*				8								0.																•				
			-				5												14												ō	3	No.	<u>s</u>		
	(Work mentioned in para 2.24 of this note)	J.C.No.160-20-000068	No.160.	ajeshwarina	at B≘ML	swamy temple surrounding	ents an		500000000000000000000000000000000000000	this note)	(Work mentioned in para 2.25 of		I C No. 160-20-000093		arinagara in Wa	surrounding area in	besides in Sai Lotus Layout and	to 1st main road RNS college	Improvements and maintenance					this rote)	owor≺ mentioned in para 2.21 of		.1 C No 180-20-000085	Ward No 160	stage in Rajarajashwarinagara	Surrounding proper BEMI Ath	at oth cross roa	la servición de la servición d		Name of the work		
						18.12.202C	17.12.2020								•	1			16.12.2020						1					15 10 2020		14 12 2020	napoconon	Date of		
and excess payment are shown in	(Details of excess measurements	being paid by the concerned officers are held responsible.	the M.B. book and excess amount	d to have b	executed. Excess measurements	made for the works which were not	were prepared and	the investigation report)	ess	(Details of excess measurements		are held responsible.	being paid by the concerned officers	the M.B. book and excess amount	d to have b	executed. Excess measurements	made for the works which were not	Bills were prepared and payments		tion report)	and excess payment are shown in	(Details of excess measurements		ίn		excess amount being paid by the	been recorded in the M.B. book and	urements were found t	were not executed. Excess	made for the works w	Bills were crepared and			Findings of the I.O		ANNEXURE-A
						(a)	74,32,128.00				2	7.5							99,33,042.00								10					92.51.239.00	in Rs.	misappropriated	Amount	
of KRIDL/	Nagar Division, BBMP, Bengaluru.		Bengaluru.	B.B.M.P.,	Office,	Rajarajeshwarinagar Zonal	1.Sri Vijayakumar, Chief Engineer		4. Officers of K.R.I.D.L	Bengaluru.	Nagar Division, BBMP,	3.Sri Basavaraj, AEE, R२	2.Sri M.Siddaramaiah, AE	Bengaluru.	B.B.M.P.,	Office,	Rajarajeshwarinagar Zonal	Chief Engineer,	1.Sri Vijayakumar,		Til	4. Officers of K.R.I.D.L	Bengaluru.	Nagar Division, BBMP,	3.Sri Basavaraj, AEE, RF	2.Sri M.Siddaramaiah, AE	Bengaluru.	B.B.M.P.,	Office,	Rajarajeshwarinagar Zonal	Chief Engineer	1. Sri Viiavakumar		responsible	Officers/Officials	

(Details of excess measurements and excess payment are shown in

4. Officers of K.R.I.D.L,

ಕರ್ನುಟಕ

300 KOD

				ANNEXURE-A		
	S. No.	Name of the work	Date of inspection	e 1.0	Amount misappropriated in Rs.	Officers/Officials responsible
,		<b>6</b>		the investigation report)	**	
-	16	Improvements and maintenance to drains 1st main road, 8th main roac surrounding roads at BEML 5th stage in Rajarajeshwarinagara Ward No.60.	18.12.2020 19.12.2020 8 21,12.2020	Bills were prepared and payments made for the works which were not executed. Excess measurements were found to have been recorded in the M.B. book and excess amount being paid by the concerned officers are held responsible.	77,37, 875.00	1.Sri Vijayakumar, Chief Engineer, Rajarajeshwarinagar Zonal Office, B.B.M.P., Bengaluru. 2.Sri M.Siddaramaiah, AE
		(Wor≺ mentioned in para 2.22 of this rote)	9	(Details of excess measurements and excess payment are shown in the investigation report)	59	3.Sri Basavaraj, AEE, RR Nagar Division, BBMP, Bengaluru. 4. Officers of K.R.I.D.L
2 m	17.	Improvements and maintenance to drains prampd layout, Raghavendraswamy temple and surrounding areas in Rajarajeshwarinagar Ward No. 150.	28.12.2020 & 30.12.2020	Bills were prepared and payments made for the works which were not executed. Excess measurements were found to have been recorded in the M.B. book and excess amount being paid by the concerned officers are held responsible.	77,40,537.00	1.Sri Vijayakumar, Chief Engineer, Rajarajeshwarinagar Zonal Office, B.B.M.P., Bengaluru. 2.Sri M.Siddaramaiah, AE 3.Sri Basavaraj, AEE, RR
# Jan Car		(Work mentioned in para 2.23 of this note)	16 E c	(Details of excess measurements and excess payment are shown in the investigation report)		Nagar Division, BBMP, Bengaluru. 4. Officers of K.R.I.D.L



	The investigation report			
4. Officers of K.R.I.D.L	and excess payment are shown in			
Bengaluru	(Details of excess measurements		this note)	
3.Sri Basavaraj, AEE,	are rield responsible.		(Work mentioned in para 2.28 of	
2.Sri M.Siddaramaiah, AE	are held responsible		0.140.	
	the M.B. book and excess amount		.1 C No. 160-20-000086	
	were found to have been recorded in		in Rajarajeshwarinagara in Ward	
	executed. Excess measurements		Badavane and surrounding area	,
	the works	05.01.2021	in Kalegowda Iayout & Kampada	
1,03,19,339.00	Bills were prepared and payments	04.01.2021 &	to 1 <sup>st</sup> main road & 4 <sup>th</sup> main road	
	the investigation report)			3
	and excess payment are shown in			1
	(Details of excess measurements		7	
	200 - CO		this note)	
	are held responsible		(Work mentioned in para 2.26 of	20
	the M.B. book and excess amount		J.C.No.160-20-000084	
	were found to have been recorded in		No.160.	
	executed. Excess measurements		in Rajarajeshwarinagara in Ward	
		06.01.2021	cross road and surrounding area	
1,07,25,372,00	Bills were prepared and payments	Ø	to BEML 2 <sup>nd</sup> cross road, 2rd	9
100	the litrestigation report)	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Improvements and mointenage	0
	and excess payment are shown in			
	(Details of excess measurements		this note)	
			(Work mentioned in para 2.27 of	
	are held responsible.			
	being paid by the concerned officers		J.C.No.160-20-000089	
	the M.B. hook and excess amount		No.160.	T#
	war found to have been constant in		warinagara Wa	
	executed Excess measurements	01.01.2021	road and surrounding area in	
	made for the works which were not	01 01 2021	Thirtichi Mahaswamy 80 ft main	
94,62,299.00	Bills were prepared and payments	31.12.2020 &	Improvements and maintenance to K.K.Mahesh PU college road	ά
misappropriated in Rs.	Findings of the :.U	inspection	Name of the work	No.
Amount	1	Date of		2
	ANNEXURE-A			

ಕರ್ನಾಟಕ

S. S.	Name of the work	Date of inspection	Findings of the I.O	Amount misappropriated in Rs.	Officers/Officials responsible
				00 70 884 00	1 Sri Vijavakumar
21	Improvements and maintenance to drains E <sup>th</sup> main road & surrounding areas BEML 5 <sup>th</sup> stage and surrounding area	06.01.2021 & 08.01.2021	Bills were prepared and payments made for the works which were not executed. Excess measurements	00:+00	Chief Engineer, Rajarajeshwarinagar Zonal Office, B.B.M.P.,
	in Rajarajeshwarinagara in Ward No.160. J.C.No.160-20-000063	ě.	were found to have been recorded the M.B. book and excess amount being paid by the concerned officers are held responsible.		Bengaluru. 2.Sri M.Siddaramaiah, AE 3.Sri Basavaraj, AEE, RR
	(Work mentioned in para 2.14 of this note)		(Details of excess measurements and excess payment are shown in the investigation report)		Bengaluru. 4. Officers of K.R.I.D.L
22	Improvements and maintenand to drains in ideal home	te 11.01.2021	Bills were prepared and payments made for the works which were not	89,72,700.00	T.Sit vljayakuna., Chief Engineer, Rajarajeshwarinagar Zonal
	surrounding area in Ward No.160.	E 5	executed. Excess measurements were found to have been recorded in the M.B. book and excess amount being paid by the concerned officers are held responsible.	ž	B.B.M.P., Bengaluru. 2.Sri M.Sidaramaiah, AE 3.Sri Basavaraj, AEE, RR
80	(Work mentioned in para 2.09 this note)	of	(Details of excess measurements and excess payment are shown in the investigation report)		Nagar Division, power, Bengaluru. 4. Officers of K.R.I.D.L
N N	23. Improverrents and maintenance to Shaneshwara swamy temple road, Subhashchandra Nagar BEML Layout and surrounding	ar ng	Bills were prepared and payments made for the works which were not executed. Excess measurements executed to have been recorded in	1,06,03,396.00	1.Sri Vijayakumar, Chief Engineer, Rajarajeshwarinagar Zonal Office, B.B.M.P.,
	area in Rajarajeshwari nagara Ward No.160. J.C.No.160-20-000088		the M.B. book and excess amount being paid by the concerned officers are held responsible.		Bengaluru. 2.Sri M.Siddaramaiah, AE 3.Sri Basavaraj, AEE, RR Nanar Division. BBMP.
806400	(Work mentioned in para 2.29 this note)	o	(Details of excess measurements and excess payment are shown in the investigation report)		Bengaluru. 4. Officers of K.R.I.D.L.

		thi		J.C	×.	are	BE	ō	24. lm	1.00	SI.		
		this note)	fork montioned is not 2.15 of	J.C.No.160-20-000056	Ward No.160.	area in Rajarajeshwarinagara in	BEML _ayout and surrounding	to drains in Krishnappa Layout,	Improvements and maintenance		Name of the work		
									13.01.2021		inspection	Data of	
TOTAL	the investigation report)	(Details of excess measurements	are held responsible.	being paid by the concerned officers	the M.B. book and excess amount	were found to have been recorded in	executed. Excess measurements	made for the works which were not 1,17,17,386.00	Bills were prepared and payments		Findings of the I.O		ANNEXURE-A
23,68,20,263/-					•			1,17,17,386.00		III IXO.	misappropriated	Amount	
	Bengaluru. 4. Officers of K.R.I.D.L	Nagar Division, BBMP,	2.Sri M.Siddaramaiah, AE	Bengaluru.	B.B.M.P.	Office,	Rajarajeshwarinagar Zonal	Chief Engineer,	1.Sri Vijayakumar,		responsible	Officers/Officials	



	cials Ne	i a	eer istant neer neer I.D.L ection		neer sistant neer ineer I.D.L pection
	Officers/Officials responsible	ıkta, Bengaluru	Assistant Engineer Sri Umesh, Assistant Executive Engineer Executive Engineer Officers of K.R.I.D.L Third party inspection team		Assistant Engineer Sri Umesh, Assistant Executive Engineer Executive Engineer Officers of K.R.I.D.L. Third party inspection team
	Amount misappropriated in Rs.	č, Karnataka Lokayu	86,30,817.00 1. 2. 3. 4.		1,68,93,643.00 (The said amount does not include GST deducted for the work)
ANNEXURE-A	Findings of the I.O	Chandrappa.M, Assistant Executive Engineer-3, TAC, Karnataka Lokayukta, Bengaluru	Bills were prepared and payments made for the works which were not executed. Excess measurements were found to have been recorded in the M.B. book for few works executed and excess amount being paid by the concerned officers are held responsible.	(Details of the same mentioned in the investigation report)	Bills have been paid without execution of works mentioned in the M.B. Book and concerned officers are held responsible.
	Date of inspection	handrappa.M	24.11.2020		25.11.2020
	XIO.		I maintenance ika Badavane, Badavane, pa-k and areas in d Nb.73	para 2.114	naintenance Badavane, hi Park, hent and eas in 0.73, 24.
	Name of the work	Investigation Officer. Sri	Improvements and maintenance to drains in Vinayaka Badavane, BDA. Bandemaramma park and surrounding areas in Kottigepalya, Ward Nb.73 J.C.No.073-2C-000023	(Work mentioned in para 2.114 of this note)	Improvement and maintenance to drains in BDA Badavane, Mahathma Gandhi Park, Brahmagiri apartment and surrounding areas in Kottigepalya Ward No.73.  J.C.No.073-20-000024.  (Work mentioned in para 2.111 of this note)
	SI. No.		25.		. 56.

Executive Engineer Executive Engineer Officers of K.R.I.D.L. Third party inspection

დ. <del>4</del>. დ

(The said amount does

are held responsible.

not include GST deducted for the work)

team

Assistant Engineer Sri Umesh, Assistant

1,70,38,559.00

Bills have been paid without execution of works mentioned in the M.B. Book and concerned officers

30.11.2020

Improvement and maintenance

27.

to drains in Magala layout,

Ramakrishna

Magalagrama,

layout and surrounding areas in

Kottigepalya Ward No.73 J.C.No 073-20-003025. (Work mentioned in para 2.118

of this note)

ರೋಕಾರ್ಯ

TON WOOD

Date of inspection  e 01.12.2020  n n 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	30. Improvement and maintenance to drains in premnagar, promodnagar and surrounding areas n Kottigepalya ward no.73. J.C.No.C73-20-000045. (Work mentioned in para 2.123 of this rote)	29. Improvement and maintenance to drains in Sollapuradamma layout, Srinivasnagar and surrounding areas in Kottige-balya Ward No.73 J.C.No.073-20-000047.  (Work mentioned in para 2.124 of this note)	28. Improvement and maint to drains in Srigandad! Industrial Estate surrounding areas Kottigecalya Ward No.73. J.C.No.073-20-000050.  (Work mentioned in para of this note)	SI. Name of
Bills were prepared and payments made for the work were not executed measurements were found been recorded in the M.B. It few works executed and amount being paid by the conofficers are held responsible.  (Details of the same mentione investigation report)  Bills were prepared and a the works which were not execept removing of silt frodrain. Concerned officer responsible.  (Details of the same mentione investigation report)  Bills were prepared and payments made for the works were not executed. It measurements were found to been recorded in the M.B. Be few works executed and amount being paid by the conofficers are held responsible.  (Details of the same mentioned investigation report)		intena irradar ar s 73	intena adhak s s 73.	Name of the work
prepared the N.B. buted.  prepared and by the consible.  prepared and prepared of silt from the works.  prepared and prepared of the works.  prepared the works.  prepared the m.B. bothe M.B. bothe M.B. bothe componsible.		02.12.2020	01.12.2020	Date of inspection
Amount misappropriated in Rs. 95,30,256.00 95,30,256.00 1,64,76,530.00 1,36,11,445.00	ad and rks which Excess to have book for excess oncerned	Bills were prepared and paid for the works which were not executed except removing of silt from the drain. Concernec officers are responsible.  (Details of the same mentioned in the investigation report)	prepared r the work uted. re found re found he M.B. b he M.B. b the and by the col ponsible.	
	<ol> <li>Assistant Engineer</li> <li>Sri Umesh, Assistant Executive Engineer</li> <li>Executive Engineer</li> <li>Officers of K.R.I.D.I.</li> <li>Third party inspection team</li> </ol>	Assistant Engineer     Sri Umesh, Assistant Executive Engineer     Officers of K.R.I.D.     Third party inspection team	1. Assistant Engineer 2. Sri Umesh, Assistant Executive Engineer 3. Executive Engineer 4. Officers of K.R.I.D.L 5. Third party inspect on team	Officers/Officials responsible

			ANNEXURE-A			
S. No.	. Name of the work	Date of inspection	Findings of the I.O	Amount misappropriated in Rs.	Officers/Officials responsible	
2	main road, Sophia High School road, 2 <sup>nd</sup> 'H' main road and surrounding areas roads in Kottigepalya Ward No.73 J.C.No.073-20-000030 (Work mentioned in para 2.119 of this note)	05.12.2020	Bills were prepared and payments made for the works which were not executed. Substandard asphalt work carried out. Excess measurements were found to have been recorded in the M.B. book for few works executed and excess amount being paid by the concerned officers are held responsible.  (Details of the same mentioned in the investigation report)	1,68,97,165.00	Assistant Engineer     Sri Umesh, Assistant     Executive Engineer     Executive Engineer     Officers of K.R.I.D.L     Third party inspection team	
32.	Comprehensive development of roads and drains in Muneshwara layout and surrounding areas in Ward No.69, laggere, J.C.No.069-20-000016.	a n	Bills were prepared and paid for the works which were not executed except removing of silt from the drain. Concerned officers are responsible.	1,25,53,350.00		
	(Work mentioned in para 2.48 of this note)		(Details of the same mentioned in the investigation report)		<ol> <li>Third party inspection team</li> </ol>	
33.	Improvement and maintenance to drains in Gangamma garden, Krishnanandanagar Magala and surrounding areas in Kottige palya ward No.73.  J.C.No.073-20-000026.	a a e e	Bills were prepared and paid for the works which were not executed except removing of silt from the drain. Concerned officers are responsible	1,69,11,336.00 (The said amount does not include GST deducted for the work)	Assistant Engineer     Sri Umesh, Assistant     Executive Engineer     Executive Engineer     Officers of K.R.I.D.L     Third party inspection     team	
	of this note)	<b>V</b>				
Ser. 73.	34. Improvement and maintenance to drains in Nagarabhavi 2 <sup>nd</sup>	e 10.12.2020	Bills were prepared and payments made for the works which	1,72,62,236.00	Assistant Engineer     Sri Umesh, Assistant	
300 BOOK			887 (A		1	1
					7	

NOT GOOD

			4		
37.		36	35	SI.	
Improvements to roads at 13 <sup>th</sup> main road and surrounding cross roads in Vinayaka layout, ward no 73 kottigensive	extention, Nagarabhavi 7" block and surrounding areas in Kottigepalya ward No.73. J.C. No.073-20-000035.  (Work mentioned in para 2.113 of this note)	Improvernents and maintenance to drains in Marilingappa	block, Nagarabhavi 3 <sup>rd</sup> block and surrounding areas in ward no.73 Kottigepalya. J.C:No.073-20-000036.  (Work mentioned in para 2.122 of this note)  Improvements and maintenance to drains in Vinayaka layout, Nanjappa Garden and surrounding areas in Ward No.73 Kottigepalya. J.C No.073-20-000033.  (Work mentioned in para 2.115 of this note)	Name of the work	
15.12.2020	×	14.12.2020	11.12.2020	Date of inspection	
Bills were prepared and payments made for the works which were not executed. Substandard	were not executed Excess measurements were found to have been recorded in the M.3. book for few works executed and excess amount being paid by the concerned officers are held responsible.  (Details of the same ment oned in the investigation report)	Bills were prepared and payments made for the works which	were not executed. Excess measurements were found to have been recorded in the M.B. book for few works executed and excess amount being paid by the concerned officers are held responsible. (Details of the same mentioned in the investigation report)  Bills were prepared and payments made for the works which were not executed. The concerned officers are held responsible.	Findings of the I.O	ANNEXURE-A
1,70,26,527.00	2. 2. 3.	1,36,78,720.00	1,60,06,866.00 (The said amount does not include GST deducted for the work)	Amount misappropriated in Rs.	
Assistant Engineer     Sri Umesh, Assistant     Executive Engineer     Executive Engineer	Executive Engineer 3. Executive Engineer 4. Officers of K.R.I.D.L. 5. Third party inspection team	<ol> <li>Assistant Engineer</li> <li>Sri Umesh, Assistant</li> </ol>	Executive Engineer 3. Executive Engineer 4. Officers of K.R.I.D.L 5. Third party inspection team  1. Assistant Engineer 2. Sri Umesh, Assistant Executive Engineer 3. Executive Engineer 4. Officers of K.R.I.D.L 5. Third party inspection team	Officers/Officials responsible	

10 mo

ANNEXURE-A	Findings of the I.O Amount Officers/Officials in Rs.	been recorded in the M.B. baok for few works executed and excess amount being paid by the concerned officers are held responsible.  (Details of the same mentioned in the investigation report)	Bills were prepared and payments 1,70,49,470.00 1. Assistant Engineer area for the works which were not executed. Substandard asphalt work carried out. Excess measurements were found to have been recorded in the M.B. book for few works executed and excess amount being paid by the concerned officers are held responsible.  (Details of the same mentioned in the investigation report)	Bills were prepared and 1,69,61,087.00 1. Assistant Engineer payments made for the works which work executed. Substandard asphalt work carried out. Excess measurements were found to have been recorded in the M.B. book for few works executed and excess amount being paid by the concerned officers are held responsible.  (Details of the same mentioned in the investigation report)	were prepared and 1,68,21,797.00 1. Assistant Engineer
	Date of inspection	30	16.12.2020	17.12.2020	18.12.2020
		7. ara 2.02 of		roads at Extension, k and other roads in 0.73.	ads at 10 <sup>m</sup>
	Name of the work	J.C.No 073-20-000027. (Work mentioned in para 2.02 of this note)	Improvements to roads at Nagarabhavi 5 <sup>th</sup> Block and BDA Complex surrounding cross roads in Kottigepalya Ward No.73. J.C.No.073-20-000082. (Work mentioned in para 2.04 of this note)	Improvements to roads at Marilingappa Extension, Nagarabhavi 5 <sup>th</sup> Block and other surrounding cross roads in Kottigepalya Ward No.73. J.C.No.073-20-000031. (Work mentioned in para 2.05 of this note)	Improvements to roads
	S. No.		38	39.	Service.

ಗೆಂಗಳಾ<sup>©</sup>

para keriji pali nili

main rcad, 9 <sup>th</sup> main Nanjapta Garden su cross roads in Ko Ward No.73.  J.C.No.073-20-000028  (Work mentioned in paths note)	SI. Name
main rcad, 9 <sup>th</sup> m. Nanjappa Garden cross roads in Ward No.73.  J.C.No.073-20-000 (Work mentioned in this note)	Name
road Irroun ittigep	Name of the work
	Date of inspection
payments made for the works which were not executed. Substandard asphalt work carried out. Excess measurements were found to have been recorded in the M.B. book for few works executed and excess amount being paid by the concerned officers are held responsible.	ANNEXURE-A Findings of the I.O
•	Amount misappropriated in Rs.
ળ ધમ	
Sri Umesh, Assistant Executive Enginee: Executive Enginee: Officers of K R.I.D.L Third party inspection team	Officers/Officials responsible
	payments made for the works which were not executed. Substandard asphalt work carried out. Excess measurements were found to have been recorded in the M.B. book for few works executed and excess amount being paid by the concerned officers are held responsible.

	SI. No.	Name of the work	ork	Date of inspection	Findings of the I.O	Amount misappropriated	Officers/Officials responsible	
٥	43.	Improvements and maintenance to drairs in Telephone Employee Sollapuradamma Iayout, Sollapuradamma in strial estate and surrounding areas in Kottigepalya ward no.73.  J.C.No.073-20-000049.  (Work mertioned in para 2.126 of this note)	maintenance Telephone layout, layout, layout, arrial estate areas in 5.73. 49.	23,12,2020	Bills were prepared and payments made for the works which were not executed. Excess measurements were found to have been recorded in the M.B. book for few works executed and excess amount being paid by the concerned officers are held responsible.  (Details of the same mentioned in the investigation report)	86,87,574.00	1. Assistant Engineer 2. Sri Umesh, Assistant Executive Engineer 3. Executive Engineer 4. Officers of K.R.I.D.L 5. Third party inspection team	
	44	Comprehensive development of roads and drains from Aladhamara circle to Rajiv Gandhi circle in ward no.69, Laggere.  J.C.No.069-20-000019.  (Work mentioned in para 2.47 of this note)	elopment of ins from to Rajiv ard no.69, 19.	24.12.2020	Bills were prepared and payments made for the works which were not executed. Substandard asphalt work carried out. Excess measurements were found to have been recorded in the M.B. book for few works executed and excess amount being paid by the concerned officers are held responsible.  (Details of the same mentioned in the investigation report)	1,17,45,190.00	1. Assistant Engineer 2. Sri Umesh, Assistant Executive Engineer 3. Executive Engineer 4. Officers of K.R.I.D.L 5. Third party inspection team	
	\$2°50	Improvements and maintenance to drains at 4 <sup>th</sup> main, 5 <sup>th</sup> main, 6 <sup>th</sup> main road and cross roads in ITI layout and surrounding areas in Jnanabharathi ward no. 129. J.C.No.129-20-000050.  (Work mentioned in para 2.108 of this note)	naintenance 1, 5 <sup>th</sup> main, sss roads in nding areas d no. 129. 50. para 2.108	29.12.2020	Bills were prepared and payments made for the works which were not executed. Excess measurements were found to have been recorded in the M.B. book for few works executed and excess amount being paid by the concerned officers are held responsible.	81,69,903.00	Sri Siddaramaiah, Junior Engineer     Sri Basavaraj, Assistant Executive Engineer     Executive Engineer     Cofficers of K.R.I.D.L.     Third party inspection team	

(Details of the same mentioned in the

ANNEXURE-A





St. Name of the work Integration Officer. Sin Gurupirased, Assistant Engineer-16, TAC, Karnataka Lokeyukta, Bengahuru Loddong areas in a Challes are held for some talley with the south of the note).  Also improvements and meintenance 24.11.2020 The measurements recorded to design to fall the south of th							. · ·		·=								_	i de ju	0,1	30 V	×		к:
Name of the work    Date of   Findings of the I.O		Officere/Officiale	responsible	٥	galuru	Engineer, TVCC Cell, BBMP Head Office, N.R. Square, Bengaluru.			Engineer, Rajarajeshwal nagar Zonal Office,			Assistant, O/o the Chief	Engineer, 1VCC Cell, BBMP Head Office, N.R.			Rajarajeshwarinagar Project Division, BBMP,			Technical Assistant,	Rajarajeshwarinagar Project Division, BBMP		- 7**	A.E.E., Rajarajeshwarinagar
Name of the work    Date of   Findings of the I.O		-			ı, Beni	-	- 5	സ												1			
Name of the work    Date of   Findings of the I.O		400000	Amount nisappropriated in Rs.		nataka Lokayukta	78,85,383.00			>				D.										
Improvements and maintenance to drains at Chancrashekar badavane 2nd main coad and surrounding areas in Jnana Bharathi 'Ward No. 129 J.C.No. 129-20-000022 (Work mentioned in para 2.49 of this note)		ANNEXURE-A		٠٠		neasurements record Book does not tall urements actually	officers are held responsible for the excess payments made.			•	22		n n				3			Α .	c .		
Improvements and maintenance to drains at Chancrashekar badavane 2nd main coad and surrounding areas in Jnana Bharathi 'Ward No. 129 J.C.No. 129-20-000022 (Work mentioned in para 2.49 of this note)			Date of inspection		icer. Sri Gurup	24.11.2020																	
Improvements a to drains at badavane 2nd road and surround Juana Bharathi Juana Bharathi his note)			ork		tigation Off	_	g areas in No.129	ara 2.49 of		•			):										
	6		Name of the w		Inves	Improvements and motion to drains at Char badavane 2 <sup>nd</sup> main	road and surrounding Juana Bharathi 'Ward	(Work mentioned in p	this note)						1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	e g Son e			100		ă.	¥.	
			S. S.			48				21				×							1	243	್ಯೆಯೊ

Solve on the second of the sec

	97		Ģi i					F 9																		
8 F	dy:	Į.	49	v į																			No.	š		
J.C.No.129-20-000021 (Work mentioned in para 2.52 of this note)	areas in Jnana Bharathi Ward No.129	to Drains at RHCS Layout 2 <sup>nd</sup> stage 'A' Block and surrounding	Improvements and maintenance	X The Principle of the State of		(A)	3					(5)												Name of the work		
			25 11 2020					3															mapection	Date of		
excess payments made.	<u> </u>	Book does not tally with surements to actually record	The measurements recorded in the					2 >							in .									Findings o⁴ the I.O	ANNEXOXE-A	ANNITY I DE L
	28	0.00	86 32 304 00					8			8	* 3							100				in Rs.	Amount misappropriated		
27.74		ç	Bengaluru.	Kajarajeshwarina jar Division, BBMP,	Manager,	11. Sri Guligowda, Sub	Division, BBMP,	Rajarajeshwarina jar	Cashier,	10. Smt. Anitha.	Bengaluru.	division, BBMP,	No.73. Laggere sub-	Assistant Engineer Ward		9 Srillmesh Assistant	Bengaluru.	division BBMP	Rajarajashwarinagar Sub-	No 129 & 160	Assistant Engineer Ward	DIVISION & SUB-dIVISION.		Officers/Officials responsible	1	

Q

4

50.

Improvements and maintenance to drains at 34<sup>th</sup> main road, 35<sup>th</sup>

- do -

79,82,117.00

COND MOSE

		[4]	
Officers/Officials responsible		-00	- <b>о</b> р
Amount in Rs.		85,22,069.00	1,02,70,583.00
Findings of the I.O		op	- op -
Date of inspection	+ - -	02.12.2020	01.12.2020
ork  a & cross yout and in Jnana ara 2.60 of ara 2.60 of	Road, book and and lin Juana and ara 2.44 of	aintenance road, 35 <sup>th</sup> of & cross 4CS Layout as in Jnana 9 9 73 9	naintenance in road, 1 <sup>st</sup> road in Layout & surrounding arathi Ward
Mame of the work  main, 36 <sup>th</sup> main road & cross road in RHCS Layout and surrounding area in Jnana Bharathi Ward No.129 J.C.No.129-20-000074 (Work mentioned in para 2.60 of this note)	to Drains at 5" main road, be main, 7" main road & cross road in RHCS Layout and surrounding areas lin Jnana Bharathi Ward No.129 J.C.No.129-20-000014 (Work mentioned in para 2.44 of this note)	Improvements and maintenance to Drains at 2 <sup>nd</sup> main road, 35 <sup>th</sup> main, 36 <sup>th</sup> main road & cross road in Iranapalya RHCS Layout and surrounding areas in Jnana Bharathi Ward No.129 J.C.No.129-20-000073 (Work mentioned in para 2.62 of this note)	Improvements and maintenance to Drains at 5th main road, 1st stage & cross road in Annapoorneshwari Layout & RHCS Layout and surrounding areas in Jnana Bharathi Ward
No.		52.	E. Sura

di ki age a done. Lanie deli

4

	g 90			
	56.		55 54	No.
2	Improvements and maintenance to Crains at 28 <sup>th</sup> main, 29 <sup>th</sup> main road, 5 <sup>th</sup> main and cross road in Poornachandra Layout and surrounding areas in Jnana Bharathi Ward No.129 J.C.No.129-20-000070 (Work mentioned in para 2.68 of this note)	road, 6 <sup>th</sup> main, 4 <sup>th</sup> main and cross road to RCHS Layout and Srigandhadakaval and surrounding areas in Jnana Bharathi Ward No.129 J.C.No.129-20-000015 (Work mentioned in para 2.67 of this note)	main reamain reamain reamain reamain Schoonal School school reamain reamain reamain reamain aria aria aria aria aria aria aria a	Name of the work  J.C.No.129-20-000020 (Work mentioned in para 2.64 of this note)
	09.12.2020	2	05.12.2020	Date of inspection
	- do -		- do -	ANNEXURE-A Findings of the I.O
	95,72,919.00		1,03,46,210.00 94,67,186.00	Amount misappropriated in Rs.
BREUS	-do-		do	Officers/Officials responsible

				ANNEXURE-A		
S. O.	Name of the work	×	Date of inspection	Findings of the I.O	Amount misappropriated in Rs.	Officers/Officials responsible
57	Improvements and maintenance to Drains at 5th mair, 6th cross road in Bhavaninagara and surrounding areas in Jnana Bharath: Ward No.129 J.C.No.129-20-000066 (Work mentioned in para 2.85 of this note)	ttenance off cross ara and Jnana a 2.85 of	10.12.2020	op.	1,02,91,718.00	-op-
28	Improvements and maintenance to Drains at Govt. Press Layout and other surround rig areas in Jnana Bharathi Ward No.129 J.C.No.129-20-000030 (Work mentioned in para 2.63 of this note)	ntenance s Layout areas in o.129 a 2.63 of	11.12.2020	- op -	96,95,257.00	<del>o</del> p
59	Improvements and maintenance to Drains at Health Layout 4 <sup>th</sup> main and surrounding areas in Jhana Bharathi Ward No.129 J.C.No.129-20-000023 (Work r-entioned in para 2.66 of this note)	ntenance ayout 4 <sup>th</sup> areas in o.129 a 2.66 of	14.12.2020	- oр -	78,14,560.00	-op-
00	Improvements and me to Drains at Health main and surrounding Juana Bharathi, Warr J.C.No. 129-20-000000000000000000000000000000000	aintenance Layout 3 <sup>rd</sup> Layout 1 <sup>st</sup> 1g areas in d No.129 24 bara 2.57 of	15.12.2020	op -	88,64,870.00	<del>-</del> 0
d on	Improvements to Roads in Sri	ds in Sri	15.12.2020	The measurements recorded in the	1,00,55,846.00	-op-

rion thor

	65.	+	Σ σ.	62.	No.	
7	Improvements and maintenance to Drains at 4 <sup>th</sup> cross and 7 <sup>th</sup>	improvements and maintenance to Drains at Jnanajyothinagar, 14th crcss, 15th cross and surrounding areas in Jnana Bharath Ward No.129 J.C.No.129-20-000028 (Work mentioned in para 2.89 of this note)	Improvements to Roads in NGEF Layout, 2 <sup>nd</sup> Main, 3 <sup>rd</sup> Main and other surrounding cross roads in Jnana Bharathi Ward No.129 J.C.No.129-20-000008 (Work mentioned in para 2.50 of this note)	M.V. Layout and surrounding cross roads in Jnana Bharathi Ward Nc.129 J.C.No.129-20-000010 (Work mentioned in para 2.70 of this note)  Improvements to Roads in Muneshwaranagar, Ulalla Main road and other surrounding cross roads in Jnana Bharathi Ward No.129 J.C.No.129-20-000011 (Work mentioned in para 2.69 of this note)	Name of the work	
	19.12.2020	18.12.2020	16.12.2020	15.12.2020	Date of inspection	
	- do -	do +	The measurements recorded in the M.B. Book does not tally with the measurements actually recorded during spot inspection. Substandard asphalt work carried cut. Concerned officers are held responsible for the excess payments made.	M.B. Book does not tally with the measurements actually recorded during spot inspection. Substandard asphalt work carried out. Concerned officers are held responsible for the excess payments made.  The measurements recorded in the M.B. Book does not tally with the measurements actually recorded during spot inspection. Substandard asphalt work carried out. Concerned officers are held responsible for the excess payments made.		ANNEXURE-A
	1,17,73,426.00	97,18,892.00	1,53,54,469.00	94,92,387.00	Amount misappropriated in Rs.	
000	-do- to	, do-	-do-	-do-	Officers/Officias responsible	

3017 too

St.   Name of the work   Date of   Findings of the I.O   Inseparopriated   Insepar					ANNEXURE-A		
reain in Adarsha Layout and surrounding areas in Janaa Bhazahi Vard Ko.129  J. C. No. 179-20-000058  (Work mentioned in para 2.81 of this note)  Improvements and maintenance in Janaa areas in Janaa Bhazahii Ward Ko.129  Improvements and maintenance in para 2.83 of this note)  Improvements and maintenance in Janaa 2.83 of this note)  Improvements and maintenance in Janaa 2.83 of this note)  Improvements and maintenance in Janaa 2.83 of this note)  Improvements and maintenance in Janaa 2.83 of this note)  Improvements and maintenance in Janaa 2.83 of this note)  Improvements and maintenance in Janaa 2.83 of this note)  Improvements and drains in Janaa 2.84 of this note)  Improvements and drains in Janaa 2.84 of this note)  Improvements and drains in Janaa 2.84 of this note)  Improvements and drains in Janaa 2.84 of this note)  Improvements and drains in Janaa 2.84 of this note)  Improvements and drains in Janaa 2.84 of this note)  Improvements and drains and Janaa 2.84 of this note)  Improvements areas in Janaa 2.84 of this note)	<u>S</u> S	Name of the work	NO.	Date of inspection		Amount misappropriated in Rs.	Officers/Officials responsible
Work mentioned in para 2.81 of this note)  Improvements and maintenance 19.12.2020  Improvements and maintenance 19.12.		) o _	_		•		* *
Improvements and maintenance to drains at 2" main and 3" this note)  No. 129-20-000018  Work mentioned in para 2.88 of this note)  A.C.No. 129-20-000018  (Work mentioned areas in Juna Bharathi Ward No. 129-20-000018  (Work mentioned areas in Juna Bharathi Ward No. 129-20-000018  (Work mentioned in para 2.58 of this note)  Surrounding areas in Ward No. 129-20-00018  (Work mentioned in para 2.44 of this note)  Surrounding areas in Ward Nork weecuted as per tender  Diriling of 3ore/wells and 22.12.2020  Providing water supply through		(Work mentioned in para 2 this note)	2.81 of				
main in NGEF Layout and surrounding areas in Junaa Bharathi Ward No.129-20-00043  (Work mentioned in para 2.83 of this note) Improvements and rhaintenance in Junaa Bharathi Ward Comprehensive Development of a cross road in Annapoonneshwari Layout & RCHS Layout and surrounding areas in Juna Bharathi Ward No.129-20-000018  (Work mentioned in para 2.58 of this note)  Comprehensive Development of a construction and drains in Kempegowda Layout and cross and drains in Kempegowda Layout and surrounding areas in Ward No.69. Laggere  J.C.No.059-20-4014  (Work mentioned in para 2.44 of this note)  J.C.No.059-20-4014  (Work mentioned in para 2.44 of this note)  Diffilling of sorewells and 22.12.2020 Work executed as per tender providing water supply through	.99	Improvements and mainte to drains at 2" main a	+	19.12.2020	- op -	86,81,725.00	-op
Bharathi Ward No.129 U.C.No.129-20-000043 (Work mentioned in para 2.83 of this note) this note) to Drains at 4 <sup>th</sup> main and 3 <sup>th</sup> main and surrounding areas in Jhana Bharathi Ward No.129. U.C.No.129-20-000018 (Work mentioned in para 2.58 of this note) Comprehensive Development of 23.12.2020 this note) Comprehensive Development of 23.12.2020 this note) Comprehensive Davelopment of and and crains in Ward No.63, Laggere U.C.No.059-20-4014 (Work mentioned in para 2.44 of this note) Drilling of sorewells and 22.12.2020 Voork executed as per tender Drilling of sorewells and providing water supply through		main in NGEF Layout surrounding areas in	ut and Jnana				
this note)  Improvements and relating areas in Ward No.68, Laggere J.C.No. 639-20-4014 (Work mentioned in para 2.44 of this note)  In sole)  Comprehensive Development of surrounding areas in Ward No.68, Laggere J.C.No.692-20-4014 (Work mentioned in para 2.44 of this note)  Dr.No.692-20-4014 (Work mentioned in para 2.44 of this note)  Dr.No.693-20-4014  Work mentioned in para 2.44 of this note)  Dr.No.693-20-4014  Work mentioned in para 2.44 of this note)  Dr.No.693-20-4014  Dr.No.693-20-4014  Work mentioned in para 2.44 of this note)  Dr.No.693-20-4014  Dr.N		Bharathi Ward No.129 J.C.No.129-20-000043					
Improvements and rhaintenance to Drains at 4° main and 3° main and		(Work mentioned in para this note)	2.83 of	14		<u> </u>	182
to Drains at 4th main and 3th main and stroad in Annapoorneshwari Layout & RCHS Layout and surrounding areas in Jhana Bharathi Ward No.129-20-000018 (Work mentioned in para 2.58 of this note)  Comprehensive Development of 23.12.2020 - do - this note)  Comprehensive Development of 23.12.2020 - do - this note)  Comprehensive Development of 23.12.2020 - do - this note;  Comprehensive Development of 23.12.2020 Work executed as per tender Nil specification	67	+	enance	19.12.2020	~ op -	1,03,46,210.00	-op-
Annapoomeshwari Layout & Annapoomeshwari Layout & Annapoomeshwari Layout & Annapoomeshwari Layout and surrounding areas in Juna Bharathi Ward No.129.  J.C.No.129-20-000018 (Work mentioned in para 2.58 of this note)  Comprehensive Development of comprehensive Development of this note)  Comprehensive Development of 23.12.2020  Comprehensive Development of comprehensive Development of comprehensive Development of comprehensive Development of this note;  No.69, Lagout and surrounding areas in Ward No.69, Lagout and Surrounding areas in Ward No.69, Lagout and Surrounding of comprehensive Drilling Of comprehensive		_	and 3 <sup>rd</sup>		No. 2 (1)		
Activation of this note)  No. 69, Laggere J. C. No. 695-20-4014  (Work mentioned in para 2.44 of this note)  No. 69 Laggere J. C. No. 695-20-4014  (Work mentioned in para 2.44 of this note)  Drilling of sorewells and 22.12.2020  Activated as per tender  Niles and para 2.44 of this note)  Drilling of sorewells and 22.12.2020  Activated as per tender  Niles and 22.12.2020  Work executed as per tender  Niles and 22.12.2020  No. 69 Laggere  J. C. No. 695-20-4014  Work executed as per tender  Niles and 22.12.2020  No. 69 Laggere  J. C. No. 695-20-4014  Work executed as per tender  Niles and 22.12.2020  No. 69 Laggere  J. C. No. 695-20-4014  Work executed as per tender  Niles and 22.12.2020  No. 69 Laggere  J. C. No. 695-20-4014		_					
areas in Jnána Bhárathi Ward No.129. J.C.No.129-20-000018 (Work mentioned in para 2.58 of this note) Comprehensive Development of conding areas in Ward No.69, Laggere J.C.No.059-20-4014 (Work mentioned in para 2.44 of this note) Drilling of correwells and 22.12.2020 Work executed as per tender Drilling water supply through		RCHS Layout and surro	unding			s= 1	
No.129.  No.129.  J.C.No.129-20-000018  (Work mentioned in para 2.58 of this note)  Comprehensive Development of 23.12.2020  No.69, Laggere  J.C.No.039-20-4014  (Work mentioned in para 2.44 of this note)  Drilling of 20 providing water sumply through		areas in Juana Bharathi	i Ward	4			
(Work mentioned in para 2.58 of this note)  Comprehensive Development of roads and drains in Kempegowda Layout and surrounding areas in Ward No.69, Laggere J.C.No.059-20-4014  (Work mentioned in para 2.44 of this note)  Drilling of providing water sumply through		No.129.				10 mm m	
this note)  Comprehensive Development of 23.12.2020  Comprehensive Development		(Work mentioned in para	2.58 of		30		
Comprehensive Development of 23.12.2020 - 00 - 1,33,02,313.00   roads and drains in Kempegowda Layout and surrounding areas in Ward No.69, Laggere J.C.No.059-20-4014   (Work mentioned in para 2.44 of this note)   Drilling of sorewells and 22.12.2020 Work executed as per tender   Nil    Specification   Nil		7				4 22 02 242 00	of the second se
Kempegowda Layout and surrounding areas in Ward No.69, Laggere J.C.No.039-20-4014 (Work mentioned in para 2.44 of this note) Drilling of sorewells and 22.12.2020 Work executed as per tender Nil specification	68.	_	ment of	23.12.2020	- op -	1,33,02,313.00	-07
Surrounding areas in Ward No.69, Laggere J.C.No.039-20-4014 (Work mentioned in para 2.44 of this note) Drilling of sorewells and 22.12.2020 Work executed as per tender Nil specification		and	'n	E			
No.69, Laggere J.C.No.039-20-4014 (Work mentioned in para 2.44 of this note)  Lining of sorewells and specification specificatio		areas	>		e.		
U.C.No.059-20-4014 (Work mentioned in para 2.44 of this note)  this note)  Drilling of sorewells and 22.12.2020 Work executed as per fender Nil specification		No.69, Laggere					
this note)  Drilling of sorewells and 22.12.2020 Work executed as per fender  Providing water supply through specification		_	12.44 of	C (A)			
providing water supply through	169	-	s and	22.12.2020	Work executed as per tender	īZ	**
	07	-	through		specification		

		ANNEXUKE-A		
SI. Name of the work No.	Date of inspection	Findings of the I.O	Amount misappropriated in Rs.	Officers/Officials responsible
pipeline in ward No.17, 78 and				
42 in R.R.Nagar Constituency.				
J.C.No.042-19-000013				
(Work mentioned in para 2.43 of		¥		
this note)		e		
of debris	and 23.12.2020	Work executed as per tender	Z	
overburden of earth in		specification		
D.Devara urs truck terminal				
limited of ward No.42 in				
R.R.Nagar Division, BBMP.				
J.C.No.042-20-000017				
(Work mentioned in para 2.42 of	3.0			
ナデンファナン				
נוווס ווטנפ)		TOTAL	20 40 50 400	



Date of Findings of the I.O Amount inspection
---

Investigation Officer - Sri Ashok.N, Assistant Engineer-1, TAC, Karnataka Lokayukta, Bengaluru

	-		
Sri Doddaiah,     Sri Basavaraju     Sri.Siddaramaiah,	1. Sri Doddaiah, 2. Sri Basavaraju, 3. Sri.Siddaramaiah, Officers of K.R.I.D.L.,	1. Sri Doddaiah, 2. Sri Basavaraju, 3. Sri Siddaramajah, Officers of K.R.I.D.L.,	Sri Doddaiah, Chief     Sri Basavaraju,     Sri Siddaramaiah,     Officers of K.R.I.D.L.,
62,91,080.25	54,23,125.28	41,03,264.86	61,06,129.56
During spot inspection drainage works performed were found unsatisfactory. However, additional bills were prepared and approved. The concerned officers are held responsible.	During investigation sub-standard work of the drainage were noticed towards which additional bills were prepared and approved, for which concerned officers are held responsible.	Works that were not attended were entered in the M.B. and additional bills were prepared, for which the concerned officers are held responsible.	Works conducted were not up to the mark towards which additional bills were prepared and approved. All the concerned officers are responsible.
20.01.2021	30.01.2021	28.01.2021	29.01.2021
haintenance & 6 <sup>th</sup> cross Nagar and in Jnana 9. 36 para 2.96 of	naintenance Gavipuram Iding areas rd no.129 rd sea 2.92 of	laintenance lin & cross ayout and in Jnana in Jnana 16	laintenance 9 <sup>th</sup> main in surrounding trathi ward 17
improvements and maintenance to drains 5th main 8 6th cross road in Bhavani Nagar and surrounding areas in Juana Bharathi ward No.129. J.C.Nc.129-20-000036 (Work mentioned in para 2.96 of this note)	Improvements and maintenance to drains at Gavipuram badavane & surrounding areas in Jnana Bharathi ward no.129 J.C.No.129-20-000029 (Work mentioned in para 2.92 of this note)	Improvements and maintenance to drains 3 <sup>rd</sup> , 4 <sup>th</sup> main & cross roads in NGEF Layout and surrounding area in Jnana Bharathi ward no.129 J.C.No.129-20-000046 (Work mentioned in para 2.98 of this note)	Improvements and maintenance to drains 11th main & 9th main in Bhavani Nagar and surrounding area in Jnana Bharathi ward no.129 J.C.No.129-20-000037 (Work mentioned in para 2.103

75		SI.	
marrowaments and maintenance 22.01.2021	of this note)	Name of the work	
22 04 2024		Date of inspection	
The granite cover slahs were not 56.41.100.24	0	Findings of the I.O	ANNEXURE-A
58 41 100 DA		Amount misappropriated in Rs.	
1 Sri Doddaiah		Officers/Officials responsible	

W <del>18</del>			
78.	77,	76.	75.
Improvements and maintenance to drains. 6th main road & cross road in ITI Layout & surrounding area in Jnana Bharathi ward no.129 J.C.No.129-20-00048 (Work mentioned in para 2.99 of	Improvements and maintenance to drains. 1 <sup>st</sup> main road, 2 <sup>nd</sup> main road in Sir M.V 9 <sup>th</sup> block & surrounding area in Jnana Bharathi ward no.129 J.C.No.129-20-000047 (Work mentioned in para 2.100 of this note)	Improvements and maintenance to drains, 2 <sup>nd</sup> main & 11 <sup>th</sup> cross road and cross roads in NGEF Layout & surrounding area in Jnana Bharathi ward no.129 J.C.No.129-20-000044 (Work mentioned in para 2.101 of this note)	Improvements and maintenance to *drains 2 <sup>nd</sup> cross & 9 <sup>th</sup> cross roads in NGEF Layout & surrounding areas in Jnana Bharathi ward no.129 J.C.No.129-20-000039 (Work mentioned in para 2.82 of this note)
18.01.2021	15.01.2021 and 16.01.2021	02.02.2021	22.01.2021
Though the works were not performed as mentioned in the M.B. additional bills were prepared and approved for which the concerned officers are held responsible.	Though the works were not performed as mentioned in the M.B. additional bills were prepared and approved for which the concerned officers are held responsible.	The granite cover slabs were not properly dressed and the work performed though was not satisfactory additional bills were prepared. The concerned officers are held responsible.	The granite cover slabs were not properly dressed and the work performed though was not satisfactory additional bills were prepared. The concerned officers are held responsible.
55,96,244.17	48,97,068.97	62,85,895.79	56,41,109.24
್ಯೂ			<ol> <li>Sri Doddaiah,</li> <li>Sri Basavaraju,</li> <li>Sri Siddaramaiah,</li> <li>Officers of K.R.I.D.L.</li> </ol>

\* Corner

ſ		7			<u> </u>	
	Officers/Officials responsible					
	Amount misappropriated in Rs.		58,94,975.75	61,87,177.76	56,74,111.97	61,75,726.00
ANNEXURE-A	n Findings of the I.O		Works performed were not up to the mark, inspite of which additional bills were prepared and approved. Concerned officers are held responsible.	Though some of the works were not performed, were mentioned in M.B. and additional bills were prepared and approved for which concerned officers are held responsible.	Though sub-standard works were performed additional bills were prepared and approved and the concerned officers were responsible.	Though sub-standard works were performed additional bills were prepared and approved and the concerned officers were responsible.
	Date of inspection		08.01.2021 and 11.01.2021	12.01.2021 and 13.01.2021	25.01.2021	01.02.2021
	work		naintenance 11 <sup>th</sup> main, ss roads in ut and in Jnana in Jnana 49	raintenance 15 <sup>th</sup> main & ba complex as in Jnana 51.	aintenance & 1st cross layout and roads in no.129 54.	aintenance war Nagar n road and roads in
	Name of the work	tris note)	Improvements and maintenance to drains 12 <sup>th</sup> main, 11 <sup>th</sup> main, 15 <sup>st</sup> main road & cross roads in Fonnappa layout and surrounding areas in Jnana Bharathi ward no.129 J.C.No.129-20-000049 ('Work mentioned in para 2.81 of this note)	Improvements and maintenance to drains 16 <sup>th</sup> main, 15 <sup>th</sup> main & cross roads in Deepa complex and surrounding areas in Jhana Eharathi ward no. 129 J.C.No.129-20-000051. (Nork mentioned in para 2.107 of this note)	Improvements and in to drains 10 <sup>th</sup> cross main cross in KK surrounding cross Jnana Bharathi ward J.C.No.129-20-00006 (Work mentioned in or this note)	Improvements and maintenance to drains at Muneshwar Nagar 1st cross & Ullal main road and surrounding cross roads in
	S. No.		79.	80.	6	82.

and the state of the

86.	85.	84.	83.		No.
Improvements to roads in Basaveshwara Badavane, Gattigere extension and surrounding areas in	Improvements and maintenance to drains 30 <sup>th</sup> main, 31 <sup>st</sup> main, 32 <sup>nd</sup> main road & cross roads in RHCS layout and surrounding areas in Jnana Bharathi ward no.129 J.C.No.123-20-000075 (Work mentioned in para 2.88 of this note)	Improvements and maintenance to drains at Govt, press Layout & surrounding areas in Jnana Bharathi ward no.129 J.C.No.129-20-000060 (Work mentioned in para 2.91 of this note)	Improvements and maintenance to drains at Munneshwara Nagar 8 <sup>th</sup> & 12 <sup>th</sup> cross roads and surrounding areas in Jnana Bharathi ward no.129 J.C.No.129-20-000056 (Work mentioned in para 2.104 of this note)	Jnana Bharathi ward no.129 J.C.No.129-20-000055 (Work mentioned in para 2.105 of this note)	Name of the work
19.01.2021	06.01.2021 and 07.01.2021	21.01.2021	27.01.2021		Date of inspection
Substandard asphait work carried out. Sub-standard work was noticed during inspection but additional bills were prepared and approved for	Some of the works mentioned in the M.B. were not performed but additional bills were prepared and approved for the same. The concerned officers are responsible.	Some of the works mentioned in the M.B. were not performed but additional bills were prepared and approved for the same. The concerned officers are responsible.	Some of the works mentioned in the M.B. were not performed but additional bills were prepared and approved for the same. The concerned officers are responsible.		Findings of the I.O
1,32,12,966.70	57,63,687.87	08,56,809.00	59,22,170.00		Amount misappropriated in Rs.
Engineers & staff of Quality  Control sub-division and the staff of Quality  Bengaluru.					Officers/Officials responsible

Г	T'	1			T × 12 × 12 × 12
	Officers/Officials responsible	•	Concerned engineers are responsible.	Concerned engineers are responsible.	Concerned engineers are responsible
	Amount misappropriated in Rs.	v	52,23,432.00	51,06,928.51	83,54,316.62
ANNEXURE-A	Findings of the I.O	which concerned officers were responsible.	Though some of the items mentioned in the M.B. were not attended, additional bills were prepared and approved for which concerned officers are responsible.	Though some of the items mentioned in the M.B. were not attended, additional bills were prepared and approved for which concerned officers are responsible.	Though some of the works were not performed as described in M.B. additional bills were 'prepared and approved. The concerned officers are responsible.
	Date of inspection		01.01.2021 and 02.01.2021	04.01.2021 and 05.01.2021	30.12.2020 and 31.12.2020
	work	ar in ward 34 3ara 2.38 of	ain, 11 <sup>th</sup> main Mavinathopu s at BEML 5 <sup>th</sup> shwari Najar 0066 n para 2.40 of	aintenance od layout, urrounding ri Nagar in 5 . ara 2.4* of	naintenance Garden, 1st Kampada surrounding wari Nagar 87
	Name of the work	Rajarajeshwari Nagar in ward no.160 J.C.No.123-20-000034 (Work mentioned in para 2.38 of this note)	Improvements and maintenance to drains 10th main, 11th main road & Mavinathopu surrounding roads at BEML 5th stage in Rajarajeshwari Najar ward no.160 J.C.No.129-20-000066 (Work mentioned in para 2.40 of this note)	Improvements and maintenance to drains at Prampd layout, Reddy layout and surrounding area in Rajarajeshwari Nagar in ward no.160 J.C.No.160-20-000075 (Work mentioned in para 2.4* of this note)	Improvements and rodins at Ayyappa main road in Badavane and areas in Rajarajest ward no.160 J.C.No.160-20-0000 (Work mentioned in this note)
	SI. O		87.	88	88 (4.3. <sup>4</sup>

ರೋಕಾರ್ಬ್ಗ

Findings of the I.O misappropriated respo	Name of the work	Date of spection	Findings of the I.O	 Officers/Officials responsible
inspection Findings of the I.O misappropriated		ate of pection	Findings of the I.O	Officers

\$4 m					
,543.31 1.Sri Siddaramaiah AE 2.Sri Basavaraju, AEE 3.Sri Doddaiah, CE & 4.K.R.I.D.L Officers	56,15,543.3	The drainage works were performed, though were not up to the mark, additional bills were prepared and some of the items mentioned in the M.B. were found missing. The additional bills were approved by the concerned.	23.12.2020 24.12.2020	Improvements and maintenance to drains 6 <sup>th</sup> main, 1 <sup>st</sup> main & 8 <sup>th</sup> road in BEML layout and surrounding areas in Rajarajeshwari Nagar in ward no.160.  J.C.No.163-2C-000097. (Work mentioned in para 2.77 of this rote)	92
		5	1	J.C.No.160-20-000092 (Work mentioned in para 2.39 of this note)	-
		during spot inspection. However, additional bills were prepared for the same and approved. Concerned officers are responsible.	22.12.2020 03.02.2021	main road & 6 <sup>th</sup> main road in BEML layout and surrounding area in Rajarajeshwari Nagar ward no.160	
,742.78 Concerned engineers are responsible	10,15,742.78	Some of the items mentioned in the M.B. were found unattended	18.12.2020 21.12.2020	Improvements and maintenance to drains at 4th main road, 5th	91.
,				no.160 J.C.No.160-20-000090 (Work mentioned in para 2.90 of this note)	
		additional bills were prepared and approved. The concerned officers are responsible.	03.02.2021	Academy, BEML layout and surrounding areas in Raiarajeshwarinagar in ward	6
.02.64 Concerned enginee's are responsible	6,60,402.64	Though some of the works we're not performed as described in M.B.	19.12.2020 and	Improvements and maintenance to drains 1 <sup>st</sup> main road, Paryaya	90

																				Ť		14												
	Officers/Officials responsible	avukta. Bengaluru	1. Sri Doddaiah. Chief	Engineer TV C C Cell	2. Sri Sathish,	A.E.E,T.V.C.C. Cell,	3. Sri Vijay Kumar,	Chief Engineer,	4. Smt. Shilpa,		5. Sri Mohan,		6. Smt. Bharathi,	7. Sri Basavaraj,		8. Sri Siddaramaiah,		9. Sri Umesh,	-	10. Smt. Anitha,		11. Sri Guligouda,		12. Sri Srinivas,			14. Third party inspection	-dop-			1 19		<i>a</i> ?	/
	Amount misappropriated in Rs.	AC, Karnataka Loka	94,85,399.00																					>				93.00.464.00						
ANNEXURE-A	Findings of the I.O	M. Nagarathna, Assistant Executive Engineer-2, TAC, Karnataka Lokavukta. Bengaluru	Works that were not attended were	entered in the M.B. and excess	amount was mentioned in the		the concerned officers are held	responsible.		(Details of the same mentioned in the	iiivestigation (eport)				•			1 1 1 1						()		1.0	•	Works that were not attended were	entered in the M.B. and excess	amount was mentioned in the	approved for v	the concerned officers are held	responsible.	
	Date of inspection		01.12.2020																			(4)						02.12.2020						
	work	Officer:- Smt	evelopment	s in Vidhana	+4	s in ward		015.		n para 2. 46					í			5			. 9							and	Drains and	aggere Bus	hi circle.	.020.	n para 2.45	
	Name of the work	Investigation Officer - Smt.	Comprehensive development	of roads and drains in Vidhana	soudha layou	surround ng areas	no.69, Laggere.	J.C.No.059-20-000015.		(Work mentioned in para 2, 46 of this para)	(בורון פווון וח	×					-	ı. Ta	8				sec <sup>37</sup>					Improvements	maintenance of	Foothpath from Laggere	stand to Rajivgandhi circle	J.C.No.C69-20-000020	(Work mentioned in para 2.45	
	S. S.		93.		¥																		*		į			94			i i	/	_	

Toneso \*

				Amount	Officers/Officials
<u>SI</u>	Name of the work	inspection	Findings of the I.O	misappropriated	responsible
No.		mapaction		in Rs.	

Q

		_	_									_																				
	ži.	*/	20		ļ,	97.															96										95.	
(Work mentioned in para 2.93	J.C.No.129-20-000063	jnanabharathi ward no.129.	other surrounding areas in	jnana jyothinagar 9 <sup>th</sup> main and	maintenance of Drains to	Improvements and							of this note)	(Work mentioned in para 2.90	W	J.C.No.160-20-000033	jnanabharathi ward no.129	and other surrounding area in	jnana jyothi nagar 9 <sup>th</sup> main	maintenance to drains at	Improvements and	,	of this note)	(Work mentioned in para 2.84	.1 C No 129-20-000045	a bharathi ward	and surrounding areas in	cross roads in NGEF lavout	8th main	maintenance of Drains, 10th	Improvements and	of this note)
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \						19.12.2020					1	8									18.12.2020										08.12.2020	
nivesilgation report)	(Details of the same mentioned in the		sible.	officers approving it are held		Bill was prepared for the works that							investigation report)	(Details of the same mentioned in the		responsible.	the concerned officers are held	additional bill and approved for which	amount was mentioned in the	entered in the M.B. and excess	Works that were not attended were		investigation report)	(Details of the same mentioned in the	* 700 0000		the concerned officers are held	al bill and approved for w	was mentioned	entered in the M.B. and excess	Works that were not attended were	(Details of the same mentioned in the investigation report)
	*				11.5	1,14,96,443.00		588 8	s <sup>2</sup>	e .			1.0		(000 60	Qu.		0			1,19,94,455.00	* <sub>14</sub>	15							*	94,65,097.00	
	၂ က ၂	ָרני	4	ω	'n			14.	13	12.	1	10.	9.	œ	7.	ნ.	5	4.	ω	2												
Sri Siddaramaiah,	Smt. Bharathi,		Smt. Shilpa	Sri Viiav Kumar	Sri Sathish,	Sri Doddaiah,	team	. Third party inspection		. Sri Srinivas,			Sri Umesh,	Sri Siddaramaiah,	Sri Basavaraj,	Smt. Bharathi,	Sri Mohan,	Smt. Shilpa,	Sri Vijay Kumar,	Sri Sathish,	Sri Doddaiah,				team		4 Officers of K.B. D.I			Assistant Engineer	1. Sri Siddaraju,	

4

\* COT 800

					ANNEXURE-A			
9	No.	Name of the work	Date of inspection	tion	Findings of the I.O	Amount misappropriated in Re	Officers/Officials responsible	
		of this note)						
				====			9. Sri Umesh.	
					*		10. Smt. Anitha,	
							12. Sri Srinivas, 13. Officers of K P I D I	
	äÖ							741
	5	maintenance of Des 20	and 21.12.2020		During the investigation only some of		team	
				the work	the works mentioned in the M.B. were	1,27,60,725.00	1. Sri Doddaiah,	
		nada	π	round to	round to have been attended but bills			
			jnana	were profession	were prepared and approved for		4. Smt Shilns	_
		bharathi ward no. 129.		officers	officers are held responsible		5. Sri Mohan.	
		J.C. 189. 128-20-000035			and copolisione.			×
		(Work ment oped in 22.5.2 of	20.0	(Details	(Details of the same mentioned in the			
		of this note)	26.7	investiga	investigation report)	U.	8. Sri Siddaramaiah,	1
		10					_	
			, ,	0,				
			18.					
		in the second		35				
			E.	×			14. Officers of K.R.I.D.L	
-	99.	Imgroyements	+	+	State of the state		15. Third party inspection	
		to or an	40th US. 12.2020		Bill was prepared for the works that	1 23 64 074 00	ream 1	
-		cross, 6th main road and cross	880	were not	it performed and all the	00.4.0.4.0.1.	Sri Sathish	
		roads in Gurukrupa badavane	ane	Officers	approving it are held			
		and surrounding areas	2.⊑	esponsible.	ile.			
		jnana bharathi ward no.129.		(Details of			5. Sri Mohan.	-
		J.C. No.129-20-000042	P 4	investigati	investigation report)			
					(hodo)			
7		(vvork mentioned in para 2.86	.86	1			8. Sri Siddaramaiah,	
30 A	/	(2) (1) (2)	2				9. Sri Umesh,	
7	000							Š
ch.	200		-					-
	,,,,						13. Assistant Engineer	
, Te.	0							7

5.

The state of the s

	*	3 4 2 2		
102.	3	101.	100	No.
Improvements and maintenance to Drains at	of this note)	Improvements and maintenance of Drains to jnana jyothinagar 7 <sup>th</sup> main and other surrounding areas in jnanabharathi ward no.129 J.C.No.129-20-000032.  (Work mentioned in para 2.59	Improvements and maintenance to drains 11 <sup>th</sup> cross and 12 <sup>th</sup> cross and surrounding cross roads in papareddy palya in jnanabharathi ward no.129 J.C.No.129-20-000053 (Work mentioned in para 2.72 of this note)	Name of the work
29.12.2020	-	28.12.2020	23.12.2020	Date of inspection
Bills were prepared for the unattended works that were entered		During investigation some or me works mentioned in the M.B. were found unattended, but bills were prepared and approved. Concerned officers are held responsible.  (Details of the same mentioned in the investigation report)		Findings of the I.O
1,20,44,352.00		1.22,01,127,000		Amount misappropriated in Rs.
2. Sri Sathish,	Smt. Anitha, Sri Guligouda, Sri Srinivas, Officers of K.R.I.D.L. Third party inspection team.	2. Sri Sathish, 3. Sri Vijay Kumar, 4. Smt. Shilpa, 5. Sri Mohan, 6. Smt. Bharathi, 7. Sri Basavaraj, 8. Sri Siddaramaiah, 9. Sri Umesh,	14. Officers of K.R.I.D.L. 15. Third party inspection team  1. Sri Doddaiah, 2. Sri Sathish, 3. Sri Vijay Kumar, 4. Smt. Shilpa, 5. Sri Mohan, 6. Smt. Bharathi, 7. Sri Basavaraj, 8. Sri Siddaramaiah, 9. Sri Umesh, 10. Smt. Anitha, 11. Sri Guligouda, 12. Sri Srinivas, 13. Sri Chandregowda, 14. Third party inspection team.	responsible

				ANNEXURE-A			
Nam	Name of the work	work	Date of inspection	Findings of the I.O	Amount misappropriated in Rs.	Officers/Officials responsible	
jnana jyoth and other si jnana bhara J.C.No.129- (Work ment of this note)	jnana jyothinagar 10 <sup>th</sup> crand and other surrounding areas jnana bharathi ward no.129 J.C.No.129-20-000027 (Work mentioned in para 2 of this note)	jnana jyothinagar 10 <sup>th</sup> cross and other surrounding areas in jnana bharathi ward no.129 J.C.No.129-20-000027 (Work mentioned in para 2.61 of this note)		in the M.B. and were also approved. Concerned officers are held responsible. (Details of the same mentioned in the investigation report)		3. Sri Vijay Kumar, 4. Smt. Shilpa, 5. Stj Mohan, •6. Smt. Bharathi, 7. Sri Basavaraj, 8. Sri Siddaramaiah, 9. Sri Umesh, 10. Smt. Anitha, 11. Sri Guligouda, 12. Executive Engineer, 13. Sri Siddaraju, 14. Officers of K.R.I.D.L. 15. Third party inspection team	
Improvements maintenance of jnana jyothinagar other surroundin jnanabharathi war J.C.No.129-20-00 of this note)	Improvements maintenance of Drains jnana jyothinagar 7th main other surrounding areas jnanabharathi ward no.129 J.C.No.129-20-000062 of this note)	Improvements and maintenance of Drains to inana jyothinagar 7th main and other surrounding areas in inanabharathi ward no.129 J.C.No.129-20-000062 of this note)	19.12.2020	Bills were prepared for the unattended works that were entered in the M.B. and were also approved. Concerned officers are held responsible.  (Details of the same mentioned in the investigation report)	97,57,680.00	1. Sri-Doddaiah, 2. Sri Sathish, 3. Sri Vijay Kumar, 4. Smt. Shilpa, 6. Smt. Bharathi, 7. Sri Basavaraj, 8. Sri Ziddaramaiah, 9. Sri Umesh, 10. Smt. Anitha, 11. Sri Guligouda, 12. Sri Srinivas, 13. Officers of K.R.I.D.L 14. Third party inspection team.	
Improvements maintenance muneshwara and 12th surrounding a bharathi ward	35 SE O	and Drains at ingar 8th cross and cross and seas in jnana 2,129	30.12.2020	Bills were prepared for the unattended works that were entered in the M.B. and were also approved. Concerned officers are held responsible.	1,26,14,429.00	1. Sri Doddaiah, 2. Sri Sathish, 3. Sri Vijay Kumar, 4. Smt. Shilpa, 5. Sri Mohan, 6. Smt. Bharathi,	

	106.	105.	SI.
\	Improvements and maintenance to Drains at Malathahalli and Sunkadakatte cross roads and surrounding areas in jnana bharathi ward no.129.  J.C.No.129-20-000041  (Work mentioned in para 2.71 of this note)	J.C.No.129-20-00026  (Work mentioned in para 2.54 of this note)  Improvements and maintenance of Drains, 9th cross, 9th 'D' road in jnana jyothi nagar and surrounding areas in jnana bharathi ward no.129  J.C.No.129-20-000034  (Work mentioned in para 2.55 of this note)	Name of the work
	04.01.2021	08.12.2020	Date of inspection
	During investigation some of the works mentioned in the M.B. were found unattended, but bills were prepared and approved. Concerned officers are held responsible.  (Details of the same mentioned in the investigation report)	(Details of the same mentioned in the investigation report)  During investigation some of the works mentioned in the M.B. were found unattended, but bills were prepared and approved. Concerned officers are held responsible.  (Details of the same mentioned in the investigation report)	Findings of the I.O
	1,36,27,728.00	1,23,94,498.00	Amount misappropriated in Rs.
- 11	1. Sri Doddaiah, 2. Sri Sathish, 3. Sri Vijay Kumar, 4. Smt. Shilpa, 5. Sri Mohan, 6. Smt. Bharathi, 7. Sri Basavaraj, 8. Sri Siddaramaiah, 9. Sri Umesh, 10. Smt. Anitha	7. Sri Basavaraj, 8. Sri Siddaramaiah, 9. Sri Umesh, 10. Smt. Anitha, 11. Sri Guligouda, 12. Executive Engineer, 13. Sri Siddaraju, 14. Officers of K.R.I.D.L 15. Third party inspection team 1. Sri Doddaiah, 2. Sri Sathish, 2. Sri Sathish, 3. Sri Vijay Kumar 4. Smt. Shilpa, 5. Sri Mohan, 6. Smt. Bharathi, 7. Sri Basavaraj, 8. Sri Siddaramaiah, 9. Sri Umesh, 10. Smt. Anitha, 11. Sri Guligouda, 12. Sri Srinivas, 13. Sri Siddaraju, 14. Officers of K.R.I.D.L 15. Third party inspection	Officers/Officials responsible

CON KNOO

				ANNEXURE-A		
S S	Name of the work	the work	Date of inspection	Findings of the I.O	Amount misappropriated in Rs.	Officers/Officials responsible
						11. Sri Guligouda, 12. Sri Srinivas, 13. Sri Siddaraju, 14. Officers of K.R.I.D.I
107	Improvements and maintenance to Drains in Juana jyothi nagara 14 <sup>th</sup> cross, 15 <sup>th</sup> cross, and other surrounding areas in Jnanabharathi ward no.129. J.C.No.129-20-000058	and Drains in ara 14 <sup>th</sup> cross, and other areas in trd no.129.	04.01.2021	During investigation some of the works mentioned in the M.B. were found unattended, but bills were prepared and approved. Concerned officers are held responsible.  (Details of the same mentioned in the investigation report)	1,04,93,342.00	بن الله الله الله الله الله الله الله الل
			. 4			9. Sri Umesh, 10. Smt. Anitha, 11. Sri Guligouda, 12. Sri Srinivas, 13. Sri Siddaraju, 14. Officers of K.R.I.D.L
8.0 8.0 8.0 8.0 8.0 8.0 8.0 8.0 8.0 8.0	Improvements and maintenance to drains at Muneshwara nagar 1st cross and ullal rrain road surrounding cross roads in papa reddy palya in jnanabharathii ward no.129. J.C.No.129-20-000025 (Work mentioned in para 2.80 of this note)	and to drains at nagar 1st cross rain road cross roads in ward no.129.	05.01.2021	During investigation, it was found some bills were not made for the works attended, but at the same time additional bills were found approved for which concerned officers are held responsible.  (Details of the same mentioned in the investigation report)	1,02,61,423.00	
10				*		11. Sri Guligoud

ANNEXURE-A Date of inspection  Findings of the I.O misappropriated in Rs.  O7.01.2021  Some of the works that were not attended were mentioned in the M.B. and accordingly bills were prepared and approved, for which the concerned officers are held responsible. Substandard asphalt work carried out.  (Details of the same mentioned in the investigation report)
1990 MF M 13 KJ 11

				ANNEXURE-A			
" Z	SI, Name of the work	the work	Date of inspection	of ion Findings of the I.O	Amount misappropriated	Officers/Officials	П
	Basaveshwara	ne a		Were prepared additionally	in Rs.		
	Rajarajeshwari	nagar ward		ned of		4. Smt. Shilpa,	
	J.C.No.160-20-000052	000052			•		•
	(Work mentioned in page 2.2			(Details of the same mentioned in the investigation report)		271 22	
_	of this note)	III pala 2.31				9. Sri Umesh,	
						10 0	
				22 75			
112.	2. Improvements t	11 1000				15. Third party inspection	_
	Dwaraka east	st loads in	15.01.2021	During investigation the works that	16144 241 00	team.	
	Surrounding	area in		were attended previously were found to have been reported	00.112,51.	1. Sri Doddaiah, 2. Sri Sathish	
	No 160	gara in ward		the works mentioned in the M B were			
-0-	J.C.No.16C-20-000043	0043		left unattended. Substandard asphalt	6,	4. Smt. Shilpa,	
	(Work mention			out.		6. Smt. Bharathi	
	of this note;	n para 2.33	98	approved for which concerned officers	**		
				are neld responsible.	P A	o. ori olddaramaiah, 9. ori Umesh	
				(Details of the same mentioned in the			
				Investigation report)		<ol> <li>Sri Guligouda,</li> <li>Sri Srinivas</li> </ol>	
				**			
113.	Improvements to	roads at	15.01.2021	. 1		14. Third party inspection	
	Giridhama	layı	7	as noticed for which average	1,70,60,722.00	Sri Doddajah	
		nagar and		amount was paid. Substandard			
	ari na	lara in ward		asphalt work carried out. Some of the works that were unattended	Ω 4.	5. Sri Vijay Kumar, 4. Smt. Shilna	
38	J.C.No.160-20-000033	033		mentioned in the M.B. towards which additional bill was presented	<u>τυ, το,</u>		
ಲ್ಟ್				ပိ	7		
000				***		oil Siddaramaiah,	

-					115								-	114		30.12			1	No.	<u>s</u>		
	(Work mentioned in para 2.35 of this note)	J.C.No.160-20-000041	اسا مؤلا	Dwaraka layout BEML 4th	Improvements to roa		2	Of Kills (1994)	(Work mentioned in para 2.34 of this note)	C. C. 120.	ġ	stage and surrounding area in Rajarajeshwari nagara in	Dwaraka layout, BEML 4"	Dr.Arunachalam Road	5		of this note)	(Work mentioned in para 2.36			Name of the work		
)					08.01.2021								,		16.01.2021						inspection	Date of	
	(Details of the same mentioned in the investigation report)	held responsible.	additional bill was prepared and additional bill was prepared work approved. Substandard asphalt work approved. All concerned officers are	been repeated and itemiorical accordingly in the M.B. for which	vere fou			Investigation report	(Details of the same mentioned in the	held responsible.	carried out. All concerned officers are	additional bill was prepared and	he M.B. for v	attended earlier were found to have heen repeated and mentioned	During investigation works that were		investigation report)	(Details of the same mentioned in the	held responsible.			Findings of the I.O	ANNEXONES
	TO TO		0 7-0			-				-					1,37,49,575.00						in Rs.	misappropriated	Amount
13. Sri Chandregowda	10. Smt. Anitha, 11. Sri Guligouda, 12. Sri Srinivas			4. Smt. Shilpa,	<ul><li>2. Sri Sathish,</li><li>3. Sri Vijay Kumar,</li></ul>	1. Sri Doddaiah,	14. Third party inspection team	13. Sri Chandregowda,		9 Sri Oriesii,	0.0	6 Smt. Bharathi,	5. Sri Mohan,	3. Sri Vijay Kumar,	2. Sri Sathish.	team	٠.	12 Sri Srinivas,				responsible	Officers/Officials

Soresou ...

Officers/Officials responsible	14. Third party inspection team 1. Sri Doddaiah, 2. Sri Sathish, 3. Sri Vijay Kumar, 4. Smt. Shilpa, 5. Sri Mohan, 6. Smt. Bharathi, 7. Sri Basavaraj, 8. Sri Clmesh, 9. Sri Umesh,	
Amount misappropriated in Rs.	1,20,29,416.00	29,20,54,737.00 I is as below:
F Findings of the I.O	During investigation sub-standard works were noticed and repetition of noticed for which additional bills were asphalt work carried out. All the responsible.  (Details of the same mentioned in the investigation report	SI. Name of Investigation Officers the amount of misappropriation is as below:
Date of inspection	18.01.2021	on Officers
Name of the work	Improvements to roads at Sudharshan badavane, Chandrashekar Block, Badavane and surrounding area in Rajarajeshwarinagara ir ward no.160.  J.C.No.160-20-00035  (Work mentioned in para 2.37 of this note)	SI. Name of Investigation Office
o N N O N O N O N O N O N O N O N O N O	4s pe	

of insappropriation is as b	riated as per							
decinical h	Amount misapprop	I.O reports	Rs. 23,68,20,263/-	Rs. 32,60,43,419/-	Ks. 20,76,53,469/-	Ks. 12,00,07,909/-	RS. 29,20,54,737/- Rs 118 25 75 75	-//6//67/077
Namo of L	The of investigation Officer Amount misappropriated as ner	Sri. R. Ravishankar					ted	
SI.	No.	1	2	3	4	5	Total a	1.740

State of Karnataka.

A STANE

