Final Report
On

Comprehensive Assessment of Thippagondanahalli Reservoir Catchment Area and its Preservation Zone

August, 2015

Volume-II
(Writ Petitions)

Prepared By

Center for Lake Conservation (CLC)
Environmental Management and Policy Research Institute (EMPRI)

Final Report on

Comprehensive Assessment of Thippagondanahalli Reservoir (TGR) Catchment Area and Its Preservation Zone

Volume-II
(Writ Petitions)

Submitted to

HON'BLE HIGH COURT OF KARNATAKA, BENGALURU

August, 2015

(Hon'ble High Court of Karnataka Order dated 02/02/2015 in WP. No.38218/2013)

Prepared By:

Centre for Lake Conservation,
Environmental Management and Policy Research Institute (EMPRI),
Department of Forest, Ecology and Environment,
Government of Karnataka

Chapter No.	Content	Page No.
	Volume-I	
	Executive Summary	i
1	General Introduction	001
2	TGR Catchment Area and Notification	010
3	Literature Survey: Analysis of Study Reports Published for TGR catchment area	024
4	State of Affairs in TGR Catchment Area (ToR-1)	043
5	Change in Landuse/ Landcover for the period 2003-2014 (ToR-2, 3 & 4)	179
6	Water Yield and Availability (ToR-6)	206
7	Water Quality Deterioration and Reasons for Pollution (ToR-7 & 8)	215
8	An Analysis of Various Stakeholder Meetings	243
9	Methodologies Adopted in other States in India and other Countries for Rejuvenation, Conservation and Preservation of Rivers and River Courses in Urban Agglomerations (ToR-9)	252
10	Conclusions and Recommendations (ToR-10)	288
	Reference	308
	Volume-II (ToR-5) (Writ Petitions connected to 38218/2013)	
11	Commercial Superstructures	312
12	Residential Superstructures (WP.No.48047/2013)	386
	Atlas for Commercial Superstructures under Litigation	1039

Volume-III
(Annexures)

Chapter-1: General Introduction

1.1	TGR Preservation Notification dated: 18.11.2003	1099
1.2	TGR Preservation Notification Withdrawal Order dated: 24.07.2014	1103
1.3	Hon'ble High Court Interim Order on WP No. 38218/ 2013 dated 28.11.2014	1106
1.4	Hon'ble High Court Interim Order on WP No. 38218/ 2013 dated 18.12.2014	1110
1.5	Hon'ble High Court Interim Order on WP No. 38218/ 2013 dated 02.02.2015	1113
1.6	Government of Karnataka Order dated: 02.12.2014	1116
1.7	Constitution of Technical/ Advisory Committee for TGR Project dated: 03.12.2014	1120
1.8	EMPRI Office Memorandum for Constitution of Technical/ Advisory Committee of TGR Project dated: 04.03.2015	1122
1.9	Proceedings of Three Advisory Committee Meetings dated: 06.12.2014, 12.02.2015 and 10.04.2015	1124
1.10	Proceeding of Technical Committee Meeting dated: 27.03.2015	1141

Chapter-2: TGR Catchment Area and Notification

2.1	Bangalore Urban Zilla Panchayat Order dated: 12.04.2011	1145

Chapter-3: Literature Survey

3.1	Thippagondanahalli Biodiversity Report by IISc.	1146

3.2	Project Report on "Change Analysis of Drainage Pattern for TGR Catchment Area" by Chandana, A.L.	1161

Chapter-4: State of Affairs in TGR Catchment Area

4.1	Table Containing the Observations in the TGR	1197
4.2	Table Containing the Observations in the Hesaraghatta Reservoir	1199
4.3	Table Containing the Observations in Zone-2 villages of TGR Catchment area	1200
4.4	Table Containing the Observations in Zone-3 and 4 villages of Arkavathi River Course	1203
4.5	Table Containing the Observations in Zone-3 and 4 villages of Kumudvathi River Course	1220
4.6	Table Containing the Observations in Zone-1 villages of Hesaraghatta Sub-catchment Area	1224
4.7	Table Containing the Observations in Zone-1 villages of Arkavathi Sub-catchment Area	1237
4.8	Table Containing the Observations in Zone-1 villages of Kumudvathi Sub-catchment Area	1244

Chapter-5: Change in Landuse/ Landcover for the period 2003-2014

5.1	Village-wise Landuse/ Landcover Change Data between the years 2003 and 2014	1251
5.2	Village-wise Changes in Built-up Area between the years 2003 and 2014	1335
5.3	Village-wise Landuse/ Landcover Maps between the years 2003 and 2014	1343
5.4	Arkavathi River Sub-catchment: Village-wise Changes in Area under Superstructures between the years 2004 and 2014	1389

5.5	Kumudvathi River Sub-catchment: Village-wise Changes in Area under Superstructures between the years 2004 and 2014	1404
5.6	Note on Encroachment of Tanks	1408
5.7	TGR Catchment Area Drainage Change Analysis	1420

Chapter-8: Analysis of Various Stakeholder Meetings

8.1	Bachenahatti Gram Panchayat Meeting Proceedings dated: 17.12.2014	1427
8.2	Choudanayakanahalli Gram Panchayat Meeting Proceedings dated: 19.12.2014	1430
8.3	Nelamangala Taluk Panchayat Meeting Proceedings dated: 12.01.2015	1434
8.4	Bangalore North Taluk Panchayat Meeting Proceedings dated: 17.01.2015	1439
8.5	Status Report of the Monitoring Committee Constituted for TGR	1445
8.6	'The Karnataka Arkavathi and Kumudvathi River Basin Conservation and Development Bill, 2013' proposed by UDD	1453
8.7	NPA letter regarding TGR catchment area dated: 03.03.2015	1471
8.8	MPA letter regarding TGR catchment area dated: 18.03.2015	1475
8.9	DMG letter regarding TGR catchment area dated: 30.03.2015	1484
8.10	KSPCB letter regarding TGR catchment area dated: 26.02.2015	1489
8.11	BIAAPA letter regarding TGR catchment area dated: 27.03.2015	1492

Chapter-10: Conclusions and Recommendations

10.1	Proceeding of Research and Training Advisory Committee (RTAC) Meeting of EMPRI dated: 16.04.2015	1493
10.2	Concept Note on Utilization of Recycled Water for Recharging the Arkavathi Sub-catchment Area	1499
10.3	Concept Note on Decentralised Wastewater Treatment Systems (DEWATS)	1501

Chapter-11: Commercial Superstructures

11.1	Gramin Bhandara Yojana/ Rural Godown Scheme (RGS)	1505
11.2	*Panchanama* for ground verification of Superstructures involved in Writ Petitions	1506

Chapter-12: Residential Superstructures

12.1	Spot Verification Questioner	1561
12.2	Village wise *Panchanama* for ground verification of Superstructures involved in Writ Petitions	1563
12.3	List of Petitioners in the Adakimaranahalli village	1587
12.4	List of Petitioners in the Siddanahosahalli village	1594
12.5	List of Petitioners in the Dombarahalli village	1599
12.6	List of Petitioners in the Tarabanahalli village	1603
12.7	List of Petitioners in the Sasuveghatta village	1607
12.8	List of Petitioners in the Makali village	1610
12.9	List of Petitioners in the Heggadadevanapura village	1613
12.10	List of Petitioners in the Madanayakanahalli village	1616

12.11	List of Petitioners in the Kadaranahalli village	1619
12.12	List of Petitioners in the Lakshmipura village	1621
12.13	List of Petitioners in the Hanumanthasagara village	1622
12.14	List of Petitioners in the Kumbarahalli village	1623
12.15	List of Petitioners in the Bilijaji village	1624
12.16	List of Petitioners in the Soladevanahalli, Harokyathanahalli and Hesaraghatta villages	1624

Chapter–11: Commercial Superstructures

11.1. Introduction:

As a conservation measure to protect the Thippagondanahalli Reservoir catchment area measuring 1453 square kilometres, the Department of Ecology and Environment, GoK issued a Government Order under section-5 of the Environment (Protection) Act, 1986, dated 18th November 2003, by declaring the entire catchment area as ecologically sensitive, classifying into four zones and prohibiting different types of development activities in the catchment area. Thippagondanahalli Reservoir catchment area has been categorized into four zones and the regulations are described below:

Zone-1: **Entire Thippagondanahalli reservoir catchment:** Exploitation of ground water should be monitored and no fresh leases or licence for mining, quarrying and stone crushers should be granted.

Zone-2: **Area covered within 2 kilometres from the Thippagondanahalli reservoir boundary:** Except agricultural activities all other activities are prohibited without prior permission.

Zone-3: **Area that falls within 1 kilometre distance from the river banks of Arkavathi and Kumudvathi:** No activities other than agriculture and related activities are permitted without prior permission.

Zone-4: **Area that falls within 1 to 2 kilometres distance from the above mentioned rivers upto Hesaraghatta tank:** only Green category industries having scientific waste treatment facilities and rainwater harvesting system are permitted. Permit new buildings with only ground and first floor with mandatory adoption of rainwater harvesting systems.

The catchment area of the reservoir extends upto Dobbaspet towards North-West of Bangalore city on the Bangalore-Tumakuru NH-4 and upto Nandi hills, about 60 Kms North of Bangalore city covering the Taluks of Doddaballapur, Chikkaballapur, Devanahalli, Bangalore North, Bangalore South, Magadi and Nelamangala. There are 735 villages coming under the scheduled zones of the TGR catchment area.

Unplanned developments in the catchment areas (that includes houses, layouts and commercial establishments) has adversely affected the quality of water and also reduced inflow of water into the reservoir. Increasing urbanization and industrialization has led to alteration of the drainage pattern in the TGR catchment area. In the year 2013, a general demolition notification was issued through a publication in the newspaper under Section 15(4) and 17(4) of Karnataka Town and Country Planning Act, 1961 to all the building owners, as their structures situated are in Zone-3 of the Notification. Since the notice was published in the newspaper as a general notice, some of the farmers and land owners having buildings in the notified area approached the Hon'ble High Court in the year 2013.

In this background in accordance with one of the terms of reference of the study entrusted to EMPRI by Hon'ble High Court, a survey was carried out to study the current status of the structures that are the subject matter in the batch of writ petitions No. 38218/2013 and its connected 61 cases filed before the Hon'ble High Court of Karnataka (WP Nos. 38218/2013; 38493-505/2013; 38697-701/2013; 38795-800/2013; 38492/2013; 38518/2013; 39030/2013; 38506/2013; 39029/2013; 38183/2013; 39614/2013; 39938-40/2013; 40193/2013; 40269-273/2013; 41793-794/2013;41042-43/2013; 40970/2013; 40508/2013; 38793/2013; 38737/2013; 44160/2013; 40779/2013; 40782/2013; 40781/2013; 40783/2013; 40780/2013; 40411-413/2013;48047/2013 and 58328/2013).

Eventually, during the survey an effort has been made to understand the nature of the structure, utilization of the land, purpose for which they are presently utilized and also its impacts on environment.

11.2. Location of the Writ Petitions Superstructures:

Structures that are subject matter in the batch of writ petitions which are filed before the Hon'ble High Court of Karnataka (Details of the 61 writ petitions is given in the (Table-11.1) are mainly from the villages of two taluks i.e. Bangalore North and Magadi and most of these structures are in the Zone-3 of the river banks of Arkavathi and Kumudvathi. Most of these structures have been found to be godowns for storage purpose except one writ petition (Writ Petition No.48047/2013), which involves 870 households.

Out of 61 writ petitions, 58 WP's are connected to GODOWNS (in Zone-3) of the Bangalore North Taluk; one WP is connected to LAYOUT DEVELOPMENT (in Zone-3) of Magadi Taluk; one WP is connected to INDUSTRY (in the Zone-4) of the Bangalore North Taluk (Figure-11.1); and one WP is connected to 870 RESIDENTIAL HOUSES of 20 Villages (falling in Zone-1, 3 and 4) of the Bangalore North Taluk. Most (99%) of the petitions are filed from the villages near the Arkavathi and remaining 1% are filed from the Kumudvathi river stretch village. These villages come under the jurisdiction of Bangalore Development Authority (BDA), Magadi Planning Authority (MPA) and Bangalore Mysore Infrastructure Corridor Area Planning Authority (BMICAPA). Table-11.2 and Figure-11.2 shows the Planning Authorities under which the Writ Petitioners villages are falling.



Figure-11.1: Writ Petitions filed from 10 Villages

Table-11.2. Location of 61WP Superstructures

Sl. No	Villages	No. of WP's	Jurisdictions of	Hobli	Taluk
1	Adakamaranahalli	08	BDA	Dasanapura	Bangalore North
2	Dasanapura	02			
3	Dombarahalli	02			
4	Harokyathnalli	01			
5	Heggadadevanapura	10			
6	Makali	18			
7	Siddanahosahalli	04			
8	Hurulichikkanahalli	01		Hesaraghatta	
9	Madanayakanahalli	14	BMICAPA	Dasanapura	
10	Basavenahalli	01	MPA	Solur	Magadi
	Total	61			



Figure-11.2: Village-wise location of Writ Petitions

11.3. Methodology:

Before carrying out the survey, an Advisory Committee Meeting was convened on 12th February, 2015 in the Vikasa Soudha, by inviting all the consent Departments/ Authorities. In that meeting a committee with members from the concerned Departments/ Authorities was formed to carry out the survey and subsequently two representatives representing petitioners were nominated to be present during the survey by the committee. The committee was headed by Sri. V. Sreenivas, Research Scientist, EMPRI. The following (Table-11.3) are the members nominated by the consent Departments/ Authorities:

Table-11.3. Ground verification team nominated by the consent Dept./ Authorities

Sl. No	Name, Designation and the Departments/ Authorities
1.	**Sri. V. Sreenivas,** Research Scientist, EMPRI
2.	**Sri. Balappa,** Addl. Tahsildar, Bangalore North Taluk Panchayat, Bangalore Urban District
3.	**Sri. Lamani,**Tahsildar, Bangalore North Taluk Panchayat, Bangalore Urban District
4.	**Sri. Dayananda,** Tahsildar, Bangalore South Taluk Panchayat, Bangalore Urban District
5.	**Sri. Madhusudhan,** EO, Karnataka State Pollution Control Board
6.	**Sri. S. S. Shamanna,** Deputy Director, Town Planning, Bangalore Development Authority
7.	**Sri. Shridhar,** Asst. Director, Bangalore North Taluk Panchayat, Bangalore Urban District
8.	A representative from BMICAPA
9.	**Sri. V. Venu Gopal,** A representative from petitioners' side
10.	**Sri. Ravi Kumar,** A representative from petitioners' side

The schedule of the field survey was intimated to the members and to the representatives of the petitioners through Email or Letters and subsequently the field survey was carried out. The observations made during the ground truth survey of each writ petitioners land were recorded and photographs, videos were also taken along with the geo-tagged reference and the same transferred to the GIS domain. Further, a statement (PANCHANAMA) was written in the presence of all the members of the committee, petitioner and local people of the village along with their signatures (Note: The GPS location of all the WP's were taken by using Garmin GPS. The accuracy of the used GPS is ± 5 to 10m and for more accuracy this can be checked by the Revenue Department).

11.3.1. Field Visits Schedule:

As per the schedule the field survey was carried out by the EMPRI's team along with the members nominated by the concerned departments/authorities. In the month of February, 2015 the field visits were scheduled, over all 10 field visits were made by covering 60 writ petitions and per day two to eight writ petition related structures were surveyed. The date wise details of the field visits are given in the Table-11.4 and the details of the Officials who involved in the field visits are given in the Table-11.5.

Table-11.4. Details on ground verification of writ petition superstructures

Sl. No	Date of Visit	Writ petition no.	Survey No.	Village
1	19.02.2015	38797/2013	45/1	Heggadadevanapura
		38697/2013	64 & 72/2	
		40193/2013	64/4	
		40269/2013	63	
		38698/2013	72/1	

Sl. No	Date of Visit	Writ petition no.	Survey No.	Village
2	21.02.2015	40779/2013	6/5	Madanayakanahalli
		40781/2013	53/11	
		40780/2013	6/8 & 6/4	
		40508/2013	12/7,1,7B	
		38218/2013	52/3	
		41042/2013	6/7	
3	24.02.2015	38518/2013	52/4B & 51	Madanayakanahalli
		40782/2013	8/1	
		39940/2013	50	
		40411/2013	53/6-9	
		40412/2013		
		40413/2013		
		40783/2013	53/10	
		39939/2013	41/1	Heggadadevanapura
		39029/2013	65/1	
4	26.02.2015	40272/2013	65	Heggadadevanapura
		38699 (a)/2013	6/10	Makali
		38700(b)/2013	10	
		39614/2013	10	
		38505/2013	06	
		38483/2013	06	
		38500/2013	06	
		38504/2013	06	
5	28.02.2015	38793/2013	14	Makali
		38796/2013	09	
		38797/2013		
		38798/2013		
		38799/2013		
		40270/2013	5/2 & 5/10	Makali
		38800/2013	6/2	
		38737/2013	13	
		38183/2013	11/2, 11/6, 11/9	
		38506/2013	11/2, 11/6, 11/9	
6	03.03.2015	38501/2013	24/2	Dombarahalli
		38499/2013	24/2	
		38503/2013	32	Siddanahoshalli
		40970/2013	27/2C & 31/2A	
		39030/2013	5/1	

Sl. No	Date of Visit	Writ petition no.	Survey No.	Village
		39938/2013	6/4	Makali
		39939/2013		
		39940/2013		
7	05.03.2015	38701/2013	8/2	Adakamaranahalli
		38492/2013	04	
8	07.03.2015	41793/2013	100	Dasanpura
		41794/2013		
		40273/2013	67/4	Heggadadevanapura
		38502/2013	06	Adakamaranahalli
		38498/2013	102/1	Harokyatanahalli
9	31.03.2015	38493/2013 (1a)	4/1P1	Adakamaranahalli
		38494/2013 (1b)	04/2	
		38495/2013 (1c)	04/2	
		38496/2013 (1d)	04/2	
		38497/2013 (1e)	04/2	
		58328/2013	74	Basavenahalli
10	04.04.2015	40271/2013	64	Heggadadevanapura
		44160/2013	74	Hurulichikkanahalli

Table-11.5. Officials involved in the Ground verification of WP's superstructures

Sl. No	Name & Designation of the official	Departments
1	**Sri. V. Sreenivas,** Research Scientist	EMPRI, Headed the survey
2	**Sri. Madhusudhan,** Environmental officer	Karnataka State Pollution Control Board
3	**Miss. Maheshwari Singh,** Asst. Environmental Officer	Karnataka State Pollution Control Board
4	**Sri. Shamanna,** Deputy Directory, Town Planning	Bangalore Development Authority
5	**Sri. Suresh Pratap Singh,** Assistant Director	Bangalore Development Authority
6	**Sri. Ravishankar,** Assistant Engineer, TPM	Bangalore Development Authority
7	**Sri. Udaykumar,** Assistant Engineer	Bangalore Development Authority
8	**Sri. Sridhar,** Assistant Director	Bangalore North Taluk Panchayat
9	**Sri. Sharanappa,** Assistant Director	Bangalore North Taluk Panchayat
10	**Sri. Anandraj,** Revenue Inspector	Bangalore North Tahsildar Office

Sl. No	Name & Designation of the official	Departments
11	**Sri. N. Anil,** Revenue Inspector	Madavara circle, B'luru(N)
12	**Sri. Dhananjay,** Village Accountant	Madavara Circle, Alur GP
13	**Smt. Anita**, Secretary	Alur Gram Panchayat
14	**Sri. D. Venkatesh,** Secretary	Dasanpura Gram Panchayat
15	**Sri. Ravikumar,** Bill collector	Madanayakanahalli Gram Panchayat
16	**Sri. Lakshmipathi**, Bill collector	Madanayakanahalli Gram Panchayat
17	**Sri. V. Venugopal**	Representative representing petitioners
18	**Sri. Ravikumar**	Representative representing petitioners

11.4. Ground Verifications and Field Observations of the Superstructures for Writ Petitions

Since the details of all the 61 Writ Petitions which also includes one Writ Petition (No. 48047/2013) involving 870 households are very voluminous, the report for the Writ Petitions has been prepared in a separate volume (Volume-II).

Ground truth verification of each of the structures/ buildings involved in the 61 writ petitions were carried out and in some cases it was found that 3 to 4 writ petitions are filed by one petitioner. Out of 61 writ petitions most of the writ petitions are in the villages of Bangalore North Taluk i.e. Makali, Madanayakanahalli, Heggadaddevanapura and Adakamarnahalli. The ground verification was intended to gather information pertaining to the nature of the structure, utilization of the land and purpose of utilization of the structures that are subject matter in the batch of writ petitions.

While carrying out the ground truth survey of the petitioners land/ property it was found that godowns have been constructed over an area varying from 1 to 5 Acres or more than 5 Acres in the agricultural land and in some cases 4 to 5 godowns have been constructed in one survey number and also one godown having 3 to 5 partitions with different type of utilities were found. In some cases the godowns constructed in the lake bed and all these godowns are within 1 Km radius of the restricted zone of the Arkavathi river stretch. It was also found that a layout is coming up in the restricted zone of the Kumudvathi river stretch.

While interacting with the petitioners it was found that, all the rural godowns have been constructed under the Rural Godown Scheme or Gramin Bhandaran Yojana initiated during the year 01.04.2001 (Annexure–11.1). Most of the lands for construction of the godowns are inherited properties from their forefathers because of division of property among legal heirs. Further, the objective of this scheme was creation of scientific storage capacity with allied facilities in rural areas to meet out various requirements of the farmers for storing farm produce, processed farm produce, agricultural inputs, etc., and prevention of distress sale by creating the facility of pledge loan and marketing credit.

During the field survey, it was also found that all the constructed rural godowns have been approved by the Gram Panchayat by sanctioning NOC, General Licenses, Plan approval and in subsidy the banks have given the loans. Subsequently these godowns have not been

utilized for storage of agricultural produce since there is no requirement for such storage. These godowns have been rented out to various reputed companies for warehouse purpose and it was also found that presently these godowns are being used for storing goods like, electronic gadgets, automobiles, reliance network accessories, fabrics, chemicals, gas cylinders, finished cosmetics products, Groceries, Biscuits, and others. In some cases the godowns were rented out to the garments units which have been subsequently closed due to closure order issued by the Bangalore-Mysore Infrastructure Corridor Area Planning Authority (BMICAPA) as the garment units were located in the restricted Zone-3. Further it was also found that some of the godowns have remained vacant from past 6 months to 1 year. The details of the current status of the writ petitioners on survey number basis are given in the Table-11.6 below:

Table-11.6. Existing status of the WP's superstructure

Sl. No.	Villages	No. of WP's	Total Structure/ Godowns	Working	Non-Working	Purpose of Utility
1	Adakamaranahalli	08	16	16	0	Ware Houses
2	Dasanapura	02	2	0	2	College
3	Dombarahalli	02	6	6	0	Ware Houses
4	Harokyathnalli	01	1	0	1	Vacant
5	Heggadadevanapura	10	16	10	6	Ware Houses & Vacant
6	Madanayakanahalli	14	23	19	4	Ware Houses & Vacant
7	Makali	18	42	29	13	Ware Houses, LPG Stock & Vacant
8	Siddanahosahalli	04	14	14	0	Ware Houses
9	Hurulichikkanahalli	01	1	1	0	Industry
10	Basavenahalli	01	1	1	0	Residential Layout
	Total	61	122	96	26	

Further the survey also reveals that 95% of these godowns are having borewells which is the main source of water and some are also having septic tanks for the discharge of sewerage water. Further the survey witnessed existence of many other godowns all around the godowns of the petitioners, indicating rampant development of similar structures through the Grameena Bhandara Yojana.

The ground truth observations and also the information collected while interacting with the petitioners are discussed below village wise. Further, the PANCHANAMA for the ground verification for each commercial superstructure under the litigation are annexed in the Annexure–11.2 (Volume-III).

11.4.1. Writ Petitions of Makali Village of the Bangalore North Taluk:

There are 18 writ petitions filed from Makali village and there are few cases where 02 to 04 petitions have been filed by one petitioner. The Makali village falls in the Zone-3 of the Arkavathi river stretch (Figure-11.3).

According to the survey it was found that a total of 38 structures have been constructed in the lands of the petitioners. Out of 42 structures, 29 are godowns and currently these godowns are used for warehouse purpose and remaining 13 godowns are vacant. Further, the survey witnessed that all the godowns which are working are rented out.

It was also observed that 99% of the land owners in the Makali village have constructed agricultural godowns over an extent varying from 1 to 9 acres, in few cases it was found that 3 to 5 godowns have been constructed in same land and also one godown having 3 to 5 partitions are being used for different types of utilities. Further, it was found that 90% of the godowns are having borewells. Septic tanks are also constructed in some cases for the discharge of waste water. In many places these are not connected and not functioning. The survey revealed that all these rural godowns have been constructed under Gramina Bhandarah Yojana by taking approval by the Gram Panchayat and all these godowns are located within 1 Km radius of the restricted zone of the Arkavathi river stretch. The current status of 18 writ petitions structures in the Makali village are discussed below;



Figure-11.3: Location of Makali village in TGR Zone Map
(Source – NPA)

11.4.1.1. Writ Petition No. 38504/2013: In the Survey No. 6 of an extent of 4.05 Acres, four godowns has been constructed in the year 2004 (Figure-11.4). Out of four godowns three godowns are rented out to the companies i.e. M/s. Break Bouce, M/s. English Blazer (Branch of Gokul Das) and M/s. V-Xpress and remaining one godown is presently vacant. Currently, readymade garments were stored in the two godowns and chemicals and engine oil were stored in another godown. It was found that, 400 employees were working in these godowns. There are two borewells in this survey number which is the main source of water. Further, it was found that the waste water is discharged into septic tank.

Survey No. 6	

Figure-11.4: Location of WP superstructure in Google Earth image-2014

11.4.1.2. Writ Petition No. 38505/2013: In the Survey No. 6 in an extent of 1.5 Acres, one godown (Figure-11.5) has been constructed in the year 2005. It was also found that two towers and three residential houses been constructed in this survey number. The existing godown has been rented out to the company M/s. Colgate Palmolive (I) Ltd. Currently the Colgate products were stored in this godown. It was found that, 20 employees were working in this godown. There is one borewell in this survey number which is the main source of water. It was found that daily 1000 lts of water is being utilized and septic tank has been constructed for the discharge of waste water.

Survey No. 6	

Figure-11.5: Location of WP superstructure in Google Earth image-2014

11.4.1.3. Writ Petition No. 38500/2013: In the Survey No. 6 of extent 01 Acres, two godowns (Figure-11.6) have been constructed in the year 2006. It was also found that eight shops and eight residential houses have been constructed in this survey number. The existing two godowns are rented out to the companies i.e. M/s. AAJ Enterprises (Pvt). Ltd. and M/s. Colgate Palmolive (I) Ltd. Currently books and Colgate products were stored in these two godowns. It was found that, 30 employees were working in these two godowns. One borewell was found in this survey number which is the main source of water. It was found that daily 1000 lts of water is being utilized and waste water is being discharged into septic tank and also movement of Heavy Motor Vehicle were observed during the survey.

Survey No. 6	

Figure-11.6: Location of WP superstructure in Google Earth image-2014

11.4.1.4. Writ Petition No. 38483/2013: In the Survey No. 6 of an extent of 6 Acres, four godowns (Figure-11.7) has been constructed in the year 2001-02. In this survey number along with godowns four shops were found which have been rented out. Out of four godowns two godowns are rented out and remaining two are vacant. It was also found that one of the godowns been partitioned and rented out to two companies i.e. M/s. Reliance Communication and M/s. Franke Faber (I) Pvt. Ltd. Currently the godowns were stored with mobile accessories, kitchen cookware and electronic goods. Further, it was found that two godowns are vacant. Overall 40 employees are working in these companies. One borewell was found in this survey number which is the main source of water. Further it was found that daily 1500 lts of water is being utilized and subsequently, the waste water is being discharged into septic tank.

Survey No. 6	



Figure-11.7: Location of WP superstructure in Google Earth image-2014

11.4.1.5. Writ Petition No. 39614/2013: In the Survey No. 10 of extent 7.39 Acres, five godowns (Figure-11.8) were found. The existing five godowns are rented out for the companies, namely, M/s. Pidilite Industries Ltd., M/s. Milistar Retail (P) Ltd., M/s. Kuehne Nagel, M/s. Sidma Agency and M/s. S. S. Indane Services. Presently, aluminium bangles, readymade garments (e-marketing), and gas cylinders were stored in these godowns. It was found that overall 80 employees are working in theses godowns. Two borewells were found in this survey number which is the main source of water. It was found that daily around 2000 ltrs of water is being utilized. Further waste water discharged into septic tank and also movement of Heavy Motor Vehicle were observed during the survey.

Survey No. 10	

Figure-11.8: Location of WP superstructure in Google Earth image-2014

11.4.1.6. Writ Petition No. 38699(a)/2013: In the Survey No. 6/10 of an extent 1.10 Acres, one godown and a ground+2 building (Figure-11.9) has been constructed in the year 2002. Currently, the godown is vacant and it was found that earlier the godown was rented out for the company i.e. Future Agro Pvt. Ltd. and ground+02 building was utilized for office and canteen purpose. Further, in this survey number there was a bore well which is currently in non-working condition.

Survey No. 6/10	

Figure-11.9: Location of WP superstructure in Google Earth image-2014

11.4.1.7. Writ Petition No. 38700(b)/2013: In the Survey No. 10 of extent 1.10 Acres, one godown (Figure-11.10) has been constructed in the year 2002. During the survey it was found that three partitions have been made in the existing godown and rented out to three companies, namely, M/s. Nilkamal Ltd, M/s. SRL Enterprises and M/s. Country Wide Logistics. Currently plastic trays, tractor equipments and dry cargo were stored in these godowns. It was found that overall 10 employees were working in theses godowns. One borewell was found in this survey number which is the main source of water.

Survey No. 10	

Figure-11.10: Location of WP superstructure in Google Earth image-2014

11.4.1.8. Writ Petition No. 38737/2013: In the Survey No. 13 of an extent of 3.31 Acres, one godown has been constructed in the year 2006-07. During the survey it was found that the godown has been constructed on the lakebed (Figure-11.11) as per the village map of Makali (Figure-11.12). The existing one godown is rented out for the company i.e. M/s. Himalaya Drugs and the finished cosmetics products were stored in the godown along with the existence of the godown there was a small structure in which the Himalaya cosmetic products were also stored. It was found that overall 15 employees are presently working in this godown. One borewell was found in this survey number which is the main source of water. Further, waste water is being discharged into septic tank.

Figure-11.11: Location of WP superstructure on Lake in Google Earth image-2014



Figure-11.12: Location of lake in village map

11.4.1.9. Writ Petition No. 38183/2013: In the Survey No. 11/2, 11/6 & 11/9 of an extent of 1.10 Acres, one godown (Figure-11.13) has been constructed in the year 2005. During the survey it was found that three partitions made in the existing godown and rented out for the three companies i.e. M/s. Volvoline Cummins, M/s. Yusen Logistics India Ltd. and M/s. DTDC Courier office. Currently helmets, engine oils and machinery parts were stored in one of the unit and in other two units electronic goods and household goods were stored. It was found that overall 18 employees working in these units. One borewell was found in this survey number which is the main source of water. It was found that daily around 300 ltrs of water is being utilized. Further waste water discharged into septic tank was observed during the survey.

Survey No. 11/2, 11/6 and 11/9	

Figure-11.13: Location of WP superstructure in Google Earth image-2014

11.4.1.10. Writ Petition No. 38506/2013: In the Survey No. 11/2, 11/6, 11/9 of an extent of 2 Acres, one godown (Figure-11.14) has been constructed in the year 2002. Currently, the godown is vacant and adjacent to the godown there was one small structure, which was earlier used as a security room and it was found that earlier the godown was rented out for a company and also it was found that the godown has been vacant from past one year. Further one borewell was found in this survey number. Further septic tank has been constructed for waste water discharge.

Survey No. 11/2, 11/6 & 11/9	

Figure-11.14: Location of WP superstructure in Google Earth image-2014

11.4.1.11. Writ Petition No. 38793/2013: In the Survey No. 14 of an extent of 9.10 Acres, one godown (Figure-11.15) has been constructed in the year 2005-06 with a built up area of 3800 Sq. ft. Currently, the godown is vacant and is being used for own use and it was found that earlier it was rented out for a company and its been vacant from past one year. Further, two borewells were found in this survey number. For waste water, septic tank has been constructed. The two existing small structures are utilized for providing accommodation to the staff.

Survey No. 14	

Figure-11.15: Location of WP superstructure in Google Earth image-2014

11.4.1.12. Writ Petition No. 39938-40/2013: In the Survey No. 6/4 of an extent of 4.20 Acres, six structures (Figure-11.16) have been constructed in the year 1994-95. During the survey it was observed that two godowns have been rented out to the companies i.e. M/s. Nisarga Warehouse and M/s. Suraj Wood Products and currently paper rollers and plywood were stored in these godowns. It was found that one G+1 godown is under renovation, another one godown is vacant and also there was two small structures utilized for providing accommodation to the staff. Further, it was also found that overall 5-6 employees were working in these godowns. One borewell was found in this survey number which is the main source of water. For waste water discharge, septic tank has been constructed.

Survey No. 6/4	

Figure-11.16: Location of WP superstructure in Google Earth image-2014

11.4.1.13. Writ Petition No. 40270/2013: In the Survey No. 5/2, 5/10 of an extent of 2 Acres, two godowns (Figure-11.17) have been constructed in the year 1982-85. During the survey it was found that in the survey no. 5/2 one godown has been constructed and its been rented out to the company i.e. M/s. Ultra Tech Cement and currently white cement was stored in this godown.

Further it was found that in the survey No. 5/10, one godown has been constructed and this been partitioned into three units and have been rented out to three companies i.e. M/s. Bindya Cargo Pvt. Ltd., M/s. Shubham Fright Carrier Pvt. Ltd and M/s. Prakash Parcel Services. It was found that overall 50 employees were working in these units. One borewell was found in this survey number which is the main source of water. For discharge of waste water, septic tank has been constructed.

Survey No. 5/2 & 5/10	

Figure-11.17: Location of WP superstructure in Google Earth image-2014

11.4.1.14. Writ Petition No. 38800/2013: In the Survey No. 6/2 of an extent of 4.2 Acres, six godowns (Figure-11.18) have been constructed in the year 1972-82. During the survey it was found that all the six godowns have been rented out for various companies. It was also found that among the six godowns four godowns have been partitioned into three to four units and remaining two godowns have been rented out to the companies i.e. M/s. Indian Pollution Control Association and M/s. Mahendra & Mahendra. Currently, motor cycle parts, two wheeler, talcum powder, tillers, corns, handicap accessories, etc. are stored in these godowns. It was found that overall 60-70 employees were working in these units. Two borewells were found in this survey number which is the main source of water. It was found that daily around 3000 ltrs of water is being utilized. For discharge of waste water, septic tank has been constructed.

Survey No. 6/2	

Figure-11.18: Location of WP superstructure in Google Earth image-2014

11.4.1.15. Writ Petition No. 38796-99/2013: In the Survey No. 9 of an extent of 2.1 Acres, 02 godowns (Figure-11.19) have been constructed in the year 2002. During the survey it was found the two godowns have been rented out to the companies i.e. M/s. Khaitan Electricals Ltd. and M/s. Parle Products Pvt. Ltd. and currently the products of Parle and electronic goods were stored in these godowns and along with the 02 existing godowns there was a G+1 structure which are rented out to commercial shops (seven shops). It was found that overall 150 employees were working in these godowns. One borewell was found in this survey number which is the main source of water. Further, septic tank has been constructed for discharge of wastewater.

Survey No. 09	

Figure-11.19: Location of WP superstructure in Google Earth image-2014

11.4.2. Writ Petitions of Madanayakanahalli Village of the Bangalore North Taluk:

There are 14 writ petitions filed from the village of the Madanayakanahalli and there are few cases whereas 02 to 03 petitions been filed by one petitioners. The Madanayakanahalli village falls in the Zone-3 of the Arkavathi river stretch (Figure-11.20).

According to the survey it was found that overall 23 structures have been constructed in the lands of the petitioners. Out of 23 structures, 19 are godowns and currently these godowns are used for warehouse purpose and remaining 4 godowns are vacant. Further, the survey witnessed that all the godowns which are working are rented out.

It was also observed that 99% of the land owners in the Madanayakanahalli village have constructed agricultural godowns of an extent area varying from 30 guntas to 5 acres. Further, it was found that 72% of the godowns are having borewells. Septic tanks are also constructed in some cases for the discharge of waste water. In many places these are not connected and not functioning. The survey revealed that all these rural godowns were constructed under Gramina Bhandarah Yojana under approval by the Gram Panchayat and all these godowns are located within 1 Km radius of the restricted zone of the Arkavathi river stretch. The current status of 14 writ petitions structures in the Madanayakanahalli village are discussed below;



Figure-11.20: Location of Madanayakanahalli village
in TGR Zone Map (Source – NPA)

11.4.2.1. Writ Petition No. 40783/2013: In the Survey No. 53/10 of an extent of 1 Acres, one godown (Figure-11.21) has been constructed in the year 2004 with a built up area of 80,000 Sq.ft. Currently the godown is vacant and it was found that earlier the godown was rented out for a garment unit i.e. M/s. Bombay Royan Fashions Pvt. Ltd. Later on it was closed due to order issued by the BMICAPA and also it was found that the godown is closed from past one year. Further, one borewell was found in this survey number. Septic tank was constructed for wastewater discharge.

Survey No. 53/10	

Figure-11.21: Location of WP superstructure in Google Earth image-2014

11.4.2.2. Writ Petition No. 40411-13/2013: In the Survey No. 53/6, 53/7, 53/8, 53/9 of an extent of 1.04 Acres, two godowns (Figure-11.22) have been constructed in the year 2007 with a built up area of 23,000 Sq.ft. During the survey it was found that the two godowns have been rented out to the companies i.e. M/s. Pavilions Interiors Pvt. Ltd. (G+1) and M/s. Saj Foods Products Pvt. Ltd. and currently biscuits box and wood designs were stored in these godowns. It was found that overall 09 employees were working in these godowns. One borewell was found in this survey number which is the main source of water. It was found that daily 8000 ltrs of water is utilized. Further septic tank has been constructed for wastewater discharge.

Survey No. 53/6, 53/7, 53/8 and 53/9	

Figure-11.22: Location of WP superstructure in Google Earth image-2014

11.4.2.3. Writ Petition No. 40782/2013: In the Survey No. 8/1 of an extent of 1.2 Acres, at present, no structure was found in this survey number. During the survey it was found that earlier there was a temporary shed which was rented out M/s. Mahalakshmi Metal Works and presently it has been demolished (Figure-11.23).

Survey No. 8/1	

Figure-11.23: Location of WP superstructure in Google Earth image-2014

11.4.2.4. Writ Petition No. 39940/2013: In the Survey No. 50 of an extent of 5.31 Acres, six godowns (Figure-11.24) have been constructed in the year1994-95 and the compound wall is constructed to the edge of the river stream. During the survey it was found that out of six godowns five godowns have been rented out to the companies i.e. M/s/ Aditya Birla Groups, M/s. Inland World Logistics Pvt. Ltd., M/s. Bata Company, M/s. Inland Logistics Pvt. Ltd., and M/s. Logistics and remaining one godown was vacant and it was found that, groceries, Bata items and wood designs were stores in these godowns. Further it was found that overall 20-35 employees were working in these godowns. Two borewells were found in this survey number which is the main source of water. It was found that daily 2000ltrs of water was being utilized. Septic tank was found to have been constructed for wastewater discharge.

Survey No. 50	

Figure-11.24: Location of WP superstructure in Google Earth image-2014

11.4.2.5. Writ Petition No. 38518/2013: In the Survey No. 52/4-B, 51 of an extent of 39 Guntas and 1.27 Acres, it was found that survey no. 52/4-B a plane land and in survey no. 51, G+1 godown (Figure-11.25) has been constructed in the year 2005-06. Presently ground floor of the godown is rented out to the company i.e. M/s. Reliance fresh (fruits &vegetable storage) and first floor is rented to the dry cargo unit. It was also found that overall 50 employees were working in these godowns. One borewell was found in this survey number which is the main source of water. It was found that daily 2000ltrs of water was being utilized. Septic tank has been constructed for wastewater discharge. It was found that the consent is given by KSPCB to run this unit.

Survey No. 52/4B and 51	

Figure-11.25: Location of WP superstructure in Google Earth image-2014

11.4.2.6. Writ Petition No. 40779/2013: In the Survey No. 6/5 of an extent of 29 Guntas, two godowns (Figure-11.26) were found. Presently one godown has been rented out to M/s. Amaron Batteries (Storage of batteries) and another godown is vacant. It was also found that overall 12 employees were working in these godowns.

Survey No. 6/5	

Figure-11.26: Location of WP superstructure in Google Earth image-2014

11.4.2.7. Writ Petition No. 40780/2013: In the Survey No. 6/8 and 6/4 of an extent of 1.8 Acres hallow brick factory (Figure-11.27) was established in the year 2002. During the survey it was found that earlier there was a hallow brick factory in this survey number and presently it has been closed in the year 2014 due to notice issued by the authorities. It was found that unused machinery items were dumped inside the unit. Further three borewells were observed in this survey number.

Survey No. 6/8 and 6/4	

Figure-11.27: Location of WP superstructure in Google Earth image-2014

11.4.2.8. Writ Petition No. 40508/2013: In the Survey No. 12/7, 1, 7B of an extent of 36 Guntas, one godown (Figure-11.28) has been constructed in the year 2007. During the survey it was found that the godown is rented out to the company i.e. M/s. Arpitha Agencies and presently cello company products were stored in the godown. Further one borewell was observed in this survey number, which is in non-working condition.

Survey No. 12/7, 1, 7B	



Figure-11.28: Location of WP superstructure in Google Earth image-2014

11.4.2.9. Writ Petition No. 41042-43/2013: In the Survey No. 66/7 of an extent of 2.8 Acres, two godowns (Figure-11.29) have been constructed in the year 2007 and 2013. Presently these godowns are rented out to the companies i.e. M/s. Access Warehouse Pvt. Ltd. and M/s. Heinz India Pvt. Ltd. Presently, corn flakes (Kelloggs) and Glucon-D products were stored in these godowns. It was also found that overall 19 employees were working in these godowns. One borewell was found in this survey number which has dried up.

Survey No. 66/7	

Figure-11.29: Location of WP superstructure in Google Earth image-2014

11.4.2.10. Writ Petition No. 40781/2013: In the Survey No. 53/11of an extent of 1.0 Acres, one godown (Figure-11.30) has been constructed in the year 2006. Presently, the godown is vacant and it was found that earlier it was rented out to the garment unit i.e. M/s. Seems Fab Pvt. Ltd., it was also found that from past six months it has been vacant and this garment unit was closed due to closure notice issued by the BMICAPA.

Survey No. 53/11	

Figure-11.30: Location of WP superstructure in Google Earth image-2014

11.4.2.11. Writ Petition No. 38218/2013: In the Survey No. 52/3of an extent of 2.1 Acres, four godown (Figure-11.31) have been constructed in the year 1970 and 2004 (three godowns). These godowns are rented out to the companies i.e. M/s. Navneeth Publications, M/s. Fusion Chapels, and M/s. Plaster Construction Technology (I) Ltd. Presently, these godowns are stored with furnitures, construction materials, books, and chapels. It was also found that overall 20 employees were working in these godowns.

Survey No. 52/3	



Figure-11.31: Location of WP superstructure in Google Earth image-2014

11.4.3. Writ Petitions of Heggadadevanapura Village of the Bangalore North Taluk:

There are 10 writ petitions filed from the village of the Heggadadevanapura. The Heggadadevanapura village falls in the restricted Zone-3 of the Arkavathi river stretch (Figure-11.32).

According to the survey it was found that overall 16 structures have been constructed in the lands of the petitioners. Out of 16 structures, 10 are godowns and currently these godowns are used for warehouse purpose and remaining 6 godowns are vacant. Further, the survey witnessed that all the godowns which are working are rented out.

It was also observed that 99% of the land owners in the Heaggadadevanapura village have constructed agricultural godowns of an extent area varying from 30 guntas to 5 acres. Further, it was found that 80% of the godowns are having borewells. Septic tanks are also constructed in some cases for the discharge of waste water. In many places these are not connected and not functioning. The survey revealed that all these rural godowns were constructed under Gramina Bhandarah Yojana which was approved by the Gram Panchayat and all these godowns are located within 1 Km radius of the restricted zone of the Arkavathi river stretch. The current status of 10 writ petitions structures in the Heaggadadevanapura village are discussed below;



Figure-11.32: Location of Heggadadevanapura village in TGR Zone Map (Source – NPA)

11.4.3.1. Writ Petition No. 40269/2013: In the Survey No. 63 of an extent of 2 Acres, one godown (Figure-11.33) has been constructed in the year 2007. Presently, it is vacant; it was found that earlier it was rented out. Further two borewells were found in this survey number, in which one is working and other in non-working condition.

Survey No. 63	

Figure-11.33: Location of WP superstructure in Google Earth image-2014

11.4.3.2. Writ Petition No. 38697/2013: In the Survey No. 64 and 72/2 of an extent of 1.3 Acres, three godowns (Figure-11.34) were found in the Sy. No. 64 one godown has been constructed and rented out to M/s. Amway Company, in which the cosmetics products were stored. Further, in the survey number 72/2, two godowns are constructed, presently these godowns are vacant.

Survey No. 64 and 72/2	

Figure-11.34: Location of WP superstructure in Google Earth image-2014

11.4.3.3. Writ Petition No. 40193/2013: In the Survey No. 64/4 of an extent of 1.0 Acres, four godowns (Figure-11.35) have been constructed in the year 2000. Presently, the godown has been rented out to the company i.e. M/s. Agarwal Movers and Packers (transporting the goods). It was also found that overall 25-30 employees were working in these godowns. One borewell was found in this survey number which is the main source of water. The waste water discharge into the septic tank and also movement of heavy motor vehicle was observed inside the godown during the survey.

Survey No. 64/4	

Figure-11.35: Location of WP superstructure in Google Earth image-2014

11.4.3.4. Writ Petition No. 38698/2013: In the Survey No. 72/1of an extent of 1.37 Acres, two godowns (Figure-11.36) were found. Presently theses godowns are vacant and it was found that earlier it was rented to some company. After the issue of closure notice from BDA the godown has been closed.

Survey No. 72/1	



Figure-11.36: Location of WP superstructure in Google Earth image-2014

11.4.3.5. Writ Petition No. 38795/2013: In the Survey No. 45/1of an extent of 2.0 Acres, one godown (Figure-11.37) has been constructed in the year 2006. The godown has been rented out to the company i.e. M/s. Whirlpool Pvt. Ltd. Presently this godown is stored with electronic gadgets. It was also found that overall 15 employees were working in this godown. One borewell was found in this survey number which is the main source of water. Waste water discharge into the septic tank and also movement of heavy motor vehicle was observed inside the godown during the survey.

Survey No. 45/1	

Figure-11.37: Location of WP superstructure in Google Earth image-2014

11.4.3.6. Writ Petition No. 39029/2013: In the Survey No. 65/1 of an extent of 5.09 Acres, two godowns (Figure-11.38) have been constructed in the year 2003 and it was found that three to four godowns were also there. Presently, two godowns have been rented out to the company i.e. M/s. Bajaj Electrical Ltd. and the godowns were stored with electrical goods. It was also found that overall 100 employees were working in these godowns. Two borewells were found in in this survey number which is the main source of water. Waste water discharge into the septic tank and also movement of heavy motor vehicle was observed inside the godown during the survey.

Survey No. 65/1	

Figure-11.38: Location of WP superstructure in Google Earth image-2014

11.4.3.7. Writ Petition No. 39939/2013: In the Survey No. 41/1 of an extent of 2.37 Acres, two godowns (Figure-11.39) has been constructed in the year 1995. Presently in the G+2 godown, ground floor was stored with construction materials; 1st floor was stored with the Bata company goods and 2nd floor was vacant. Further another one godown renovation work was in progress. Two borewells were found in this survey number which is the main source of water.

Survey No. 41/1	

Figure-11.39: Location of WP superstructure in Google Earth image-2014

11.4.3.8. Writ Petition No. 40272/2013: In the Survey No. 65 of an extent of 1.02 Acres, one godown (Figure-11.40) has been constructed in the year 1999-2000 and this godown has two partitions. Presently the godown is vacant, it was found that earlier it was rented out to the company i.e. M/s. WIPRO and the godown has been vacant from past one year. One borewell was found in this survey number.

Survey No. 65	

Figure-11.40: Location of WP superstructure in Google Earth image-2014

11.4.3.9. Writ Petition No. 40273/2013: In the Survey No. 67/4 of an extent of 37 Guntas, one godown (Figure-11.41) and small structure was found in this survey number. Presently, the godown is rented out to the company i.e. M/s. Navabharath Archive Apress Pvt. Ltd. and various documents were stored in this godown. Further, a small structure was found which is being used for the officer purposes and overall 5-6 employees were working in this godown. One borewell was found in this survey number which is the main source of water. Septic tank has been constructed for waste water discharge.

Survey No. 67/4	

Figure-11.41: Location of WP superstructure in Google Earth image-2014

11.4.3.10. Writ Petition No. 40271/2013: In the Survey No. 64 of an extent of 30Guntas, one godown (Figure-11.42) and small structure was found in this survey number. Presently, the godown is vacant. One borewell and a septic tank were observed in this survey number during the survey.

Survey No. 64	

Figure-11.42: Location of WP superstructure in Google Earth image-2014

11.4.4. Writ Petitions of Adakamaranahalli Village of the Bangalore North Taluk:

There are 08 writ petitions filed from the village of the Adakamaranahalli. The Adakamaranahalli village falls in the restricted Zone-3 of the Arkavathi river stretch (Figure-11.43).

It was observed that in few cases that 3 to 5 godowns have been constructed in same land and also one godown was having 3 to 5 partitions with different type of utilities.

According to the survey it was found that overall 16 structures have been constructed in the lands of the petitioners. Out of 16 structures, 16 are godowns and currently these godowns are used for warehouse purpose. Further, the survey witnessed that all the godowns which are working are rented out.

It was also observed that 99% of the land owners in the Adakamaranahalli village have constructed agricultural godowns of an extent area varying from 1 to 5 acres. Further, it was found that 80% of the godowns were having borewells. Septic tanks are also constructed in some cases for the discharge of waste water. In many places these are not connected and not functioning. The survey revealed that all these rural godowns have been constructed under Gramina Bhandarah Yojana which was approved by the Gram Panchayat and all these godowns are located within 1 Km radius of the restricted zone of the Arkavathi river stretch. The current status of 08 writ petitions structures in the Adakamaranahalli village are discussed below;



Figure-11.43: Location of Adakamaranahalli village in TGR Zone Map
(Source – NPA)

11.4.4.1. Writ Petition No. 38493(1a)/2013: In the Survey No.4/1P1of an extent of 7 Acres, one godown (Figure-11.44) has been constructed in the year2006 and this godown is partitioned into two units. These godowns are rented out to the companies i.e. M/s. Fly Wheel Logistics and M/s. Axpress Logistics and automobiles. Presently these units are stored with all types of materials. Further, a small structure was found which is been used for the office purposes. Overall 24 employees are working in these godowns.

Survey No. 4/1P1	

Figure-11.44: Location of WP superstructure in Google Earth image-2014

11.4.4.2. Writ Petition No. 38494(1b)/2013: In the Survey No. 4/1P1 of an extent of 7 Acres, 01 godown (Figure-11.45) has been constructed in the year 2006 and this godown is partitioned into four units. Presently these units are rented out to the companies i.e. M/s. Samsung, M/s. NCR, M/s. Cannon and M/s. Blue Star and all these units are of M/s. FED EX company. It was also found that overall 150 employees were working in these units. It was found that the godown was having a septic tank for the discharge of waste water. Further, two DG sets were found in these units and also heavy vehicle movement was observed inside the godown during the survey.

Survey No. 4/1P1	

Figure-11.45: Location of WP superstructure in Google Earth image-2014

11.4.4.3. Writ Petition No. 38495(1c)/2013: In the Survey No. 04/2 of an extent of 7 Acres, two godowns (Figure-11.46) have been constructed in the year 2006 and it was found that one godown was partitioned into three units. Further, it was observed that the survey number was having G+2 structure, three shops and one hotel. The godowns are rented out to the companies i.e. M/s. CCI Logistics Ltd, M/s. Kokuyo Camlin Ltd, M/s. Blue Star and M/s. MIRC Electronics Ltd. Presently, these units were stored with polyol liquids, stationeries and electronic goods. Further it was observed that the G+2 structure was used for office purpose and the shops are rented out. It was found that overall 12 employees were working in these units. The movement of heavy motor vehicles were observed inside the godowns during the survey.

Survey No. 04/2	

Figure-11.46: Location of WP superstructure in Google Earth image-2014

11.4.4.4. Writ Petition No. 38496(1d)/2013: In the Survey No. 04/2 of an extent of 7 Acres, two godowns (Figure-11.47) have been constructed in the year 2006. The godowns are rented out to the companies i.e. M/s. Camlin Stationery and M/s. AWL Accelerated Warehouse Logistics. Presently, the godowns were storing stationeries and bathroom fitting items and it was observed that the godowns were having one DG set. Overall 40 employees are working in these two godowns. Further, one borewell was found in this survey number which is the main source of water.

Survey No. 04/2	

Figure-11.47: Location of WP superstructure in Google Earth image-2014

11.4.4.5. Writ Petition No. 38497(1e)/2013: In the Survey No. 04/2 of an extent of 7 Acres, one godown (Figure-11.48) has been constructed in the year 2006. The godown is rented out to the company i.e. M/s. Redington (I) Ltd. Presently, the godown was stored with computer accessories items. It was observed that the godown was having septic tank for the discharge of waste water. Overall 35 employees were working in this godown.

Survey No. 04/2	

Figure-11.48: Location of WP superstructure in Google Earth image-2014

11.4.4.6. Writ Petition No. 38492/2013: In the Survey No. 04 of an extent of 5.0 Acres, five godowns along with one G+1 structure (Figure-11.49) have been constructed in the year 2004-05. One godown is rented out to the companies i.e. M/s. FEDEX and four godowns are rented out to M/s. Smart Retail Ltd. Presently, these godowns were stored with soft drinks, water bottles, groceries, papers and fruits and vegetables. Further G+1 structure is used for the office purpose. Overall 40 employees were working in these godowns. Two borewells were found in this survey number which is the main source of water and also it was found that daily 1000 ltrs of water is utilized. The godown is having septic tank for the discharge of waste water and also the movement of heavy motor vehicle was observed inside the godown.

Survey No. 04	

Figure-11.49: Location of WP superstructure in Google Earth image-2014

11.4.4.7. Writ Petition No. 38701/2013: In the Survey No. 8/2 of an extent of 2.3 Acres, two godowns (Figure-11.50) have been constructed in the year 2006. The godowns are rented out to the M/s. Himalaya Drugs Company and presently, these godowns were stored with finishing Ayurvedic Medicines and Cosmetics products. Overall 40 employees are working in these godowns. One borewell was found in this survey number as the main source of water and also it was found that daily 500 ltrs of water is utilized. The godown is having septic tank for the discharge of waste water.

Survey No. 8/2	

Figure-11.50: Location of WP superstructure in Google Earth image-2014

11.4.4.8. Writ Petition No. 38502/2013: In the Survey No. 06 of an extent of 1.29 Acres, two godowns (Figure-11.51) have been constructed in the year 2007-08. The godowns are rented out to the companies i.e. M/s. Startrek Logistics Pvt. Ltd. (Courier Services) and M/s. Home Logistics (Storage and Dispatch). Overall 60 employees are working in these godowns. One borewell was found in this survey number which is the main source of water and also it was found that daily 400 ltrs of water is been utilized. The godown is having a septic tank for the discharge of waste water. Movement of heavy motor vehicle was found inside the godown.

Survey No. 06	

Figure-11.51: Location of WP superstructure in Google Earth image-2014

11.4.5. Writ Petitions of Siddanahosahalli Village of the Bangalore North Taluk:

There are 03 writ petitions filed from the village of the Siddanahosahalli. The Siddanahosahalli village falls in the Zone-3 of the Arkavathi river stretch (Figure-11.52).

According to the survey it was found that overall 14 structures have been constructed in the lands of the petitioners. Out of 14 structures, all are godowns which are used for warehouse purpose. Further, it was found that all the godowns, which are working have been rented out.

It was also observed that agricultural godowns have been constructed over area varying from 5 guntas to 6 acres. Further, it was found that the godowns are having borewells. Septic tanks are also constructed in some cases for the discharge of waste water. In many places these are not connected and not functioning. The survey revealed that all these rural godowns were constructed under Gramina Bhandarah Yojana with approval by Gram Panchayat and all these godowns are located within 1 Km radius of the restricted zone of the Arkavathi river stretch. The current status of 03 writ petitions structures in the Siddanahosahalli village are discussed below;



Figure-11.52: Location of Siddanahosahalli village in TGR Zone Map
(Source – NPA)

11.4.5.1. Writ Petition No. 39030/2013: In the Survey No. 5/1 of an extent of 6.2 Acres, six godowns (Figure-11.53) have been constructed in the year 1994-95, in which two godowns were G+1, G+2 and G+5 Structures. Among the six godowns, three godowns are rented out to the companies i.e. M/s. Modern Jyothi Pvt. Ltd., M/s. Holizol Logistics and M/s. Urban Ladder Furniture's and these godown is stored with plastic chairs and furniture. In the G+1 structure, ground floor has been rented out and stored with Yamaha Two Wheeler Bikes; it was also found that the first floor was vacant. In the G+2 structure, ground floor and first floor are rented out to the company i.e M/s. Urban Ladder Furnitures and the second floor is vacant. Further, in the G+5 structure, ground floor and first floor are rented out to the company i.e. M/s. Adcok Ingram Healthcare Pvt. Ltd. and it was stored with pharmaceutical products and four floors were vacant. Overall 50 employees are working in these godowns. Three borewells were found in this survey number which is the main source of water and also it was found that daily 2500 ltrs of water is being utilized. The godown was having STP and also the movement of heavy motor vehicle was observed inside the godowns.

Survey No. 5/1	

Figure-11.53: Location of WP superstructure in Google Earth image-2014

11.4.5.2. Writ Petition No. 38503/2013: In the Survey No. 32 of an extent of 2.02 Acres, two godowns (Figure-11.54) have been constructed in the year 2008-09. The two godowns are rented out to the companies i.e. M/s. Aircel Ltd. and M/s. Tol India Logistics and the godowns were stored with housekeeping and network materials. Overall 40 employees are working in these godowns. It was found that daily 1000 ltrs of water is being utilized. The godown is having septic tank for the discharge of wastewater.

Survey No. 32	

Figure-11.54: Location of WP superstructure in Google Earth image-2014

11.4.5.3. Writ Petition No. 40970/2013: In the Survey No. 27/2c, & 31/2a of an extent of 21 Gunta and 3.16 Acres, presently there were no structures found in the Sy. No. 27/2c and in this open land construction materials, wooden cable rollers and JCB's were found.

Further in the Sy. No. 31/2a of an extent 3.16 Acres, two godowns and two small structures (Figure-11.55) have been constructed in the year 2013. Presently the two godowns are rented out to the company i.e. M/s. Himachal Futuristic Communication Ltd and these godowns are stored with networking accessories. The two small structures are used for office purpose. Overall 25 employees are working in these godowns. One borewell was found in this survey number which is in non-working condition. It was also found that weekly 6000 ltrs of water is been utilized. The godown is having septic tank for the discharge of wastewater. A plantation of mango and coconut around the godown was observed during the survey.

Survey No. 31/2a	

Figure-11.55: Location of WP superstructure in Google Earth image-2014

11.4.6. Writ Petitions of Dasanapura Village of the Bangalore North Taluk:

There are 02 writ petitions filed from the village of the Dasanapura. The Dasanapura village falls in the restricted Zone-3 of the Arkavathi river stretch (Figure-11.56).



Figure-11.56: Location of Dasanapura village in TGR Zone Map (Source – NPA)

According to the survey it was found that overall three structures have been constructed in the land of the petitioner, which is a college.

It was also observed that a college has been constructed in the agricultural land, which is located within 1 Km radius of the restricted zone of the Arkavathi river stretch. The current status of 01 writ petition structure in the Dasanapura village is discussed below;

11.4.6.1. Writ Petition No. 41793-94/2013: In the Survey No. 100 of an extent of 25 Acres, there is a college i.e. BJR College of Nursing and BJR Medical College (Figure-11.57), presently which is closed. There were three structures within this land i.e. one building used for teaching, one hostel and another security room.

Survey No. 100	

Figure-11.57: Location of WP superstructure in Google Earth image-2014

11.4.7. Writ Petitions of Dombarahalli Village of the Bangalore North Taluk:

Whereas there are 02 writ petitions filed from the village of the Dombarahalli. The Dombarahalli village falls in the restricted Zone-3 of the Arkavathi river stretch (Figure-11.58).

According to the survey it was found that overall 06 structures have been constructed in the lands of the petitioners. Out of 06 structures, all are godowns are being used for warehouse purpose. Further, the survey witnessed that all the godowns which are working are rented out.

It was also observed that agricultural godowns constructed are having an area varying from 6 to 8 acres. Further, it was found that the godowns are having borewells and septic tanks for the discharge of waste water. The survey revealed that all these rural godowns were constructed under Gramina Bhandarah Yojana under approval by the Gram Panchayat and all these godowns are located within 1 Km distance in the restricted zone of the Arkavathi river stretch. The current status of 02 writ petitions structures in the Dombarahalli village are discussed below;



Figure-11.58: Location of Dombarahalli village in TGR Zone Map
(Source – NPA)

11.4.7.1. Writ Petition No. 38499/2013: In the Survey No. 24/2 of an extent of 6.2 Acres, four godowns (Figure-11.59) have been constructed in the year 2009-10. The four godowns are rented out to the companies i.e. Nelkamal Ltd. M/s. Reliance Jlo Infocomm Ltd, M/s. Metro and M/s. Drive India Enterprises Solutions Ltd. Presently these godowns are stored with plastic, elevators and tower items. Overall 100 employees are working in these godowns. One borewell was found in this survey number which is the main source of water. The godown is having septic tank for the discharge of waste water and also movement of Heavy Motor Vehicle were observed during the survey.

Survey No. 24/2	

Figure-11.59: Location of WP superstructure in Google Earth image-2014

11.4.7.2. Writ Petition No. 38501/2013: In the Survey No. 24/2 of an extent of 8.1 Acres, two godowns (Figure-11.60) have been constructed in the year 2006. The two godowns are rented out to the companies i.e. M/s. Meyer and M/s. Jyothi Laboratories Ltd. Presently these godowns are stored with pharmaceutical and detergents products. Overall 33 employees are working in these godowns. One borewell was found in this survey number which is the main source of water. The godown is having septic tank for the discharge of waste water and adoption of rainwater harvesting system was observed during the survey.

Survey No. 24/2	



Figure-11.60: Location of WP superstructure in Google Earth image-2014

11.4.8. Writ Petitions of Harokyathnalli Village of the Bangalore North Taluk:

There is only 01 writ petition filed from the village of the Horakyathanalli. The Harokyathanalli village falls in the restricted Zone-3 of the Arkavathi river stretch (Figure-11.61).

According to the survey it was found that one structure has been constructed in the land of the petitioner which is vacant

Further, it was found that the godowns are having borewells and septic tanks for the discharge of waste water. The survey revealed that all these rural godowns have been constructed under Gramina Bhandarah Yojana which was approved by the Gram Panchayat and all these godowns are located within 1 Km radius of the restricted zone of the Arkavathi river stretch. The current status of the writ petition structure in the Harokyathnalli village is discussed below;



Figure-11.61: Location of Harokyathanalli village in TGR Zone Map (Source – NPA)

11.4.8.1. Writ Petition No. 38498/2013: In the Survey No. 102/1 of an extent of 3 Acres, one godown (Figure-11.62) has been constructed in the year 2006. Presently the godown is vacant and it was found that earlier the godown was rented out to M/s. Videocon Company. Further, one borewell was found in this survey number. The godown is having septic tank for the discharge of waste water was observed during the survey.

Survey No. 102/1	

Figure-11.62: Location of WP superstructure in Google Earth image-2014

11.4.9. Writ Petitions of Huruli Chikkanahalli Village of the Bangalore North Taluk:

There is only 1 writ petitions filed from the village of the Huruli Chikkanahalli. The Huruli Chikkanahalli village falls in the restricted Zone-3 of the Arkavathi river stretch (Figure-11.63).

According to the survey it was found that one structure has been constructed in the land of the petitioner, which is an industry. Further, the survey witnessed that the industry has been rented out.

Further, it was found that the industry is having borewell and septic tank for the discharge of waste water. The current status of 01 writ petition structure in the Huruli Chikkanahalli village is discussed below;

Figure-11.63: Location of Huruli Chikkanahalli village in TGR Zone Map (Source – NPA)

11.4.9.1. Writ Petition No. 44160/2013: In the Survey No. 74 of an extent of 4.19 Acres, during the survey one industry was found (Figure-11.64). Presently this industry has been rented out to the company i.e. M/s. Colton Industries (welding manufacturing industry). It was found that, within the building one portion is utilized for the office staff for accommodation, having two toilets and security room. Overall 25 employees are working in this industry. Further, one borewell was found in this survey number which is the main source of water. The industry is having septic tank for the discharge of waste water. Industry is surrounded with mango, coconut and chickoo plantation.

Survey No. 74	

Figure-11.64: Location of WP superstructure in Google Earth image-2014

11.4.10. Writ Petitions of Basavenahalli Village of the Magadi Taluk:

There is only 1 writ petition filed from the village of the Basavenahalli. The Basavenahalli village falls in the restricted Zone-3 (Figure-11.65) of the Kumudvathi river stretch.

It was observed that agricultural land has been converted to commercial purpose. Further, it was found that the land is having borewells. The current status of 01 writ petition structure in the Basavenahalli village is discussed below;



Figure-11.65: Location of Basavenahalli village in TGR Zone Map (Source – NPA)

11.4.10.1. Writ Petition No. 58328/2013: In the Survey No. 74 of an extent of 5.6 Acres, during the survey it was found that the land has been converted into layout (Figure-11.66). The layout development was in progress. Quarrying of stone was found in the centre of the land which is a Karab. One borewell was observed in this survey number and also a small structure was found which is used by the watchman.

Survey No. 74	

Figure-11.66: Location of WP superstructure in Google Earth image-2014

11.5. Environmental Issues:

- Some of the godowns are having two to five floors structures, commercial shops and canteens and in few cases fifty to hundred workers are working in the godowns. Some of the godowns do not have septic tank and the generated sewage is discharged into the open area also there is no proper solid waste management. The pollutants from all these are carried into the surface water, ground water and contributes in contaminating the river.
- Some of the godowns which were surveyed are storing oil, chemicals, batteries, drugs. Any accidental spillage of these hazardous materials would pose a significant risk in terms of water pollution and adverse effects on environment.
- Lack of proper sanitation increases the environmental problem.

11.6. Conclusions:

Based on the observations the following broad conclusions have been drawn regarding the writ petitions:

- Most of the godowns have been constructed under the Grameena Bhandara Scheme with the support of subsidized funding from banks. While the godowns involved in writ petition has been seen in detail, there are many similar structures being used for similar purposes around these properties.
- These godowns have been given on rent and are being utilized for storage of mostly finished goods and products.
- Planning Authorities has not sanctioned permission for construction of godowns but No Objection Certificate (NOC) from Gram Panchayat has been obtained in most cases.
- The Notices for demolition have been given many years after the actual construction.
- Proper solid waste management should be carried out to minimize the environmental impacts.
- These godowns are dependent on ground water which is a scarce resource in the area. Rain water harvesting should be enforced to take care of the water requirement.
- Some of the structures have been constructed on tank bed. Action should be undertaken by concerned authorities in this regard.

With regards to the Environmental issues and landuse changes of each writ petition superstructures and other related matters are illustrated in **Litigated Superstructure Atlas Card**.

Table-11.1. Details of the 61 Writ Petitions

Sl. No.	Case No.	Petitioner Name	Respondents	Sy. No.	Extent (A.G)	Remarks
14 Writ Petitions from Makali Village, Dasanapura Hobli, Bangalore North Taluk of Bangalore Urban District						
1	WP. 38699/2013 (3a)	Yethivendranaik & Others	The Commissioner, BDA, DC Rural, KSPCB	6/10	1.10	2 agricultural rural Godowns measuring 27,600 & 26,290 sqft
2	WP.38700/2013 (3b)					
3	WP.38483/2013	E.Krishnappa	State of Karnataka & Others	6	2.00	Godown constructed
4	WP.38793/2013	C.S. Puttegowda		14	9.10	Godown constructed
5	WP. 38506/2013	Smt. M.Kamalamma	BDA & others	11 (11/6, 11/6 & 11/9)	2.00	Warehouse building measuring 25200 sqft
6	WP.38500/2013	Rathnamma & Others	The Commissioner, BDA, DC Rural, KSPCB	6	1.00	2 Agricultural Rural godowns totally measuring 30000 sqft
7	WP.38504/2013			6	4.05	1 Agricultural rural godown measuring 95000 sqft
8	WP.38505/2013			6	1.05	1 Agricultural rural godowns of 20800 sq. ft
9	WP. 39938/2013	Sri. H. Ravi	State of Karnataka & Others	6/4	4.20	Structures and building
10	WP. 38796/2013	Smt. B.Saroja Devi & others	The Commissioner BDA & Others	9	2.10	2 Agricultural Rural godowns measuring 12500 sq. ft and 25000 sqft
11	WP. 38797/2013					
12	WP. 38798/2013					
13	WP. 38799/2013					
14	WP. 38800/2013			6/2	4.20	6 Agricultural Rural godowns measuring 20000, 22000, 22000,22000, 22000 and 36000 sq ft.
15	WP. 38737/2013	Sri. Lakshmi Kantha	State of Karnataka & Others	13	3.31	Godown constructed
16	WP.40270/2013	Smt. G. S. Rathnamma & others	The Commissioner BDA & Others	5/2 and 5/10	2.00 and 2.00	1 Agricultural Rural godown of 14,000 sq. ft
17	WP. 38183/2013	Sri N. Lokesh	State of Karnataka and others	11/2, 11/6, 11/9 (New Sy. Nos. 11/1A,	0.20	Godown measuring 10000sqft

Sl. No.	Case No.	Petitioner Name	Respondents	Sy. No.	Extent (A.G)	Remarks
				1A and 1D)		
18	WP. 39614/2013	H.S. Mahadev	State of Karnataka & Others	10	7.39	
14 Writ Petitions from Madanayakanahalli Village, Dasanapura Hobli, Bangalore North Taluk of Bangalore Urban District						
1	WP. 40779/2013	Smt.Soubhaghya	State of Karnataka & Others	6/5	0.29	Rural Godown Construction
2	WP. 40780/2013			6/8 & 6/4	1.08	
3	WP.38218/2013	T. RajaKumar	BDA	52/3	2.10	Part of land converted for non-agricultural purpose
4	WP. 38518/2013	Smt. Jagadamba	State of Karnataka & Others	52/4-B (old 52/4) and 51 (new 75)	0.39 and 1.27	Godown constructed
5	WP.40781/2013	Sri.M. Rangaswamy		53/11	1.00	Rural Godown Construction
6	WP. 39940/2013			50	5.31	Structures and building
7	WP. 41042/2013	Smt. Shivamma	The Commissioner BDA & Others	66/7	2.08	Food grains storage godowns
8	WP.41043/2013					
9	WP.40508/2013	Govindappa	BMICP & others	12/7, 1, 7B	0.36	Agricultural godown measruing 12,000 sqft
10	WP. 40782/2013	Rangaswamy	State of Karnataka and others	8/1	1.02	Construction of Agricultural rural godown
11	WP. 40783/2013	Thimmarasaiah		53/10	1.00	Construction of Agricultural rural godown
12	WP. 40411/2013	Hanumantharayappa & others		53/6, 53/7, 53/8, 53/9	1.04	Agricultural Godown (given on rent)
13	WP 40412/2013					
14	WP. 40413/2013					
10 Writ Petitions from Heggadadevanapura Village, Dasanapura Hobli, Bangalore North Taluk of Bangalore Urban District						
1	WP.40193/3013	Smt. K.M. Gayana	State of Karnataka, BDA, DC Urban & KSPCB	64/4	1.00	4 Agricultural Godown on rent
2	WP. 38697/2013	Yethivendranaik& Others	The Commissioner, BDA ,DC Rural, KSPCB	64 & 72/2	1.30	3 Agricultural rural godowns. measuring 16,000; 13,200 & 30120 sqft
3	WP.38698/2013			72/1	1.37	2 Agricultural rural godowns

Sl. No.	Case No.	Petitioner Name	Respondents	Sy. No.	Extent (A.G)	Remarks
						measuring 47500 & 42,000 sqft
4	WP. 39939/2013		State of Karnataka & Others	41	2.37	Structures and building
5	WP. 39029/2013	Smt.Sujatha, w/o HG. Ramaiah	State of Karnataka UDD, BDA, DC Urban, KSPCB	65/1 (65)	5.09	Agriculture Godown
6	WP. 38795/2013	Smt. B.Saroja Devi & others	The Commissioner BDA & Others	45/1	2.00	1 agricultural rural godowns measuring 40000 sq. ft
7	WP.40269/2013 (Petitioner No.1)	G.S. Rathnamma & Others		63	2.00	Construction of Agricultural rural godown measuring 53,908 sqft
8	WP.40271/2013			64	0.30	1 Agricultural Rural Go down measuring 14400 sq. ft
9	WP.40272/2013			65	1.02	1 Agricultural Rural Go down measuring 25000 sq. ft
10	WP.40273/2013			67/4	0.37	1 Agricultural Rural godown measuring 21000 sqft
8 Writ Petitions from Adakamaranahalli Village, Dasanapura Hobli, Bangalore North Taluk of Bangalore Urban District						
1	WP. 38701/2013	Yethivendranaik & Others	The Commissioner, BDA, DC Rural, KSPCB	8/2	2.3	2 Godowns measuring a total of 75000 sqft; on rented
2	WP.38493/2013 (1a)	Rathnamma & Others		4/2 (old no.4) & 4/1P1	2.10	5 Agricultural rural godowns of which 3 are measuring 50,000 sqft and 2 measuring 16000 sqft
3	WP.38494/2013 (1b)					
4	WP.38495/2013 (1c)					
5	WP.38496/2013 (1d)					
6	WP.38497/2013 (1e)					
7	WP.38502/2013			6	1.29	1 Agricultural rural godown measuring 60000 sqft
8	WP.38492/2013	Sri. A.G. Siddappa	State of Karnataka & Others	4	5.00	Demolish of Building constructed
4 Writ Petitions from Siddanahosahalli Village, Dasanapura Hobli, Bangalore North Taluk of Bangalore Urban District						
1	WP.39030/2013	Sri. C.Niranjan	State of Karntaka, BDA, DC Rural & KSPCB	5/1	6.20	3 Agriculture godowns; G+5, G+2 and G+1- each 01 building

Sl. No.	Case No.	Petitioner Name	Respondents	Sy. No.	Extent (A.G)	Remarks
2	WP.38503/2013	Rathnamma& Others	The Commissioner, BDA ,DC Rural, KSPCB	32	2.02 and 0.05 of karab	1 Agricultural rural godown measuring 60000 sqft
3	WP. 40970/2013	K. Govindaraju	State of Karnataka & Others	27/2c and 31/2A	0.21 and 3.16	S.No 27/2c- land (Telecom materials stocked) S.No 31/2A- 2 Godowns and 02 labour buildings
4	WP. 48047/2013	Ravikumar	State of Karnataka & Commissioner BDA	870 Connected to Residential Houses		
2 Writ Petitions from Dasanapura Village, Dasanapura Hobli, Bangalore North Taluk of Bangalore Urban District						
1	WP.41793/2013	B B .Bajentri	BDA & others	100	25.00	College building
2	WP 41794/2013					
2 Writ Petitions from Dombarahalli Village, Dasanapura Hobli, Bangalore North Taluk of Bangalore Urban District						
1	WP.38499/2013	Rathnamma & Others	The Commissioner, BDA ,DC Rural, KSPCB	24/2	6.20	Agricultural Rural godown measuring 60000 sq.ft.
2	WP.38501/2013			24/2	8.10	1 Agricultural rural godown measuring 75000 sqft
1 Writ Petition from Harokyathnalli Village, Dasanapura Hobli, Bangalore North Taluk of Bangalore Urban District						
1	WP.38498/2013	Rathnamma & Others	The Commissioner, BDA ,DC Rural, KSPCB	102/1	3	Agricultural Rural godown measuring 67900 sq.ft.
1 Writ Petition from Basavenahalli Village, Solur Hobli, Magadi Taluk of Ramanagara District						
1	WP. 58328/2013	Smt. Radhika Ganesh	Secretary, GoK, Dept. of Revenue, DC Ramanagara, Town & Country Planning & NPA	74	5.06	Layout
1 Writ Petition from Huruli Chikkanahalli Village, Hesaraghatta Hobli, Bangalore North Taluk of Bangalore Urban District						
1	WP. 44160/2013	Shirley Oliver	State of Karnataka & Others	74	4. 19	Industry

Chapter–12: Residential Superstructures

12.1. Introduction:

Writ Petition No. 48047/2013 is connected to 870 residential houses, which are filed before the Hon'ble High Court of Karnataka in the batch of Writ Petition No. 38218/2013 (connected with 60 writ petitions). The writ petition has been filed by the petitioner Mr. Ravi Kumar and the case has been advocated by the Advocate K.N. Rakshit, M/s. Nag Associates, Bengaluru against the respondents of State Government of Karnataka represented by Chief Secretary and Commissioner of Bangalore Development Authority (BDA).

As per the orders of the Hon'ble High Court dated 02.02.2015, the ground truth verification was carried out to study the current status of the 870 petitioners residential houses, which are located in the 20 villages (Figure-12.1) of the Bangalore North Taluk *i.e.* Adakimaranahalli, Dombarahalli, Lakshmipura, Siddanahosahalli, Tarabanahalli, Heggadadevanapura, Makali, Sasuveghatta, Madanayakanahalli, Kadaranahalli, Hanumanthasagara, Kumbarahalli, Bilijaji, Soladevanahalli, Kuduragere, Harokyathanahalli, Hesaraghatta, Madavara, Chikkabidarakallu and Bagalagunte. These villages are coming under the Gram Panchayaths of Dasanapura, Madanayakanahalli, Hurlichikknahalli, Alur and Kasghattapura of the Bangalore North Taluk and also these villages are coming under the jurisdiction of Bangalore Development Authority (BDA), Bangalore Mysore Infrastructure Corridor Area Planning Authority (BMICAPA) and Bangalore International Airport Area Planning Authority (BIAAPA), BBMP. Further, these 20 villages either falls in the Zone-3, Zone–1 and 3 and few of the villages falls in Zone-1, 3 and 4, Zone–1 and 4 and Zone-1 of the TGR catchment area.



Figure-12.1. Writ Petitions filed from the Highlighted (white colour) villages in Arkavathi river course (Source - NPA)

Due to constraint of time ground truth verification could not be completed for all the 870 residential houses before submission of interim report except Siddanahosahalli village of Bangalore North Taluk. However the same field verification was further carried forward and during the field

verification an effort has been made to understand the current status of individual residential houses of petitioners.

12.2. Methodology:

Ground truth verification was carried out by a team of Research Scientists, Research Associates, Technical Assistants and Field Assistants of Centre for Lake Conservation (CLC) in EMPRI, two representatives representing the petitioners and Gram Panchayat members of the consent villages. A questionnaire was designed and used during the ground truth verification, which is annexed in Annexure-12.1. The questionnaire was filled by the persons carrying out the verification in consultation with the individual petitioner in the villages. The observations made during the ground truth verification of each house were recorded with photographs and videographs along with the geo-tagged references and the same transferred to the GIS domain. The questionnaire intends to gather information about structure of the individual houses, number of families and members, basic amenities, purposes of utility etc. Further, a written statement (PANCHANAMA) was written in the presence of all the members of the committee i.e. EMPRI staff, two representatives of the petitioners and local people of the village along with their signatures.

12.2.1. Field Visits Schedule:

The field verification was carried out by the EMPRI team along with the Panchayat Development Officer (PDO), secretary, two representatives representing the petitioners, and three members from concerned villages who accompanied during the verification. Further, in the month of May, 2015 the field visits were scheduled, overall 15 field visits were made for covering 870 residential houses as per the details submitted by the M/s. Nag Associates. Subsequently, 12 to 82 houses were verified per day. The details of the field visit date for each village are given in the Table-12.1.

12.2.2. Ground Verifications of the Petitioners Residential Houses:

During the ground truth verification, out of 870 residential houses, 669 superstructures could be identified and remaining 201 superstructures could not be identified. The reasons for non-identification of 201 residential properties are (a) Few of the petitioners have sold their houses and relocated to Bengaluru City (b) Few of them have rented out their houses (c) Few of them have passed away and few of the respondent addresses were not know to the local people of the village or to the persons accompanying in the field verification. The ground truth verification witnessed that in few cases two to five petitions have been filed from one family *i.e.* father and son or husband and wife etc. Further, the ground truth verification revealed that some of the residential houses constructed in the year 1942, 1952 and it was found that after 80's and 90's many houses have come-up and more intensively after 2000. It was also found that most of the houses are constructed in the Gramathana and also constructed in the sites allotted by the Government under the Ashraya Yojane Scheme, Janatha Niveshana Scheme, Rajiv Gandhi Housing Scheme etc. While some houses are constructed in the revenue sites and some houses have been constructed in the developing layouts, most of the houses are constructed in the inherited land and few of the sites are

vacant. During the field verification it was found that the petitioners are having valid title deeds for the site which is issued by the Government and in few cases under Bhagya Jyothi Scheme, Government has provided electricity connections for the economically weaker sections. In few cases it was found that, division of sites and houses has happened among the children and many houses are renovated adding 1 floor to 2 floors and in few cases are being used as commercial shops which are rented out for the generating income.

Table-12.1. Details of the ground verification date for villages

Sl. No	Name of Village	Date of Visit	No. of Cases Verified	Total Cases/ Villages
1	Siddanahosahalli	04.04.2015	17	85
		07.04.2015	39	
		18.05.2015	27	
		08.06.2015	02	
2	Adakimaranahalli	06.05.2015	82	130
		07.05.2015	48	
3	Makali	08.05.2015	57	60
		08.06.2015	03	
4	Heggadadevanapura	12.05.2015	53	53
5	Dombarahalli and Lakshmipura	13.05.2015	50	93
		14.05.2015	43	
6	Madanayakanahalli	15.05.2015	36	42
		08.06.2015	06	
7	Tarabanahalli	23.05.2015	65	66
		27.05.2015	01	
8	Sasuveghatta	25.05.2015	53	55
		27.05.2015	02	
9	Hanumanthasagara	26.05.2015	20	20
10	Kadaranahalli		30	32
		08.06.2015	02	
11	Kumbarahalli	26.05.2015	14	16
		27.05.2015	02	
12	Bilijaji	27.05.2015	13	13
13	Hesaraghatta		01	1
14	Soladevanahalli		02	2
15	Harokyathanahalli	08.06.2015	01	1
			Total	669

During the ground verification, while interacting with the petitioners and when they were asked about the year of construction of the houses 70% petitioners informed that the houses have been constructed in 80's and 90's but while analysing the land use changes it was found that the 75% of houses have been constructed after 2004 (as per the Google earth image).

Subsequently 5% of the petitioners submitted Title deeds issued by the Government and 99% of the petitioners submitted electricity bills as a substantiation documents during the residential houses field verification.

Further while interacting with the petitioners it was found that the Gram Panchayat's are supplying water through borewells and mini water supply schemes and in few cases it was also found that the petitioners are having borewells in their houses. Wastewater discharge into pit, open drain sanitation, accessibility to road and management of solid waste in few villages are some of the observation made during the field verification. The number of cases in each village, number of identified cases and also the category wise details of each residential house of the petitioners are shown in the Table-12.2.

Table-12.2. Village wise abstract for identified and unidentified superstructures

Sl. No.	Name of the Villages	No. of Cases	No. of Cases	
			Identified	Unidentified
1.	Adakimaranahalli	191	130	61
2.	Siddanahosahalli	109	85	24
3.	Dombarahalli	92	76	16
4.	Tarabanahalli	75	55	20
5.	Sasuveghatta	75	66	09
6.	Makali	68	60	08
7.	Heggadadevanapura	67	53	14
8.	Madanayakanahalli	50	42	08
9.	Kadaranahalli	35	32	03
10.	Lakshmipura	24	17	07
11.	Hanumanthasagara	20	20	00
12.	Kumbarahalli	19	16	03
13.	Bilijaji	13	13	00
14.	Soladevanahalli	03	02	01
15.	Kuduregere	02	00	02
16.	Harokyathanahalli	01	01	00
17.	Hesaraghatta	01	01	00
18.	Bagalagunte	01	00	01
19.	Madavar	01	00	01
20.	Chikkabidarukallu	01	00	01
21.	Incorrect addresses	22	00	22
	TOTAL	**870**	**669**	**201**

Note: Village wise distribution of petitioners residential houses as per the document provided by M/s. Nag Associates.

The populations of the villages that are subject matter in the batch of writ petitions of Bangalore North Taluk have been analyzed to assess the development pressure of these areas. The population density in these villages has drastically increased as per the 2011 census data. Adakimaranahalli, Siddanahosahalli and Dombarahalli villages population was highly increased (Figure-12.2). The reason for such drastic increase may be attributed to their proximity to the BBMP area. The drastic increase in the population may also be due to migration of people for job opportunities. The details of each village extent, population and households are tabulated in the Table-12.3.

Village wise Panchanama of the ground verification of the residential superstructure are annexed in the Annexure-12.2. The ground truth observations and also the information collected by interacting with the petitioners while carrying out the residential house verification are discussed below in village wise.

Table-12.3. Description of petitioners villages

Sl. No.	Village Name	Planning Authority	Area	Households			Total Population		
				1991	2001	2011	1991	2001	2011
1	Adakimaranahalli	BDA	90.64	192	387	1056	898	1859	4137
2	SiddanaHosahalli	BDA	79.02	135	375	1694	626	1496	6165
3	Dombarahalli	BDA	102.77	40	167	724	40	216	2640
4	Tarabanahalli	BDA	84.96	126	260	315	669	1151	1294
5	Makali	BDA	79.49	224	292	744	839	1222	2873
6	Heggadadevanapura	BDA	181.37	195	316	1254	971	1346	4820
7	Sasuveghatta	BDA	200.68	86	117	182	495	555	737
8	Madanayakanahalli	BMICAPA	227.96	592	1427	3452	2728	5913	12563
9	Kadaranahalli	BDA	170.88	55	66	88	312	287	412
10	Lakshmipura	BDA	406.19	205	318	454	1096	1424	1895
11	Hanumanthasagara	BDA	45.17	40	71	176	219	287	649
12	Kumbarahalli	BDA	139.02	187	260	357	1058	1260	1459
13	Bilijaji	BDA	196.5	118	162	201	665	818	840
14	Soladevanahalli	BDA	155.31	192	252	812	1023	1179	2940
15	Harokyanthanahalli	BDA	291.76	193	261	670	1032	1198	2513
16	Hesaraghatta	BIAAPA	630.36	1311	1626	2002	6493	7186	8166
17	Kuduregere	BDA	300.4	193	291	589	1099	1369	2425
18	Bagalagunte	BBMP	2.29	1066	-	-	4616	-	-
19	Madavar	BDA	263.14	344	850	2307	1648	3544	8742
20	Chikkabidarakallu	BDA	1.41	687	1252	3083	2971	5081	11554



Figure-12.2: Population trend in the villages

12.3. Adakimaranahalli Village:

Adakimaranahalli village is coming under the jurisdiction of Dasanapura Gram Panchayat and as per the 2011 census the village has an area of 0.91 Sq. Km. with population of 4,137 and 1,056 households. The Adakimaranahalli village falls in the Zone-3 and 4 of the Arkavathi river stretch of the TGR catchment area (Figure-12.3).

In the Adakimaranahalli village, 191 cases are filed (Annexure-12.3) and during the ground verification it was found that in few cases two to three petitions have been filed by members of one family *i.e.* father and son or husband and wife etc. The ground truth verification revealed that 99% of the respondent houses are constructed in the survey no. 30 and 32. Some of the residential houses were constructed before 1942 and it was found that after 80's and 90's many houses have come-up and more intensively after 2000. At present many houses are renovated adding one floor to two floors and in few cases are being used as commercial shops which are rented out for livelihood. Further, it was found that few houses have been constructed in the Gramathana. Most houses have been constructed on the sites allotted by the Government under the Ashraya Yojane Scheme. Whereas, few houses have been constructed in the revenue sites and in the inherited land. The ground truth verification also revealed that the petitioners are having the site title deeds which are issued by the Government and in few cases under Bhagya Jyothi scheme, Government has provided electricity connections to the economically weaker sections.



Figure-12.3. Location of Adakimaranahalli village in Zone–3 and 4 of Arkavathi river course (Source - NPA)



Figure-12.4: Population trend in the Adakimaranahalli village

While interacting with the petitioners it was found that the Gram Panchayat supplying water through borewells and mini water supply. Some of the general observations include sewage discharge into pit, grey water discharge into open drain, solid waste management by the

Arkavathi Association, open drain sanitation and accessibility to road. There has been rapid growth of the population (Figure-12.4) and households (Figure-12.5) in the Adakimaranahalli village. The main reasons behind this rapid growth are proximity to BBMP area, NH-4 passing (Bengaluru–Tumakuru Road) through the village and also job opportunities.



Figure-12.5: Households statistics in the Adakimaranahalli village

During the ground truth verification, out of 191 cases 130 residential houses were identified and remaining 61 houses could not be identified (Figure-12.6). Pertaining to the unidentified residential houses, while interacting with the local people it was found that few owners sold their houses, few owners rented out their houses and relocated to Bengaluru and also it was found that few owners have passed away.



Figure-12.6: Field verification status in the Adakimaranahalli village

Further, a written statement (PANCHANAMA) was written in the presence of all the members of the committee *i.e.* EMPRI staff, two representatives of the petitioners and local people of the village along with their signatures. Panchanama of the ground verification of the residential superstructure is annexed in the Annexure-12.2. The current status of each identified residential houses in the Adakimaranahalli village are discussed below;

12.3.1. Petitioner No.4: Sri. Thimmarayappa, aged about 79 years S/o Sanna Hanumanthaiah residing at 24, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the interaction with the petitioner it was found that after the demolition of the 100 yrs old house the new duplex house has been constructed in the year 2008 (Figure-12.7). Further it was found that the house is coming under the Gramathana and presently six members are living in the house.

Petitioner No. 04	
Duplex House	

Figure-12.7: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.2. Petitioner No.12: Sri. H. Venkataiah, aged about 57 years S/o Hanumanthaiah residing at 177, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the house was constructed in the year 1989 (Figure-12.8) in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 12	
Residential Building	



Figure-12.8: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.3. Petitioner No.13: Sri. Venkatarasappa, aged about 77 years S/o Sanna Hanumaiah residing at 24, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1988 (Figure-12.9) and presently three members are living in these houses.

Petitioner No. 13	
Residential House	

Figure-12.9: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.4. Petitioner No.35: Smt. Galihanumaiah aged about 70 years W/o Bylappa residing at 16, Adakimaranahalli, Bangalore North Taluk, Bangalore Urban District – 562 123.

Petitioner No.762: Sri. Hanumegowda aged about 36 years S/o Galihanumaiah residing at 160-2, Adakimaranahalli, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2005 (Figure-12.10) in the site allotted by the Government under Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 35 and 762	
Residential House	

Figure-12.10: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.5. Petitioner No.40: Sri. Mariyappa, aged about 69 years S/o Siddalingaiah residing at, Adakimaranahalli, Bangalore North Taluk, Bangalore Urban District – 562 123.

Petitioner No.836: Smt. Mangalagowramma aged about 33 years W/o Maraiyappa residing at 155, Adakimaranahalli, Bangalore North - 562 123.

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that the single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1995 (Figure-12.11) in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 40 and 836	
Residential House	



Figure-12.11: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.6. Petitioner No.52: Sri. Kadirahanumaiah, aged about 68 years S/o Karihanumaiah residing at 108- B, Adakimaranahalli, Bangalore North – 562 123.

Documents Obtained: Electricity bill and title deed

Remarks: During the ground truth verification it was found that single house was constructed in the ground floor of the existing site and further the house has been partitioned into three houses for division among the Children. During the interaction with the petitioner it was found that the house was constructed in the year 1997 (Figure-12.12) in the site allotted by the Government under the Ashraya Yojane Scheme and electricity supply has been provided under the Bhagya Jyothi Scheme. Presently, three families with a total of fifteen members are living in these houses.

Petitioner No. 52	
Residential House	

Figure-12.12: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.7. Petitioner No.55: Sri. A.V. Narayanappa, aged about 68 years S/o Venkataramanappa residing at 46-D, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1985 (Figure-12.13) in the site allotted by the Government under the Ashraya Yojane Scheme and presently six members are living in these houses.

Petitioner No. *55*	
Residential House	

Figure-12.13: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.8. Petitioner No.57: Smt. Thimmakka, aged about 68 years W/o Siddalingaiah residing at 51, Adakimaranahalli, Bangalore North Taluk, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill and Title deed

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1987 (Figure-12.14) and later on renovated by constructing another house adjacent to the existing house due to division. Further it was found that the house has been constructed in the site allotted by the Government site under the Ashraya Yojane Scheme and presently, six members are living in these houses.

Petitioner No. *57*	
Residential House	

Figure-12.14: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.9. Petitioner No.64: Sri. Bailapp, aged about 67 years S/o Anjanappa residing at 48, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill and Title deed

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1998 (Figure-12.15) in the site allotted by the Government under the Ashraya Yojane Scheme and electricity supply has been provided under the Bhagya Jyothi Scheme. Presently two members are living in the house.

Petitioner No. 64	
Residential House	



Figure-12.15: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.10. Petitioner No.71: Sri. N.B. Shankaramurthy, aged about 66 years S/o Veerabadrappa residing at 187, Adakimaranahalli, Bangalore North – 562 123.

Remarks: During the ground truth verification it was found that G+2 building has been constructed and further it was found that the building was having four houses. During the interaction with the petitioner it was found that the house was constructed in the year 1995 (Figure-12.16) in the site allotted by the Government under the Ashraya Yojane Scheme and presently a total of thirty members are living in these houses.

Petitioner No. 71	
Residential Building	

Figure-12.16: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.11. Petitioner No.82: Smt. Chikmma aged about 65 years W/o Borashettappa residing at 235-2, Adakimaranahalli, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the old house was constructed in the year 1996 (Figure-12.17) which has been renovated in the year 2003. It was found that the house was constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently nine members are living in these houses.

Petitioner No. 82	
Residential Building	



Figure-12.17: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.12. Petitioner No.90: Sri. Shrirma aged about 29 years S/o M. Basavaraju residing at 187, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Petitioner No.327: Sri. Basavaraju aged about 51 years S/o Chikkaboregowda residing at 149-4, Adakimaranahalli, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the house was constructed in the year 2001 (Figure-12.18) in the site allotted by the Government under the Ashraya Yojane Scheme and presently six members are living in these houses.

Petitioner No. 90 and 327	
Residential Building	



Figure-12.18: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.13. Petitioner No.93: Sri. Vasudevamurthy aged about 29 years S/o Dhalivenkatayya residing at 95, Adakimaranahalli, Bangalore North – 562 123.

Petitioner No.416: Smt. V. Shoba aged about 25 years W/o Vasudevamurthi residing at 95, Adakimaranahalli, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of same family and further it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1999 (Figure-12.19) and has been renovated in the year 2005. Further it was found that the house was constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently six members are living in these houses.

Petitioner No. 93 and 416	
Residential House	

Figure-12.19: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.14. Petitioner No.102: Smt. Kamalamma aged about 63 years W/o late Siddappa residing at # 129, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2000 (Figure-12.20) in the site allotted by the Government under the Ashraya Yojane Scheme and presently eight members are living in these houses.

Petitioner No. 102	
Residential House	



Figure-12.20: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.15. Petitioner No.117: Sri. H. Jayaram aged about 29 years S/o Hanumantharayappa residing at Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1987 (Figure-12.21) in the site allotted by the Government under the Ashraya Yojane Scheme and presently five members are living in this house.

Petitioner No. 117	
Residential House	



Figure-12.21: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.16. Petitioner No.129: Smt. Padmamma aged about 61 years W/o Late Ganhadhaiah residing at 73, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that the building was having five houses. During the interaction with the petitioner it was found that the house was constructed in the year 1999 (Figure-12.22) in the site allotted by the Government under the Ashraya Yojane Scheme and presently a total of eight members are living in these houses.

Petitioner No. 129	
Residential Building	

Figure-12.22: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.17. Petitioner No.138: Sri. Mudlagiriyappa aged about 60 years S/o Venkatappa residing at 181, Adakimaranahalli, Bangalore North Taluk, Bangalore Urban District–562 123.

Petitioner No.320: Sri. Rajanna aged about 51 years S/o Madugiriyappa residing at 247-A- 17, Adakimaranahalli, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed from the members of the same family and further it was found that G+1 building has been constructed. While carrying out the ground truth verification, the petitioner house was locked and as per the information collected from the neighbour the house was constructed in the year 2012 (Figure-12.23) in the site allotted by the Government under the Ashraya Yojane Scheme and presently six members are living in the house.

Petitioner No. 138 and 320	
Residential Building	



Figure-12.23: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.18. Petitioner No.145: Sri. K. G. Panchallingaiah aged about 60 years S/o Gangappa residing at 47-4, Adakimaranahalli, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in the inherited land. During the interaction with the petitioner it was found that the house was constructed in the year 2008 (Figure-12.24) and presently three members are living in the house.

Petitioner No. 145	
Residential House	



Figure-12.24: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.19. Petitioner No.156: Sri. Rama Bahaddur aged about 59 years S/o Lal Bahaddur residing at # 161, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1997 (Figure-12.25) in the site allotted by the Government under the Ashraya Yojane Scheme and presently three families are living in these houses.

Petitioner No. 156	
Residential House	



Figure-12.25: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.20. Petitioner No.173: Sri. Kempaiah aged about 58 years S/o Kadiralakkaiah Residing at 104, Adakimaranahalli, Bangalore North – 562 123.

Documents obtained: Electricity bill and Title deed

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1987 (Figure-12.26) in the site allotted by the Government under the Ashraya Yojane Scheme and electricity supply has been provided under the Bhagya Jyothi scheme. Presently six members are living in the house.

Petitioner No. 173	
Residential House	



Figure-12.26: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.21. Petitioner No.174: H G Mayanna aged about 58 years S/o Gejjaiah residing at 189, Adakimaranahalli, Bangalore North – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed in the inherited land. During the interaction with the petitioner it was found that the house was constructed in the year 2000 (Figure-12.27) in an area 30'x35' and presently five members are living in the house.

Petitioner No. 174	
Residential Building	



Figure-12.27: GPS location of the petitioner house (Yellow colour) on Google Earth Image of 2014

12.3.22. Petitioner No.175: Sri. K. Gangaiah aged about 58 years S/o Kadiraiah residing at 146, Adakimaranahalli, Dasanapura Hobli, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two buildings have been constructed *i.e.* one G+ 1 building and single house in the ground floor in the existing site. During the interaction with the petitioner it was found that the buildingss were constructed in the year 1987 (Figure-12.28) and 2007 in the site allotted by the Government under the Ashraya Yojane Scheme and also electricity supply has been provided under the Bhagya Jyothi scheme. Presently a total of nine members are living in these houses.

Petitioner No. 175	
Residential Building	



Figure-12.28: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.23. Petitioner No.180: Sri. Shivananda Singha aged about 58 years S/o Ramashree Singha residing at 16, Adakimaranahalli, Bangalore North, Bangalore Urban District– 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2008 (Figure-12.29) in the site allotted by the Government under the Ashraya Yojane Scheme and presently two families with eight members are living in the house.

Petitioner No. 180	
Residential House	

Figure-12.29: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.24. Petitioner No.181: Smt. Sandrabai aged about 58 years W/o Narasinha Rao residing at 114, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two G+1 buildings have been constructed and further it was found that among the two buildings, one of the G+1 building under construction was in progress. During the interaction with the petitioner it was found that the old house was constructed in the year 1995 (Figure-12.30) and presently five members are living in the house.

Petitioner No. 181	
Residential Building	



Figure-12.30: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.25. Petitioner No.196: Smt. Putta Nanjamma aged about 57 years W/o Hanumantharayappa residing at 101, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. While carrying out the ground truth verification, the petitioner house was locked and as per the information collected from the neighbours the house was constructed in the year 1973 (Figure-12.31) in the site allotted by the Government under the Ashraya Yojane Scheme and presently three members is living in the house.

Petitioner No. 196	
Residential House	

Figure-12.31: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.26. Petitioner No.217: Smt. Manjula aged about 45 years W/o Hanumaiah residing at #123, Adakimaranahalli, Bangalore, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1987 (Figure-12.32) in the site allotted by the Government under the Ashraya Yojane Scheme and presently three members are living in these houses.

Petitioner No. 217	
Residential House	

Figure-12.32: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.27. Petitioner No.219: Sri. Hanumantharayappa aged about 56 years S/o Hanumaiah residing at 194, Adakimaranahalli, Bangalore North – 562 123.

Petitioner No.813: Smt. Venkatalakshmamma aged about 34 years W/o Hanumantharayappa residing at Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that single house has been constructed in the ground floor. While carrying out the ground truth verification, the petitioners house was locked and as per the information collected from the neighbours, the house was constructed in the year 1987 (Figure-12.33) and renovated in the year 2009. Further it was found that the house constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 219 and 813	
Residential House	



Figure-12.33: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.28. Petitioner No.220: Smt. N.Rudramma aged about 56 years W/o Govindaraju residing at 96, Adakimaranahalli, Bangalore North – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses along with shop have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1987 (Figure-12.34) in site allotted by the Government under the Ashraya Yojane Scheme and presently three members are living in these houses.

Petitioner No. 220	
Residential House along with shop	



Figure-12.34: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.29. Petitioner No.221: Sri. Bairappa aged about 56 years S/o Andanappa residing at 149-2, Adakimaranahalli, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building along with two commercial shops have been constructed in the existing site. During the interaction with the petitioner it was found that the building was constructed in the year 1980 (Figure-12.35) and further renovated in the year 2012. It was also found that the house has been constructed in site allotted by the Government under the Ashraya Yojane Scheme and presently a total of thirteen members are living in these houses.

Petitioner No. 221	
Residential Building along with shops	



Figure-12.35: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.30. Petitioner No.223: Smt. Mahalakshmi aged about 56 years W/o Narasinhayya residing at 247-A-31, Adakimaranahalli, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. While carrying out the ground truth verification, the petitioners house was locked and as per the information collected from the neighbours the house has been constructed in the year 1987 (Figure-12.36) in the site allotted by the Government under the Ashraya Yojane Scheme and presently five members are living in the house.

Petitioner No. 223	
Residential House	

Figure-12.36: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.31. Petitioner No.225: Sri. Devajja aged about 56 years S/o Ramanna residing at 48-3, Adakimaranahalli, Bangalore Urban District – 562 123.

Petitioner No.588: Sri. Manjunath about 36 years S/o Devajja residing at 48-3, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill.

Remarks: During the ground truth verification it was found that two petitions have been filed from the members of the same family and further it was found that single house has been constructed in the ground floor. During the interaction with the petitioners it was found that the house was constructed in the year 2010 (Figure-12.37) in the site allotted by the Government under the Ashraya Yojane Scheme and presently five members are living in the house.

Petitioner No. 225 and 588	
Residential House	



Figure-12.37: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.32. Petitioner No.226: Sri. Krishnappa aged about 55 years S/o Puttaswamppa residing at 171-A Adakimaranahalli, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor (Figure-12.38). During the interaction with the petitioner it was found that the house was constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 226	
Residential House	



Figure-12.38: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.33. Petitioner No.238: Sri. Ramakrishnappa aged about 55 years S/o Thimmahanumay residing at 187, Adakimaranahalli, Bangalore North – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor and further it was found that among the two houses one of the house have been vacant. During the interaction with the petitioner it was found that the house was constructed in the year 1996 (Figure-12.39) in the site allotted by the Government under the Ashraya Yojane Scheme and presently three members are living in the house.

Petitioner No. 238	
Residential House	

Figure-12.39: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.34. Petitioner No.239: Smt. Nilamma aged about 55 years W/o Ramachandra residing at 39, Adakimaranahalli, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1995 (Figure-12.40) in the site allotted by the Government under the Ashraya Yojane Scheme and presently five members are living in the house.

Petitioner No. 239	
Residential House	

Figure-12.40: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.35. Petitioner No.240: Sri. T.Venkateswa aged about 55 years S/o Thimmaiah residing at 126, Adakimaranahalli, Bangalore North – 562 123.

Petitioner No.243: Smt. T. S. Lakshmamma aged about 55 years W/o Venkateshappa residing at 157, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Petitioner No.732: Sri. Govindaraju aged about 37 years S/o Venkateshappa residing at 24, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that three petitions have been filed by the members of the same family and further it was found that two houses along with one commercial shop was constructed in the ground floor. During the interaction with the petitioners it was found that the house was constructed in the year 1995 (Figure-12.41) in the site allotted by the Government under the Ashraya Yojane Scheme and presently ten members are living in these houses.

Petitioner No. 240, 243 and 732	
Residential House along with shop	



Figure-12.41: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.36. Petitioner No.241: Sri. Vajrappa aged about 55 years S/o Maregowda residing at 197, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1985 (Figure-12.42) in the site allotted by the Government under the Ashraya Yojane Scheme and presently five members are living in the house.

Petitioner No. 241	
Residential House	



Figure-12.42: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.37. Petitioner No.244: Sri. Hanumantharayappa aged about 55 years S/o Rangappa residing at 129, Adakimaranahalli, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill and Title deed

Remarks: During the ground truth verification it was found that G+2 building along with two shops has been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 2002 (Figure-12.43) in the site allotted by the Government under the Ashraya Yojane Scheme and presently six members are living in these houses.

Petitioner No. 244	
Residential Building along with the shops	

Figure-12.43: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.38. Petitioner No.246: Sri. Shivalingaiah aged about 55 years S/o Hemaiah residing at #47, Adakimaranahalli, Bangalore North, Bangalore Urban – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed in the existing site and further it was found that building was having six houses. During the interaction with the petitioner it was found that the building was constructed in the year 1987 (Figure-12.44) in the site allotted by the Government under the Ashraya Yojane Scheme and presently six families are living in these houses.

Petitioner No. 246	
Residential Building	

Figure-12.44: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.39. Petitioner No.249: Sri. Somachar aged about 28 years S/o Siddachar residing at 48-1, Adakimaranahalli, Bangalore Urban – 562 123.

Petitioner No.633: Sri. Hanumanthachar aged about 41 years S/o Siddachar residing at 167, Adakimaranahalli, Bangalore North, Bangalore Urban – 562 123.

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that G+3 building along with shop has been constructed in the existing site. During the interaction with the petitioner it was found that after the demolition of old house the new building was constructed in the year 2014 (Figure-12.45) in the site allotted by the Government under the Ashraya Yojane Scheme and presently, three families and a total of twelve members are living in these houses.

Petitioner No. 249 and 633	
Residential Building	



Figure-12.45: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.40. Petitioner No. 255: Sri. Veeranna aged about 54 years S/o Erappa residing at 137-26, Adakimaranahalli, Bangalore Urban – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2005 (Figure-12.46) in the site allotted by the Government under the Ashraya Yojane Scheme and presently five members are living in these houses.

Petitioner No. 255	
Residential House	



Figure-12.46: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.41. Petitioner No.256: Sri. M.Mahimanna aged about 54 years S/o Munichannappa residing at 170, Adakimaranahalli, Bangalore Urban – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses along with the shop have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1996 (Figure-12.47) in the site allotted by the Government under the Ashraya Yojane Scheme and presently nine members are living in these houses.

Petitioner No. 256	
Residential House	

Figure-12.47: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.42. Petitioner No.259: Sri. Navaraja Bandari aged about 54 years S/o Kadakbhaddura residing at 99-1, Adakimaranahalli, Bangalore Urban – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 2013 (Figure-12.48) in the site allotted by the Government under the Ashraya Yojane Scheme and presently seven members are living in these houses.

Petitioner No. 259	
Residential Building	

Figure-12.48: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.43. Petitioner No.264: Sri. G.Kiran aged about 28 years S/o Goraka Bahuddoor residing at Adakimaranahalli, Bangalore North, Bangalore Urban – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor (Figure-12.49). While carrying out the ground truth verification, the petitioners house was locked and as per the information collected from the neighbours that the house was constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently eight members are living in the house.

Petitioner No. 264	
Residential House	

Figure-12.49: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.44. Petitioner No.272: Sri. Siddappa aged about 53 years S/o Henjarappa residing at 185, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2005 (Figure-12.50) in the inherited land and presently ten members are living in these houses.

Petitioner No. 272	
Residential House	

Figure-12.50: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.45. Petitioner No.286: Sri. Mala aged about 27 years S/o Ballappa residing at 181, Adakimaranahalli, Bangalore North, Bangalore Urban – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building has been constructed and further it was found that the second floor was having two rooms. During the interaction with the petitioner it was found that the house was constructed in the year 2013 (Figure-12.51) in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in these houses.

Petitioner No. 286	
Residential Building	



Figure-12.51: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.46. Petitioner No.294: Smt. Parvathamma. J. aged about 52 years W/o Gangadharappa residing at 183, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that five houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the old house was constructed in the year 1987 (Figure-12.52) which has been renovated in the year 2002 and further it was found that the house has been constructed in the site allotted by the Government under the Ashraya Yojane Scheme. Presently, five families and a total of twelve members are living in these houses.

Petitioner No. 294	
Residential House	



Figure-12.52: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.47. Petitioner No.298: Smt. Lakshmamma aged about 52 years W/o Nagaraju residing at 79-B, Adakimaranahalli, Bangalore Urban – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that four houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1990 (Figure-12.53) in the site allotted by the Government under Ashraya Yojane Scheme and presently a total of eight members are living in these houses.

Petitioner No. 298	
Residential House	



Figure-12.53: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.48. Petitioner No.318: Sri. Dharambahadoor aged about 51 years S/o Karambahadoor residing at 54, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that four houses have been constructed in the ground floor During the interaction with the petitioner it was found that the house was constructed in the site allotted by the Government under Ashraya Yojane Scheme and further it was found that the old house was constructed in the year 1993 (Figure-12.54) which has been renovated in the year 2012. Presently a total of eighteen members are living in these houses.

Petitioner No. 318	
Residential House	



Figure-12.54: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.49. Petitioner No.319: Sri. S.N.Rajanna aged about 51 years S/o Sibegowda residing at 172 A, Adakimaranahalli, Bangalore Urban – 562 123.

Documents obtained: Nil

Remarks: During the ground truth verification it was found that G+1 building has been constructed. While carrying out the ground truth verification, the petitioner house was locked and as per the information collected from the neighbours the building was constructed in the year 2011 (Figure-12.55) in the site allotted by the Government under the Ashraya Yojane Scheme and presently seven members are living in the house.

Petitioner No. 319	
Residential Building	

Figure-12.55: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.50. Petitioner No.321: Sri. Thimmaiah aged about 51 years S/o Hanumanthappa residing at 149-2, Adakimaranahalli, Bangalore Urban – 562 123.

Remarks: During the ground truth verification it was found that house G+1 building has been constructed and further it was found that first floor was having one room (Figure-12.56). While carrying out the ground truth verification, the petitioner house was locked and as per the information collected from the neighbours the house was constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 321	
Residential Building	



Figure-12.56: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.51. Petitioner No.322: Sri. Bylappa aged about 51 years S/o Venkatappa residing at #234-37, Adakimaranahalli, Bangalore North, Bangalore Urban – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the old house was constructed in the year 1970 (Figure-12.57) which has been renovated in the year 2010. Further it was found that the house was constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently six members are living in the house.

Petitioner No. 322	
Residential House	

Figure-12.57: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.52. Petitioner No.323: Smt. Girijamma aged about 51 years W/o Lakeshappa residing at Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Petitioner No.853: Sri. L. Harish aged about 32 years S/o N. Lokesha residing at 166, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1993 (Figure-12.58) in the site allotted by the Government under the Ashraya Yojane Scheme and presently a total of fourteen members are living in these houses.

Petitioner No. 323 and 853	
Residential House	



Figure-12.58: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.53. Petitioner No.324: Smt. Gangamma aged about 51 years W/o Venkatappa residing at 187-2, Adakimaranahalli, Bangalore Urban – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2004 (Figure-12.59) in the site allotted by the Government under the Ashraya Yojane Scheme and presently five members are living in the house.

Petitioner No. 324	
Residential House	

Figure-12.59: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.54. Petitioner No.333: Sri. Nataraja aged about 27 years S/o Kallelingachari residing at 04, Adakimaranahalli, Bangalore Urban – 562 123.

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the houses were constructed in the year 2005 (Figure-12.60) in the site allotted by the Government under the Ashraya Yojane Scheme and presently a total of ten members are living in these houses.

Petitioner No. 333	
Residential House	

Figure-12.60: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.55. Petitioner No.336: Sri. Prakasha aged about 27 years S/o Gnanamurthi residing at 163, Adakimaranahalli, Bangalore Urban – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2013 (Figure-12.61) in the site allotted by the Government under the Ashraya Yojane Scheme and presently a total of ten members are living in these houses.

Petitioner No. 336	
Residential House	



Figure-12.61: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.56. Petitioner No.363: Smt. Lakshmamma aged about 50 years W/o Honnagangaiah residing at 188, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1990 (Figure-12.62) in the site allotted by the Government under the Ashraya Yojane Scheme and presently one family with three members are living in the house.

Petitioner No. 363	
Residential House	

Figure-12.62: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.57. Petitioner No.364: Sri. Mohan aged about 50 years S/o Ramachandrappa residing at 234-55, Adakimaranahalli, Bangalore Urban – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1985 (Figure-12.63) in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 364	
Residential House	

Figure-12.63: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.58. Petitioner No.365: Sri. Sudakar aged about 50 years S/o Gangadasappa residing at 211, Adakimaranahalli, Bangalore North Taluk, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2006 (Figure-12.64) in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 365	
Residential House	

Figure-12.64: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.59. Petitioner No.366: Sri. Bailappa aged about 50 years S/o Hanumaiah residing at 160, Adakimaranahalli, Bangalore North, Bangalore Urban – 562 123.

Petitioner No.474: Sri. A.B. Madhu aged about 24 years S/o Bailappa residing at 160, Adakimaranahalli, Bangalore Urban – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of same family and further it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2005 (Figure-12.65) in the inherited land and presently three members are living in the house.

Petitioner No. 366 and 474	
Residential House	



Figure-12.65: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.60. Petitioner No.367: Sri. Chandrashekara aged about 50 years S/o Siddaiah residing at 202, Adakimaranahalli, Bangalore North Taluk, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house which was constructed in the year 1993 (Figure-12.66) has been demolished and construction of new building was under progress in the site allotted by the Government under the Ashraya Yojane Scheme.

Petitioner No. 367	
Before Demolition	After demolition construction under progress
Changes observed during the field verification	



Figure-12.66: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.61. Petitioner No. 370: Smt. Hanumanarasamma aged about 50 years W/o Late. Muniyappa residing at 175, Adakimaranahalli, Bangalore North Taluk, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that the four houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1998 (Figure-12.67) in the site allotted by the Government under the Ashraya Yojane Scheme in an area of (18'x25') and presently a total of seven members are living in these houses.

Petitioner No. 370	
Residential House	

Figure-12.67: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.62. Petitioner No.372: Sri. S. N. Narayanappa aged about 50 years S/o Narasaiah residing at 133, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building has been constructed. During the interaction with the petitioner it was found that the old house was constructed in the year 1997 (Figure-12.68) which has been renovated in the year 2011. Further it was found that the house has been constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently nine members are living in these houses.

Petitioner No. 372	
Residential Building	



Figure-12.68: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.63. Petitioner No.373: Sri. Narasimhamurthy aged about 50 years S/o Narasimhaiah residing at 95, Adakimaranahalli, Bangalore North Taluk, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2005 (Figure-12.69) in the site allotted by the Government under the Ashraya Yojane Scheme in the area 20'x25' and presently six members are living in these houses.

Petitioner No. 373	
Residential House	



Figure-12.69: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.64. Petitioner No.407: Sri Muthuraj aged about 48 years S/o Hanumanthayya residing at 156-1, Adakimaranahalli, Bangalore Urban – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that four houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1992 (Figure-12.70) in the site allotted by the Government under the Ashraya Yojane Scheme and presently thirteen members are living in these houses.

Petitioner No. 407	
Residential House	

Figure-12.70: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.65. Petitioner No.409: Smt. Kamalamma aged about 48 years W/o Ramaiah residing at # 124, Adakimaranahalli, Bangalore North, Bangalore Urban – 562 123.

Remarks: During the ground truth verification it was found that three houses along with one shop have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1987 (Figure-12.71) in the site allotted by the Government under the Ashraya Yojane Scheme and presently six members are living in these houses.

Petitioner No. 409	
Residential House along with shop	



Figure-12.71: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.66. Petitioner No.415: Sri. K.S. Chandrashekar aged about 48 years S/o Siddappa residing at 247-A-24, Adakimaranahalli, Bangalore Urban District– 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor (Figure-12.72). During the interaction with the petitioner it was found that the house was constructed in the allotted by the Government under the Ashraya Yojane Scheme and presently six members are living in these houses.

Petitioner No. 415	
Residential House	

Figure-12.72: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.67. Petitioner No.417: Sri. Raju aged about 48 years S/o Ningappa residing at 208, Adakimaranahalli, Bangalore North Taluk, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that the building was having five houses. During the interaction with the petitioner it was found that the building was constructed in the year 2005 (Figure-12.73) in the site allotted by the Government under the Ashraya Yojane Scheme and presently fifteen members are living in these houses.

Petitioner No. 417	
Residential Building	



Figure-12.73: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.68. Petitioner No.418: Sri. Rajappa aged about 48 years S/o Govindaswamy residing at 104, Adakimaranahalli, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1986 (Figure-12.74) in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in this house.

Petitioner No. 418	
Residential House	



Figure-12.74: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.69. Petitioner No.433: Sri. Kemparaju aged about 47 years S/o Kempiah residing at 239, Adakimaranahalli, Bangalore North Taluk, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1997 (Figure-12.75) in the site allotted by the Government under the Ashraya Yojane Scheme and presently two families, with a total of nine members are living in these houses.

Petitioner No. 433	
Residential House	



Figure-12.75: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.70. Petitioner No.457: Smt. Hanumanthamma aged about 46 years W/o Bylappa residing at #234-37, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor (Figure-12.76). During the interaction with the petitioner it was found that the house was constructed in the site allotted by the Government under the Ashraya Yojane Scheme and also electricity supply have been provided under the Bhagya Jyothi and presently, three families with a total of twelve members are living in these houses.

Petitioner No. 457	
Residential House	



Figure-12.76: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.71. Petitioner No.459: Sri. V. Ramakrishnappa aged about 46 years S/o Venkatappa residing at 176, Adakimaranahalli, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building along with shop (flour mill) has been constructed. During the interaction with the petitioner it was found that the house has been constructed in the year 1987 (Figure-12.77) and further the house has been renovated in the year 2002 in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 459	
Residential Building along with a shop	



Figure-12.77: GPS location of the petitioner house (Yellow colour) on Google Earth Image of 2014 in the Adakimaranahalli Village

12.3.72. Petitioner No.460: Smt. Nilakumari aged about 46 years W/o Govindaraju residing at 123-5, Adakimaranahalli, Bangalore Urban District – 562 123.

Petitioner No.526: Sri. Bharath aged about 24 years S/o D. Govindaraj residing at 123-5, Adakimaranahalli, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1992 (Figure-12.78) in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 460 and 526	
Residential House	



Figure-12.78: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.73. Petitioner No.461: Sri. Sher Bahadur aged about 46 years S/o C. Lalbahadur residing at 99, Adakimaranahalli, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2003 (Figure-12.79) in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 461	
Residential House	



Figure-12.79: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.74. Petitioner No.462: Sri. Chikkagangaiah aged about 46 years S/o Hanumanthaiah residing at 234-16, Adakimaranahalli, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1987 (Figure-12.80) and further renovated in the year 2000. Further it was found that the house was constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 462	
Residential House	

Figure-12.80: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.75. Petitioner No.463: Smt. Varalakshmi aged about 46 years W/o Partrasarathi residing at 12, Adakimaranahalli, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill and Title deed

Remarks: During the ground truth verification it was found that single house along with a shop has been constructed in the ground floor. During the interaction with the petitioner it was found that the new house was constructed in the year 1998 (Figure-12.81) after the demolition of the old building which was constructed in the year 1987 in the site allotted by the Government under the Ashraya Yojane Scheme. Presently five members are living in the house.

Petitioner No. 463	
Residential house along with a shop	



Figure-12.81: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.76. Petitioner No.464: Smt. Susheelamma aged about 46 years W/o Krishnappa residing at 191, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill and Title deed

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that the first floor having a single room. During the interaction with the petitioner it was found that the house was constructed in the year 1996 (Figure-12.82) and further renovated in the year 2007. It was also found that, the house was constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently three members are living in the house.

Petitioner No. 464	
Residential Building	



Figure-12.82: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.77. Petitioner No.492: Sri. Paramesha aged about 45 years S/o Obalappa residing at 113, Adakimaranahalli, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the houses were constructed in the year 1990 (Figure-12.83) in the site allotted by the Government under the Ashraya Yojane Scheme and presently two families with a total of four members are living in these houses.

Petitioner No. 492	
Residential House	

Figure-12.83: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.78. Petitioner No.519: Smt. Girija aged about 44 years W/o Narayan residing at 114-A1, Adakimaranahalli, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2007 (Figure-12.84) in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 519	
Residential House	



Figure-12.84: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.79. Petitioner No.523: Smt. Manjula aged about 44 years W/o Munihanumanthaiah residing at # 51, Adakimaranahalli, Dasanapura Hobli, Bangalore North – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor (Figure-12.85). During the interaction with the petitioner it was found that the houses have been constructed in the inherited land and presently four members are living in these houses.

Petitioner No. 523	
Residential House	



Figure-12.85: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.80. Petitioner No.549: Sri. Ramaiah aged about 43 years S/o Puttaiah residing at 195 Adakimaranahalli, Bangalore North Taluk, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2009 (Figure-12.86) in the site allotted by the Government under the Ashraya Yojane Scheme and presently three members are living in the house.

Petitioner No. 549	
Residential House	



Figure-12.86: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.81. Petitioner No.*557*: Smt. Rathnamma aged about 43 years W/o N. Rajanna residing at 221, Adakimaranahalli, Bangalore North – 562 123.

Documents obtained: Nil

Remarks: During the ground truth verification it was found that the two houses have been constructed in the ground floor. While carrying out the ground truth verification, the petitioner house was locked and as per the information collected from the neighbours the house was constructed in the year 1997 (Figure-12.87) in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in these houses.

Petitioner No. *557*	
Residential House	

Figure-12.87: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.82. Petitioner No.*559*: Smt. Nagamma aged about 43 years W/o Narasimhaiah residing at 228, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1995 (Figure-12.88) in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. *559*	
Residential House	



Figure-12.88: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.83. Petitioner No.573: Sri. N. Harish aged about 22 Years S/o Narasimha Murthy residing at 266, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill and Title deed

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2000 (Figure-12.89) site allotted by the Government under the Ashraya Yojane Scheme and presently t members are living in the house.

Petitioner No. 573	
Residential House	



Figure-12.89: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.84. Petitioner No.587: Smt. Bhagya about 33 years D/o Thimmahanumanna residing at 218, Adakimaranahalli Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that the single house has been constructed in the ground floor (Figure-12.90). While carrying out the ground truth verification, the petitioner house was locked and as per the information collected from the neighbours the house has been constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently two members are living in the house.

Petitioner No. 587	
Residential House	

Figure-12.90: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.85. Petitioner No.589: Smt. Palaniyamma about 42 years W/o Raju residing at Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses along with a shop have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1995 (Figure-12.91) which has been renovated in the year 2002. Further, it was found that the house has been constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in these houses.

Petitioner No. 589	
Residential House along with the shop	



Figure-12.91: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.86. Petitioner No.590: Sri. Mani about 42 years S/o Ramaswamy residing at 52, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1997 (Figure-12.92) and presently four members are living in the house.

Petitioner No. 590	
Residential House	



Figure-12.92: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.87. Petitioner No.608: Sri. T. Gopal aged about 47 years S/o A.H. Thimmarayappa residing at #24, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 2009 (Figure-12.93) and presently three members are living in house.

Petitioner No. 608	
Residential Building	

Figure-12.93: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.88. Petitioner No.618: Sri. Munegowda aged about 41 years S/o Ganganna residing at 43, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2009 (Figure-12.94) and presently eight members are living in these houses.

Petitioner No. 618	
Residential House	



Figure-12.94: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.89. Petitioner No.628: Sri. Iranna aged about 41 years S/o Ganganarasappa residing at 137-5, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Petitioner No.852: Smt. Pushpalatha aged about 32 years W/o Iranna residing at 137- 5, Adakimaranahalli, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill.

Remarks: During the ground truth it was found that two petitions have been filed by the members of the same family and further it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the old houses have been renovated in the year 2010 (Figure-12.95) and the houses have been constructed in the site allotted by the Government under the Ashraya Yojane Scheme. Presently, two families with nine members are living in these houses.

Petitioner No. 628 and 852	
Residential House	

Figure-12.95: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.90. Petitioner No.630: Sri. Dharmegaud aged about 41 years S/o Subbegaud residing at 248-5, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. Further it was found that the petitioner has rented out the house and the house has been constructed in the year 1995 (Figure-12.96) and presently five members are living in the house.

Petitioner No. 630	
Residential House	

Figure-12.96: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.91. Petitioner No.650: Smt. Jayalakshmi aged about 40 years W/o Chandrashekar residing at 169, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2010 (Figure-12.97) in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 650	
Residential House	



Figure-12.97: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.92. Petitioner No.651: Smt. Saraswathi aged about 40 years W/o Parappa residing at 165, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses along with a shop have been constructed in ground floor. Further, it was found that currently the shop is vacant. During the interaction with the petitioner it was found that the house was constructed in the year 1994 (Figure-12.98) in the site allotted by the Government under the Ashraya Yojane Scheme and presently eleven members are living in these houses.

Petitioner No. 651	
Residential House	



Figure-12.98: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.93. Petitioner No.653: Smt. Venkatalakshmi aged about 40 years W/o Venkatesh residing at 137-32, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the old house was constructed in the year 1987 (Figure-12.99) which has been renovated in the year 2000. Further it was found that the house was constructed in the site allotted by the Government under the Ashraya Yojane Scheme.

Petitioner No. 653	
Residential House	

Figure-12.99: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.94. Petitioner No.655: Smt. D. N. Suma about 40 years W/o Late Krishnappa residing at 42, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the old house was constructed in the year 1996 (Figure-12.100) which has been renovated in the year 2010. It was also found that the house has been constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently three members are living in these houses.

Petitioner No. 655	
Residential House	



Figure-12.100: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.95. Petitioner No.658: Sri. Venkateswa aged about 40 years S/o Dollaiah residing at 127, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1994 (Figure-12.101) in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 658	
Residential House	



Figure-12.101: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.96. Petitioner No.659: Smt. Gangalakshmamma aged about 40 years W/o Madesh residing at 137-6, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the houses was constructed in the year 1990 (Figure-12.102) in the site allotted by the Government under the Ashraya Yojane Scheme and presently three families with twelve members are living in these houses.

Petitioner No. 659	
Residential House	



Figure-12.102: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.97. Petitioner No.677: Sri. Maregowda aged about 39 years S/o Galihanumaih residing at #16, Adakimaranahalli, Dasanapura Hobli, Bangalore North, Bangalore Urban– 562 123.

Remarks: During the ground truth verification it was found that G+2 building has been constructed and further it was found that the building have five houses. During the interaction with the petitioner it was found that the building was constructed in the year 2014 (Figure-12.103) and presently a total of twenty members are living in these houses.

Petitioner No. 677	
Residential Building	



Figure-12.103: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.98. Petitioner No.678: Sri. Ramanjinappa aged about 39 years S/o Hanumaiah residing at 159-2, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Petitioner No.797: Smt. Manjamma aged about 31 years W/o Ramanjinappa residing at 159-2, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that G+2 building has been constructed and also building divided into eight houses. During the interaction with the petitioner it was found that the building was constructed in the year 2012 (Figure-12.104) and presently a total of twenty members are living in these houses.

Petitioner No. 678 and 797	
Residential Building	



Figure-12.104: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.99. Petitioner No.680: Sri. P. Gopal aged about 39 years S/o Prem Bahadoor residing at 137, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1992 (Figure-12.105) in the site allotted by the Government under the Ashraya Yojane Scheme and presently ten members are living in the house.

Petitioner No. 680	
Residential House	

Figure-12.105: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.100. Petitioner No.705: Smt. Jayamma aged about 38 years W/o Rajanna residing at # 128, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the old house that was constructed in the year 1987 (Figure-12.106) has been renovated in the year 2005. Further it was found that the house was constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently five members are living in these houses.

Petitioner No. 705	
Residential House	



Figure-12.106: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.101. Petitioner No.725: Sri. Lakshmanamurthy aged about 37 years S/o Galihanumaih residing at 17, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that the single houses along with three shops have been constructed in the ground floor (Figure-12.107). While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours the house has been constructed in the allotted site by the Government under the Ashraya Yojane Scheme and presently six members are living in the house.

Petitioner No. 725	
Residential House along with shops	

Figure-12.107: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.102. Petitioner No.753: Sri. N. Anand aged about 36 years S/o H. Nagaraju residing at 42, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours the house has been constructed in the year 2008 (Figure-12.108) and presently four members are living in the house.

Petitioner No. 753	
Residential House	

Figure-12.108: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.103. Petitioner No.754: Smt. Shanthamma aged about 36 years W/o Ramachandrappa residing at 190-4, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that the four houses have been constructed in the ground floor (Figure-12.109). While carrying out the ground truth verification, the petitioner house was locked and as per the information collected from the neighbours the house was constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently four families and overall eight members are living in these houses.

Petitioner No. 754	
Residential House	



Figure-12.109: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.104. Petitioner No. 761: Sri. Muniraju. A. aged about 36 years S/o Anjinappa residing at 11, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Petitioner No.763: Sri. Muniraju aged about 36 years S/o Sanjeevappa residing at 42-1, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two cases have been filed from the members of the same family and G+2 building has been constructed and further it was found that the building was having four houses. During the interaction with the petitioner it was found that the building was constructed in the year 1995 (Figure-12.110) in the site allotted by the Government under the Ashraya Yojane Scheme and presently twelve members are living in these houses.

Petitioner No. 761 and 763	
Residential House	



Figure-12.110: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.105. Petitioner No.784: Smt. Indra aged about 35 years W/o Hanumaiah residing at 176, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the old house has been renovated in the year 2008 (Figure-12.111). Further it was found that the houses have been constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently three families with a total of nine members are living in these houses.

Petitioner No. 784	
Residential House	



Figure-12.111: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.106. Petitioner No.785: Sri. Karisiddappa aged about 35 years S/o Mahadevaiah residing at 251, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the old house was constructed in the year 1985 (Figure-12.112) which has been renovated in the year 1995. Further it was found that the house has been constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently two families with a total of eight members are living in these houses.

Petitioner No. 785	
Residential House	

Figure-12.112: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.107. Petitioner No.794: Sri. Banumathi aged about 35 years S/o Govindaraju residing at 14, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building along with one shop has been constructed and it was also found that the first floor was having one room. During the interaction with the petitioner it was found that the old house was constructed in the year 1990 (Figure-12.113) which has been renovated in the year 2004. Further it was found that the house has been constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently five members are living in the house.

Petitioner No. 794	
Residential Building along with shop	



Figure-12.113: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.108. Petitioner No.795: Sri. Ramesh aged about 34 years S/o Thammaiah residing at 83, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1997 (Figure-12.114) in the site allotted by the Government under the Ashraya Yojane Scheme and presently a total of seven members are living in these houses.

Petitioner No. 795	
Residential House	



Figure-12.114: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.109. Petitioner No.811: Sri. Shivanna aged about 34 years S/o Shivaraiah residing at 217, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2013 (Figure-12.115) in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 811	
Residential House	



Figure-12.115: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.110. Petitioner No.812: Smt. A. G. Bhagyalaksmi aged about 34 years W/o Hanumantharaju residing at 13, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the houses were constructed in the year 2009 (Figure-12.116) in the site allotted by the Government under the Ashraya Yojane Scheme and presently twelve members are living in these houses.

Petitioner No. 812	
Residential House	

Figure-12.116: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.111. Petitioner No.818: Smt. Yashodhamma aged about 34 years W/o Rangaswamaiah residing at 137-29, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner, it was found that the house has been constructed in the year 1987 (Figure-12.117) in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 818	
Residential House	



Figure-12.117: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.112. Petitioner No.840: Sri. V. Raju aged about 33 years S/o Venkatesh residing at 70, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2010 (Figure-12.118) in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 840	
Residential House	

Figure-12.118: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.113. Petitioner No.851: Sri. R. Manjunatha aged about 31 years S/o Rajanna residing at 58, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor (Figure-12.119). While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours the house has been constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently three members are living in the house.

Petitioner No. 851	
Residential House	



Figure-12.119: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.114. Petitioner No.858: Smt. V. Manjula aged about 32 years W/o Muniraju residing at Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1995 (Figure-12.120) in the site allotted by the Government under the Ashraya Yojane Scheme and presently four members are living in the house.

Petitioner No. 858	
Residential House	



Figure-12.120: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Adakimaranahalli Village

12.3.115. Unidentified Petitioners: In the Adakimaranahalli village, out of 191 cases 130 residential houses case were identified and remaining 61 properties pertaining to the cases that could not be identified are given below:

1. **Petitioner No. 72:** Smt. Gangamma aged about 66 years W/o Rangappa residing at 179-3, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
2. **Petitioner No. 103:** Sri. H.N. Hanumaiah aged about 63 years S/o Narasimhaiah residing at 98, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
3. **Petitioner No. 121:** Sri. Narasinhamurthy aged about 29 years S/o Narayanappa residing at 46d, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
4. **Petitioner No. 128:** Smt. Asha aged about 29 years W/o Somashekar residing at 217(3), Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
5. **Petitioner No. 147:** Sri. Chandrappa aged about 60 years S/o Siddappa residing at 81, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
6. **Petitioner No. 159:** Smt. Bairamma aged about 59 years W/o Sajeevappa residing at 41, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
7. **Petitioner No.231:** Sri. S Manjula aged about 28 years S/o T.I. Chandrashekhara residing at 234, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
8. **Petitioner No. 233:** Smt. Vijayalakshmi aged about 28 years W/o Kumaraswami residing at 95-1, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
9. **Petitioner No. 245:** Sri. Venkatesh aged about 55 years S/o Hanumanthappa residing at 124, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
10. **Petitioner No.251:** Smt. Saraswathi aged about 28 years D/o Nagaraju residing at 98, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
11. **Petitioner No.254:** Sri. T. Chandrashekhar aged about 54 years S/o T. Giriyappa residing at 234, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
12. **Petitioner No.296:** Sri. Narasegowda aged about 52 years S/o Sidegowda residing at 193-1, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
13. **Petitioner No.299:** Sri. Krishnappa aged about 52 years S/o Thimmaiah residing at 191, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
14. **Petitioner No.300:** Smt. Padma aged about 52 years W/o A.V. Narayanappa residing at 46-D, Adakimaranahalli, Bangalore North, Bangalore Urban – 562 123.
15. **Petitioner No.317:** Sri. S.D. Ramachandramurthy aged about 51 years S/o Dasappa residing at 179, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
16. **Petitioner No.328:** Smt. Gowramma aged about 51 years W/o Viranna residing at 137-28, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

17. **Petitioner No.329:** Sri. Nanjundappa aged about 51 years S/o Revanasiddeshwar residing at #46-D-10, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
18. **Petitioner No.362:** Sri. M. Basavaraju aged about 50 years S/o Munisvamigoedaru residing at 184, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
19. **Petitioner No.369:** Sri. Hanumantharayappa aged about 50 years S/o Narasappa residing at 235-68, Adakimaranahalli, Bangalore Urban District – 562 123.
20. **Petitioner No.394:** Sri. V. Sharath Kumar aged about 49 years S/o Veeranna residing at #226, 8th Cross, Girishkarnad Road, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
21. **Petitioner No.396:** Sri. Hemavathi aged about 26 years S/o Sanjivayya residing at 177-1, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
22. **Petitioner No.397:** Sri. Varunkumar aged about 26 years S/o Veeranna residing at #226, 8th Cross, Girishkarnad Road, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
23. **Petitioner No.398:** Sri. Maruthi Prasanna aged about 26 years S/o Hanumantharayappa residing at 194, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
24. **Petitioner No.419:** Sri. Prasanna aged about 25 years S/o Venkateshappa residing at 55-1, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
25. **Petitioner No.442:** Sri. Basavaraju aged about 46 years S/o Thimmayya residing at #247-A-21, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
26. **Petitioner No.454:** Sri. R.B. Narayanaswami aged about 25 years S/o Ballappa residing at 69, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
27. **Petitioner No.458:** Sri. Thippeswami aged about 46 years S/o Govindaraju residing at 171-A-1, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
28. **Petitioner No.493:** Sri. R. Keshavamurthy aged about 45 years S/o Ramachandrappa residing at 248, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
29. **Petitioner No.521:** Smt. V. Madhu aged about 24 years S/o S. Veeranna residing at 246, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
30. **Petitioner No.522:** Sri. Nanjappa aged about 44 years S/o Narasimhaiah residing at 24-6, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
31. **Petitioner No.528:** Sri. M.N. Mohan Kumar aged about 24 years S/o M. Nagaraju residing at 169, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.
32. **Petitioner No.567:** Smt. G.H. Jagadamba aged about 23 years W/o Varun Kumar residing at #226, 8th Cross, Girishkarnad, Road, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

33. **Petitioner No.585:** Smt. Manjula about 42 years W/o Nagaraja residing at 476, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

34. **Petitioner No.625:** Smt. Kanchamma aged about 41 years W/o Hanumantharayappa residing at 235-68, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

35. **Petitioner No.631:** Sri. H.S. Nagaraj aged about 41 years S/o Sharanappa residing at 123-2, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

36. **Petitioner No.632:** Sri. Venkatesh aged about 41 years S/o Ballappa residing at 1-37-2, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

37. **Petitioner No.640:** Sri. N. Anatharao aged about 40 years S/o Nagojirao residing at # 26, 1st Cross, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

38. **Petitioner No.642:** Sri. Ramesh aged about 19 years residing at Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

39. **Petitioner No.652:** Smt. Suma aged about 30 years S/o Ramesha residing at 83, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

40. **Petitioner No.656:** Sri. Chandramma aged about 40 years S/o Nanjundappa residing at #46-10, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

41. **Petitioner No.657:** Smt. H.B. Jayalakshmi aged about 40 years W/o Nagaraju residing At 157, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

42. **Petitioner No.660:** Smt. Sharadamma aged about 40 years W/o Siddaramaiah residing at 179-2, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

43. **Petitioner No.663:** Sri. Prem aged about 30 years S/o Narasinhamurthi residing at 91, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

44. **Petitioner No.679:** Sri. Parwathi aged about 39 years S/o Srrinivas residing at 31-5, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

45. **Petitioner No.685:** Sri. Panthappa aged about 39 years S/o Alukondappa residing at #27(1), Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

46. **Petitioner No.696:** Smt. Yashodha aged about 30 years W/o Srinivas residing at 177-1, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

47. **Petitioner No.713:** Sri. Mahadevayya aged about 38 years S/o Doddanarasinhayya residing at 223-2, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

48. **Petitioner No.728:** D. Sri. Srinivas Murthy, S/o Dasappa, aged about residing at 410, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

49. **Petitioner No.733:** Sri. Ramesh Babu aged about 37 years S/o Rama Chandrappa residing at 48, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

50. **Petitioner No.756:** Sri. Manjula aged about 36 years W/o Chandrappa residing at 230, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

51. **Petitioner No.786:** Sri. Gangraj aged about 35 years S/o Thimmappaiah residing at 155-5, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

52. **Petitioner No.787:** Sri. Kumaraswami aged about 35 years S/o Lakkappa residing at 95-1, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

53. **Petitioner No.789:** Sri. K. S. Gopalkrishna aged about 35 years S/o Seebinarsaiah residing at No 134/1, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

54. **Petitioner No.791:** Sri. Gangaraju aged about 35 years S/o Thimmaiah residing at 216, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

55. **Petitioner No.792:** Sri. Mahesh aged about 35 years S/o Narasinhayya residing at 137 -31, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

56. **Petitioner No.793:** Smt. Krishnaveni aged about 35 years W/o V. Ramakrishnappa residing at 176, Adakimaranahalli, Bangalore Urban District - 562 123.

57. **Petitioner No.819:** Smt. V. Kamala aged about 34 years W/o Maregowda residing at 149, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

58. **Petitioner No.824:** Sri. Shivu aged about 31 years S/o Ramaiah residing at 56, Adakimaranahalli, Bangalore North, Bangalore Urban District -562 123.

59. **Petitioner No.825:** Sri. Sujatha aged about 31 years D/o Ballappa residing at 234-1, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

60. **Petitioner No.838:** Sri. Gopalkrishna aged about 31 years S/o Narasimaiah residing at 247-A-31, Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

61. **Petitioner No.842:** Sri. M. Anil aged about 31 years S/o N. Muniraju residing at Adakimaranahalli, Bangalore North, Bangalore Urban District – 562 123.

12.4. Siddanahosahalli Village:

Siddanahosahalli is coming under the jurisdiction of Madanayakanahalli Gram Panchayat and as per the 2011 census the Siddanahosahalli has an area of 0.79 Sq.Km. with population of 6,165 and 1,694 households. The Siddanahosahalli village falls in the Zone-3 and 4 of the Arkavathi river stretch of the TGR catchment area (Figure-12.121).



Figure-12.121: Location of Siddanahosahalli village in the Zone–3 & 4 (Source – NPA)

In the Siddanahosahalli village, 109 petitions are filed (Annexure–12.4) and during the ground verification it was found that in few cases two to three petitions have been filed by members of one family *i.e.* father and son or husband and wife etc. The ground truth verification revealed that most of the houses are constructed in the survey No. 12, 14, 16, 19, 20, 29, 30, 33 and 34, few of the houses have been constructed in the Gramathana and whereas few houses have been constructed in the developing layouts and also few of the sites are vacant. The ground truth verification also revealed that in survey No. 30, land was allotted by the Mysore Government to an extent of 2.37 Acres in the year 1972 for housing to the economically weaker sections (houseless people) and presently there are 70 to 80 houses in this survey number. During the ground truth verification it was also found that some of the residential houses were constructed in the year 1942, 1952 and it was found that after 80's and 90's many houses have come-up and more intensively in 2000. At present many houses are renovated adding 1-2 floors and in few cases are being used as commercial shops which are rented out for income generation.

While interacting with the petitioner it was found that the Gram Panchayat is supplying water through borewells and mini water supply and in few cases it was found that the houses were having borewells. Some of the general observations include sewage discharge into pit, grey water discharge into open drain, solid waste managed by Gram Panchayat, open drain sanitation and accessibility to road. There has been rapid growth of the population (Figure-12.122) and also number of households (Figure-12.123) in the Siddanahosahalli village and the main reasons behind this rapid growth are proximity to BBMP area, NH-4 passing (Bengaluru-Tumakuru Road) through the village and also job opportunities.

During the ground truth verification, out of 109 cases 85 residential houses cases were identified and remaining 24 houses could not be identified (Figure-12.124). The local people and the persons accompanying the ground truth exercise expressed inability to locate these addresses. Further, a written statement (PANCHANAMA) was written in the presence of all the members of the committee i.e. EMPRI staff, two representatives of the petitioners and local

people of the village along with their signatures. Panchanama of the ground verification of the residential superstructure is annexed in the Annexure-12.2. The current status of each of the identified petitioners houses in the Siddanahosahalli village are discussed below:



Figure-12.122: Population trend in the Siddanahosahalli village



Figure-12.123: Households statistics in the Siddanahosahalli village



Figure-12.124: Field verification status in the Siddanahosahalli village

12.4.1. Petitioner No.2: Smt. Thangamma aged about 81 years W/o Late Murugeshappa residing at E-334, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (30′x40′). During the interaction with the petitioner it was found that the building was constructed in the site allotted by the Mysore Government for the economically weaker section in the year 1972 (Figure-12.125) which has been renovated in the year 2000 and presently eight members are living in these houses.

Petitioner No. 02	
Residential Building	

Figure-12.125: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.2. Petitioner No.16: Sri. Venakataramanappa aged about 76 years S/o Mudagiriyappa residing at E-842, Hanumanthagowdanapalya, Siddanahosahalli-2, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that the building was having nine houses. During the interaction with the petitioner it was found that the building was constructed in the year 2006 (Figure-12.126) and presently a total of twenty four members are living in these houses.

Petitioner No. 16	
Residential Building	

Figure-12.126: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.3. Petitioner No.17: Sri. Govindappa aged about 76 years S/o Veerabhirappa residing at 32-1, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building along with shops have been constructed in an area of 26′x77′ and the building is coming under the Gramathana. During the interaction with the petitioner it was found that the building was constructed in the year 1987 (Figure-12.127) which has been renovated in the year 2004 and presently ten members are living in these houses.

Petitioner No. 17	
Residential building along with the commericail shop	

Figure-12.127: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.4. Petitioner No.19: Sri. Puttayya aged about 73 years S/o Chikkanna, residing at E-338-E, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 30′x40′. During the interaction with the petitioner it was found that the house was constructed in the site allotted by the Mysore Government for the economically weaker section in the year 1972 (Figure-12.128) and presently four members are living in the house.

Petitioner No. 19	
Residential House	

Figure-12.128: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.5. Petitioner No.50: Sri. Chandra Shekaraiah aged about 57 years S/o H. Ramaiah residing at E-990, Hanumanthagowdanapalya, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1985 (Figure-12.129) and presently a total of ten members are living in these houses.

Petitioner No. 50	
Residential House	

Figure-12.129: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.6. Petitioner No.54: Sri. Mahadevaiah aged about 35 years S/o Krishnappa residing at E-1023, Hanumanthagowdanapalya, Siddanahosahalli-2, Bangalore North, Bangalore Urban-District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 20′x30′. During the interaction with the petitioner it was found that the house has been constructed in the year 2014 (Figure-12.130) and presently three members are living in the house.

Petitioner No. 54	
Residential House	

Figure-12.130: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.7. Petitioner No.65: Sri. H.B. Bylappa aged about 66 years S/o Venkataramaiah residing at 91, Hanumanthagowdanapalya, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 20′x30′. During the interaction with the petitioner it was found that the house was constructed in the year 1975 (Figure-12.131) which has been renovated in the year 2000 and presently six members are living in the house.

Petitioner No. 65	
Residential House	

Figure-12.131: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.8. Petitioner No.73: Sri. Bhadrayya aged about 66 years S/o Papanna residing at 27-3, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 1970 (Figure-12.132) and presently five members are living in these houses.

Petitioner No. 73	
Residential Building	

Figure-12.132: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.9. Petitioner No.85: Sri. Venkatappa aged about 64 years S/o Balla Hanumaiah residing at 892, Hanumanthagowdanapalya, Siddanahosahalli-2, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed During the interaction with the petitioner it was found that the building was constructed in the year 2015 (Figure-12.133) and presently six members are living in the house.

Petitioner No. 85	
Residential Building	

Figure-12.133: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.10. Petitioner No.97: Smt. Puttamma aged about 63 years W/o Narayanappa residing at 102, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house along with shop has been constructed in the ground floor and the house is coming under the Gramathana. During the interaction with the petitioner it was found that after the demolition of the old house, which was constructed in the year 1942 (Figure-12.134) the new house has been constructed in the year 2012.

Petitioner No. 97	
Residential house along with the shop	

Figure-12.134: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.11. Petitioner No.98: Smt. Lalithamma aged about 29 years S/o Hanumanthayya residing at E-363, Siddanahosahalli-1, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed (Figure-12.135). While carrying out the ground verification the petitioner house was locked and as per information collected from the neighbours presently twelve members are living in the house.

Petitioner No. 98	
Residential House	

Figure-12.135: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.12. Petitioner No.142: Sri. Veerabhadrayya aged about 60 years S/o Late Rudrayya Laxmipur residing at Laxmipur Road, Virabhadra Nilaya, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building along with the shops have been constructed in an area of 30′x40′. During the interaction with the petitioner it was found that building was constructed in the year 2009 (Figure-12.136) in the Chikkabyrappa layout and presently a total of ten members are living in these houses.

Petitioner No. 142	
Residential building along with the shops	

Figure-12.136: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.13. Petitioner No.143: Sri. Basavarajappa aged about 60 years S/o Late Gangappa residing at E-444, Siddanahosahalli-1, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of 30′x40′. During the interaction with the petitioner it was found that building was constructed in the year 2000 (Figure-12.137) and presently four members are living in the house.

Petitioner No. 143	
Residential Building	

Figure-12.137: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.14. Petitioner No. 152: Sri. H.K. Rajanna aged about 59 years S/o Kempegowda residing at # 16, Hanumanthagowdanapalya, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of 30′x40′. During the interaction with the petitioner it was found that building was constructed in the year 2006 (Figure-12.138) and presently a total of fifteen members are living in these houses.

Petitioner No. 152	
Residential Building	

Figure-12.138: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.15. Petitioner No.170: Sri. Muniyappa aged about 58 years S/o Irabairappa residing at E-875, Hanumanthagowdanapalya, Siddanahosahalli-2, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that house was constructed in the year 2014 (Figure-12.139) and presently three members are living in the house.

Petitioner No. 170	
Residential House	

Figure-12.139: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.16. Petitioner No.171: Sri. Ramakrishnaiah aged about 58 years S/o Chikkabhairappa residing at #E-343, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that four houses have been constructed in the ground floor in an area of 100′x120′. During the interaction with the petitioner it was found that house was constructed in the year 2004 (Figure-12.140) in the Chikkabyrappa layout and presently a total of twenty members are living in these houses.

Petitioner No. 171	
Residential Houses	

Figure-12.140: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.17. Petitioner No.192: Sri. Anthony Raj aged about 57 years S/o Soosiyappa residing at #68, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+2 building has been constructed and it was found that the building was having five houses. During the interaction with the petitioner it was found that building was constructed in the site allotted by the Mysore Government for the economically weaker section in the year 1980 (Figure-12.141) which has been renovated in the year 1983 and presently a total of twenty members are living in these houses.

Petitioner No. 192	
Residential Building	

Figure-12.141: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.18. Petitioner No.206: Smt. Lakshmamma aged about 56 years W/o. Gangappa residing at #101b, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that five houses have been constructed in an area of 30′x70′ and the house is coming under the Gramathana. During the interaction with the petitioner it was found that house was constructed in the year 1952 (Figure-12.142) and presently a total of twenty one members are living in these houses.

Petitioner No. 206	
Residentila House	

Figure-12.142: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.19. Petitioner No. 207: Smt. Gangamma aged about 56 years W/o Late Muniyappa residing at E-435, Siddanahosahalli-1, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that house was constructed in the year 2000 (Figure-12.143) in the Govindappa layout and presently a total of six members are living in these houses.

Petitioner No. 207	
Residentila House	

Figure-12.143: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.20. Petitioner No.208: Sri. Muniyappa aged about 56 years S/o Hanumaiah residing at 114, Siddanahosahalli-2, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of 15'x40'. During the interaction with the petitioner it was found that the house was constructed in the site allotted by the Mysore Government for the economically weaker section in the year 1972 (Figure-12.144) which has been renovated in the year 2000 and presently a total of fourteen members are living in these houses.

Petitioner No. 208	
Residential Building	

Figure-12.144: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.21. Petitioner No.218: Smt. Jayamma aged about 56 years W/o Late Galihanumayya residing at E-287, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Petitioner No.841: Sri. G. Nagaraju aged about 31 years S/o Galihanumaiah residing at 107A, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found two petitions have been filed by the members of the same family and further it was found that single house has been constructed in the ground floor in an area of 15′x40′. During the interaction with the petitioner it was found that the house has been constructed in the year 2005 (Figure-12.145) and presently three members are living in the house.

Petitioner No. 218 and 841	
Residential House	



Figure-12.145: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.22. Petitioner No.252: Smt. Gangabairamma aged about 54 years W/o Rangeswami residing at E-486, Siddanahosahalli-1, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 2006 (Figure-12.146) and presently six members are living in the house.

Petitioner No. 252	
Residential Building	

Figure-12.146: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.23. Petitioner No.270: Sri. M.R. Dorai aged about 53 years S/o Muniswamy residing at #80, Hanumanthagowdanapalya, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of 30'x40 'and it was found that the building was having three houses. During the interaction with the petitioner it was found that the building was constructed in the year 2004 (Figure-12.147) and presently a total of eleven members are living in these houses.

Petitioner No. 270	
Residential Building	

Figure-12.147: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.24. Petitioner No.290: Sri. E. Nagaraj aged about 52 years S/o Venkatappa residing at E-864, Hanumanthagowdanapalya, Siddanahosahalli-2, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2003 (Figure-12.148) and presently five members are living in the house.

Petitioner No. 290	
Residential House	

Figure-12.148: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.25. Petitioner No.313: Sri. Channappa aged about 51 years S/o Appanna residing at #E 255, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2003 (Figure-12.149) and presently four members are living in the house.

Petitioner No. 313	
Residential House	

Figure-12.149: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.26. Petitioner No.325: Smt. Lakshmidevamma aged about 51 years W/o Ramayya residing at 375-E-A, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1994 (Figure-12.150) and presently eight members are living in the house.

Petitioner No. 325	
Residential House	

Figure-12.150: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.27. Petitioner No.334: Smt. Shailaja aged about 27 years W/o Manjunath residing at E-288, Siddanahosahalli, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that the site area of 30′x40′ was vacant and it is located in Narayanappa layout (Figure-12.151).

Petitioner No. 334	
Vacant Site	

Figure-12.151: GPS location of the petitioner site (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.28. Petitioner No.355: Sri. K. Lakshmikantha aged about 50 years S/o Krishna Murthi residing at 177, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building has been constructed in an area of (30′x40′). During the interaction with the petitioner it was found that the building was constructed in the year 2011 (Figure-12.152) and presently a total of five members are living in these houses.

Petitioner No. 355	
Residential Building	

Figure-12.152: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.29. Petitioner No.356: Sri. Narayanaswamy aged about 50 years S/o Puttananjaiah residing at 6, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (30'x40') and it was found that the building was having twenty five houses. During the interaction with the petitioner it was found that the building was constructed in the year 2002 (Figure-12.153) and presently a total of hundred members are living in these houses and it was also found that the house was having bore well.

Petitioner No. 356	
Residential Building	

Figure-12.153: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.30. Petitioner No.376: Sri. Kuldip aged about 50 years S/o Jaganatha Sharma residing at E-28, Siddanahosahalli-1, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (30'x40'). During the interaction with the petitioner it was found that the building was constructed in the year 2003 (Figure-12.154) and presently five members are living in the house.

Petitioner No. 376	
Residential Building	

Figure-12.154: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.31. Petitioner No.381: Sri. Jagadish aged about 26 years S/o Hanumnatharayappa residing at Ew-873, Hanumanthagowdanapalya, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor and presently the house is vacant (Figure-12.155). As per the information collected from the neighbours the petitioner has shifted out from the house.

Petitioner No. 381	
Vacant House	

Figure-12.155: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-1 Village

12.4.32. Petitioner No.390: Sri. Malleshaiah aged about 49 years S/o Bhadrappa residing at E-362- E, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor in an area of (30'x40'). During the interaction with the petitioner it was found that the houses have been constructed in the year 2004 (Figure-12.156) and presently six members are living in these houses.

Petitioner No. 390	
Two houses in the ground floor	

Figure-12.156: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.33. Petitioner No.410: Sri. Ramakrishna aged about 48 years S/o Hanumanthaiah residing at E-350, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that the site area of 50' x 39' was vacant and it is located in Veerabhadrappa layout (Figure-12.157).

Petitioner No. 410	
Vacant Site	

Figure-12.157: GPS location of the petitioner site (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.34. Petitioner No.431: Sri. Y.D. Hanumegowda aged about 47 years S/o Dodda Kunnegowda residing at # 16, 1st Main Road,1st Cross, Hanumanthagowdanapalya, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2014 (Figure-12.158) and presently a total of six members are living in these houses.

Petitioner No. 431	
Residential House	

Figure-12.158: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.35. Petitioner No.448: Sri. Venkatesha, aged about 46 years S/o Hanumayya residing at E-862, Hanumanthagowdanapalya, Siddanahodahalli-2, Bangalore Urban District – 562 123.

Petitioner No.510: Sri. Muniraju aged about 44 years S/o Hanumayya residing at E-861, Hanumanthagowdanapalya, Siddanahosahalli-2, Bangalore Urban District – 562 123.

Petitioner No.805: Smt. Maithradevi aged about 34 years W/o Krishnappa residing at E-863, Hanumanthagowdanapalya, Siddanahosahalli-2, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that three petitions have been filed by the members of the same family and further it was fund that three houses have been constructed in the ground floor in an area of (40′x60′) in the inherited land. During the interaction with the petitioners it was found that the houses have been constructed in the year 1990 (Figure-12.159) and presently ten members are living in these houses.

Petitioner No. 448, 510 & 805	
Residential House	

Figure-12.159: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.36. Petitioner No.449: Sri. Maruthi, aged about 46 years S/o Mariayappa residing at E-217, Siddanahodahalli-1, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 15′x40′. During the interaction with the petitioner it was found that the house has been constructed in the year 2012 (Figure-12.160) in Lakshmidevamma layout and presently three members are living in the house.

Petitioner No. 449	
Residential House	

Figure-12.160: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.37. Petitioner No.451: Smt. Chikkamma aged about 46 W/o Virkempaiah residing at #E-103, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 20′x30′. During the interaction with the petitioner it was found that the house has been constructed in the year 1995 (Figure-12.161) and presently five members are living in the house.

Petitioner No. 451	
Residential House	

Figure-12.161: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.38. Petitioner No.480: Sri. G. Shivakumara aged about 24 years S/o Govindappa residing at E-857, Hanumanthagowdanapalya, Siddanahosahalli-2, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two house have been constructed in the ground floor in an area of 30′x40′. During the interaction with the petitioner it was found that the house was constructed in the year 2002 (Figure-12.162) and presently five members are living in these houses.

Petitioner No. 480	
Residential House	

Figure-12.162: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.39. Petitioner No.485: Sri. Venkatanarasaiah aged about 45 years S/o Gangappa residing at 40, Hanumanthagowdanapalya, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor in an area of (33′x60′). During the interaction with the petitioner it was found that the house was constructed in the year 1998 (Figure-12.163) and presently a total of twelve members are living in these houses.

Petitioner No. 485	
Residential House	

Figure-12.163: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.40. Petitioner No.486: Smt. Renuka aged about 45 years W/o Nagaraju residing at E-210, Siddanahosahalli-1, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that the site area of 10′x15′ was vacant and it is located in Narayanappa layout (Figure-12.164).

Petitioner No. 486	
Vacant Site	

Figure-12.164: GPS location of the petitioner site (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.41. Petitioner No.490: Sri. Channaveerappa aged about 45 years S/o B.S. Siddagangappa residing at 65-E, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1992 (Figure-12.165) and presently four members are living in the house.

Petitioner No. 490	
Residential House	

Figure-12.165: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.42. Petitioner No.511: Sri. A. S. Chayadevi aged about 44 years S/o K. Lakshmikantha residing at 177, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building has been constructed and it was found that the building was having seven houses. During the interaction with the petitioner it was found that the building has been constructed in the year 2003 (Figure-12.166) and presently a total of forty two members are living in these houses and it was also found that the house was having borewell.

Petitioner No. 511	
Residential Building	

Figure-12.166: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.43. Petitioner No.517: Sri. Ramakrishnayya aged about 44 years S/o Venkataramayya residing at E-15, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 30′x40′. During the interaction with the petitioner it was found that the house has been constructed in the year 2008 (Figure-12.167) and presently four members are living in the house.

Petitioner No. 517	
Residential House	

Figure-12.167: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.44. Petitioner No.548: Sri. Venkatesh aged about 43 years S/o Thimmaiah residing at 1048, Hanumanthagowdanapalya Siddanahosahalli, Bangalore North, Bangalore Urban District -562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2006 (Figure-12.168) and presently five members are living in the house.

Petitioner No. 548	
Residential House	

Figure-12.168: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.45. Petitioner No.550: Sri. J. Puttegoud Hecha aged about 43 years S/o Julegaud residing at E-452, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 30′x40′. During the interaction with the petitioner it was found that the house has been constructed in the Anandappa layout (Figure-12.169) and presently four members are living in the house.

Petitioner No. 550	
Residential House	

Figure-12.169: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.46. Petitioner No.580: Sri. Hanumantharaju aged about 42 years S/o Munihanumayya residing at E-424, Siddanahodahalli-1, Bangalore North, Bangalore Urban District – 562 123.

Petitioner No.788: Smt. Shobha aged about 35 years W/o Hanumnatharaju residing at E-424, Siddanahosahalll-1, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and it was found that five houses along with two shops have been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2005 (Figure-12.170) and presently a total of twenty members are living in these houses and it was found that the house was having borewell.

Petitioner No. 580 and 788	
Residential house along with the shops	

Figure-12.170: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.47. Petitioner No.620: Sri. K. G. Srinivas aged about 41 years S/o Jayanna residing at #3, (Behind School), Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor in an area of 30′x40′. During the interaction with the petitioner it was found that the house has been constructed in the year 2000 (Figure-12.171) in Govindappa layout and presently a total of ten members are living in these houses.

Petitioner No. 620	
Residential House	

Figure-12.171: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.48. Petitioner No.621: Smt. Jayamma aged about 41 years W/o Puttegaud residing at E-452, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that the site area of 30'x40' was vacant and it is located in the Anandappa layout (Figure-12.172).

Petitioner No. 621	
Vacant Site	

Figure-12.172: GPS location of the petitioner site (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.49. Petitioner No.623: Sri. Manjunatha aged about 41 years S/o Chhalapathi residing at E-367, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor in an area of 16'x27'. During the interaction with the petitioner it was found that the house was constructed in the year 2006 (Figure-12.173) in Narayanappa layout and presently a total of thirteen members are living in these houses.

Petitioner No. 623	
Residential House	



Figure-12.173: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.50. Petitioner No.624: Smt. Kamalamma aged about 41 years W/o Chhalapathi residing at E 367, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area 30'x40'. During the interaction with the petitioner it was found that the house has been constructed in the year 2005 (Figure-12.174) in Narayanappa layout and presently five members are living in the house.

Petitioner No. 624	
Residential House	

Figure-12.174: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.51. Petitioner No.626: Sri. V. Nagaraju aged about 41 years S/o Viranna residing at E-427, Siddanahosahalli-2, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that the site area of 35'x40' was vacant and it is located in the Poojarappa layout (Figure-12.175).

Petitioner No. 626	
Vacant Site	



Figure-12.175: GPS location of the petitioner site (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.52. Petitioner No.672: Sri. Nipur Patak aged about 39 years S/o Rajanish Patak residing at Hanumanthagowdanapalya, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 30'x40'. During the interaction with the petitioner it was found that the house has been constructed in the year 2015 (Figure-12.176) and presently four members are living in the house.

Petitioner No. 672	
Residential House	

Figure-12.176: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.53. Petitioner No.673: Sri. Ravi Kumar aged about 39 years S/o Narayanappa residing at E-250, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building along with four shops have been constructed in an area of 26'x77' and building is coming under the Gramathana. During the interaction with the petitioner it was found that the building was constructed in the year 1942 (Figure-12.177) which has been renovated in the year 1993.

Petitioner No. 673	
Residential Building along with the shops	

Figure-12.177: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.54. Petitioner No.674: Smt. Annapoorna aged about 39 years W/o R. Manjunath residing at 873, Hanumanthagowdanapalya, Siddanahosahalll-2, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses along with one shop have been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2014 (Figure-12.178) and presently four members are living in these houses.

Petitioner No. 674	
Residential house along with the shop	

Figure-12.178: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.55. Petitioner No.675: Sri. S. Ramesh Shetty aged about 39 years S/o B. Shankarayya Setty residing at 127c, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor in an area of 30'x40'. During the interaction with the petitioner it was found that the house was constructed in the year 2008 (Figure-12.179) in Narayanapppa layout and presently a total of seven members are living in these houses.

Petitioner No. 675	
Residential House	

Figure-12.179: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.56. Petitioner No.702: Sri. Manjunatha aged about 38 years S/o Late Basappa residing at E-461, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (30′x25′). During the interaction with the petitioner it was found that the building was constructed in the year 2004 (Figure-12.180) and presently five members are living in the house.

Petitioner No. 702	
Residential Building	

Figure-12.180: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.57. Petitioner No.703: Sri. H.R. Prashanth Kumar aged about 38 years S/o H. Rama residing at E-119/A, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 30′x40′. During the interaction with the petitioner it was found that the house has been constructed in the year 2003 (Figure-12.181) and presently three members are living in the house and it was also found that the house was having borewell.

Petitioner No. 703	
Residential House	

Figure-12.181: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.58. Petitioner No.704: Smt. Jayalakshmi aged about 38 years W/o Shrinivas residing at 360- E, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+2 building has been constructed in an area of 20'x40'. During the interaction with the petitioner it was found that the building was constructed in the year 2007 (Figure-12.182) and presently a total of fifteen members are living in these houses.

Petitioner No. 704	
Residential Building	

Figure-12.182: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.59. Petitioner No.722: Smt. Aarathi. R. Chattarakki aged about 37 years W/o Ravikumara residing at #E-468, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of 30'x40'. During the interaction with the petitioner it was found that the building was constructed in the year 1994 (Figure-12.183) and presently a total of 12 members are living in these houses.

Petitioner No. 722	
Residential Building	

Figure-12.183: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.60. Petitioner No.726: Smt. Manjula aged about 37 years W/o Shiva Kumar Swamy residing at 438, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 30'x40'. During the interaction with the petitioner it was found that the house has been constructed in the year 2004 (Figure-12.184) and presently four members are living in the house.

Petitioner No. 726	
Residential House	

Figure-12.184: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.61. Petitioner No.727: Smt. Gayithri aged about 37 years W/o Ramamurthi residing at E-364, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single G+1 building has been constructed in an area of 15'x30'. During the interaction with the petitioner it was found that the building was constructed in Narayanappa layout (Figure-12.185) and presently a total of 12 members are living in these houses.

Petitioner No. 727	
Residential House	

Figure-12.185: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.62. Petitioner No.735: Sri. Veerbhadraiah aged about 37 years S/o Shivarudrappa residing at Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single G+1 building has been constructed in an area of 30'x40'. During the interaction with the petitioner it was found that the building has been constructed in the year 2008 (Figure-12.186) in Narayanappa layout and presently a total of four members are living in these houses.

Petitioner No. 735	
Residential Building	

Figure-12.186: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.63. Petitioner No.741: Smt. Sharada aged about 36 years W/o Gangaraju residing at E-482, Siddanahosahalli-1, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that four houses have been constructed in the ground floor in an area of 30'x40'. During the interaction with the petitioner it was found that the house was constructed in Chikkbyraappa layout (Figure-12.187) and presently a total of fourteen members are living in these houses.

Petitioner No. 741	
Residential House	

Figure-12.187: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.64. Petitioner No.743: Smt. Sarojamma aged about 36 years W/o Venkatesh residing at E-938, Hanumanthagowdanapalya, Siddanahosahalli-2, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor in an area of 45'x35'. During the interaction with the petitioner it was found that the house was constructed in the year 1995 (Figure-12.188) and presently a total of eleven members are living in these houses.

Petitioner No. 743	
Residential House	

Figure-12.188: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli -2 Village

12.4.65. Petitioner No.744: Smt. Bhagyamma aged about 36 years W/o Prakash residing at E-449, Siddanahosahalli-2, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2000 (Figure-12.189) and presently three members are living in the house.

Petitioner No. 744	
Residential House	

Figure-12.189: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.66. Petitioner No.745: Sri. Gopalakrishna aged about 36 years S/o Bairappa residing at E-373, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2000 in Narayanappa layout (Figure-12.190) and presently six members are living in these houses.

Petitioner No. 745	
Residential House	

Figure-12.190: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.67. Petitioner No.746: Sri. Shivanna aged about 36 years S/o Krishnappa residing at # E-227, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2000 (Figure-12.191) and presently three members are living in the house.

Petitioner No. 746	
Residential House	

Figure-12.191: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.68. Petitioner No.755: Smt. P. Savitha aged about 36 years S/o Chandrashekara residing at 131, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of 15'x40'. During the interaction with the petitioner it was found that the building has been constructed in the year 2004 (Figure-12.192) and presently four members are living in the house.

Petitioner No. 755	
	
Residential Building	

Figure-12.192: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.69. Petitioner No.757: Sri. Sreenivas aged about 36 years S/o Chikkabairappa residing at 125, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor in an area 15'x45'. During the interaction with the petitioner it was found that the house was constructed in the site allotted by the Mysore Government for the economically weaker section in the year 1978 (Figure-12.193) and presently a total of ten members are living in these houses.

Petitioner No. 757	
Residential House	

Figure-12.193: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.70. Petitioner No. 758: Sri. Ashok aged about 36 years S/o Pundalingappa residing at E-217, Siddanahosahalli-1, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that the construction of new building in an area of 15'x50' was under progress (Figure-12.194).

Petitioner No. 758	
Construction of a new building	

Figure-12.194: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.71. Petitioner No.777: Sri. Maregaud aged about 35 years S/o Hanumanthayya residing at 950, Hanumanthagowdanapalya, Siddanahosahalli-2, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 2010 (Figure-12.195) which has been further renovated in the year 2015 and presently eight members are living in these houses.

Petitioner No. 777	
Residential Building	

Figure-12.195: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.72. Petitioner No.779: Sri. Nagarathna aged about 35 years S/o Honnappa residing at #E 181, Behind Garments Factory, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed and it was found that the building was having four houses. During the interaction with the petitioner it was found that the building was constructed in the year 2009 (Figure-12.196) in Srinivasmurthy layout and presently a total of fourteen members are living in these houses and it was also found that the house was having borewell.

Petitioner No. 779	
Residential Building	

Figure-12.196: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.73. Petitioner No.780: Smt. Ganga Hanumakka aged about 35 years W/o Manjunatha residing at 192, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2003 (Figure-12.197) in Govindappa layout and presently three members are living in the house.

Petitioner No. 780	
Residential House	

Figure-12.197: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.74. Petitioner No.807: Sri. Mohan Kumar aged about 34 years S/o Bairappa residing at Siddanahosahalli-2, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that the site area of 20′x30′ was vacant (Figure-12.198) and while carrying out the ground truth verification the petitioner was not present.

Petitioner No. 807	
Vacant Site	

Figure-12.198: GPS location of the petitioner site (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.75. Petitioner No.815: Smt. V. Vimala aged about 34 years W/o Gopalkrishnaiah residing at 131 Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in Narayanappa layout (Figure-12.199) and presently four members are living in the house.

Petitioner No. 815	
Residential House	

Figure-12.199: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.76. Petitioner No.832: Sri. B.D. Kantharaju aged about 33 years S/o Devegowda residing At # 12/1, Hanumanthagowdanapalya, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 30'x40'. During the interaction with the petitioner it was found that the house has been constructed in the year 2004 (Figure-12.200) and presently three members are living in the house.

Petitioner No. 832	
Residential House	

Figure-12.200: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.77. Petitioner No.833: Sri. N. Narasimhamurthy aged about 33 years S/o D. Narasappa residing at 114, Hanumanthagowdanapalya, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed and it was found that the building was having four houses. During the interaction with the petitioner it was found that the building was constructed in the year 2004 in an area of 30'x40' (Figure-12.201) and presently a total of 12 members are living in these houses.

Petitioner No. 833	
Residential Building	

Figure-12.201: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.78. Petitioner No.848: Sri. P. Suresh Kumar aged about 32 years S/o Puttananjaiah residing at 124, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 2004 and which has been renovated in the year 2015 (Figure-12.202). Presently a total of fourteen members are living in these houses.

Petitioner No. 848	
Residential Building	

Figure-12.202: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.79. Petitioner No.859: Smt. Saubhagya aged about 32 years W/o Ramesh residing at E-79, Siddanahosahalli-1, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed and it was found that the building was having nine houses. During the interaction with the petitioner it was found that the building was constructed in the year 2006 (Figure-12.203) in Vinayakanagara and presently a total of 17 members are living in these houses and it was also found that the house was having borewell.

Petitioner No. 859	
Residential Building	

Figure-12.203: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.80. Petitioner No.861: Smt. Mangala aged about 32 years W/o Timmaraju residing at # Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 30'x40'. During the interaction with the petitioner it was found that the house has been constructed in the year 2005 (Figure-12.204) and presently five members are living in the house.

Petitioner No. 861	
Residential House	

Figure-12.204: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli Village

12.4.81. Petitioner No.869: Sri. Jayarama aged about 31 years S/o Bura Rama residing at E-327, Siddanahosahalli-2, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that the construction of new building was under progress (Figure-12.205).

Petitioner No. 869	
New building under construction	

Figure-12.205: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Siddanahosahalli-2 Village

12.4.82. Unidentified Cases: In the village of Siddanahosahalli out of 109 cases 85 residential houses cases were identified and remaining 24 properties pertaining to the cases that could not be identified are given below:

1. **Petitioner No.53:** Sri. Ramesha aged about 42 years S/o Late Revanna residing at E-985, Hanumanthegowdanapalya, Siddanahosahalli-2, Bangalore North, Bangalore Urban District – 562 123.

2. **Petitioner No.56:** Sri. Rajanna aged about 48 years S/o Honnagangaiah residing at 75, Hanumanthegowdanapalya, Bangalore North, Bangalore Urban District – 562 123.

3. **Petitioner No.137:** Smt. R. Bhagya aged about 29 years W/o B. Shantharaju residing at 99 E, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

4. **Petitioner No.234:** Sri. C. Dayanand aged about 55 years S/o Siddavyrappa residing at 856, Hanumanthegowdanapalya, Bangalore North, Bangalore Urban District – 562 123.

5. **Petitioner No.304:** Sri. Sathish aged about 27 years S/o Dore residing at #80, Hanumanthegowdanapalya, Bangalore North, Bangalore Urban District – 562 123.

6. **Petitioner No.316:** Sri. T. Ramu aged about 51 years S/o Rajanaidu residing at 180, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

7. **Petitioner No.348:** Sri. Gangadharamurthi aged about 50 years S/o Lakkegaud residing at E-375, Siddanahosahalli-2, Bangalore North, Bangalore Urban District – 562 123.

8. **Petitioner No.354:** Sri. Hemojirao aged about 50 years S/o Govinda Rao residing at E-313, Siddanahosahalli-2, Bangalore North, Bangalore Urban District – 562 123.

9. **Petitioner No.404:** Sri. C. Shivanna aged about 48 years S/o Late Chikkalingaiah residing at #26, Hanumanthegowdanapalya, Bangalore North, Bangalore Urban District – 562 123.

10. **Petitioner No.456:** Sri. Manjunath aged about 46 years S/o Chikkabhairappa residing at E-344, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

11. **Petitioner No.470:** Sri. R. G. Chandrashekar aged about 25 years S/o Gangappa residing at #140, E-A, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

12. **Petitioner No.508:** Sri. Ningappa aged about 44 years S/o Chandrappa residing at E75, Siddanahosahalli-2, Bangalore North, Bangalore Urban District – 562 123.

13. **Petitioner No.516:** Sri. Narayanappa aged about 44 years S/o Gangadarappa residing at E-37, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

14. **Petitioner No.551:** Sri. Srinivas aged about 43 years S/o Gangappa residing at 360-E, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

15. **Petitioner No.552:** Sri. L. Suryanarayana aged about 43 years S/o Seetharamaiah residing at 128a, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

16. **Petitioner No.581:** Smt. Mamatha Girish aged about 42 years W/o B.M. Girish residing at #E-500-2, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

17. **Petitioner No.609:** Sri. Avinash aged about 41 years S/o Krishna residing at 98/A1, Navy layout, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

18. **Petitioner No.610:** Sri. Mohd. Iqbal Khan aged about 41 years S/o Haroon Khan residing at #25, 2nd Floor, Sri Lakshmi Nilaya, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

19. **Petitioner No.611:** Smt. Sarw Mangal aged about 41 years W/o Sangameswaryya residing at #E-379, Behind Garments Factory, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

20. **Petitioner No.721:** Sri. Viranna aged about 37 years S/o Late Shivanna residing at E-461, Siddanahosahalli-1, Bangalore North, Bangalore Urban District – 562 123.

21. **Petitioner No.734:** Smt. M. C. Shanthamma aged about 37 years W/o S. N. Srinivas residing at #24(1), Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

22. **Petitioner No.806:** Sri. S. N. Hemalatha aged about 34 years S/o Narayappa residing at 31, Siddanahosahalli-2, Bangalore North, Bangalore Urban District – 562 123.

23. **Petitioner No.835:** Sri. P. Krishnappa aged about 33 years S/o Puttananjayya residing at Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

24. **Petitioner No.837:** Smt. S. C. Manjunath aged about 33 years W/o Late Chandrayya Shetty, residing at E-288, Siddanahosahalli, Bangalore North, Bangalore Urban District – 562 123.

12.5. Dombarahalli Village:

Dombarahalli village is coming under the jurisdiction of Madanayakanahalli Gram Panchayat and as per the 2011 census the Dombarahalli village has an area of 1.03 Sq.Km. with population of 2,640 and 724 households. The Dombarahalli village falls in the Zone-3 and 4 of the Arkavathy river stretch of the TGR catchment area (Figure-12.206).



Figure-12.206: Location of Dombarahalli village in the Zone-3 & 4 (Source – NPA)

In the Village of the Dombarahalli 92 cases are filed (Annexure–12.5) and during the ground verification it was found that in few cases two to three petitions have been filed by the members of one family *i.e.* father

loors and in few cases are being used as commercial shops which are rented out for income generation. Further, it was found that most of the respondent houses have been constructed in the survey No. 2, 8, 15, 16, 24, 27, 28, 31 and few of the houses have been constructed in the Gramathana. It was also found that few of the houses have been constructed in the sites allotted by the Government under the

Ashraya Yojage Scheme, whereas most of the houses have been constructed in the revenue sites and few of the houses have been constructed in the recently developed layouts and also few of the have been constructed in the inherited land. About 99% of the petitioners submitted Electricity bills as substantiation documents during the residential houses field verification.

While interacting with the petitioners it was found that the Gram Panchayat is supplying water through borewells and mini water supply scheme and it was also found that few of the houses were having borewells. Some of the general observation includes sewage discharge into pit, grey water discharge into open drain, solid waste management by Gram Panchayat in few areas, open drain sanitation and accessibility to road. There has been rapid growth of the population (Figure-12.207) and also households (Figure-12.208) in the Dombarahalli village. The main reasons behind this rapid growth are proximity to BBMP area, NH-4 passing (Bengaluru–Tumakuru Road) through the village and also job opportunities. During the ground truth verification, out of 92 cases 76 residential houses could be identified and remaining 16 cases could not be identified (Figure-12.209). Pertaining to the addresses involving unidentified residential houses, the local people and the persons accompanying the ground truth exercise expressed inability to locate these addresses. Further, a written statement (PANCHANAMA) was written in the presence of all the members of the committee i.e. EMPRI staff, two representatives of the petitioners and local people of the village along with their signatures. Panchanama of the ground verification of the residential superstructure is

annexed in the Annexure-12.2. The current status of each identified petitioners houses in the Dombarahalli village are discussed below:



Figure-12.207: Population trend in the Dombarahalli village



Figure-12.208: Households statistics in the Dombarahalli village



Figure-12.209: Field verification status in the Dombarahalli village

12.5.1. Petitioner No.47: Smt. Ramakka aged about 68 years W/o Marappa residing at 41a, Dombarahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District – 562 123.

Petitioner No.799: Sri. Muddahanumaiah aged about 34 years S/o Marappa residing at 41a, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by members of the same family and it was found that duplex house has been constructed in an area of (50'x49'). During the interaction with the petitioner it was found that the house has been constructed in the year 2001 (Figure-12.210) in the inherited land and presently twelve members are living in the house and further it was found that the house was having borewell.

Petitioner No. 47 and 799	
Duplex House	

Figure-12.210: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.2. Petitioner No.49: Smt. Gandabraramma aged about 68 years W/o Narasimhaiah residing at Dombarahalli Post, Bangalore North Taluk – 562 123.

Petitioner No.547: Sri. Siddaraju aged about 43 years Sidnarasimhaiah residing at 64, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Petitioner No.800: Sri. Arasappa aged about 34 years S/o Narasimhaiah residing at 64, Dombarahalli, Bangalore North, Bangalore- 562123

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that three petitions have been filed by the members of the same family and it was found that four houses have been constructed in the ground floor in an area of (50'x30'). During the interaction with the petitioner it was found that the house was constructed in the year 1994 (Figure-12.211) and presently, four families are living in these houses.

Petitioner No. 49, 547 and 800	
Residential House	

Figure-12.211: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.3. Petitioner No.63: Smt. C. G. Sujatha aged about 29 years D/o Puttaswamaiah residing at 79, Dombarahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+2 building along with shops have been constructed in an area of (30'x30'). During the interaction with the Petitioner it was found that the building was constructed in the year 2010 (Figure-12.212) and presently a total of ten members are living in these houses.

Petitioner No. 63	
Residential Building along with the shops	

Figure-12.212: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.4. Petitioner No. 78: Sri. Shankarappa aged about 65 years S/o Channappa residing at #15, Lakshmipura, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building has been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 2008 (Figure-12.213) in the Vidyanagar layout and presently, nine members are living in these houses.

Petitioner No. 78	
Residential Building	

Figure-12.213: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.5. Petitioner No.79: Smt. Lakshmidevi aged about 65 years W/o Siddappa residing at 31a, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor in an area of (15'x30'). During the interaction with the petitioner it was found that the house has been constructed in the year 2005 (Figure-12.214) and presently, a total of seven members are living in these houses.

Petitioner No. 79	
Residential House	

Figure-12.214: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.6. Petitioner No.124: Sri. Ramaiah aged about 61 years S/o Mudirappa residing at 56a, Dombarahalli, Lakshmipura, Bangalore North – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that seven houses along with one shop have been constructed in the ground floor in an area of (60'x50'). During the interaction with the petitioner it was found that the house was constructed in the year 1992 (Figure-12.215) and presently, a total of sixteen members are living in these houses.

Petitioner No. 124	
Residential House along with a shop	

Figure-12.215: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.7. Petitioner No.146: Sri. Chinnagiriyappa aged about 60 years S/o Venkatachaiah residing at 6, Dombarahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building, three houses in the ground floor and three shops have been constructed in an area of (80'x50') and it was found that the building was having five houses. During the interaction with the petitioner it was found that the old house was constructed in the year 1970 which has been renovated in the year 2001 (Figure-12.216) and presently, a total of 21 members are living in these houses and further it was found that the house was having borewell.

Petitioner No. 146	
Residential Building along with the shops	

Figure-12.216: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.8. Petitioner No.149: Smt. G. Geetha aged about 59 years W/o K. Ganesha residing at 81, Dombarahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of (30'x40') and it was found the house has been constructed in the Vidyanagar layout (Figure-12.217). Further, while carrying out the ground truth verification, the petitioner house was locked and as per the information collected from the neighbours presently six members are living in the house.

Petitioner No. 149	
Residential House	

Figure-12.217: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.9. Petitioner No.150: Smt. Lakshmi Narasamma aged about 59 years W/o Chikka Hanumaiah residing at Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor (Figure-12.218). Further, while carrying out the ground truth verification, the petitioner house was locked and as per the information collected from the neighbours presently six members are living in these houses.

Petitioner No. 150	
Residential House	

Figure-12.218: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.10. Petitioner No.178: Smt. Hiramma aged about 58 years W/o Kemparangaiah residing at 38, Dombarahalli, Lakshmipura-2, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (25'x35') and it was found that the building was having three houses. During the interaction with the petitioner it was found that the building was constructed in the year 2009 (Figure-12.219) and presently, fourteen members are living in these houses.

Petitioner No. 178	
Residential Building	

Figure-12.219: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.11. Petitioner No.191: Sri. Mallappa Kalakappa aged about 57 years S/o Kalakappa residing at Dombarahalli, Lakshmipura Post, Dasanapura Hobli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building has been constructed in the Byraweshwara layout and it was found that the building was having three houses. During the interaction with the petitioner it was found that the building has been constructed in the year 2010 (Figure-12.220) and presently, a total of six members are living in these houses.

Petitioner No. 191	
Residential Building	

Figure-12.220: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.12. Petitioner No.205: Sri. K.R. Chandrashekhara aged about 56 years S/o Ramanathaiah residing at No.3, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in the Byraweshwara layout. During the interaction with the petitioner it was found that the house was constructed in the year 2009 (Figure-12.221) and presently, five members are living in the house.

Petitioner No. 205	
Residential House	

Figure-12.221: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.13. Petitioner No.250: Smt. Nagamma aged about 54 years W/o Kambanna residing at Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in an area of (30'x15'). During the interaction with the petitioner it was found that the house was constructed in the year 1995 (Figure-12.222) and presently, three members are living in the house.

Petitioner No. 250	
Residential House	

Figure-12.222: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.14. Petitioner No.257: Sri. Gangahanumaiah aged about 54 years S/o Govindaiah residing at 11A, Dombarahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that the first floor was having one room. During the interaction with the petitioner it was found that the building has been constructed in the year 2003 (Figure-12.223) in an area of (30'x40') and presently, five members are living in the house and also it was found that the house was having borewell.

Petitioner No. 257	
Residential Building	

Figure-12.223: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.15. Petitioner No.269: Sri. K.R. Chandrashekhar aged about 53 years S/o Rangappa residing at Dombarahalli, Lakshmipura Post, Bangalore North Taluk – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the Byraweshwara layout in an area of (30'x40'). During the interaction with the petitioner it was found that the house was constructed in the year 2007 (Figure-12.224) and presently, ten members are living in the house.

Petitioner No. 269	
Residential House	

Figure-12.224: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.16. Petitioner No.288: Sri. D.L. Chandrashekhar aged about 27 years S/o R. Lakshmidevammam residing at 228, Dombarahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. While carrying out the ground truth verification the petitioner house was locked and as per the information collected from the neighbours the house was constructed in the year 1964 (Figure-12.225) and presently the house is vacant.

Petitioner No. 288	
House is Vacant	

Figure-12.225: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.17. Petitioner No.289: Sri. Anamcharanbehara aged about 52 years S/o Ramchandrabehara residing at Dombarahalli, Lakshmipura Post, Dasanapura Hobli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in the Byraweshwara layout. During the interaction with the petitioner it was found that the house was constructed in the year 2011 (Figure-12.226) and presently, four members are living in the house.

Petitioner No. 289	
Residential House	

Figure-12.226: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.18. Petitioner No.326: Sri. Ramakrishnappa aged about 51 years S/o Sanjeevappa residing at 64, Dombarahalli, Lakshmipura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill.

Remarks: During the ground truth verification it was found that fifteen houses have been constructed in the ground floor in an area of 10 Guntas. During the interaction with the petitioner it was found the house was constructed in the year 1975 (Figure-12.227) in the inherited land. Further it was found that out of fifteen houses eleven houses are vacant and a total of twelve members are living in these houses.

Petitioner No. 326	
Residential House	

Figure-12.227: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.19. Petitioner No.346: Smt. Thimakka aged about 50 years W/o Revanna residing at 17B, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found the houses was constructed in the year 1995 (Figure-12.228) in an area of (15'x50') and presently ten members are living in the house.

Petitioner No. 346	
Residential House	

Figure-12.228: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.20. Petitioner No.347: Smt. D. Savithramma aged about 50 years W/o K. B. Nagaraju residing at 218, Dombarahalli, Lakshmipura-2, Bangalore NorthBangalore Urban District – 562 123.

Documents Obtained: Electricity bill.

Remarks: During the ground truth verification it was found that G+3 building has been constructed in an area of (30'x40') and it was found that second and third floor were vacant. During the interaction with the petitioner it was found that the house has ben constructed in the year 2010 (Figure-12.229) and presently, a total of eight members are living in these houses.

Petitioner No. 347	
Residential Building	

Figure-12.229: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.21. Petitioner No.349: Smt. Puttamma aged about 50 years W/o Hanumantharayappa residing at #43, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building has been constructed and further it was found that the building was having seven houses. During the interaction with the petitioner it was found that the house was constructed in the year 2008 (Figure-12.230) in the Basaweshwaranagara layout and presently, a total of twenty members are living in these houses.

Petitioner No. 349	
Residential Building	

Figure-12.230: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.22. Petitioner No.387: Sri. Narayana aged about 49 years S/o Siddappa residing at 24B, Dombarahalli, Lakshmipura-2, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that eight houses have been constructed in the ground floor. During the interaction with the petitioner it was found the house was constructed in the year 1996 (Figure-12.231) in an area of (30'x50') and presently twenty members are living in these houses.

Petitioner No. 387	
Residential House	

Figure-12.231: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.23. Petitioner No.388: Smt. Sharadamma aged about 49 years W/o Narasimhaiah residing at Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that nine houses have been constructed in the ground floor. During the interaction with the petitioner it was found the houses were constructed in the year 1995 (Figure-12.232) in an area (30'x50') and presently a total of twenty members are living in these houses.

Petitioner No. 388	
Residential House	

Figure-12.232: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.24. Petitioner No.389: Smt. Gangamma aged about 49 years W/o Revanna residing at Dombarahalli, Bangalore North Taluk, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found the houses was constructed in the year 1995 (Figure-12.233) in an area of (30'x50') and presently a total of twelve members are living in these houses.

Petitioner No. 389	
Residential House	

Figure-12.233: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.25. Petitioner No.403: Sri. Ramachandra S Pujari aged about 48 years, S/o Shankarappa residing at Dombarahalli, Lakshmipura, Bangalore North, Bangalore Urban District – 592 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor in the Byraveshwara layout. During the interaction with the petitioner it was found that the houses was constructed in the year 2010 (Figure-12.234) and presently, six members are living in these houses.

Petitioner No. 403	
Residential House	

Figure-12.234: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.26. Petitioner No.414: Sri. H. Manjunath aged about 25 years S/o Gangatharappa residing at Dombarahalli, Lakshmipura-2, Dasanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of (30'x40'). During the interaction with the petitioner it was found that the house was constructed in the year 2013 (Figure-12.235) and presently, four members are living in the house.

Petitioner No. 414	
Residential House	

Figure-12.235: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.27. Petitioner No.428: Smt. Lalitha aged about 47 years W/o Voovaiahmoolya residing at Dombarahalli, Lakshmipura-2, Dasanapura Hobli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that first floor was having one room. During the interaction with the petitioner it was found the house was constructed in the year 2009 (Figure-12.236) and presently two members are living in the house.

Petitioner No. 428	
Residential Building	

Figure-12.236: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.28. Petitioner No.430: Smt. H. Rajamma aged about 47 years W/o A. R. Krishna residing at 27F, Dombarahalli, Lakshmipura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+2 building has been constructed and further it was found that building was having ten houses. During the interaction with the petitioner it was found the building was constructed in the year 2007 (Figure-12.237) and presently a total of fifteen members are living in these houses and it was also found that the house was having borewell.

Petitioner No. 430	
Residential Building	

Figure-12.237: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.29. Petitioner No.482: Smt. Padmamma aged about 45 years W/o Shivagangadharaiah residing at # 41, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (60'x20'). During the interaction with the petitioner it was found the building was constructed in the year 2004 (Figure-12.238) and presently a total of six members are living in the house.

Petitioner No. 482	
Residential Building	

Figure-12.238: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.30. Petitioner No.494: Sri. Narayanappa aged about 45 years S/o Hanumaiah Dombarahalli, Lakshmipura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that four houses have been constructed in the ground floor in an area of (15'x30'). While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours the house was constructed in the year 1990 (Figure-12.239) and presently a total of sixteen members are living in these houses.

Petitioner No. 494	
Residential House	

Figure-12.239: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.31. Petitioner No.495: Sri. Mutharayappa aged about 45 years S/o Rangamuttaiah residing at Dombarahalli, Near Benaka School, Lakshmipura Road, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. While carrying out the ground truth verification the petitioner house was locked and as per the information collected from the neighbours the house has been constructed in the year 2002 (Figure-12.240) and presently two members are living in the house.

Petitioner No. 495	
Residential House	

Figure-12.240: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.32. Petitioner No.504: Sri. Malali Davalasaba Pinchar aged about 44 years residing at Dombarahalli, Lakshmipura Post, Dasanapura Hobli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours the house was constructed in the year 2006 (Figure-12.241) and presently five members are living in the house.

Petitioner No. 504	
Residential House	

Figure-12.241: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.33. Petitioner No.505: Smt. Lakshmamma aged about 44 years W/o Arasappa residing At Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two G+1 buildings have been constructed and it was found that the building was having eleven houses (Figure-12.242). During the interaction with the petitioner it was found that a total of 20 members living in these house.

Petitioner No. 505	
Residential Building	

Figure-12.242: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.34. Petitioner No.507: Sri. Shivakumar aged about 44 years S/o Muddavirappa residing at No.E-267, Dombarahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building along with three shops have been constructed in the Rajeshwari layout and further it was found that first floor was having two rooms. During the interaction with the petitioner it was found that the house was constructed in the year 2005 (Figure-12.243) and presently, seven members are living in these houses.

Petitioner No. 507	
Residential Building along with shops	

Figure-12.243: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.35. Petitioner No.512: Smt. Kempamani aged about 44 years W/o K.V. Varadaraju residing at Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that five houses have been constructed in the ground floor. While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours the house was constructed in the year 1985 (Figure-12.244) and presently a total of 15 members are living in these houses.

Petitioner No. 512	
Residential House	

Figure-12.244: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.36. Petitioner No.520: Smt. N.S. Nayana aged about 44 years W/o N.B. Sanna Gowder residing at #32, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2008 (Figure-12.245) in an area of (30'x40') and presently four members living in the house.

Petitioner No. 520	
Residential House	

Figure-12.245: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.37. Petitioner No.542: Sri. Mariyappa aged about 43 years S/o Devanna residing at Dombarahalli, Lakshmipura-2, Dasanapura, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in an area of 30'x40' in the Vidyanagar layout. During the interaction with the petitioner it was found that the house was constructed in the year 2010 (Figure-12.246) and presently, four members are living in the house.

Petitioner No. 542	
Residential House	

Figure-12.246: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.38. Petitioner No.543: Sri. Omprakash aged about 43 years S/o K.B. Bharath Singh residing at #31, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of 30'x40' in the Vidyanagar layout (Figure-12.247) and it was found that the building was having two houses. During the interaction with the petitioner it was found that presently, four members are living in the house.

Petitioner No. 543	
Residential Building	

Figure-12.247: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.39. Petitioner No.544: Smt. Munirathnamma aged about 43 years S/o Narayanappa residing at # 18a, Dombarahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1995 (Figure-12.248) in an area of (15'x50') and presently a total of ten members living in these houses.

Petitioner No. 544	
Residential House	

Figure-12.248: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.40. Petitioner No.546: Smt. Jayamma aged about 43 years W/o S. Gopal residing at # 68, Dombarahalli (Left Side), Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 40'x40'. During the interaction with the petitioner it was found that the house was constructed in the year 2002 (Figure-12.249) and presently, eight members are living in the house.

Petitioner No. 546	
Residential House	

Figure-12.249: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.41. Petitioner No.*555*: Sri. Mallikarjun aged about 43 years residing at Jenukallu Nilaya, Byregowda Layout, Dombarahalli, Lakshmipura Post, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill.

Remarks: During the ground truth verification it was found that G+1 building has been constructed in the Byraveshwaranagar and it was found that the building was having three houses. During the interaction with the petitioner it was found the building was constructed in the year 2007 (Figure-12.250) and presently seven members are living in the house.

Petitioner No. *555*	
Residential Building	

Figure-12.250: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.42. Petitioner No.576: Sri. V. Manjunatha aged about 21 years S/o Viramma residing at #02, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2003-04 (Figure-12.251) and presently, two members are living in the house.

Petitioner No. 576	
Residential House	

Figure-12.251: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.43. Petitioner No.603: Sri. R.H. Jagadish aged about 41 years S/o Doddahuchaiah residing at # 13/6, Dombarahalli (Left Side), Bangalore North, Bangalore Urban District -562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 30'x40' in Vidyanagar layout (Figure-12.252). While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours presently four members are living in the house.

Petitioner No. 603	
Residential House	

Figure-12.252: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.44. Petitioner No.604: Sri. Nagaraju aged about 41 years S/o Nanjundappa residing at #25b, Dombarahalli, Lakshmipura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor in an area of 30'x40' in Vidyanagar layout (Figure-12.253). While carrying out the ground truth verification the petitioner house was locked and as per the information collected from the neighbours, presently a total of ten members are living in these houses.

Petitioner No. 604	
Residential House	

Figure-12.253: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.45. Petitioner No.605: Sri. Rajesh aged about 41 years S/o K. B. Nharath Singh residing at Dombarahalli, Lakshmipura-2, Dasanapura Hobli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+2 building has been constructed in an area of 30'x40'. Further it was found that the building was having three houses and presently two houses were vacant. During the interaction with the petitioner it was found the house was constructed in the year 2009 (Figure-12.254) and presently four members are living in the house.

Petitioner No. 605	
Residential Building	

Figure-12.254: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.46. Petitioner No.607: Sri. Shivanna aged about 41 years S/o Doddarudrayya residing at No.E427, Dombarahalli, Lakshmipura-2, Bangalore North Taluk, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours the house was constructed in the year 2005 (Figure-12.255) and presently four members are living in the house.

Petitioner No. 607	
Residential House	

Figure-12.255: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.47. Petitioner No.643: Sri. Devaraju aged about 40 years S/o Deveeramma residing at 14B, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house along with a shop has been constructed in the ground floor in the Rajeshwarinagar Layout. During the interaction with the petitioner it was found that the old house was constructed in the year 2000 (Figure-12.256) which has been renovated in the year 2015 and presently five members are living in the house.

Petitioner No. 643	
Residential House	

Figure-12.256: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.48. Petitioner No.644: Smt. Lakshmamma aged about 40 years W/o Ranganatha residing at 54A, Dombarahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building along with shop has been constructed and further it was found that the first floor was having single room. During the interaction with the petitioner it was found the house was constructed in the year 2004 (Figure-12.257) in the Rajeshwarinagar layout and presently three members are living in the house.

Petitioner No. 644	
Residential building along with the shop	

Figure-12.257: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.49. Petitioner No.646: Sri. E. Gurumurthy aged about 40 years S/o Eranna residing at Dombarahalli, Lakshmipura Post, Dasanapura Hobli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building along with shop has been constructed and further it was found that first floor was having single room. While carrying out the ground truth verification, the petitioners house was locked and as per the information collected from the neighbours the house was constructed in the year 2010 (Figure-12.258) in the Byraveshwara layout.

Petitioner No. 646	
Residential house along with the shop	



Figure-12.258: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.50. Petitioner No.654: Sri. Nagaraju aged about 40 years S/o Chowdappa residing at 5AE, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that twelve houses have been constructed in an area of (140'x20'). During the interaction with the petitioner it was found that house was constructed in the year 1990 (Figure-12.259) and presently a total of 25 members are living in these houses.

Petitioner No. 654	
Residential House	

Figure-12.259: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.51. Petitioner No.669: Smt. B.S. Meenashi aged about 39 years W/o Pandurangaiah residing at Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. While carrying out the ground truth verification the petitioner house was locked and as per the information collected from the neighbours the house has been constructed in the year 2014 (Figure-12.260) in an area of (30'x40') and presently four members are living in the house.

Petitioner No. 669	
Residential House	

Figure-12.260: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.52. Petitioner No. 684: Smt. Rangamman aged about 39 years W/o Ramakrishnan residing at Dombarahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District -562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2009 (Figure-12.261) and presently, four members are living in the house.

Petitioner No. 684	
Residential House	

Figure-12.261: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.53. Petitioner No.694: Sri. K. Hanumantharaju aged about 30 years S/o P. Krishnappa residing at Dombarahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+2 building along with two shops have been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 1995 (Figure-12.262) and presently, six members are living in the houses.

Petitioner No. 694	
Residential House	

Figure-12.262: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.54. Petitioner No.698: Smt. N. Sharada aged about 38 years W/o V. Venkatesh residing at Dombarahalli, Dasanapura Hobli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. While carrying out the ground truth verification, the petitioners house was locked and as per the information collected from the neighbours the house has been constructed in the year 2005 (Figure-12.263).

Petitioner No. 698	
Residential House	

Figure-12.263: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.55. Petitioner No.711: Sri. Ramachandra aged about 38 years residing at Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building has been constructed and cattle shed was found adjacent to the house. During the interaction with the petitioner it was found that the building was constructed in the year 2012 (Figure-12.264) and presently three members are living in the house.

Petitioner No. 711	
Residential Building	

Figure-12.264: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.56. Petitioner No.716: Sri. J.A. Kamaraju aged about 37 years S/o J.L. Anjappa residing at # 107, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building has been constructed and further it was found that building was having three houses. During the interaction with the petitioner it was found that the building was constructed in the year 2012 (Figure-12.265) in the inherited land and presently a total of 12 members are living in these houses.

Petitioner No. 716	
Residential Building	

Figure-12.265: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.57. Petitioner No.719: Sri. Shivanna aged about 37 years S/o Veeranna residing at No.20, Byregowda Layout, Dombarahalli, Lakshmipura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (20'x30'). During the interaction with the petitioner it was found that the house was constructed in the year 2007 (Figure-12.266) and presently two families with a total of thirteen members are living in these houses.

Petitioner No. 719	
Residential Building	

Figure-12.266: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.58. Petitioner No.730: Sri. Manjula about 37 years S/o Shankarappa at Dombarahalli (Left Side), Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2002 (Figure-12.267) and presently five members are living in the house.

Petitioner No. 730	
Residential House	

Figure-12.267: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.59. Petitioner No.759: Smt. Sharadamma aged about 36 years W/o Shivanna residing at Dombarahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house along with shop has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2002 in Vidyanagar layout (Figure-12.268) and presently five members are living in the house.

Petitioner No. 759	
Residential House along with a shop	

Figure-12.268: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.60. Petitioner No.760: Sri. Ashoka aged about 36 years S/o Nanjappa residing at 63E, Dombarahalli, Lakshmipura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2012 in Vidyanagar layout (Figure-12.269) and presently four members are living in the house.

Petitioner No. 760	
Residential House	

Figure-12.269: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.61. Petitioner No.770: Smt. V. Yashoda aged about 35 years W/o K.B. Shankar residing at #118, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor in an area of 30'x40'. During the interaction with the petitioner it was found that the houses were constructed in the Basaweshwaranagar layout (Figure-12.270) and presently eight members are living in these houses.

Petitioner No. 770	
Residential House	

Figure-12.270: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.62. Petitioner No.773: Sri. C. Gangadhard aged about 35 years S/o Chowdaiah residing at 5F, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that duplex house has been constructed in the inherited property. During the interaction with the petitioner it was found that the old house was demolished (1935) and new house has been constructed in the year 2007 (Figure-12.271) in an area of (65'x60'). Further it was found that presently eight members are living in the house and also house was having borewell.

Petitioner No. 773	
Duplex House	

Figure-12.271: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.63. Petitioner No.775: Smt. Bhagyamma aged about 35 years W/o Krishnappa residing at Dombarahalli, Lakshmipura Post, Dasanapura Hobli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building along with shop has been constructed and further it was found that the building was having four houses. During the interaction with the petitioner it was found that the building was constructed in the year 2010 (Figure-12.272) and presently thirteen members are living in these houses.

Petitioner No. 775	
Residential Building along with a shop	

Figure-12.272: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.64. Petitioner No.801: Sri. Nagaraju aged about 34 years S/o Chinnappa residing at Dombarahalli (Left Side), Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house along with one shop has been constructed in the ground floor in Tippaiah layout. During the interaction with the petitioner it was found that the house was constructed in the year 2012 (Figure-12.273) and presently five members are living in the house.

Petitioner No. 801	
Residential House along with a shop	



Figure-12.273: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.65. Petitioner No.802: Smt. N.S. Suma aged about 34 years W/o Shiva Kumar residing at Dombarahalli, Lakshmipura Post, Dasanapura Hobli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 30′x40′. During the interaction with the petitioner it was found that the house was constructed in the year 2011 (Figure-12.274) and presently, five members are living in the house.

Petitioner No. 802	
Residential House	

Figure-12.274: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.66. Petitioner No.804: Smt. Githa aged about 34 years W/o Lokesh residing at Dombarahalli, Lakshmipura post, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building has been constructed and further it was found that the building was having nine houses. During the interaction with the petitioner it was found that the house was constructed in the year 2010 (Figure-12.275) and presently fifteen members are living in these houses.

Petitioner No. 804	
Residential Building	

Figure-12.275: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.67. Petitioner No.814: Smt. Radha aged about 34 years W/o Ramakrishna residing at 24A, Dombarahalli, Lakshmipura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (50'x20') and further it was found that the building was having four houses. During the interaction with the petitioner it was found that the building was constructed in the year 2006 (Figure-12.276) and presently, six members are living in these houses.

Petitioner No. 814	
Residential Building	

Figure-12.276: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.68. Petitioner No.827: Sri. M. R. Deniesh aged about 33 years S/o Ramygowda residing at #152, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses along with two shops have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2005 (Figure-12.277) in an area of 30'x40' and presently, eight members are living in the houses.

Petitioner No. 827	
Residential House along with the shops	

Figure-12.277: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.69. Petitioner No.828: Sri. R. D. Hanumantharaju aged about 33 years S/o Ramanjinappa residing at #3/2A, Near Temple, Dombarahalli, Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building along with shops has been constructed and further it was found that the building was having six houses. During the interaction with the petitioner it was found that the house was constructed in the year 1999 (Figure-12.278) in an area of 20'x40' and presently, a total of nine members are living in these houses.

Petitioner No. 828	
Residential Building along with the shops	

Figure-12.278: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.70. Petitioner No.830: Sri. H. Nataraja aged about 33 years S/o Hanumantharayappa residing at 35D, Dombarahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 15'x40'. During the interaction with the petitioner it was found that the house has been constructed in the year 2000 (Figure-12.279) and presently, six members are living in the house.

Petitioner No. 830	
Residential House	

Figure-12.279: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.71. Petitioner No.847: Smt. V. S. Prema aged about 32 years W/o V. H. Venkatesh residing at No.16, Ganapati Layout, Dombarahalli, Lakshmipura, Bangalore North, Bangalore Urban District -562 123.

Remarks: During the ground truth verification it was found that two buildings have been constructed in the ground floor (Figure-12.280) and further it was found that among the two buildings one of the building was having three houses. During the interaction with the petitioner it was found that presently, a total of 12 members are living in these houses.

Petitioner No. 847	
Residential Houses	

Figure-12.280: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.72. Petitioner No.855: Sri. Prakasha aged about 32 years S/o Ramayya residing at Dombarahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found the house was constructed in the year 2005 in the Vidyanagar layout (Figure-12.281) and presently a total of eight members are living in the houses.

Petitioner No. 855	
Residential House	

Figure-12.281: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.73. Petitioner No.868: Sri. R. Shanmugaraj aged about 31 years residing at #9, Vasantha Nilaya, Near Benaka English School, Dombarahalli, Lakshmipura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (30'x40'). During the interaction with the petitioner it was found that the building was constructed in the year 2008 (Figure-12.282) and presently, eight members are living in the house and it was also found that the house was having borewell.

Petitioner No. 868	
Residential Building	

Figure-12.282: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Dombarahalli Village

12.5.74. Unidentified Cases: In the Dombarahalli village, out of 92 cases 76 residential houses cases were identified and remaining 16 properties pertaining to the cases that could not be identified are given below:

1. **Petitioner No.48:** Smt. C. Rukmini aged about 68 years W/o R. Srinivasalu residing at # 259, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.
2. **Petitioner No.248:** Smt. Ganganarasamma aged about 54 years W/o K. Veeraiah residing at Dombarahalli, Lakshmipura Post, Bangalore North, Dasanapura Hobli, Bangalore North– 562 123.
3. **Petitioner No.297:** Smt. Sharadamma aged about 52 years W/o C. Nagaraju residing at Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.
4. **Petitioner No.478:** Sri. D. A. Manjunatha aged about 24 years S/o Arasappa residing at 173, Dombarahalli, Bangalore Urban District – 562 123.
5. **Petitioner No.479:** Sri. Hanumanthappa aged about 45 years S/o Chikkahanumamma residing at 100, 2nd Cross, Dombarahalli, Lakshmipura, Bangalore North, Bangalore Urban District–562123.
6. **Petitioner No.483:** Sri. K. J. Rajanna aged about 45 years S/o Jayanna residing at No.21, Dombarahalli, Lakshmipura Post, Dasanapura Hobli, Bangalore North, Bangalore Urbsan District - 562 123.
7. **Petitioner No.484:** Sri. H. Kishan Singh aged about 45 years S/o L. Hanuman Singh residing at Dombarahalli (Left Side), Bangalore North, Bangalore Urban District–562123.
8. **Petitioner No.566:** Sri. S. Kusuma aged about 23 years D/o Umapathi residing at Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.
9. **Petitioner No.638:** Sri. Shashikala about 20 years S/o K.C. Prakash at Dombarahalli, Dasanapura Hobli, Bangalore North, Bangalore Urban District – 562 123.
10. **Petitioner No.718:** Sri. V. Umaesh aged about 37 years S/o Virahaiah residing at #59, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.
11. **Petitioner No.729:** Sri. T. D. Madhusudhan aged about 37 years S/o Dasappa residing at Dombarahalli, Lakshmipura, Bangalore North, Bangalore Urban District – 562 123.
12. **Petitioner No.772:** Smt. Renuka aged about 35 years W/o Nagaraja residing at Lakshmipura, Daranapura Hobli, Bangalore North, Bangalore Urban District – 562 123.
13. **Petitioner No.781:** Sri. C.S. Shivakumar aged about 35 years S/o Srikantappa residing at #78, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.
14. **Petitioner No.829:** Sri. R.S. Anandha aged about 33 years S/o R. Sidhappa residing at No.164, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.
15. **Petitioner No.845:** Smt. Shanthamma W/o Govindagowda residing at Dombarahalli, Lakshmipura Post, Bangalore North, Bangalore Urban District– 562 123.
16. **Petitioner No.854:** Sri. Oivin Mandona aged about 32 years S/o Thiouy Mandons residing at #25/1, Dombarahalli, Bangalore North, Bangalore Urban District – 562 123.

12.6. Tarabanahalli Village:

Tarabanahalli is coming under the jurisdiction of Hurlichikkanhalli Gram Panchayat and as per the 2011 census the village has an area of 1.78 Sq.Km. with population of 2,161 and 582 households. The Tarabanahalli village falls in the Zone-3 of the Arkavathi river stretch of the TGR catchment area (Figure-12.283).

In the Tarabanahalli village, 75 cases have been filed (Annexure-12.6) and during the ground verification it was found that in few of the cases two to five petitions have been filed by the members of the same family *i.e.* father and son or husband and wife etc. The ground truth verification revealed that few of the residential houses have been constructed in 80's and 90's and it was found that after 2000, many houses have come-up. At present many houses are renovated adding 1-2 floors and in few cases houses are being used as commercial shops which are rented out for income generation. Further, it was found that few of the houses have been constructed in Gramathana. Most of the houses have been constructed in the survey No. 3, 47, 56, 58, 59 and 71, and in the inherited land. Some of the houses have been constructed in the revenue sites and few of the houses was constructed in the sites allotted by the Government to the socially and economically weaker sections (Janatha colony). Few of the houses have been constructed in the developing layouts. 99% of the petitioners submitted electricity bills as a substantiation document during the residential houses field verification.



Figure-12.283: Location of Tarabanahalli village in Zone–3 of Arkavathi River Course (Source – NPA)

While interacting with the petitioners it was found that the Gram Panchayat is supplying water through borewells and mini water supply and it was also found that few houses were having borewells. Some of the general observations include sewage discharge into pits, grey water discharge into open drains, improper management of solid waste, open drain sanitation and accessibility to road. There has been slight growth of the population (Figure-12.284), households (Figure-12.285) and also in the developments in the Tarabanahalli village.

During the ground truth verification, out of 75 cases 55 residential houses cases could be identified and remaining 20 cases could not be identified (Figure-12.286). Pertaining to the addresses involving unidentified residential houses, the local people and the persons accompanying the ground truth exercise expressed inability to locate these addresses. Further, a written statement (PANCHANAMA) was written in the presence of all the members of the committee i.e. EMPRI staff, two representatives of the petitioners and local people of the village along with their signatures. Panchanama of the ground verification of the residential

superstructure is annexed in the Annexure-12.2. The current status of each identified petitioners houses in the Tarabanahalli village are discussed below;



Figure-12.284: Population trend in the Tarabanahalli village



Figure-12.285: Households statistics in the Tarabanahalli village



Figure-12.286: Field verification status

12.6.1. Petitioner No.14: Smt. Ashwathamma aged about 76 years W/o Thimmaiah residing at # 14, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Petitioner No.386: Sri. Ramaswamy aged about 49 years S/o Thimmaiah residing at 115, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed from the same family and further it was found that G+1 building along with the six shops have been constructed in an area of 100'x 100'. During the interaction with the petitioner it was found that the old house was constructed in the year 1995 (Figure-12.287) which has been renovated in the year 2005 and presently a total of fourteen members are living in these houses.

Petitioner No. 14 and 386	
Residential Building along with the shops	

Figure-12.287: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.2. Petitioner No.23: Sri C. Premavathi aged about 72 years W/o Late. B.M. Nanjappa, residing at #13, Anjandari Layout, Tarabanahalli, Bangalore North – 560 090.

Petitioner No.619: Sri.C. R. Harshavaradana aged about 20 years S/o C.M. Renikavijaya residing at #13, Anjandari Layout, Tarabanahalli, Bangalore North – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that single house has been constructed in the ground floor (Figure-12.288). During the interaction with the petitioner it was found that presently two members are living in the house.

Petitioner No. 23 and 619	
Residential House	

Figure-12.288: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.3. Petitioner No.29: Sri. Hanumayya aged about 71 years S/o Munnenkatappa residing at 338, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth survey it was found that two houses have been constructed in the ground floor. Further it was found that the petitioner has rented out the house and as per the information given by the tenants the house was constructed in the year 2009 (Figure-12.289) in the inherited land and presently five members are living in these houses.

Petitioner No. 29	
Residential House	

Figure-12.289: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.4. Petitioner No.34: Sri. Govindappa aged about 70 years S/o Late Nanjappa residing at # 58, Siledepura Road, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+3 building has been constructed and further it was found that the building was having seven houses. During the interaction with the petitioner it was found that the building has been constructed in the year 2007 (Figure-12.290) in an area of (30'x40') and presently twenty members are living in these houses.

Petitioner No. 34	
Residential Building	

Figure-12.290: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.5. Petitioner No.42: Sri. Honnasiddappa aged about 69 years S/o Mallaiah residing at 19, Tarabanahalli, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that single house along with two shops have been constructed in the ground floor. While carrying out the ground verification the petitioners house was locked and as per the information collected from the neighbours the house has been constructed in the year 2000 (Figure-12.291) and presently two members are living in the house.

Petitioner No. 42	
Residential House along with shops	

Figure-12.291: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.6. Petitioner No.51: Sri. Bailappa aged about 68 years S/o Hanumanthappa residing at House No.201, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2000 (Figure-12.292) in an area of (30'x40') and presently six members are living in the house.

Petitioner No. 51	
Residential House	

Figure-12.292: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.7. Petitioner No.70: Sri. Shivajirao aged about 66 years S/o Narayanarao residing at 6, Tarabanahalli, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in the inherited land. During the interaction with the petitioner it was found that the old house that was constructed in the year 1965 (Figure-12.293), which has been renovated in the year 2005 and presently three members are living in the house.

Petitioner No. 70	
Residential Building	

Figure-12.293: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.8. Petitioner No.88: Smt. Lakchmibayi aged about 29 years W/o K. Vishwanath residing at 5, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of (30'x20'). During the interaction with the petitioner it was found that the old house was constructed in the year 1995 (Figure-12.294) which has been renovated in the year 2013 and presently a total of five members are living in these houses.

Petitioner No. 88	
Residential House	

Figure-12.294: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.9. Petitioner No.114: Smt. Jayamma aged about 62 years W/o Honnappa residing at 3, Tarabanahalli, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Petitioner No.599: Sri. Rajashekar aged about 41 years S/o Honappa residing at 3, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Petitioner No.723: Smt. Chandrakala aged about 37 years W/o Rajashekhar residing at 3, Tarabanahalli, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that three petitions have been filed by the members of the same family and further it was found that single house has been constructed in the ground floor in an area of (30'x40'). During the interaction with the petitioner it was found that the house has been constructed in the year 2008 (Figure-12.295) and presently five members are living in the house.

Petitioner No. 114, 599 and 723	
Residential House	

Figure-12.295: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.10. Petitioner No.141: Sri. Shivakumar aged about 60 years S/o Nanjappa residing at 71, Tarabanahalli, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Petitioner No.413: Smt. Sarojamma aged about 48 years S/o Shivakumar residing at 71, Tarabanahalli, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of same family and further it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1997 (Figure-12.296) and presently three members are living in the house.

Petitioner No. 141 and 413	
Residential House	

Figure-12.296: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.11. Petitioner No.169: Sri. Chikkanna aged about 58 years S/o Kempanna residing at 216/A, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Petitioner No.425: Smt. Manjamma aged about 47 years W/o Chikkanna residing at 218/A, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Petitioner No.473: Sri. C. Keshavamurthy aged about 24 years S/o Chikkanna residing at 216/A, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that three Petitions have been filed from the members of the same family and further it was found that two individual houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the houses were constructed in the year 2003 (Figure-12.297) in the inherited land and presently nine members are living in these houses.

Petitioner No. 169,425 and 473	
Residential House	

Figure-12.297: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.12. Petitioner No.182: Smt. D. Karthikeyan aged about 28 years W/o R. Devendra residing at Tarabanahalli, Hesaraghatta, Bangalore North, Bangalore Urban District – 560 090.

Petitioner No.229: Sri. R. Devendra aged about 55 years S/o Rangaraj residing at Tarabanahalli, Hesaraghatta, Bangalore North, Bangalore Urban District – 560 090.

Petitioner No.378: Smt. D. Kalke Chelvan aged about 26 Years W/o R. Devendra residing at Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Petitioner No.541: Smt. D. Hamsaveni aged about 43 years W/o R. Devendra residing at Silepura Road, Tarabanahalli, Hesaraghatta, Bangalore North – 560 090.

Petitioner No.574: Smt. K. Sukanya aged about 21 years W/o D. Karthikeyan residing at #14, Tarabanahalli, Hesaraghatta, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that five petitions have been filed by the members of the same family and further it was found that G+1 building has been constructed. While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours the house has been constructed in the year 2011 (Figure-12.298) and presently seven members are living in the house.

Petitioner No. 182, 229, 378, 541 and 574	
Residential House	

Figure-12.298: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.13. Petitioner No.193: Smt. Savithramma aged about 57 years W/o Muddaiah residing at 83-A, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two individual houses have been constructed in the ground floor in an area of (30'x40'). During the interaction with the petitioner it was found that the houses were constructed in the year 2005 (Figure-12.299) and presently a total of seven members are living in these houses.

Petitioner No. 193	
Residential House	

Figure-12.299: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.14. Petitioner No.213: Smt. V. Chandrabai aged about 56 years S/o S. Shyamrao residing at 345, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of (30'x40'). During the interaction with the petitioner it was found that the house has been constructed in the year 2014 (Figure-12.300) and presently five members are living in the house.

Petitioner No. 213	
Residential House	

Figure-12.300: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.15. Petitioner No.236: Sri. Shivakumar aged about 55 years S/o Pravathayya residing at house No.50, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Petitioner No.361: Smt. Rudramma aged about 50 years W/o Shivakumar residing at house No.118, Tarabanahalli, Bangalore North Taluk (Addl.), Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that single house along with two shops have been constructed in the ground floor. While carrying out the ground verification the petitioners houses was locked and as per the information collected from the neighbours the house was constructed in the year 1999 (Figure-12.301) and presently fives members are living in the house.

Petitioner No. 236 and 361	
Residential House along with shops	

Figure-12.301: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.16. Petitioner No.242: Sri. Kemparaju aged about 55 years S/o Honnappa residing at 162, Tarabanahalli, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Petitioner No.359: Smt. Neelamma aged about 50 years W/o Kemparaju residing at 162, Tarabanahalli, Bangalore North (Addl.) Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that two houses have been constructed i.e. G+1 and single house in the ground floor and also it was found that the first floor was having three houses. During the interaction with the petitioner it was found that after demolition of 100 years old house, the new houses have been constructed in the year 2007 (Figure-12.302) in the inherited land and presently twenty five members are living in these houses.

Petitioner No. 242 and 359	
Residential Building	

Figure-12.302: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.17. Petitioner No. 307: Sri. Puttaraju aged about 51 years S/o Honnaiah residing at 11, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in the inherited property. During the interaction with the petitioner it was found that the old house that was constructed in the year 1987 (Figure-12.303) which has been renovated in the year 2001 and presently fifteen members are living in these houses.

Petitioner No. 307	
Residential Building	



Figure-12.303: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.18. Petitioner No.311: Smt. H. S. Manjula aged about 27 years W/o R. Mallesh residing at 204, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Petitioner No.849: Sri. Mallesh aged about 32 years S/o Shivashankaraiah residing at 204-B, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that two houses have been constructed in the ground floor in an area of (30'x40'). During the interaction with the petitioner it was found that the house was constructed in the year 2007 (Figure-12.304).

Petitioner No. 311 and 849	
Residential House	

Figure-12.304: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.19. Petitioner No.340: Sri. Nagaraju aged about 50 years S/o Thimmaiah residing at 5-A Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that G+1 building along with shop has been constructed in an area of (40′x20′) and further it was found that the building was having three houses. During the interaction with the petitioner it was found that the building was constructed in the year 2008 (Figure-12.305) and presently a total of five members are living in these houses.

Petitioner No. 340	
Residential House along with the shops	

Figure-12.305: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.20. Petitioner No.341: Smt. Janakamma aged about 50 years S/o Gurushanthappa residing at 18-A, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that G+3 building has been constructed in an area of (15′x20′) and further it was found that the building was having three houses. During the interaction with the petitioner it was found that the building was constructed in the year 2013 (Figure-12.306) and presently a total of six members are living in these houses.

Petitioner No. 341	
Residential Building	

Figure-12.306: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.21. Petitioner No.342: Sri. Hanumantharayappa aged about 50 years S/o Byranna residing at house No.8, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building constructed and further it was found that the building was having fourteen shops. During the interaction with the petitioner it was found that the building was constructed in the year 2000 (Figure-12.307).

Petitioner No. 342	
Commercial Shops	

Figure-12.307: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.22. Petitioner No.371: Sri. Muniraju aged about 50 years S/o Muniswamaiah residing at 26, Tarabanahalli, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that the first floor was having one room. During the interaction with the petitioner it was found that the building has been constructed in the year 2005 (Figure-12.308) and presently three members are living in this building.

Petitioner No. 371	
Residential Building	

Figure-12.308: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.23. Petitioner No.375: Sri. Nagaraju aged about 50 years S/o Siddappa residing at 33, Tarabanahalli, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Petitioner No.714: Sri. Suresh aged about 37 years S/o Siddappa residing at 33, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Petitioner No.768: Sri. Ramesh aged about 35 years S/o Siddappa residing at 33, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that three petitions have been filed by the members of the same family and further it was found that the two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the houses were constructed in the year 2008 (Figure-12.309) and presently a total of five members are living in these houses.

Petitioner No. 375, 714 and 768	
Residential House	

Figure-12.309: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.24. Petitioner No.434: Sri. Gangappa aged about 47 years S/o Muniyappa, residing at 2, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that G+2 building along with three shops have been constructed and further it was found that the building was having six houses (Figure-12.310). While carrying out the ground verification the petitioner's house was locked.

Petitioner No. 434	
Residential Building along with the shops	

Figure-12.310: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.25. Petitioner No.435: Sri. Chandrashekhar aged about 47 years S/o Nanjappa residing at 2, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building along with two shops have been constructed in an area of (30′x40′). During the interaction with the petitioner it was found that the building was constructed in the year 2010 (Figure-12.311) and presently a total of eight members are living in these houses.

Petitioner No. 435	
Residential Building along with the shops	

Figure-12.311: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.26. Petitioner No.446: Sri. Kiran aged about 25 years S/o Kempraju residing at 86, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that single house has been constructed in an area of (18′x44′). During the interaction with the petitioner it was found that the house has been constructed in the year 1965 (Figure-12.312) and presently two members are living in the house.

Petitioner No. 446	
Residential House	

Figure-12.312: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.27. Petitioner No.556: Smt. H.G. Jayalakshmi aged about 43 years W/o H. Jilakshmi Narayan residing at 25, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of (30′x40′). During the interaction with the petitioner it was found that the house has been constructed in the year 2012 (Figure-12.313) and presently three members are living in the house.

Petitioner No. 556	
Residential House	

Figure-12.313: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.28. Petitioner No.570: Sri. Rathnamma aged about 42 years S/o Manjunatha residing at 36, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1995 (Figure-12.314) in inherited land and presently four members are living in the house.

Petitioner No. 570	
Residential House	

Figure-12.314: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.29. Petitioner No.572: Smt. Fathima aged about 22 years W/o Rajasab residing at Tarabanahalli, Hesaraghatta Main Road, Bangalore North, Bangalore Urban District – 560 090.

Petitioner No.584: Smt. Ambiba aged about 20 years W/o Akbar residing at Silverpura, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Petitioner No.597: Sri. Akbar aged about 20 years S/o Rajsab residing at Tarabanahalli, Hesaraghatta, Main Road, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that three petitions have been filed by the members of the same family and further it was found that single house along with two shops have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1985 (Figure-12.315) and presently a total of ten members are living in the house.

Petitioner No. 572, 584 and 597	
Residential House along with shops	

Figure-12.315: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.30. Petitioner No.649: Sri. Ashoka aged about 40 years S/o Srinivas residing at #24, Hesaraghatta Road, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Petitioner No.699: Smt. Bharathi aged about 30 years W/o Ashok residing at Hesaraghatta Road, Anjanadri Layout, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that two petitions have been filed from the members of the same family and further it was found that the unfinished single house has been constructed in the ground floor (Figure-12.316). As per the information collected from the neighbours the construction work has been stopped since nine months.

Petitioner No. 649 and 699	
Unfinished construction of a house	

Figure-12.316: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.31. Petitioner No.667: Sri. T. P Ravi Kumar aged about 39 years S/o Parvathappa residing at 13, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (80′x40′) and further it was found that the building was having eight houses. During the interaction with the petitioner it was found that the building was constructed in the year 2007 (Figure-12.317) and presently a total of twenty eight members are living in these houses.

Petitioner No. 667	
Residential Building	

Figure-12.317: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.32. Petitioner No.682: Sri. S. Suresh aged about 39 years S/o Shivakumar residing at #13-1, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2013 (Figure-12.318) in the inherited land and presently six members are living in the house.

Petitioner No. 682	
Residential House	

Figure-12.318: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.33. Petitioner No.707: Sri. V.S. Lokesh aged about 38 years S/o V.N. Shankarappa residing at 9/B, Tarabanahalli, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Petitioner No.850: Smt. K.S. Nagarathna aged about 32 years W/o V.S. Lokesh residing at 9/B, Tarabanahalli, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that two G+1 buildings have been constructed and among the two buildings one of the G+ 1 building was under construction. During the interaction with the petitioner it was found that the existing building was constructed in the year 2013 (Figure-12.319) and presently twelve members are living in these houses.

Petitioner No. 707 and 850	
Residential Building	

Figure-12.319: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.34. Petitioner No.809: Sri. K. Vishwanath aged about 35 years S/o Siddappa residing at 8, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor (Figure-12.320). While carrying out the ground verification the petitioner house was locked.

Petitioner No. 809	
Residential House	

Figure-12.320: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.35. Petitioner No.816: Sri. S. Vishalakshit aged about 34 Years S/o N.S. Rudresh residing at 76, Tarabanahalli, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that G+3 building has been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 2015 (Figure-12.321) and presently five members are living in the house and further it was found that the house was having borewell.

Petitioner No. 816	
Residential Building	

Figure-12.321: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Tarabanahalli Village

12.6.36. Unidentified Cases: In the village of Tarabanahalli out of 75 cases 55 residential houses cases were identified and remaining 20 properties pertaining to the cases that could not be identified are given below:

1. **Petitioner No.274:** Sri. Giriyappa aged about 53 years S/o Narasimhaiah residing at house No.172, Tarabanahalli, Bangalore North Taluk (Addl.), Bangalore Urban District - 560 090.

2. **Petitioner No.309:** Sri. Venkatesh aged about 51 years S/o Munivenkateshappa residing at 37/A, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

3. **Petitioner No.382:** Sri. B.N. Vasantha Kumar aged about 26 years S/o B.R. Nagappa residing at #7, Siluvepura Road Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

4. **Petitioner No.554:** Sri. V. Vedavathi aged about 23 years S/o Venkatesh residing at #37/A, Hesaraghatta Road, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

5. **Petitioner No.558:** Smt. N. Ayesha aged about 23 years W/o B.N. Rajesh residing at #13, Anjanadri Layout, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

6. **Petitioner No.568:** Smt. R. Asha aged about 22 years W/o Deepu residing at Siddamatta Road, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

7. **Petitioner No.586:** Sri. V. Mohan Kumar about 20 years S/o Venkatesh residing at #37/A, Tarabanahalli, Hesaraghatta Road, Bangalore North, Bangalore Urban District – 560 090.

8. **Petitioner No.602:** Sri. B.N. Rajesh aged about 41 years S/o Late B. M. Nanjappa residing at #13, Anjandari Layout, Tarabanahalli, Bangalore North, Bangalore Urban District -560 090.

9. **Petitioner No.616:** Sri. C.R. Govindaraju aged about 41 years S/o K. H. Rangaiah residing at 16/B, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

10. **Petitioner No.668:** Smt. Anusuya aged 39 years W/o Vekatesh residing at 371a, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

11. **Petitioner No.676:** Sri. Janardhana Rao aged about 39 years S/o Rama Kripoji Rao residing at 42, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

12. **Petitioner No.701:** Smt. Hemalatha aged about 30 years W/o Govindaraju residing at 16/B, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

13. **Petitioner No.724:** Sri. Krishnamurthy aged about 37 years S/o Shivanna residing at 35-C, Tarabanahalli, Bangalore North (Addl.), Bangalore Urban District – 560 090.

14. **Petitioner No.738:** Smt. Umabai aged about 36 years W/o Anantharao residing at #26, 1st Cross, Government School Near, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

15. **Petitioner No.750:** Smt. S. Manjula Baj aged about 36 years W/o V. Manjunatha Rao residing at 345, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

16. **Petitioner No.751:** Sri. S. Ramesh Rao aged about 36 years S/o S. Shyamarao residing at 345, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

17. **Petitioner No.752:** Smt. Premabai aged about 36 years W/o Janardana Rao residing at 42, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

18. **Petitioner No.769:** Smt. Javaramma aged about 35 years W/o Rajanna residing at Siddamaita Road, M.E.S. Road, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

19. **Petitioner No.817:** Sri. T.S. Rajashekhar aged about 34 years S/o Shivakumar residing at 71, Tarabanahalli, Bangalore North (Addl.), Bangalore Urban District – 560 090.

20. **Petitioner No.844:** Smt. Padma aged about 32 years W/o Manjunatha residing at 50-C, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

12.7. Sasuveghatta Village:

Sasuveghatta is coming under the jurisdiction of Hurlichikkanhalli Gram Panchayat and as per 2011 census the village has an area of 2.01 Sq.Km. with population of 737 and 182 households. The Sasuveghatta village falls in the Zone-3 and 4 of the Arkavathi river stretch of the TGR catchment area (Figure-12.322).

In the Sasuveghatta village, 75 cases are filed (Annexure-12.7) and during the ground verification it was found that in few cases two to three petitions have been filed by members of one family *i.e.* father and son or husband and wife etc. The ground truth verification revealed that few of the residential houses have been constructed in 50's, 60's, 80's and 90's and it was also found that after 2000 many houses have come-up. It was found that most of the houses have been constructed in Gramathana and also in the survey No. 6, 37, 61, 63 and 64. Further, the ground truth verification witnessed that major of the houses have been constructed in the Gramathana. Whereas, most of the houses have been constructed in the inherited land and few of the houses have been constructed in the



Figure-12.322: Location of the Sasuveghatta village in the Zone-3 and 4 of Arkavathi river course (Source – NPA)

revenue sites. 99% of the petitioners submitted Electricity bills as a substantiation document during the residential houses field verification.

While interacting with the respondent it was found that the Gram Panchayat is supplying water through borewells and mini water supply. Some of the general observations include sewage discharge into pit, grey water discharge into open drain, improper management of solid waste (disposed into nearby vacant-land or dumped in their land), open drain sanitation and accessibility to road. There has been slight growth of the population (Figure-12.323) and households (Figure-12.324).



Figure-12.323: Population trend in the Sasuveghatta village



Figure-12.324: Households statistics in the Sasuveghatta village

During the ground truth verification, out of 75 cases 66 residential houses cases were identified and remaining 09 houses could not be identified (Figure-12.325). The local people and the persons accompanying the ground truth exercise expressed inability to locate these addresses. Further, a written statement (PANCHANAMA) was written in the presence of all the members of the committee i.e. EMPRI staff, two representatives of the petitioners and local people of the village along with their signatures. Panchanama of the ground verification of the residential superstructure is annexed in the Annexure-12.2. The current status of each of the identified petitioners houses in the Sasuveghatta village are discussed below:



Figure-12.325: Field verification status

12.7.1. Petitioner No.3: Sri. Gangappa aged about 80 years S/o Motayya residing at house No.48, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the old house was constructed in the year 1952 (Figure-12.326) which has been renovated in the year 2012 and presently six members are living in the house.

Petitioner No. 03	
Residential House	

Figure-12.326: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.2. Petitioner No.5: Sri. Narayanappa aged about 78 years S/o Byralingappa residing at 50, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (30'x40'). During the interaction with the petitioner it was found that the house has been constructed in the year 2014 (Figure-12.327) and presently four members are living in these houses.

Petitioner No. 05	
Residential Building	

Figure-12.327: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.3. Petitioner No.15: Sri. Huchabairappa aged about 76 years S/o Ajjegowda residing at 113, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor (Figure-12.328). During the interaction with the petitioner it was found that presently five members are living in the house.

Petitioner No. 15	
Residential House	

Figure-12.328: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.4. Petitioner No.22: Smt. Gangamma aged about 72 years W/o Hanumantharayappa residing at 60, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2011 (Figure-12.329) and presently three members are living in the house.

Petitioner No. 22	
Residential House	

Figure-12.329: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.5. Petitioner No.24: Sri. Chikkanna aged about 72 years S/o Veeregowda residing at 19, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (30'x40'). During the interaction with the petitioner it was found that the building has been constructed in the year 2012 (Figure-12.330) and presently eight members are living in the house.

Petitioner No. 24	
Residential Building	

Figure-12.330: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.6. Petitioner No.30: Smt. Lakshmamma aged about 71 years W/o Erappa residing at 171, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1950 (Figure-12.331) and presently one member is living in the house.

Petitioner No. 30	
Residential House	

Figure-12.331: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.7. Petitioner No.41: Sri. Gangadhar aged about 34 years S/o Gangamma residing at Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2013 (Figure-12.332) and presently four members are living in the house.

Petitioner No. 41	
Residential House	

Figure-12.332: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.8. Petitioner No.68: Sri. Hanumantharayappa aged about 66 years S/o Bailappa residing at 166, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Petitioner No.617: Sri. H. Lakshmi Narayana aged about 41 years S/o Hanumantharayappa residing at 166, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed from the members of the same family and further it was found that single house has been constructed in the ground floor in an area of (20'x30'). During the interaction with the petitioner it was found that the house has been constructed in the year 2005 (Figure-12.333) and presently five members are living in the house.

Petitioner No. 68 and 617	
Residential House	

Figure-12.333: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.9. Petitioner No.74: Smt. Shanthamma aged about 66 years W/o Prabhudas residing at 216, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1960 (Figure-12.334) and presently seven members are living in the house.

Petitioner No. 74	
Residential House	

Figure-12.334: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.10. Petitioner No.112: Smt. Mahimakka aged about 62 years W/o Nanjappa residing at 44, Sasuveghatta, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that single house which was constructed in the year 1960 (Figure-12.335) is presently vacant.

Petitioner No. 112	
Vacant House	

Figure-12.335: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.11. Petitioner No.113: Sri. Maimanna aged about 62 years S/o Narasimhaiah residing at 3, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of (40'x45'). During the interaction with the petitioner it was found that that the old house which was constructed in the year 1965 has been renovated in the year 2002 (Figure-12.336) and presently nine members are living in the house.

Petitioner No. 113	
Residential House	

Figure-12.336: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.12. Petitioner No.116: Smt. Usha aged about 29 years W/o Chandrashekhara residing at 6, Sasuveghatta, Tarabanahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building has been constructed and it was found that the building was having three houses. During the interaction with the petitioner it was found that the building was constructed in the year 2014 (Figure-12.337) and presently four members are living in the house.

Petitioner No. 116	
Residential Building	

Figure-12.337: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.13. Petitioner No.122: Sri. Kempaiah aged about 61 years S/o Thimmannappa residing at 187, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the building has been constructed in the year 1993 (Figure-12.338) and presently seven members are living in the house.

Petitioner No. 122	
Residential Building	

Figure-12.338: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.14. Petitioner No.123: Sri. Jayamma aged about 61 years S/o Huchaiah residing at 167-E, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1970 (Figure-12.339) and presently five members are living in the house.

Petitioner No. 123	
Residential House	

Figure-12.339: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.15. Petitioner No.144: Sri. B. Hanumaiah aged about 60 years S/o Bailappa residing at 62, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Petitioner No.693: Sri. Madhu aged about 30 years S/o Hanumaiah residing at 166, Sasuveghatta, Bangalore North (Addl.) Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that G+1 building (Figure-12.340) has been constructed in an area of (30'x40'). During the interaction with the petitioner it was found that presently six members are living in the house.

Petitioner No. 144 and 693	
Residential Building	

Figure-12.340: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.16. Petitioner No.158: Sri. Narayanappa aged about 59 years S/o Hanumanthappa residing at 175, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that that the building has been constructed in the year 2013 (Figure-12.341) and presently four members are living in the house.

Petitioner No. 158	
Residential Building	

Figure-12.341: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.17. Petitioner No.168: Sri. Kempanna aged about 58 years S/o Narasimhaiah residing at 96, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2000 (Figure-12.342) and presently five members are living in the house.

Petitioner No. 168	
Residential House	

Figure-12.342: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.18. Petitioner No.177: Smt. Jayamma aged about 58 years W/o Gangahanumantharayappa residing at 94, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that that the building has been constructed in the year 1995 (Figure-12.343) and presently seven members are living in the house.

Petitioner No. 177	
Residential Building	

Figure-12.343: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.19. Petitioner No.186: Sri. Muniyappa aged about 57 years S/o Hanumantharayappa residing at 60, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that four houses has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2000 (Figure-12.344) and presently ten members are living in these houses.

Petitioner No. 186	
Residential House	

Figure-12.344: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.20. Petitioner No.187: Sri. Bairanna aged about 57 years S/o Gali Hanumaiah residing at 39, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (28'x80') and further it was found that the building was having eight houses. During the interaction with the petitioner it was found that the building has been constructed in the year 2007 (Figure-12.345) and presently a total of twenty eight members are living in these houses.

Petitioner No. 187	
Residential Building	

Figure-12.345: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.21. Petitioner No.189: Smt. Gangamma aged about 57 years W/o Joganna residing at 97, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1980 (Figure-12.346) and presently three members are living in the house.

Petitioner No. 189	
Residential House	

Figure-12.346: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.22. Petitioner No.190: Sri. Muthegowda aged about 57 years S/o Muniyappa residing at 98, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1985 (Figure-12.347) and presently three members are living in the house.

Petitioner No. 190	
Residential House	

Figure-12.347: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.23. Petitioner No.203: Sri. Chikanna aged about 56 years S/o Mariyappa residing at 215, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of (20'x35'). During the interaction with the petitioner it was found that the house has been constructed in the year 1993 (Figure-12.348) and presently five members are living in the house.

Petitioner No. 203	
Residential House	

Figure-12.348: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.24. Petitioner No.204: Sri. N. Kalachar aged about 56 years S/o Nayachar residing at 191, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Petitioner No.648: Smt. Subblakshmi aged about 40 years W/o N. Nagarajachar residing at house No.8-2, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the old house which was constructed in the year 1995 (Figure-12.349) has been renovated in the year 2005 and presently four members are living in these houses.

Petitioner No. 204 and 648	
Residential House	

Figure-12.349: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.25. Petitioner No.215: Sri. Puttegowda aged about 56 years S/o Chikkabairappa residing at 179, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of (60'x45'). During the interaction with the petitioner it was found that the house has been constructed in the year 1980 (Figure-12.350) and presently four members are living in the house.

Petitioner No. 215	
Residential House	

Figure-12.350: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.26. Petitioner No.222: Smt. Rajamma aged about 56 years W/o Gangahanumaiah residing at 218, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1980 (Figure-12.351) and presently three members are living in the house.

Petitioner No. 222	
Residential House	

Figure-12.351: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.27. Petitioner No.237: Sri. Ayyannagowda aged about 55 years S/o Byralingappa residing at 213, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the house has been constructed in the year 2000 (Figure-12.352) and presently four members are living in the house.

Petitioner No. 237	
Residential Building	

Figure-12.352: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.28. Petitioner No.284: Smt. Ammajamma aged about 52 years W/o Hanumantharayappa residing at 17, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the old house constructed in the year 1950 (Figure-12.353) which has been renovated in the year 2010 and presently one member is living in the house.

Petitioner No. 284	
Residential House	

Figure-12.353: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.29. Petitioner No.285: Sri. B. Bairaya aged about 52 years S/o Bairanna residing at 66, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the old house which was constructed in the year 1985 (Figure-12.354) has been renovated in the year 2003 and presently six members are living in the house.

Petitioner No. 285	
Residential House	

Figure-12.354 GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.30. Petitioner No.292: Sri. Madappa aged about 52 years S/o Ganganarasimhaiah residing at 82, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (30'x40'). During the interaction with the petitioner it was found that the building has been constructed in the year 2005 (Figure-12.355) and presently three members are living in the house.

Petitioner No. 292	
Residential Building	

Figure-12.355: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.31. Petitioner No.293: Sri. Rangappa aged about 52 years S/o Ajjegaud residing at 82, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1965 (Figure-12.356) and presently three members are living in the house.

Petitioner No. 293	
Residential House	

Figure-12.356: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.32. Petitioner No.308: Sri. H. Chennappa aged about 51 years S/o Huchappa residing at 176, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in the ancestors property. During the interaction with the petitioner it was found that the building has been constructed in the year 2007 (Figure-12.357) and presently five members are living in the house.

Petitioner No. 308	
Residential Building	

Figure-12.357: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.33. Petitioner No.343: Sri. Nagaraja aged about 50 years S/o Annadanappa residing at house No.17, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that two houses has been constructed in the ground floor (Figure-12.358). While carrying out the ground truth verification the petitioner house was locked.

Petitioner No. 343	
Residential House	

Figure-12.358: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.34. Petitioner No.385: Sri. Puttaswamy Gowda aged about 49 years S/o Byranna residing at 195, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two individual houses have been constructed in the ground floor in the ancestors property. During the interaction with the petitioner it was found that the houses were constructed in the year 1965 (Figure-12.359) and presently six members are living in these houses.

Petitioner No. 385	
Residential House	

Figure-12.359: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.35. Petitioner No.393: Sri. Rajanna aged about 49 years S/o Hanumantharayappa residing at 166-E, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1960 (Figure-12.360) and presently six members are living in the house.

Petitioner No. 393	
Residential House	

Figure-12.360: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.36. Petitioner No.401: Sri. Muthegowda aged about 48 years S/o Chikkaveerappa residing at 68, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 2012 (Figure-12.361) and presently five members are living in the house and it was also found that the house was having borewell.

Petitioner No. 401	
Residential Building	

Figure-12.361: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.37. Petitioner No.424: Sri. Lakkappa aged about 47 years S/o Huchaiah residing at 52, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building has been constructed in an area of (30'x40') and further it was found that the building was having six houses. During the interaction with the petitioner it was found that the building was constructed in the year 2002 (Figure-12.362) and presently a total of twenty one members are living in these houses.

Petitioner No. 424	
Residential Building	

Figure-12.362: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.38. Petitioner No.426: Sri. Lingappa aged about 47 years S/o Ramaiah residing at 100, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor (Figure-12.363). While carrying out the ground truth verification the petitioners house was locked.

Petitioner No. 426	
Residential House	

Figure-12.363: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.39. Petitioner No.436: Smt. Jayamma aged about 47 years W/o Jayaramaiah residing at 43, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1960 (Figure-12.364) and presently four members are living in the house.

Petitioner No. 436	
Residential House	

Figure-12.364: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.40. Petitioner No.444: Sri. Muthegowda aged about 38 years S/o Mutharayappa residing at 198-E, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Petitioner No.712: Sri. Shanthakumar aged about 38 years S/o Mutharayappa residing at 198-E, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found two petitions have been filed by the members of the same family and further it was found that G+1 building has been constructed and also it was found that the first floor having one room. During the interaction with the petitioner it was found that the building has been constructed in the year 1988 (Figure-12.365) in the inherited land and presently seven members are living in these houses.

Petitioner No. 444 and 712	
Residential Building	

Figure-12.365: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.41. Petitioner No.445: Sri. Narayanappa aged about 46 years S/o Gangappa residing at 243, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that G+1 building has been constructed. While carrying out the ground verification the petitioners house was locked and as per the information collected from the neighbours the building has been constructed in the year 2005 (Figure-12.366) and presently four members is living in the house.

Petitioner No. 445	
Residential Building	

Figure-12.366: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.42. Petitioner No.453: Sri. Umesha aged about 46 years S/o Muniyappa residing at 185, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building has been constructed in an area of (30'x40'). During the interaction with the petitioner it was found that the building has been constructed in the year 2000 (Figure-12.367) and presently five members are living in the house.

Petitioner No. 453	
Residential Building	

Figure-12.367: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.43. Petitioner No.489: Smt. Munilakshmamma aged about 45 years W/o Bairanna residing at 240, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (33'x25') and further it was found that the building was having three houses. During the interaction with the petitioner it was found that the building has been constructed in the year 2000 (Figure-12.368) and presently six members are living in the house.

Petitioner No. 489	
Residential Building	

Figure-12.368: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.44. Petitioner No.503: Sri. Anantharamu aged about 44 years S/o Muniyappa residing at 185, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that the old house which was constructed in the year 1985 (Figure-12.369) has been demolished and construction of new building in the area 60'x40' was under progress.

Petitioner No. 503	
Construction of new building under progress	

Figure-12.369: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.45. Petitioner No.571: Sri. Hanumantharayappa aged about 42 years S/o Munihanumaiah residing at 42, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours that the house has been constructed in the year 1975 (Figure-12.370) and presently three members are living in the house.

Petitioner No. 571	
Residential House	

Figure-12.370: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.46. Petitioner No.476: Sri. Ramegowda aged about 45 years S/o Appannagowda residing at 75, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of 23′x27′ and further it was found that the building was having three houses. During the interaction with the petitioner it was found that the building was constructed in the year 2012 (Figure-12.371) and presently fifteen members are living in the houses.

Petitioner No. 476	
Residential Building	

Figure-12.371: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.47. Petitioner No.477: Sri. Thimmegowda aged about 45 years S/o Ramaswamy residing at 37, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2000 (Figure-12.372) and presently four members are living in the house.

Petitioner No. 477	
Residential House	

Figure-12.372: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.48. Petitioner No.629: Smt. Nagarathnamma aged about 41 years W/o Puttagangaiah residing at 240, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in the ground floor. During the interaction with the petitioner it was found that the building has been constructed in the year 2005 (Figure-12.373) and presently four members are living in the house.

Petitioner No. 629	
Residential Building	



Figure-12.373: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.49. Petitioner No.639: Sri. Raju aged about 40 years S/o Vevkataramanappa residing at 46, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the old house which was constructed in the year 1970 (Figure-12.374) has been renovated in the year 2005 and presently three members are living in the house.

Petitioner No. 639	
Residential House	

Figure-12.374: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.50. Petitioner No.645: Sri. Narayanaswamy aged about 48 years S/o Muniyappa residing at Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the house has been constructed in the year 2014 (Figure-12.375) and presently four members are living in the house.

Petitioner No. 645	
	
Residential Building	

Figure-12.375: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.51. Petitioner No.681: Sri. Kumar aged about 39 years S/o Huchcraiah residing at 67, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that single house along with two shops have been constructed in the ground floor in an area of (18′x30′). During the interaction with the petitioner it was found that the house was constructed in the year 2013 (Figure-12.376) and presently four members are living in the house.

Petitioner No. 681	
Residential House along with the shops	

Figure-12.376: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.52. Petitioner No.683: Sri. S. H. Manjunatha aged about 39 years S/o Hanumantharayappa residing at 64, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2005 (Figure-12.377) and presently five members are living in the house.

Petitioner No. 683	
Residential House	

Figure-12.377: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.53. Petitioner No.686: Smt. Prema aged about 25 years W/o Venkatachaiah residing at 25, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2011 (Figure-12.378) and presently four members are living in the house.

Petitioner No. 686	
Residential House	

Figure-12.378: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.54. Petitioner No.692: Smt. Vasantha aged about 29 years W/o Muniraju residing at 18, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2009 (Figure-12.379) and presently four members are living in the house.

Petitioner No. 692	
Residential House	

Figure-12.379: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.55. Petitioner No.715: Sri. Manjunath aged about 37 years S/o Chikkabyrappa residing at 34, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that four houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the old house which was constructed in the year 1945 (Figure-12.380) has been renovated in the year 2005 and presently thirteen members are living in these houses.

Petitioner No. 715	
Residential House	

Figure-12.380: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.56. Petitioner No.739: Smt. Manjula aged about 36 years W/o Hanumantharayappa residing at 18, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the was constructed in the year 2011 (Figure-12.381) and presently five members are living in the house.

Petitioner No. 739	
Residential House	

Figure-12.381: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.57. Petitioner No.720: Sri. Manjunath aged about 30 years S/o Channappa residing at 169, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that G+1 building has been constructed (Figure-12.382). While carrying out the ground truth verification the petitioners house was locked.

Petitioner No. 720	
Residential Building	

Figure-12.382: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.58. Petitioner No.731: Sri. Puttahanumaiah aged about 37 years S/o Thimakka residing at Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (30'x40'). During the interaction with the petitioner it was found that the building has been constructed in the year 2010 (Figure-12.383) and presently four members are living in the house.

Petitioner No. 731	
Residential Building	

Figure-12.383: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.59. Petitioner No. 737: Sri. Nagaraju aged about 36 years S/o Giriyappa residing at 26, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house along with shop has been constructed in the ground floor in an area of (10'x40'). During the interaction with the petitioner it was found that the house has been constructed in the year 2000 (Figure-12.384) and presently four members are living in the house.

Petitioner No. 737	
Residential House	

Figure-12.384: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.60. Petitioner No.810: Smt. Yashodamma aged about 36 years W/o Narayanaswamy residing at 55, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of (35'x28'). During the interaction with the petitioner it was found that the house has been constructed in the year 2011 (Figure-12.385) and presently two members are living in the house.

Petitioner No. 810	
Residential House	

Figure-12.385: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.61. Petitioner No.843: Sri. Narasimha Murthy aged about 32 years S/o Giriyappa residing at 41, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1963 (Figure-12.386) and presently four members are living in the house.

Petitioner No. 843	
Residential House	

Figure-12.386: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.62. Petitioner No.856: Sri. Nataraju aged about 31 years S/o Muniyappa residing at 168, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor (Figure-12.387) in an area of (18'x30'). During the interaction with the petitioner it was found that presently six members are living in the house.

Petitioner No. 856	
Residential House	

Figure-12.387: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Sasuveghatta Village

12.7.63. Unidentified Cases: In the village of Sasuveghatta out of 75 cases 66 residential houses cases were identified and remaining 09 properties pertaining to the cases that could not be identified are given below:

1. **Petitioner No.18:** Sri. Hanumantharayappa aged about 75 years S/o Gangappa residing at house No.23, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.
2. **Petitioner No 26:** Sri. Hanumaiah aged about 72 years S/o Thimmaiah residing at 57, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.
3. **Petitioner No.81:** Smt. Gangabairamma aged about 65 years W/o Ramaiah residing at 56, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.
4. **Petitioner No.127:** Sri. Gangappa aged about 61 years S/o Hanumaiah residing at 99, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.
5. **Petitioner No.312:** Sri. H. Hanuman aged about 27 years S/o B. Hanumaiah residing at 62, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.
6. **Petitioner No.331:** Sri. Rajanna aged about 51 years S/o Mayanna residing at 223- E, Sasuveghatta, Bangalore North (Addl.), Bangalore Urban District – 560 090.
7. **Petitioner No.402:** Sri. Nagaraju aged about 48 years S/o Huchappa residing at 53, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.
8. **Petitioner No.427:** Sri. Gangadhara aged about 47 years S/o Bairegowda residing at 74, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.
9. **Petitioner No.540:** Smt. Rathnamma aged about 43 years W/o Lingappa residing at 193, Sasuveghatta, Bangalore North, Bangalore Urban District – 560 090.

12.8. Makali Village:

Makali village is coming under the jurisdiction of Dasanapura Gram Panchayat and as per the 2011 census the village has an area of 0.79 Sq. Km. with population of 2873 and 744 households. The Makali village falls in the Zone-3 of the Arkavathi river stretch of the TGR catchment area (Figure-12.388).



Figure-12.388: Location of the Makali village in the Zone-3 of Arkavathi river course (Source – NPA)

In the Makali village, 68 cases are filed (Annexure-12.8) and during the ground verification in few cases it was found that two to hree petitions have been filed by members of one family *i.e.* father and son or husband and wife etc. The ground truth verification revealed that few of the residential houses were constructed in 80's and 90's and it was found that after 2000 many houses have come-up. At present many houses are renovated adding 1-2 floors and in few cases they are being used as commercial shops which are rented out for income. Further, it was found that most of the houses have been constructed in the survey No. 2, 3, 4, 5, 9 and 14 and majority of the houses are constructed in the survey No. 4, 5, and 9. Further, the ground truth verification revealed that few of the houses have been constructed in the Gramthana, whereas few of the houses have been constructed in the site allotted by the Government under Ashraya Yojane Scheme. Some of the houses have been constructed in the sites allotted by the Government under the Janatha Niveshana in the survey No. 14, some of the houses are constructed in the inherited land, some of the houses constructed in the revenue sites and also few were vacant sites. 99% of the petitioners submitted electricity bill as a substantiation documents during the residential houses field verification.

While interacting with the petitioners it was found that the Grama Panchayat is supplying water through borewells and mini water supply and in few cases it was found that the houses having borewells. Some of the general observation includes sewage discharge into pit, grey water discharge into open drain, solid waste management by Grama Panchayat, open drain sanitation and accessibility to road. There has been rapid growth of the population (Figure-12.389) and households (Figure-12.390) in the Makali village. The main reasons behind this rapid growth are proximity to BBMP area, NH-4 passing (Bengaluru–Tumakuru Road) through the village and also job opportunities.

During the ground truth verification, out of 68 cases 60 residential houses cases were identified and remaining 08 houses could not be identified(Figure-12.391). The local people and the persons accompanying the ground truth exercise expressed inability to locate these addresses. Further, a written statement (PANCHANAMA) was written in the presence of all the members of the committee i.e. EMPRI staff, two representatives of the petitioners and local people of the village along with their signatures. Panchanama of the ground verification of the

residential superstructure is annexed in the Annexure-12.2. The current status of each of the identified petitioners houses in the Makali village are discussed below:



Figure-12.389: Population trend in the Makali village



Figure-12.390: Households statistics in the Makali village



Figure-12.391: Field verification status in the Makali village

12.8.1. Petitioner No.27: Smt. Chikkabylamma aged about 71 years W/o Yallappa residing at 27-2, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor. During the interaction with the respondent it was found that the house was constructed in the year 1992 (Figure-12.392) in the site allotted by the Government under the Janata Niveshana Yojane Scheme and presently eighteen members are living in these houses.

Petitioner No. 27	
Residential House	

Figure-12.392: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.2. Petitioner No.32: Smt. Parvathamma aged about 70 years W/o Ramarao residing at 63, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the site allotted by the Government under the Janata Niveshana Yojane Scheme in the year 1982 (Figure-12.393) and presently six members are living in these houses.

Petitioner No. 32	
Residential House	

Figure-12.393: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.3. Petitioner No.39: Sri. Bailappa aged about 69 years S/o Gullappa residing at E-12, Makali, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the site allotted by the Government under the Janata Niveshana Yojane Scheme in the year 2010 (Figure-12.394) and presently six members are living in the house.

Petitioner No. 39	
Residential House	

Figure-12.394: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.4. Petitioner No.45: Smt. Arasamma aged about 68 years W/o Sampangi residing at E-25, Makali, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the site allotted by the Government under the Janata Niveshana Yojane Scheme in the year 2010 (Figure-12.395) and presently eight members are living in these houses.

Petitioner No. 45	
Residential House	

Figure-12.395: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.5. Petitioner No.77: Sri. R. Rangappa aged about 65 years S/o Ramaiah residing at E-207, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that a G+2 building has been constructed in the existing site and further it was found that the building was having six houses. During the interaction with the petitioner it was found that the building has been constructed in the year 1998 (Figure-12.396) and presently eighteen members are living in these houses.

Petitioner No. 77	
Residential Building	

Figure-12.396: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.6. Petitioner No.94: Sri. A. H. Gangaiah aged about 63 years S/o Kapaneegowda residing at E -14, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the site allotted by the Government under the Janata Niveshana Yojane Scheme. Further it was found that the old house was constructed in the year 1982 which has been renovated in the year 2009 (Figure-12.397) and presently five members are living in the house.

Petitioner No. 94	
Residential House	

Figure-12.397: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.7. Petitioner No.95: Sri. Basavaiah aged about 63 years S/o Basavaiah residing at E-60, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building along with two shops have been constructed in the existing site. During the interaction with the petitioner it was found that the building was constructed in the year 1982 (Figure-12.398) in the site allotted by the Government under the Janatha Niveshana Yojane Scheme and presently nine members are living in the house.

Petitioner No. 95	
Residential Building along with shops	

Figure-12.398: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.8. Petitioner No. 96: Sri. Bailappa aged about 63 years S/o Muniyappa residing at E-62, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth survey it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1982 (Figure-12.399) in the site allotted by the Government under the Janatha Niveshana Yojane and presently five members are living in these houses.

Petitioner No. 96	
Residential House	

Figure-12.399: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.9. Petitioner No.110: Smt. Lakshmamma aged about 62 years W/o Muniyappa residing At 12, Prabhanagara, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the site allotted by the Government under the Ashrya Yojane Scheme in the year 2000 (Figure-12.400) and presently two members are living in the house.

Petitioner No. 110	
Residential House	



Figure-12.400: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.10. Petitioner No.133: Sri. Siddagangamma aged about 60 years residing at E-214, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in the existing site and further it was found that the building was having seven houses. During the interaction with the petitioner it was found that the building was constructed in the year 1998 (Figure-12.401) and presently a total of twenty three members are living in these houses.

Petitioner No. 133	
Residential Building	

Figure-12.401: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.11. Petitioner No.164: Sri. A.C. Hanumantharaju aged about 58 years S/o Channappa residing at E-216, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2004 (Figure-12.402) and presently a total of eight members are living in these houses.

Petitioner No. 164	
Residential House	

Figure-12.402: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.12. Petitioner No.167: Sri. Mahadevaiah aged about 58 years S/o Veeranna residing at 114-2, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building along with two shops have been constructed in the existing site and further it was found that the building was having seven houses. During the interaction with the petitioner it was found that the building was constructed in the year 2004 (Figure-12.403) and presently a total of thirteen members are living in these houses.

Petitioner No. 167	
Residential Building along with shops	

Figure-12.403: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.13. Petitioner No.172: Sri. Hotte Muniyappa aged about 58 years S/o Anjinappa residing at E67, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor and further it was found that one house was vacant. During the interaction with the petitioner it was found that the house was constructed in the site allotted by the Government under the Janatha Niveshana Yojane Scheme in the year 1974 (Figure-12.404) and presently two members are living in the house.

Petitioner No. 172	
Residential House	

Figure-12.404: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.14. Petitioner No.183: Smt. Chandramma aged about 57 years W/o Siddappa residing at 17, Makali, Bangalore North, Bangalore Urban District – 562 123.

Petitioner No.471: Sri. S. Ramesh aged about 45 years S/o Siddappa residing at 17, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that four houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the houses was constructed in the year 1992 (Figure-12.405) in the inherited land and presently sixteen members are living in these houses.

Petitioner No. 183	
Residential House	

Figure-12.405: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.15. Petitioner No.184: Sri. H. Jayashankar aged about 57 years S/o Hanumantappa residing at E-158, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the old house was constructed in the year 1965 (Figure-12.406) which has been renovated in the year 2000 and presently ten members are living in these houses.

Petitioner No. 184	
	
Residential Building	

Figure-12.406: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.16. Petitioner No.185: Smt. Gangamma aged about 57 years W/o Muniyappa residing at 12-1, Makali, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor (Figure-12.407). While carrying out the ground verification the petitioners house was locked as per the information collected from the neighbours presently four members are living in these houses.

Petitioner No. 185	
Residential House	

Figure-12.407: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.17. Petitioner No. 202: Smt. B. Gowramma aged about 56 years W/o R. Nagendra residing at 97, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the site allotted by the Government under the Janata Niveshana Yojane Scheme in the year 1990 (Figure-12.408) and presently ten members are living in these houses.

Petitioner No. 202	
Residential House	

Figure-12.408: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.18. Petitioner No.227: Sri. Bylanjanappa aged about 55 years S/o L.E. Muniarasappa residing at 80-3, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1982 (Figure-12.409) and presently three members are living in the house.

Petitioner No. 227	
Residential House	



Figure-12.409: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.19. Petitioner No.266: Sri. S. Raju aged about 53 years S/o L.E. Siddappa residing at 01, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in the existing site. During the interaction with the petitioner it was found that the building was constructed in the year 2001 (Figure-12.410) and presently three members are living in the house.

Petitioner No. 266	
Residential House	

Figure-12.410: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.20. Petitioner No.267: Sri. Marappa aged about 53 years S/o Dodda Yalagappa residing at 51, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the site allotted by the Government under the Janata Niveshana Yojane Scheme in the year 1996 (Figure-12.411) and presently eight members are living in these houses.

Petitioner No. 267	
Residential House	

Figure-12.411: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.21. Petitioner No.281: Smt. Sharadamma aged about 52 years W/o L.E Das T. S. residing at 121, Makali, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2003 (Figure-12.412) and presently twelve members are living in these houses.

Petitioner No. 281	
Residential House	

Figure-12.412: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.22. Petitioner No.282: Sri. Byregowda aged about 52 years S/o Chenna Byraiah residing at E 170, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth survey it was found that G+1 building along with one shop have been constructed and further it was found that first floor was having a post office. During the interaction with the petitioner it was found that the building was constructed in the year 1998 (Figure-12.413) and presently two members are living in the house.

Petitioner No. 282	
Residential Building along with the shop	

Figure-12.413: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.23. Petitioner No.303: Smt. Munilakshmamma aged about 51 years W/o H. N. Gangadharaiah residing at #C-216, Alur Road, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building along with shops have been constructed and further it was found that building was having three houses and four shops i.e. ground and first floor having two shops each. During the interaction with the petitioner it was found that the building was constructed in the year 1990 (Figure-12.414) and presently a total of ten members are living in these houses.

Petitioner No. 303	
Residential Building along with the shops	

Figure-12.414: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.24. Petitioner No.305: Sri. G. K. Lakshmana aged about 51 years S/o Kempanna residing at 106, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that five houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1984 (Figure-12.415) and presently a total of twenty six members are living in these houses.

Petitioner No. 305	
Residential House	

Figure-12.415: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.25. Petitioner No.306: Sri. G. Parvathi aged about 51 years S/o S. P. Gurumurthy residing at E 217, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth survey it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the old house was constructed in the year 1975 (Figure-12.416) which has been renovated in the year 1996 and presently seven members are living in the house.

Petitioner No. 306	
Residential House	

Figure-12.416: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.26. Petitioner No.335: Sri. R. Bhaskar aged about 50 years S/o Ramarao residing at E-76, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the site allotted by the Government under the Janata Niveshana Yojane Scheme in the year 1982 (Figure-12.417) and presently three members are living in the house.

Petitioner No. 335	
Residential House	

Figure-12.417: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.27. Petitioner No.338: Sri. K.H. Ravi aged about 50 years S/o Huchhappa residing at E-10, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth survey it was found that G+1 building along with one shop has been constructed and further it was found that the building was having four houses. During the interaction with the petitioner it was found that the building was constructed in the year 2005 (Figure-12.418) and presently a total of fifteen members are living in these houses.

Petitioner No. 338	
Residential Building along with a shop	

Figure-12.418: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.28. Petitioner No.339: Sri. Jayalakshmamma aged about 50 years S/o Muniyappa residing at 142-6, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth survey it was found that four houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2001 (Figure-12.419) in the inherited land and presently twelve members are living in these houses.

Petitioner No. 339	
Residential House	

Figure-12.419: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.29. Petitioner No.353: Sri. M. Anand aged about 26 years S/o Marayya residing at E-18, Prabhanagar, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth survey it was found that the three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the houses were constructed in the year 2005 (Figure-12.420) and presently three families with a total of fifteen members are living in these houses.

Petitioner No. 353	
Residential House	

Figure-12.420: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.30. Petitioner No.384: Sri. Ramanjinappa aged about 49 years S/o Ellappa residing at 36, Makali, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that the old house which was built in 1961 was demolished and foundation has been laid down for construction of new house (Figure-12.421).

Petitioner No. 384	
Foundation laid for construction	

Figure-12.421: GPS location of the petitioner site (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.31. Petitioner No.399: Sri. Jaganath aged about 48 years S/o Ramu residing at #415, Makali, Dasanapura Hobli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth survey it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 2001 (Figure-12.422) and also the house was having borewell. Presently four members are living in the house.

Petitioner No. 399	
Residential Building	

Figure-12.422: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.32. Petitioner No.408: Sri. Ramanjaneya aged about 25 years S/o Ningappa residing at E-20, Prabhanagar, Makali, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth survey it was found that single house has been constructed in the ground floor (Figure-12.423). While carrying out the survey the petitioner's house was locked and as per the information collected from the neighbours the house has been constructed in the site allotted by the Government under the Ashraya Yojane Scheme and presently five members are living the house.

Petitioner No. 408	
Residential House	

Figure-12.423: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.33. Petitioner No.423: Sri. Kemparaju aged about 47 years S/o Hanumanthappa residing at 8-2, Prabhanagara, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that four houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the houses were constructed in the site allotted by the Government under the Ashraya Yojane Scheme in the year 2000 (Figure-12.424) and presently a total of twelve members are living these houses.

Petitioner No. 423	
Residential House	

Figure-12.424: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.34. Petitioner No.472: Sri. Nagesh aged about 24 years S/o Muniraju residing at E-18, Prabhanagar, Makali, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor (Figure-12.425). While carrying out the ground verification the petitioners house was locked.

Petitioner No. 472	
Residential House	

Figure-12.425: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.35. Petitioner No.498: Sri. Bhagyamma aged about 45 years S/o Ramachandraiah residing at E-267, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that four houses have been constructed in the ground floor and further it was found that the petitioner has rented out the houses. During the interaction with the tenant it was found that the houses have been constructed in the year 1985 (Figure-12.426) and presently four members are living these houses.

Petitioner No. 498	
Residential House	

Figure-12.426: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.36. Petitioner No.527: Sri. H. S. Mahabalesh aged about 44 years S/o Singappa Gowda residing at E-288, Makali, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that the building was having seven houses (Figure-12.427). During the interaction with the petitioner it was found that presently a total of twenty two members are living these houses.

Petitioner No. 527	
Residential Building	

Figure-12.427: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.37. Petitioner No.532: Sri. Shashikala aged about 43 years S/o Shivaraj residing at 15-8, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two individual houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the houses were constructed in the site allotted by the Government under the Janata Niveshana Yojane Scheme in the year 1982 (Figure-12.428) and presently five members are living in the houses.

Petitioner No. 532	
Residential Building	

Figure-12.428: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.38. Petitioner No.533: Sri. Rajanna aged about 43 years S/o Thimmayyappa residing at 9, Prabhanagar, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the site allotted by the Government under the Aharaya Yojane Scheme in the year 1990 (Figure-12.429) and presently five members are living in the house.

Petitioner No. 533	
Residential House	

Figure-12.429: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.39. Petitioner No.534: Smt. Shylaja aged about 43 years W/o Jayanna residing at 121, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building along with a shop has been constructed in the existing site. During the interaction with the petitioner it was found that the building has been constructed in the year 2002 (Figure-12.430) and presently eight members are living in the house.

Petitioner No. 534	
Residential Building along with a shop	

Figure-12.430: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.40. Petitioner No.535: Sri. Ramaiah aged about 43 years S/o Muninarsaiah residing at Makali, Dasanapura Hobli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth survey it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1982 (Figure-12.431) in the site allotted by the Government under the Janatha Niveshana Yojane and presently three families are living these houses.

Petitioner No. 535	
Residential House	

Figure-12.431: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

2.8.41. Petitioner No.536: Smt. Jayamma aged about 43 years W/o Late. Hanumantharayappa residing at 522/1, Makali, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth survey it was found that G+1 building has been constructed and further it was found that the building was having seven house. During the interaction with the petitioner it was found that the building was constructed in the year 2005 (Figure-12.432) and presently thirty members are living in these houses.

Petitioner No. 536	
Residential Building	

Figure-12.432: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.42. Petitioner No.537: Sri. Mudalagiriyappa aged about 43 years S/o Late. Thimmaiah residing at E-26, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house along with two shops have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the site allotted by the Government under the Janata Niveshana Yojane Scheme in the year 1982 (Figure-12.433) and presently four members are living in the house.

Petitioner No. 537	
Residential House along with two shops	

Figure-12.433: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.43. Petitioner No.538: Smt. G. Nagarathna aged about 43 years W/o V. Muthuraju residing at 96-1, Makali, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth survey it was found that the site was vacant (Figure-12.434).

Petitioner No. 538	
Vacant Site	

Figure-12.434: GPS location of the petitioners vacant site (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.44. Petitioner No.539: Sri. B. Krishna aged about 43 years S/o Late. Bailanjinappa residing at E-146, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the houses were constructed in the year 1992 (Figure-12.435) and presently ten members are living in these houses.

Petitioner No. 539	
Residential House	

Figure-12.435: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.45. Petitioner No.564: Sri. M. Nagaraju aged about 42 years S/o Marappa residing at 5-2, Prabhanagara, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the site allotted by the Government under the Ashraya Yojane Scheme in the year 1990 (Figure-12.436) and presently five members are living in the house.

Petitioner No. 564	
Residential House	

Figure-12.436: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.46. Petitioner No.*565*: Sri. Ashwath Reddy aged about 42 years S/o Sanjiv Reddy residing at E 104, Makali, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that the foundation has been laid the existing site (Figure-12.437).

Petitioner No. *565*	
Vacant Site	

Figure-12.437: GPS location of the petitioner site (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.47. Petitioner No.569: Sri. Poojarangamma aged about 42 years S/o L. Kariyappa residing at 26, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the site allotted by the Government under the Janata Niveshana Yojane Scheme in the year 1992 (Figure-12.438) and presently ten members are living in these houses.

Petitioner No. 569	
Residential House	

Figure-12.438: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.48. Petitioner No.*595*: Smt. Lilavathi aged about 41 years W/o Mallikarjun residing at E-250, Makali, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+2 building has been constructed and further it was found that the building was having ten houses. During the interaction with the petitioner it was found that the building was constructed in the year 2005 (Figure-12.439) and presently twenty two members are living in these houses.

Petitioner No. *595*	
Residential Building	

Figure-12.439: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.49. Petitioner No.596: Sri. Narasingh aged about 41 years S/o Bhavanisingh residing at E-100, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building along with the shop has been constructed and further it was found that the building was having twenty houses. During the interaction with the petitioner it was found that the old house that was constructed in the year 1953 (Figure-12.440) has been renovated in the year 1995 and presently twenty families are living in these houses.

Petitioner No. 596	
Residential Building along with a shop	

Figure-12.440: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.50. Petitioner No.598: Sri. Arun Kumar aged about 41 years S/o Krishnappa residing at 5, Makali, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that the building was having four houses. During the interaction with the petitioner it was found that the house has been constructed in the year 2002 (Figure-12.441) and presently a total of sixteen members are living in these houses.

Petitioner No. 598	
Residential Building	

Figure-12.441: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.51. Petitioner No.664: Smt. Anjinamma aged about 39 years W/o Late Rajanna residing at 1, Prabhanagara, Makali, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2004 (Figure-12.442) and presently a total of seven members are living in these houses.

Petitioner No. 664	
Residential House	

Figure-12.442: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.52. Petitioner No.665: Smt. Anusuya aged about 39 years W/o Chandrahas residing at # 141-2, Makli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+2 building has been constructed (Figure-12.443) and further it was found that the buildings was having six houses and presently thirty members are living in these houses.

Petitioner No. 665	
Residential Building	



Figure-12.443: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.53. Petitioner No.666: Sri. H. M. Mayigowda aged about 39 years S/o Madegowda residing at 112-1, Makali, Bangalore North, Bangalore Urban District – 562 123.

Petitioner No.736: Smt. H. P. Veena aged about 36 years W/o N. Udayakumar residing at #3, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that G+2 building has been constructed and also building was having eleven houses (Figure-12.444). During the interaction with the petitioner it was found presently a total of 40 members are living in these houses.

Petitioner No. 666 and 736	
Residential Building	

Figure-12.444: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.54. Petitioner No.695: Smt. Leelabai, aged about 38 years, W/o Venugopal, residing at E 362, Makali, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the old house which was constructed in the year 1985 (Figure-12.445) has been renovated in the year 2005 and presently four members are living in the house.

Petitioner No. 695	
Residential House	

Figure-12.445: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.55. Petitioner No.796: Sri. Hanumaiah aged about 34 years S/o Hanumanthara Yappa residing at E-04, Prabhanagar, Makali, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that four houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1973 (Figure-12.446) and presently a total of fifteen members are living in these houses.

Petitioner No. 796	
Residential House	

Figure-12.446: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.56. Petitioner No.798: Smt. Shakunthala aged about 34 years W/o Vhikkaswamy residing at 138, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth survey it was found that G+1 building along with three shops have been constructed and further it was found that the building was having five houses. During the interaction with the petitioner it was found that the building was constructed in the year 2002-03 (Figure-12.447) and presently five families with a total of thirty members are living in these houses.

Petitioner No. 798	
Residential Building along with shops	

Figure-12.447: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.57. Petitioner No.864: Sri. Lokesh aged about 31 years S/o Gowramma residing at E-11, Prabhanagar, Makali, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth survey it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2007 (Figure-12.448) in the site allotted by the Government under the Ashraya Yojane Scheme and presently two families with a total of seven members are living in these houses.

Petitioner No. 864	
Residential House	

Figure-12.448: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.58. Petitioner No.865: Sri. Viramaregowda aged about 31 years S/o Ramaiah residing at #E 54, Makali, Dasanapura Hobli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1982 (Figure-12.449) and presently a total of five members are living in these houses.

Petitioner No. 865	
Residential House	

Figure-12.449: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Makali Village

12.8.59. Unidentified Cases: In the village of Makali out of 68 cases 60 residential houses cases were identified and remaining 08 properties pertaining to the cases that could not be identified are given below:

1. **Petitioner No.179:** Sri. Ravi Shankar aged about 28 years S/o Hanumantharayappa residing at #17/1, Makali, Bangalore North, Bangalore Urban District – 562 123.
2. **Petitioner No.287:** Sri. Lakshmibai aged about 27 years S/o Late. Mohan Singh residing at E-315, Makali, Bangalore North, Bangalore Urban District – 562 123.
3. **Petitioner No.337:** Sri. D. Ramesh aged about 50 years S/o Dhandapani residing at 86, Makali, Bangalore North, Bangalore Urban District – 562 123.
4. **Petitioner No.383:** Sri. Chandrappa aged about 49 years S/o Krishnappa residing at E237, Makali, Bangalore North, Bangalore Urban District – 562 123.
5. **Petitioner No.443:** Sri. Govindraju Aged about 46 Years S/o Lakshminarayana residing At 330, Makali, Bangalore North, Bangalore Urban District – 562 123.
6. **Petitioner No.671:** Smt. G. Hemavathi aged about 30 years W/o R. Lakshman residing at E288, Makali, Bangalore North, Bangalore Urban District – 562 123.
7. **Petitioner No.747:** Sri. N. Thimmaiah aged about 30 years S/o Narasimhalah residing at #126, Maruthi Nursing Home Road, Makali, Bangalore North, Bangalore Urban District - 562 123.
8. **Petitioner No.776:** Sri. G. Prakash aged about 30 years S/o Hucha Gangayya residing at E-195, Makali, Bangalore North, Bangalore Urban District – 562 123.

12.9. Heggadadevanapura Villages:

Heggadadevanapura village is coming under the jurisdiction of Alur Gram Panchayat and as per the 2011 census, the Heggadadevanapura village has an area of 1.81 Sq.Km. with population of 4,820 and 1,254 households. The Heggadadevanapura village falls in the Zone-3 and 4 of the Arkavathi river stretch of the TGR catchment area (Figure-12.450).

Figure-12.450: Location of the Heggadadevanapura village in Zone-3 and 4 of Arkavathi river course (Source – NPA)

In the Heggadadevanapura village, 67 cases are filed (Annexure-12.9) and during the ground verification it was found that in few cases two to three petitions have been filed by the members of the same family *i.e.* father and son or husband and wife etc. The ground truth verification revealed that few of the residential houses have been constructed in 1945, 1970's and it was found that after 80's and 90's many houses have come-up and more intensively after 2000. At present many houses are renovated adding 1-2 floors and in few cases are being used as commercial shops which are rented out for income generation. Further, it was found that most of the houses have been constructed in Gramathana and also in the survey No. 12, 13, 15, 16, 37, 38, 39 and 40. Whereas it was found that most of the houses have been constructed in the inherited land, revenue sites and few of the houses have been constructed in the recently developing layouts. 99% of the petitioners submitted electricity bills as a substantiation document during the residential houses field verification.

While interacting with the petitioners it was found that the Gram Panchayat supplying water through borewells and mini water supply and in few cases it was found that the houses were having borewells. Some of the general observations include sewage discharge into pit, grey water discharge into to open drain, no proper solid waste management (disposed into nearby vacant-land), open drain sanitation and accessibility to road. There has been rapid growth of the population (Figure-12.451) and also increase in the number of households (Figure-12.452) in the Heggadadevanapura village. The main reasons behind this rapid growth are proximity to BBMP area, NH-4 passing (Bengaluru–Tumakuru Road) through the village and also job opportunities.

During the ground verification, out of 67 cases 53 residential houses cases were identified and remaining 14 houses could not be identified (Figure-12.453). The local people and the persons accompanying the ground truth exercise expressed inability to locate these addresses. Further, a written statement (PANCHANAMA) was written in the presence of all the members of the committee i.e. EMPRI staff, two representatives of the petitioners and local people of the village along with their signatures. Panchanama of the ground verification of the

residential superstructure is annexed in the Annexure-12.2. The current status of each of the identified petitioners houses in the Heggadadevanapura village are discussed below:



Figure-12.451: Population trend in the Heggadadevanapura village



Figure-12.452: Households statistics in the Heggadadevanapura village



Figure-12.453: Field verification status

12.9.1. Petitioner No.7: Sri. Ramaiah aged about 78 years S/o Chikkaveerappa residing at 24, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in the existing site. During the interaction with the petitioner it was found that the building was constructed in the year 1946 (Figure-12.454) and further which has been renovated in the year 2005 and presently ten members are living in the house.

Petitioner No. 07	
Residential Building	

Figure-12.454: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.2. Petitioner No.8: Sri. Govindappa aged about 78 years S/o Kempahanumaiah residing at 72, Heggadadevanapura, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity and paid house tax bill

Remarks: During the ground truth verification it was found that single house has been constructed in an area of (15'x53'). During the interaction with the petitioner it was found that the house was constructed 100 years back (Figure-12.455) in the inherited land and presently six members are living in the house.

Petitioner No. 08	
Residential House	

Figure-12.455: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.3. Petitioner No.21: Sri. Channappa aged about 73 years S/o Kemahanumaiah, residing at 74, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Petitioner No.688: Sri. Ashwathanarayana aged about 39 years S/o Channappa residing at 74, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that single house has been constructed in an area of (16'x31'). During the interaction with the petitioner it was found that after demolition of the 75 years old house the new house has been constructed in the year 2005 (Figure-12.456) and presently six members are living in the house.

Petitioner No. 21 and 688	
Residential House	

Figure-12.456: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.4. Petitioner No.36: Sri. H. M. Veeranna aged about 70 years S/o Muddubyrappa residing at 85, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that duplex building has been constructed. During the interaction with the petitioner it was found that the building has been constructed in the year 2014 (Figure-12.457). Presently six members are living in the house.

Petitioner No. 36	
Residential Building	

Figure-12.457: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.5. Petitioner No.37: Sri. Gangappa aged about 70 years S/o Huchhappa residing at 31, Heggadasevanapura, Bangalore North, Bangalore Urban District – 562 123.

Petitioner No.105: Sri. Bhyamma aged about 63 years W/o Ganganna residing at 31, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that two individual buildings have been constructed in the existing site i.e. G+1 and single house in the ground floor. During the interaction with the petitioner it was found that the buildings were constructed in the year 1984 (Figure-12.458) and presently two families with a total of eight members are living in these houses.

Petitioner No. 37 & 105	
Residential Building	

Figure-12.458: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.6. Petitioner No.38: Sri. Veeradasappa aged about 70 years S/o Bylappa residing at 103, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Petitioner No.60: Smt. Hobakka aged about 68 years W/o Veeradasappa residing at 79, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1960 (Figure-12.459) and presently five members are living in the house.

Petitioner No. 38 &60	
Residential House	

Figure-12.459: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.7. Petitioner No.58: Sri. Thimmappa aged about 68 years S/o Ramaiah residing at 77, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building along with a shop has been constructed and further it was found that the building was having five houses. During the interaction with the petitioner it was found that the house was constructed in the year 2000 (Figure-12.460) and presently fifteen members are living in these houses.

Petitioner No. 58	
Residential Building along with a shop	

Figure-12.460: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.8. Petitioner No.59: Sri. Anjinappa aged about 68 years S/o Gangappa residing at 27, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1950 (Figure-12.461) and presently two members are living in the house.

Petitioner No. 59	
Residential House	

Figure-12.461: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.9. Petitioner No.76: Sri. Narayanappa aged about 66 years S/o Chikkaveerappa residing at 26, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building has been constructed and it was found that the building was having four houses. During the interaction with the petitioner it was found that the building was constructed in the year 2007 (Figure-12.462) and presently a total of 12 members are living in these houses.

Petitioner No. 76	
Residential Building	

Figure-12.462: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.10. Petitioner No.104: Sri. Krishnappa aged about 63 years S/o Muddegowda residing at 20, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two buildings have been constructed *i.e.* G+1 and one ground floor building and further it was found that building was having five houses (Figure-12.463). During the interaction with the petitioner it was found that the buildings was constructed in the inherited land in an area of (40'x61') and presently five families with a total of thirty members are living in these houses.

Petitioner No. 104	
Residential Building	

Figure-12.463: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.11. Petitioner No.106: Sri. Bailamma aged about 63 years S/o Thimmappa residing at 77, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth inspection it was found that G+1 building along with one shop has been constructed and further it was found that the building was having nine houses. During the interaction with the petitioner it was found that the house was constructed in the year 1980 (Figure-12.464) and presently a total of fifty one members are living in these houses.

Petitioner No. 106	
Residential Building along with a shop	

Figure-12.464: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.12. Petitioner No.107: Sri. Bailappa aged about 63 years S/o Veeradasappa residing at 87, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Petitioner No.247: Smt. Hemakshamma aged about 55 years S/o Ballappa residing at 87, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth inspection it was found that two petitions have been filed by the members of the same family and further it was found that duplex house has been constructed. During the interaction with the petitioner it was found that the house has been constructed in the year 2014 (Figure-12.465) and presently five members are living in the house.

Petitioner No. 107 and 247	
Duplex House	

Figure-12.465: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.13. Petitioner No.135: Sri. H. A. Gopinath aged about 29 years S/o Ananthamurthy residing at 158B, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+2 building has been constructed and further it was found that the building was having seven houses. During the interaction with the petitioner it was found that the house was constructed in the year 2006 (Figure-12.466) and presently a total of 27 members are living in these houses.

Petitioner No. 135	
Residential Building	

Figure-12.466: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.14. Petitioner No.139: Sri. H.N. Dinesh aged about 29 years S/o H. Narayanappa. residing at Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the old house which was constructed in the year 1960 (Figure-12.467) has been renovated in the year 2000. Further the house is coming under the Gramthana and presently five members are living in the house.

Petitioner No. 139	
Residential Building	

Figure-12.467: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.15. Petitioner No.140: Sri. H. B. Nagesh aged about 29 years S/o Bailappa residing at 87, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two shops have been constructed in the ground floor. During the interaction with the petitioner it was found that the shop was constructed in the year 1985 (Figure-12.468).

Petitioner No. 140	
Commericial Shops	

Figure-12.468: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.16. Petitioner No.148: Sri. Andanappa aged about 60 years S/o Chikkirappa residing at 29, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1984 (Figure-12.469) in the inherited land and presently three members are living in the house.

Petitioner No. 148	
Residential House	

Figure-12.469: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.17. Petitioner No.165: Smt. N. Shashikala aged about 29 years W/o Narayanaswamy residing at 71, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (19'x30'). During the interaction with the petitioner it was found that the old house has been renovated in the year 2010 (Figure-12.470) and presently five members are living in the house.

Petitioner No. 165	
Residential Building	

Figure-12.470: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.18. Petitioner No.166: Sri. M. Siddaramaiah aged about 58 years S/o Muddegowda residing at 154, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed (Figure-12.471). While carrying out the ground verification the petitioner house was locked.

Petitioner No. 166	
Residential Building	

Figure-12.471: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.19. Petitioner No.198: Sri. Manuraju aged about 57 years S/o Chikkamaheshwaraiah residing at 160, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building along with three commercial shops have been constructed in an area of (30'x40'). During the interaction with the petitioner it was found that the building was constructed in the year 2005 (Figure-12.472) in the inherited land and presently three families with a total of ten members are living in these houses.

Petitioner No. 198	
Residential Building with commerical shops	

Figure-12.472: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.20. Petitioner No.199: Sri. H. N. Manjappa aged about 57 years S/o Nanjundappa residing at 48, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+2 building has been constructed and further it was found that the first floor having three houses and second floor having one room. During the interaction with the petitioner it was found that the building was constructed in the year 2009 (Figure-12.473) and presently seven members are living in these houses.

Petitioner No. 199	
Residential Building	

Figure-12.473: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the

12.9.21. Petitioner No.261: Sri. Arasappa aged about 54 years S/o Hanumantappa residing at E -7, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1998 (Figure-12.474). Further the house is coming in the Gramthana and presently six members are living in the house.

Petitioner No. 261	
Residential House	

Figure-12.474: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.22. Petitioner No.265: Smt. Lila aged about 28 years W/o Ramesha residing at E-221, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that six houses along with two commercial shops have been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2003 (Figure-12.475) and presently thirty six members are living in these houses.

Petitioner No. 265	
Residential House along with the commerical shops	

Figure-12.475: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.23. Petitioner No.273: Sri. B. T. Nandana aged about 28 years S/o Shivaharasamma residing at # 222, behind Govt. School, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in the Byraveshwara layout. During the interaction with the petitioner it was found that the house has been constructed in the year 2012 (Figure-12.476) and presently seven members are living in the house.

Petitioner No. 273	
Residential House	

Figure-12.476: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.24. Petitioner No.276: Smt. Lakshmamma aged about 53 years residing at #115, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses along with a shop (flour mill) have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1965 (Figure-12.477) and presently three members are living in these houses.

Petitioner No. 276	
Residential House along with a shop	

Figure-12.477: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.25. Petitioner No.278: Sri. H. R. Krishnappa aged about 53 years S/o Ramaiah residing at 32, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two individual buildings i.e. G+1 and single house has been constructed and further it was found that the building was having ten houses (Figure-12.478). During the interaction with the petitioner it was found that the houses have been constructed in the inherited land. Presently forty members are living in these houses.

Petitioner No. 278	
Residential Building	

Figure-12.478: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.26. Petitioner No.279: Smt. Jayamma aged about 53 years W/o Venkataramaiah residing at 30, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1970 (Figure-12.479) and presently a total of thirteen members are living in these houses.

Petitioner No. 279	
Residential House	

Figure-12.479: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.27. Petitioner No.302: Sri. K. S. Mani aged about 52 years S/o Krishna residing at Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth inspection it was found that six houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the old house was constructed in the year 1998 (Figure-12.480) which has been renovated in the year 2002 and presently a total of thirty members are living in these houses.

Petitioner No. 302	
Residential House	

Figure-12.480: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.28. Petitioner No.332: Sri. M. Chandrashekar aged about 51 years S/o Muddegowda residing at 155, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+2 building along with the two shops have been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 2005 (Figure-12.481) and presently eight members are living in these houses and also it was found that the house was having a borewell.

Petitioner No. 332	
Residential Building along with two shops	

Figure-12.481: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.29. Petitioner No.345: Sri. Cha. J. Devaraju aged about 27 years S/o Gangaramayya residing at E-60, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building along with two shops have been constructed and further it was found that the building was having six houses. During the interaction with the petitioner it was found that the old house which has been renovated in the year 2005 (Figure-12.482) and presently a total of thirty five members are living in these houses.

Petitioner No. 345	
Residential Building along with the shops	

Figure-12.482: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.30. Petitioner No.379: Smt. Bhagyamma aged about 50 years W/o Ganganna residing at 82, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor (Figure-12.483). While carrying out the ground truth verification the petitioners house was locked.

Petitioner No. 379	
Residential House	

Figure-12.483: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.31. Petitioner No.420: Smt. Siddagangamma aged about 48 years W/o Arasappa residing at 2, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that four houses along with a shop have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1984 (Figure-12.484) and presently eighteen members are living in these houses.

Petitioner No. 420	
Residential House along with a shop	

Figure-12.484: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.32. Petitioner No.422: Sri. Muddegowda aged about 48 years S/o Veeradasappa residing at 102, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in the existing site. During the interaction with the petitioner it was found that the house was constructed in the year 2005 (Figure-12.485) and presently a total of seven members are living in these houses.

Petitioner No. 422	
Residential Building	

Figure-12.485: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.33. Petitioner No.468: Sri. S. Veeregowda aged about 46 years S/o H. G. Siddappa residing at 45, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1975 (Figure-12.486) and presently six members are living in the house.

Petitioner No. 468	
Residential House	

Figure-12.486: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.34. Petitioner No.475: Sri. N. Uday Kumar aged about 45 Years S/o T. N. Narasimhaiah. residing at #162, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that the single building has been constructed in the ground floor and presently using for the commercial purpose i.e. manufacture of bakery products and distributing to all the bakeries. During the interaction with the petitioner it was found that the building was constructed in the year 1999 (Figure-12.487) and currently three to five employees are working in the unit and it was also found that the building was having borewell.

Petitioner No. 475	
Commercial Building	

Figure-12.487: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.35. Petitioner No.499: Sri. Ramakrishnappa aged about 45 years S/o Maheshwarappa residing at 82, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that building was having five houses. During the interaction with the petitioner it was found that the house was constructed in the year 1999 (Figure-12.488) and presently twenty members are living in these houses.

Petitioner No. 499	
Residential Building	

Figure-12.488: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.36. Petitioner No.500: Sri. Eshvarayya aged about 45 years S/o Chikkamaheshwariah residing at 160A, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor and further it was found that among the two houses one of the house was vacant. During the interaction with the petitioner it was found that the house was constructed in the year 1974 (Figure-12.489) and presently four members are living in the house.

Petitioner No. 500	
Residential House	

Figure-12.489: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.37. Petitioner No.501: Sri. B. Ashwathaiah aged about 45 years S/o Byregowda residing at Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 1990 (Figure-12.490) in the inherited land. Further it was found that the house was having two borewells and presently eight members are living in the house.

Petitioner No. 501	
Residential Building	

Figure-12.490: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.38. Petitioner No.502: Smt. Pushpalatha aged about 45 years W/o S. Janardhan residing at near Tapovana, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. While carrying out the ground verification the petitioners house was locked and as per the information collected from the neighbours the house was constructed in the year 2013 (Figure-12.491) and presently four members are living in the house.

Petitioner No. 502	
Residential House	

Figure-12.491: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.39. Petitioner No.524: Sri. M. Nagaraju. aged about 44 years S/o Mahalingappa residing at No.162, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Petitioner No.525: Sri. M. Narasimhamurthy aged about 44 years S/o Mahalingappa residing at 162, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of same family and further it was found that two individual buildings have been constructed i.e. G+1 building and other building partitioned into two houses. During the interaction with the petitioner it was found that the buildings were constructed in the year 1991 (Figure-12.492) and 1998 in inherited land in an area of (120'x80'). Presently, three families with a total of eleven members are living in these houses.

Petitioner No. 524 and525	
Residential Buildings	

Figure-12.492: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.40. Petitioner No.529: Sri. Ramachandra aged about 44 years S/o Veeradasappa residing at 79, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth inspection it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1995 (Figure-12.493) in an area of (40'x15') and presently a total of twelve members are living in these houses.

Petitioner No.529	
Residential House	

Figure-12.493: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.41. Petitioner No.593: Smt. Shanthamma aged about 42 years W/o H. T. Jayaraju residing at 104, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (80'x60'). During the interaction with the petitioner it was found that the building was constructed in the year 2006 (Figure-12.494) and presently, three members are living in the house.

Petitioner No. 593	
Residential Building	

Figure-12.494: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.42. Petitioner No.635: Sri. Shiva Shankara aged about 41 years S/o Narayanappa residing at Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 2011 (Figure-12.495) and presently five members are living in the house.

Petitioner No.635	
Residential Building	

Figure-12.495: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.43. Petitioner No.636: Sri. Bheemaraju aged about 41 years S/o Maheshwaraiah residing at 182, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that building was having eight houses. During the interaction with the petitioner it was found that the building has been constructed in the year 2009 (Figure-12.496) and presently a total of twenty seven members living in these houses and also it was found that the house was having borewell.

Petitioner No. 636	
Residential Building	

Figure-12.496: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.44. Petitioner No.662: Sri. Basavaraju aged about 40 year S/o. Annadanappa, residing at 21, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+2 building has been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 2005 (Figure-12.497) and presently a total of ten members are living in these houses.

Petitioner No. 662	
Residential Building	

Figure-12.497: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.45. Petitioner No.766: Sri. H. G. Ramachandrappa aged about 36 years S/o Galappa residing at 26, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+2 building has been constructed in an area of 100′x40′. While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours the house has been constructed in the year 1995 (Figure-12.498) and presently five members are living in the house.

Petitioner No. 766	
Residential Building	

Figure-12.498: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.46. Petitioner No.820: Sri. H. B. Vanajakshamma aged about 34 years D/o Bailappa residing at 87, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that the building was having five houses. During the interaction with the petitioner it was found that the building was constructed in the year 1991 (Figure-12.599) and presently a total of thirty members are living in these houses.

Petitioner No.820	
Residential Building	

Figure-12.499: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.47. Petitioner No.822: Smt. Girija aged about 34 years W/o Muddegowda residing at 79, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours the house has been constructed in the year 1995 (Figure-12.500) and presently four members are living in the house.

Petitioner No. 822	
Residential House	

Figure-12.500: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.48. Petitioner No.860: Sri. M. Basavaraju aged about 32 years S/o Marulasiddaiah residing at Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor (Figure-12.501). During the interaction with the petitioner it was found that the house was constructed in an area of (30'x40') and presently six members are living in these houses.

Petitioner No. 860	
Residential House	

Figure-12.501: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Heggadadevanapura Village

12.9.49. Unidentified Cases: In the village of Heggadadevanapura out of 67 cases 53 residential houses cases were identified and remaining 14 properties pertaining to the cases that could not be identified are given below:

1. **Petitioner No.10:** Smt. H. A. Mahalakshmi aged about 39 years W/o Ramachandra residing at 79, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.
2. **Petitioner No.176:** Sri. G. Chandra Shekar aged about 29 years S/o Ganganna residing at 82, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.
3. **Petitioner No.277:** Smt. Gangamma aged about 53 years W/o Venkatappa residing at No 140, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.
4. **Petitioner No.377:** Sri. H. Muniraju aged about 50 years S/o Huchhaiah residing at Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.
5. **Petitioner No.400:** Smt. C. Lakshmi aged about 48 years W/o Basavaraju residing at #82, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.
6. **Petitioner No.438:** Smt. Bhagya aged about 47 years W/o Jayaram residing at #121 Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.
7. **Petitioner No.553:** Sri. M. Mahesh aged about 24 years S/o Mahadeva residing at 75, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.
8. **Petitioner No.560:** Smt. R. Pushpa aged about 43 years W/o C. Manju residing At #28, police layout, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.
9. **Petitioner No.561:** Smt. Susheela aged about 43 years W/o Subramaniyan residing at Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.
10. **Petitioner No.634:** Sri. A. G. Murthy aged about 41 years S/o Thimamma residing at Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.
11. **Petitioner No.670:** Sri. B. R. Manjula aged about 30 years S/o G. Chandrashekar residing at 221, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.
12. **Petitioner No.765:** Sri. Venkatesha aged about 36 years S/o Thimmayya residing at # E- 7, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.
13. **Petitioner No.790:** Sri. N. Girisha aged about 31 years residing at #12, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.
14. **Petitioner No.862:** Smt. A. Vimalah aged about 32 years W/o Venkatesh residing at 02, Heggadadevanapura, Bangalore North, Bangalore Urban District – 562 123.

12.10. Madanayakanahalli Village:

Madanayakanahalli village is coming under the jurisdiction of Madanayakanahalli Gram Panchayat and as per the 2011 census the village has an area of 2.28 Sq.Km. with population of 12,563 and 3,452 households. The Madanayakanahalli village falls in the Zone-3 and 4 of the Arkavathi river stretch of the TGR catchment area (Figure-112.502).

In the Madanayakanahalli village, 50 cases are filed (Annexure-12.10) and during the ground verification in few cases it was found that two to three cases have been filed by members of one family *i.e.* father and son or husband and wife etc. The ground truth verification revealed that few of the residential houses were constructed in 80's and 90's and it was found that after 2000 many houses have come-up. At present many houses are renovated adding 1 floor to 2 floors and in few cases they are being used as commercial shops which are rented out for income generation. Further, it was found that majority of the houses have been constructed in the survey no. 44. Further, the ground verification revealed that most of the houses have been constructed in the revenue sites and also few of the houses constructed in the developing layouts. 99% of the petitioners submitted electricity bill as a substantiation document during the residential houses field verification.



Figure-12.502: Location of the Madanayakanahalli village in the Zone-3 and 4 of Arkavathi river course (Source - NPA)

While interacting with the petitioners it was found that the Gram Panchayat is supplying water through borewells and mini water supply. Some of the general observations include sewage discharge into pit, grey water discharge into open drain, solid waste management by the Gram Panchayat, open drain sanitation and accessibility to road. There has been rapid growth of the population (Figure-12.503) and number of households (Figure-12.504) in the Madanayakanahalli village. The main reasons behind this rapid growth are proximity to BBMP area, NH-4 passing (Bengaluru – Tumakuru Road) through the village and also job opportunities.

During ground truth verification, out of 50 cases 42 residential houses cases could be identified and remaining 09 houses could not be identified (Figure-12.505). Pertaining to the addresses involving unidentified residential houses, it was found that few owners have sold their houses and few of the houses are rented out and relocated to the other places. Further, a written statement (PANCHANAMA) was written in the presence of all the members of the committee i.e. EMPRI staff, two representatives of the petitioners and local people of the village along with their signatures. Panchanama of the ground verification of the residential

superstructure is annexed in the Annexure-12.2. The current status of each identified petitioners residential houses in the Madanayakanahalli village are discussed below;



Figure-12.503: Population trend in the Madanayakanahalli village



Figure-12.504: Households statistics in the Madanayakanahalli village



Figure-12.505: Field verification status

12.10.1 . Petitioner No.69: Sri. Ramachandrabhat aged about 66 years S/o Ganesh Bhat residing at 609, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Petitioner No. 210: Sri. Vedavathi aged about 56 years S/o Ramachandrabhat residing at 609, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that two Petitions have been filed by the members of the same family and further it was found that single house has been constructed in the ground floor (Figure-12.506). During the interaction with the petitioner it was found that presently four members are living in the house.

Petitioner No. 69 and 210	
Residential House	

Figure-12.506: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.2. Petitioner No.86: Sri. G. Krishnamurthy aged about 64 years residing at Shreshakthi, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1990 (Figure-12.507) and presently five members are living in the house.

Petitioner No. 86	
Residential House	

Figure-12.507: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.3. Petitioner No.89: Smt. Lakshmamma Aged about 64 Years W/o Ramakrishnappa residing at 591, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that the building was having six houses. During the interaction with the petitioner it was found that the building has been constructed in the year 1990 (Figure-12.508) and presently sixteen members are living in these houses.

Petitioner No. 89	
Residential Building	

Figure-12.508: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.4. Petitioner No.119: Smt. Rukkamma aged about 62 years W/o P. Nataraju residing at 645, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that building was having three houses. During the interaction with the petitioner it was found that the old house that was constructed in the year 1999 (Figure-12.509) has been renovated in the year 2010 and presently a total of ten members are living in these houses.

Petitioner No. 119	
Residential Building	

Figure-12.509: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.5. Petitioner No.125: Sri. Jayalakshmee aged about 61 years W/o Krishnamurthy residing at 610, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of 30'x40'. During the interaction with the petitioner it was found that the building has been constructed in the year 2002 (Figure-12.510) and presently sixteen members are living in these houses and it was also found that the house was having borewell.

Petitioner No. 125	
Residential Building	

Figure-12.510: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.6. Petitioner No.155: Smt. Gayathramma aged about 59 years W/o Arjunappa residing at 614, Bheemeshwaranagar, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2001 (Figure-12.511) and presently four members are living in the house.

Petitioner No. 155	
Residential House	

Figure-12.511: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.7. Petitioner No.209: Sri. Ramyayya aged about 56 years S/o L.E. Venkatappa residing at 578, Bheemeshwaranagar, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor (Figure-12.512). During the interaction with the petitioner it was found that presently a total of three members are living in these houses.

Petitioner No. 209	
Residential House	

Figure-12.512: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.8. Petitioner No.211: Sri. G. S. Nanjappa aged about 56 years S/o Siddalingappa residing at 460-2, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that G+1 building along with a shop has been constructed in an area of (18′x25′) and further it was found that the building was having three houses. During the interaction with the petitioner it was found that the house was constructed in the year 2002 (Figure-12.513) and presently a total of twelve members are living in these houses.

Petitioner No. 211	
Residential Building along with a shop	

Figure-12.513: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.9. Petitioner No.212: Sri. Thangaraj aged about 56 years S/o L.E. Ramaswami Raj residing at 473, Bheemeshwaranagar, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that the building was having four houses. During the interaction with the petitioner it was found that the building was constructed in the year 2002 (Figure-12.514) and presently a total of sixteen members are living in these houses.

Petitioner No. 212	
Residential Building	

Figure-12.514: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.10. Petitioner No.235: Smt. Bharathi aged about 55 years W/o H.S. Rameshababu residing at # 56, Bheemeshwaranagar, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of 30'x40'. During the interaction with the petitioner it was found that the building was constructed in the year 1990 (Figure-12.515) and presently a total of eight members are living in these houses.

Petitioner No. 235	
Residential Building	

Figure-12.515: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.11. Petitioner No.260: Smt. G. Kalavathi aged about 54 years W/o D.R. Gandhi residing at # 490, Bheemeshwaranagar, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 1996 (Figure-12.516) and presently a total of six members are living in these houses.

Petitioner No. 260	
Residential Building	

Figure-12.516: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.12. Petitioner No.262: Sri. Narayan No. 261 aged about 54 years S/o Nanjundappa residing at 600, Bheemeshwaranagar, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that the building was having four houses in an area of 30′x40′. During the interaction with the petitioner it was found that the house was constructed in the year 2005 (Figure-12.517) and presently a total of sixteen members are living in these houses.

Petitioner No. 262	
Residential House	

Figure-12.517: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.13. Petitioner No.271: Sri. Thotappa aged about 53 years S/o Late Siddappa residing at Bheemeshwaranagar, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 30′x40′. During the interaction with the petitioner it was found that the building was constructed in the year 1995 (Figure-12.518) and presently six members are living in the house.

Petitioner No. 271	
Residential House	

Figure-12.518: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.14. Petitioner No.291: Smt. Shyamala aged about 52 years W/o Yuvarayan residing at 507, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (30'x40'). During the interaction with the petitioner it was found that the building was constructed in the year 1990 (Figure-12.519) has been renovated and presently five members are living in these houses.

Petitioner No. 291	
Residential Building	

Figure-12.519: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.15. Petitioner No.301: Smt. Raje Gowda aged about 52 years W/o Lingegowda residing at 476-1, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that G+3 building has been constructed in an area of (60′x40′) and further it was found that the building was having nine houses. During the interaction with the petitioner it was found that the building was constructed in the year 2007 (Figure-12.520) and presently a total of twenty members are living in these houses.

Petitioner No.301	
Residential Building	

Figure-12.520: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.16. Petitioner No.357: Sri. Shrikantha Bhat aged about 50 years S/o Surynarayana Bhat residing at 734, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (30′x40′) and further it was found that building was having three houses. During the interaction with the petitioner it was found that the building was constructed in the year 2005 (Figure-12.521) and presently a total of ten members are living in these houses.

Petitioner No.357	
Residential Building	

Figure-12.521: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.17. Petitioner No.358: Smt. Revathi aged about 50 years W/o Lakshmana Kekundara residing at 521, Bheemeshwaranagar, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1995 (Figure-12.522) and presently three members are living in the house.

Petitioner No.358	
Residential House	

Figure-12.522: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.18. Petitioner No.380: Sri. R. B. Rudre Gowda aged about 50 years S/o Late Basanna Patel residing at #27, Bheemeshwaranagar, Near Ganesha Temple, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1995 (Figure-12.523) and presently six members are living in these houses.

Petitioner No.380	
Residential House	

Figure-12.523: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.19. Petitioner No.406: Smt. Sharadamma aged about 48 years W/o Veerupakasayya residing at 485-2, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the houses was constructed in the year 2000 (Figure-12.524) and presently a total of six members are living in these houses.

Petitioner No.406	
Residential House	

Figure-12.524: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.20. Petitioner No.412: Smt. Nandini aged about 48 years W/o Panchakshraiah residing at 21, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that the building was having seven houses. During the interaction with the petitioner it was found that the building was constructed in the year 1997 (Figure-12.525) and presently a total of twenty two members are living in these houses.

Petitioner No.412	
Residential Building	

Figure-12.525: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.21. Petitioner No.421: Sri. Surendrasingh aged about 48 years S/o Ajeez Singh residing at #88, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that duplex house has been constructed in an area of (40′x40′). During the interaction with the petitioner it was found that the house was constructed in the year 1990 (Figure-12.526) and presently eight members are living in the house.

Petitioner No.421	
Residential Building	

Figure-12.526: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.22. Petitioner No.432: Sri. R. Karunanidhi aged about 47 years S/o M.S. Ramaswamy residing at No. 3, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that G+2 building has been constructed in an area of 15'x40'. During the interaction with the petitioner it was found that the building was constructed in the year 1995 (Figure-12.527) and presently a total of ten members are living in these houses.

Petitioner No. 432	
Residential Building	

Figure-12.527: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.23. Petitioner No.437: Smt. M. N. Rathnamma aged about 47 years W/o A. Srinivasamurhty residing at 56/3, 3rd Cross Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building along with shop has been constructed and further it was found that building was having two houses in the first floor and two shops in the ground floor. During the interaction with the petitioner it was found that the building was constructed in the year 2005 (Figure-12.528) and presently two families with a total of seven members are living in these houses.

Petitioner No.437	
Residential Building along with the shops	

Figure-12.528: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.24. Petitioner No.439: Sri. Sohan Singh aged about 47 years S/o Lalraja Ram residing at 613, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the building that was constructed in the year 1990 (Figure-12.529) has been renovated in the year 2010 and presently eight members are living in these houses.

Petitioner No.439	
Residential Building	



Figure-12.529: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.25. Petitioner No.465: Smt. M. Rathnamma aged about 46 years W/o Ramakrishnappa residing at 500, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1991 (Figure-12.530) and presently eleven members are living in these houses.

Petitioner No.465	
Residential House	

Figure-12.530 GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.26. Petitioner No.466: Smt. N. Siddagangamma aged about 46 years W/o S.C. Bailappa residing at #550, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building along with a shop has been constructed and further it was found the building was having four houses. During the interaction with the petitioner it was found that the building was constructed in the year 1995 (Figure-12.531) and presently a total of ten members are living in these houses.

Petitioner No.466	
Residential Building along with a shop	

Figure-12.531: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.27. Petitioner No.467: Sri. Pavan Kumar aged about 46 years S/o Gnansingh residing at 622, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in an area of (30′x40′). During the interaction with the petitioner it was found that the house was constructed in the year 1990 (Figure-12.532) and presently five members are living in the house.

Petitioner No.467	
Residential House	

Figure-12.532: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.28. Petitioner No.469: Sri. L. R. Jayarama aged about 46 years S/o K. Ramaiah residing at E-124, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building along with the shops have been constructed in an area of (100′x100′) and it was found that the building was having thirteen houses and three shops. During the interaction with the petitioner it was found that the building was constructed in the year 2006 (Figure-12.533) and presently a total of forty members are living in these houses.

Petitioner No.469	
Residential Building along with the shops	



Figure-12.533: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.29. Petitioner No.487: Sri. Chidambaram aged about 45 years S/o Late Ayyapillai residing at 522F, Bheemeshwaranagar, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2006 (Figure-12.534) and presently four members are living in the house.

Petitioner No.487	
Residential House	

Figure-12.534: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.30. Petitioner No.496: Sri. S. Shrimathi aged about 45 years S/o B.A. Srinivas residing at 629A, Bheemeshwaranagar, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building has been constructed in an area of (60'x40') and further it was found that the building was having sixteen houses. During the interaction with the petitioner it was found that the building was constructed in the year 2003 **(**Figure-12.535**)** and presently a total of fifty members are living in these houses.

Petitioner No.496	
Residential Building	

Figure-12.535: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.31. Petitioner No.497: Sri. N. Nagarajaiah aged about 45 years S/o Narasimhaih residing at # 105, 5th Cross, Vinayakanagar, Madanayakanahalli, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor in an area of (30'x40'). While carrying out the ground verification the petitioners house was locked and as per the information collected from the neighbours the house was constructed in the year 2010 (Figure-12.536) and presently seven members are living in these houses.

Petitioner No.497	
Residential House	

Figure-12.536: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.32. Petitioner No.515: Sri. R.R. Sharma aged about 44 years S/o Baburam Sharma residing at 489, Madanayakanahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 1995 (Figure-12.537) and presently a total of twelve members are living in the houses.

Petitioner No.515	
Residential Building	

Figure-12.537: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.33. Petitioner No.614: Sri. Devaraju aged about 41 years S/o Kempaiah residing at 120, Madanayakanahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor (Figure-12.538). While carrying out the ground truth verification the petitioner house was locked.

Petitioner No.614	
Residential House	

Figure-12.538: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.34. Petitioner No.615: Sri. A. M. Ganganna aged 41 years residing at 513, Madanayakanahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that the building was having five houses. During the interaction with the petitioner it was found that the building was constructed in the year 1990 (Figure-12.539) and presently a total of 20 members are living in these houses.

Petitioner No.615	
Residential Building	

Figure-12.539: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.35. Petitioner No.661: Smt. Jayalakshmi aged about 40 years W/o Honnegowda residing at Madanayakanahalli, Bheemeshwaranagar, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that the building was having nine houses. During the interaction with the petitioner it was found that the building was constructed in the year 2003 (Figure-12.540) and presently a total of thirty members are living in these houses.

Petitioner No. 661	
Residential Building	

Figure-12.540: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.36. Petitioner No.700: Smt. Nagaratnamma aged about 38 years W/o Lakshmaiah residing at 276-2, Madanayakanahalli, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1995 (Figure-12.541) and presently five members are living in these houses.

Petitioner No.700	
Residential House	

Figure-12.541: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.37. Petitioner No.706: Sri. Sumashekhara aged about 38 years S/o Gangadharappa residing at 468/4, Madanayakanahalli-3, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor (Figure-12.542). While carrying out the ground truth verification the petitioners house was locked.

Petitioner No.706	
Residential House	

Figure-12.542: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.38. Petitioner No.708: Sri. L. C. Veeresh aged about 30 years S/o Chandrappa residing at #12, Bheemeshwaranagar, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house which was constructed in the year 1990 (Figure-12.543) has been renovated in the year 2010 and presently eight members are living in these houses.

Petitioner No.708	
Residential House	

Figure-12.543: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.39. Petitioner No.764: Sri. Bhajan Singh aged about 36 years S/o Parushuram Singa residing at # 592, Bheemeshwaranagar, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed (Figure-12.544). While carrying out the ground truth verification the petitioners house was locked.

Petitioner No.764	
Residential Building	

Figure-12.544: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.40. Petitioner No.783: Smt. Saroja aged about 35 years W/o Krishnamurthi residing at 626, Bheemeshwaranagar, Madanayakanahalli-3, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor in an area of (20′x40′). During the interaction with the petitioner it was found that the house was constructed in the year 1990 (Figure-12.545) and presently eight members are living in these houses.

Petitioner No.783	
Residential House	

Figure-12.545: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.41. Petitioner No.870: Smt. Yashodha Bai aged about 51 W/o. Anantharamasingh residing at 562, Madanayakanahalli, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building along with a shop has been constructed in an area of 30′x40′ and further it was found that the building was having three houses. During the interaction with the petitioner it was found that the building was constructed in the year 2001 (Figure-12.546) and presently eight members are living in these houses.

Petitioner No.870	
Residential Building along with a shop	

Figure-12.546: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Madanayakanahalli Village

12.10.42. Unidentified Cases: In the village of Madanayakanahalli out of 50 cases 42 residential houses cases was identified and remaining 08 properties pertaining to the cases that could not be identified are given below:

1. **Petitioner No.126:** Sri. Lakshmamma aged about 61 years S/o Venkataramanna residing at 534a, Bheemeshwaranagar, Madanayakanahalli-3, Bangalore North, Bangalore Urban District – 562 123.
2. **Petitioner No.136:** Sri. Hanumantharav aged about 60 years S/o Danojirao residing at Lakshmipura, Bangalore North, Bangalore Urban District – 562 123.
3. **Petitioner No.160:** Smt. Sunila Kumar aged about 59 years W/o Prabhukumar residing at 620, Bheemeshwaranagar, Madanayakanahalli-3, Bangalore North, Bangalore Urban District – 562 123.
4. **Petitioner No.195:** Smt. Pushpalatha aged about 28 years W/o Krishnamurthi residing at #621, Bheemeshwaranagar, Madanayakanahalli, Bangalore North, Bangalore Urban District – 562 123.
5. **Petitioner No.295:** Smt. K.P. Girija aged about 27 years W/o K.K. Gangadhara residing at #298, 1st Main, Madanayakanahalli, Bangalore North, Bangalore Urban District – 562 123.
6. **Petitioner No.577:** Sri. Anantharaju aged about 42 years S/o Chikkakariyappa residing at Lakshmipura Road, Madanayakanahalli, Dasanapura Hobli, Bangalore North, Bangalore Urban District – 562 123.
7. **Petitioner No.749:** Smt. Sharadhamma aged about 36 years W/o Govindaraju residing at 465-1, Madanayakanahalli, Bangalore North, Bangalore Urban District – 562 123.
8. **Petitioner No.808:** Sri. K.R. Suddaraju aged about 34 years S/o Krishnauji Rao residing at 618, Beemeshwaranagar, Madanayakanahalli-3, Bangalore North, Bangalore Urban District – 562 123.

12.11. Kadaranahalli Village:

Kadaranahalli village is coming under the jurisdiction of Madanayakanahalli Gram Panchayat and as per the 2011 census the Kadaranahalli village has an area of 1.71 Sq.Km. with population of 412 and 88 households. The Kadaranahalli village falls in the Zone-3 and 4 of the Arkavathi river stretch of the TGR catchment area (Figure-12.547).



Figure-12.547: Location of the Kadaranahalli village in the Zone-3 and 4 of the Arkavathi river course (Source - NPA)

In the Kadaranahalli village, 35 cases are filed (Annexure-12.11) and during the ground verification it was found that in few cases two to three petitions have been filed by members of one family *i.e.* among brothers or father and son etc. The ground truth verification revealed that few of the residential houses have been constructed in 1952, 60's, 70's, 80's and 90's and it was found that after 2000 few houses have come-up. At present many houses are renovated adding 1-2 floors. Further, it was found that most of the houses have been constructed in the Gramathana and also in the survey No. 2, 4, 19, and 38. Whereas the ground truth verification also witnessed that most of the houses have been constructed in the Gramathana. Most of the houses have been constructed in the inherited land, whereas few of the houses have been constructed in the site allotted by Government under the Rajiv Gandhi Housing Scheme for the economically weaker sections and

few houses have been constructed in the developing layout. 99% of the petitioners submitted electricity bills as a substantiation document during the residential houses field verification.

While interacting with the petitioners it was found that the Gram Panchayat is supplying water through borewells and mini water supply and in few cases it was found that houses were having borewells. Some of the general observations include sewage discharge into pit, grey water discharge into open drain, improper solid waste management (either disposed into nearby vacant land or disposed into their own land), open drain sanitation and accessibility to road. There has been slight growth of the population (Figure-12.548) and also increase in number of households (Figure-12.549) in the Kadaranahalli village.

During the ground truth verification out of 35 cases 32 residential houses could be identified and remaining 03 cases could not be identified (Figure-12.550). Pertaining to the addresses involving unidentified residential houses, the local people and the persons accompanying the ground truth exercise expressed inability to locate these addresses. Further, a written statement (PANCHANAMA) was written in the presence of all the members of the

committee i.e. EMPRI staff, two representatives of the petitioners and local people of the village along with their signatures. Panchanama of the ground verification of the residential superstructure is annexed in the Annexure-12.2. The current status of each of the identified petitioners houses in the Kadaranahalli village are discussed below;



Figure-12.548: Population trend in the Kadaranahalli village



Figure-12.549: Households statistics of the Kadaranahalli village



Figure-12.550: Field verification status

12.11.1. Petitioner No.9: Sri. Gangalakkaiah aged about 77 years S/o Venkatappa, residing at 50, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth survey it was found that single house has been constructed in the ground floor in an area of (30′x40′). During the interaction with the petitioner it was found that the house was constructed in the year 1985 (Figure-12.551) and presently, five members are living in the house.

Petitioner No. 9	
Residential House	

Figure-12.551: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.2. Petitioner No.43: Sri. Ramanjinappa aged about 68 years S/o Jadiyappa residing at 3, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that four houses have been constructed in the ground floor. While carrying out the ground truth verification the petitioner house was locked and as per the information collected from the neighbours the house was constructed in the year 1985 (Figure-12.552) and presently four families with a total of thirteen members are living in these houses.

Petitioner No. 43	
Residential House	

Figure-12.552: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.3. Petitioner No.44: Sri. Channabasappa aged about 68 years S/o Nanjappa residing at 38, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found G+1 building has been constructed in the inherited land. During the interaction with the petitioner it was found that the building was constructed in the year 2011 (Figure-12.553) and presently, fourteen members are living in these houses and it was also found that the house was having a borewell.

Petitioner No. 44	
Residential Building	

Figure-12.553: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.4. Petitioner No.61: Sri. K. S. Basavaraju aged about 67 years S/o Shivanna residing at 24, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Petitioner No.440: Sri. Chandrashekaraiah aged about 46 years S/o Shivanna residing at 19, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1952 (Figure-12.554) and presently, nine members are living in these houses.

Petitioner No. 61 and 440	
Residential House	

Figure-12.554: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.5. Petitioner No.84: Sri. Mahadevappa aged about 64 years S/o Balaiah residing at 10, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of (20′x30′). During the interaction with the petitioner it was found that the house has been constructed in the year 1980 (Figure-12.555) and presently, four members are living in the house.

Petitioner No. 84	
Residential House	

Figure-12.555: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.6. Petitioner No.91: Sri. Rangaiah aged about 63 years S/o Ranganarasaiah residing at 27, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2002 (Figure-12.556) and presently two members are living in the house.

Petitioner No. 91	
Residential House	

Figure-12.556: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.7. Petitioner No.92: Smt. Lakshmamma aged about 63 years W/o Venkatanarasaiah residing at 41, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor (Figure-12.557). While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours the house was renovated in the year1995 and presently seven members are living in the house.

Petitioner No. 92	
Residential House	

Figure-12.557: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.8. Petitioner No.101: Smt. Hanumanarasamma aged about 63 years W/o Hanumanarasimhaiah residing at 12, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor (Figure-12.558). While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours presently two members are living in the house.

Petitioner No. 101	
Residential House	

Figure-12.558: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.9. Petitioner No.108: Sri. Singappa aged about 62 years S/o Narasaiah residing at 35, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two individual houses have been constructed in the ground floor and further it was found that one of the house have been vacant. During the interaction with the petitioner it was found that the houses have been constructed in the year 1965 (Figure-12.559) and presently, ten members are living in the house.

Petitioner No. 108	
Residential House	

Figure-12.559: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.10. Petitioner No.120: Sri. Arasaiah aged about 61 years S/o Venkatappa residing at 48, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1975 (Figure-12.560) in the site allotted by Government under Rural Housing Scheme and presently, two members are living in the house

Petitioner No. 120	
Residential House	

Figure-12.560: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.11. Petitioner No.131: K.P. Sri. Siddagangaiah aged about 60 years S/o Puttasiddappa residing at 25, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1972 (Figure-12.561) and presently three members are living in the house.

Petitioner No. 131	
Residential House	

Figure-12.561: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.12. Petitioner No.132: Sri. Adaveeshaiah aged about 60 years S/o Shivanna residing at 43, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the house was constructed in the year 1975 (Figure-12.562) and presently, five members are living in the house.

Petitioner No. 132	
Residential Building	



Figure-12.562: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.13. Petitioner No.161: Sri. D. L. Channabasavaiah aged about 58 years S/o Lingannappa residing at 1, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (78'x30'). During the interaction with the petitioner it was found that the house was constructed in the year 1990 (Figure-12.563) in the DC converted layout and presently, five members are living in the house.

Petitioner No. 161	
Residential Building	

Figure-12.563: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.14. Petitioner No.162: Smt. Lakshminarasamma aged about 58 years W/o Venkatahanumaiah residing at 25, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1975 (Figure-12.564) in the site allotted by Government under Rajiv Gandhi Housing Scheme and presently, six members are living in the house.

Petitioner No. 162	
Residential House	

Figure-12.564: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.15. Petitioner No.163: Sri. Manthaiah aged about 58 years S/o Channappa residing at 34, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1975 (Figure-12.565) in the inherited property and presently, five members are living in the house.

Petitioner No. 163	
Residential House	

Figure-12.565: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.16. Petitioner No.200: Sri. Ramachandramurthy aged about 56 years S/o Venkataswamaiah residing at 30, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1985 (Figure-12.566) and presently, four members are living in the house.

Petitioner No. 200	
Residential House	



Figure-12.566: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.17. Petitioner No. 263: Smt. P. Subbalakshmi aged about 53 years W/o H.K. Raghoththam residing at 187, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor of an area of (60'x40'). During the interaction with the petitioner it was found that the house has been constructed in the year 1988 (Figure-12.567) and presently, five members are living in the house.

Petitioner No. 263	
Residential House	

Figure-12.567: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.18. Petitioner No.280: Sri. Bailavenkataiah aged about 52 years S/o Venkatappa residing at 53, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of (30'x40'). During the interaction with the petitioner it was found that the house has been constructed in the year 1975 (Figure-12.568) in the site allotted by Government under Rajiv Gandhi Housing Scheme and presently ten members are living in the house.

Petitioner No. 280	
Residential House	

Figure-12.568: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.19. Petitioner No.395: Sri. Krishnamurty aged about 48 years S/o Gangaiah residing at 54, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1994 (Figure-12.569) in the site allotted by Government under Rajiv Gandhi Housing Scheme and presently, nine members are living in the house.

Petitioner No. 395	
Residential House	



Figure-12.569: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.20. Petitioner No.405: Smt. Chandramma aged about 48 years W/o Chandrappa residing at 20, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Petitioner No.562: Smt. Sujatha aged about 42 years W/o Eshwarappa residing at 18, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Petitioner No.823: Sri. S. Chandrashekaraiah aged about 33 years S/o Siddagangaiah residing at #44, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found three petitions have been filed by members of the same family and further it was found that three individual houses have been constructed in the ground floor. During the interaction with the petitioners it was found that the houses have been constructed in the year 1965 (Figure-12.570) in the inherited land. Presently, three families and a total of ten members are living in these houses.

Petitioner No. 405,562 and 823	
Residential House	

Figure-12.570: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.21. Petitioner No.531: Smt. Vishalamma aged about 43 years W/o Mahadevappa residing at 26, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (31'x21.5'). During the interaction with the petitioner it was found that the building has been constructed in the year 2013-14 (Figure-12.571) and presently, four members are living in the house and it was also found that the house was having a borewell.

Petitioner No. 531	
Residential Building	

Figure-12.571: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.22. Petitioner No.563: Smt. Rathnamma aged about 42 years W/o Muniramaiah residing at 51, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of (30'x40'). During the interaction with the petitioner it was found that the old house which was constructed in the year 1965 (Figure-12.572) has been renovated in the year 2014 and presently three members are living in the house.

Petitioner No. 563	
Residential House	



Figure-12.572: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.23. Petitioner No.582: Sri. K.P. Narasimhamurthy aged about 42 years S/o Puttanarasimhaiah residing at 15, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that seven houses have been constructed in the ground floor in an area of (51'x38'). During the interaction with the petitioner it was found that the house was constructed in the year 1999 (Figure-12.573) and presently, seven families with a total of thirty four members are living in these houses.

Petitioner No. 582	
Residential House	

Figure-12.573: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.24. Petitioner No.594: Sri. Munnarasaiah aged about 41 years S/o Ramaiah residing at 33, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two individual houses have been constructed in the ground floor (Figure-12.574). During the interaction with the petitioner it was found that the houses have been constructed 100 years back in the inherited land and presently, nine members are living in these houses.

Petitioner No. 594	
Residential House	

Figure-12.574: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.25. Petitioner No.637: Sri. Srinivasa about 40 years S/o Narasappa residing at 63, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2010 (Figure-12.575) in the inherited land and presently, five members are living in the house.

Petitioner No. 637	
Residential House	

Figure-12.575: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.26. Petitioner No.689: Sri. K. R. Muddireshaiah aged about 38 years S/o Rajashekaraiah residing at 39, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2005 (Figure-12.576) and presently, five members are living in the house.

Petitioner No. 689	
Residential House	

Figure-12.576: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.27. Petitioner No.767: Sri. Ravikumar aged about 35 years S/o Gangaiah residing at 54B, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District - 562123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours the house has been constructed in the year 2013 (Figure-12.577) and presently five members are living in the house.

Petitioner No. 767	
Residential House	

Figure-12.577: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.28. Petitioner No.782: Sri. Revanasiddappa aged about 30 years S/o Rajanna residing at 2, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of (43'x35'). During the interaction with the petitioner it was found that the house has been constructed in the year 1990 (Figure-12.578) in the DC converted layout and presently, nine members are living in the house.

Petitioner No. 782	
Residential House	

Figure-12.578: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.29. Petitioner No.863: Smt. Lakshmamma aged about 31 years W/o Muniraju residing at 60, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 2011 (Figure-12.579) in the inherited land and presently, four members are living in the house.

Petitioner No. 863	
Residential House	

Figure-12.579: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kadaranahalli Village

12.11.30. Unidentified Cases: In the village of Kadaranahalli out of 35 cases 32 residential houses cases were identified and remaining 04 properties pertaining to the cases that could not be identified are given below:

1. **Petitioner No.109:** Smt. Narasamma aged about 62 years W/o Narasappa residing at 63, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District – 562 123.

2. **Petitioner No.441:** Smt. R. Sowbhagya aged about 46 years W/o Ramachandraiah residing at 3, Kadaranahalli, Bangalore North, Bangalore Urban District – 562 123.

3. **Petitioner No.530:** Sri. Narasimhamurthy aged about 43 years S/o Narasimhaiah residing at 63, Kadaranahalli, Lakshmipura-2, Bangalore North, Bangalore Urban District – 562 123.

12.12. Lakshmipura Village:

Lakshmipura village is coming under the jurisdiction of Madanayakanahalli Gram Panchayat and as per the census the village has an area of 4.06 Sq.Km. with the population of 1,895 and 454 households. The Lakshmipura village falls in the Zone–3, 4 and 1 of the Arkavathi river stretch of the TGR catchment area (Figure-12.580).

In the Lakshmipura village, 24 cases are filed (Annexure-12.12) and during the ground truth verification it was found that the many houses have come-up more intensively after 2000 and it was found that most of the houses have been constructed in the survey No. 101, 102 and 104. Further it was found that most of the houses constructed in the revenue sites and also many houses constructed in the developing layouts.



Figure-12.580: Location of the Lakshmipura village in the Zone-3, 4 and 1 of Arkavathi river course (Source – NPA)

While interacting with the petitioners it was found that the Gram Panchayat is supplying water through borewells and mini water supply and it was also found that few of the houses were having borewells. Some of the general observations include sewage discharge into pit, grey water discharge into open drain, improper solid waste management (disposed into nearby vacant-land), open drain sanitation and accessibility to road. There has been slight growth of the population (Figure-12.581) and also in number of households (Fig-12.582) in the Lakshmipura village.

During the ground truth verification of 24 cases 17 residential houses could be identified and remaining 07 cases could not be identified (Figure-12.583). Pertaining to the addresses involving unidentified residential houses, the local people and the persons accompanying the ground truth exercise expressed inability to locate these addresses. Further, a written statement (PANCHANAMA) was written in the presence of all the members of the committee i.e. EMPRI staff, two representatives of the petitioners and local people of the village along with their signatures. Panchanama of the ground verification of the residential superstructure is annexed in the Annexure-12.2. The current status of each of the identified petitioners houses in the Lakshmipura village are discussed below:



Figure-12.581: Population trend in the Lakshmipura village



Figure-12.582: Households statistics of the Lakshmipura village



Figure-12.583: Field verification status

12.12.1. Petitioner No.33: Sri. Ramachandrachari aged about 70 years S/o Gopalachari residing at E-283, Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2006 (Figure-12.584) and presently, six members are living in the house.

Petitioner No. 33	
Residential House	

Figure-12.584: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Lakshmipura Village

12.12.2. Petitioner No.151: Sri. Natarajan aged about 59 years S/o Krishnappa residing at #297, Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of (30'x40'). During the interaction with the petitioner it was found that the house was constructed in the year 2014 (Figure-12.585) and presently, five members are living in the house.

Petitioner No. 151	
Residential House	

Figure-12.585: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Lakshmipura Village

12.12.3. Petitioner No.201: Smt. Nandini aged about 28 years W/o Lokesh residing at Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that G+1 building along with one shop (Figure-12.586) has been constructed in an area of (30'x40'). While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours presently four members are living in the house.

Petitioner No. 201	
Residential Building along with a shop	

Figure-12.586: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Lakshmipura Village

12.12.4. Petitioner No.232: Sri. Ramegowda aged about 55 years S/o Giriyamma residing at No.1, Rajeshwari Layout, Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that G+3 building has been constructed in an area of (30'x40') and further it was found that the building was having six houses. During the interaction with the petitioner it was found that the building has been constructed in the year 2000 (Figure-12.587) and presently, a total of twenty members are living in these houses and also it was found that the house was having borewell.

Petitioner No. 232	
Residential Building	

Figure-12.587: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Lakshmipura Village

12.12.5. Petitioner No.310: Sri. R. Raju aged about 51 years S/o Rangaiah residing at #26, Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours the house has been constructed in the year 2007 (Figure-12.588) and presently, four members are living in the house.

Petitioner No. 310	
Residential House	

Figure-12.588: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Lakshmipura Village

12.12.6. Petitioner No.429: Sri. Kullegowda aged about 47 years S/o Singarigowda residing at Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that G+2 building has been constructed and further it was found that building was having seven houses. During the interaction with the petitioner it was found the building was constructed in the year 2013 (Figure-12.589) in an area of (30'x40') and presently a total of 20 members are living in these houses.

Petitioner No. 429	
Residential Building	

Figure-12.589: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Lakshmipura Village

12.12.7. Petitioner No.481: Smt. Mayamma aged about 45 years W/o Thimayya residing at No.184, Rajeshwarinagar, Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours, the house has been constructed in the year 2010 (Figure-12.590).

Petitioner No. 481	
Residential House	

Figure-12.590: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Lakshmipura Village

12.12.8. Petitioner No.545: Sri. Shivashankar aged about 43 years S/o Siddappa residing at Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found first floor was used for godown purpose. During the interaction with the petitioner it was found that the house was constructed in the year 2007 (Figure-12.591).

Petitioner No. 545	
	
Residential cum Commericial	

Figure-12.591: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Lakshmipura Village

12.12.9. Petitioner No.606: Sri. Gnanashekhara aged about 41 years S/o Ranganathachari residing at E-281, Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (30'x40'). During the interaction with the petitioner it was found that the building was constructed in the year 2004 (Figure-12.592) and presently six members are living in the house and it was also found that the house was having borewell.

Petitioner No. 606	
Residential Building	

Figure-12.592: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Lakshmipura Village

12.12.10. Petitioner No.627: Sri. H. Manjunatha aged about 41 years S/o Hanumantharayappa residing at Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that duplex house has been constructed in an area of (15'x40') in the Rajeshwarinagara layout. During the interaction with the petitioner it was found that the house was constructed in the year 2015 (Figure-12.593) and presently, four members are living in the house.

Petitioner No. 627	
Duplex House	

Figure-12.593: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Lakshmipura Village

12.12.11. Petitioner No.697: Smt. T. G. Uma aged about 38 years W/o G.C. Ramesh residing at Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that G+1 building along with shop has been constructed in an area of (60'x40'). While carrying out the ground truth verification the petitioners house was locked and as per the information collected from the neighbours the house has been constructed in the year 2006 (Figure-12.594) and presently four members are living in the house.

Petitioner No. 697	
Residential Building along with a shop	

Figure-12.594: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Lakshmipura Village

12.12.12. Petitioner No.710: Smt. M. S. Jyothi aged about 30 years W/o B. Ramaiah residing at # 109, Rajeshwarinagar, Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (30'x40') and further it was found that the building was having three houses. During the interaction with the petitioner it was found that the building has been constructed in the year 2010 (Figure-12.595) and presently a total of fourteen members are living in theses houses.

Petitioner No. 710	
Residential Building	

Figure-12.595: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Lakshmipura Village

12.12.13. Petitioner No.717: Sri. Gangaraju aged about 37 years S/o Chandrappa residing at #72, Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found G+1 building has been constructed in an area of (30'x40') and further it was found that the building was having three houses (Figure-12.596). While carrying out the ground truth verification the petitioners house was locked.

Petitioner No. 717	
Residential House	

Figure-12.596: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Lakshmipura Village

12.12.14. Petitioner No.771: Smt. Mahadevi aged about 35 years W/o Chandrakanth residing at Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that G+2 building has been constructed and further it was found that the building was having six houses. During the interaction with the petitioner it was found that the building has been constructed in the year 2009 in the Rajeshwarinagar layout (Figure-12.597) and presently twenty five members are living in these houses.

Petitioner No. 771	
Residential Building	

Figure-12.597: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Lakshmipura Village

12.12.15. Petitioner No.803: Smt. Anithalakshmi aged about 34 years W/o G. R. Rajkumar residing at #10, Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found the house has been constructed in the year 2001 in the Rajeshwarinagar layout (Figure-12.598) and presently three members are living in the house.

Petitioner No. 803	
Residential House	

Figure-12.598: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Lakshmipura Village

12.12.16. Petitioner No.866: Sri. Ramakrishna aged about 31 years S/o Ningappa residing at Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2005 (Figure-12.599) and presently, six members are living in the house.

Petitioner No. 866	
Residential House	

Figure-12.599: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Lakshmipura Village

12.12.17. Petitioner No.867: Sri. Lalitha aged about 31 years S/o Ramesh Babu residing at Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. While carrying out the ground truth verification, the petitioner house was locked and the house is constructed in the Rajarajeshwari layout (Figure-12.600).

Petitioner No. 867	
	
Residential House	

Figure-12.600: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Lakshmipura Village

12.12.18. Unidentified Cases: In the Lakshmipura village, out of 24 cases 17 residential houses cases were identified and remaining 07 properties pertaining to the cases that could not be identified are given below:

1. **Petitioner No.230:** Smt. Ganganarasamma aged about 55 years W/o Ramayya residing at Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.
2. **Petitioner No.506:** Sri. Manja Nayak aged about 44 years residing at Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.
3. **Petitioner No.518:** Sri. Srinivasa aged about 44 years S/o Narasinhayya residing at E-323, Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.
4. **Petitioner No.575:** Sri. R. Basavaraju aged about 42 years S/o Malle Gowda residing at Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.
5. **Petitioner No.742:** Sri. Ramakrishna aged about 36 years S/o Narayanappa residing at #130, Rajeshwarinagar, Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.
6. **Petitioner No.839:** Smt. D. N. Suma aged about 33 years W/o B.A. Suresh residing at #20, Maruthi Farm, Near Benaka School, Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.
7. **Petitioner No.846:** Sri. D. K. Manjunatha aged about 32 years S/o Krishnagowda residing at No.124, Lakshmipura, Bangalore North, Bangalore Urban District - 562 123.

12.13. Hanumanthasagara Village:

Hanumanthasagara village is coming under the jurisdiction of Madanayakanahalli Gram Panchayat and as per the 2011 census, the village has an area of 0.45 Sq.Km. with population of 649 and 176 households. The Hanumanthasagara village falls in the Zone-3 of the Arkavathi river stretch of the TGR catchment area (Figure-12.601).



Figure-12.601: Location of the Hanumanthasagara village in the Zone-3 of Arkavathi river course (Source-NPA)

In the Hanumanthasagara village, 20 cases are filed (Annexure-12.13) during the ground verification it was found that in few cases two petitions have been filed by members of one family *i.e.* mother and son etc. The ground truth verification revealed that few of the residential houses have been constructed in 1950, 1965, 80's and 90's and it was found that after 2000 few houses have come-up. At present many houses are renovated adding 1-2 floors. Further, it was found

that most of the houses constructed in the Gramathana and also few houses have been ted in the revenue land. 99% of the petitioners submitted electricity bills as a substantiation document during the residential houses field verification.

While interacting with the petitioner it was found that the Gram Panchayat is supplying water through borewells and mini water supply and it was also found that few of the houses were having borewells. Some of the general observations include sewage discharge into pit, grey water discharge into to open drain, improper solid waste management (either disposing into nearby vacant land or disposed into their own land), open drain sanitation and accessibility to road. There has been rapid growth of the population (Figure-12.602) and number of households (Figure-12.603) in the Hanumanthasagara village. There has been slight growth of the population and number of households in the Hanumanthasagara village.



Figure-12.602: Population trend in the Hanumanthasagara village



Figure-12.603: Households statistics in the Hanumanthasagara village

Further, a written statement (PANCHANAMA) was written in the presence of all the members of the committee i.e. EMPRI staff, two representatives of the petitioners and local people of the village along with their signatures. Panchanama of the ground verification of the residential superstructure is annexed in the Annexure-12.2. During the ground truth verification out of 20 cases 20 residential houses cases were identified and the current status of each identified petitioners residential houses in the Hanumanthasagara village are discussed below:

12.13.1. Petitioner No.1: Sri. P. Ramaiah aged about 87 Years S/o Puttaiah residing at 28/1, Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that building having three houses. During the interaction with the petitioner it was found that after demolition of the old house the new house has been constructed in the year 2008 (Figure-12.604) and presently two families with a total of nine members are living in these houses.

Petitioner No.1	
Residential House	

Figure-12.604: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.13.2. Petitioner No.20: Sri. T. Narayanappa, aged about 73 years, S/o Thimmaiah residing at 43, Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (20'x25') and further it was found that the building was having four houses. During the interaction with the petitioner it was found that the old house which was constructed in the year 1965 (Figure-12.605) has been renovated in the year 2010 and presently a total of thirteen members are living in these houses.

Petitioner No. 20	
Residential Building	

Figure-12.605: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.13.3. Petitioner No.62: Sri. G. Bylappa aged about 67 years S/o Gangamaraiah residing at 183, Hanumanthasagara, Bangalore North Taluk, Bangalore District – 562123

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2003 (Figure-12.606) and presently one family with six members are living in the house.

Petitioner No.62	
Residential House	

Figure-12.606: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.13.4. Petitioner No.80: Smt. Jayamma aged about 65 years W/o Narayanappa residing at 30, Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Petitioner No.452: Sri. Mudda Hanumantha Raju aged about 46 years S/o Narayanappa residing at 51, Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that four houses have been constructed in the ground floor in an area of (38'x30'). During the interaction with the petitioner it was found that the houses were constructed in the year 1986 (Figure-12.607) and presently three families with a total of seventeen members are living in these houses.

Petitioner No.80 and 452	
Residential House	

Figure-12.607: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.13.5. Petitioner No.153: Sri. Mariyappa, aged about 59 years S/o Thimarayappa residing at # 23, Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 20′x30′. During the interaction with the petitioner it was found that the house has been constructed in the year 1999 (Figure-12.608) and presently ten members are living in these houses.

Petitioner No.153	
Residential House	

Figure-12.608: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.13.6. Petitioner No.154: Sri. Sanjevaiah aged about 59 years S /o Veerappa residing at 47, Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of 25′x30′. During the interaction with the petitioner it was found that the house has been constructed in the year 1980 (Figure-12.609) and further it has been renovated in the year 2005. Presently ten members are living in the house.

Petitioner No. 154	
Residential House	

Figure-12.609: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.13.7. Petitioner No.194: Sri. Honnappa aged about 57 years S/o Thopaiah residing at 40, Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1974 (Figure-12.610) and presently one family with five members are living in the house.

Petitioner No. 194	
Residential House	

Figure-12.610: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.13.8. Petitioner No.253: Sri. Chandrashekar aged about 54 years S/o Veerappa residing at 11, Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1955 (Figure-12.611) and presently one family with two members are living in the house.

Petitioner No. 253	
Residential House	

Figure-12.611: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.13.9 . Petitioner No.315: Sri. Ramaiah Aged about 51 Years S/o Thopaiah residing at 48, Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill.

Remarks: During the ground truth verification it was found that two individual buildings have been constructed i.e. G+1 building and four houses in the ground floor and further it was found that three houses have been rented out. During the interaction with the petitioner it was found that the houses have been constructed in the year 2013 (Figure-12.612) and presently four families with a total of fifteen members are living in these houses.

Petitioner No. 315	
Residential Building	

Figure-12.612: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.13.10. Petitioner No.368: Sri. Krishnamurthy aged about 50 years S/o Govindappa residing at 44, Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor in an area of (30'x25'). During the interaction with the petitioner it was found that the house has been constructed in the year 1990 (Figure-12.613) and presently four members are living in these houses.

Petitioner No. 368	
Residential House	

Figure-12.613: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.13.11. Petitioner No.391: Sri. Ramachandraiah aged about 49 Years S/o Thopaiah residing at 49, Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that four houses has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1996 (Figure-12.614) which has been renovated in the year 2012 and presently four families with a total of sixteen members are living in these houses.

Petitioner No. 391	
Residential House	

Figure-12.614: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.13.12. Petitioner No.392: Sri. Hanumaiah aged about 49 years S/o Venkataramanappa residing at #41, Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the house has been constructed in the year 1954 (Figure-12.615) and presently five members are living in the house.

Petitioner No.392	
Residential Building	

Figure-12.615: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.13.13. Petitioner No.411: Sri. Puttarama aged about 48 years S/o Govindappa residing at 44, Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the house was constructed in the year 1965 (Figure-12.616) and presently eight members are living in these houses and it was also found that the house was having a borewell.

Petitioner No.411	
Residential Building	

Figure-12.616: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.13.14. Petitioner No.513: Sri. Venkateswa aged about 44 years S/o Thopaiah residing at 50, Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor and further it was found that among three houses two houses have been rented out. During the interaction with the petitioner it was found that the houses were constructed in the year 1990 (Figure-12.617) and presently three families with a total of fourteen members are living in these houses.

Petitioner No. 513	
Residential House	

Figure-12.617: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.13.15. Petitioner No.514: Sri. H. V. Chandru aged about 44 years S/o Venkatappa residing at 35, Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill.

Remarks: During the ground truth verification it was found that two houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1996 (Figure-12.618) and presently two families with a total of eight members are living in these houses.

Petitioner No. 514	
Residential House	



Figure-12.618: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.13.16. Petitioner No.613: Sri. Janardhana aged about 41 years S/o Muttaiah residing at 39, Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1974 (Figure-12.619) and presently four members are living in the house.

Petitioner No. 613	
Residential House	

Figure-12.619: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.13.17. Petitioner No.647: Smt. Rathnamma aged about 40 years W/o Shnaiah residing at 13, Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 1996 (Figure-12.620) and presently five members are living in the house.

Petitioner No. 647	
Residential House	

Figure-12.620: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.13.18. Petitioner No.709: Sri. Lokesha aged about 38 years S/o Ramaiah residing at 36, Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of (55'x60'). During the interaction with the petitioner it was found that the house was constructed in the year 1950 (Figure-12.621) and presently one family with a total of nine members are living in the house.

Petitioner No.709	
Residential House	

Figure-12.621: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.13.19. Petitioner No.748: Sri. S. Virabhadrappa aged about 36 years S/o Siddappa residing at Hanumanthasagara, Bangalore North, Bangalore Urban District – 562 123.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of (30'x40'). During the interaction with the petitioner it was found that the house was constructed in the year 2010 (Figure-12.622) and presently one family with a total of three members are living in the house.

Petitioner No.748	
Residential House	

Figure-12.622: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hanumathasagara Village

12.14. Kumbarahalli Village:

Kumbarahalli village is coming under the jurisdiction of Kasghattapura Gram Panchayat and as per the 2011 census the village has an area of 1.39 Sq.Km. with population of 1,459 and 357 households. The Kumbarahalli village falls in the Zone-3, 4 and 1 of the Arkavathi river stretch of the TGR catchment area (Figure-12.623).

In the Kumbarahalli village, 19 cases are filed (Annexure-12.14) and ground truth verification revealed that few of the residential houses have been constructed in 1963, 60's, 70's, 80's and 90's and it was found that after 2000 few houses have come-up. At present many houses are renovated adding 1-2 floors. Further, it was found that few of the houses have been constructed in the Gramathana and most of the houses have been constructed in the survey No. 1, 8, 40, 67 and 111. Whereas, the ground truth verification witnessed that, most of the houses have been constructed in the inherited land and in the revenue site. 99% of the petitioners submitted electricity bills as a substantiation document during the residential houses field verification.

Figure-12.623: Location of the Kumbarahalli village in the Zone-3, 4 and 1 of Arkavathi river course (Source-NPA)

While interacting with the petitioners it was found that the Gram Panchayat is supplying water through borewells and mini water supply and it was also found that the few of the houses were having borewells. Some of the general observations include sewage discharge into pit, grey water discharge into open drain, improper solid waste management (either disposed into nearby vacant land or disposed into their own land), open drain sanitation and accessibility to road. There has been slight growth of the population (Fig-12.624) and also number of households (Fig-12.625) in the Kumbarahalli village.

During the ground truth verification out of 19 cases 16 residential houses cases could be identified and remaining 03 cases could not be identified (Figure-12.626). Pertaining to the addresses involving unidentified residential houses, the local people and the persons accompanying the ground truth exercise expressed inability to locate these addresses. Further, a written statement (PANCHANAMA) was written in the presence of all the members of the committee i.e. EMPRI staff, two representatives of the petitioners and local people of the village along with their signatures. Panchanama of the ground verification of the residential superstructure is annexed in the Annexure-12.2.The current status of each identified petitioners residential houses in the Kumbarahalli village are discussed below:



Figure-12.624: Population trend in the Kumbarahalli village



Figure-12.625: Households statistics in the Hanumanthasagara village



Figure-12.626: Details of the Petitioners

12.14.1. Petitioner No.11: Sri. Chikkarevanna, aged about 77 years S/o. Chikkanappa residing at 53, Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in the inherited land. During the interaction with the petitioner it was found that the house has been constructed in the year 1985 (Figure-12.627). Further it was found that the house is coming under Gramathana and presently four members are living in the house.

Petitioner No.11	
Residential House	

Figure-12.627: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kumbarahalli Village

12.14.2. Petitioner No.67: Sri. K. Gangadharappa, aged about 66 years S/o Kempaiah residing at 45, Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (30'x40') and further it was found that the building was having eight houses. During the interaction with the petitioner it was found that the house has been constructed in the year 1985 (Figure-12.628) and presently a total of forty members are living in these houses and also it was found that the house having a borewell.

Petitioner No.67	
Residential Building	

Figure-12.628: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kumbarahalli Village

12.14.3. Petitioner No.75: Sri. Ashwathappa aged about 66 years S/o Chikkavirappa residing at 49, Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in the inherited land. During the interaction with the petitioner it was found that the house has been constructed in the year 1995 (Figure-12.629) and presently six members are living in the house.

Petitioner No.75	
Residential House	

Figure-12.629: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kumbarahalli Village

12.14.4. Petitioner No.100: Sri. V. Thimmegowda aged about 63 years S/o Venkatappa residing at House No.1, Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two building has been constructed in the ground floor in an area of (106'x25'). During the interaction with the petitioner it was found that the old house which was constructed in the year 1975 (Figure-12.630) has been renovated in the year 2014 and presently a total of eleven members are living in these houses.

Petitioner No. 100	
Residential House	

Figure-12.630: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kumbarahalli Village

12.14.5. Petitioner No.111: Sri. Siddappa aged about 62 years S/o Duddarevanna residing at 74, Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1975 (Figure-12.631) and presently fifteen members are living in the house.

Petitioner No.111	
Residential House	

Figure-12.631: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kumbarahalli Village

12.14.6. Petitioner No.130: Sri. Thimmappa aged about 61 years S/o Giriyappa residing at 165, Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed and further it was found that the building was having six houses. During the interaction with the petitioner it was found that the 1963 (Figure-12.632) old house has been demolished and constructed a new building in the year 2015 and presently a total fifteen members are living in the house and also it was found that the house was having borewell.

Petitioner No. 130	
Residential Building	

Figure-12.632: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kumbarahalli Village

12.14.7. Petitioner No.134: Sri. Venkatappa aged about 60 years S/o Chikkahanumayya residing at House No.42, Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1996 (Figure-12.633) and presently five members are living in the house.

Petitioner No. 134	
Residential House	

Figure-12.633: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kumbarahalli Village

12.14.8. Petitioner No.197: Sri. Gangappa aged about 57 years S/o Venkatappa residing at 19, Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor (Figure-12.634). While carrying out the ground truth verification the petitioners house was locked.

Petitioner No. 197	
Residential House	

Figure-12.634: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kumbarahalli Village

12.14.9. Petitioner No.224: Sri. Bailappa aged about 56 years S/o Giriyappa residing at 165, Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.

Petitioner No.374: Smt. Rathnamma aged about 50 years W/o Bailappa residing at house No.165, Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that two petitions have been filed by the members of the same family and further it was found that duplex house has been constructed in the inherited land. During the interaction with the petitioner it was found that the old house which was constructed in the year 1960 (Figure-12.635) has been renovated in the year 2005 and presently six members are living in the house and also it was found that the house was having a borewell.

Petitioner No. 224,374	
Dupex House	

Figure-12.635: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kumbarahalli Village

12.14.10. Petitioner No.275: Sri. Govindaraju aged about 53 years S/o Giriyappa residing at 165, Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in the ground floor. During the interaction with the petitioner it was found that the building has been constructed in the year 1963 (Figure-12.636) and presently five members are living in the house.

Petitioner No. 275	
Residential Building	

Figure-12.636: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kumbarahalli Village

12.14.11. Petitioner No.283: Sri. Govindappa aged about 52 years S/o Ramaiah residing at 18, Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of (30'x36'). During the interaction with the petitioner it was found that the house has been constructed in the year 1985 (Figure-12.637) and presently eight members are living in the house.

Petitioner No.283	
Residential House	

Figure-12.637: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kumbarahalli Village

12.14.12. Petitioner No.583: Sri. Manukumar aged about 21 years S/o Suresh residing at Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (30'x40'). During the interaction with the petitioner it was found that the house has been constructed in the year 2010 (Figure-12.638) and presently a total of ten members are living in the house.

Petitioner No. 583	
Residential Building	

Figure-12.638: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kumbarahalli Village

12.14.13. Petitioner No.601: Sri. Hanumegowda aged about 41 years S/o Thimmaiah residing at 2, Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. While carrying out the ground truth verification the petitioners house was locked as per the information collected from the neighbours the house has been constructed in the year 2013 (Figure-12.639).

Petitioner No.601	
Residential House	

Figure-12.639: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kumbarahalli Village

12.14.14. Petitioner No.691: Sri. G. V. Venkatagiriyappa aged about 29 years S/o Venkatachalappa residing at 255, Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.

Remarks: During the ground truth verification it was found that G+1 building has been constructed. While carrying out the ground truth verification the petitioners house was locked as per the information collected from the neighbours the building has been constructed in the year 2012 (Figure-12.640).

Petitioner No. 691	
Residential Building	

Figure-12.640: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kumbarahalli Village

12.14.15. Petitioner No.826: Sri. Shivakumar aged about 33 years S/o Yallappa residing at 39-B, Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in the inherited land. During the interaction with the petitioner it was found that the house has been constructed in the year 1995 (Figure-12.641). Further it was found that the house is coming in the Gramathana and presently four members are living in the house.

Petitioner No. 826	
Residential House	

Figure-12.641: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Kumbarahalli Village

12.14.16. Unidentified Cases: In the village of Kumbarahalli out of 19 cases 16 residential houses cases were identified and remaining 03 properties pertaining to the cases that could not be identified are given below:

1. **Petitioner No.83:** Sri. Siddappa aged about 65 years S/o Revanna residing at 39, Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.
2. **Petitioner No.188:** Sri. Ballappa aged about 57 years S/o Chikkanna residing at 76, Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.
3. **Petitioner No.600:** Sri. Gangaraju aged about 41 years S/o Anjinappa residing at 9, Kumbarahalli, Bangalore North, Bangalore Urban District – 560 090.

12.15. Bilijaji Village:

Bilijaji village is coming under the jurisdiction of Hurlichikkanhalli Gram Panchayat and as per the 2011 census the village has an area of 1.97 Sq.Km. with population of 840 and 201 households. The Bilijaji village falls in the Zone-3, 4 and 1 of the Arkavathi river stretch of the TGR catchment area (Figure-12.642).

In the Bilijaji village, 13 cases are filed (Annexure-12.15) and the ground truth verification revealed that few of the residential houses have been constructed 100 years back, 70's, 90's and it was found that after 2000 few houses have come-up. At present many houses are renovated adding 1-2 floors. Further, it was found that most of the houses have been constructed in the Gramathana and also in the survey no. 3, 11, 21 and 27. Whereas, the ground truth verification also witnessed that few of the houses have been constructed in the inherited land. 99% of the petitioners submitted electricity bills as a substantiation documents during the residential houses field verification.



Figure-12.642: Location of the Bilijaji village in the Zone-3, 4 and 1 of Arkavathi river course (Source – NPA)

While interacting with the respondent it was found that the Gram Panchayat is supplying water through borewells and mini water supply. Some of the general observations

include sewage discharge into pit, grey water discharge into open drain, improper solid waste management (either disposed into nearby vacant land or disposed into their own land), open drain sanitation and accessibility to road. There has been slight growth of the population (Figure-12.643) and also number of households (Figure-12.644) in the Bilijaji village.

Further, a written statement (PANCHANAMA) was written in the presence of all the members of the committee i.e. EMPRI staff, two representatives of the petitioners and local people of the village along with their signatures. Panchanama of the ground verification of the residential superstructure is annexed in the Annexure-12.2. During the ground truth verification out of 13 cases, all the 13 residential houses cases were identified and the current status of each identified petitioners residential houses in the Bilijaji village are discussed below:



Figure-12.643: Population trend in the Bilijaji village



Figure-12.644: Households statistics in the Bilijaji Village

12.15.1. Petitioner No.6: Smt. Basamma aged about 78 years W/o Munishamayya residing at House No.51, Bilijaji, Bangalore North, Bangalore Urban District – 560 088.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the old house which was constructed in the years1935 has been renovated in the year 2010 (Figure-12.645). Further it was found that the house has been constructed in the Gramathana and presently seven members are living in the house.

Petitioner No. 6	
Residential House	

Figure-12.645: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Bilijaji Village

12.15.2. Petitioner No.25: Sri. Muniraju aged about 72 years S/o Munishamaiah residing at 142, Bilijaji, Bangalore North, Bangalore Urban District – 560 088.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed 100 years back (Figure-12.646). Further it was found that the house has been constructed in the Gramathana and presently thirteen members are living in these houses.

Petitioner No. 25	
Residential House	

Figure-12.646: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Bilijaji Village

12.15.3. Petitioner No.31: Sri. Venkatalakshmayya aged about 71 years S/o Hanumanthaiah residing at 117, Bilijaji, Bangalore North, Bangalore Urban District – 560 088.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single houses has been constructed in the ground floor. During the interaction with the petitioner it was found that the house which was constructed in the year 1975 (Figure-12.647) has been renovated in the year 2005. Further it was found that the house has been constructed in the Gramathana and presently five members are living in the house.

Petitioner No. 31	
Residential House	

Figure-12.647: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Bilijaji Village

12.15.4. Petitioner No.87: Sri. D. Narasimhamurthy aged about 64 years S/o Doddanarasappa residing at 85, Bilijaji, Bangalore North, Bangalore Urban District – 560 088.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed 100 years back (Figure-12.648). Further it was found that the house has been constructed in the Gramathana and presently seven members are living in the house.

Petitioner No. 87	
Residential House	

Figure-12.648: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Bilijaji Village

12.15.5. Petitioner No.115: Smt. Siddagangamma aged about 62 years W/o Basavaraju residing at 136, Bilijaji, Bangalore North, Bangalore Urban District – 560 088.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in the inherited land. During the interaction with the petitioner it was found that the house was constructed in the year 2013 (Figure-12.649) and presently five members are living in the house.

Petitioner No. 115	
Residential Building	

Figure-12.649: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Bilijaji Village

12.15.6. Petitioner No.157: Sri. Venkatalakshmaiah aged about 59 years S/o Doddakempaiah residing at 1/1, Bilijaji, Bangalore North, Bangalore Urban District – 560 088.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor in an area of (22'x35'). During the interaction with the petitioner it was found that the house was constructed in the year 1990 (Figure-12.650) and presently six members are living in the house.

Petitioner No. 157	
Residential House	

Figure-12.650: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Bilijaji Village

12.15.7. Petitioner No.214: Sri. T. Venkateshaiah aged about 56 years S/o Thimmaiah residing at Bilijaji, Bangalore North, Bangalore Urban District – 560 088.

Remarks: During the ground truth verification it was found that two houses have been constructed in the inherited land. During the interaction with the petitioner it was found that the house was constructed in the year 1985 (Figure-12.651) and presently six members are living in these houses.

Petitioner No. 214	
Residential House	

Figure-12.651: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Bilijaji Village

12.15.8. Petitioner No.216: Smt. Anusuya aged about 28 years W/o Murthy residing at 161, Bilijaji, Bangalore North, Bangalore Urban District – 560 088.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house has been constructed in the year 1975 (Figure-12.652). Further it was found that the house has been constructed in the Gramathana and presently four members are living in the house.

Petitioner No. 216	
Residential House	

Figure-12.652: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Bilijaji Village

12.15.9. Petitioner No.258: Sri. M. Munivenkatappa aged about 54 years S/o Mudalappa residing at 50, Bilijaji, Bangalore North, Bangalore Urban District – 560 088.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the building was constructed in the year 2014 (Figure-12.653) and presently four members are living in the house.

Petitioner No.258	
Residential Building	

Figure-12.653: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Bilijaji Village

12.15.10. Petitioner No.360: Smt. Gowramma aged about 50 years W/o Nagaraju residing at house No.62, Bilijaji, Bangalore North, Bangalore Urban District – 560 088.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in the inherited land and further it was found that the first floor was having one room. During the interaction with the petitioner it was found that the building was constructed in the year 2010 (Figure-12.654) and presently four members are living in the house.

Petitioner No. 360	
Residential Building	

Figure-12.654: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Bilijaji Village

12.15.11. Petitioner No.488: Sri. M. Mahimanna aged about 45 years S/o Muninarasappa residing at 96, Bilijaji, Bangalore North, Bangalore Urban District – 560 088.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that three houses have been constructed in the ground floor in an area of (40'x50'). During the interaction with the petitioner it was found that the house has been constructed in the year 1995 (Figure-12.655). Further it was found that the house has been constructed in the Gramathana and presently five members are living in the house and also it was found that the house was having a borewell.

Petitioner No. 488	
Residential House	

Figure-12.655: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Bilijaji Village

12.15.12. Petitioner No.491: Sri. Srinivas aged about 45 years S/o Lakshmaiah residing at 9, Bilijaji, Bangalore North, Bangalore Urban District – 560 088.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that a hut has been constructed in the agricultural land. During the interaction with the petitioner it was found that the hut has been constructed in the year 1990 (Figure-12.656) and also it was found that the land having litigation. Further it was found that presently two members are living in the hut.

Petitioner No. 491	
Hut	

Figure-12.656: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Bilijaji Village

12.15.13. Petitioner No.591: Sri. B.V. Nagaraju about 42 years S/o Venkatalakshmaiah residing at 28, Bilijaji, Bangalore North, Bangalore Urban District – 560 088.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that single house has been constructed in the ground floor. During the interaction with the petitioner it was found that the house was constructed in the year 2013 (Figure-12.657) and presently five members are living in the house.

Petitioner No. 591	
Residential House	

Figure-12.657: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Bilijaji Village

12.16. Soladevanahalli, Harokyathanahalli and Hesaraghatta Villages:

Soladevanahalli:

As per the 2011 census the Soladevanahalli village has an area of 1.55 Sq.Km. with population of 2,940 and 812 households and village is falling in the Zone–3, 4 and l of the Arkavathi river stretch of the TGR catchment area (Figure-12.658).

In the Soladevanahalli three cases are filed (Annexure-12.16) and during the ground truth verification it was found that the houses have been constructed in the year 1990 and 2005. Whereas among the two houses one house has been constructed in the Gramathana and another one house has been constructed in the survey No.57.

Harokyathanahalli:

As per the 2011 census the Harokyathanahalli village has an area of 2.92 Sq.Km. with population of 2,513 and 670 households and village is falling in the Zone–3 and 4 of the Arkavathi river stretch of the TGR catchment area (Figure-12.658).

In Harokyathanahalli village 01 case has been filed (Annexure-12.16) and during the ground truth verification it was found that the house has been constructed in the year 2006 in the inherited land.



Figure-12.658: Location of the Soldevanahalli, Harokyathanahalli and Hesaraghatta villages in the Arkavathi river course (Source – NPA)

Hesaraghatta:

As per the 2011 census the Hesaraghatta village has an area of 11.9 Sq.Km. with population of 8,166 and 2,002 households and village is falling in the Zone-3, 4 and 1 of the Arkavathi river stretch of the TGR catchment area (Figure-12.658).

In Hesaraghatta village one case has been filed (Annexure-12.16) and during the ground truth verification it was found that after the demolition of the old house, construction of new building was in progress.

While interacting with the petitioners of these villages it was found that the Gram Panchayats are supplying water through borewells and mini water supply. Some of the general observations include sewage discharge into pit, grey water discharge into open drain, improper solid waste management (either disposed into nearby vacant land or disposed into their own land), open drain sanitation and accessibility to road. There has been rapid growth of the population and also in number of households in the villages *i.e.* Soladevanahalli and Harokyathanahalli.

During the ground truth verification out of 03 cases 02 residential houses cases could be identified in the Soladevanahalli village and remaining 01 case could not be identified. Pertaining to the address involving unidentified residential house, the local people and the persons accompanying the ground truth exercise expressed inability to locate these address. The current status of the identified residential houses of each petitioner in the villages of the Soladevanahalli, Harokyathanahalli and Hesaraghatta are discussed below:

12.16.1. Soladevanahalli Village:

12.16.1.1. Petitioner No.28: Sri. S. Gopal Reddy aged about 71 years S/o S.T. Ramareddy residing at 91, Soladevanahalli, Bangalore Urban District -560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+2 building along with the shop has been constructed in an area of (154'x45') and further it was found that the building was having seven houses. During the interaction with the petitioner it was found that after the demolition of 100 years old building the new building has been constructed in the year 1995 (Figure-12.659). Further it was found that the building has been constructed in the Gramathana and presently a total of twenty two members are living in these houses.

Petitioner No. 28

Figure-12.659: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Soladevanahalli Village

12.16.1.2. Petitioner No.46: Smt. Lakshmamma aged about 68 years residing at 4, Soladevanahalli, Bangalore Urban District – 560 090.

Documents Obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed. During the interaction with the petitioner it was found that the building has been constructed in the year 2005 (Figure-12.660) and presently four members are living in these houses.

Petitioner No. 46

Figure-12.660: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Soladevanahalli Village

12.16.1.3. Unidentified Petitioner: In the village of Soladevanahalli, out of 03 cases 02 residential houses cases were identified and remaining 01 property pertaining to the case that could not be identified is given below:

1. **Petitioner No.344:** Sri. N. Manju aged about 50 years S/o D. Narasimhaiah residing at 4, Soladevanahalli, Bangalore Urban District – 560 090.

12.16.2. Harokyathanahalli Village:

12.16.2.1. Petitioner No.66: Sri. S. Arasappa aged about 66 years S/o Siddappa residing at 296, Harokyathanahalli, Bangalore Urban District – 562 123.

Documents obtained: Electricity bill

Remarks: During the ground truth verification it was found that G+1 building has been constructed in an area of (60'x80'). During the interaction with the petitioner it was found that the building has been constructed in the year 2006 (Figure-12.661) and presently five members are living in these houses.

Figure-12.661: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Harokyathanahalli Village

12.16.3. Hesaraghatta Village:

12.16.3.1. Petitioner No.330: Sri. K. Govindappa aged about 51 years S/o Krishnappa residing at 648, Hesaraghatta, Bangalore North (Addl.), Bangalore Urban District – 562 123.

Remarks: During the ground truth verification, it was found that the construction of new building is in progress (Figure-12.662). During the interaction with the petitioner it was found that 100 years old house has been demolished and constructing a new building.

Figure-12.662: GPS location of the petitioner house (Yellow colour) on Google Earth Image (2014) in the Hesaraghatta Village

12.17. Incorrect Addresses: During the ground verification of the residential houses of the 870 petitioners. Out of 870 residential houses cases, 27 residential house addresses was not able to identify and while carrying out the ground truth verification these petitioners houses addresses founds to be incorrect. Pertaining to the incorrect addresses of the petitioners are given below:

1. **Petitioner No.99:** Sri. A.B. Somashekar aged about 29 years S/o Bylavenkatayya residing at 274, 2nd main road, Manjunathanagar, Tumkur Main road, Nagasandra, Yeshwanthapura Hobli, Bangalore North Taluk – 562 123.
2. **Petitioner No.118:** Smt. Mahabubi aged about 62 years W/o Peerkhan residing at 970, 6th Cross, Arasikere, Hassan District – 562 123.
3. **Petitioner No.228:** Sri. B. Narayanaswamy aged about 55 years S/o Bylappa residing at 11- B1, Bangalore North Taluk, Bangalore Rural District – 562 123.

4. **Petitioner No.268:** Sri. Ramu aged about 53 years S/o Mariyappa residing at Ramakrishna Layout, Malagala, Viswaneedam, Bangalore North, Bangalore – 560 091.
5. **Petitioner No.314:** Sri. U. Kumaraguru aged about 51 years S/o R.N. Umapathi residing at S/o Muthyalanagar, 2nd A Main Road, Bangalore – 562 123.
6. **Petitioner No.350:** Sri. M.N. Shankaraiah aged about 50 years S/o Nanjundaiah residing at #74/4, 4th Main Road, Gokul 1st Stage, 3rd Phase, Bangalore – 560 054.
7. **Petitioner No.351:** Sri. B.E. Omkara Murthy aged about 50 years S/o Eshwarappa residing at #12, Acharya College Main Road, Andrahalli, Bangalore North, Viswaneedam Bangalore – 560 091.
8. **Petitioner No.352:** Sri. M. Kempegowda aged about 50 years S/o Marigowda residing at 21, Thavariekere, Nelamangala, Mandya – 571 418.
9. **Petitioner No.447:** Sri. M. Ningegowda aged about 46 years S/o Honneppa residing at No 34, 8th Cross Goraguntepalya, Bengalore – 560 022.
10. **Petitioner No.450:** Sri. Shanakar Reddy aged about 46 years S/o Muniswamy Reddy residing at LIC Agent Shashi Kiranam, 1st Cross, Devi Nagar, Motappa Layout, RMV 2nd Stage, Bangalore – 560 094.
11. **Petitioner No.455:** Sri. Thirumalesha J Yadava aged about 25 years S/o K.E. Jayanna residing at 889, Indiranagar, Huliyarumannam 801 Rind 977-Huliyaru, Chikkanayakanahalli, Tumkur – 572 218.
12. **Petitioner No.509:** Sri. B.S. Chaluvegowda aged about 44 years S/o Huchegowda residing at #14/8, 4th Cross, Gorguntepalya, Bangalore – 560 022.
13. **Petitioner No.578:** Sri. B.I. Danappa Gowda aged about 42 years S/o Lrappagowda residing at No.361, 6th Cross, Bagalagunte, Bangalore – 560 073.
14. **Petitioner No.579:** Sri. D.R. Veerabhadrachar aged about 42 years S/o B. Rudrachar residing at 75-1, Lakshmidevinagar, Bangalore North – 562 123.
15. **Petitioner No.592:** Sri. H.P. Bhagyarekha aged about 42 years S/o K.C. Thimmaray Gowda residing at #15/4, 2nd Cross, 2nd Block, Nandini Layout, Bangalore – 560 096.
16. **Petitioner No.612:** Sri. Kantharaju aged about 41 years S/o Virappa residing at #E-655, Kuduregere, Bangalore North, Bangalore Urban District – 562 123.
17. **Petitioner No.622:** Sri. Sanjivanna aged about 41 years S/o Kariyappa residing at 193, Lakshmidevinagar, Bangalore North – 562 123.
18. **Petitioner No.641:** Sri. Babu aged about 19 years S/o Katachalapathy residing at # 656, 4th Cross, Mahalakshmi Layout, Bangalore - 560 096.
19. **Petitioner No.687:** Sri. B. Manjunath aged about 39 years S/o Ibailappa residing at 583, Madavar, Bangalore Urban District – 562 123.
20. **Petitioner No.690:** Sri. Anusuya aged about 38 years S/o Ballappa residing at #5, Mahal, Bangalore North Taluk, Bangalore District – 582 123.
21. **Petitioner No.740:** Sri. Shankaraiah aged about 36 years S/o Kasaiah residing at 157, Rajeshwarinagar, 5th Cross, Laggere, Bangalore North, Bangalore Urban District – 560 058.
22. **Petitioner No.774:** Smt. Arojamma aged about 35 years W/o Mudappa residing at No. 159, 2nd Cross, 2nd Main Road, Manjunathanagar, Bangalore – 560 010.
23. **Petitioner No.778:** Sri. H.Y. Dinesh aged about 35 years S/o Yalakkigowda residing at E157-325, Chikkabidarakallu-3, Bangalore Urban District – 560 073.
24. **Petitioner No. 821:** Smt. V. Savitha aged about 34 years W/o K. Mahendra residing at #6/1, 17th Cross, Agrahara, Dasarahalli, Bangalore – 560 079.
25. **Petitioner No.831:** Smt. Latha aged about 33 years W/o S.D. Suresh residing at #52, 8th Main Road, Nandini Layout, Bangalore – 560 096.
26. **Petitioner No.834:** Sri. N. Narasimharaju aged about 33 years S/o N. Narasinhamurthy residing at 194, Kuduregere, Bangalore Urban District – 562 123.
27. **Petitioner No.857:** Sri Narayanagowda aged about 32 years S/o Thimmegowda residing at 4/1, Bangalore North Taluk, Bangalore District – 560 090.

12.8. Conclusion:

Based on the observation, the following conclusions have been drawn regarding 870 residential houses writ petitions:

i. In few cases two to five petitions have been filed by the members of the same family. These writ petitions have been filed in response to the general demolition notification issued through a publication in the newspaper under Section-15(4) and 17(4) of Karnataka Town and Country Planning Act, 1961 to all the building owners, as their superstructures situated in Zone-3 of the Notification. Since the notice was published in the newspaper as a general Notice, some of the farmers and land owners having buildings in the notified area were approached the Hon'ble High Court of Karnataka in the year 2013.

ii. The petitioners are the residents of the 20 villages of the Bangalore North Taluk *i.e.* Adakimaranahalli, Dombarahalli, Lakshmipura, Siddanahosahalli, Tarabanahalli, Heggadadevanapura, Makali, Sasuveghatta, Madanayakanahalli, Kadaranahalli, Hanumanthasagara, Kumbarahalli, Bilijaji, Soladevanahalli, Kuduragere, Harokyathanahalli, Hesaraghatta, Madavara, Chikkabidarakallu and Bagalagunte. Out of 20 villages three villages *i.e.* Makali, Hanumanthasagara and Tarabanahalli fall within the Zone-3 of the catchment area. Whereas, the villages *i.e.* Adakimaranahalli, Dombarahalli, Siddanahosahalli, Heggadadevanapura, Sasuveghatta, Madanayakanahalli, Kadaranahalli, Kumbarahalli, Bilijaji and Harokyathanahalli fall in the Zone-3 and 4 of the catchment area.

iii. Most of the houses have been constructed in the inherited properties and substantially in the sites allotted by the Government under the Ashraya Yojane Scheme, Rajiv Gandhi Rural Housing Scheme, Janatha Niveshana, etc. for the economically weaker sections. Most of the houses have been constructed in the Gramathana and few of the houses have been constructed in the revenue sites and also in the developing layouts. Few of the sites were also found to be vacant. In some cases Government has provided electricity connections to the houses under the Bhagya Jyothi Scheme for the economically weaker sections.

iv. Few of the houses have been constructed in 40's and 50's in the Gramathana and majority of the houses have been constructed in 80's and 90's and more intensely after 2000. Further, many houses are renovated adding one floor to two floors and few houses are being used for commercial shops which are rented out and also in few cases division of house among the children has happened.

v. The villages are having open drain sanitation, accessibility to road and the Gram Panchayats are supplying water through borewells and mini water supply schemes. Few houses are having borewells and management of the solid waste in few villages is being done by the Gram Panchayats.

vi. Siddanahosahalli, Madanayakanahalli, Makali, Dombarahalli villages are located along the ribbon of the NH-4 have witnessed drastic increase in the population, number of households and also growth in-terms of infrastructure. The main reason for this is better economic conditions and employment opportunities.

Atlas for Superstructures under Litigation

WP. No. 38183/2013 Date of visit: 28.02.2015 on 11:00 A.M.

LOCATION INFORMATION		
Sy. No: 11/2, 11/6, 11/9 (11/1A, 1A, 1D)	**Petitioner Name:** N. Lokesh	**Respondents**
Village Name: Makali	**Distance from River (m):** 550 (Approx.)	Govt. of Karnataka & others
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 2.00	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'59.2" **N**	
Jurisdiction: BDA	**Long**. 77°27'01.3" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
Year of Establishment	2005	**No. of bore wells**	01
Structure size (sq. ft)	10000	**Depth of bore well (ft.)**	300
Floor types	Concrete	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Yes	
Roof type	Galvanized sheet	**Generation of Sewerage:** Nil	
Used for	03 partitions: Electronic goods, engine oil & machinery parts stocks and furniture stock	**Rainwater Harvesting:** No	
Used by	Yusen Logistics/ Valvoline/ DTDC courier	**Other issues:** Burnt wastes and solid wastes disposed in the premises	
Surrounding area (50m)	Road, vacant land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection Certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	✓
5	Jurisdiction (Planning Authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any) [Conversion certificate & Loan details]	✓

Copies of the above marked (✓) documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTO

UTILITY PHOTOS (Electronic goods, engine oil & machinery parts)

ISSUES PHOTOS (Solid waste disposal)

WP. No. 38218/ 2013 Date of visit: 21.02.2015 on 02:10 P.M.

LOCATION INFORMATION		
Sy. No: 52/3	**Petitioner Name**: T. Rajkumar	**Respondents**
Village Name: Madanayakanahalli	**Distance from River (m):** 130.00 (Approx.)	BDA
Grama Panchayat: Madanayakanahalli	**TGR Zone: 3**	
Hobli Name: Dasanapura	**Extent area (A-G):** 2.10	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'47.3''**N**	
Jurisdiction: BDA	**Long.** 77°27'23.7''**E**	

STATUS OF SUPERSTRUCTURE					DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	1	2	3	4	**Constructed scheme**	**GBY**
Type of Superstructures	Godown	Godown	Godown	Godown	**Fence**	Compound wall
Year of Establishment	2014	2014	2014	2008	**No. of bore wells**	One
Structure size (sq. ft.)	-	-	-	-	**Depth of bore well (ft.)**	750
Floor types	Asphalt	Asphalt	Asphalt	Asphalt	**ISSUES**	
No. of Floors	Ground	Ground			**Generation of solid wastes:** Yes	
Roof type	Asbestos	Asbestos	Asbestos	Asbestos	**Generation of Sewerage:** Yes	
Used for	Furniture stock	Books & stationeries	Footwear stock	Building construction materials	**Rainwater harvesting:** No	
Used by	-	Navneet Publications	Fuzon Footware	Plas Tech	**Other issues:** Nil	
Surrounding area (50m)	Godowns and Highway (NH4)					

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	X
4	Tax paid to GP	✓
5	Jurisdiction (Planning Authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	✓
8	Any others (if any) Sale deed, EC	✓

Copies of the marked (✓) documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Furniture, Books, Footwear and construction materials stock)

WP. No. 38483/2013 Date of visit: 26.02.2015 on 12:30 P.M.

LOCATION INFORMATION		
Sy. No: 6	**Petitioner Name:** E. Krishnappa	**Respondents**
Village Name: Makali	**Distance from River (m):** 460 (Approx.)	Govt. of Karnataka & others
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 2.00	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'07.0" **N**	
Jurisdiction: BDA	**Long.** 77°27'10.0" **E**	

STATUS OF SUPERSTRUCTURE				
No. of Superstructures	01	02	03	04
Type of Superstructures	Godown	Godown	Godown	Building
Year of Establishment	2001-02	2001-02	2001-02	2001-02
Structure size (sq. ft)	52,000	32,000	20,000	10,000
Floor types	Concrete	Concrete	Concrete	Concrete
No. of Floors	Ground	Ground	Ground	G+2
Roof type	Asbestos	Asbestos	Asbestos	RCC
Used for	02 partitions:Mobile accessories and kitchen appliances	Electronic goods	Vacant	Vacant
Used by	Reliance Ltd. and Franke Faber Ind. Ltd. (Rent)	Geen Dust Pvt. Ltd. (Rent)	Vacant	Vacant
Surrounding area (50m)	Road, vacant land			

DETAILS OF SUPERSTRUCTURE		ISSUES
Constructed scheme	GBY	**Generation of solid wastes:** Yes
Fence	Compound wall	**Generation of Sewerage:** Yes
No. of bore wells	2	**Rainwater harvesting:** No
Depth of bore well (ft)	800	**Other issues:** Packing materialas and unused laboratory utensils dumped

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection Certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	X
5	Jurisdiction (Planning Authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any) [Electricity connection sanctioned from BESCOM]	✓

Copies of the above marked (✓) documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)

COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS

ISSUES PHOTOS (Solid wastes and waste tissue culture bottles dumped)

WP. No. 38492/2013 Date of visit: 05.03.2015 on 11:10 A.M.

LOCATION INFORMATION		
Sy. No: 4	**Petitioner Name:** A. G. Siddappa	**Respondents**
Village Name: Adakimaranahalli	**Distance from River (m):** 662 (Approx.)	Govt. of Karnataka & others
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 5.00	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'52.7" **N**	
Jurisdiction: BDA	**Long.** 77°26'51.9" **E**	

STATUS OF SUPERSTRUCTURE						
No. of Superstructures	01	02	03	04	05	06
Type of Superstructures	Godown	Godown	Godown	Godown	Godown	Building
Year of Establishment	2008	2008	2008	2008	2008	2012
Structure size (sq. ft.)	-	-	-	-	-	-
Floor types	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete
No. of Floors	Ground	Ground	Ground	Ground	Ground	G+1
Roof type	Asbestos sheets	Asbestos sheets	Asbestos sheets	Asbestos sheets	Asbestos sheets	RCC
Used for	Courier stock	Provision stock	Food stock	Soft drinks & water bottle	GSMs Paper stock	FedEx Office
Used by	Fedex Courier Co. (Rent)	Smart Retail Ltd. (Rent)				FedEx
Surrounding area (50m)	Road, vacant land and godowns					

DETAILS OF SUPERSTRUCTURE		ISSUES
Constructed scheme	GBY	**Generation of solid wastes:** Nil
Fence	Compound wall	**Generation of Sewerage:** Nil
No. of bore wells	One	**Rainwater harvesting:** No
Depth of bore well (ft.)	180	**Other issues:** Inside the godown premises solid wastes dumped

S. No	PERMISSION GRANTED BY	
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning Authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any) [Form 15]	X
None of the documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)

COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS

ISSUES PHOTOS (Solid wastes)

WP. No. 38493/2013 (1a) Date of visit: 31.03.2015 on 11:50 A.M.

LOCATION INFORMATION		
Sy. No: 4/1P1	**Petitioner Name:** Rathnamma	**Respondents**
Village Name: Adakimaranahalli	**Distance from River (m):** 742 (Approx.)	1. The Commissioner, BDA
Grama Panchayat: Dasanpura	**TGR Zone:** 3	2. DC, Rural
Hobli Name: Dasanpura	**Extent area (A-G):** 2.10	3. KSPCB
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'51.3" **N**	
Jurisdiction: BDA	**Long**. 77°26'47.1" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
Year of Establishment	2006	**No. of bore wells**	One
Structure size (sq. ft.)	-	**Depth of bore well (ft.)**	750
Floor types	Concrete	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Yes	
Roof type	Junk Sheet	**Generation of Sewerage:** Yes	
Used for	Godown having 02 partitions, auto mobile spare parts are stored	**Rainwater harvesting:** No	
Used by	Fly wheel Logistics and Express Logistics (Rent)	**Other issues:** Movement of (HMVs) and storage of packing materials	
Surrounding area (50m)	Godown and vacant land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection Certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	✓
5	Jurisdiction (Planning Authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Copies of the marked (✓) documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)

COMPARATIVE GOOGLE IMAGE



EXISTING SUPERSTRUCTURE PHOTO

UTILITY PHOTO (Storage of logistics goods)

ISSUES PHOTO (Packing materials)

W. P. No: 38494/2013 (1b) Date of visit: 31.03.2015 on 12:15P.M.

LOCATION INFORMATION		
Sy. No: 4/1P1	**Petitioner Name:** Venugopal	**Respondents**
Village Name: Adakimaranahalli	**Distance from River (m):** 750 (Approx.)	1. The Commissioner, BDA
Grama Panchayat: Dasanpura	**TGR Zone:** 3	2. DC, Rural
Hobli Name: Dasanpura	**Extent area (A-G):** 2.10	3. KSPCB
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'49.9" **N**	
Jurisdiction: BDA	**Long**. 77°26'48.1" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
Year of Establishment	2006	**No. of bore wells**	One
Structure size (sq. ft)	-	**Depth of bore well (ft)**	750
Floor types	Concrete	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Yes	
Roof type	Galvanized Sheet	**Generation of Sewerage:** Yes	
Used for	Godown having 04 partitions & electronic goods(Samsung, Canon, Blue star), ATM spare parts are stored	**Rainwater harvesting:**	
Used by	Fedex (Rent)	**Other issues:** Solid wastes and scrap items dumped in the premises.	
Surrounding area (50m)	Godown and vacant land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	✓
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Copies of the marked (✓) documents submitted by the petitioner.

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE



EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Blue star, Canon goods stored)

ISSUES PHOTOS (Dumping of solid wastes and scrap items in godown premises)

W.P. No: 38495/2013 (1c) Date of visit: 31.03.2015 on 10: 20A.M.

LOCATION INFORMATION		
Sy. No: 4/2	**Petitioner Name:** Hanumegowda	**Respondents**
Village Name: Adakimaranahalli	**Distance from River (m):** 360 (Approx.)	1. The Commissioner, BDA
Grama Panchayat: Dasanpura	**TGR Zone:** 3	2. DC, Rural
Hobli Name: Dasanpura	**Extent area (A-G):** 2.10	3. KSPCB
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'46.6" **N**	
Jurisdiction: BDA	**Long**. 77°26'50.5" **E**	

STATUS OF SUPERSTRUCTURE				DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	02	03	**Constructed scheme**	GBY
Type of Superstructures	Godown	Godown	Building	**Fence**	Compound wall
Year of Establishment	2006	2006	2006	**No. of bore wells**	One
Structure size (sq. ft.)	-	-	-	**Depth of bore well (ft.)**	750
Floor types	Concrete	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	Ground	G+2	**Generation of solid wastes:** Nil	
Roof type	Junk Sheet	Junk Sheet	RCC	**Generation of Sewerage:** Nil	
Used for	Storage of Polyol liquid	Stationeries & electronics goods stock	Commercial shops, hotel	**Rainwater harvesting:** No	
Used by	CCI Logistics Ltd. (Rent)	Kokuyo Camlin Ltd. & Blue star (Rent)	Rent	**Other issues:** Movement of (HMVs)	
Surrounding area (50m)	Godown				

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	✓
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X
Copies of the marked (✓) document submitted by the petitioner.		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS

W.P. No: 38496/2013 (1d) Date of visit: 31.03.2015 on 11:00 A.M.

LOCATION INFORMATION		
Sy. No: 4/2	**Petitioner Name:** Arasegowda	**Respondents**
Village Name: Adakimaranahalli	**Distance from River (m):** 610 (Approx.)	1. The Commissioner, BDA
Grama Panchayat: Dasanpura	**TGR Zone:** 3	2. DC, Rural
Hobli Name: Dasanpura	**Extent area (A-G):** 2.10	3. KSPCB
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'47.8" **N**	
Jurisdiction: BDA	**Long.** 77°26'50.9" **E**	

STATUS OF SUPERSTRUCTURE			DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	02	**Constructed scheme**	GBY
Type of Superstructures	Godown	Godown	**Fence**	Compound wall
Year of Establishment	2006	2006	**No. of bore wells**	One
Structure size (sq. ft)	16,000	16,000	**Depth of bore well (ft)**	750
Floor types	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	Ground	**Generation of solid wastes:** Yes	
Roof type	Junk Sheet	Junk Sheet	**Generation of Sewerage: Yes**	
Used for	Stationeries stock	Bathroom fittings stock	**Rainwater harvesting:** No	
Used by	Camlin Pvt. Ltd. (Rent)	AWL Accelerated Logistics (Rent)	**Other issues:** Movement of HMVs, solid and burnt wastes dumped.	
Surrounding area (50m)	Road, Godown and vacant land	Road, Godown and vacant land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection Certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	✓
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Copies of the marked (✓) documents submitted by the petitioner.

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Stationeries and bathroom fittings stock)

ISSUES PHOTO (Burnt wastes disposed)

W.P. No: 38497/2013 (1e) Date of visit: 31.03.2015 on 10:55 A.M.

LOCATION INFORMATION		
Sy No: 4/2	**Petitioner Name:** Srinivasmurthy	**Respondents**
Village Name: Adakimaranahalli	**Distance from River (m):** 714 (Approx.)	1. The Commissioner, BDA
Grama Panchayat: Dasanpura	**TGR Zone:** 3	2. DC, Rural
Hobli Name: Dasanpura	**Extent area (A-G):** 5.06	3. KSPCB
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'48.2" **N**	
Jurisdiction: BDA	**Long.** 77°26'45.7" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
Year of Establishment	2006	**No. of bore wells**	One
Structure size (sq. ft.)	-	**Depth of bore well (ft.)**	750
Floor types	Concrete	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Nil	
Roof type	Junk Sheet	**Generation of Sewerage:** Nil	
Used for	Storage of computer accessories	**Rainwater harvesting:** No	
Used by	Redington India Pvt. Ltd. (Rent)	**Other issues:** Movement of Heavy Motor Vehicles and solid waste dumped in the premises	
Surrounding area (50m)	Godowns		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	✓
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Copies of the marked (✓) documents submitted by the petitioner.

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTO (Computer accessories stock)

ISSUES PHOTO (Solid wastes disposed)

W.P. No: 38498/2013 Date of visit: 07.03.2015 on 10: 25 A.M.

LOCATION INFORMATION		
Sy. No: 102/1	**Petitioner Name:** A. H. Timmarayappa	**Respondents**
Village Name: Harokyatanahalli	**Distance from River (m):** 504 (Approx.)	1. The Commissioner, BDA
Grama Panchayat: Dasanpura	**TGR Zone:** 3	2. DC, Rural
Hobli Name: Dasanpura	**Extent area (A-G):** 3.00	3. KSPCB
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'43.1" **N**	
Jurisdiction: BDA	**Long.** 77°26'50.6" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
Year of Establishment	2006	**No. of bore wells**	One
Structure size (sq. ft)	67,900	**Depth of bore well (ft.)**	300
Floor types	Concrete	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Nil	
Roof type	Junk sheet	**Generation of Sewerage:** Nil	
Used for	Vacant	**Rainwater harvesting:** No	
Used by	Vacant	**Other issues:** Nil	
Surrounding area (50m)	Road, farm and vacant land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	✓
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any) [Loan detail]	✓

Copies of the marked (✓) documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE



EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTO (Vacant)

WP. No. 38499/2013 Date of visit: 03.03.2015 on 03:00 P.M.

LOCATION INFORMATION		
Sy. No: 24/2	**Petitioner Name:** H. Prabhudev	**Respondents**
Village Name: Dombarahalli	**Distance from River (m):** 672 (Approx.)	1. The Commissioner, BDA
Grama Panchayat: Madanayakanahalli	**TGR Zone:** 3	2. DC, Rural
Hobli Name: Dasanpura	**Extent area (A-G):** 6.20	3. KSPCB
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'07.2" **N**	
Jurisdiction: BDA	**Long.** 77°27'32.9" **E**	

STATUS OF SUPERSTRUCTURE					DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	02	03	04	**Constructed scheme**	GBY
Type of Superstructures	Godown	Godown	Godown	Godown	**Fence**	Compound wall
Year of Establishment	2009-10	2009-10	2009-10	2009-10	**No. of bore wells**	One
Structure size (sq. ft.)	60,000				**Depth of bore well (ft.)**	-
Floor types	Concrete	Concrete	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	Ground	Ground	Ground	**Generation of solid wastes:** Yes	
Roof type	Junk sheet	Junk sheet	Junk sheet	Junk sheet	**Generation of Sewerage:** Yes	
Used for	Plastic furniture stock	Telecom Network spares stock	Elevators stock	DG sets, batteries stock and repair	**Rainwater Harvesting:** Yes	
Used by	Neelkamal Ltd. (Rent)	Reliance Info (Rent)	Valvoline (Rent)	Diesel- TATA Enterprises) (Rent)	**Other issues:** Repair of DG sets & battery scrap dumped in the premises	
Surrounding area (50m)	Road and vacant land					

S. No	PERMISSION GRANTED BY	
1	General License (from GP)	✓
2	No Objection Certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP & Tax paid to GP	✓
4	Jurisdiction (Planning Authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/	X
5	Consent from KSPCB (under Water/ Air Act)	X
6	RTC/ MR documents	X
7	Any others (if any) [Loan details]	✓

Copies of the marked (✓) documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE



EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Storage of furniture, batteries)

ISSUES PHOTOS (Scrap and batteries dump)

WP. No. 38500/2013 Date of visit: 26.02.2015 on 11:35 P.M.

LOCATION INFORMATION		
Sy. No: 6	**Petitioner Name:** A. V. Chikkegowda	**Respondents**
Village Name: Makali	**Distance from River (m):** 485 (Approx.)	1. The Commissioner, BDA
Grama Panchayat: Dasanpura	**TGR Zone:** 3	2. DC, Rural
Hobli Name: Dasanpura	**Extent area (A-G):** 1.00	3. KSPCB
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'08.5" **N**	
Jurisdiction: BDA	**Long.** 77°27'11.2" **E**	

STATUS OF SUPERSTRUCTURE				DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	02	03	**Constructed scheme**	GBY
Type of Superstructures	Godown	Godown	Buliding	**Fence**	Compound wall
Year of Establishment	2006	2006	-	**No. of bore wells**	1
Structure size (sq. ft)	30,000	30,000	-	**Depth of bore well (ft.)**	500
Floor types	Concrete	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	Ground	Ground	**Generation of solid wastes:** Nil	
Roof type	Junk sheet	Junk sheet	Asbestos	**Generation of Sewerage:** Nil	
Used for	Books stock	Colgate products	Commercial purpose and houses	**Rainwater harvesting:** No	
Used by	AAJ Enterprises (Rent)	Colgate (I) Pvt. Ltd. (Rent)	Hotels, Bakery, Provision stores and houses (Rent)	**Other issues:** Nil	
Surrounding area (50m)	Road and vacant land				

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any) [NOC from BESCOM]	✓
Copies of the marked (✓) documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE



EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Books, tooth paste and hotels)



WP. No. 38501/2013 Date of visit: 03.03.2015 on 03: 40 P.M.

LOCATION INFORMATION		
Sy. No: 24/2	**Petitioner Name:** Sharadamma	**Respondents**
Village Name: Dombarahalli	**Distance from River (m):** 965 (Approx.)	1. The Commissioner, BDA
Grama Panchayat: Madanayakanahalli	**TGR Zone:** 3	2. DC, Rural
Hobli Name: Dasanpura	**Extent area (A-G):** 8.10	3. KSPCB
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'03.0" **N**	
Jurisdiction: BDA	**Long**. 77°27'37.2" **E**	

STATUS OF SUPERSTRUCTURE			DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	02	**Constructed scheme**	GBY
Type of Superstructures	Godown	Godown	**Fence**	Compound wall
Year of Establishment	2006	2006	**No. of bore wells**	One
Structure size (sq. ft)	70,000	75,000	**Depth of bore well (ft.)**	-
Floor types	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	Ground	**Generation of solid wastes:** Nil	
Roof type	Junk sheet	Junk sheet	**Generation of Sewerage:** Nil	
Used for	Soaps and detergents stock	Pharmaceuticals stock	**Rainwater harvesting:** Yes	
Used by	Jyothi Laboratories Ltd. (Rent)	Meyer (Rent)	**Other issues:** Inside the godown premises solid waste dumped	
Surrounding area (50m)	Road, vacant land			

S. No	PERMISSION GRANTED BY	
1	General License (from GP)	✓
2	No Objection Certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	✓
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any) [Loan details]	✓
Copies of the above marked (✓) documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)

MPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Detergents, soaps and pharmaceuticals stock)

WP. No. 38502/2013 Date of visit: 07.03.2015 on 10:20 A.M.

LOCATION INFORMATION		
Sy. No: 6	**Petitioner Name:** Rathnamma	**Respondents**
Village Name: Adakimaranahalli	**Distance from River (m):** 617 (Approx.)	1. The Commissioner, BDA
Grama Panchayat: Dasanpura	**TGR Zone:** 3	2. DC, Rural
Hobli Name: Dasanpura	**Extent area (A-G):** 1.29	3. KSPCB
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'45.0" **N**	
Jurisdiction: BDA	**Long.** 77°26'47.6" **E**	

STATUS OF SUPERSTRUCTURE			DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	02	**Constructed scheme**	GBY
Type of Superstructures	Godown	Godown	**Fence**	Compound wall
Year of Establishment	2007-08	2007-08	**No. of bore wells**	One
Structure size (sq. ft)	60,000	-	**Depth of bore well (ft.)**	300
Floor types	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	Ground	**Generation of solid wastes:** Yes	
Roof type	Galvanized sheets	Galvanized sheets	**Generation of Sewerage:** Yes	
Used for	Logistics (Chemicals)	Logistics (Chemicals)	**Rainwater harvesting:** No	
Used by	Startek Logistics (Rent)	Home Logistics (Rent)	**Other issues:** Solid wastes, scrap items dumped in the premises and waste water discharged into surrounding area.	
Surrounding area (50m)	Road, parking area and godowns			

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection Certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Copies of the marked (✓) documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE



EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Logistics and Chemicals)

ISSUES PHOTOS (Scrap dumped and waste water discharge)

WP. No. 38503/ 2013 Date of visit: 03.03.2015 on 04.30 P.M.

LOCATION INFORMATION		
Sy. No: 32	**Petitioner Name**: Rathnamma	**Respondents**
Village Name: Siddanahosahalli	**Distance from River (m):** 460.00 (Approx.)	1. Commissioner, BDA 2. DC, Bengaluru Rural 3. KSPCB
Grama Panchayat: Madanayakanahalli	**TGR Zone: 3**	
Hobli Name: Dasanapura	**Extent area (A-G):** 2.02 and 0.05 (kharab)	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'18.6''**N** **Long.** 77°27'36.8''**E**	
Jurisdiction: BDA		

STATUS OF SUPERSTRUCTURE			DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	1	2	**Constructed scheme**	**GBY**
Type of Superstructures	Godown	Godown	**Fence**	Compound wall
Year of Establishment	2008-09	2008-09	**No. of bore wells**	One
Structure size (sq. ft.)	43,000	14,500	**Depth of bore well (ft.)**	750
Floor types	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	Ground	**Generation of solid wastes:** Nil	
Roof type	Junk sheet	Junk sheet	**Generation of Sewerage:** Yes	
Used for	Storage of Telecom products	Floor cleaning products	**Rainwater harvesting:** No	
Used by	Aircel Telecom Ltd (Rent)	TOL (I) Logistics (Rent)	**Other issues:** Nil	
Surrounding area (50m)	Vacant land and godown			

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Copies of the marked (✓) documents submitted by the petitioner.

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE



EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Telecom product and floor cleaning product stock)



W.P. No: 38504/2013 Date of visit: 26.02.2015 on 10:20 AM

LOCATION INFORMATION		
Sy No: 6	**Petitioner Name:** A. G. Muddhegowda	**Respondents**
Village Name: Makali	**Distance from River (m):** 412 (Approx.)	The Commissioner, BDA & others
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 4.05	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'11.3" **N**	
Jurisdiction: BDA	**Long**. 77°27'13.0" **E**	

STATUS OF SUPERSTRUCTURE					DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	02	03	04	**Constructed scheme**	GBY
Type of Superstructures	Godown	Godown	Godown	Godown	**Fence**	Compound wall
Year of Establishment	2008	2008	2008	2008	**No. of bore wells**	2
Structure size (sq. ft.)					**Depth of bore well (ft.)**	650
Floor types	Asphalt	Asphalt	Asphalt	Asphalt	**ISSUES**	
No. of Floors	Ground	Ground	Ground	Ground	**Generation of solid wastes:** Nil	
Roof type	Asbestos	Asbestos	Asbestos	Asbestos	**Generation of Sewerage:** Nil	
Used for	Garment stock	Garment stock	Chemicals, engine oil stock	Vacant	**Rainwater harvesting:** Yes (only in 3rd godown RWH installed)	
Used by	Break Bounce (Rent)	English Blazer (Rent)	V- xpress (Rent)	Vacant	**Other issues:** In godown premises solid wastes dumped	
Surrounding area (50m)	Road, godowns					

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICPA/ NPA/ MPA/ BMRDA/ BIAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X
None of the documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)



DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Garments, engine oil and chemical stock)

ISSUES PHOTOS (Solid wastes dumped)

WP. No. 38505/2013 Date of visit: 26.02.2015 on 11:20 A.M.

LOCATION INFORMATION		
Sy No: 6	**Petitioner Name:** Veerachannegowda	**Respondents**
Village Name: Makali	**Distance from River (m):** 488 (Approx.)	1. The Commissioner, BDA
Grama Panchayat: Dasanpura	**TGR Zone:** 3	2. DC, Rural
Hobli Name: Dasanpura	**Extent area (A-G):** 1.05	3. KSPCB
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'10.2" **N**	
Jurisdiction: BDA	**Long**. 77°27'11.3" **E**	

STATUS OF SUPERSTRUCTURE			DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	02	**Constructed scheme**	GBY
Type of Superstructures	Godown	Building	**Fence**	Compound wall
Year of Establishment	2005	-	**No. of bore wells**	2
Structure size (sq. ft.)	20,800	-	**Depth of bore well (ft.)**	650
Floor types	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	G+1	**Generation of solid wastes:** Nil	
Roof type	Asbestos	Asbestos	**Generation of Sewerage:** Nil	
Used for	Toothpaste stock	Houses and commercial shops	**Rainwater harvesting:** No	
Used by	Colgate Palmolive (I) Pvt. Ltd. (Rent)	Rent	**Other issues:** In godown premises solid wastes burnt.	
Surrounding area (50m)	Road and vacant land			

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X
None of the documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Toothpaste stock and commercial shops)

ISSUES PHOTO

.

W.P. No: 38506/2013 Date of visit: 28.02.2015 on 02: 45 P.M.

LOCATION INFORMATION		
Sy. No: 11/6, 11/9	**Petitioner Name:** Smt. Kamalamma	**Respondents**
Village Name: Makali	**Distance from River (m):** 518 (Approx.)	BDA & others
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 2.00	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'56.3" **N**	
Jurisdiction: BDA	**Long.** 77°27'03.7" **E**	

STATUS OF SUPERSTRUCTURE			DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	02	**Constructed scheme**	GBY
Type of Superstructures	Godown	Building	**Fence**	Compound wall
Year of Establishment	2008	2008	**No. of bore wells**	02
Structure size (sq. ft.)	25200	-	**Depth of bore well (ft.)**	350
Floor types	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	Ground	**Generation of solid wastes:** Nil	
Roof type	Junk sheet	Asbestos sheets	**Generation of Sewerage:** Nil	
Used for	Vacant	Security office	**Rainwater harvesting:** No	
Used by	Vacant	Security personnel	**Other issues:** Inside the godown premises, solid waste dumped	
Surrounding area (50m)	Road, godown and vacant land			

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any) [Sale deed, Loan detail]	X
None of the documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTO (Vacant godown)

ISSUES PHOTO (Solid wastes dumped in the premises)

WP. No. 38518/2013

Date of visit: 24.02.2015 on 04:15 PM

LOCATION INFORMATION		
Sy. No: 52/4-B and 51	**Petitioner Name:** T. A. Jagadamba	**Respondents**
Village Name: Madanayakanahalli	**Distance from River (m):** 840m (Approx.)	Govt. of Karnataka & others
Grama Panchayat: Madanayakanahalli	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 0.39 and 1.27	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'49.0" **N**	
Jurisdiction: BDA	**Long.** 77°27'18.3" **E**	

STATUS OF SUPERSTRUCTURE			DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	02	**Constructed scheme**	GBY
Type of Superstructures	Godown	Godown	**Fence**	Compound wall
Year of Establishment	2005-06	2005-06	**No. of bore wells**	One
Structure size (sq. ft.)	70,000	40,000	**Depth of bore well (ft.)**	300
Floor types	Mud	Mud	**ISSUES**	
No. of Floors	G+1	Ground	**Generation of solid wastes:** Yes	
Roof type	Junk sheets	Junk sheets	**Generation of Sewerage:** Yes	
Used for	Ground floor godown with vegetables & fruits stock	Dry cargos	**Rainwater harvesting:** No	
Used by	Reliance fresh	RCPL Limited	**Other issues:** Inside the godown scrap dumped and in premises solid waste dumped and burnt	
Surrounding area (50m)	Highway, godown and river			

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X
None of the documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)

COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS



UTILITY PHOTOS (Vegetable and dry cargos stock)

ISSUES PHOTOS (Scrap and solid wastes dumped)

WP. No. 38697/ 2013 Date of visit: 19.02.2015 on 12:35 P.M.

LOCATION INFORMATION		
Sy. No: 64/4 & 72/2	**Petitioner Name:** Yethivendra Naik	**Respondents**
Village Name: Heggadadevanapura	**Distance from River (m):** 810 & 630.00 (Approx.)	1. Commissioner, BDA 2. DC, Rural 3. KSPCB
Grama Panchayat: Alur	**TGR Zone: 3**	
Hobli Name: Dasanapura	**Extent area (A-G):** 1.30	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'32.9''**N**	
Jurisdiction: BDA	**Long.** 77°27'04.9''**E**	

STATUS OF SUPERSTRUCTURE				DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	1 @ 64/4	2 @ 72/2	3 @72/2	**Constructed scheme**	**GBY**
Type of Superstructures	Godown	Godown	Godown	**Fence**	Compound wall
Year of Establishment	2005	2008	2008	**No. of bore wells**	One
Structure size (sq. ft.)	30120	16000	13200	**Depth of bore well (ft.)**	350
Floor types	Concrete	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	Ground	Ground	**Generation of solid wastes:** Yes, dumped in the premises of Sy. No. 72/2	
Roof type	Asbestos sheet	Junk sheet	Junk sheet	**Generation of Sewerage:** Yes	
Used for	Amway products	Vacant	Vacant	**Rainwater harvesting:** No	
Used by	Amway India Pvt Ltd (Rent)	Vacant	Vacant	**Other issues:** Solid wastes, organic wastes and construction debris dumped	
Surrounding area (50m)	Godown and Road				

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X
None of the documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)



DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE





EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTO (Amway products stock and vacant godown)

ISSUES PHOTO (Solid wastes, organic wastes and construction debris)

WP. No. 38698/ 2013 Date of visit: 19.02.2015 on 01:05 P.M.

LOCATION INFORMATION		
Sy. No: 72/1	**Petitioner Name:** Chandrashekar Naik	**Respondents**
Village Name: Heggadadevanapura	**Distance from River (m):** 600 (Approx.)	1. Commissioner, BDA 2.DC, Bengaluru Rural 3. KSPCB
Grama Panchayat: Alur	**TGR Zone: 3**	
Hobli Name: Dasanapura	**Extent area (A-G):** 1.37	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'32.4''**N** **Long.** 77°27'12.1''**E**	
Jurisdiction: BDA		

STATUS OF SUPERSTRUCTURE			DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	1	2	**Constructed scheme**	**GBY**
Type of Superstructures	Godown	Godown	**Fence**	Compound wall
Year of Establishment	2006-07	2006-07	**No. of bore wells**	Nil
Structure size (sq. ft.)	42,000	47,500	**Depth of bore well (ft.)**	-
Floor types	Asphalt	Asphalt	**ISSUES**	
No. of Floors	Ground	Ground	**Generation of solid wastes:** Nil	
Roof type	Asbestos	Asbestos	**Generation of Sewerage:** Nil	
Used for	Vacant	Vacant	**Rainwater harvesting:** Yes (Not working)	
Used by	Vacant	Vacant	**Other issues:** Nil	
Surrounding area (50m)	Road, Godowns and vacant land			

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X
None of the documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

ISSUES PHOTOS (Solid wastes and weeds in the premises)

WP. No. 38699/2013 Date of visit: 26.02.2015 on 02:50 P.M.

LOCATION INFORMATION		
Sy No: 6/10	**Petitioner Name:** K.V. Ravikumar	**Respondents**
Village Name: Makali	**Distance from River (m):** 480 (Approx.)	1. Commissioner, BDA 2.DC, Bengaluru Rural 3. KSPCB
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 1.10	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'02.4" **N**	
Jurisdiction: BDA	**Long.** 77°27'07.2" **E**	

STATUS OF SUPERSTRUCTURE			DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	02	**Constructed scheme**	GBY
Type of Superstructures	Godown	Building	**Fence**	Compound wall
Year of Establishment	2002	2002	**No. of bore wells**	1
Structure size (sq. ft.)	27,600	26,290	**Depth of bore well (ft.)**	-
Floor types	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	G+2	**Generation of solid wastes:** Nil	
Roof type	Asbestos	RCC	**Generation of Sewerage:** Nil	
Used for	Vacant	Office & Canteen	**Rainwater harvesting** : No	
Used by	Vacant	Vacant	**Other issues** : Nil	
Surrounding area (50m)	Road, vacant land			

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICPA/ NPA/ MPA/ BMRDA/ BIAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Copies of the marked (✓) documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS

WP. No. 38700(b)/2013 Date of visit: 26.02.2015 on 03:45 PM

LOCATION INFORMATION		
Sy. No: 10	**Petitioner Name:** K. V. Prabhakar	**Respondents**
Village Name: Makali	**Distance from River (m):** 840m (Approx.)	1. Commissioner, BDA 2.DC, Bengaluru Rural 3. KSPCB
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** ~2.00	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'05.9" **N**	
Jurisdiction: BDA	**Long**. 77°27'08.5" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
Year of Establishment	2004	**No. of bore wells**	1
Structure size (sq. ft.)	-	**Depth of bore well (ft.)**	-
Floor types	Concrete	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Yes	
Roof type	Junk sheet	**Generation of Sewerage:** Yes	
Used for	03 partitions: Furniture stock, Tiller machine stock and Dry cargoes	**Rainwater harvesting:** No	
Used by	Nilkamal Ltd, SRL Enterprises & Country wide logistics (Rent)	**Other issues:** Soild waste dumped in the premises	
Surrounding area (50m)	Road and vacant land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection Certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Copies of the marked (✓) documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Tiller machine stock and Dry cargos)

ISSUES PHOTO (Solid wastes dumped)

WP. No. 38701/2013 Date of visit: 05.03.2015 on 10:10 A.M.

LOCATION INFORMATION		
Sy. No: 8/2	**Petitioner Name:** Yetivendra Naik	**Respondents**
Village Name: Adakimaranahalli	**Distance from River (m):** 597 (Approx.)	1. Commissioner, BDA 2.DC, Bengaluru Rural 3. KSPCB
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 2.30	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'58.7" **N**	
Jurisdiction: BDA	**Long.** 77°26'55.4" **E**	

STATUS OF SUPERSTRUCTURE			DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	02	**Constructed scheme**	GBY
Type of Superstructures	Godown	Godown	**Fence**	Compound wall
Year of Establishment	2006	2006	**No. of bore wells**	One
Structure size (sq. ft.)	75,000	-	**Depth of bore well (ft.)**	300
Floor types	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	Ground	**Generation of solid wastes:** Nil	
Roof type	Galvanized sheets	Galvanized sheets	**Generation of Sewerage** : Nil	
Used for	Ayurvedic medicines and cosmetics stock	Ayurvedic medicines and cosmetics stock	**Rainwater harvesting** : No	
Used by	Himalaya Drugs (Rent)		**Other issues:** Inside the godown premises construction debris dumped	
Surrounding area (50m)	Road, vacant land			

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any) [Form 15]	✓

Except Form 15, other documents were not submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE



EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Storage of drugs & cosmetics stock)

ISSUES PHOTO

WP. No. 38737/ 2013 Date of visit: 28.02.2015 on 12:45 P.M.

LOCATION INFORMATION		
Sy. No: 13	**Petitioner Name**: Lakshmikantha	**Respondents**
Village Name: Makali	**Distance from River (m):** 100.00 (Approx.)	Govt. of Karnataka and others
Grama Panchayat: Dasanpura	**TGR Zone: 3**	
Hobli Name: Dasanapura	**Extent area (A-G):** 3.31	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'45.9''**N**	
Jurisdiction: BDA	**Long**. 77°27'04.9''**E**	

STATUS OF SUPERSTRUCTURE			DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	1	2	**Constructed scheme**	**GBY**
Type of Superstructures	Godown	Building	**Fence**	Compound wall
Year of Establishment	2006-07	2006-07	**No. of bore wells**	Two
Structure size (sq. ft.)	40,000	-	**Depth of bore well (ft.)**	750
Floor types	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	Ground	**Generation of solid wastes:** Yes	
Roof type	Junk sheet	Junk sheet	**Generation of Sewerage:** Yes, through soak pit waste water disposed	
Used for	Himalaya Drugs stock		**Rainwater harvesting:** No	
Used by	Himalaya Drugs Co. (Rent)		**Other issues:** As per village map this survey number is a water body, which was encroached and godown was constructed.	
Surrounding area (50m)	Waste land			

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

None of the documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE VILLAGE MAP and GOOGLE IMAGES



EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Himalaya Drugs Stock)

ISSUES PHOTO (Construction debris dumped)

WP. No. 38793/ 2013 Date of visit: 28.02.2015 on 10.12 A.M.

LOCATION INFORMATION		
Sy. No: 14	**Petitioner Name** C.S. Puttegowda	**Respondents**
Village Name: Makali	**Distance from River (m):** 1.00 (Approx.)	Govt. of Karnataka and others
Grama Panchayat: Dasanpura	**TGR Zone: 3**	
Hobli Name: Dasanapura	**Extent area (A-G):** 9.10	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'47.2''**N**	
Jurisdiction: BDA	**Long.** 77°27'13.6''**E**	

STATUS OF SUPERSTRUCTURE				DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	1	2	3	**Constructed scheme**	**GBY**
Type of Superstructures	Godown	Building	Building	**Fence**	Compound wall
Year of Establishment	2005-06	2005-06	2005-06	**No. of bore wells**	Two
Structure size (sq. ft.)	44,000	-	-	**Depth of bore well (ft.)**	350
Floor types	Concrete	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	Ground	Ground	**Generation of solid wastes:** Nil	
Roof type	Asbestos sheet	RCC	RCC	**Generation of Sewerage** : Nil	
Used for	Vacant	Labour quarters	Labour quarters	**Rainwater harvesting** : No	
Used by	Vacant			**Other issues:** Construction debris dumped	
Surrounding area (50m)	Godown, Houses and road				

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection Certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	X
4	Tax paid to GP	✓
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Copies of the marked (✓) documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE



EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTO (Vacant)

ISSUES PHOTO (Construction debris dumped)

WP. No. 38795/ 2013 Date of visit: 19.02.2015 on 03:15 P.M.

LOCATION INFORMATION		
Sy. No: 45/1	**Petitioner Name:** B. Saroja Devi	**Respondents**
Village Name: Heggadadevanapura	**Distance from River (m):** 703.59 (Approx.)	1. Commissioner, BDA 2. Principal Secretory, UDD 3. KSPCB 4. DC, Bengaluru Rural
Grama Panchayat: Alur	**TGR Zone: 3**	
Hobli Name: Dasanapura	**Extent area (A-G):** 2.10	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'24.0''**N** **Long.** 77°27'05.2''**E**	
Jurisdiction: BDA		

STATUS OF SUPERSTRUCTURE				DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	1	2	3	**Constructed scheme**	**GBY**
Type of Superstructures	Godown	Building	House	**Fence**	Compound wall
Year of Establishment	2008	2008	2008	**No. of bore wells**	One
Structure size (sq. ft.)	40,000	-	-	**Depth of bore well (ft.)**	800-1000
Floor types	Concrete	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	G+1 Floor	Ground	**Generation of solid wastes:** Nil	
Roof type	Metal Sheet	RCC	RCC	**Generation of Sewerage:** Yes	
Used for	Whirlpool of India Ltd.	Administration of Godown stock	Guest House	**Rainwater harvesting:** Yes (Not working)	
Used by	A&M Enterprises (Rent)		Owner	**Other issues:** Nil	
Surrounding area (50m)	Waste land				

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Copies of the documents (✓) submitted by the petitioner.

STRUCTURE (GOOGLE IMAGE)



DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTO (Whirlpool electronic goods stock)



ISSUES PHOTO (Sewage generation)

WP. No. 38796/2013 Date of visit: 28.02.2015 on 03: 20 P.M.

LOCATION INFORMATION		
Sy. No: 9	**Petitioner Name:** B. Naveen	**Respondents**
Village Name: Makali	**Distance from River (m):** 695 (Approx.)	The Commissioner, BDA & others
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 2.10	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'04.2" **N**	
Jurisdiction: BDA	**Long**. 77°27'00.8" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01 (Partition 1- P1)	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
Year of Establishment	2002	**No. of bore wells**	One
Structure size (sq. ft.)	25,000	**Depth of bore well (ft.)**	-
Floor types	Mud	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Yes	
Roof type	Asbestos sheets	**Generation of Sewerage:** Yes	
Used for	Biscuits stocks	**Rainwater harvesting:** No	
Used by	Parle	**Other issues:** Waste water discharged and solid waste dumped	
Surrounding area (50m)	Road, godown and land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

None of the documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Biscuits, electrical items stock)

ISSUES PHOTOS (Open waste water discharge)

WP. No. 38797/2013 Date of visit: 28.02.2015 on 03: 20 P.M.

LOCATION INFORMATION		
Sy. No: 9	**Petitioner Name:** Bailappa	**Respondents**
Village Name: Makali	**Distance from River (m):** 695 (Approx.)	The Commissioner, BDA & others
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 2.10	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'04.2" **N**	
Jurisdiction: BDA	**Long**. 77°27'00.8" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01 (Partition 2- P2)	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
Year of Establishment	2002	**No. of bore wells**	One
Structure size (sq. ft.)	25,000	**Depth of bore well (ft.)**	-
Floor types	Mud	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Yes	
Roof type	Asbestos sheets	**Generation of Sewerage:** Yes	
Used for	Biscuits stocks	**Rainwater harvesting:** No	
Used by	Parle	**Other issues:** Solid wastes dumped	
Surrounding area (50m)	Road, godown and land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X
None of the documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Biscuits, electrical items stock)

ISSUES PHOTOS (Solid waste dump)

WP. No. 38798/2013 Date of visit: 28.02.2015 on 03: 20 P.M.

LOCATION INFORMATION		
Sy. No: 9	**Petitioner Name:** Smt. Sharada	**Respondents**
Village Name: Makali	**Distance from River (m):** 695 (Approx.)	The Commissioner, BDA & others
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 2.10	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'04.2" **N**	
Jurisdiction: BDA	**Long**. 77°27'00.8" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
Year of Establishment	2002	**No. of bore wells**	One
Structure size (sq. ft.)	12,500	**Depth of bore well (ft.)**	-
Floor types	Mud	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Yes	
Roof type	Asbestos sheets	**Generation of Sewerage:** Yes	
Used for	Electrical goods stock	**Rainwater harvesting:** No	
Used by	Khaitan Electricals	**Other issues:** Solid wastes dumped	
Surrounding area (50m)	Road, godown and land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

None of the documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)



DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Biscuits, electrical items stock)

ISSUES PHOTOS (Solid wastes dumped)



WP. No. 38799/2013 Date of visit: 28.02.2015 on 03: 20 P.M.

LOCATION INFORMATION		
Sy. No: 9	**Petitioner Name:** Mohan	**Respondents**
Village Name: Makali	**Distance from River (m):** 695 (Approx.)	The Commissioner, BDA & others
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 2.10	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'04.2" **N**	
Jurisdiction: BDA	**Long**. 77°27'00.8" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	GBY
Type of Superstructures	Building	**Fence**	Compound wall
Year of Establishment	2002	**No. of bore wells**	One
Structure size (sq. ft.)	-	**Depth of bore well (ft.)**	-
Floor types	Concrete	**ISSUES**	
No. of Floors	G+1	**Generation of solid wastes:** Yes	
Roof type	RCC	**Generation of Sewerage:** Yes	
Used for	07 commercial shops	**Rainwater harvesting:** No	
Used by	On rent	**Other issues:** Waste water discharged and Solid wastes dumped	
Surrounding area (50m)	Road, godown and land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Copies of the documents not submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Dhaba and commercial shops)

ISSUES PHOTOS (Waste water discharged and solid waste dump)

WP. No. 38800/2013 Date of visit: 28.02.2015 on 03:50 P.M.

LOCATION INFORMATION		
Sy. No: 6/2	**Petitioner Name:** Manjesh	**Respondents**
Village Name: Makali	**Distance from River (m):** 310 (Approx.)	The Commissioner, BDA & others
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 4.20	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'01.4" **N**	
Jurisdiction: BDA	**Long.** 77°27'12.3" **E**	

STATUS OF SUPERSTRUCTURE						
No. of Superstructures	01	02	03	04	05	06
Type of Superstructures	Godown	Godown	Building	Godown	Godown	Godown
Year of Establishment	1982	1982	1982	1982	1982	1982
Structure size (sq. ft.)	20,000	22,000	20,000	22,000	20,000	30,000
Floor types	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete
No. of Floors	Ground	Ground	G+1	Ground	Ground	Ground
Roof type	Junk sheet	Junk sheet	Junk sheet	Junk sheet	Junk sheet	Junk sheet
Used for	Logistics (04 partition)	Vehicle spare parts stock	Recycling soaps and talcum powders	Vehicles and logistics stock (3 partition)	Tyres, Vechiles & Food stock (3 partition)	Food and Tiller machine stock (2 partition)
Used by	V –Express/ KP Transport/ Caper Logistics/ Cuba Logistics	Mahendra Co.	Indian Pollution Control Association	Honda/ Visco Rehabilitation	JK Tyres/ Bajaj/ Agrotech Ltd.	Radial Co. and Kirloskar Ltd.
Surrounding area (50m)	Mud road and godowns					

DETAILS OF SUPERSTRUCTURE		ISSUES
Constructed scheme	GBY	**Generation of solid wastes:** Yes
Fence	Compound wall	**Generation of Sewerage:** Yes
No. of bore wells	02	**Rainwater harvesting:** No
Depth of bore well (ft.)	-	**Other issues:** Inside the godown premises, solid waste and burnt wastes dumped

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection Certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any) [Loan details]	✓

Copies of the marked (✓) documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS





UTILITY PHOTOS (Automobiles & spare parts stock, plywood stock)

ISSUES PHOTOS (Solid wastes and burnt wastes)

W. P. No. 39030/2013 Date of visit: 03.03.2015 on 01:15 PM

LOCATION INFORMATION		
Sy No: 5/1	**Petitioner Name:** Niranjan	**Respondents**
Village Name: Siddanahosahalli	**Distance from River (m):** 421 (Approx.)	1. Govt. of Karnataka
Grama Panchayat: Madanayakanahalli	**TGR Zone:** 3	2. BDA
Hobli Name: Dasanpura	**Extent area (A-G):** 6.20	3. DC, Rural
Taluk Name: Bengaluru North	**Geographical Coordinates**	4. KSPCB
District Name: Bengaluru Urban	**Lat.** 13°03'29.0" **N**	
Jurisdiction: BDA	**Long**. 77°27'32.7" **E**	

STATUS OF SUPERSTRUCTURE

No. of Superstructures	01	02	03	04	05	06
Type of Superstructures	Godown	Godown	Godown	Godown	Godown	Godown
Year of Establishment	2005	2014	1994-95	1994-95	2008	1994-95
Structure size (sq. ft.)	-	-	-	-	-	-
Floor types	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete
No. of Floors	Ground	Ground	G+1	G+5	Ground	G+2
Roof type	Galvanized sheet	Galvanized sheet	Galvanized sheet + RCC	Galvanized sheet +RCC	Galvanized sheet	Galvanized sheet + RCC
Used for	Plastic chairs stock	Dry cargos	Vehicle stock	Health care products	Furniture stock	Furniture stock
Used by	Modern Jyothi Products (Rent)	Holizol Logistics (Rent)	Yamaha (Rent)	Ingram health care (Rent)	Urban Ladder (Rent)	Urban Ladder (Rent)
Surrounding area (50m)	Road, Godowns and vacant land					

DETAILS OF SUPERSTRUCTURE		ISSUES
Constructed scheme	GBY	**Generation of solid wastes:** Yes
Fence	Compound wall	**Generation of Sewerage** : Yes
No. of bore wells	2	**Rainwater harvesting** : Yes
Depth of bore well (ft)	300-350	**Other issues:** Solid wastes disposed in the premises

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

None of the documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)



DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Furniture, Dry cargo, Vehicles and medicine stock)



ISSUES PHOTOS (Solid wastes dumped)



WP. No. 39029/2013 Date of visit: 24.02.2015 on 10:05 A.M.

LOCATION INFORMATION		
Sy. No: 65/1	**Petitioner Name:** V. D. Sujatha	**Respondents**
Village Name: Heggadadevanapura	**Distance from River (m):** 714 (Approx.)	1. Govt. of Karnataka
Grama Panchayat: Alur	**TGR Zone:** 3	2. UDD
Hobli Name: Dasanpura	**Extent area (A-G):** 5.09	3. BDA
Taluk Name: Bengaluru North	**Geographical Coordinates**	4. DC, Urban
District Name: Bengaluru Urban	**Lat.** 13°04'26.2" **N**	5. KSPCB
Jurisdiction: BDA	**Long.** 77°27'09.3" **E**	

STATUS OF SUPERSTRUCTURE			DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	02	**Constructed scheme**	GBY
Type of Superstructures	Godown	Godown	**Fence**	Compound wall
Year of Establishment	2008	2008	**No. of bore wells**	Two
Structure size (sq. ft.)	-	-	**Depth of bore well (ft.)**	300
Floor types	Asphalt	Asphalt	**ISSUES**	
No. of Floors	Ground	Ground	**Generation of solid wastes:** Yes	
Roof type	Asbestos sheets	Asbestos sheets	**Generation of Sewerage:** Yes	
Used for	Electrical goods	Electrical goods	**Rainwater harvesting:** No	
Used by	Bajaj Electricals	Bajaj Electricals	**Other issues:** Solid wastes and burnt wastes disposed	
Surrounding area (50m)	Godowns and a farm			

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection Certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any) (Loan sanctioned documents and survey report conducted by private firm)	✓
Copies of the marked (✓) documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Electrical goods stock)

ISSUES PHOTO (Solid wastes disposed)



WP. No. 39614/2013 Date of visit: 26.02.2015 on 01:15 P.M.

LOCATION INFORMATION		
Sy. No: 10	**Petitioner Name:** H.S. Mahadev	**Respondents**
Village Name: Makali	**Distance from River (m):** 607 (Approx.)	Govt. of Karnataka & others
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 7.39	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'07.3" **N**	
Jurisdiction: BDA	**Long.** 77°27'06.2" **E**	

STATUS OF SUPERSTRUCTURE					
No. of Superstructures	01	02	03	04	05
Type of Superstructures	Godown	Godown	Godown	Godown	Godown
Year of Establishment	2008	2008	2009	2010	2009
Structure size (sq. ft.)	-	-	-	-	-
Floor types	Concrete	Concrete	Concrete	Concrete	Concrete
No. of Floors	Ground	Ground	Ground	Ground	Ground
Roof type	Galvanized sheet	Galvanized sheet	Galvanized sheet	Galvanized sheet	Galvanized sheet
Used for	Fevicol stock	Clothes stock	Aluminium angle stock	LPG stock	LPG stock
Used by	Pidilite Industries Ltd. (Rent)	Milistar Retail Pvt. Ltd. (Rent)	Kuhne Nagel Co. (Rent)	Sidma Agency (Rent)	S S Indane Services (Rent)
Surrounding area (50m)	Road, Godowns and vacant land				

DETAILS OF SUPERSTRUCTURE		ISSUES
Constructed scheme	GBY	**Generation of solid wastes:** Yes
Fence	Compound wall	**Generation of Sewerage:** Yes
No. of bore wells	2	**Rainwater Harvesting:** No
Depth of bore well (ft.)	300-350	**Other issues:** Solid wastes disposed in the premises

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP and Tax paid to GP	X
4	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/	X
5	Consent from KSPCB (under Water/ Air Act)	X
6	RTC/ MR documents	X
7	Any others (if any)	X

None of the documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE



EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Glue, garment, Aluminium materials and LPG cylinders stock)





ISSUES PHOTO

WP. No. 39938/2013 Date of visit: 03.03.2015 on 10:15 A.M.

LOCATION INFORMATION		
Sy. No: 6/4	**Petitioner Name:** H. Ravi	**Respondents**
Village Name: Makali	**Distance from River (m):** 840m (Approx.)	Govt. of Karnataka & others
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 4.20	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'12.8" **N**	
Jurisdiction: BDA	**Long**. 77°27'17.6" **E**	

STATUS OF SUPERSTRUCTURE						
No. of Superstructures	01	02	03	04	05	06
Type of Superstructures	Godown	Godown	Godown	Godown	Building	Building
Year of Establishment	2004	2009	2009	2004	2004	2004
Structure size (sq. ft.)	-	-	-	-	-	-
Floor types	Concrete	Concrete	Concrete	Concrete	Concrete	Concrete
No. of Floors	Ground	Ground	G+1	Ground	Ground	G+1
Roof type	Junk sheet	Junk sheet	RCC	Junk sheet	RCC	RCC
Used for	Paper roll stock	Plywood stock	Renovating	Vacant	Labour quarters	Labour quarters
Used by	Private firm	Suraj Wood Products (Rent)	Vacant	Vacant	Labours	Labours
Surrounding area (50m)	Road, godowns					

DETAILS OF SUPERSTRUCTURE		ISSUES
Constructed scheme	GBY	**Generation of solid wastes:** Nil
Fence	Compound wall	**Generation of Sewerage:** Nil
No. of bore wells	One	**Rainwater harvesting:** No
Depth of bore well (ft.)	350	**Other issues:** Inside the godown premises, solid wastes, burnt wastes and construction debris dumped

S. No	PERMISSION GRANTED BY	
1	General License (from GP)	✓
2	No Objection certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP and Tax paid to GP	✓
4	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA	X
5	Consent from KSPCB (under Water/ Air Act), RTC/ MR documents	X
6	Any others (if any) [Loan details]	✓

Copies of the marked (✓) documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Paper rolls, Plywood stock and vacant godwon)





ISSUES PHOTOS

WP. No. 39939/2013 Date of visit: 24.02.2015 on 11: 30 A.M.

LOCATION INFORMATION		
Sy. No: 41/1	**Petitioner Name:** H. Ravi	**Respondents**
Village Name: Heggadadevanapura	**Distance from River (m):** 320 (Approx.)	Govt. of Karnataka & others
Grama Panchayat: Alur	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 2.37	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'18.6" **N**	
Jurisdiction: BDA	**Long**. 77°27'16.4" **E**	

STATUS OF SUPERSTRUCTURE			DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	02	**Constructed scheme**	GBY
Type of Superstructures	Godown	Godown	**Fence**	Compound wall
Year of Establishment	1995/2015 (renovating)	2008	**No. of bore wells**	One
Structure size (sq. ft.)	-	-	**Depth of bore well (ft.)**	300
Floor types	Mud	Mud	**ISSUES**	
No. of Floors	Ground	G+2	**Generation of solid wastes:** Yes	
Roof type	Junk sheets	Junk sheets	**Generation of Sewerage:** Yes	
Used for	Under renovation	Construction materials at ground floor	**Rainwater harvesting:** No	
Used by	Under renovation	-	**Other issues:** Construction debris and solid wastes dumped inside the premises of godown	
Surrounding area (50m)	Highway and godowns			

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Copies of the marked (✓) documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Construction material stock)

ISSUES PHOTOS (Construction debris and solid wastes dumped)

WP. No. 39940/2013 Date of visit: 24.02.2015 on 03:15 P.M.

LOCATION INFORMATION		
Sy. No: 50	**Petitioner Name:** H Ravi	**Respondents**
Village Name: Madanayakanahalli	**Distance from River (m):** 25 (Approx.)	Govt. of Karnataka & others
Grama Panchayat: Madanayakanahalli	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 5.31	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'43.8" **N**	
Jurisdiction: BDA	**Long.** 77°27'17.0" **E**	

STATUS OF SUPERSTRUCTURE

No. of Superstructures	01	02	03	04	05	06
Type of Superstructures	Godown	Godown	Godown	Godown	Godown	Godown
Year of Establishment	1994-95	2008	2008	1994-95	1994-95	1994-95
Structure size (sq. ft.)	-	-	-	-	-	-
Floor types	Mud	Mud	Mud	Mud	Mud	Mud
No. of Floors	Ground	Ground	Ground	Ground	Ground	Ground
Roof type	Junk sheet	Junk sheet	Junk sheets	Junk sheet	Junk sheet	Junk sheet
Used for	Provision items stock	Grocery items stock	Furniture stock	Exhibition stall spares stock	Foot ware stock	Vacant
Used by	Aditya Birla groups	Inland World logistics	Inland World logistics	Logistics execution Co.	Bata	-
Surrounding area (50m)	Road, godowns and river					

DETAILS OF SUPERSTRUCTURE		ISSUES
Constructed scheme	GBY	**Generation of solid wastes:** Yes
Fence	Compound wall	**Generation of Sewerage** : Yes
No. of bore wells	Two	**Rainwater harvesting** : No
Depth of bore well (ft.)	400	**Other issues:** In the godown premises, solid wastes dumped

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP and Tax paid to GP	✓
4	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
5	Consent from KSPCB (under Water/ Air Act)	X
6	RTC/ MR documents	X
7	Any others (if any)	X

Copies of the marked (✓) documents were submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Dry logistics and Foot ware stocks)



ISSUES PHOTOS (Solid wastes dumped)

WP. No. 40193/ 2013 Date of visit: 19.02.2015 on 12:10 P.M.

LOCATION INFORMATION		
Sy. No: 64/4	**Petitioner Name:** K. M. Gayana	**Respondents**
Village Name: Heggadadevanapura	**Distance from River (m):** 500 (Approx.)	1. Govt. of Karnataka 2. BDA 3. DC, Urban 4. KSPCB
Grama Panchayat: Alur	**TGR Zone: 3**	
Hobli Name: Dasanapura	**Extent area (A-G):** 1.00	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'31.6''**N** **Long.** 77°27'06.1''**E**	
Jurisdiction: BDA		

STATUS OF SUPERSTRUCTURE					DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	1	2	3	4	**Constructed scheme**	**GBY**
Type of Superstructures	Godown	Godown	Godown	Godown	**Fence**	Compound wall
Year of Establishment	2000	2000	2000	2000	**No. of bore wells**	One
Structure size (sq. ft.)	-	-	-	-	**Depth of bore well (ft.)**	-
Floor types	Concrete	Concrete	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	Ground	Ground	Ground	**Generation of solid wastes:** Yes	
Roof type	Asbestos	Asbestos	Asbestos	Asbestos	**Generation of Sewerage** : Yes	
Used for	Dry Cargos	Dry Cargos	Dry Cargos	Dry Cargos	**Rainwater harvesting** : No	
Used by	Agarwal Packers and Movers (Rent)				**Other issues:** Waster water discharged from godown	
Surrounding area (50m)	Godowns and road					

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X
None of the documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Dry cargoes)

ISSUES PHOTO (Sewage generated)

WP. No. 40269/2013 Date of visit: 19.02.2015 on 10: 35 A.M.

LOCATION INFORMATION		
Sy. No: 63	**Petitioner Name:** G. S. Rathnamma	**Respondents**
Village Name: Heggadadevanapura	**Distance from River (m):** 804 (Approx.)	The Commissioner, BDA & others
Grama Panchayat: Alur	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 2.00	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'34.7" **N**	
Jurisdiction: BDA	**Long.** 77°27'05.9" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
Year of Establishment	2007	**No. of bore wells**	One
Structure size (sq. ft.)	53,908	**Depth of bore well (ft.)**	-
Floor types	Concrete	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Yes	
Roof type	Galvanized sheets	**Generation of Sewerage:** Nil	
Used for	Vacant godown	**Rainwater harvesting:** No	
Used by	Vacant godown	**Other issues:** Nil	
Surrounding area (50m)	Road, vacant land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

None of the documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTO (Vacant godown)

WP. No. 40270/2013 Date of visit: 28.02.2015 on 05:05 P.M.

LOCATION INFORMATION		
Sy. No: 5/2 and 5/10	**Petitioner Name:** Shailendra Babu	**Respondents**
Village Name: Makali	**Distance from River (m):** 357 (Approx.)	The Commissioner, BDA & others
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 2.00 and 2.00	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'24.4" **N**	
Jurisdiction: BDA	**Long**. 77°27'14.5" **E**	

STATUS OF SUPERSTRUCTURE			DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	02	**Constructed scheme**	GBY
Type of Superstructures	Godown	Godown	**Fence**	Compound wall
Year of Establishment	1982-85	1982-85	**No. of bore wells**	01
Structure size (sq. ft.)	14,000	11,000	**Depth of bore well (ft.)**	300
Floor types	Mud	Mud	**ISSUES**	
No. of Floors	Ground	Ground	**Generation of solid wastes:** Nil	
Roof type	Asbestos	Asbestos	**Generation of Sewerage:** Nil	
Used for	03 partitions: Dry cargoes (Parcels services)	Stock of Birla Ultratech Cement	**Rainwater harvesting:** No	
Used by	Bindya cargo/ Shubhm Freight/ Prakash parcel service	Birla	**Other issues:** Movement of HMVs and burnt wastes in the premises	
Surrounding area (50m)	Road, godowns and vacant land			

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X
Copies of the documents not submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Dry cargos and cement stock)

ISSUES PHOTO (Burnt waste)

WP. No. 40271/2013 Date of visit: 04.04.2015 on 10:15 A.M.

LOCATION INFORMATION		
Sy. No: 64	**Petitioner Name:** Byregowda	**Respondents**
Village Name: Heggadadevanapura	**Distance from River (m):** 780 (Approx.)	The Commissioner, BDA & others
Grama Panchayat: Alur	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 0.30	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'30.8'' **N**	
Jurisdiction: BDA	**Long.** 77°27'05.1'' **E**	

STATUS OF SUPERSTRUCTURE			DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	02	**Constructed scheme**	GBY
Type of Superstructures	Godown	Small building	**Fence**	Compound wall
Year of Establishment	2008	2005	**No. of bore wells**	One
Structure size (sq. ft.)	14,400	-	**Depth of bore well (ft.)**	-
Floor types	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	Ground	**Generation of solid wastes:** Nil	
Roof type	Sheets	RCC	**Generation of Sewerage:** Nil	
Used for	Vacant	Vacant	**Rainwater harvesting:** No	
Used by	Vacant	Vacant	**Other issues:** Solid waste dumped in the premises observed	
Surrounding area (50m)	Road	Road		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Petitioner was absent during the survey. Hence, copies of the documents were not obtained

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS



UTILITY PHOTO (Vacant godown)

ISSUES PHOTOS (Solid wastes dumped)

WP. No. 40272/2013 Date of visit: 26.02.2015 on 04: 30 P.M.

LOCATION INFORMATION		
Sy. No: 65	**Petitioner Name:** H. Sunitha	**Respondents**
Village Name: Heggadadevanapura	**Distance from River (m):** 762 (Approx.)	The Commissioner, BDA & others
Grama Panchayat: Alur	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 1.02	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'29.3" **N**	
Jurisdiction: BDA	**Long.** 77°27'07.7" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
Year of Establishment	1999-2000	**No. of bore wells**	2
Structure size (sq. ft.)	25,000	**Depth of bore well (ft.)**	350
Floor types	Concrete	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Nil	
Roof type	Junk sheet	**Generation of Sewerage:** Nil	
Used for	Vacant	**Rainwater harvesting:** No	
Used by	Vacant	**Other issues:** Weeds surrounding the godown and burnt wastes observed	
Surrounding area (50m)	Road, vacant land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

None of the documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTO (Vacant)

ISSUES PHOTO (Weeds and burnt wastes)

WP. No. 40273/2013 Date of visit: 07.03.2015 on 12:30 P.M.

LOCATION INFORMATION		
Sy. No: 67/4	**Petitioner Name:**	**Respondents**
Village Name: Heggadadevanapura	**Distance from River (m):** 354 (Approx.)	The Commissioner, BDA & others
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 0.37	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'22.8" **N**	
Jurisdiction: BDA	**Long**. 77°27'20.6" **E**	

STATUS OF SUPERSTRUCTURE			DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	02	**Constructed scheme**	GBY
Type of Superstructures	Godown	Small building	**Fence**	Compound wall
Year of Establishment	2012	2012	**No. of bore wells**	One
Structure size (sq. ft.)	21,000	-	**Depth of bore well (ft.)**	300
Floor types	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	Ground	**Generation of solid wastes:** Nil	
Roof type	Junk sheets	RCC	**Generation of Sewerage:** Yes	
Used for	Documents stored in multistory structure	Security office	**Rainwater harvesting:** No	
Used by	Navabharath Archive Xpress (Rent)	Security personnel (Rent)	**Other issues:** Nil	
Surrounding area (50m)	Road, vacant land			

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Petitioner was absent during the survey. Hence, copies of the documents were not obtained

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Storage of documents- database)

WP. No. 40411/2013 Date of visit: 24.02.2015 on 01:00 P.M.

LOCATION INFORMATION		
Sy. No: 53/6, 7	**Petitioner Name:** G. J. Murthy	**Respondents**
Village Name: Madanayakanahalli	**Distance from River (m):** 250 (Approx.)	Govt. of Karnataka and others
Grama Panchayat: Madanayakanahalli	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 1.04	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'43.9" **N**	
Jurisdiction: BDA	**Long**. 77°27'28.4" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
ear of Establishment	2007	**No. of bore wells**	One
Structure size (sq. ft.)	-	**Depth of bore well (ft.)**	630
Floor types	Concrete	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Yes	
Roof type	RCC	**Generation of Sewerage:** Yes	
Used for	Interior designing materials stock	**Rainwater harvesting:** No	
Used by	Pavilions and Interiors	**Other issues:** In the premises scrap items dumped	
Surrounding area (50m)	Highway, godown and vacant land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection Certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	✓
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any) (Loan details and survey report conducted by private firm)	✓
Copies of the marked(✓) documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



OMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTO

UTILITY PHOTOS (Interior designing materials stock)

ISSUES PHOTOS (Scrap dumped)

WP. No. 40412/2013 Date of visit: 24.02.2015 on 01:00 P.M.

LOCATION INFORMATION		
Sy. No: 53/ 8	**Petitioner Name:** Hanumantharayappa	**Respondents**
Village Name: Madanayakanahalli	**Distance from River (m):** 250 (Approx.)	Govt. of Karnataka and others
Grama Panchayat: Madanayakanahalli	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 1.04	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'43.9" **N**	
Jurisdiction: BDA	**Long**. 77°27'28.4" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01 (Partition 1-P1)	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
Year of Establishment	2007	**No. of bore wells**	One
Structure size (sq. ft.)	-	**Depth of bore well (ft.)**	630
Floor types	Concrete	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Yes	
Roof type	Junk sheet	**Generation of Sewerage:** Yes	
Used for	Biscuits stock	**Rainwater harvesting:** No	
Used by	Marie Co.	**Other issues: S**olid wastes and burnt wastes	
Surrounding area (50m)	Highway, godown and vacant land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection Certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	✓
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any) (Loan details and survey report conducted by private firm)	✓
Copies of the marked(✓) documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTO

UTILITY PHOTOS (Biscuits stocks at partition 1)

ISSUES PHOTOS (Solid wastes)

WP. No. 40413/2013 Date of visit: 24.02.2015 on 01:00 P.M.

LOCATION INFORMATION		
Sy. No: 53/9	**Petitioner Name:** Raju	**Respondents**
Village Name: Madanayakanahalli	**Distance from River (m):** 250 (Approx.)	Govt. of Karnataka and others
Grama Panchayat: Madanayakanahalli	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 1.04	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'43.9" **N**	
Jurisdiction: BDA	**Long**. 77°27'28.4" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01 (Partition 2- P2)	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
Year of Establishment	2007	**No. of bore wells**	One
Structure size (sq. ft.)	-	**Depth of bore well (ft.)**	630
Floor types	Concrete	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Yes	
Roof type	Junk sheet	**Generation of Sewerage:** Yes	
Used for	Biscuits stock	**Rainwater harvesting:** No	
Used by	Marie Co.	**Other issues:** Solid wastes and burnt wastes	
Surrounding area (50m)	Highway, godown and vacant land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection Certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	✓
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any) (Loan details and survey report conducted by private firm)	✓
Copies of the marked(✓) documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTO

UTILITY PHOTOS (Biscuits stock at partition 2)

ISSUES PHOTOS (Solid wastes and burnt wastes)

WP. No. 40508/2013 Date of visit: 21.02.2015 on 01:15 P.M.

LOCATION INFORMATION		
Sy. No: 12/7,1,7B	**Petitioner Name:** Govindappa	**Respondents**
Village Name: Madanayakanahalli	**Distance from River (m):** 160 (Approx.)	BMICAPA & others
Grama Panchayat: Madanayakanahalli	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 0.36	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'06.2" **N**	
Jurisdiction: BDA	**Long.** 77°27'35.4" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
Year of Establishment	2007	**No. of bore wells**	-
Structure size (sq. ft.)	12000	**Depth of bore well (ft.)**	-
Floor types	Asphalt	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Yes	
Roof type	Junk sheets	**Generation of Sewerage:** No	
Used for	Hot box stock	**Rainwater harvesting:** No	
Used by	Cello	**Other issues:** Nil	
Surrounding area (50m)	Road and vacant land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection Certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Copies of the marked (✓) documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)

COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Cello- Hot box stock)

WP. No. 40779/ 2013 Date of visit: 21.02.2015 on 10:20 A.M.

LOCATION INFORMATION		
Sy. No: 6/5	**Petitioner Name**: M. Sowbhagya	**Respondents**
Village Name: Madanayakanahalli	**Distance from River (m):** 230.00 (Approx.)	Govt. of Karnataka and others
Grama Panchayat: Madanayakanahalli	**TGR Zone: 3**	
Hobli Name: Dasanapura	**Extent area (A-G):** 0.29	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'56.4''**N**	
Jurisdiction: BDA	**Long.** 77°27'38.3''**E**	

STATUS OF SUPERSTRUCTURE			DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	1	2	**Constructed scheme**	GBY
Type of Superstructures	Godown	Godown	**Fence**	Compound wall
Year of Establishment	2008	2008	**No. of bore wells**	Nil
Structure size (sq. ft.)	-	-	**Depth of bore well (ft.)**	-
Floor types	Concrete	Concrete	**ISSUES**	
No. of Floors	Ground	Ground	**Generation of solid wastes:** Yes	
Roof type	Galvanized sheets	Galvanized sheets	**Generation of Sewerage:** Yes	
Used for	Amaron Batteries Stock		**Rainwater harvesting:** No	
Used by	Amar Raj Batteries (Rent)	SS Controls (Rent)	**Other issues:** Due to HMV movement air pollution; plastic packing covers and wooden box stored in a room; brunt wastes dumped	
Surrounding area (50m)	Godowns and houses			

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	X
4	Tax paid to GP	✓
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	✓
8	Any others (if any) Sale deed, EC	✓

Copies of the marked (✓) documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)



DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Amaron Batteries stock)

WP. No. 40780/2013 Date of visit: 21.02.2015 on 10:55 A.M.

LOCATION INFORMATION		
Sy. No: 6/8 and 6/4	**Petitioner Name:** M. Sowbhagya	**Respondents**
Village Name: Madanayakanahalli	**Distance from River (m):** 430(Approx.)	Govt. of Karnataka & others
Grama Panchayat: Madanayakanahalli	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 1.08	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'55.5" **N**	
Jurisdiction: BDA	**Long.** 77°27'42.9" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	Vacant land with sheds	**Constructed scheme**	GBY
Type of Superstructures	Brick factory (Closed)	**Fence**	Compound wall
Year of Establishment	2002	**No. of bore wells**	03
Structure size (sq. ft.)	-	**Depth of bore well (ft.)**	400
Floor types	-	**ISSUES**	
No. of Floors	-	**Generation of solid wastes:** Nil	
Roof type	-	**Generation of Sewerage:** Nil	
Used for	Unused machineries	**Rainwater harvesting:** No	
Used by	-	**Other issues:** Location has old, nonfunctional machineries and scraps dumped	
Surrounding area (50m)	Road, vacant land an godown		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any) (Loan obtained document & Survey report carried out by private firm)	X
None of the documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)

COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTO

UTILITY PHOTOS (Location has old, nonfunctional machineries)

ISSUES PHOTO (Scraps dumped)

W.P. No: 40781/2013 Date of visit: 21.02.2015 on 01:15 PM

LOCATION INFORMATION		
Sy No: 53/11	**Petitioner Name:** M. Rangaswamy	**Respondents**
Village Name: Madanayakanahalli	**Distance from River (m):** 265 (Approx.)	The Commissioner, BDA & others
Grama Panchayat: Madanayakanahalli	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 1.00	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'41.5" **N**	
Jurisdiction: BDA	**Long.** 77°27'27.8" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
Year of Establishment	2006	**No. of bore wells**	
Structure size (sq. ft.)	40,000	**Depth of bore well (ft.)**	
Floor types	Concrete	**ISSUES**	
No. of Floors	G+5	**Generation of solid wastes:** Nil	
Roof type	Both RCC & Asbestos sheets	**Generation of Sewerage:** Nil	
Used for	Vacant	**Rainwater harvesting:** No	
Used by	Vacant	**Other issues:** Building has old, nonfunctional garment machineries	
Surrounding area (50m)	Road, vacant land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICPA/ NPA/ MPA/ BMRDA/ BIAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any) (Loan obtained document & Survey report carried out by private firm)	✓
Copies of the marked (✓) documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS

WP. No. 40782/2013 Date of visit: 24.02.2015 on 02:50 P.M.

LOCATION INFORMATION		
Sy. No: 8/1	**Petitioner Name:** M. Rangaswamy	**Respondents**
Village Name: Madanayakanahalli	**Distance from River (m):** 180 (Approx.)	Govt. of Karnataka & others
Grama Panchayat: Madanayakanahalli	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 1.02	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'55.4" **N**	
Jurisdiction: BDA	**Long**. 77°27'31.8" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	GBY
Type of Superstructures	Godown demolished	**Fence**	Compound wall
Year of Establishment	-	**No. of bore wells**	One
Structure size (sq. ft.)	-	**Depth of bore well (ft.)**	-
Floor types	-	**ISSUES**	
No. of Floors	-	**Generation of solid wastes:**	-
Roof type	-	**Generation of Sewerage:**	-
Used for	-	**Rainwater harvesting:**	-
Used by	-	**Other issues:** This place is used to park goods/ cargo lorries	
Surrounding area (50m)	Road, godown & vacant land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X
None of the documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS (Godown demolished- vacant land)

UTILITY PHOTOS (Vacant land)

WP. No. 40783/2013 Date of visit: 24.02.2015 on 12:25 P.M.

LOCATION INFORMATION		
Sy. No: 53/10	**Petitioner Name:** Timmarasaiah	**Respondents**
Village Name: Madanayakanahalli	**Distance from River (m):** 250 (Approx.)	Govt. of Karnataka & others
Grama Panchayat: Madanayakanahalli	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 1.00	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'42.4" **N**	
Jurisdiction: BDA	**Long**. 77°27'28.0" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
Year of Establishment	2008-09	**No. of bore wells**	One
Structure size (sq. ft.)	30,000	**Depth of bore well (ft.)**	600
Floor types	Concrete	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Nil	
Roof type	Asbestos sheet	**Generation of Sewerage:** Nil	
Used for	Vacant	**Rainwater harvesting:** No	
Used by	Vacant	**Other issues:** Nil	
Surrounding area (50m)	Godowns and road		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	✓
2	No Objection Certificate (issued by GPs for electrical supply)	✓
3	Plan approval by GP	✓
4	Tax paid to GP	✓
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Copies of the marked (✓) documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTO

PHOTO (Vacant godown)

WP. No. 40970/2013 Date of visit: 03.03.2015 on 01:20 P.M.

LOCATION INFORMATION		
Sy. No: 27/2C & 31/2A	**Petitioner Name:** K. Govindraju	**Respondents**
Village Name: Siddanahosahalli	**Distance from River (m): 740** (Approx.)	The Commissioner, BDA & others
Grama Panchayat: Madanayakanahalli	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 2.02	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'21.5" **N**	
Jurisdiction: BDA	**Long**. 77°27'37.6" **E**	

STATUS OF SUPERSTRUCTURE					
No. of Superstructures	At 27/2C	01 at 31/2A	02 at 31/2A	03 at 31/2A	04 at 31/2A
Type of Superstructures	Land	Godown	Godown	Building	Building
Year of Establishment	-	2013	2013	2013	2013
Structure size (sq. ft.)	-	-	-	-	-
Floor types	-	Concrete	Concrete	Concrete	Concrete
No. of Floors	-	Ground	Ground	Ground	Ground
Roof type	-	Junk sheet	Junk sheet	RCC	RCC
Used for	Telecom materials (OFCs rolls, Metal angles, stock)	Telecom materials	Telecom materials	Labour quarters	Security Office
Used by	Reliance Telecom (Rent)	Himachal Futuristic Communication Ltd. (Rent)		Labours	Security personnel
Surrounding area (50m)	Road and godowns				

DETAILS OF SUPERSTRUCTURE		ISSUES
Constructed scheme	GBY	**Generation of solid wastes:** Yes
Fence	Compound wall	**Generation of Sewerage:** Yes
No. of bore wells	One	**Rainwater harvesting:** No
Depth of bore well (ft.)	400	**Other issues:** Unused metal pipes, machineries and scrap items dumped

S. No	PERMISSION GRANTED BY	
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP and Tax paid to GP	X
4	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA	X
5	Consent from KSPCB (under Water/ Air Act)	X
6	RTC/ MR documents and any others (if any) [Loan details]	X

None of the documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)



DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS



UTILITY PHOTOS

ISSUES PHOTO (Unused metal pipes, machineries and scrap items dumped)

WP. No. 41042/2013 Date of visit: 21.02.2015 on 01:15 P.M.

LOCATION INFORMATION		
Sy. No: 66/7	**Petitioner Name:** Smt.Shivamma	**Respondents**
Village Name: Madanayakanahalli	**Distance from River (m):** 265 (Approx.)	The Commissioner, BDA & others
Grama Panchayat: Madanayakanahalli	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 2.08	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'56.2" **N**	
Jurisdiction: BDA	**Long.** 77°27'44.1" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
Year of Establishment	2007	**No. of bore wells**	-
Structure size (sq. ft.)	-	**Depth of bore well (ft.)**	-
Floor types	Concrete	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Yes	
Roof type	Asbestos sheets	**Generation of Sewerage:** No	
Used for	Glucon D stock	**Rainwater harvesting:** No	
Used by	Heinz India	**Other issues:** Solid wastes dumped and HMVs movement	
Surrounding area (50m)	Road, vacant land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any) (Loan obtained document & Survey report carried out by private firm)	✓
Copies of the marked (✓) documents submitted by the petitioner		

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE



EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Glucon D stock)

ISSUES PHOTOS (Solid wastes dumped)

WP. No. 41043/2013 Date of visit: 21.02.2015 on 01:15 P.M.

LOCATION INFORMATION		
Sy. No: 66/7	**Petitioner Name:** Jayanna	**Respondents**
Village Name: Madanayakanahalli	**Distance from River (m):** 265 (Approx.)	The Commissioner, BDA & others
Grama Panchayat: Madanayakanahalli	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 2.08	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°03'56.2" **N**	
Jurisdiction: BDA	**Long.** 77°27'44.1" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	GBY
Type of Superstructures	Godown	**Fence**	Compound wall
Year of Establishment	2007	**No. of bore wells**	-
Structure size (sq. ft.)	-	**Depth of bore well (ft.)**	-
Floor types	Concrete	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Yes	
Roof type	Junk sheets	**Generation of Sewerage:** No	
Used for	Corn flakes stock & automobiles spare parts	**Rainwater harvesting:** No	
Used by	Access Pvt. Ltd (Kelloggs)	**Other issues:** Solid wastes dumped and HMVs movement	
Surrounding area (50m)	Road, vacant land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any) (Loan obtained document & Survey report carried out by private firm)	✓

Copies of the marked (✓) documents submitted by the petitioner

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)

COMPARATIVE GOOGLE IMAGE



EXISTING SUPERSTRUCTURES PHOTOS

UTILITY PHOTOS (Cornflakes stock)

ISSUES PHOTOS (Solid wastes dumped)

WP. No. 41793/2013 Date of visit: 07.03.2015 on 02:00 P.M.

LOCATION INFORMATION		
Sy. No: 100	**Petitioner Name:** Siddagangamma & Karnataka Adi Jambava Social & Educational Trust	**Respondents**
Village Name: Dasanpura	**Distance from River (m):** 1150 (Approx.)	BDA & others
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 25.00	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'39.2" **N**	
Jurisdiction: BDA	**Long.** 77°26'58.6" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	GBY
Type of Superstructures	Building	**Fence**	Compound wall
Year of Establishment	2004	**No. of bore wells**	One
Structure size (sq. ft.)	-	**Depth of bore well (ft.)**	300
Floor types	Concrete	**ISSUES**	
No. of Floors	G+1	**Generation of solid wastes:** Nil	
Roof type	RCC	**Generation of Sewerage:** Nil	
Used for	Nursing and Medical college	**Rainwater Harvesting:** No	
Used by	BJR College of Nursing and Medical college, building, 6 months ago college was closed.	**Other issues:** Nil	
Surrounding area (50m)	Road and vacant land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Petitioner was absent during the survey. Hence, copies of the documents were not obtained

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE



EXISTING SUPERSTRUCTURES PHOTOS (Nursing and Medical college building)

UTILITY PHOTOS (Vacant class rooms)

WP. No. 41794/2013 Date of visit: 07.03.2015 on 02:00 P.M.

LOCATION INFORMATION		
Sy. No: 100	**Petitioner Name:** Siddagangamma & Karnataka Adi Jambava Social & Educational Trust	**Respondents**
Village Name: Dasanpura	**Distance from River (m):** 1150 (Approx.)	BDA & others
Grama Panchayat: Dasanpura	**TGR Zone:** 3	
Hobli Name: Dasanpura	**Extent area (A-G):** 25.00	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°04'39.2" **N**	
Jurisdiction: BDA	**Long.** 77°26'58.6" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	02	**Constructed scheme**	GBY
Type of Superstructures	Building	**Fence**	Compound wall
Year of Establishment	2004	**No. of bore wells**	One
Structure size (sq. ft.)	-	**Depth of bore well (ft.)**	300
Floor types	Concrete	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Nil	
Roof type	RCC	**Generation of Sewerage:** Nil	
Used for	Nursing and Medical college Hostel	**Rainwater Harvesting:** No	
Used by	BJR College of Nursing and Medical college, building, 6 months ago college was closed.	**Other issues:** Nil	
Surrounding area (50m)	Road and vacant land		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Petitioner was absent during the survey. Hence, copies of the documents were not obtained

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTOS (Nursing and Medical college Hostel building)

UTILITY PHOTOS (Vacant rooms in hostel)

WP. No. 44160/2013 Date of visit: 04.04.2015 on 12:05 P.M.

LOCATION INFORMATION		
Sy. No: 74	**Petitioner Name:** Shirley Oliver	**Respondents**
Village Name: Huralichikkanahalli	**Distance from River (m):** 1660 (Approx.)	The Commissioner, BDA & others
Grama Panchayat: Huralichikkanahalli	**TGR Zone:** 4	
Hobli Name: Hesaraghatta	**Extent area (A-G):** 4.19	
Taluk Name: Bengaluru North	**Geographical Coordinates**	
District Name: Bengaluru Urban	**Lat.** 13°06'47.1" **N**	
Jurisdiction: BDA	**Long.** 77°29'51.4" **E**	

STATUS OF SUPERSTRUCTURE		DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01	**Constructed scheme**	-
Type of Superstructures	Industry/Factory	**Fence**	Fenced
Year of Establishment	2004	**No. of bore wells**	One
Structure size (sq. ft.)	-	**Depth of bore well (ft.)**	-
Floor types	Concrete	**ISSUES**	
No. of Floors	Ground	**Generation of solid wastes:** Yes	
Roof type	Sheets	**Generation of Sewerage:** Yes	
Used for	Assembling of welding machines and within the building one portion is utilized for office staff for accommodation	**Rainwater harvesting:** No	
Used by	Colton Industry	**Other issues:** Scrap stored in the premises	
Surrounding area (50m)	Road, Coconut, Mango and Sapota plantations		

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Petitioner was absent during the survey. Hence, copies of the documents were not obtained

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)



COMPARATIVE GOOGLE IMAGE

EXISTING SUPERSTRUCTURES PHOTO

UTILITY PHOTOS (Assembling unit of welding machine)



ISSUES PHOTOS (Scrap stored in the premises)

WP. No. 58328/2013 Date of visit: 31.03.2015 on 02:45 P.M.

LOCATION INFORMATION		
Sy. No: 74	**Petitioner Name:** Radika Ganesh	**Respondents**
Village Name: Basavanahalli	**Distance from River (m):** 770 (Approx.)	1. Secretary, Govt. of Karnataka,
Grama Panchayat: Basavanahalli	**TGR Zone:** 3	2. Revenue department
Hobli Name: Solur	**Extent area (A-G):** 5.06	3. DC, Ramanagara
Taluk Name: Magadi	**Geographical Coordinates**	4. Town and Country Planning
District Name: Ramanagara	**Lat.** 13°02'04.4" **N**	5. NPA
Jurisdiction: MPA	**Long.** 77°19'16.9" **E**	

STATUS OF SUPERSTRUCTURE			DETAILS OF SUPERSTRUCTURE	
No. of Superstructures	01 (Layout)	02	**Constructed scheme**	-
Type of Superstructures	Layout construction	Shed	**Fence**	-
Year of Establishment	Layout construction (development) under progress	2014	**No. of bore wells**	One
Structure size (sq. ft.)			**Depth of bore well (ft.)**	350
Floor types	-	Concrete	**ISSUES**	
No. of Floors	-	Ground	**Generation of solid wastes:** Nil	
Roof type	-	Asbestos sheet	**Generation of Sewerage:** Nil	
Used for	Layout	Security office	**Rainwater harvesting:** No	
Used by	-	Security personnel	**Other issues:** Stone removal	
Surrounding area (50m)	Road and vacant land			

S. No	PERMISSION GRANTED BY	DOCUMENTS
1	General License (from GP)	X
2	No Objection Certificate (issued by GPs for electrical supply)	X
3	Plan approval by GP	X
4	Tax paid to GP	X
5	Jurisdiction (Planning authority approval): BDA/ BMICAPA/ NPA/ MPA/ BMRDA/ BIAAPA	X
6	Consent from KSPCB (under Water/ Air Act)	X
7	RTC/ MR documents	X
8	Any others (if any)	X

Petitioner was absent during the survey. Hence, copies of the documents were not obtained

STRUCTURE (GOOGLE IMAGE)

DISTANCE FROM RIVER (GOOGLE IMAGE)

COMPARATIVE GOOGLE IMAGE





EXISTING PHOTO (A layout development)

UTILITY PHOTO (A layout development)

ISSUES PHOTO (Stone removal)



Environmental Management and Policy Research Institute

Department of Forest, Ecology and Environment, Government of Karnataka

"Hasirubhavana", Doresanipalya Forest Campus, Vinayakanagar Circle,
J.P.Nagar 5th Phase, Bengaluru-560078, Tel: 080-26490747/46, Fax: 080-26490745,
email: empri.blr@gmail.com www.empri.kar.nic.in

EMPRI
Environmental Management & Policy Research Institute