



Storm Water Drain Work Progress
in West Zone



SWD Work Progress					
Sl No	SWD ID	Progress	Sl No	SWD ID	Progress
1	H200	Completed	43	V114	Not Completed
2	H200	Not Completed	44	V114	Completed
3	H204	In Progress	45	V115	Not Completed
4	H204	Completed	46	V115	Completed
5	V100	Completed	47	V116	Not Completed
6	V100	Completed	48	V116	In Progress
7	V100	Completed	49	V116	Not Completed
8	V100	Completed	50	V116	Completed
9	V100	Not Completed	51	V116	Not Completed
10	V100	Completed	52	V116	Completed
11	V100	In Progress	53	V200	Completed
12	V100	Completed	54	V200	Not Completed
13	V100	Not Completed	55	V202	Completed
14	V100	In Progress	56	V202	Completed
15	V100	Completed	57	V202	Completed
16	V100	In Progress	58	V202	Not Completed
17	V100	In Progress	59	V202	Completed
18	V100	In Progress	60	V202	Completed
19	V100	Completed	61	V202	Not Completed
20	V100	In Progress	62	V202	In Progress
21	V100	In Progress	63	V202	Not Completed
22	V106	In Progress	64	V202	Completed
23	V106	Completed	65	V202	Not Completed
24	V106	In Progress	66	V203	Completed
25	V106	In Progress	67	V203	Not Completed
26	V106	Completed	68	V203	Completed
27	V106	In Progress	69	V203	Completed
28	V106	Completed	70	V203	Not Completed
29	V106	Completed	71	V203	Not Completed
30	V106	In Progress	72	V203	Completed
31	V106	Not Completed	73	V204	Not Completed
32	V107	Not Completed	74	V204	Completed
33	V108	In Progress	75	V205	Completed
34	V108	Completed	76	V205	Not Completed
35	V108A	Not Completed	77	V206	Completed
36	V109	Completed	78	VIC121	Completed
37	V111	Not Completed	79	VIC121	Not Completed
38	V111	Completed	80	VIC121	Completed
39	V112	Completed	81	VIC121	Not Completed
40	V112	In Progress	82	VK122	In Progress
41	V113	Completed	83	VK122	Completed
42	V113	Not Completed	84	VN114	Completed

Vulnerable Location Details			
SL No	V - ID	NAME	Progress
1	48	Agrahara Dasarahalli	Attended
2	49	Ngef Layout	Attended
3	50	Nethaji Nagara	Attended
4	51	Nagamaa Nagara	Attended
5	52	Ravi Badavane	Attended
6	53	Kamala Nagara	Attended
7	54	Shankar Nagara	Attended
8	55	Sanegurvanhalli	To Be Attended
9	56	Sri Rama Nagara	To Be Attended
10	59	Prakesh Nagara Near Mudaliyar Choultry	Attended
11	60	Basaveshwara Nagara	To Be Attended
12	61	Gubanna Industrial Area Srirama Mandira Ward 108	Attended
13	62	Nayandana Halli	Attended
14	63	Link Road	Attended
15	64	Church	To Be Attended
16	65	Sandip Bar Bridge To 5 Th Cross Ravi Layout	Attended
17	66	Nagarbhavi	Attended
18	67	Muni Krishnappa Layout	To Be Attended
19	68	Kino Theater Sheshadripuram	Attended
20	69	Lakshimi Naryanpura	Attended
21	70	Near Pattegar Palya Bridge	Attended
22	71	Near Balenakere	Attended
23	72	Muneshwara Block	Attended
24	73	Kantirava Nagara	Attended
25	74	Shankarappa Garden	Attended

Legend

Encroachment Details

Removed

To Be Removed

Vulnerable Location

Attended

Not Attended

SWD Work Progress

Work Completed

Work in Progress

Work to be done

Main Roads

Railway Line

Ward Boundary

Water Bodies