



Storm Water Drain Work Progress
in East Zone



SWD Work Progress					
Sl No	SWD ID	Progress	Sl No	SWD ID	Progress
1	C100	Not Completed	67	H100	Completed
2	C100	Completed	68	H100	Not Completed
3	C100	Completed	69	H100	Completed
4	C100	Work in Progress	70	H100	Completed
5	C100	Completed	71	H100	Not Completed
6	C100	Completed	72	H101	Completed
7	C100	Completed	73	H101	Not Completed
8	C100	Work in Progress	74	H102	Completed
9	C100	Completed	75	H102A	Completed
10	C100	Not Completed	76	H103	Completed
11	C100	Work in Progress	77	H103	Completed
12	C100	Work in Progress	78	H103	Not Completed
13	C100	Not Completed	79	H104	Work in Progress
14	C100	Completed	80	H200	Completed
15	C100	Completed	81	H200	Not Completed
16	C100	Work in Progress	82	H201	Completed
17	C101	Completed	83	H201	Completed
18	C102	Completed	84	H202	Completed
19	C102	Completed	85	H202	Not Completed
20	C104	Completed	86	H206	Completed
21	C105	Completed	87	H207	Completed
22	C105	Not Completed	88	H300	Work in Progress
23	C105	Work in Progress	89	H306	Completed
24	C105	Not Completed	90	H306	Completed
25	C105	Completed	91	H306	Work in Progress
26	C106	Completed	92	H306	Completed
27	C106	Not Completed	93	H306	Not Completed
28	C200	Completed	94	H306A	Work in Progress
29	C200	Not Completed	95	H306A	Completed
30	C200	Work in Progress	96	H306B	Work in Progress
31	C200	Completed	97	H307	Work in Progress
32	C200	Work in Progress	98	H307	Work in Progress
33	C200	Work in Progress	99	H308	Work in Progress
34	C200	Completed	100	H400	Completed
35	C200	Not Completed	101	H400	Not Completed
36	C202	Completed	102	H400	Completed
37	C203	Work in Progress	103	H400	Not Completed
38	C203	Completed	104	H400	Completed
39	C204	Completed	105	H400	Not Completed
40	C204	Work in Progress	106	H400	Not Completed
41	H 300	Work in Progress	107	H400A	Work in Progress
42	H 300	Work in Progress	108	H401	Work in Progress
43	H 300	Completed	109	H401A	Not Completed
44	H 300	Work in Progress	110	H401A	Work in Progress
45	H 300	Completed	111	H401A	Work in Progress
46	H 300	Completed	112	H401A	Work in Progress
47	H 300	Work in Progress	113	H401A	Work in Progress
48	H 300	Completed	114	H401A	Work in Progress
49	H 300	Work in Progress	115	H401A	Not Completed
50	H 300	Not Completed	116	H401A	Not Completed
51	H 300	Work in Progress	117	H401A	Not Completed
52	H 301	Not Completed	118	H401A	Not Completed
53	H 301	Completed	119	H401A	Not Completed
54	H 302	Work in Progress	120	H401A	Not Completed
55	H 302	Not Completed	121	H401A	Not Completed
56	H 303	Not Completed	122	H401A	Work in Progress
57	H 304	Work in Progress	123	H401A	Work in Progress
58	H 304	Completed	124	H401A	Work in Progress
59	H 304	Completed	125	H401B	Work in Progress
60	H 304 A	Work in Progress	126	H401B	Work in Progress
61	H 304 B	Work in Progress	127	H401B	Completed
62	H 304 C	Work in Progress	128	H401B	Not Completed
63	H 305	Work in Progress	129	MD312	Work in Progress
64	H100	Completed	130	MD313	Completed
65	H100	Not Completed	131	MD313	Work in Progress
66	H100	Completed			

Sl No	V - ID	NAME	Progress
1	1	Cambridge Lyt	Attended
2	2	Koyala Nagara	To Be Attended
3	4	Karmachand Layout Near Kariyama Palya Ward No.24	Attended
4	5	Varasova Lyt	Attended
5	6	Byrassandra	Attended
6	7	Richards Town	Attended
7	8	Kurt Doddi	Attended
8	9	Chinnappa Garden	Attended
9	10	Sh Garden	Attended
10	11	Q Hall	Attended
11	12	Seethappa Layout Rt Nagara	Attended
12	13	Jeevanahalli	Attended
13	14	Sathy nagara	Attended
14	15	Prakruthi Layout Near Hbr Layout (N6)	Attended
15	16	Arm Strong	Attended
16	17	Doddanna Bural Ground H-307 In Ward No.47	Attended
17	18-1	Rajiv Gandhi Colony	Attended
18	18-2	2nd Km Shivajinagara Ward	Attended
19	19-1	Iro Siam	Attended
20	19-2	Pole Bar	Attended
21	20-1	Tempo Stand Jogulpalya	Attended
22	20-2	Appalah Garden	Attended
23	21	Shyampura Railway Gate To Nagawara Main Road In Ward No.23	Attended
24	22	Varasova Palya Ward No.23 Nagawara	Attended
25	23	Kamraj Nagar Near Shyampura Railway Gate	Attended
26	24	Shampura Slum	Attended
27	25	Chakrabanaswadi To Fire Station In Ward No.24	Attended
28	26	Nagawara Main Road To Kamrajnagar In W.No.24	Attended
29	27	Missing Bts In Ward No.24	Attended
30	28	Kamachandappa Layout In Ward No.30	Attended
31	29	Dodda Banasawadi Main Road	Attended
32	30	Jaijavan Nagara Tojoin H-400 In Ward No.27	Attended
33	31	5th Main Road To 7th Main Road In Ward No.27	Attended
34	32	Kayen Nagar In Ward No.27	Attended
35	33	Janak Ram Layout In Ward No.28	Attended
36	34	Kammanahalli Main Road To 5th Main In Ward No.29	Attended
37	35	Kadugondanahalli Ward Area In Ward No.30	Attended
38	36	Basavanna Nagara Near Kadugondanahalli	Attended
39	37	lingarajapura To Kanakadasa Layout Ward No.49	Attended
40	38	lingarajapura Khb Quarters To Hemur Main Road Ward No.49	Attended
41	39	Subbarao Palya Ramachandrapur Layout Sangannagara	Attended
42	40	Alamiya Govt School To Modi Garden (Football Ground) In Ward No.48	Attended
43	41	Ambekar Nagara	Attended
44	42	Bandappa Colony Old Bispanahalli	Attended
45	43	Murugeswarpalya	Attended
46	44	Nathasha	Attended
47	45	RMZ	Attended
48	46	Behind Cammondo Hospital	Attended

Legend

Encroachment Details

Removed

To Be Removed

Vulnerable Location

Attended

Not Attended

SWD Work Progress

Work Completed

Work in Progress

Work to be done

Main Roads

Railway Line

Ward Boundary

Water Bodies