



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahar
StreetID	StreetName	Significant LandMark
W0259	Ambedkar Nagar Slum	Balappa Garden
SegmentNo	TotalLength	
63/S-W0259/S072322	46.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Roads to Concer vency home at Balappa Garden in Ward no 63	200000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	Public Utilities
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000010
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/330/13-14	21/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0186	NA	SWD
SegmentNo	TotalLength	
63/S-W0186/S073336	402.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Reconstruction of Retaining Wall in SWD in Ward no 63	499000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000014
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/334/13-14	21/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0186	NA	Benson Town
SegmentNo	TotalLength	
63/S-W0186/S073914	402.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Repairs to Damaged Portion of Roads at Benson Town in Ward no 63	490000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000016
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/336/13-14	22/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahar
StreetID	StreetName	Significant LandMark
W0186	NA	Queens Road and Xavier's School
SegmentNo	TotalLength	
63/S-W0186/S074239	402.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Deselting of SWD at Queens Road to Xavier's School in Ward no 63	200000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000012
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/332/13-14	21/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0186	NA	Xavier's School to Shivaji Road
SegmentNo	TotalLength	
63/S-W0186/S074551	402.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Deselting of SWD at St. Xavier's School to Shivaji Road in Ward no 63	200000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000013
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/333/13-14	21/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0242	NA	Janker Town
SegmentNo	TotalLength	
63/S-W0242/S075005	265.68	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to Janker Town Surroundings Area in Ward no 63	1000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000018
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/338/13-14	21/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0159	NA	Miller Road
SegmentNo	TotalLength	
63/S-W0159/S075354	190.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of Drain at Miller Road 1st main in Ward no 63	500000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000008
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/328/13-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahar
StreetID	StreetName	Significant LandMark
W0098	NA	Contonement Bridge
SegmentNo	TotalLength	
63/S-W0098/S075719	52.34	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Deselting of Drains and Improvements of Roads at Contonement Bridge Area and Surrounding Roads of Railway Station towards Vasantha Nagar in Ward no 63	1000000	2012
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-12-000063
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/204/13-14	30/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0234	NA	Tasker Town
SegmentNo	TotalLength	
63/S-W0234/S080235	448.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V. Vishwanath 9448489206		0.00
PhoneNo	EmailId	
9448489206		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of Drains and F/P at Tasker Town in Ward no 63	2000000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	063-11-000045
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/TEND/WO/121/12-13	03/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0257	NA	Tasker Town
SegmentNo	TotalLength	
63/S-W0257/S080722	135.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V. Vishwanath 9448489206		0.00
PhoneNo	EmailId	
9448489206		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of Drains and F/P at Tasker Town in Ward no 63	2000000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	063-11-000045
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/TEND/WO/121/12-13	03/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0188	NA	St. Xavier's School
SegmentNo	TotalLength	
63/S-W0188/S080918	76.41	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing CC road at St. Xavier's School near Health Point in Ward no 63	499000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-13-000173
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/215/13-14	03/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0159	NA	Benson Cross Raod
SegmentNo	TotalLength	
63/S-W0159/S081306	190.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of Drains and F/P at Benson Cross Raod and Sorroundings in Ward no 63	700000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-13-000005
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/196/13-14	03/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0046	NA	Millert Road
SegmentNo	TotalLength	
63/S-W0046/S081729	93.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing CC Road to Service road of Miller Road in Ward no 63	400000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-13-000171
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/214/13-14	03/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0161	NA	Benson Road
SegmentNo	TotalLength	
63/S-W0161/S082058	185.22	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing CC Road to Benson Road and Crosses in Ward no 63	900000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-13-000004
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/195/13-14	03/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahar
StreetID	StreetName	Significant LandMark
W0048	NA	Near Anjaneya Temple
SegmentNo	TotalLength	
63/S-W0048/S082611	162.43	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing CC Road Near Anjaneya Temple (Adjustent to Nandidurga Road) in Ward no 63	800000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-13-000003
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/194/13-14	03/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahar
StreetID	StreetName	Significant LandMark
W0222	NA	Balappa Garden
SegmentNo	TotalLength	
63/S-W0222/S093200	133.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to the Drains at Balappa Garden in Ward no 63	200000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000009
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/329/13-14	21/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0062	NA	BBMP Office Ward Building
SegmentNo	TotalLength	
63/S-W0062/S093443	39.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Repairs to BBMP Office Ward Building in Ward no 63	300000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000001
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/321/13-14	21/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahala
StreetID	StreetName	Significant LandMark
W0267	Maheshwari Nagar Ambedkar Rd	Shivaji Nagar
SegmentNo	TotalLength	
63/S-W0267/S093916	43.81	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing CC Road to Damaged portion in Shivaji Nagar Surroundings in Ward no 63	999000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000051
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/160/14-15	09/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0171	NA	Cockburn Road
SegmentNo	TotalLength	
63/S-W0171/S094558	251.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to Cockburn Road from Petrol Bunk to Thimmaiah road in Ward no 63	2215000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000030
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/94/14-15	20/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahar
StreetID	StreetName	Significant LandMark
W0069	NA	Nandidurga Extension
SegmentNo	TotalLength	
63/S-W0069/S095919	176.60	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Deselting of Drains and Improvements to Nandidurga Extension Area in Ward no 63	700000	2012
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-12-000056
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/203/13-14	03/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahar
StreetID	StreetName	Significant LandMark
W0071	NA	Nandidurga Extension
SegmentNo	TotalLength	
63/S-W0071/S100328	120.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Deselting of Drains and Improvements to Nandidurga Extension Area in Ward no 63	700000	2012
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-12-000056
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/203/13-14	03/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0063	Om Shakthi Lyt 6th Crs	Nandidurga Extension
SegmentNo	TotalLength	
63/S-W0063/S100547	310.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Deselting of Drains and Improvements to Nandidurga Extension Area in Ward no 63	700000	2012
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-12-000056
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/203/13-14	03/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0060	NA	Bamboo Bazar
SegmentNo	TotalLength	
63/S-W0060/S101311	114.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Covering Slab for RCC Drain at Bamboo Bazar in Ward no 63	300000	2013
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-13-000176
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/119/14-15	02/09/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0167	NA	Bore Bank Road
SegmentNo	TotalLength	
63/S-W0167/S101853	177.18	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Bore Bank Road and Surroundings in Ward no 63	1000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000007
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/327/13-14	21/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0230	NA	Shivaji Nagar 1st Cross
SegmentNo	TotalLength	
63/S-W0230/S102655	222.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing CC Road to Road at Shivaji Nagar 1st Cross and Surroundings in Ward no 63	270000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-13-000170
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/213/13-14	03/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahar
StreetID	StreetName	Significant LandMark
W0007	NA	3rd Main Road
SegmentNo	TotalLength	
63/S-W0007/S104158	444.98	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 3rd Main Road and Surroundings in Ward no 63	6441000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000026
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/189/14-15	03/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 63	WardName Jayamaharal
StreetID W0037	StreetName NA	Significant LandMark 3rd Main Road
SegmentNo 63/S-W0037/S104556	TotalLength 61.62	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9480828251	EmailId	

Work Details		
NameOfWork Asphalting to 3rd Main Road and Surroundings in Ward no 63	Sanctioned Amount 6441000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Asphalting	Other Work Type
Tender Not a Tender	WorkDetails 0	Job No Work Code 063-14-000026
Work OrderNo EE/SJN/VO/189/14-15	Work Order Date 03/01/2015	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name pujarppa
Date of Inspection 26/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0033	NA	3rd Main Road
SegmentNo	TotalLength	
63/S-W0033/S104737	50.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 3rd Main Road and Surroundings in Ward no 63	6441000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000026
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/189/14-15	03/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahar
StreetID	StreetName	Significant LandMark
W0040	NA	3rd Main Road
SegmentNo	TotalLength	
63/S-W0040/S104836	198.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 3rd Main Road and Surroundings in Ward no 63	6441000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000026
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/189/14-15	03/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0028	NA	3rd Main Road
SegmentNo	TotalLength	
63/S-W0028/S104948	73.33	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 3rd Main Road and Surroundings in Ward no 63	6441000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000026
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/189/14-15	03/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0003	NA	3rd Main Road
SegmentNo	TotalLength	
63/S-W0003/S105056	219.05	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 3rd Main Road and Surroundings in Ward no 63	6441000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000026
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/189/14-15	03/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0034	NA	3rd Main Road
SegmentNo	TotalLength	
63/S-W0034/S105210	65.96	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 3rd Main Road and Surroundings in Ward no 63	6441000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000026
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/189/14-15	03/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahar
StreetID	StreetName	Significant LandMark
W0032	NA	3rd Main Road
SegmentNo	TotalLength	
63/S-W0032/S105307	67.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 3rd Main Road and Surroundings in Ward no 63	6441000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000026
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/189/14-15	03/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0020	NA	3rd Main Road
SegmentNo	TotalLength	
63/S-W0020/S105401	68.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 3rd Main Road and Surroundings in Ward no 63	6441000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000026
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/189/14-15	03/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahar
StreetID	StreetName	Significant LandMark
W0018	NA	3rd Main Road
SegmentNo	TotalLength	
63/S-W0018/S105510	67.84	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 3rd Main Road and Surroundings in Ward no 63	6441000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000026
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/189/14-15	03/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 63	WardName Jayamahar
StreetID W0008	StreetName NA	Significant LandMark 5th Main Road and PWD Quarters
SegmentNo 63/S-W0008/S110020	TotalLength 601.16	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9480828251	EmailId	

Work Details		
NameOfWork Asphalting to 5th Main Road and PWD Quarters Surroundings in Ward no 63	Sanctioned Amount 10257000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Asphalting	Other Work Type
Tender Not a Tender	WorkDetails 0	Job No Work Code 063-14-000025
Work OrderNo EE/SJN/WO/191/14-15	Work Order Date 03/01/2015	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name pujarppa
Date of Inspection 26/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 63	WardName Jayamahar
StreetID W0002	StreetName NA	Significant LandMark 5th Main Road and PWD Quarters
SegmentNo 63/S-W0002/S110217	TotalLength 87.38	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9480828251	EmailId	

Work Details		
NameOfWork Asphalting to 5th Main Road and PWD Quarters Surroundings in Ward no 63	Sanctioned Amount 10257000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Asphalting	Other Work Type
Tender Not a Tender	WorkDetails 0	Job No Work Code 063-14-000025
Work OrderNo EE/SJN/WO/191/14-15	Work Order Date 03/01/2015	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name pujarppa
Date of Inspection 26/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 63	WardName Jayamahala
StreetID W0004	StreetName NA	Significant LandMark 5th Main Road and PWD Quarters
SegmentNo 63/S-W0004/S110325	TotalLength 140.73	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9480828251	EmailId	

Work Details		
NameOfWork Asphalting to 5th Main Road and PWD Quarters Surroundings in Ward no 63	Sanctioned Amount 10257000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Asphalting	Other Work Type
Tender Not a Tender	WorkDetails 0	Job No Work Code 063-14-000025
Work OrderNo EE/SJN/WO/191/14-15	Work Order Date 03/01/2015	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name pujarppa
Date of Inspection 26/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahar
StreetID	StreetName	Significant LandMark
W0006	NA	5th Main Road and PWD Quarters
SegmentNo	TotalLength	
63/S-W0006/S110435	114.89	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 5th Main Road and PWD Quarters Surroundings in Ward no 63	10257000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000025
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/191/14-15	03/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 63	WardName Jayamahar
StreetID W0001	StreetName NA	Significant LandMark 5th Main Road and PWD Quarters
SegmentNo 63/S-W0001/S110643	TotalLength 212.16	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9480828251	EmailId	

Work Details		
NameOfWork Asphalting to 5th Main Road and PWD Quarters Surroundings in Ward no 63	Sanctioned Amount 10257000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Asphalting	Other Work Type
Tender Not a Tender	WorkDetails 0	Job No Work Code 063-14-000025
Work OrderNo EE/SJN/WO/191/14-15	Work Order Date 03/01/2015	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name pujarppa
Date of Inspection 26/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahar
StreetID	StreetName	Significant LandMark
W0012	NA	5th Main Road and PWD Quarters
SegmentNo	TotalLength	
63/S-W0012/S110746	34.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 5th Main Road and PWD Quarters Surroundings in Ward no 63	10257000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000025
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/191/14-15	03/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 63	WardName Jayamahar
StreetID W0005	StreetName NA	Significant LandMark 5th Main Road and PWD Quarters
SegmentNo 63/S-W0005/S110919	TotalLength 119.80	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9480828251	EmailId	

Work Details		
NameOfWork Asphalting to 5th Main Road and PWD Quarters Surroundings in Ward no 63	Sanctioned Amount 10257000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Asphalting	Other Work Type
Tender Not a Tender	WorkDetails 0	Job No Work Code 063-14-000025
Work OrderNo EE/SJN/WO/191/14-15	Work Order Date 03/01/2015	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name pujarppa
Date of Inspection 26/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 63	WardName Jayamahar
StreetID W0009	StreetName NA	Significant LandMark 5th Main Road and PWD Quarters
SegmentNo 63/S-W0009/S111024	TotalLength 44.67	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9480828251	EmailId	

Work Details		
NameOfWork Asphalting to 5th Main Road and PWD Quarters Surroundings in Ward no 63	Sanctioned Amount 10257000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Asphalting	Other Work Type
Tender Not a Tender	WorkDetails 0	Job No Work Code 063-14-000025
Work OrderNo EE/SJN/WO/191/14-15	Work Order Date 03/01/2015	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name pujarppa
Date of Inspection 26/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 63	WardName Jayamahar
StreetID W0014	StreetName NA	Significant LandMark 5th Main Road and PWD Quarters
SegmentNo 63/S-W0014/S111134	TotalLength 185.44	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9480828251	EmailId	

Work Details		
NameOfWork Asphalting to 5th Main Road and PWD Quarters Surroundings in Ward no 63	Sanctioned Amount 10257000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Asphalting	Other Work Type
Tender Not a Tender	WorkDetails 0	Job No Work Code 063-14-000025
Work OrderNo EE/SJN/WO/191/14-15	Work Order Date 03/01/2015	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name pujarppa
Date of Inspection 26/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0036	NA	Jayamahal 1st, 2nd and 3rd Main Roads
SegmentNo	TotalLength	
63/S-W0036/S111617	548.77	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to Jayamahal 1st, 2nd and 3rd Main Roads in Ward no 63	7700000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000024
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/190/14-15	03/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahala
StreetID	StreetName	Significant LandMark
W0029	NA	Jayamahala 1st, 2nd and 3rd Main Roads
SegmentNo	TotalLength	
63/S-W0029/S111834	76.18	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to Jayamahala 1st, 2nd and 3rd Main Roads in Ward no 63	7700000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000024
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/190/14-15	03/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahala
StreetID	StreetName	Significant LandMark
W0038	NA	Jayamahala 1st, 2nd and 3rd Main Roads
SegmentNo	TotalLength	
63/S-W0038/S111954	91.91	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to Jayamahala 1st, 2nd and 3rd Main Roads in Ward no 63	7700000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-14-000024
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/190/14-15	03/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 63	WardName Jayamahahal
StreetID W0023	StreetName NA	Significant LandMark Jayamahahal 1st, 2nd and 3rd Main Roads
SegmentNo 63/S-W0023/S112059	TotalLength 169.14	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9480828251	EmailId	

Work Details		
NameOfWork Asphalting to Jayamahahal 1st, 2nd and 3rd Main Roads in Ward no 63	Sanctioned Amount 7700000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Asphalting	Other Work Type
Tender Not a Tender	WorkDetails 0	Job No Work Code 063-14-000024
Work OrderNo EE/SJN/WO/190/14-15	Work Order Date 03/01/2015	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name pujarppa
Date of Inspection 26/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	63	Jayamahal
StreetID	StreetName	Significant LandMark
W0036	NA	Jayamahal 1st Main Road
SegmentNo	TotalLength	
63/S-W0036/S112216	548.77	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828251		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Eootpath and Drains to Jayamahal 1st main Road in Ward no 63	2000000	2013
Year	Type of Work	Other Work Type
2014 - 2015	Footpath Layering	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	063-13-000030
Work OrderNo	Work Order Date	Period of Extention
EE/SJN/WO/10/14-15	21/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pujarppa
Date of Inspection	Remarks	
26/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	