



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0212	NA	D.C.P office police quaters
SegmentNo	TotalLength	
147/S-W0212/S075744	954.11	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.Kanakaraj		0.00
PhoneNo	EmailId	
7899090815		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drains and Footpaths at 20 th main road & Police Quarters in ward No.147 Adugodi	25	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Footpath Layering	
Tender	WorkDetails	Job No Work Code
Tender	200mtr drain at behind govt. school and 350.00 mtr footpath on both side(from petrol bunk to chamundeshwari temple road)	147-14-000027
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/84/2014-15	14/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0084	NA	Anjaneya Temple
SegmentNo	TotalLength	
147/S-W0084/S052342	21.47	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.B		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	This is work for removal debries and Disiting of drains	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14 dt 31-10-2013	25/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
10/09/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 147	WardName Adugodi
StreetID W0082	StreetName NA	Significant LandMark Anjaneya temple
SegmentNo 147/S-W0082/S052754	TotalLength 27.36	

ContractorDetails		
NameofContractor Patel.b	ContractorRegNo	Expenditure 0.00
PhoneNo 9448561985	EmailId	

Work Details		
NameOfWork Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	Sanctioned Amount 12	Sanctioned Year
Year 2012 - 2013	Type of Work Others	Other Work Type
Tender Tender	WorkDetails This is work for removal debries and Disiting of drains	Job No Work Code 147-13-000048
Work OrderNo EE(BTM)/Je/e-Proc/W.O/71/2013-14	Work Order Date 21/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 147	WardName Adugodi
StreetID W0080	StreetName NA	Significant LandMark Anjaneya temple
SegmentNo 147/S-W0080/S053046	TotalLength 31.43	

ContractorDetails		
NameofContractor Patel.b	ContractorRegNo	Expenditure 0.00
PhoneNo 9448561985	EmailId	

Work Details		
NameOfWork Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	Sanctioned Amount 12	Sanctioned Year
Year 2012 - 2013	Type of Work Others	Other Work Type
Tender Tender	WorkDetails This is work for removal debries and Disiting of drains	Job No Work Code 147-13-000048
Work OrderNo EE(BTM)/Je/e-Proc/W.O/71/2013-14	Work Order Date 21/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0070	NA	Anjaneya tmple
SegmentNo	TotalLength	
147/S-W0070/S053237	34.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	This is work for removal debries and Disiting of drains	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0066	NA	Anjaneya temple
SegmentNo	TotalLength	
147/S-W0066/S053402	34.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	This is work for removal debries and Disiting of drains	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0060	NA	Anjaneya temple
SegmentNo	TotalLength	
147/S-W0060/S053516	31.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.B		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013 -14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0058	NA	Anjaneya Temple
SegmentNo	TotalLength	
147/S-W0058/S053758	31.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.B		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
	This is work for removal debries and Disiting of drains	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0050	NA	Anjaneya Temple
SegmentNo	TotalLength	
147/S-W0050/S053951	32.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	This is work for removal debries and Disiting of drains	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0048	NA	Ambedka Bhavan
SegmentNo	TotalLength	
147/S-W0048/S054059	34.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender	This is work for removal debries and Disiting of drains	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0044	NA	Ambedkar Bhavan
SegmentNo	TotalLength	
147/S-W0044/S054232	35.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2		
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender	This is work for removal debries and Disiting of drains	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 147	WardName Adugodi
StreetID W0034	StreetName NA	Significant LandMark Ambedka bhavan
SegmentNo 147/S-W0034/S054332	TotalLength 37.89	

ContractorDetails		
NameofContractor Patel.b	ContractorRegNo	Expenditure 0.00
PhoneNo 9448561985	EmailId	

Work Details		
NameOfWork Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	Sanctioned Amount 12	Sanctioned Year
Year 2012 - 2013	Type of Work	Other Work Type
Tender Tender	WorkDetails This is work for removal debries and Disiting of drains	Job No Work Code 147-13-000048
Work OrderNo EE(BTM)/Je/e-Proc/W.O/71/2013-14	Work Order Date 21/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0032	NA	Ambedkar bhavan
SegmentNo	TotalLength	
147/S-W0032/S054440	40.68	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender	This is work for removal debries and Disiting of drains	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0022	NA	Ambedkar Bhavan
SegmentNo	TotalLength	
147/S-W0022/S054655	36.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2		
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender	This is work for removal debries and Disiting of drains	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
10/09/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0018	NA	Ambedkar Bhavan
SegmentNo	TotalLength	
147/S-W0018/S054803	31.12	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2		
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender	This is work for removal debries and Disiting of drains	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0014	NA	Ambedkar bhavan
SegmentNo	TotalLength	
147/S-W0014/S054906	27.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender	This is work for removal debries and Disiting of drains	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0021	1st Crs	Near Ambedkar Bhavan
SegmentNo	TotalLength	
147/S-W0021/S055223	57.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender	land mark 1st main road is changed as 15th cross road and This work is for removal debries and Disiting of drains	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0023	2nd Crs	near Ambedkar Bhavan
SegmentNo	TotalLength	
147/S-W0023/S055343	55.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
	Land mark 1st main is changed as 15th cross road and This work is for removal debries and Disiting of drains	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
10/09/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0031	3rd Crs	near Ambedkar bhavan
SegmentNo	TotalLength	
147/S-W0031/S055505	53.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.B		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender	Maintanance work for removal debries and Disiting of drains	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0035	4th Crs	Near ambedkar bhavan
SegmentNo	TotalLength	
147/S-W0035/S055618	52.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.B		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
	Maintanance work for removal debries and Disiting of drains.	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0043	5th Crs	near ambedkar bhavan
SegmentNo	TotalLength	
147/S-W0043/S055736	49.44	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
	Maintanance work for removal of debries and disilting of drains	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0053	6th Crs	Near Ambedkar bhavan
SegmentNo	TotalLength	
147/S-W0053/S061120	47.28	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
		147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
10/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0059	7th Crs	Near Tamil and kannada School
SegmentNo	TotalLength	
147/S-W0059/S061232	44.68	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender	REMOVING OF DEBRIES AND DESILTING OF DRAIN	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0061	8th Crs	Near Tamil and kannada school
SegmentNo	TotalLength	
147/S-W0061/S061350	42.51	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
		147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
10/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0075	9th Crs	Near tamil and kannada school
SegmentNo	TotalLength	
147/S-W0075/S061808	41.27	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2		
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
		147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
10/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0077	10th Crs	near tamil and kannada school
SegmentNo	TotalLength	
147/S-W0077/S061916	38.63	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
		147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
10/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0081	11th Crs	near tamil and kannada school
SegmentNo	TotalLength	
147/S-W0081/S062025	36.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
		147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
10/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0091	12th Crs	Near tamil and kannada school
SegmentNo	TotalLength	
147/S-W0091/S062132	33.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
		147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
10/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0099	13th Crs	Near tamil and kannada school
SegmentNo	TotalLength	
147/S-W0099/S062239	30.81	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
		147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
10/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0105	14th Crs	Near tamil and kannada school
SegmentNo	TotalLength	
147/S-W0105/S062403	29.12	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.b		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2		
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
		147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
10/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0010	16th Crs, Rajendranagar	Beside SWD drain
SegmentNo	TotalLength	
147/S-W0010/S062602	286.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.B		0.00
PhoneNo	EmailId	
9448561985		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private tractor and Labours for Maintainance of Footpath roads and Road side drains Emeregency works in ward no. 147 (Adugodi) For the year 2	12	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender	REMOVING DEBRIES AND DESILTING OF DRAIN	147-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/71/2013-14	21/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0247	1st Main Rd	Near Ambedkar park
SegmentNo	TotalLength	
147/S-W0247/S063958	162.75	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480701749		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains and footpath of 1st F main road and surrounding area roads in 8th block, koramangala in ward No.147	12.35	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender	Construction flagging course and B.S.Paving slabs and Culverts	147-13-000052
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/249/2013-14	31/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0147	NA	RAM MANDIR
SegmentNo	TotalLength	
147/S-W0147/S035013	30.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.Pratheek		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Cement Concrete to roads at Devegouda block and adugodi in ward no.147	19.96	
Year	Type of Work	Other Work Type
	Others	
Tender	WorkDetails	Job No Work Code
Tender	CONCRETE ROAD	147-11-000011
Work OrderNo	Work Order Date	Period of Extention
EE/(BTM)/W.O/JE/23/2010-11	16/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
10/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0175	NA	ram mandir
SegmentNo	TotalLength	
147/S-W0175/S042134	62.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.Pratheek		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Cement Concrete to damaged roads at adugodi and 8th block koramangala in ward no.147	19.9	
Year	Type of Work	Other Work Type
	Others	
Tender	WorkDetails	Job No Work Code
Tender	Concrete road	147-11-000039
Work OrderNo	Work Order Date	Period of Extention
EE/(BTM)/W.O/je/e-Tend/214/2011-12	13/09/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
10/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0013	1st Crs, Rajendranagar	Ambedkar bhavan
SegmentNo	TotalLength	
147/S-W0013/S043321	591.09	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C. Munireddy		0.00
PhoneNo	EmailId	
9342510737		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Concreting of damaged 1st main road (Reach-2) and surrounding roads at Rajendra nagar slum at adugodi in ward no.147	10.25	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	Concrete road	147-12-000038
Work OrderNo	Work Order Date	Period of Extention
EE/(BTM)/W.O/je/e-Tend/10/2012-13	12/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0109	Link Rd	opp to passs port office
SegmentNo	TotalLength	
147/S-W0109/S044749	717.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C. munireddy		0.00
PhoneNo	EmailId	
9342510737		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of R.C.C box drain at opp. passport office and surrounding roads at rajendra nagar slum at adugodi in ward no.147	15.8	
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	R.C.C box drain	147-12-000039
Work OrderNo	Work Order Date	Period of Extention
EE/(BTM)/W.O/je/e-Tend/11/2012-13	12/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 147	WardName Adugodi
StreetID W0079, W0076, W0096, W0092, W0068	StreetName 10th Main Rd, 8th C Crs, 6th Crs, Rajendranagar, 7th D Crs, 9th Crs, Rajendranagar	Significant LandMark karumariamamma temple
SegmentNo 147/C-W0079/S053617	TotalLength 78.82	

ContractorDetails		
NameofContractor C. Munireddy	ContractorRegNo	Expenditure 0.00
PhoneNo 9342510737	EmailId	

Work Details		
NameOfWork Construction of R.C.C box drain at 10th main road (reach- 1) and surrounding roads at rajendra nagar slum at adugodi in ward no.147	Sanctioned Amount 14.38	Sanctioned Year
Year 2012 - 2013	Type of Work Others	Other Work Type
Tender Tender	WorkDetails Concrete road	Job No Work Code 147-12-000036
Work OrderNo EE/(BTM)/W.O/je/e-Tend/07/2012 -13	Work Order Date 12/06/2012	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 147	WardName Adugodi
StreetID W0079, W0020, W0042, W0056, W0046, W0068, W0077, W	StreetName 10th Main Rd, 3rd Main Rd, Rajendranagar, 13th D Crs, NA, 12th Crs, Rajendranagar, 9th Crs, Rajendr	Significant LandMark karumariamamma temple
SegmentNo 147/C-W0079/S054906	TotalLength 153.23	

ContractorDetails		
NameofContractor c. Munireddy	ContractorRegNo	Expenditure 0.00
PhoneNo 9342510737	EmailId	

Work Details		
NameOfWork Construction of R.C.C box drain at 10th main road (reach- 1) and surrounding roads at rajendra nagar slum at adugodi in ward no.147	Sanctioned Amount 10.2	Sanctioned Year
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails RCC BOX DRAIN REACH-2	Job No Work Code 147-12-000046
Work OrderNo EE/(BTM)/W.O/je/e-Tend/08/2012 -13	Work Order Date 12/06/2012	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name savitri
Date of Inspection 11/09/2015	Remarks
Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0096	6th Crs, Rajendranagar	Madini majid
SegmentNo	TotalLength	
147/S-W0096/S060451	216.84	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C. munireddy		0.00
PhoneNo	EmailId	
9342510737		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of R.C.C box drain at 6th cross road (reach-1) and surrounding roads at rajendra nagar slum at adugodi in ward no.147	13	
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	R.C.C box drain	147-12-000032
Work OrderNo	Work Order Date	Period of Extention
EE/(BTM)/W.O/je/e-Tend/03/2012-13	12/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 147	WardName Adugodi
StreetID W0096, W0064, W0088, W0068, W0033, W0072	StreetName 6th Crs, Rajendranagar, 10th B Crs, 7th Crs, 9th Crs, Rajendranagar, 4th Main Rd, NA	Significant LandMark madani majid
SegmentNo 147/C-W0096/S061120	TotalLength 121.11	

ContractorDetails		
NameofContractor .munireddy	ContractorRegNo	Expenditure 0.00
PhoneNo 9342510737	EmailId	

Work Details		
NameOfWork Construction of R.C.C box drain at 4h cross road (reach- 2) and surrounding roads at rajendra nagar slum at adugodi in ward no.147	Sanctioned Amount 10.2	Sanctioned Year
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails RCC Box drain, Name of work Reach-2 is changed as reach-1, Work order no 06 is changed as 05, Job code no. 147-12-000035 is changed as 147-12-000034.	Job No Work Code 147-12-000035
Work OrderNo EE/(BTM)/W.O/je/e-Tend/06/2012 -13	Work Order Date 12/06/2012	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0188	NA	Ambedkar park
SegmentNo	TotalLength	
147/S-W0188/S065524	241.26	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager Karnataka Rural Infrastructure Development Ltd		0.00
PhoneNo	EmailId	
Work Details		
9900862091		

NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of R.C.C box to shiva theatre road right side from shaneshwar temple to 2nd cross road and surrounding roads at 8th block, koramangala i	19.98	
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
	construction of RCC box drain	147-13-000036
Work OrderNo	Work Order Date	Period of Extention
EE/(BTM)/W.O/254/2013-14	31/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0261	NA	Bheem chandra kalyan mantap
SegmentNo	TotalLength	
147/S-W0261/S070517	48.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.Krishna		0.00
PhoneNo	EmailId	
9740377357		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains and Footpath of 3 rd main , 2nd main (from Bheema chandra Kalyana mantappa to towards Tata indicom) and Road connect	19.99	
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
	CONSTRUCTION OF FLAGGING COARSE OF DRAIN AND CULVERT	147-13-000063
Work OrderNo	Work Order Date	Period of Extention
EE/(BTM)/Je/e-Proc/W.O/29/2013 -14	09/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
08/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0218	3rd Crs	Bheema chandra Kalyan Mantap
SegmentNo	TotalLength	
147/S-W0218/S072836	108.56	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.Krishna		0.00
PhoneNo	EmailId	
9740377357		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains and Footpath of 3 rd main , 2nd main (from Bheema chandra Kalyana mantappa to towards Tata indicom) and Road connect	19.99	
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
	CONSTRUCTION OF FLAGGING COARSE TO DRAIN AND CULVERT	147-13-000063
Work OrderNo	Work Order Date	Period of Extention
EE/(BTM)/Je/e-Proc/W.O/29/2013 -14	09/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
08/09/2015	

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0123	2nd A Main Rd	Corporation Bank
SegmentNo	TotalLength	
147/S-W0123/S074234	112.37	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.Kanaka Raj		0.00
PhoneNo	EmailId	
7899090815		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drains and providing precast slabs at 2 nd A and 2nd B Cross and surrounding cross roads, 8th block, Koramangala in ward no. 147	12.15	
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		147-12-000027
Work OrderNo	Work Order Date	Period of Extention
EE/(BTM)/Je/e-Tend/W.O/138/2012-13	01/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0117	2nd B Main Rd	Corporation bank
SegmentNo	TotalLength	
147/S-W0117/S075031	163.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.Kanaka Raj		0.00
PhoneNo	EmailId	
7899090815		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drains and providing precast slabs at 2 nd A and 2nd B cross and surrounding cross roads, 8th block, Koramangala in ward no. 147	12.15	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender	0	147-12-000027
Work OrderNo	Work Order Date	Period of Extention
EE/(BTM)/Je/e-Tend/W.O/138/2012-13	01/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0202	NA	Ambedkar park
SegmentNo	TotalLength	
147/S-W0202/S075542	144.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T.T.Vasanthkumar		0.00
PhoneNo	EmailId	
9980558555		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drains and providing precast slabs at 2 nd 'D' main and surrounding cross roads, 8th block, Koramangala in ward no. 147	12.5	
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of fagging course to drain and Culvert	147-12-000026
Work OrderNo	Work Order Date	Period of Extention
EE/(BTM)/Je/e-Tend/W.O/163/2012-13	08/10/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Savitri
Date of Inspection	Remarks	
26/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0253	NA	Ambedkar park
SegmentNo	TotalLength	
147/S-W0253/S080011	96.37	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T.T.Vasanthkumar		0.00
PhoneNo	EmailId	
9980558555		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drains and providing precast slabs at 2 nd 'D' main and surrounding cross roads, 8th block, Koramangala in ward no. 147	12.5	
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
	Construction of flagging course to drain and culvert	147-12-000026
Work OrderNo	Work Order Date	Period of Extention
EE/(BTM)/Je/e-Tend/W.O/163/2012-13	08/10/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Savitri
Date of Inspection	Remarks	
26/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0198	NA	Ambedkar park
SegmentNo	TotalLength	
147/S-W0198/S080236	118.05	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T.T.Vasanthkumar		0.00
PhoneNo	EmailId	
9980558555		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drains and providing precast slabs at 2 nd 'D' main and surrounding cross roads, 8th block, Koramangala in ward no. 147	12.5	
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of flagging course to drain and culvert	147-12-000026
Work OrderNo	Work Order Date	Period of Extention
EE/(BTM)/Je/e-Tend/W.O/163/2012-13	08/10/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Savitri
Date of Inspection	Remarks	
26/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0211	NA	Corporation bank
SegmentNo	TotalLength	
147/S-W0211/S081719	89.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.seetharam		0.00
PhoneNo	EmailId	
9341255915		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drains at 3rd A,3rd B,3rd C road and surrounding areas at adugodi in ward no.147	15.27	
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	CONSTRUCTION OF FLAGGING COURSE TO DRAIN	147-11-000043
Work OrderNo	Work Order Date	Period of Extention
EE/(BTM)/Je/e-Tend/W.O/175/2011-12	18/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0237	2nd G Main Rd	Corporation Bank
SegmentNo	TotalLength	
147/S-W0237/S030323	145.76	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.KRISHNA		0.00
PhoneNo	EmailId	
9740377357		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain 2nd 'G' main road @ 8th block surrounding area in ward No.147 Adugodi	15	
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of flagging to Eastern side , ssm drain to western side and B.S.slabs	147-14-000013
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/309/13-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0214	NA	Burial ground
SegmentNo	TotalLength	
147/S-W0214/S031048	136.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.KRISHNA		0.00
PhoneNo	EmailId	
9740377357		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain @ 7th block surrounding area in ward No.147(Adugodi)	10	
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
	Construction of flagging course and B.S.Paving slabs	147-14-000008
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/e-Proc/W.O/310/13-14	24/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0259	NA	BARIAL GROUND
SegmentNo	TotalLength	
147/S-W0259/S031729	100.34	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C. krishna		0.00
PhoneNo	EmailId	
9740377357		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains and Footpath of 3 rd main , 2nd main (from Bheema chandra Kalyana mantappa to towards Tata indicom) and Road connect	19.99	
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	SSM DRAIN	147-13-000063
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/je/e-Proc/W.O/29/13-14	09/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0273	1st Crs	Sangeeta show room
SegmentNo	TotalLength	
147/S-W0273/S034316	202.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager Karnataka Rural Infrastructure Developement Ltd		0.00
PhoneNo	EmailId	
Work Details 9900862091		

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and beautification of footpath at 1st main road from 20th main to dead end and surrounding roads at 7th block Koramangala in war	18	
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
	Constuction of flagging course S.S.M drain and concreting to footpath	147-13-000041
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/259/13-14	07/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
01/09/2015	

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0204	NA	Ambedkar park
SegmentNo	TotalLength	
147/S-W0204/S035335	146.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R.Sheker		0.00
PhoneNo	EmailId	
9916245505		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing precast slabs, kerb stones to drains at 1st cross and surrounding cross, 8th block, koramangala in ward no.147.	14.6	
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN WORK	147-12-000025
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/je/e-Tend/W.O/113/2012-13	12/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0251	NA	Ambedkar park
SegmentNo	TotalLength	
147/S-W0251/S040602	136.39	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R.Sheker		0.00
PhoneNo	EmailId	
9916245505		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing precast slabs, kerb stones to drains at 1st cross and surrounding cross, 8th block, koramangala in ward no.147.	14.6	
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	WORK ORDER DATE CHANGED TO 12-07-2012	147-12-000025
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Tend/W.O/113/2012-13	12/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0229	NA	Govt school
SegmentNo	TotalLength	
147/S-W0229/S041819	384.37	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager, Karnataka Rural Infrastructure Development Ltd		0.00
PhoneNo	EmailId	
Work Details		
9980145519		

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain from Prakruti park to Govt.School @Police Quaters in ward No.147 Adugodi.	15	
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of flagging course to drain and Construction of culvert	-14-000016
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/250/13-14	03/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0220	3rd Crs	bheema chandra kalyan mantap
SegmentNo	TotalLength	
147/S-W0220/S060323	178.97	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.KRISHNA		0.00
PhoneNo	EmailId	
9740377357		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing precast slabs, kerb stones to drains at 1st cross and surrounding cross, 8th block, koramangala in ward no.147.	14	
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	drain work	147-12-000018
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Tend/W.O/53/2012-13	16/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0233	NA	8TH BLOCK PARK SURROUNDING
SegmentNo	TotalLength	
147/S-W0233/S061159	34.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Ramachandra		0.00
PhoneNo	EmailId	
9740377357		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC Box drain to near Nanjappa layout Adjacent police quarters in ward no.147.	9.96	
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
	RCC box drain	147-11-000040
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Tend/W.O/135/2011-12	05/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0263	NA	Bheema chandra kalyan mantap
SegmentNo	TotalLength	
147/S-W0263/S062536	78.50	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.KRISHNA		0.00
PhoneNo	EmailId	
9740377357		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drains at 2nd 3rd and 4th main road and surrounding areas at 7th block, koramangala in ward no.147.	14.98	
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	drain work	147-11-000042
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Tend/W.O/188/2011-12	30/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0249	NA	Ambedkar park, 8th block
SegmentNo	TotalLength	
147/S-W0249/S044300	132.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.B		0.00
PhoneNo	EmailId	
9916364289		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Annual ward maintainance for the year 2013-14 in ward no.147 Adugodi	10	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	This work is for Debries removal and disilting of drains	147-14-000005
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/159/2013-14	21/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0231	NA	Behind Govt school police quaters
SegmentNo	TotalLength	
147/S-W0231/S045124	423.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.B		0.00
PhoneNo	EmailId	
9916364289		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Annual ward maintainance for the year 2013-14 in ward no.147 Adugodi	1000000	
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	Removal of debries and De silting of drains	147-14-000005
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/159/2013-14	21/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0192	NA	opp. chamundeshwari Temple
SegmentNo	TotalLength	
147/S-W0192/S053756	271.42	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.B		0.00
PhoneNo	EmailId	
9916364289		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Annual ward maintainance for the year 2013-14 in ward no.147Adugodi	1000000	
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	Removal of debries and De silting of drain	147-14-000005
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je-e-PROC/w.O/159/2013-14	21/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0208	NA	opp. to Chamundeshwari temple
SegmentNo	TotalLength	
147/S-W0208/S055811	213.60	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.B		0.00
PhoneNo	EmailId	
9916364289		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Annual ward maintainance for the year 2013-14 in ward no.147Adugodi	1000000	
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	Removal debries and de silting of drains	147-14-000005
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.o/159/2013-14	21/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0129	NA	Shiva temple
SegmentNo	TotalLength	
147/S-W0129/S061055	118.47	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.B		0.00
PhoneNo	EmailId	
9916364289		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Annual ward maintainance for the year 2013-14 in ward no.147Adugodi	1000000	
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
Tender	Removal of Debries and de silting of drains	147-14-000005
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/159/2013-14	21/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 147	WardName Adugodi
StreetID W0133	StreetName 13th Main Rd , Mallappa Reddy Main Rd	Significant LandMark NEAR PASSPORT OFFICE
SegmentNo 147/S-W0133/S071737	TotalLength 278.74	

ContractorDetails		
NameofContractor M.NAGESH	ContractorRegNo	Expenditure 0.00
PhoneNo 9535189292	EmailId	

Work Details		
NameOfWork PROVIDING CEMENT CONCRETE TO ROAD NEAR SHIVA THEATER AND SURROUNDING AREAS AT 8TH BLOCK, KORAMANGALA IN WARD No.147	Sanctioned Amount 1990000	Sanctioned Year
Year	Type of Work Road	Other Work Type
Tender	WorkDetails Concrete Road	Job No Work Code 147-11-000038
Work OrderNo EE (BTM)/JE/eTEND/WO/130/2011-12	Work Order Date 05/08/2011	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name savitri
Date of Inspection 01/09/2015	Remarks

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0055	5th Crs	RAJENDRA NAGAR Govt.SCHOOL
SegmentNo	TotalLength	
147/S-W0055/S082712	160.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.RAMESH		0.00
PhoneNo	EmailId	
9845013392		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 8th main roads,Rajendra nagara 7th Main road and surrounding Roads at Adugodi in ward no.147 (Adugodi)	1492000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	ASPHALT ROAD	147-12-000049
Work OrderNo	Work Order Date	Period of Extention
EE (BTM)/Je/e-Tend/W.O/170/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0160	NA	A.K.COLONY
SegmentNo	TotalLength	
147/S-W0160/S085855	113.18	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manage KRID Ltd		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to roads at 7th & 8th block koramangala, Rajendra nagara and surrounding area at Adugodi in ward no.147 (Adugodi)	4000000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
	Asphalt road	147-13-000066
Work OrderNo	Work Order Date	Period of Extention
EE (BTM) /W.O/195/2012-13	07/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0033	4th Main Rd	Rajendra nagara
SegmentNo	TotalLength	
147/S-W0033/S090827	243.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manage KRID Ltd		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to roads at 7th & 8th block koramangala, Rajendra nagara and surrounding area at Adugodi in ward no.147 (Adugodi)	4000000	
Year	Type of Work	Other Work Type
	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	ASPHALT ROAD	147-13-000066
Work OrderNo	Work Order Date	Period of Extention
EE (BTM) /W.O/195/2012-13	07/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0271	NA	ANANDA BHAVAN
SegmentNo	TotalLength	
147/S-W0271/S092314	81.99	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manage KRID Ltd		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to roads at 7th & 8th block koramangala, Rajendra nagara and surrounding area at Adugodi in ward no.147 (Adugodi)	4000000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	ASPHALT ROAD	147-13-000066
Work OrderNo	Work Order Date	Period of Extention
EE (BTM) /W.O/195/2012-13	07/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0236	NA	ANANDA BHAVAN
SegmentNo	TotalLength	
147/S-W0236/S092739	225.11	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manage KRID Ltd		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to roads at 7th & 8th block koramangala, Rajendra nagara and surrounding area at Adugodi in ward no.147 (Adugodi)	4000000	
Year	Type of Work	Other Work Type
	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	ASPHALT ROAD	147-13-000066
Work OrderNo	Work Order Date	Period of Extention
EE (BTM) /W.O/195/2012-13	07/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0265	NA	VODAFONE
SegmentNo	TotalLength	
147/S-W0265/S093016	232.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manage KRID Ltd		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to roads at 7th & 8th block koramangala, Rajendra nagara and surrounding area at Adugodi in ward no.147 (Adugodi)	4000000	
Year	Type of Work	Other Work Type
	Asphaltting	
Tender	WorkDetails	Job No Work Code
	asphalt work	147-13-000066
Work OrderNo	Work Order Date	Period of Extention
EE (BTM) /W.O/195/2012-13	07/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0269	NA	SAI BABA TEMPLE
SegmentNo	TotalLength	
147/S-W0269/S093317	48.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manage KRID Ltd		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to roads at 7th & 8th block koramangala, Rajendra nagara and surrounding area at Adugodi in ward no.147 (Adugodi)	4000000	
Year	Type of Work	Other Work Type
	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	asphalt work	147-13-000066
Work OrderNo	Work Order Date	Period of Extention
EE (BTM) /W.O/195/2012-13	07/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0126	1st A Crs	SHIVA TEMPLE
SegmentNo	TotalLength	
147/S-W0126/S094009	160.47	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manage KRID Ltd		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to roads at 7th & 8th block koramangala, Rajendra nagara and surrounding area at Adugodi in ward no.147 (Adugodi)	4000000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
Tender	ASPHALT ROAD	147-13-000066
Work OrderNo	Work Order Date	Period of Extention
EE (BTM) /W.O/195/2012-13	07/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0232	NA	NEAR ANAND BHAVAN
SegmentNo	TotalLength	
147/S-W0232/S034843	207.25	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.RAMESH		0.00
PhoneNo	EmailId	
9845013392		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to roads at 7th block main roads 8th block 2nd c main road and surrounding area at Adugodi in ward no.147 (Adugodi)	1994000	
Year	Type of Work	Other Work Type
	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	asphalt work	147-12-000050
Work OrderNo	Work Order Date	Period of Extention
EE (BTM) JE/e/Tend/W.O/171/2012-13	15/01/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0245	2nd Main Rd	LAWRENCE SCHOOL
SegmentNo	TotalLength	
147/S-W0245/S040008	223.41	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.RAMESH		0.00
PhoneNo	EmailId	
9845013392		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to roads at 7th block main roads 8th block 2nd c main road and surrounding area at Adugodi in ward no.147 (Adugodi)	1994000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
	asphalt road	147-12-000050
Work OrderNo	Work Order Date	Period of Extention
EE (BTM) JE/e/Tend/W.O/171/2012-13	15/01/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0113	2nd C Main Rd	ADUGODI MAIN ROAD
SegmentNo	TotalLength	
147/S-W0113/S040536	221.05	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.RAMESH		0.00
PhoneNo	EmailId	
9845013392		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to roads at 7th block main roads 8th block 2nd c main road and surrounding area at Adugodi in ward no.147 (Adugodi)	199400	
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
	0	147-12-000050
Work OrderNo	Work Order Date	Period of Extention
EE (BTM) JE/e/Tend/W.O/171/2012-13	15/01/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0228	1st Main Rd Koramangala	OPP STAR BAZAR
SegmentNo	TotalLength	
147/S-W0228/S041025	444.50	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.RAMESH		0.00
PhoneNo	EmailId	
9845013392		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to roads at 1st Main Road, 7th Laskar Hosur roads 20th main road and surrounding area at Adugodi in ward no.147 (Adugodi)	1987000	
Year	Type of Work	Other Work Type
	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	asphalt work	147-12-000048
Work OrderNo	Work Order Date	Period of Extention
EE (BTM) JE/e/Tend/W.O/169/2012-13	15/01/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 147	WardName Adugodi
StreetID W0206	StreetName NA	Significant LandMark MANGALA KALYANA MANTPA
SegmentNo 147/S-W0206/S051839	TotalLength 149.37	

ContractorDetails		
NameofContractor C.Raghuramachandra	ContractorRegNo	Expenditure 0.00
PhoneNo 9945266696	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO ROADSIDE DRAINS AND FOOTPATH OF 1ST CROSS ROAD AND SURROUNDING AREAS ROADS IN 8TH BLOCK KORAMANGALA WARD NO.147	Sanctioned Amount 9000000	Sanctioned Year
Year 2013 - 2014	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Construction of flagging course to drain	Job No Work Code 147-13-000062
Work OrderNo EE(BTM)/JE/e-Proc/WO/54/2013- 14	Work Order Date 24/08/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0020	3rd Main Rd, Rajendranagar	Dr.B.R.AMBEDEKAR BAVAN
SegmentNo	TotalLength	
147/S-W0020/S053352	273.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Y.KIRAN		0.00
PhoneNo	EmailId	
9980145519		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DESILTING OF DRAINS IN WARD NO.147 (ADUGODI)	6000000	
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	COVERED B.S.SLABSSM	147-13-000050
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/je/e-Proc/W.O/05/2013-14	22/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0200	NA	AMBEDKAR PARK
SegmentNo	TotalLength	
147/S-W0200/S070459	81.81	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER KARNATAKA RURAL AND INFRASTRUCTURE DEVELOPEMENT LTD		0.00
PhoneNo	EmailId	
Work Details		
9740246979		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing cement concrete to bad roads in 7th and 8th block in koramangala in ward no.147	15	
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	concrete road	147-11-000025
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/316/2011-12	05/01/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0186	NA	Near Shaneshwar temple
SegmentNo	TotalLength	
147/S-W0186/S105559	120.93	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B.S.Vishwanath		0.00
PhoneNo	EmailId	
9480701749		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains and footpath of 1st E cross road and surrounding area at 8th block koramangala in ward no. 147(Adugodi)		
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of flagging course to drain	147-13-000053
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e/Tend/w.o/289/2012-13	12/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0145	NA	RAMA MANDHIR DEVEGOWDA BLOCK
SegmentNo	TotalLength	
147/S-W0145/S055003	69.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
H.K.KALEGOWDA		0.00
PhoneNo	EmailId	
9740000020		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS IN FRONT OF RAMA MANDHIR ROAD DEVEGOWDA BLOCK IN WARD NO.147 (ADUGODI)	1000000	
Year	Type of Work	Other Work Type
	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
	Construction of SSM drain and culvert	147-14-000011
Work OrderNo	Work Order Date	Period of Extention
EE (BTM) JE/e/Tend/W.O/126/2013-14	20/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Savitri
Date of Inspection	Remarks	
26/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0235	2nd H Main Rd	LAWRENCE SCHOOL
SegmentNo	TotalLength	
147/S-W0235/S055728	307.37	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC BOX DRAIN TO LAWRENCE SCHOOL ROAD FROM 2ND C MAIN ROAD TOWARDS 2ND H MAIN ROAD AND SURROUNDING ROADS AT 8TH BLOCK,KORAMANGA	1998000	
Year	Type of Work	Other Work Type
	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
	Construction of RCC box drain	147-13-000037
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/262/2013-14	07/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
01/09/2015	

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0222	2nd Crs	Burial ground
SegmentNo	TotalLength	
147/S-W0222/S021500	356.45	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Ramesh		0.00
PhoneNo	EmailId	
9845013392		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providind Asphaltting to 7th block main roads, 8th block, 2nd C main road and surrounding roads in Ward No.147(Adugodi)	19.94	
Year	Type of Work	Other Work Type
	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	ASPHALT WORK AND JOB CODE No- 147-12-000050	15.01.2013
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/je/e-Tend/W.O/171/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0057	2nd Crs, Rajendranagar	Karumariamma Temple
SegmentNo	TotalLength	
147/S-W0057/S023353	190.33	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Ramesh		0.00
PhoneNo	EmailId	
9845013392		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
providing Asphaltting to 8th block main roads, Rajendra Nagar 7th main road and surrounding roads at Adugodi in Ward No.147(Adugodi)	14.92	
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	Asphalt road	147-12-000049
Work OrderNo	Work Order Date	Period of Extention
EE/(BTM)/Je/e-Tend/W.O/170/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0247	1st Main Rd	Ambedkar park
SegmentNo	TotalLength	
147/S-W0247/S024221	162.75	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Ramesh		0.00
PhoneNo	EmailId	
9845013392		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to 8th block main roads, Rajendra Nagar 7th main road and surrounding roads at Adugodi in ward no.147(Adugodi)	14.92	
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	Asphalt road Work Order date-15-01-2013	147-12-000049
Work OrderNo	Work Order Date	Period of Extention
EE/(BTM)/Je/e-Tend/W.O./170/2010-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0226	NA	Opp. to Airtel office
SegmentNo	TotalLength	
147/S-W0226/S042720	73.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R,JAGADISHA		0.00
PhoneNo	EmailId	
9008880111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing precast slabs, kerb stones to drains at 1st 'A' main and surrounding cross roads, 7th block, Koramangala in ward no. 147 (Adugodi)	14.95	
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	ssm drain, Work Order Date is Changed as 23-07-2012.	147-12-000022
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Tend/W.O/123/2012-13	23/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 147	WardName Adugodi
StreetID W0275	StreetName NA	Significant LandMark Opp. to Airtel office
SegmentNo 147/S-W0275/S062935	TotalLength 163.41	

ContractorDetails		
NameofContractor R,JAGADISHA	ContractorRegNo	Expenditure 0.00
PhoneNo 9008880111	EmailId	

Work Details		
NameOfWork Providing precast slabs, kerb stones to drains at 1st 'A' main and surrounding cross roads, 7th block, Koramangala in ward no. 147 (Adugodi)	Sanctioned Amount 14.95	Sanctioned Year
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Construction of flagging coarse to drain, Work Order Date is Changed as 23-07-2012.	Job No Work Code 147-12-000022
Work OrderNo EE(BTM)/Je/e-Tend/W.O/123/2012-13	Work Order Date 23/07/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
08/09/2015	

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0224	NA	Opp. to Airtel Office
SegmentNo	TotalLength	
147/S-W0224/S063440	52.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R,JAGADISHA		0.00
PhoneNo	EmailId	
9008880111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing precast slabs, kerb stones to drains at 1st 'A' main and surrounding cross roads, 7th block, Koramangala in ward no. 147 (Adugodi)	14.95	
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	ssm drain, Work order date is Changed as 23-07-2012	147-12-000022
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Tend/W.O/123/2012-13	23/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0046	12th Crs, Rajendranagar	Urdu School
SegmentNo	TotalLength	
147/S-W0046/S064324	264.35	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.MUNIREDDY		0.00
PhoneNo	EmailId	
9342510737		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drians and footpath at 13th cross road at Rajendra nagar in ward no. 147	8.68	
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	ssm drain	147-11-000033
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Tend/W.O/320/2011-12	18/01/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0045	NA	Near Karimaruamma temple
SegmentNo	TotalLength	
147/S-W0045/S031518	56.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Patel.B		0.00
PhoneNo	EmailId	
9916364289		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Annual ward maintainance for the year 2013-14 in ward No. 147 Adugodi	10	
Year	Type of Work	Other Work Type
2013 - 2014	Routine Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	This work is for removal of debries and Disilting of drains.	147-14-000005
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/Je/e-Proc/W.O/159/2013-14	21/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0169	NA	Ram mandir
SegmentNo	TotalLength	
147/S-W0169/S044058	57.44	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.Pratheek		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing cement concrete to roads at Devegouda block and adugodi in ward no.147	19.96	
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
Tender	Concrete road	147-11-000011
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O./Je/23/2010-11	16/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		I
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0163	NA	Ram mandir
SegmentNo	TotalLength	
147/S-W0163/S051908	54.67	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.Pratheek		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing cement concrete to roads at Devegouda block and adugodi in ward no.147	19.96	
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
Tender	Concrete road	147-11-000011
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O./Je/23/2010-11	16/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0157	NA	Ram mandir
SegmentNo	TotalLength	
147/S-W0157/S052221	48.91	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.Pratheek		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing cement concrete to roads at Devegouda block and adugodi in ward no.147	19.96	
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
Tender	Concrete road	147-11-000011
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O./Je/23/2010-11	16/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0155	NA	Ram mandir
SegmentNo	TotalLength	
147/S-W0155/S052434	109.80	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.Pratheek		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing cement concrete to damaged roads at adugodi and 8th block koramangala in ward no.147	19.9	
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
Tender	Concrete road	147-11-000039
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O./Je/e-Tend/214/2011-12	13/09/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0132	NA	Ram mandir
SegmentNo	TotalLength	
147/S-W0132/S053401	298.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.Pratheek		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing cement concrete to damaged roads at adugodi and 8th block koramangala in ward no.147		
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
	Concrete road	147-11-000039
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/je/e-Tend/214/2011-12	13/09/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
12/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0194	NA	Chamundeshwari park
SegmentNo	TotalLength	
147/S-W0194/S042720	79.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager Karnataka Rural Infrastructure Development Ltd		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to Adugodi area, 8th block and surrounding area roads in ward No.147	45	
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
	Asphalt road	147-13-000065
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/193/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0239	NA	Chamundeshwari Park
SegmentNo	TotalLength	
147/S-W0239/S043403	241.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER KARNATAKA RURAL INFRASTRUCTURE DEVELOPEMENT LTD		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Adugodi area, 8th block and surrounding area roads in ward No.147	45	
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
	0	147-13-000065
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.0/193/2012-13	07/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0243	NA	CHAMUNDESHWARI Park
SegmentNo	TotalLength	
147/S-W0243/S044226	171.77	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to Adugodi area,8th block and surrounding area roads in ward No.147	45	
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	Asphalt road	147-13-000065
Work OrderNo	Work Order Date	Period of Extention
EE/(BTM)/W.0/193/2012-13	07/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0241	NA	CHAMUNDESHWARI PARK
SegmentNo	TotalLength	
147/S-W0241/S044740	123.96	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager Karnataka Rural Infrastructure Developement Ltd		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to Adugodi area,8th block and surrounding area roads in ward No.147		
Year	Type of Work	Other Work Type
	Asphaltting	
Tender	WorkDetails	Job No Work Code
	ASPHALTING WORK AND WORK ORDER DATE- 07-03- 2013	147-13-000065
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/193/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0184	NA	CORPORATION BANK
SegmentNo	TotalLength	
147/S-W0184/S045534	116.57	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
kRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to Adugodi area , 8th block and surrounding area roads in ward No.147	45	
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
	0	147-13-000065
Work OrderNo	Work Order Date	Period of Extention
EE/(BTM)/W.O/193/2012-13	07/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0219	N R Layout	Corporation Bank
SegmentNo	TotalLength	
147/S-W0219/S050236	129.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to Adugodi area,8th block and surrounding area roads in ward No.147	45	
Year	Type of Work	Other Work Type
	Asphaltting	
Tender	WorkDetails	Job No Work Code
	ASPHALT	147-13-000065
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)W.O/193/2012-13	07/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0213	3rd Main Rd	CORPORATION BANK
SegmentNo	TotalLength	
147/S-W0213/S050626	126.48	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager Karnataka Rural Infrastructure Development Ltd		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to Adugodi area,8th block and surrounding area roads in ward No.147	45	
Year	Type of Work	Other Work Type
	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	ASPHALT ROAD	147-13-000065
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/193/2012-13	07/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0209	2nd Main Rd	CORPORATION BANK
SegmentNo	TotalLength	
147/S-W0209/S051213	123.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager Karnataka Rural Infrastructure Developement Ltd		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
pROVIDING ASPHALTING TO aDUGODI AREA,8TH BLOCK AND SURROUNDING AREA ROADS IN WARD nO.147	45	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
	ASPHALT ROAD	147-13-000065
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/193/2012-13	07/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0134	NA	Shiva Temple
SegmentNo	TotalLength	
147/S-W0134/S062604	152.13	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager karnataka Rural Infrastructure Developement Ltd		0.00
PhoneNo	Emailld	
94489270147		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphalting to roads at 7th & 8th block koramangala Rajendra nagar and surrounding area roads in ward no. 147	40	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender	ASPHALT ROAD	147-13-000066
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/195/2012-13	07/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0140	Koramangala Rd	BBMP Health Centre
SegmentNo	TotalLength	
147/S-W0140/S064417	975.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER KARNATAKA RURAL INFRASTRUCTURE DEVELOPEMENT LTD		0.00
PhoneNo	EmailId	
Work Details 9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Adugodi main road in ward No.147(Adugodi)	49.52	
Year	Type of Work	Other Work Type
	Asphaltting	
Tender	WorkDetails	Job No Work Code
	0	147-14-000021
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/230/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0178	NA	GANESH HOTEL
SegmentNo	TotalLength	
147/S-W0178/S065731	326.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager Karnataka Rural Infrastructure Developement Ltd		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING ASPHALTING FROM HOSUR ROAD (GANESH HOTEL) TO POLICE QUATERS GATE IN WARD NO.147(ADUGODI)	10	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	147-14-000022
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/214/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	147	Adugodi
StreetID	StreetName	Significant LandMark
W0142	NA	BBMP Health Centre
SegmentNo	TotalLength	
147/S-W0142/S070515	134.80	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager Karnataka Rural Infrastructure Development Ltd		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting from Hosur road (Ganesh Hotel) to Police Quaters gate in Ward No.147(Adugodi)		
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
	0	147-14-000022
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/214/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		savitri
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	