



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0132	NA	Behind VET College
SegmentNo	TotalLength	
177/S-W0132/S020737	203.90	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A. Channareddy		0.00
PhoneNo	EmailId	
9845334879		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to bad reaches of road Sy.No. 32 Marenahalli and behind VET College in J.P. Nagar 2nd phase in ward no. 177.	60	
Year	Type of Work	Other Work Type
2016 - 2017	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	0	177-16-000020
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/NPW/	28/07/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/09/2016	27/09/2019	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
03/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	

BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0154	NA	JP Nagar
SegmentNo	TotalLength	
177/S-W0154/S123724	259.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A. Channareddy		0.00
PhoneNo	Emailld	
9845334879		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and asphaltting to 12th cross, 12th'A'cross, 13th cross(from 6th main to 2nd main) and 14th cross from 8th main to 6th'B'main in Ward No.1		
Year	Type of Work	Other Work Type
2016 - 2017	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	SDBC	177-16-000016
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/NPW/2 /	28/07/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/10/2016	26/10/2019	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
03/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0142	NA	JP Nagara
SegmentNo	TotalLength	
177/S-W0142/S125235	165.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A. Channareddy		0.00
PhoneNo	Emailld	
9845994879		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and asphaltting to 12th cross, 12th'A'cross, 13th cross(from 6th main to 2nd main) and 14th cross from 8th main to 6th'B'main in Ward No.1	50	
Year	Type of Work	Other Work Type
2016 - 2017	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	0	177-16-000016
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/	28/07/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/10/2016	26/10/2019	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
03/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0171	NA	14th cross
SegmentNo	TotalLength	
177/S-W0171/S013640	330.50	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A. Channareddy		0.00
PhoneNo	Emailld	
9845334879		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and asphaltting to 12th cross, 12th'A'cross, 13th cross(from 6th main to 2nd main) and 14th cross from 8th main to 6th'B'main in Ward No.1	50	
Year	Type of Work	Other Work Type
2016 - 2017	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	SDBC	177-16-000016
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/NPW	28/07/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/10/2016	26/10/2019	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
03/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0109	NA	JP Nagar 3rd phase
SegmentNo	TotalLength	
177/S-W0109/S021929	1088.29	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A. Channareddy		0.00
PhoneNo	EmailId	
9845334879		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to bad reaches of road in 3rd phase JP Nagar in Ward No.177	70	
Year	Type of Work	Other Work Type
2016 - 2017	Asphaltting	
Tender	WorkDetails	Job No Work Code
	0	177-16-000020
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/NPW/	28/07/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/10/2016	27/10/2019	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
03/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0098	NA	J.P. Nagar 2nd phase
SegmentNo	TotalLength	
177/S-W0098/S025858	131.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A. Chennareddy		0.00
PhoneNo	Emailld	
9845334879		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to bad reaches of road in Sy No. 32 Marenahalli and behind VET college in J.P. Nagar 2nd phase in Ward No. 177	60	
Year	Type of Work	Other Work Type
2016 - 2017	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	0	177-16-000020
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/NPW/16-17	28/07/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/10/2016	26/10/2019	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
03/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0193	Vinayaka Lyt 2nd Crs	J.P. Nagar Dollar layout
SegmentNo	TotalLength	
177/S-W0193/S113230	74.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A Chenna reddy		0.00
PhoneNo	Emailld	
9845334879		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to damaged roads in dollars layout 4th phase and KSRTC layout 2nd phase J.P Nagar in ward No. 177	70	
Year	Type of Work	Other Work Type
2016 - 2017	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	0	177-16-000017
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/NPW/28/	28/07/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/09/2016	27/09/2019	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
03/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0215	NA	KSRTC
SegmentNo	TotalLength	
177/S-W0215/S114151	108.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A Chenna reddy		0.00
PhoneNo	Emailld	
9845334879		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to damaged roads in dollars layout 4th phase and KSRTC layout 2nd phase J.P. Nagar in ward no. 177.	70	
Year	Type of Work	Other Work Type
2016 - 2017	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	0	177-16-000017
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/NPW/28/	28/07/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/09/2016	27/09/2019	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
03/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0162	NA	J.P. Nagar
SegmentNo	TotalLength	
177/S-W0162/S121049	199.84	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A Chenna reddy		0.00
PhoneNo	Emailld	
9845334879		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to damaged roads in dollars layout 4th phase & KSRTC layout 2nd phase J.P. Nagar in ward no. 177.	70	
Year	Type of Work	Other Work Type
2016 - 2017	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	0	177-16-000017
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/NPW/28/	28/07/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/09/2016	27/09/2019	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
03/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0047	NA	Ragigudda temple
SegmentNo	TotalLength	
177/S-W0047/S122204	141.42	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A. Channareddy		0.00
PhoneNo	Emailld	
9845334879		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to bad reaches of surrounding ragigudda temple 1st JP Nagar 2nd phase in ward no. 177.	50	
Year	Type of Work	Other Work Type
2016 - 2017	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	0	177-16-000019
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/NPW/ /16-17	28/07/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/09/2016	27/09/2019	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
03/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0078, W0133	NA, Vinayaka Lyt 4th Crs	18th A main
SegmentNo	TotalLength	
177/C-W0078/S035025	170.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Gopinath		0.00
PhoneNo	EmailId	
9880367999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain to 18th A main J.P. Nagar 2nd phase in Ward No. 177	19.85	
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	SDBC	177-13-000035
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/W.O./54/14-15	05/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/04/2016	26/04/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
12/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0075	NA	18th A main road
SegmentNo	TotalLength	
177/S-W0075/S041205	112.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Gopinath		0.00
PhoneNo	EmailId	
9880367999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain to 18th A main in J.P. Nagar 2nd phase in Ward No. 177.	19.85	
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		177-13-000035
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/W.O./54/14-15	05/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/04/2016	26/04/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
12/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0086, W0088, W0133	NA, Vinayaka Lyt 4th Crs	West side
SegmentNo	TotalLength	
177/C-W0086/S042409	62.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Gopinath		0.00
PhoneNo	EmailId	
9880367999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain 18th A main in J.P. Nagar 2nd phase in Ward No. 177	19.85	
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		177-13-000035
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/W.O./54/14-15	05/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/04/2016	26/04/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
12/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0131	NA	18th B main road (East side)
SegmentNo	TotalLength	
177/S-W0131/S043255	183.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Gopinath		0.00
PhoneNo	EmailId	
9980367999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain to 18th B main in J.P.Nagar 2nd phase in Ward No. 177	19.9	
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	SDBC	177-13-000036
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/WO/55/14-15	07/01/2015	380
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/04/2016	26/04/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
12/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	

BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0137	NA	17th A main (East Side)
SegmentNo	TotalLength	
177/S-W0137/S044445	234.76	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Gopinath		0.00
PhoneNo	EmailId	
9980367999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain to 18th B main in J.P.Nagar 2nd phase in Ward No. 177	19.9	
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		177-13-000036
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/WO/55/14-15	07/01/2015	380
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/04/2016	26/04/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
12/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	

BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0135	NA	18th main
SegmentNo	TotalLength	
177/S-W0135/S120451	284.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Gopinath		0.00
PhoneNo	EmailId	
9880367999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain to 18th main in J.P. Nagar 2nd phase in Ward No. 177	19.8	
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		177-13-000037
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/W.O./53/14-15	07/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
21/07/2015	20/07/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
12/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0073, W0052	NA	18th B main road
SegmentNo	TotalLength	
177/C-W0073/S121715	110.12	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Gopinath		0.00
PhoneNo	EmailId	
9880367999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain to 18th B main in J.P. Nagar 2nd phase in ward No. 177	19.9	
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		177-13-000036
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/W.O./55/14-15	07/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/04/2016	26/04/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
12/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0104, W0078, W0086, W0135	NA	18th main road
SegmentNo	TotalLength	
177/C-W0104/S125705	271.21	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Gopinath		0.00
PhoneNo	EmailId	
9880367999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain to 18th main in J.P. Nagar 2nd phase in Ward No. 177	19.8	
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		177-13-000037
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/W.O./53/14-15	07/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
21/07/2015	20/07/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
12/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	

BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0104, W0137, W0078	NA	17th A main
SegmentNo	TotalLength	
177/C-W0104/S011021	130.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Gopinath		0.00
PhoneNo	EmailId	
9880367999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain to 18th main in J.P. Nagar 2nd phase in Ward No. 177	19.8	
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		177-13-000037
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/W.O./53/14-15	07/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
21/07/2015	20/07/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
12/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0033, W0052	NA	18th main
SegmentNo	TotalLength	
177/C-W0033/S012226	110.48	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Gopinath		0.00
PhoneNo	EmailId	
9880367999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain to 18th main in J.P. Nagar 2nd phase in Ward No. 177	19.8	
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		177-13-000037
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/W.O./53/14-15	07/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
21/07/2015	20/07/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
12/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	

BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0026, W0033	NA	18th main
SegmentNo	TotalLength	
177/C-W0026/S012542	53.34	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Gopinath		0.00
PhoneNo	EmailId	
9880367999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain to 18th main in J.P. Nagar 2nd phase in Ward No. 177	19.8	
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		177-13-000037
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/W.O./53/14-15	07/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
21/07/2015	20/07/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
12/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	

BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0012, W0031	NA	J.P. Nagar Club
SegmentNo	TotalLength	
177/C-W0012/S115342	172.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Gopinath		0.00
PhoneNo	EmailId	
9880367999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain to 18th A main J.P. Nagar 2nd phase in ward no. 177	19.85	
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	SDBC	177-13-000035
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/W.O./54/14-15	05/01/2015	360
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/04/2016	26/04/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
03/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0122, W0097	NA, 16th Crs	Priyadarshini school
SegmentNo	TotalLength	
177/C-W0122/S043253	223.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Venkateshwara constructions Prop. B.C. Srinivas		0.00
PhoneNo	Emailld	
9820648757		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain to 7th cross in J.P. Nagar 3rd phase in ward no. 177.	19.85	
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	SDBC	177-13-000039
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-tender/M.O/19/15-16	08/05/2015	233
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/10/2016	26/10/2019	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
03/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0143, W0151, W0106, W0145	NA	Karur vysya bank Opposite road
SegmentNo	TotalLength	
177/C-W0143/S051913	321.26	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Venkateshwara Constructions		0.00
PhoneNo	EmailId	
9538645757		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain of 2nd & 3rd main from 1st cross to 3rd cross to KSRTC layout J.P. Nagar 2nd phase in ward no. 177.	20	
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	177-13-000031
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e- proc/TEND/W.O/38/14-15	30/09/2014	55
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
24/02/2015	23/02/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
03/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0002	NA	JP NAGAR
SegmentNo	TotalLength	
177/S-W0002/S073328	121.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
GIRISH M		0.00
PhoneNo	EmailId	
9448211568		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN IN 2ND PHASE JP NAGAR	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		177-14-000015
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/E-PROC/TEND/WO/164/13-14	20/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
29/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0125, W0131, W0098, W0123, W0096, W0129	Veera Anjaneya Temple Rd, NA	JP NAGAR POLICE STATION
SegmentNo	TotalLength	
177/C-W0125/S061001	120.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
PR ARUN KUMAR		0.00
PhoneNo	EmailId	
9448369097		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO ROAD AND DRAIN AT 8TH CROSS MARENAHALLI PALYA	1170000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	ROAD AND DRAIN
Tender	WorkDetails	Job No Work Code
Tender		177-12-000047
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/ME/WO/05/13-14	20/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
29/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0131, W0127, W0092, W0078, W0096, W0094	NA	JP NAGAR POLICE STATION
SegmentNo	TotalLength	
177/C-W0131/S061615	130.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P R ARUN KUMAR		0.00
PhoneNo	EmailId	
9448369097		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO ROAD AND DRAIN AT 18TH C MAIN IN MARENHALLI COLONY	900000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	ROAD AND DRAIN
Tender	WorkDetails	Job No Work Code
Tender		177-12-000057
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/ME/WO/10/13-14	20/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
29/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0100, W0131, W0078, W0092, W0098, W0096, W0094	NA	POLICE STATION
SegmentNo	TotalLength	
177/C-W0100/S062325	166.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P R ARUN KUMAR		0.00
PhoneNo	EmailId	
9448369097		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO ROAD AND DRAIN AT 19TH MAIN ,18TH B MAIN FROM 9TH CROSS TO 7TH CROSS W-S IN MARENHALLI COLONY	1930000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	ROAD AND DRAIN
Tender	WorkDetails	Job No Work Code
Tender		177-12-000056
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/ME/WO/07/13-14	20/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
29/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 177	WardName J P Nagara
StreetID W0131, W0121, W0127, W0078, W0123	StreetName NA	Significant LandMark JP NAGAR POLICE STATION
SegmentNo 177/C-W0131/S062828	TotalLength 121.04	

ContractorDetails		
NameofContractor P R ARUN KUMAR	ContractorRegNo	Expenditure 0.00
PhoneNo 9448369097	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO ROAD SIDE DRAIN AT 7TH CROSS FROM 18TH B MAIN TO 19TH MAIN MARENHALLI COLONY	Sanctioned Amount 510000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails	Job No Work Code 177-12-000056
Work OrderNo EE/JN/DM/ME/WO/09/13-14	Work Order Date 20/06/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name krishnakumar
Date of Inspection 29/08/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0131, W0127, W0096	NA	POLICE STATION
SegmentNo	TotalLength	
177/C-W0131/S063344	68.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P R ARUN KUMAR		0.00
PhoneNo	EmailId	
9448369097		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO ROAD AND DRAIN IN MARENHALLI PALYA	900000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	ROAD AND DRAIN
Tender	WorkDetails	Job No Work Code
Tender		177-12-000052
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/ME/WO/08/13-14	20/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
29/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0095, W0153, W0112, W0108, W0151, W0110	Om Shakthi Lyt 2nd Crs, NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	KSRTC LYT
SegmentNo	TotalLength	
177/C-W0095/S065301	336.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S L HARISH		0.00
PhoneNo	EmailId	
7766909901		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AT KSRTC LYT	2400000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		177-14-000013
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/E- PROC/TEND/WO/169/13-14	20/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
29/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0047, W0049, W0051, W0034	NA, Om Shakthi Lyt 8th Crs	JP NAGAR
SegmentNo	TotalLength	
177/S-W0047/S065750	272.18	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M GOPINATH		0.00
PhoneNo	EmailId	
9822009871		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO ROAD SIDE DRAIN AT 5TH MAIN AND 1ST CROSS	800000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		177-13-000020
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/E-PROC/TEND/WO/229/13-14	11/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
29/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0089, W0091	NA, Om Shakthi Lyt 3rd Crs	RAGHIGUDDA TEMPLE
SegmentNo	TotalLength	
177/C-W0089/S070204	79.41	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S H RAGHAVENDRARAO		0.00
PhoneNo	EmailId	
7889234561		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AND FOOTPATH AT 5TH CROSS	1000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	DRAIN AND FOOTPATH
Tender	WorkDetails	Job No Work Code
Tender		177-14-000001
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/E-PROC/TEND/WO/297/13-14	03/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
29/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0152, W0181, W0179, W0150, W0148	NA, Vinayaka Lyt 3rd Crs	JP NAGAR
SegmentNo	TotalLength	
177/C-W0152/S070655	338.67	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
ANUP VIKAS A		0.00
PhoneNo	EmailId	
9849286090		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO ROAD SIDE DRAIN AT 12 AND 12 A CROSS	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		177-13-000026
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/E- PROC/TEND/WO/129/13-14	13/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
29/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0153, W0149, W0147, W0106	NA	JP NAGAR
SegmentNo	TotalLength	
177/S-W0153/S071117	321.39	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
ANUP VIKAS A		0.00
PhoneNo	EmailId	
9848244890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO ROAD SIDE DRAIN AT 4TH MAIN AND 3RD CROSS	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		177-13-000028
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/E- PROC/TEND/WO/128/13-14	13/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
29/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0095, W0153, W0151	Om Shakthi Lyt 2nd Crs, NA	JP NAGAR
SegmentNo	TotalLength	
177/C-W0095/S071803	138.11	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M G MANJUNATH		0.00
PhoneNo	Emailld	
9964454472		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO ROAD SIDE DRAIN OF 7TH MAIN FROM 3RD CROSS 5TH CROSS KSRTC LYT	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		177-13-000032
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/E-PROC/TEND/WO/184/13-14	28/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
29/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0187, W0185, W0170	NA	JP NAGAR
SegmentNo	TotalLength	
177/S-W0187/S072328	164.57	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
GIRISH M		0.00
PhoneNo	EmailId	
9448211568		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO ROAD AND DRAIN IN 4TH PHASE DOLLERS LYT	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	ROADS AND DRAINS
Tender	WorkDetails	Job No Work Code
Tender		177-14-000014
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/E-PROC/TEND/WO/165/13-14	20/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
29/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
RR Nagara	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0481	B Narayanaswamappa Rd	CONGRESS OFFICE S.C.ROAD
SegmentNo	TotalLength	
17/S-W0481/S45667	250.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.ASHOK KUMAR		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPTS TO DRAIN & F/P 1ST MAIN ROAD Y.NARAYANASWAMAPPA ROAD (E/S) CH0.00 TO 250.00	1646000	2010
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
		045-12-000040
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
8		parashuram
Date of Inspection	Remarks	
16/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
RR Nagara	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0481	B Narayanaswamappa Rd	ADISHWAR ELECTRICALS
SegmentNo	TotalLength	
17/S-W0481/S45668	250.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.ASHOK KUMAR		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPTS TO DRAIN & F/P 1ST MAIN ROAD Y.NARAYANA SWAMAPPA ROAD (E/S) CH:250.00 TO 500.00MTRS		
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
		045-12-000039
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		parashuram
Date of Inspection	Remarks	
16/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0097, W0118	16th Crs, NA	Shivabalayogi ashram
SegmentNo	TotalLength	
177/C-W0097/S034546	209.55	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B.C. Padmakiran		0.00
PhoneNo	EmailId	
9741910794		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain to 5th cross in J.P. Nagar 3rd phase in ward no. 177	19.9	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		177-13-000041
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/W.O/23/14-15	01/09/2014	176
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/05/2015	26/05/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
03/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	177	J P Nagara
StreetID	StreetName	Significant LandMark
W0157, W0047, W0049, W0034	NA	Priyadarshini school
SegmentNo	TotalLength	
177/S-W0157/S035933	79.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B.C. Padmakiran		0.00
PhoneNo	EmailId	
9741910794		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain to 5th cross in J.P. Nagar 3rd phase in wardno. 177	19.9	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		177-13-000041
Work OrderNo	Work Order Date	Period of Extention
EE/JN/DM/e-proc/TEND/W.O/23/14-15	01/09/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/05/2015	26/05/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishnakumar
Date of Inspection	Remarks	
03/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	

