



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0393, W0272, W0377, W0284, I0395, W0274, W0268, W	NA, 1st Crs, Maheshwari Nagar, V S T Opposite, 5th Crs, 2nd Crs, Maheshwari Nagar, 3rd A Crs Maheshw	NGEF Signal
SegmentNo	TotalLength	
79/C-W0393/S085617	621.96	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	Emailld	
9902704696		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Asphalt Road to Biappanahalli Railway Parallel Road in Ward No.,79	2400000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing wet mix and Asphalting to Roads	079-14-000021
Work OrderNo	Work Order Date	Period of Extention
EE/CVR/WO/146/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/08/2014	29/08/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Girish kumar Gudda
Date of Inspection	Remarks	
29/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0377, W0284, I0395, W0274, W0268, W0282, W0381, W	V S T Opposite, 5th Crs, NA, 2nd Crs, Maheshwari Nagar, 3rd A Crs Maheshwari Nagar, 1st Crs, Lakshmi	NGEF SIGNAL
SegmentNo	TotalLength	
79/C-W0377/S090431	512.90	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9902704696		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Drain and Providing cover slabs to Biappanahalli Railway Parallel Road in Ward No.79	2600000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	Construction of drain, culvert and Providing covering slabs, and kerb stones, painting and flagging coarse	079-14-000022
Work OrderNo	Work Order Date	Period of Extention
EE/CVR/WO/145/13-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/08/2014	29/08/2015	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/02/2016	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 79	WardName Sarvagna Nagara
StreetID W0248, W0244, W0246, W0365	StreetName NA, Chikka Muniswammappa Lyt, 2nd Crs	Significant LandMark Vivekananda Metro Station
SegmentNo 79/C-W0248/S093540	TotalLength 227.78	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9902704696	EmailId	

Work Details		
NameOfWork Construction of side drains and footpath to First main road in Biappanahalli Extn. in Ward no.79	Sanctioned Amount 2000000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Road	Other Work Type
Tender Not a Tender	WorkDetails Constrction of Drain and culverts, flagging coarse kerb sothnes and painting and covering slabs	Job No Work Code 079-15-000006
Work OrderNo EE/CVR/WO/36/2014-15	Work Order Date 07/11/2014	Period of Extention
Defect Liability Period From 31/12/2014	Defect Liability Period To 30/12/2015	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name Girish kumar gudda
Date of Inspection 29/02/2016	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0246, W0365	NA, Chikka Muniswammappa Lyt, 2nd Crs	VEVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/C-W0246/S094200	319.85	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9902704696		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of side drains and footpath to First Right and left cross roads in Biappanahalli Extn in ward no.79	2014	
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	Construction of drain and culverts, flagging coarse, Providing kerb stones and painting, Providing covering slabs	079-15-000007
Work OrderNo	Work Order Date	Period of Extention
EE/CVR/WO/37/2014-15	07/11/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/12/2014	30/12/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Girish kumar gudda
Date of Inspection	Remarks	
29/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0361, W0244, W0365	Chikka Muniswammappa Lyt, 1st Crs, NA, Chikka Muniswammappa Lyt, 2nd Crs	2nd Cross
SegmentNo	TotalLength	
79/C-W0361/S094821	325.90	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9902704696		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of side drains and footpath to Second right and left cross roads in Biappanahalli Extn in Ward No.79	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	Construction drains and culverts, flagging coarse, Providing kerb stones and painting and covering slabs	079-15-000008
Work OrderNo	Work Order Date	Period of Extention
EE/CVR/WO/38/2014-15	07/11/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/12/2014	30/12/2015	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Girish kumar gudda
Date of Inspection	Remarks	
29/02/2016		
Category	Photo	
Drain Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0375, W0272, W0379, W0365, W0242	6th Crs, Muthkurappa Lyt, 1st Crs, Maheshwari Nagar, NA, Chikka Muniswammappa Lyt, 2nd Crs	2nd main 3rd cross
SegmentNo	TotalLength	
79/C-W0375/S095529	243.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9902704696		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of side drains and footpath to third right and left cross roads in Biappanahalli Extn in Ward no.79	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	Construction of Drains and culverts, flagging coarse, Providing and painting to kerb, Providing covering slabs	079-15-000010
Work OrderNo	Work Order Date	Period of Extention
EE/CVR/WO/40/2014-15	07/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/12/2014	30/12/2015	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		girish kumar gudda
Date of Inspection	Remarks	
29/02/2016		
Category	Photo	
Drain Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0307	NA	KADIRAYYANA PALYA SWEEPERS COLONY
SegmentNo	TotalLength	
79/S-W0307/S010612	117.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
08/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0309	NA	KADIRAYYANA PALYA SWEEPERS COLONY
SegmentNo	TotalLength	
79/S-W0309/S011743	79.04	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
na		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
08/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0337	NA	OLD MADRAS ROAD NEAR HONDA SHOW ROOM
SegmentNo	TotalLength	
79/S-W0337/S011958	122.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
08/10/2015	MEG road	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0339	NA	OLD MADRAS ROAD NEAR HONDA SHOW ROOM
SegmentNo	TotalLength	
79/S-W0339/S012103	65.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
08/10/2015	meg road	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0210	NA	SRI VIVEKANANDA METRO STATION INDIRA HARIZANA SEVA
SegmentNo	TotalLength	
79/S-W0210/S012245	206.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0216	NA	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0216/S012436	41.34	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0228	NA	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0228/S012548	139.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0232	NA	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0232/S012638	26.50	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0359	NA	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0359/S012736	43.22	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	0	NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0355	NA	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0355/S012832	27.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
08/10/2015	MEG CENTRE	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0353	NA	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0353/S012927	25.48	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
08/10/2015	MEG CENTRE	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0355	NA	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0355/S013115	27.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
08/10/2015	MEG CENTRE road	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0220	NA	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0220/S013236	68.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0222	NA	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0222/S013403	81.22	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0224	NA	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0224/S013519	85.81	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0226	NA	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0226/S013620	44.97	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0341	NA	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0341/S013805	36.47	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
08/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0238	NA	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0238/S013903	107.85	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0343	NA	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0343/S014003	38.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
08/10/2015	MEG road	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0234	NA	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0234/S014112	89.21	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0236	2nd Main Rd	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0236/S014340	92.47	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0230	NA	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0230/S014454	33.08	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0357	Mariyappa Lyt	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0357/S014720	123.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
08/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0351	S Krishnappa Lyt	SRI VIVEKANANDA METRO STATION
SegmentNo	TotalLength	
79/S-W0351/S014941	21.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
08/10/2015	MEG CENTRE	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0104, W0203	NA	PSK Naidu Road
SegmentNo	TotalLength	
79/C-W0104/S050556	62.98	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9986233330		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Drain and coveringt slabs in Pollaramma slum area in Ward 79	1200000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender	Cosntruction of drain and Covering slabs to drain.	079-15-000003
Work OrderNo	Work Order Date	Period of Extention
EE/CVR/WO/48/2014-15	20/11/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/11/2014	28/11/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Girish Kumar
Date of Inspection	Remarks	
05/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0124	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0124/S054808	1368.89	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0208	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0208/S054945	835.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0116	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0116/S055121	388.21	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0305	Church Rd	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0305/S055217	586.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0301	Bimel Behind Rd	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0301/S055312	395.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0168	NA	SWEEPERS COLONY, KADIRAYYANAPALYA
SegmentNo	TotalLength	
79/S-W0168/S055348	249.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NIL		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
WORK NOT CARRIED FOR LONG PERIOD		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0206	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0206/S055602	75.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0335	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0335/S055633	360.68	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
08/10/2015	MEG road	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0204	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0204/S055710	132.47	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0333	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0333/S055740	856.77	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
08/10/2015	meg road	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0172	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0172/S055830	94.55	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0303	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0303/S055906	485.96	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0170	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0170/S055946	227.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0144	3rd Crs	Sri Anjaneya temple road
SegmentNo	TotalLength	
79/S-W0144/S030825	62.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri T Rajadhekar Reddy		0.00
PhoneNo	EmailId	
8095393925		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction od concrete road with L shape drain in kallahalli cross roads behind Sri anjaneya temple in ward no 79	1500000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
Tender	Concrete road laid.	079-15-000021
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/CVR/WO/85/14-15	11/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Prasanna
Date of Inspection	Remarks	
23/08/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0085	NA	MOUNAGURU MATT
SegmentNo	TotalLength	
79/S-W0085/S035751	250.90	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. RAJASHEKAR REDDY		0.00
PhoneNo	EmailId	
8095393925		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF SIDE DRAIN AND CONCRETE ROADS IN THIMMAIAH GARDEN IN WARD NO.79	1500000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Others	DRAIN AND ROADS
Tender	WorkDetails	Job No Work Code
Tender		079-15-000024
Work OrderNo	Work Order Date	Period of Extention
EE/CVR/WO/86/2014-15	11/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
23/08/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0361, W0363, W0244, W0240, W0242, W0272, W0214, W	Chikka Muniswammappa Lyt, 1st Crs, R H B Colcny 1st Main Rd, NA, 1st Crs, Maheshwari Nagar, Chikka M	Near Metro Station
SegmentNo	TotalLength	
79/C-W0361/S045230	249.77	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9986233330		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of side drains and footpath to main road between second cross road and fourth cross roads in Biappanahalli Extn in Ward No.79	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Others	Drain Construction
Tender	WorkDetails	Job No Work Code
Not a Tender	Construction of Side drains	079-15-000012
Work OrderNo	Work Order Date	Period of Extention
EE/CVR/WO/42/2014-15	07/11/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/12/2014	28/12/2015	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
08/09/2016	

Category	Photo
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0128	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0128/S035811	1576.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0269	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0269/S035948	563.77	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0273	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0273/S040041	819.57	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0275	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0275/S040126	291.41	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0152	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0152/S040211	532.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0154	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0154/S040243	674.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0271	Ambedkar Nagar Slum	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0271/S040324	457.25	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0277	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0277/S040402	140.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0279	Ambedkar Nagar Slum	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0279/S040533	321.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0	MEG CENTRE	prasanna
Date of Inspection	Remarks	
24/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0164	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0164/S041342	565.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0281	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0281/S041420	324.89	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0295	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0295/S041457	197.45	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0162	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0162/S041553	405.11	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	0	NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0166	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0166/S041638	81.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0297	Old Panchayathi Office Rd	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0297/S041757	176.63	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0004	NA	Tamil church in MM road
SegmentNo	TotalLength	
79/S-W0004/S102517	470.59	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NIL		0.00
PhoneNo	EmailId	
123456789		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
Work executed in older period		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0011	NA	SWD NEAR MM ROAD, PULIKESHINAGAR POLICE STATION
SegmentNo	TotalLength	
79/S-W0011/S102824	261.60	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0008	NA	BBMP METERNITY HOME
SegmentNo	TotalLength	
79/S-W0008/S103039	103.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0006	NA	BBMP METERNITY HOME
SegmentNo	TotalLength	
79/S-W0006/S103211	28.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0015	NA	GOVER ROAD JUNCTION
SegmentNo	TotalLength	
79/S-W0015/S103259	30.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0283	NA	old madras road
SegmentNo	TotalLength	
79/S-W0283/S105202	126.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
na		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0285	NA	old madras road c colony
SegmentNo	TotalLength	
79/S-W0285/S105307	126.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0287	Maheshwari Nagar 4th Main Rd	old madras road c colony
SegmentNo	TotalLength	
79/S-W0287/S105338	125.98	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0289	Chikkanna Lyt	old madras road c colony
SegmentNo	TotalLength	
79/S-W0289/S105406	125.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	0	NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0289	Chikkanna Lyt	old madras road c colony
SegmentNo	TotalLength	
79/S-W0289/S105446	125.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0291	NA	old madras road c colony
SegmentNo	TotalLength	
79/S-W0291/S105524	123.90	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0293	Maheshwari Nagar Opp Police Station Rd	old madras road c colony
SegmentNo	TotalLength	
79/S-W0293/S105553	124.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0156	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0156/S105632	43.76	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0158	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0158/S105722	46.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0160	NA	MEG CENTRE
SegmentNo	TotalLength	
79/S-W0160/S110155	124.21	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0267	Maheshwari Nagar Ambedkar Rd	RMZ PRIVATE BUILDING
SegmentNo	TotalLength	
79/S-W0267/S110342	389.35	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0265	Ambedkar Nagar Slum	OLD MADRAS ROAD NEAR RMZ BUILDING
SegmentNo	TotalLength	
79/S-W0265/S110542	126.26	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NA		0.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		NA
Work OrderNo	Work Order Date	Period of Extention
NA		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		prasanna
Date of Inspection	Remarks	
21/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0099, W0045, W0043, W0049, W0044, W0055, W0051, W	NA, Om Shakthi Lyt 8th Crs	signal
SegmentNo	TotalLength	
79/C-W0099/S073030	217.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9902704696		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of asphalt road from doddigunta arch to Sri.Lakshminarayana temple road in Ward No.79	1981000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphalting to Roads	079-15-000001
Work OrderNo	Work Order Date	Period of Extention
EE/CVR/W/32/2014-15	15/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/10/2014	30/10/2015	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		girishkumar
Date of Inspection	Remarks	
02/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0035, W0018, W0037, W0041, W0016, W0043, W0085, W	NA, Om Shakthi Lyt, 9th Crs	Lakshminarayana temple
SegmentNo	TotalLength	
79/C-W0035/S074626	242.80	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9902704696		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of asphalt road from Webstar road entrance to Sri Moundagurumatt road in Ward No.79	1928000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Earth work excavation and asphalting to roads	079-15-000002
Work OrderNo	Work Order Date	Period of Extention
EE/CVR/WO/33/2014-15	15/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/10/2014	30/10/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		girishkumar
Date of Inspection	Remarks	
02/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 79	WardName Sarvagna Nagara
StreetID W0104, W0088, W0217, W0191, W0203, W0215, W0106, W	StreetName NA, Chowdeshwari Temple Rd	Significant LandMark KHB Colony
SegmentNo 79/C-W0104/S075225	TotalLength 290.55	

ContractorDetails		
NameofContractor Venkatesh Gurappa	ContractorRegNo	Expenditure 0.00
PhoneNo 9902070469	EmailId	

Work Details		
NameOfWork Providing Concrete Roads in KHB colony and Surrounding Areas in Ward No.79	Sanctioned Amount 2000000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Road	Other Work Type
Tender Tender	WorkDetails Earth work, Providing CC to roads Groove Cutting	Job No Work Code 079-12-000027
Work OrderNo EE/CVR/WO/06/2014-15	Work Order Date 10/07/2014	Period of Extention
Defect Liability Period From 30/08/2014	Defect Liability Period To 29/08/2015	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name girish kumar
Date of Inspection 02/03/2016	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	79	Sarvagna Nagara
StreetID	StreetName	Significant LandMark
W0393, W0272, W0377, W0284, I0395, W0274, W0268, W	NA, 1st Crs, Maheshwari Nagar, V S T Opposite, 5th Crs, 2nd Crs, Maheshwari Nagar, 3rd A Crs Maheshw	NGEF Signal New Biappanahalli
SegmentNo	TotalLength	
79/C-W0393/S050647	618.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9902704696		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to Main Roads and Cross roads in New Biappanahalli area in Ward No.79	2000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	Cleaning Providing and applying BC, Primar coat works	079-12-000021
Work OrderNo	Work Order Date	Period of Extention
EE/CVR//WO/76/2013-14	21/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/08/2014	29/08/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Girish kumar
Date of Inspection	Remarks	
03/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	