



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0299, W0339, W0313, W0321, W0309, W0329, W0325, W	Maheshwari Nagar Main Rd, NA, Lakshmi Sagar Lyt North Side, 1st Crs, Ambedkar Nagar Slum	3rd Main left side AK colony
SegmentNo	TotalLength	
112/C-W0299/S060224	312.03	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M S RAJU		0.00
PhoneNo	EmailId	
9845327879		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF MASONRY DRAIN WITH COVERING SLAB AT 3RD MAIN LEFT SIDE AT AK COLONY IN WARD NO 112 DOMLUR	1000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of Masonry Drain and Culverts	112-15-000051
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/49/2015-16	26/02/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
03/06/2016	02/06/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Lakshmanappa C V
Date of Inspection	Remarks	
03/06/2016		

Category	Photo
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0070, W0113, W0123, W0064, W0103, W0101, W0078, W	NA, 3rd Crs, Om Shakthi Lyt 1st Crs	Muthyalamma temple
SegmentNo	TotalLength	
112/C-W0070/S030914	162.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K R RANGASWAMY		0.00
PhoneNo	EmailId	
9945150353		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Concreting of road behind Muthyalamma temple & Cross roads & C D work in Ward No.112 domlur	1000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Road	
Tender	WorkDetails	Job No Work Code
Tender	Concreting of roads and cross roads	112-16-000006
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/40/2015-16	26/05/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/10/2016	30/10/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Lakshmanappa
Date of Inspection	Remarks	
05/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0265, W0279, W0275, W0208, W0200, W0206, W0202, W	Ambedkar Nagar Slum, NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	Anjaneya Swamy Temple
SegmentNo	TotalLength	
112/C-W0265/S052900	148.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sharanappa		0.00
PhoneNo	EmailId	
9900148273		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Masonary drain & Imprivements to footpath at Domlur village (Opp to Rama Temple) in Ward No.112 Domlur	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Others	Construction of Drain
Tender	WorkDetails	Job No Work Code
Tender	Construction of Masonary drain, footpath.	112-15-000008
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/56/2014-15	08/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
02/03/2015	01/03/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		lakshmanappa
Date of Inspection	Remarks	
09/03/2016		

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment End



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0223, W0217, W0219, W0215, W0160, W0158, W0152, W	NA, Chowdeshwari Temple Rd	Patel Srinivsaa Reddy Park
SegmentNo	TotalLength	
112/C-W0223/S012656	953.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
PRASHANT KUMAR A		0.00
PhoneNo	EmailId	
9980090557		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Desilting of drains of Main road & cross road in ward No.112 Domlur	1000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Others	Desilting
Tender	WorkDetails	Job No Work Code
Tender	Desilting of Drains	112-16-000007
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/58/2015-16	04/03/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
14/06/2016	13/06/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Chandrappa
Date of Inspection	Remarks	
10/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0265, W0227, W0241, W0243, W0251, W0180, W0231, W	Ambedkar Nagar Slum, NA, Chowdeshwari Temple Behind Rd, Maheshwaramma Temple Behind Rd	Domlur Village
SegmentNo	TotalLength	
112/C-W0265/S032202	148.08	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
PRASHANTH KUMAR A		0.00
PhoneNo	EmailId	
9980090557		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of masonry drain in domlur village & Right side of 4th main road in ward no.112 domlur	1000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of Drain Providing pre cast covering slab and desilting of road	112-16-000010
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/56/2015-16	04/03/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
14/06/2016	13/06/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/06/2016	

Category	Photo
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0065, W0079, W0077, W0063, W0069, W0081, W0046, W	Om Shakthi Lyt 5th Crs, Om Shakthi Lyt 4th Crs, NA, Om Shakthi Lyt 6th Crs, 14th Crs, 13th Crs, Om S	HAL 2nd stage
SegmentNo	TotalLength	
112/C-W0065/S124226	1632.11	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
PRATHEEK K R		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Pot Holes filling in Ward No.112 Domlur	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
Tender	Pote Holes filling	112-15-000013
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/19/2015-16	16/06/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
14/06/2016	13/06/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rachappa
Date of Inspection	Remarks	
14/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 112	WardName Domlur
StreetID W0373, W0248, W0258	StreetName East Park Reje Lyt, NA, Ambedkar Nagar Slum	Significant LandMark Andhra Colony
SegmentNo 112/C-W0373/S105843	TotalLength 90.33	

ContractorDetails		
NameofContractor S R SREEDHAR KUMAR	ContractorRegNo	Expenditure 0.00
PhoneNo 9036673220	EmailId	

Work Details		
NameOfWork Providing And Laying Cement Concreting to Roads in Andhra Colony in Ward No.112 Domlur	Sanctioned Amount 600000	Sanctioned Year 2015
Year 2015 - 2016	Type of Work Road	Other Work Type
Tender Tender	WorkDetails Concreting to roads	Job No Work Code 112-15-000052
Work OrderNo EE/SN/AE/WO/48/2015-16	Work Order Date 26/02/2016	Period of Extention
Defect Liability Period From 30/06/2016	Defect Liability Period To 29/06/2017	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name Lakshmanappa
Date of Inspection 30/06/2016	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 112	WardName Domlur
StreetID W0299, W0339, W0313, W0321, W0309, W0325, W0268, W	StreetName Maheshwari Nagar Main Rd, NA	Significant LandMark Yellamma temple
SegmentNo 112/C-W0299/S052510	TotalLength 176.20	

ContractorDetails		
NameofContractor G S RAJU	ContractorRegNo	Expenditure 0.00
PhoneNo 9845042672	EmailId ninaadconstruction@gmail.com	

Work Details		
NameOfWork Asphalting of Rama Temple road upto 8th cross Junction in Doopanahalli in ward No 112 Domlur	Sanctioned Amount 1000000	Sanctioned Year 2016-17
Year 2016 - 2017	Type of Work Asphalting	Other Work Type
Tender Tender	WorkDetails AS PER THE DEMAND BY PUBLIC AND OBSTRUCTION AT THE SITE OF RAMA TEMPLE ROAD WORK HAS BEEN SHIFTED TO 3RD MAIN TO COMPLETE FULL LENGTH AND WARD CORPORATOR REQUEST THROUGH LETTER	Job No Work Code 112-16-000004
Work OrderNo EE/SN/AE/WO/39/2016-17	Work Order Date 19/09/2016	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
16/01/2017	

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0375, W0329, W0325, W0268, W0266, W0359	6th Crs, Muthkurappa Lyt, Lakshmi Sagar Lyt North Side, 1st Crs, NA	Yellamma Temple
SegmentNo	TotalLength	
112/C-W0375/S053259	240.18	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G S RAJU		0.00
PhoneNo	EmailId	
9845042672		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting 3rd main road in Domlur layout in ward No. 112 Domlur	1000000	2016-17
Year	Type of Work	Other Work Type
2016 - 2017	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		112-16-000011
Work OrderNo	Work Order Date	Period of Extention
EE/SN/WO/38/2016-17	19/09/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		C V Lakshmanappa
Date of Inspection	Remarks	
16/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0365	Chikka Muniswammappa Lyt, 2nd Crs	domulur layout
SegmentNo	TotalLength	
112/S-W0365/S064957	311.45	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Naryanappa-Rajashekhar		0.00
PhoneNo	EmailId	
9448082676		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Contruction of Rcc Covered drain at 9th cross right side near CPWD office Domulur layout in ward no-112 Domulur	2000000	19-dec-2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC COVERED DRAIN	112-13-000006
Work OrderNo	Work Order Date	Period of Extention
EE-101	19/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		rachppa
Date of Inspection	Remarks	
15/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0149	NA	Domulur Layout
SegmentNo	TotalLength	
112/S-W0149/S070224	112.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Pushpa.C		0.00
PhoneNo	EmailId	
9880033013		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction Of Roads At Vasanthappa Garden And Oposite Roads Of Floor Mill Domulur Layout In Ward No 112,Domulur	1100000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Construction Of Asphlat	112-14-000008
Work OrderNo	Work Order Date	Period of Extention
EE-118	28/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		rachppa
Date of Inspection	Remarks	
15/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0017	NA	Cambridge Layout
SegmentNo	TotalLength	
112/S-W0017/S071152	168.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.Venkatesh		0.00
PhoneNo	EmailId	
9448012118		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction Of Drain With Covering Slab At 3rd Cross Cmebridge Layout In Ward No 112,Domlur	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Drain Work	112-14-000002
Work OrderNo	Work Order Date	Period of Extention
EE-123	13/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		rachppa
Date of Inspection	Remarks	
15/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0009	NA	Cambridge Layout
SegmentNo	TotalLength	
112/S-W0009/S071712	145.90	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V.Rohit		0.00
PhoneNo	EmailId	
9743222892		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction Of Drain Withv Covering Sabs At 6th cross Cambridge Layout in Ward No 112-DOMULUR	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Drian Maintence	112-14-000005
Work OrderNo	Work Order Date	Period of Extention
EE-124	13/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		rachppa
Date of Inspection	Remarks	
15/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0015	NA	Manjunath Temple
SegmentNo	TotalLength	
112/S-W0015/S072557	42.60	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V.Rohith		0.00
PhoneNo	EmailId	
9743222892		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction Drain With Covering Slab At 4th Cross Cambridge Layout in Ward No 112-Domlur	1100000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN MAINTENENCE	112-14-000013
Work OrderNo	Work Order Date	Period of Extention
EE-125	03/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		rachppa
Date of Inspection	Remarks	
15/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0013	NA	Manjunatha Temple
SegmentNo	TotalLength	
112/S-W0013/S073116	64.35	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V.Rohith		0.00
PhoneNo	EmailId	
9743222892		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Drain With Covering Slab at 4th Cross Cmbridge Layout in Ward No 112 -Domulur	1100000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
	DRAIN MAINTAINENCE	112-14-000013
Work OrderNo	Work Order Date	Period of Extention
EE-125	03/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		rachppa
Date of Inspection	Remarks	
15/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0240	NA	Manjunath Temple
SegmentNo	TotalLength	
112/S-W0240/S073543	111.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.Venkatesh		0.00
PhoneNo	EmailId	
9986836575		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction Of Drain Near Mnjunatha Temple in Ward no 112-Domlur	1100000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
	DRAIN MAINTAINENCE	112-14-000007
Work OrderNo	Work Order Date	Period of Extention
EE-145	03/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		rachppa
Date of Inspection	Remarks	
15/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0328	R H B Colony, 4th Crs	Amarajyothi Layout
SegmentNo	TotalLength	
112/S-W0328/S074116	182.27	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900094714		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphlating Road In Amara jyothi Layout Behind in Night Rides (Next To Royal Road) in Ward No 112-Domlur	4500000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	ASPHALTING	112-14-000027
Work OrderNo	Work Order Date	Period of Extention
EE-152	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		rachppa
Date of Inspection	Remarks	
15/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0011	NA	Cambridge Layout
SegmentNo	TotalLength	
112/S-W0011/S074825	155.37	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Naryappa-Rajashekar		0.00
PhoneNo	EmailId	
9448082676		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Drain With Covering Slab At 5th Cross Cambridge Layout in Ward No 112-Domlur	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN MAINTAINANCE	112-14-000004
Work OrderNo	Work Order Date	Period of Extention
EE-1	17/05/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		rachppa
Date of Inspection	Remarks	
15/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0299	Maheshwari Nagar Main Rd	Venkateswara Temple
SegmentNo	TotalLength	
112/S-W0299/S075542	233.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448012118		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction Of Drain With Covering Slab At 2nd Cross Domlur Layout Near Venakateswara Swamy Temple in Ward No 112-Domlur	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
Not a Tender	DRAIN MAINTENANCE	112-14-000006
Work OrderNo	Work Order Date	Period of Extention
EE-10	22/05/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		rachppa
Date of Inspection	Remarks	
15/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0200	Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	Domlur Village(OPP Rama Temple)
SegmentNo	TotalLength	
112/S-W0200/S080246	93.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SARANAPPA		0.00
PhoneNo	EmailId	
9491916787		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction Of Drain And Improvements To Footpath at Domlur Village (opp Rama Temple) In Ward No 112	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Footpath Layering	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVMENTS OF DRAIN AND FOOTPATH	112-15-000008
Work OrderNo	Work Order Date	Period of Extention
EE-56	08/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		rachppa
Date of Inspection	Remarks	
15/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0234	NA	Sri Venkateswara Temple
SegmentNo	TotalLength	
112/S-W0234/S081128	112.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.Venkatesh		0.00
PhoneNo	EmailId	
9491916787		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construcion Of Covered Drains On 1st D Main In Ward No 112	1500000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN MAINTENANCE	112-14-000056
Work OrderNo	Work Order Date	Period of Extention
EE-59	11/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		rachppa
Date of Inspection	Remarks	
15/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0309	NA	Domulur Layout
SegmentNo	TotalLength	
112/S-W0309/S081936	248.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V ROHITH		0.00
PhoneNo	EmailId	
9743222892		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction Of Covered Drain On 3rd C Cross Road In Domulur Layout In Ward No 112	1500000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN MAINTENANCE	112-14-000046
Work OrderNo	Work Order Date	Period of Extention
EE-60	11/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		rachppa
Date of Inspection	Remarks	
15/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0313	NA	Domulur Layout
SegmentNo	TotalLength	
112/S-W0313/S085004	81.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.Venkatesh		0.00
PhoneNo	EmailId	
9448012118		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
COnstruction Of Covered Drain On 3rd D Cross Domulur Layout in Ward no 112	2000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN MAINTENANCE	112-14-000054
Work OrderNo	Work Order Date	Period of Extention
EE-61	11/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		rachppa
Date of Inspection	Remarks	
15/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0050	NA	Park In HAL
SegmentNo	TotalLength	
112/S-W0050/S085438	110.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.P CONSTRUCTION		0.00
PhoneNo	EmailId	
9491916787		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Costruction Of Drain On 60 Feet Road Near Park In HAL Second STAGE In Ward N 112	1000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
	Drain Maintenance	112-14-000048
Work OrderNo	Work Order Date	Period of Extention
EE-67	02/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		rachppa
Date of Inspection	Remarks	
15/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0211	NA	CLUB ROAD
SegmentNo	TotalLength	
112/S-W0211/S090032	37.22	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V.ROHITH		0.00
PhoneNo	EmailId	
9743222892		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction Of Covered Drain On Damulur Club Road in ward no112-Domlur	2000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
	Drain Maintenance	112-14-000051
Work OrderNo	Work Order Date	Period of Extention
EE-74	09/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		rachppa
Date of Inspection	Remarks	
15/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0309	NA	Venkateswara Temple
SegmentNo	TotalLength	
112/S-W0309/S090549	248.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Naryanappa		0.00
PhoneNo	EmailId	
9448082676		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction Of Covered Drain On 2nd Cross Venkteswara Swamy Temple Road Domlur In Ward No 112-Domlur	2000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Drain Maintenance	112-14-000055
Work OrderNo	Work Order Date	Period of Extention
EE-78	30/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		rachppa
Date of Inspection	Remarks	
15/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0091	Om Shakthi Lyt 3rd Crs	Rama Temple Road
SegmentNo	TotalLength	
112/S-W0091/S091343	298.81	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V.Rohith		0.00
PhoneNo	EmailId	
9743222892		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction Of Covered Drains Rama Temple Dhooppanahalli Layout In Ward No 112	2000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Drain Maintenance	112-14-000049
Work OrderNo	Work Order Date	Period of Extention
EE-3	08/04/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		rachppa
Date of Inspection	Remarks	
15/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0355, W0357, W0278, W0339, W0345, W0276, W0288, W	NA, Mariyappa Lyt, Lakshmi Sagar Lyt, 1st Crs, S Krishnappa Lyt, 2nd Crs, R H B Colcny 2nd Main Rd,	Nagavalli Temple
SegmentNo	TotalLength	
112/C-W0355/S044116	199.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M S RAJU		0.00
PhoneNo	EmailId	
9036673220		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Masonry Drain with Covering slab at AK colony oppsite to Nagavalli temple in Ward No. 112 Domlur	1000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Others	Construction of Drain
Tender	WorkDetails	Job No Work Code
Tender	Construction of Drain, Providing Covering slabs and Construction of Culverts.	112-15-000049
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/47/2015-16	26/02/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/08/2016	31/07/2017	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Lakshmanapaa
Date of Inspection	Remarks	
01/08/2016		

Category	Photo
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0240	NA	Hutting colony opposite to Manjunatha temple
SegmentNo	TotalLength	
112/S-W0240/S053136	101.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
PARAMASHIVA. G. M		0.00
PhoneNo	EmailId	
9739047578	parichit2011@gmail.com	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of masonry drain with covering slab at Hutting colony opposite Sri Manjunatha Temple in ward No. 112 Domlur	700000	2014-15
Year	Type of Work	Other Work Type
2016 - 2017	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	CONSTRUCTION OF MASONARY DRAIN	112-15-000053
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/12/2016-17	27/04/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
06/08/2016	05/08/2017	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		C V LAKSHMANAPPA
Date of Inspection	Remarks	
08/08/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 112	WardName Domlur
StreetID W0236, W0299, W0305, W0230	StreetName 2nd Main Rd, Maheshwari Nagar Main Rd, Church Rd, NA	Significant LandMark Manjunatha Temple
SegmentNo 112/C-W0236/S035832	TotalLength 169.55	

ContractorDetails		
NameofContractor M P Constructions	ContractorRegNo	Expenditure 0.00
PhoneNo 9611594933	EmailId	

Work Details		
NameOfWork Providing and Laying Cement concrete to road 1st C and 1st B main road at Hutting colony in Ward No.112 Domlur and roads in Andhra colony in ward No.	Sanctioned Amount 1200000	Sanctioned Year 2015
Year 2014 - 2015	Type of Work Road	Other Work Type
Tender Tender	WorkDetails Cement concrete to roads	Job No Work Code 112-15-000056
Work OrderNo EE/SN/AE/VO/32/15-16	Work Order Date 01/02/2016	Period of Extention
Defect Liability Period From 29/02/2016	Defect Liability Period To 28/02/2017	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/02/2016	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0082, W0050, W0080, W0052	NA	Park 12th B Main HAL 2ND Stage
SegmentNo	TotalLength	
112/S-W0082/S094701	266.39	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M P Constructions		0.00
PhoneNo	EmailId	
9611594933		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of drain on 60 feet road near Park in HAL 2nd stage in Ward No.112 Domlur	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Earthwork excavation, Construction of Drain 2 sides	112-14-000048
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/67/2014-15	02/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/04/2015	29/04/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Laksmanappa
Date of Inspection	Remarks	
19/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0255, W0210, W0216, W0261, W0214, W0218, W0259, W	Mahadevapura Village Rd, NA, Ambedkar Nagar Slum	Hutti Maramma temple road
SegmentNo	TotalLength	
112/C-W0255/S023529	129.27	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S R Sreedhar kumar (M S Engineering Constructions)		0.00
PhoneNo	EmailId	
9036673220		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing and Laying Cement Concreting to Roads in Hutti Maramma Colony in Ward No 112 Domlur	600000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
Tender	Concreting to Roads	112-15-000048
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/51/2015-16	26/02/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/03/2016	29/03/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Lakshman
Date of Inspection	Remarks	
30/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0263, W0259, W0200, W0265, W0257, W0202, W0261, W	NA, Ambedkar Nagar Slum, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd, Mahadevapura Vill	Hutti Maramma Temple
SegmentNo	TotalLength	
112/C-W0263/S024928	156.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S R Sreedhar Kumar (M S Engineering Constructions)		0.00
PhoneNo	EmailId	
9036673220		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Masonary Drain with Covering Slab at Hutti Maramma Colony in Ward No 112 Domlur	400000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Others	Construction of Drain
Tender	WorkDetails	Job No Work Code
Tender	Earth Work Excavation, Construction of Drain and Providing covering slabs	112-15-000050
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/50/2015-16	26/02/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/03/2016	29/03/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Lakshman
Date of Inspection	Remarks	
30/03/2016		
Category	Photo	
Drain Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0337, W0339, W0333, W0343, W0331, W0345, W0288, W	NA, Lakshmi Sagar Lyt 6th Crs, S Krishnappa Lyt, 3rd A Crs Maheshwari Nagar, Mariyappa Lyt, Lakshmi	Nagavalli Temple
SegmentNo	TotalLength	
112/C-W0337/S050547	299.51	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M S RAJU		0.00
PhoneNo	EmailId	
9036673220		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing and Laying Cement Cenrete to Roads Cross at AK colony in ward no.112 Domlur	1400000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Road	
Tender	WorkDetails	Job No Work Code
Tender	Concreting to roads	112-15-000055
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/46/2016-16	26/02/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/08/2016	30/08/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Lakshmanappa
Date of Inspection	Remarks	
31/08/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	112	Domlur
StreetID	StreetName	Significant LandMark
W0157, W0123, W0096, W0129, W0151, W0145	NA	Doopanahalli Main road
SegmentNo	TotalLength	
112/C-W0157/S105717	123.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri. Prashanth Kumar. A		0.00
PhoneNo	EmailId	
9980090557	prashanthbys@gmail.com	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Concreting of road from Doopanahalli Arch to Yellamma temple cross in ward No. 112 Domlur	911366.75	2015-16
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
	Concreting of road	112-16-000005
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/57/2015-16	04/03/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		C V Lakshmanappa
Date of Inspection	Remarks	
06/09/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start

