



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0827	NA	Govt School
SegmentNo	TotalLength	
150/S-W0827/S045000	120.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.Seetharam		0.00
PhoneNo	EmailId	
8884593753		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads & drain at Govt School beside roads Devarabesanahalli village in Ward No - 150	1918000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000011
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/157/10-11		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0534	2nd Crs	Govt School
SegmentNo	TotalLength	
150/S-W0534/S045746	77.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.Seetharam		0.00
PhoneNo	EmailId	
8884593753		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads & drain at Govt School beside roads Devarabesanahalli village in Ward No - 150	1918000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000011
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/157/10-11	25/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0405, W0246, W0407	8th A Crs, NA, Mani Lyt 2nd Main Rd	BBMP Office
SegmentNo	TotalLength	
150/C-W0405/S050733	69.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B S Umashankar		0.00
PhoneNo	EmailId	
8884561231		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at bellanduru main road in Ward No - 150	1000000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000001
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/58/2010-11	25/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 150	WardName Bellanduru
StreetID W0391, W0417, W0393, W0693	StreetName NA	Significant LandMark DSR Cosmos Aparments
SegmentNo 150/C-W0391/S051417	TotalLength 161.30	

ContractorDetails		
NameofContractor B S Umashankar	ContractorRegNo	Expenditure 0.00
PhoneNo 8884561231	EmailId	

Work Details		
NameOfWork Improvements to road & drain at bellanduru colony in Ward No - 150	Sanctioned Amount 1000000	Sanctioned Year 2011
Year 2010 - 2011	Type of Work Others	Other Work Type
Tender Tender	WorkDetails 0	Job No Work Code 150-11-0000015
Work OrderNo EE/MD/WO/59/2010-11	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name Sandesh
Date of Inspection 08/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0292	3rd Crs Lakshmi Sagar Lyt	Govt School
SegmentNo	TotalLength	
150/S-W0292/S051945	47.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T Srinivas Reddy		0.00
PhoneNo	EmailId	
9491865265		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads & drains to cross roads at bellanduru in Ward No - 150	1500000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000002
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/167/2010-11	26/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0405, W0246	8th A Crs, NA	Govt School
SegmentNo	TotalLength	
150/C-W0405/S052255	62.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T Srinivas Reddy		0.00
PhoneNo	EmailId	
9491865265		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads & drains to cross roads at bellanduru in Ward No - 150	1500000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000002
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/167/2010-11	26/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0456	NA	Karnataka Bank
SegmentNo	TotalLength	
150/S-W0456/S052548	18.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T Srinivas Reddy		0.00
PhoneNo	EmailId	
9491865265		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads & drains to cross roads at bellanduru in Ward No - 150	1500000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000002
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/167/2010-11	26/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandhes
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0158	NA	Bagini House
SegmentNo	TotalLength	
150/S-W0158/S053057	388.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P Mukunda		0.00
PhoneNo	EmailId	
9916207405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Vivekananda Layout Munnekolala in Ward No - 150	1999000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000041
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/108/2011-12	08/02/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0148	NA	Vinayaka Layout
SegmentNo	TotalLength	
150/S-W0148/S053447	215.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R Srinivasa Reddy		0.00
PhoneNo	EmailId	
9491674845		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Vinayaka Layout & Manjunatha Layout in Ward No - 150	2000000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000003
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/155/2010-11	25/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0271	Ambedkar Nagar Slum	Vinayaka Layout
SegmentNo	TotalLength	
150/S-W0271/S054004	85.32	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R Srinivasa Reddy		0.00
PhoneNo	EmailId	
9491674845		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Vinayaka Layout & Manjunatha Layout in Ward No - 150	2000000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000003
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/155/2010-11	25/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0269, W0152, W0273, W0323, W0261, W0263	NA, 10th Crs Lakshmi Sagar Lyt	Vinayaka Layout
SegmentNo	TotalLength	
150/C-W0269/S054235	256.18	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R Srinivasa Reddy		0.00
PhoneNo	EmailId	
9491674845		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Vinayaka Layout & Manjunatha Layout in Ward No - 150	2000000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Others	BS Slab
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000003
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/155/2010-11	25/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0815, W0504, W0803	NA, N G E F Industrial Area	NGEF Industrial Area
SegmentNo	TotalLength	
150/C-W0815/S054732	85.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V Muniraju		0.00
PhoneNo	EmailId	
8884593837		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Devarabisanahalli village in Ward No - 150	1998000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000040
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/71/2011-12	28/07/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0803	NA	NGEF Industrial Area
SegmentNo	TotalLength	
150/S-W0803/S055200	127.50	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V Muniraju		0.00
PhoneNo	EmailId	
8884593837		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Devarabisanahalli village in Ward No - 150	1998000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000040
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/71/2011-12	28/07/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0815, W0803, W0506	NA	NGEF Industrial Area
SegmentNo	TotalLength	
150/C-W0815/S055407	93.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V Muniraju		0.00
PhoneNo	EmailId	
8884593837		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Devarabisanahalli village in Ward No - 150	1998000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000040
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/71/2011-12	28/07/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0799, W0516, W0514, W0524, W0803	NA, Muniswamy Shetty Lyt Rd	NGEF Industrial Area
SegmentNo	TotalLength	
150/C-W0799/S055703	65.99	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V Muniraju		0.00
PhoneNo	EmailId	
8884593837		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Devarabisanahalli village in Ward No - 150	1998000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000040
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/71/2011-12	28/07/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0815	NA	Govt School
SegmentNo	TotalLength	
150/S-W0815/S065243	247.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Seetharam		0.00
PhoneNo	EmailId	
8884593753		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Devarabesanahalli village in Ward No - 150	12000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000008
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/157/2010-11	25/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0213	NA	AET College
SegmentNo	TotalLength	
150/S-W0213/S065630	116.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V Muniraju		0.00
PhoneNo	EmailId	
8884593837		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Aet College surrounding roads in Doddakannelli Colony in Ward No - 150	1512000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000042
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/72/2011-12	28/07/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0216	NA	Maruthi Layout
SegmentNo	TotalLength	
150/S-W0216/S070307	206.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
H M Venkatachalapathi		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain in Munnekolala Maruthi Layout in Ward No - 150	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	CC Drain & Covering
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000007
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/01-52/WO/ /2013-14	06/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0212	NA	Maruthi Layout
SegmentNo	TotalLength	
150/S-W0212/S070531	111.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
H M Venkatachalapathi		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain in Munnekolala Maruthi Layout in Ward No - 150	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000007
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/01-52/WO/ /2013-14	06/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0622	NA	Vasalya Bhavan
SegmentNo	TotalLength	
150/S-W0622/S070754	67.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
H.M Venkatachalapathi		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain in Doddakannelli village in Ward No - 150	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000012
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/01-56/WO/63/2013-14	02/07/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1289	NA	Vasalya Bhavan
SegmentNo	TotalLength	
150/S-W1289/S071602	110.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
H.M Venkatachalapathi		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain in Doddakannelli village in Ward No - 150	2000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000012
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/01-56/WO/63/2013-14	02/07/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1295	NA	Vasalya Bhavan
SegmentNo	TotalLength	
150/S-W1295/S071905	111.96	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
H.M Venkatachalapathi		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain in Doddakannelli village in Ward No - 150	2000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000012
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/01-56/WO/63/2013-14	02/07/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandhes
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0228	NA	Lilli Line Road
SegmentNo	TotalLength	
150/S-W0228/S072102	81.96	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S G Manjunatha		0.00
PhoneNo	EmailId	
9492805326		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Munnekolala in Ward No - 150	1500000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000057
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/107/2012-13	02/07/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 150	WardName Bellanduru
StreetID W0339, W0335, W0228, W0333	StreetName NA	Significant LandMark Lilli Line Road
SegmentNo 150/C-W0339/S072416	TotalLength 148.68	

ContractorDetails		
NameofContractor S G Manjunatha	ContractorRegNo	Expenditure 0.00
PhoneNo 9492805326	EmailId	

Work Details		
NameOfWork Improvements to road & drain at Munnekolala in Ward No - 150	Sanctioned Amount 1500000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Others	Other Work Type
Tender Tender	WorkDetails 0	Job No Work Code 150-12-000057
Work OrderNo EE/MD/WO/107/2012-13	Work Order Date 02/07/2012	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name Sandesh
Date of Inspection 08/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0124	NA	Govt Lower Primary School
SegmentNo	TotalLength	
150/S-W0124/S072909	97.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Subramanyam		0.00
PhoneNo	EmailId	
9482753614		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads & drain at kadubeesanhalli in Ward No - 150	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/105/2013-14	12/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0122	NA	Govt Lower Primary School
SegmentNo	TotalLength	
150/S-W0122/S073141	106.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Subramanyam		0.00
PhoneNo	EmailId	
9482753614		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads & drain at kadubeesanhalli in Ward No - 150	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/105/2013-14	12/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1081	NA	St Peter School
SegmentNo	TotalLength	
150/S-W1081/S074113	269.70	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at kaikondrahalli in bellanduru in Ward No - 150	5000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000053
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/27/2013-14	20/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0668	NA	St Peter School
SegmentNo	TotalLength	
150/S-W0668/S074827	45.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at kaikondrahalli in bellanduru in Ward No - 150	5000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000053
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/27/2013-14	20/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0815, W0825, W0827	NA	Burial Ground
SegmentNo	TotalLength	
150/C-W0815/S075305	60.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K N Somashakar		0.00
PhoneNo	EmailId	
8884596325		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at burial ground surroundings area in devarabisanahalli in Ward No - 150	1999000	2012
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000053
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-122/WO/18/2012-13	18/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0815, W0825, W0534	NA, 2nd Crs	Burial Ground
SegmentNo	TotalLength	
150/C-W0815/S075554	58.09	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K N Somashakar		0.00
PhoneNo	EmailId	
8884596325		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at burial ground surroundings area in devarabisanahalli in Ward No - 150	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
	0	150-12-000053
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-122/WO/18/2012-13	18/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0829	NA	Burial Ground
SegmentNo	TotalLength	
150/S-W0829/S075712	50.60	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K N Somashakar		0.00
PhoneNo	EmailId	
8884596325		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at burial ground surroundings area in devarabisanahalli in Ward No - 150	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000053
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-122/WO/18/2012-13	18/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0176	NA	Ayyappa layout
SegmentNo	TotalLength	
150/S-W0176/S080001	486.03	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G R Subramanyam		0.00
PhoneNo	EmailId	
8884593582		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads & drains at Ayyappa layout Munnekolala in Ward No - 150	1996000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000039
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/19/WO/283/2012-13	26/02/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0033	NA	Challaghatta Colony
SegmentNo	TotalLength	
150/S-W0033/S080519	20.47	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Thimmarayappa		0.00
PhoneNo	EmailId	
9485236545		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain in Challaghatta Colony in Ward No - 150	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000004
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/91/2013-14	18/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0035	NA	Challaghatta Colony
SegmentNo	TotalLength	
150/S-W0035/S081034	15.18	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Thimmarayappa		0.00
PhoneNo	EmailId	
9485236545		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain in Challaghatta Colony in Ward No - 150	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000004
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/91/2013-14	18/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0037	NA	Challaghatta Colony
SegmentNo	TotalLength	
150/S-W0037/S081201	18.22	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Thimmarayappa		0.00
PhoneNo	EmailId	
9485236545		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain in Challaghatta Colony in Ward No - 150	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000004
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/91/2013-14	18/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0636	7th Crs	Karnataka Bank
SegmentNo	TotalLength	
150/S-W0636/S023224	69.67	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anil Kumar G		0.00
PhoneNo	EmailId	
9901652865		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road and drain at kaikondrahalli in Ward No - 150	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-14-000011
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/03-62/WO/94/2014-15	18/11/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0509	NA	Sakra Hospital
SegmentNo	TotalLength	
150/S-W0509/S024709	191.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting the existing and the approach road in front of Sakra World Hospital at devarabisanahally in Ward No - 150	12000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	150-14-000019
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/WO/181/2013-14	21/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1213	NA	Doddamma Temple
SegmentNo	TotalLength	
150/S-W1213/S070857	86.35	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anusha Constructions		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drains at Doddakannelli Village & Colony in Ward No - 150	1498000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000054
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-123/W0/152/12-13	11/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1215	NA	Doddamma Temple
SegmentNo	TotalLength	
150/S-W1215/S071452	64.93	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anusha Constructions		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drains at Doddakannelli Village & Colony in Ward No - 150	1498000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000054
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-123/W0/152/12-13	11/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0746	NA	Doddamma Temple
SegmentNo	TotalLength	
150/S-W0746/S071604	25.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anusha Constructions		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drains at Doddakannelli Village & Colony in Ward No - 150	1498000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000054
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-123/W0/152/12-13	11/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0748	NA	Doddamma Temple
SegmentNo	TotalLength	
150/S-W0748/S071749	61.22	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anusha Constructions		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drains at Doddakannelli Village & Colony in Ward No - 150	1498000	2012
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000054
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-123/W0/152/12-13	11/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0748, W0754, W1217, W0746	NA, Gunjur Vinayaka Nagar	Doddamma Temple
SegmentNo	TotalLength	
150/C-W0748/S071944	58.85	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anusha Constructions		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drains at Doddakannelli Village & Colony in Ward No - 150	1498000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	BS Slab Drain & Road Formation
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000054
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-123/W0/152/12-13	11/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0754	Gunjur Vinayaka Nagar	Doddamma Temple
SegmentNo	TotalLength	
150/S-W0754/S072113	78.28	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anusha Constructions		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drains at Doddakannelli Village & Colony in Ward No - 150	1498000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000054
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-123/W0/152/12-13	11/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0750	NA	Doddamma Temple
SegmentNo	TotalLength	
150/S-W0750/S072255	54.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anusha Constructions		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drains at Doddakannelli Village & Colony in Ward No - 150	1498000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000054
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-123/W0/152/12-13	11/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1231	NA	Doddamma Temple
SegmentNo	TotalLength	
150/S-W1231/S072427	108.57	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anusha Constructions		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drains at Doddakannelli Village & Colony in Ward No - 150	1498000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000054
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-123/W0/152/12-13	11/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0752	Vinayaka Nagar	Doddamma Temple
SegmentNo	TotalLength	
150/S-W0752/S072605	104.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anusha Constructions		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drains at Doddakannelli Village & Colony in Ward No - 150	1498000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000054
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-123/W0/152/12-13	11/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0519, W0525, W0531, W0360, W0527, W0517, W0533, W	NA	Davarabisanahalli main road
SegmentNo	TotalLength	
150/C-W0519/S104609	634.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K Prakash Babu		0.00
PhoneNo	EmailId	
9884593837		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drains and Covering at Davarabisanahalli main road in Ward No - 150	1990000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000051
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-120/W0/02/12- 13	18/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0480	NA	Ganesh Temple
SegmentNo	TotalLength	
150/S-W0480/S104914	119.18	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G Ganapathy		0.00
PhoneNo	EmailId	
9884593837		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road and drains at Narayana Reddy Layout at Kaikonadrahalli in Ward No - 150	1990000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000050
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-119/W0/01/11-12	18/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandhes
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0482	4th Crs	Ganesh Temple
SegmentNo	TotalLength	
150/S-W0482/S105802	51.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G Ganapathy		0.00
PhoneNo	EmailId	
9884593837		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road and drains at Narayana Reddy Layout at Kaikonadrahalli in Ward No - 150	1990000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000050
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-119/W0/01/11-12	18/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0168	NA	PR Layout 4th & 5th Cross
SegmentNo	TotalLength	
150/S-W0168/S105959	238.85	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anusha Constructions		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads in PR Layout at Munnekolala in Ward No - 150	5000000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000050
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/02-01/WO/141/12-13	22/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0170	NA	PR Layout 4th & 5th Cross
SegmentNo	TotalLength	
150/S-W0170/S110227	224.24	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anusha Constructions		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads in PR Layout at Munnekolala in Ward No - 150	5000000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000050
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/02-01/WO/141/12-13	22/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0295, W0279, W0253, W0172, W0289	NA, Ambedkar Nagar Slum, Chikkanna Lyt	PR Layout 2nd & 3rd Cross
SegmentNo	TotalLength	
150/C-W0295/S110455	241.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anusha Constructions		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads in Balance portion in Ayyappa Layout Munnekolala in Ward No - 150	4500000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
	0	150-11-000051
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/02-02/WO/140/12- 13	22/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0295	NA	PR Layout 2nd & 3rd Cross
SegmentNo	TotalLength	
150/S-W0295/S111202	47.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anusha Constructions		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads in Balance portion in Ayyappa Layout Munnekolala in Ward No - 150	4500000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000051
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/02-02/WO/140/12-13	22/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0624, W0622, W0997, W0620, W1003, W1001	4th Crs, NA, 3rd Crs	Bata showroom
SegmentNo	TotalLength	
150/S-W0624/S035920	217.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N Eshwararaju		0.00
PhoneNo	EmailId	
9731765818		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of drains	4800000	2015-16
Year	Type of Work	Other Work Type
2015 - 2016	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of drains at kasavanhalli road (Bata Show Room)	150-16-000021
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/04- 89/WO/154/2015-16	28/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Raghavendra prasad
Date of Inspection	Remarks	
17/05/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 150	WardName Bellanduru
StreetID W0995, W0640, W0638, W0993, W0999, W0636	StreetName NA, 7th Crs	Significant LandMark Kalkondrahalli
SegmentNo 150/C-W0995/S120209	TotalLength 198.25	

ContractorDetails		
NameofContractor Anil Kumar G	ContractorRegNo	Expenditure 0.00
PhoneNo 9901652865	EmailId	

Work Details		
NameOfWork Improvements to road and drains at Kaikondrahalli in	Sanctioned Amount 1000000	Sanctioned Year 2014-15
Year 2014 - 2015	Type of Work Road	Other Work Type
Tender Tender	WorkDetails Improvements to road and drains at Kaikondrahalli in	Job No Work Code 150-14-000011
Work OrderNo EE/MD/E-PMT/03-62/WO/94/2014-15	Work Order Date 18/11/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name Raghavendra
Date of Inspection 16/06/2016	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0533	NA	Devarabisanahalli
SegmentNo	TotalLength	
150/S-W0533/S100245	64.22	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.S.Prasad		0.00
PhoneNo	EmailId	
9663779514		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing drains at devarabisanahalli in ward No:150	366416	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	CC Drain and culvert
Tender	WorkDetails	Job No Work Code
Tender	CC Drain and culvert	150-16-000033
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/09/-19/WO/192/2016-17	27/12/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		N. venkatesh
Date of Inspection	Remarks	
10/02/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0483	NA	Jandardhana Reddy House
SegmentNo	TotalLength	
150/S-W0483/S025040	390.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B.S Umashankar		0.00
PhoneNo	EmailId	
9448761965		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road and drains from Outer Ring road to Jandardhana Reddy House at bellanduru in Ward No - 150	2000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000048
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/52/2012-13	18/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0393	NA	Parijatha Aparments
SegmentNo	TotalLength	
150/S-W0393/S030831	138.89	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Jayanna		0.00
PhoneNo	EmailId	
8884593837		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road Parijatha Aparments in Green Glen Layout Bellanudru in Ward No - 150	1000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000049
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55- 118/W0/148/2012-13	11/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1033	NA	Near Havell's Galaxy
SegmentNo	TotalLength	
150/S-W1033/S033404	110.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Jayanna		0.00
PhoneNo	EmailId	
8884593837		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads & drains at Maruthi Layout kaikondrahalli Village in Ward No - 150	2000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000058
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-127/WO/12-13	11/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1035	6th Crs	Near Havell's Galaxy
SegmentNo	TotalLength	
150/S-W1035/S033845	94.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Jayanna		0.00
PhoneNo	EmailId	
8884593873		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads & drains at Maruthi Layout kaikondrahalli Village in Ward No - 150	2000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000058
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-127/WO/150/12-13	11/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 150	WardName Bellanduru
StreetID W0339, W0335, W0228, W0333	StreetName NA	Significant LandMark Shanthi Nikethana Layout
SegmentNo 150/C-W0339/S034517	TotalLength 95.47	




ContractorDetails		
NameofContractor Sampamgirama Reddy	ContractorRegNo	Expenditure 0.00
PhoneNo 9880274879	EmailId	

Work Details		
NameOfWork Improvements to roads in Shanthi Nikethana Layout at Munnekollala in Ward No - 150	Sanctioned Amount 1500000	Sanctioned Year 2012
Year 2011 - 2012	Type of Work Others	Other Work Type
Tender Tender	WorkDetails 0	Job No Work Code 150-12-000041
Work OrderNo EE/MD/E-TND/31/WO/369/11-12	Work Order Date 13/02/2012	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name sindesh
Date of Inspection 06/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1301, W0850	NA	Mosque
SegmentNo	TotalLength	
150/C-W1301/S035550	91.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anusha Constructions		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads & drains at Haralaru Village in Ward No - 150	1500000	2012
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000055
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-124/WO/151/2012-13	11/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 150	WardName Bellanduru
StreetID W0216, W0355, W0236, W0238	StreetName NA, 2nd Main Rd	Significant LandMark Shanthi Nikethana Layout
SegmentNo 150/C-W0216/S052722	TotalLength 94.03	

ContractorDetails		
NameofContractor Sampamgirama Reddy	ContractorRegNo	Expenditure 0.00
PhoneNo 9880274879	EmailId	

Work Details		
NameOfWork Improvements to roads in Shanthi Nikethana Layout at Munnekollala in Ward No - 150	Sanctioned Amount 1500000	Sanctioned Year 2012
Year 2011 - 2012	Type of Work Others	Other Work Type
Tender Tender	WorkDetails 0	Job No Work Code 150-12-000041
Work OrderNo EE/MD/E-TND/31/WO/369/11-12	Work Order Date 13/02/2012	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name Sandesh
Date of Inspection 08/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0317, W0162, W0168, W0287, W0166, W0311, W0164, W	NA, Maheshwari Nagar 4th Main Rd	KMF DAIRY
SegmentNo	TotalLength	
150/C-W0317/S084849	747.11	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P.MUKUNDA		3646397.00
PhoneNo	EmailId	
9980601235		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to main road and cross roads at P.R Layout Munnekolala	3800000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		150-16-000017
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/06- 12/WO/90/2016-17	31/05/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/07/2016	29/07/2018	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		RAGHAVENDRA
Date of Inspection	Remarks	
19/08/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1072, W1549, W1551, W1573, W1088, W1571, W1529, W	NA, Street Rd	Doddakannahalli
SegmentNo	TotalLength	
150/C-W1072/S093244	627.76	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P.MUKUNDA		3428215.00
PhoneNo	EmailId	
9980601235		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Balance portion roads & drains at Doddakannalli.	3500000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	Drains & Roads
Tender	WorkDetails	Job No Work Code
Tender		150-14-000033
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/06-64/W0/91/2016 -17	31/05/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/07/2016	28/07/2018	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		RAGHAVENDRA
Date of Inspection	Remarks	
19/08/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 150	WardName Bellanduru
StreetID W0450, W0721, W0717, W0715	StreetName Papayya Reddy Lyt, 15th Crs, NA	Significant LandMark COFFEE DAY
SegmentNo 150/C-W0450/S095102	TotalLength 193.26	

ContractorDetails		
NameofContractor SUNIL J	ContractorRegNo	Expenditure 1590250.00
PhoneNo 9980601235	EmailId	

Work Details		
NameOfWork Improvements to roads and drains from ORR to Ambalipura Main Road via Pearl paradise apartment road and surroundings (Behind Coffee Day)	Sanctioned Amount 1600000	Sanctioned Year 2016
Year 2015 - 2016	Type of Work Others	Other Work Type Roads & Drains
Tender Tender	WorkDetails	Job No Work Code 150-16-000025
Work OrderNo EE/MD/E-PMT/06-19/W0/65/2016 -17	Work Order Date 17/05/2016	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/08/2016	

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0815, W0508, W0781, W0803, W0779, W0504, W0777, W	NA, Itpl Main Rd, Munireddy Lyt Rd, N G E F Industrial Area, Mariyappa Lyt Rd	SLS Apprt
SegmentNo	TotalLength	
150/C-W0815/S115126	683.58	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.Eshwararaju		0.00
PhoneNo	EmailId	
9945277738		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvmnts to Balance portion roads and drains at Devarabisanahally in ward No:150	3855577	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	RCC Drains
Tender	WorkDetails	Job No Work Code
Tender	RCC Drains	150-14-000032
Work OrderNo	Work Order Date	Period of Extention
EE/ME/E-PMT/06- 63/WO/89/2016-17	30/05/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
19/10/2016	18/10/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Venkatesh.N
Date of Inspection	Remarks	
03/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0547, W0555, W0545, W0388, W0549	1st Crs, NA, Doddamuniswammppa Lyt, 3rd Crs	Kariyamma Aghara(HAL Layout
SegmentNo	TotalLength	
150/C-W0547/S122642	211.57	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.Venugopala Raju		0.00
PhoneNo	EmailId	
9731765818		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement to Balance roads and Drains at Kariyamma Aghara at ward No:150	999060	2016
Year	Type of Work	Other Work Type
2016 - 2017	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Improvement to Balance roads and Drains at Kariyamma Aghara at ward No:150	150-14-000039
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/06- 67/WO/75/2016-17	20/05/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
19/10/2016	18/10/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Venkatesh.N
Date of Inspection	Remarks	
03/12/2016		



Category	Photo
Road Condition	
Segment End	 
Segment End	 



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0521	NA	Venu Gopala Swamy Temple
SegmentNo	TotalLength	
150/S-W0521/S034117	118.68	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B N Mohan Kumar		0.00
PhoneNo	EmailId	
8884593837		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drain from Venu Gopala Swamy Temple to Papanna Reddy House in Devarabesanahalli in Ward No - 150	1000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000052
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-121/WO/206/2012-13	15/11/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0523	NA	Venu Gopala Swamy Temple
SegmentNo	TotalLength	
150/S-W0523/S035305	106.02	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B N Mohan Kumar		0.00
PhoneNo	EmailId	
8884593837		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drain from Venu Gopala Swamy Temple to Papanna Reddy House in Devarabesanahalli in Ward No - 150	1000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	CC Road & CC Drain
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000052
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-121/WO/206/2012-13	15/11/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0897	NA	Near Ayyappa Swamy Temple
SegmentNo	TotalLength	
150/S-W0897/S035803	98.27	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B S Uma Shankar		0.00
PhoneNo	EmailId	
9448761965		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road and drain behind Ayyappa Swamy Temple Devarabisarahalli in Ward No - 150	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-14-000004
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/WO/86/2014-15	20/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0889	NA	Near Ayyappa Swamy Temple
SegmentNo	TotalLength	
150/S-W0889/S040406	85.51	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B S Uma Shankar		0.00
PhoneNo	EmailId	
9448761965		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road and drain behind Ayyappa Swamy Temple Devarabisarahalli in Ward No - 150	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-14-000004
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/WO/86/2014-15	20/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0502, W0498, W0777, W0500, W0515, W0496, W0506	2nd Crs, NA, Mariyappa Lyt Rd, 60 Feet Main Rd	Near Weone Bakery (Umesh House Road)
SegmentNo	TotalLength	
150/C-W0502/S040706	70.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B S Uma Shankar		0.00
PhoneNo	EmailId	
9448761965		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road and drain behind Ayyappa Swamy Temple Devarabisarahalli in Ward No - 150	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-14-000004
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/WO/86/2014-15	20/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0895	NA	Shyamanna Master House
SegmentNo	TotalLength	
150/S-W0895/S041918	95.24	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anil Kumar G		0.00
PhoneNo	EmailId	
9901652865		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road and drain Behind Main Road in Devarabisanahalli Colony in Ward No - 150	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-14-000005
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/02-22/WO/74/2014-15	26/08/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0873	Renuka Lyt	Madappa House
SegmentNo	TotalLength	
150/S-W0873/S042725	78.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anil Kumar G		0.00
PhoneNo	EmailId	
9901652865		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road and drain Behind Main Road in Devarabisanahalli Colony in Ward No - 150	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-14-000005
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/02-22/WO/74/2014-15	26/08/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0875	NA	Vinodamma House
SegmentNo	TotalLength	
150/S-W0875/S042943	61.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anil Kumar G		0.00
PhoneNo	EmailId	
9901652865		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road and drain Behind Main Road in Devarabisanahalli Colony in Ward No - 150	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-14-000005
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/02-22/WO/74/2014-15	26/08/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0799, W0516, W0793	NA, Muniswamy Shetty Lyt Rd	Near Gopal Reddy House
SegmentNo	TotalLength	
150/C-W0799/S050539	95.98	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
HM Venkatachalapathi		0.00
PhoneNo	EmailId	
9845332889		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road and Drain in Devarabisanahalli Colony in Ward No - 150	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000008
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/01-53/WO/68/2013-14	06/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0289	Chikkanna Lyt	PR Layout 2nd & 3rd Cross
SegmentNo	TotalLength	
150/S-W0289/S111317	28.09	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anusha Constructions		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads in Balance portion in Ayyappa Layout Munnekolala in Ward No - 150	4500000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000051
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/02-02/WO/140/12-13	22/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0906	NA	Kasanahalli Main Road
SegmentNo	TotalLength	
150/S-W0906/S111457	112.38	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sampamgirama Reddy		0.00
PhoneNo	EmailId	
9880274879		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road and drain at kasanahalli Village in Ward No - 150	1600000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/WO/142/10-11	25/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0904	NA	Kasanahalli Main Road
SegmentNo	TotalLength	
150/S-W0904/S111807	131.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sampamgirama Reddy		0.00
PhoneNo	EmailId	
9880274879		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road and drain at kasanahalli Village in Ward No - 150	1600000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/WO/142/10-11	25/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1040, W1489, W1491	NA	Radhareddy Layout
SegmentNo	TotalLength	
150/C-W1040/S115234	276.99	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P. Damodhara Raju		0.00
PhoneNo	EmailId	
8884593876		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of drain and metalling, asphaltting, Sarjapura line road in Doddakannelli Village in Ward No - 150	2500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	CC Drain & Metalling
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000049
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/39/WO/320/11-12	17/12/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0666	NA	Gayathri Layout
SegmentNo	TotalLength	
150/S-W0666/S115643	39.10	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P. Damodhara Raju		0.00
PhoneNo	EmailId	
8887531590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Kaikonadrahalli village at Ward No - 150	1098000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000008
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/10/WO/146/10-11		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1101	NA	Gayathri Layout
SegmentNo	TotalLength	
150/S-W1101/S120040	103.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P. Damodhara Raju		0.00
PhoneNo	EmailId	
8887531590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Kaikonadrahalli village at Ward No - 150	1098000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000008
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/10/WO/146/10-11	25/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1071	NA	Gayathri Layout
SegmentNo	TotalLength	
150/S-W1071/S120318	121.60	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P. Damodhara Raju		0.00
PhoneNo	EmailId	
8887531590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Kaikonadrahalli village at Ward No - 150	1098000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000008
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/10/WO/146/10-11	25/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1069	NA	Gayathri Layout
SegmentNo	TotalLength	
150/S-W1069/S120803	251.11	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P. Damodhara Raju		0.00
PhoneNo	EmailId	
8887531590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Kaikonadrahalli village at Ward No - 150	1098000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000008
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/10/WO/146/10-11	25/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1099	NA	Gayathri Layout
SegmentNo	TotalLength	
150/S-W1099/S120928	200.75	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P. Damodhara Raju		0.00
PhoneNo	EmailId	
8887531590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Kaikonadrahalli village at Ward No - 150	1098000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000008
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/10/WO/146/10-11	25/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1105	NA	Gayathri Layout
SegmentNo	TotalLength	
150/S-W1105/S121135	70.77	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P. Damodhara Raju		0.00
PhoneNo	EmailId	
8887531590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Kaikonadrahalli village at Ward No - 150	1098000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000008
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/10/WO/146/10-11	25/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0263	NA	Manjunatha Layout
SegmentNo	TotalLength	
150/S-W0263/S121623	30.08	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R. Srinivasa Reddy		0.00
PhoneNo	EmailId	
9492805522		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads & Drainage in Munnekolala Village in Ward No - 150	1918000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000003
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/10/WO/155/10-11	25/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0152, W0261, W0263	NA	Manjunatha Layout
SegmentNo	TotalLength	
150/C-W0152/S121949	72.95	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R. Srinivasa Reddy		0.00
PhoneNo	EmailId	
9492805522		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads & Drainage in Munnekolala Village in Ward No - 150	1918000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	Metalling
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000003
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/10/WO/155/10-11	25/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0337	NA	Lilly Road
SegmentNo	TotalLength	
150/S-W0337/S122158	83.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K Seetaram		0.00
PhoneNo	EmailId	
9752052533		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads in lilly lane in Munnekolala at bellanduru Ward No - 150	2000000	2012
Year	Type of Work	Other Work Type
2010 - 2011	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000040
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/318/11-12	12/10/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
28/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 150	WardName Bellanduru
StreetID W0339, W0232, W0337, W0234	StreetName NA	Significant LandMark Lilly Road
SegmentNo 150/C-W0339/S123857	TotalLength 114.77	

ContractorDetails		
NameofContractor K Seetaram	ContractorRegNo	Expenditure 0.00
PhoneNo 9752052533	EmailId	

Work Details		
NameOfWork Improvements to roads in lilly lane in Munnekolala at bellanduru Ward No - 150	Sanctioned Amount 2000000	Sanctioned Year 2012
Year 2011 - 2012	Type of Work Others	Other Work Type
Tender Tender	WorkDetails 0	Job No Work Code 150-12-000040
Work OrderNo EE/MD/WO/318/11-12	Work Order Date 12/10/2011	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name Sandesh
Date of Inspection 08/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0355, W0238, W0359	NA	Lilly Road
SegmentNo	TotalLength	
150/C-W0355/S124048	31.99	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K Seetaram		0.00
PhoneNo	EmailId	
9752052533		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads in lilly lane in Munnekolala at bellanduru Ward No - 150	2000000	2012
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000040
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/318/11-12	12/10/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0349	7th Main Rd, G M Palya	Lilly Road
SegmentNo	TotalLength	
150/S-W0349/S124243	77.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K Seetaram		0.00
PhoneNo	EmailId	
9752052533		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads in lilly lane in Munnekolala at bellanduru Ward No - 150	2000000	2012
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000040
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/318/11-12	12/10/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0815	NA	School Road
SegmentNo	TotalLength	
150/S-W0815/S124448	247.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V Muniraju		0.00
PhoneNo	EmailId	
8884598653		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drains at Devarabesanahalli village in Ward No - 150	1998000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000040
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/19/WO/71/2011-12	28/07/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0815, W0803, W0506	NA	School Road
SegmentNo	TotalLength	
150/C-W0815/S124749	96.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V Muniraju		0.00
PhoneNo	EmailId	
8884598653		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drains at Devarabesanahalli village in Ward No - 150	1998000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000040
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/19/WO/71/2011-12	28/07/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0540	NA	Bhoganahally Bus Stop
SegmentNo	TotalLength	
150/S-W0540/S124939	53.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Jayanna		0.00
PhoneNo	EmailId	
8884593875		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains at Bhoganahally village in Ward no - 150	5000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000053
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/18/WO/69/2011-12		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1043, W1041, W1047	3rd Crs, 4th Crs, 1st Crs	Auto Stand
SegmentNo	TotalLength	
150/C-W1043/S125249	77.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P. Damodhara Raju		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Kaikonadrahalli village in Ward No - 150	1200000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000008
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/146/2011-12		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1543	NA	Doddakannelli Village
SegmentNo	TotalLength	
150/S-W1543/S125615	110.71	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P S Athammanadha		0.00
PhoneNo	EmailId	
9498625761		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Doddakannelli Village in Ward No - 150	2000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	BS Slab & WEM
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000013
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/154/2011-12		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1533	NA	Doddakannelli Village
SegmentNo	TotalLength	
150/S-W1533/S010210	148.21	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P S Athammanadha		0.00
PhoneNo	EmailId	
9498625761		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Doddakannelli Village in Ward No - 150	2000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000013
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/154/2011-12		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1567	NA	Doddakannelli Village
SegmentNo	TotalLength	
150/S-W1567/S010408	102.41	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P S Athammanadha		0.00
PhoneNo	EmailId	
9498625761		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & drain at Doddakannelli Village in Ward No - 150	2000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000013
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/154/2011-12		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandhes
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0148, W0263, W0150	NA	Adishwara Building
SegmentNo	TotalLength	
150/C-W0148/S010806	103.49	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R. Srinivasa Reddy		0.00
PhoneNo	EmailId	
9492805522		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at Munnekolala village in ward no - 150	2000000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	CC Road
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000003
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/10/WO/155/10-11	25/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0152, W0261, W0263	NA	Adishwara Building
SegmentNo	TotalLength	
150/C-W0152/S011320	73.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R. Srinivasa Reddy		0.00
PhoneNo	EmailId	
9492805522		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at Munnekolala village in ward no - 150	2000000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	CC Road
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000003
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/10/WO/155/10-11	25/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0154	NA	Adishwara Building
SegmentNo	TotalLength	
150/S-W0154/S011426	91.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R. Srinivasa Reddy		0.00
PhoneNo	EmailId	
9492805522		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at Munnekolala village in ward no - 150	2000000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000003
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/10/WO/155/10-11	25/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0317, W0162, W0168, W0166, W0164, W0315, W0160, W	NA	Kempapura Village
SegmentNo	TotalLength	
150/C-W0317/S011844	329.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
H N Mohan		0.00
PhoneNo	EmailId	
8884598387		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road & Drain at Kempapura Village in Ward No - 150	1000000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-11-000017
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/150/2011-12		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
28/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0314, W0477, W0479, W0467, W0469, W0312, W0483, W	NA, 1st Crs, 4th Crs, 3rd Crs, Chikkanna Lyt 3rd Crs, Lakshmi Sagar Lyt, 1st Crs	Bellanduru main road 8 & 10th cross
SegmentNo	TotalLength	
150/C-W0314/S121831	395.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B S Umashakar		2984480.00
PhoneNo	Emailld	
9448761965		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvmnts to Balance portion of Roads and Drains at Bellandur in ward No:150	2997157	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	CC Roads and Drains
Tender	WorkDetails	Job No Work Code
Tender	CC Roads and Drains	150-14-000037
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/06- 65/WO/120/2016-17	09/06/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
06/09/2016	05/09/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		venkatesh
Date of Inspection	Remarks	
25/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0685	NA	Vijaya Lakshmi Hard ware
SegmentNo	TotalLength	
150/S-W0685/S015606	107.44	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S R Ravindra		0.00
PhoneNo	EmailId	
9880818290		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvmnts of Roads and drains at SJR Apartments sourroundings at Amnalipura In ward No:150	1500000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	CC Road and Drain
Tender	WorkDetails	Job No Work Code
Tender	Improvmnts of Roads and drains at SJR Apartments sourroundings at Amnalipura In ward No:150	150-14-000038
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/06-66/WO/56/2016-17	11/05/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
08/08/2016	07/08/2017	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		venkatesh
Date of Inspection	Remarks	
25/11/2016		
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0518, W0516, W0793, W0524	NA, Muniswamy Shetty Lyt Rd	Near Gopal Reddy House
SegmentNo	TotalLength	
150/C-W0518/S051124	33.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
HM Venkatachalapathi		0.00
PhoneNo	EmailId	
9845332889		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road and Drain in Devarabisanahalli Colony in Ward No - 150	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000008
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/01-53/WO/68/2013-14	06/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0524	NA	Near Gopal Reddy House
SegmentNo	TotalLength	
150/S-W0524/S051322	107.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
HM Venkatachalapathi		0.00
PhoneNo	EmailId	
9845332889		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road and Drain in Devarabisanahalli Colony in Ward No - 150	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	CC Drain
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000008
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/01-53/WO/68/2013-14	06/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0841, W0843, W0839, W0859, W0857, W0853	NA	Near Annapurnashwari Temple
SegmentNo	TotalLength	
150/C-W0841/S052042	71.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
HM Venkatachalapathi		0.00
PhoneNo	EmailId	
9845332889		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains at behind Near Annapurnashwari Temple and surrounding areas in Devarabisanahalli in Ward No - 150	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000009
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/01-54/WO/69/2013-14	06/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandhes
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0841	NA	Near Annapurnashwari Temple
SegmentNo	TotalLength	
150/S-W0841/S053044	56.39	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
HM Venkatachalapathi		0.00
PhoneNo	EmailId	
9845332889		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains at behind Near Annapurnashwari Temple and surrounding areas in Devarabisanahalli in Ward No - 150	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000009
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/01-54/WO/69/2013-14	06/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0843	NA	Near Annapurnashwari Temple
SegmentNo	TotalLength	
150/S-W0843/S053357	55.29	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
HM Venkatachalapathi		0.00
PhoneNo	EmailId	
9845332889		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains at behind Near Annapurnashwari Temple and surrounding areas in Devarabisanahalli in Ward No - 150	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000009
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/01-54/WO/69/2013-14	06/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandesh
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0156	NA	Ananda Reddy House
SegmentNo	TotalLength	
150/S-W0156/S102824	312.93	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Jayanna		0.00
PhoneNo	EmailId	
9901199168		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road and drain from Ananda Reddy House to CKB Layout Munnekolala in Ward No - 150	1500000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000056
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-125/WO/149/2012-13	11/11/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0325, W0152, W0273, W0323, W0156, W0150	NA, 10th Crs Lakshmi Sagar Lyt	Ananda Reddy House
SegmentNo	TotalLength	
150/C-W0325/S103451	104.47	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Jayanna		0.00
PhoneNo	EmailId	
9901199168		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road and drain from Ananda Reddy House to CKB Layout Munnekolala in Ward No - 150	1500000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-12-000056
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55- 125/WO/149/2012-13	11/11/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0683	NA	Narayana School
SegmentNo	TotalLength	
150/S-W0683/S103723	232.24	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Reasphating of road at Bellanduru Green Glen Layout in Ward No - 150	1000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	150-13-000034
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/WO/68/2012-13-14	14/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 150	WardName Bellanduru
StreetID W0150	StreetName NA	Significant LandMark SGR Dental College Road
SegmentNo 150/S-W0150/S104854	TotalLength 709.16	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9480828222	EmailId	

Work Details		
NameOfWork Reasphalting of road at Munnekolala Main Road in Ward No - 150	Sanctioned Amount 2000000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Asphalting	Other Work Type
Tender Not a Tender	WorkDetails 0	Job No Work Code 150-13-000027
Work OrderNo BBMP/EE/MD/WO/50/2012-13	Work Order Date 14/03/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name Sandesh
Date of Inspection 08/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1107, W1099, W1101, W1069, W0666	NA	Bata Showroom
SegmentNo	TotalLength	
150/C-W1107/S105510	195.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Reasphalting of road at Sarjapura road Bata Showroom to 1st Main Kasavanahalli in Ward No - 150	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	150-13-000031
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/53/2012-13	14/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0666	NA	Bata Showroom
SegmentNo	TotalLength	
150/S-W0666/S110851	39.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Reasphalting of road at Sarjapura road Bata Showroom to 1st Main Kasavanahalli in Ward No - 150	1000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	150-13-000031
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/53/2012-13	14/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1101	NA	Bata Showroom
SegmentNo	TotalLength	
150/S-W1101/S111007	103.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Reasphalting of road at Sarjapura road Bata Showroom to 1st Main Kasavanahalli in Ward No - 150	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	150-13-000031
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/53/2012-13	14/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0652, W1099, W1101, W1071, W1103, W0662, W0664, W	NA	Bata Showroom
SegmentNo	TotalLength	
150/C-W0652/S111205	203.03	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Reasphalting of road at Sarjapura road Bata Showroom to 1st Main Kasavanahalli in Ward No - 150	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	150-13-000031
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/53/2012-13	14/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0652, W1069	NA	Bata Showroom
SegmentNo	TotalLength	
150/C-W0652/S111348	115.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Reasphalting of road at Sarjapura road Bata Showroom to 1st Main Kasavanahalli in Ward No - 150	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	150-13-000031
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/53/2012-13	14/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0660	NA	Bata Showroom
SegmentNo	TotalLength	
150/S-W0660/S111601	36.08	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Reasphalting of road at Sarjapura road Bata Showroom to 1st Main Kasavanahalli in Ward No - 150	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	150-13-000031
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/53/2012-13	14/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0853	NA	Near Annapurnashwari Temple
SegmentNo	TotalLength	
150/S-W0853/S111745	56.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
HM Venkatachalapathi		0.00
PhoneNo	EmailId	
9845332889		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains at behind Near Annapurnashwari Temple and surrounding areas in Devarabisanahalli in Ward No - 150	2000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-13-000009
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/01-54/WO/69/2013-14	06/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0162	NA	Vinayaka Nagar
SegmentNo	TotalLength	
150/S-W0162/S112011	435.57	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Reasphalting of roads at Munnekolala P.R layout Main Road surroundings rafeeds in Ward No - 150	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	150-13-000032
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/55/2012-13	14/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0317, W0162, W0168, W0166, W0164, W0184, W0170, W	NA	Vinayaka Nagar
SegmentNo	TotalLength	
150/C-W0317/S112755	245.60	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Reasphalting of roads at Munnekolala P.R layout Main Road surroundings rafeeds in Ward No - 150	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	150-13-000032
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/55/2012-13	14/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0287, W0311, W0309, W0172	Maheshwari Nagar 4th Main Rd, NA	Vinayaka Nagar
SegmentNo	TotalLength	
150/C-W0287/S112912	57.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Reasphalting of roads at Munnekolala P.R layout Main Road surroundings rafeeds in Ward No - 150	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	150-13-000032
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/55/2012-13	14/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0543	NA	Patel School
SegmentNo	TotalLength	
150/S-W0543/S113204	619.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Reasphalting of road at Kariyamma Agradhara Main Road in Ward No - 150	2000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	150-13-000023
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/113/2012-13	14/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandesh
Date of Inspection	Remarks	
08/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W0555	NA	Patel School
SegmentNo	TotalLength	
150/S-W0555/S113709	277.25	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Reasphalting of road at Kariyamma Agradhara Main Road in Ward No - 150	2000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
	0	150-13-000023
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/113/2012-13	14/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sindesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1393, W0938, W1107, W1099, W0658, W0942, W0656, W	NA, 2nd Crs	Vaishnavi Apartment
SegmentNo	TotalLength	
150/C-W1393/S105337	678.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B.T.TAVIKUMAR		2892947.00
PhoneNo	EmailId	
7353903103		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement to road at Kasavanahalli road(Bata Showroom road)	3000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Road	
Tender	WorkDetails	Job No Work Code
Tender		150-16-000020
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/06- 15/WO/92/2016-17	31/05/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		P. A. RAGHAVENDRA
Date of Inspection	Remarks	
20/08/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	150	Bellanduru
StreetID	StreetName	Significant LandMark
W1405, W1172, W1403, W1401, W1805, W1409, W0918, W	NA, 7th Crs, 8th Crs, 15th Crs	KPC Layout
SegmentNo	TotalLength	
150/C-W1405/S093545	974.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B.T Ravi Kumar		0.00
PhoneNo	EmailId	
7353903103		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains in KPC Layout 2nd Main and balancec cross roads Kasavanahalli at ward No:150	4675977	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	Asphalting and Drains
Tender	WorkDetails	Job No Work Code
Tender	Asphalting and Drains	150-16-000023
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/06-16/WO/103/2016-17	03/06/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Venkatesh
Date of Inspection	Remarks	
28/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start

