



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0145	NA	Food Godown Road
SegmentNo	TotalLength	
117/S-W0145/S100707	501.25	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945525730		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and Asphalting of Basappa Road Nanjappa Road in Pujarappa Garden in Ward No - 117	10000000	2011
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	117-11-000033
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/42/2013-14	03/11/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0121, W0119, W0111, W0129, W0133, W0125, W0132	NA, Vinayaka Lyt 4th Crs, Veera Anjaneya Temple Rd	Bsavapura Road
SegmentNo	TotalLength	
117/C-W0121/S101949	474.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945525730		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and Asphalting of Basappa Road Nanjappa Road in Pujarappa Garden in Ward No - 117	10000000	2011
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
	0	117-11-000033
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/42/2013-14	03/11/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shaties
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0181	Vinayaka Lyt 3rd Crs	Church Cross Road
SegmentNo	TotalLength	
117/S-W0181/S102148	123.35	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945525730		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and Asphaltting of Basappa Road Nanjappa Road in Pujarappa Garden in Ward No - 117	10000000	2011
Year	Type of Work	Other Work Type
2013 - 2014	Others	SSN Drain
Tender	WorkDetails	Job No Work Code
Not a Tender	0	117-11-000033
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/42/2013-14	03/11/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0173, W0181, W0127, W0179, W0177, W0133, W0140	NA, Vinayaka Lyt 3rd Crs, Vinayaka Lyt 4th Crs	Church Road
SegmentNo	TotalLength	
117/C-W0173/S102404	142.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945525730		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and Asphalting of Basappa Road Nanjappa Road in Pujarappa Garden in Ward No - 117	10000000	2011
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	117-11-000033
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/42/2013-14	03/11/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shaties
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0251, W0237, W0233, W0227, W0249, W0253, W0217, W	Maheshwaramma Temple Behind Rd, NA, Chowdeshwari Temple Behind Rd	1st Main Road Vinayaka Nagara
SegmentNo	TotalLength	
117/C-W0251/S102721	281.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945525730		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Concreting of Roads and Improvements to Drain at Vinayakanagara in Ward No - 117	5000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	117-14-000035
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/46/2013-14	19/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shaties
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0215	NA	1st Main Road Vinayaka Nagara
SegmentNo	TotalLength	
117/S-W0215/S103218	31.13	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945525730		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Concreting of Roads and Improvements to Drain at Vinayakanagara in Ward No - 117	5000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	117-14-000035
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/46/2013-14	19/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0115	NA	Lakshmi Road
SegmentNo	TotalLength	
117/S-W0115/S103439	432.81	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945525730		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and Construction of drain at Lakshmi road 5th cross,7th cross and 8th cross in Ward NO - 117	5000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	150-14-0000
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/160/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0120	NA	Lakshmi Road
SegmentNo	TotalLength	
117/S-W0120/S103943	72.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945525730		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and Construction of drain at Lakshmi road 5th cross,7th cross and 8th cross in Ward NO - 117	5000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	150-14-0000
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/160/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0121, W0164, W0117, W0123	NA	7th A Cross Lakshmi Road
SegmentNo	TotalLength	
117/C-W0121/S104158	51.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945525730		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and Construction of drain at Lakshmi road 5th cross,7th cross and 8th cross in Ward NO - 117	5000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	150-14-0000
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/160/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shaties
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0118, W0126, W0128, W0111	NA	4th Cross Lakshmi Road
SegmentNo	TotalLength	
117/C-W0118/S104415	122.22	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945525730		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and Construction of drain at Lakshmi road 5th cross,7th cross and 8th cross in Ward NO - 117	5000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	150-14-0000
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/160/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shaties
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0253	NA	9th & 8th Cross road of Vinayaka Nagara
SegmentNo	TotalLength	
117/S-W0253/S104640	51.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing UGD pipeline and Concreting to road cut portions at Vinayakanagara main road in Ward No - 117	4000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-14-00006
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/148/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		somshakar
Date of Inspection	Remarks	
18/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0251	Maheshwaramma Temple Behind Rd	9th & 8th Cross road of Vinayaka Nagara
SegmentNo	TotalLength	
117/S-W0251/S105404	67.26	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing UGD pipeline and Concreting to road cut portions at Vinayakanagara main road in Ward No - 117	4000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-14-00006
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/148/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0249	NA	7th Cross Vinayaka Nagar
SegmentNo	TotalLength	
117/S-W0249/S105549	145.75	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing UGD pipeline and Concreting to road cut portions at Vinayakanagara main road in Ward No - 117	4000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-14-00006
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/148/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0235, W0245, W0231, W0241, W0249, W0225, W0239, W	NA, 4th Crs	7th Cross Vinayaka Nagar
SegmentNo	TotalLength	
117/C-W0235/S105959	140.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing UGD pipeline and Concreting to road cut portions at Vinayakanagara main road in Ward No - 117	4000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	150-14-00006
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/148/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shaties
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0205	NA	Shakthivelunagara
SegmentNo	TotalLength	
117/S-W0205/S103626	54.80	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing UGD pipeline and Concreting to road cut portions from Shakthivelunagara to JK Pura main road in Ward No - 117	3500000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	117-14-000007
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/147/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0199, W0193, W0248, W0191, W0195, W0203, W0189	NA, Vinayaka Lyt 2nd Crs	JK Pura Main Road
SegmentNo	TotalLength	
117/C-W0199/S104311	120.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing UGD pipeline and Concreting to road cut portions from Shakthivelunagara to JK Pura main road in Ward No - 117	3500000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	117-14-000007
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/147/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 117	WardName Shanthi Nagara
StreetID W0250, W0211, W0235, W0245, W0231, W0241, W0249, W	StreetName NA, 4th Crs	Significant LandMark 2nd Main
SegmentNo 117/C-W0250/S012549	TotalLength 223.55	

ContractorDetails		
NameofContractor S Narayana	ContractorRegNo	Expenditure 0.00
PhoneNo 9448070630	EmailId	

Work Details		
NameOfWork Construction of culverts and improvements to drain at 2nd main road Vinayakanagara nad 2nd C Vinayakanagara in Ward no.117 Shanthinagara	Sanctioned Amount 1700000	Sanctioned Year 2015
Year 2015 - 2016	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Construction of Drain, culverts, Providing and fixing covering slabs	Job No Work Code 117-15-000003
Work OrderNo EE/SN/AE/WO/28/2015-16	Work Order Date 30/12/2015	Period of Extention
Defect Liability Period From 28/02/2016	Defect Liability Period To 27/02/2017	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name murthy d
Date of Inspection 29/02/2016	Remarks
Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0248, W0203, W0205, W0250	NA	JK Pura Main Road
SegmentNo	TotalLength	
117/C-W0248/S104603	24.76	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing UGD pipeline and Concreting to road cut portions from Shakhivelunagara to JK Pura main road in Ward No - 117	3500000	2014
Year	Type of Work	Other Work Type
2013 - 2014		Sanitary Line & Patch Work
Tender	WorkDetails	Job No Work Code
Tender	0	117-14-000007
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/147/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0199, W0248, W0244	NA	JK Pura Main Road
SegmentNo	TotalLength	
117/C-W0199/S114254	138.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing UGD pipeline and Concreting to road cut portions from R.K School to JK Pura Main Road in Ward No - 117	2500000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	117-11-000008
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/146/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shaties
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0244	NA	JK Pura Cross Roads
SegmentNo	TotalLength	
117/S-W0244/S114523	45.91	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing UGD pipeline and Concreting to road cut portions from R.K School to JK Pura Main Road in Ward No - 117	2500000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	117-11-000008
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/146/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0197	Vinayaka Lyt 1st Crs	JK Pura Cross Roads
SegmentNo	TotalLength	
117/S-W0197/S114708	97.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing UGD pipeline and Concreting to road cut portions from R.K School to JK Pura Main Road in Ward No - 117	2500000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	117-11-000008
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/146/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 117	WardName Shanthi Nagara
StreetID W0232, W0199, W0201, W0203, W0207, W0213, W0209	StreetName NA	Significant LandMark 2nd main road of Vinayakanagara
SegmentNo 117/C-W0232/S062208	TotalLength 88.60	

ContractorDetails		
NameofContractor R Purushothama	ContractorRegNo	Expenditure 0.00
PhoneNo 9448090581	EmailId	

Work Details		
NameOfWork Constructions of Culvert and RCC drain at 2nd main road of Vinayakanagara from KSRTC compound to Shakthivelunagara, in Ward No - 117	Sanctioned Amount 2000000	Sanctioned Year 2013
Year 2012 - 2013	Type of Work Others	Other Work Type CC Road & SSM Drain
Tender Tender	WorkDetails 0	Job No Work Code 117-13-000002
Work OrderNo EE/SN/AE/WO/54/2012-13	Work Order Date 13/08/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	shaties
27/09/2015	Remarks
Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0232, W0236, W0207	NA, 2nd Main Rd	2nd main road of Vinayakanagara
SegmentNo	TotalLength	
117/C-W0232/S062515	25.98	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R Purushothama		0.00
PhoneNo	EmailId	
9448090581		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constructions of Culvert and RCC drain at 2nd main road of Vinayakanagara from KSRTC compound to Shakthivelunagara, in Ward No - 117	2000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	RCC Drain
Tender	WorkDetails	Job No Work Code
Tender	0	117-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/54/2012-13	13/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shaties
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0010, W0004, W0005, W0006, W0002	NA	Arab Lane
SegmentNo	TotalLength	
117/C-W0010/S062735	58.76	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R Purushothama		0.00
PhoneNo	EmailId	
9448090581		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Culvert and Concreting to road at Arab Lane A B Street in Ward No - 117	2000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	Sanitary Line & RCC Drain, CC Road
Tender	WorkDetails	Job No Work Code
Tender	0	117-13-000001
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/53/2012-13	23/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shaties
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0006	NA	Arab Lane
SegmentNo	TotalLength	
117/S-W0006/S063004	52.24	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R Purushothama		0.00
PhoneNo	EmailId	
9448090581		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Culvert and Concreting to road at Arab Lane A B Street in Ward No - 117	2000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	117-13-000001
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/53/2012-13	23/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0204	NA	E Street PK Colony
SegmentNo	TotalLength	
117/S-W0204/S063156	97.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G M Paramashiva		0.00
PhoneNo	EmailId	
9739047578		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Supplying and fixing of 12" inches dia Sanitary pipeline and Concreting to road cutting portions at 'E' Street of PK Colony in Ward No - 117	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	117-13-000008
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/41/2013-14	04/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0250	NA	1st Main C cross vinayakanagara
SegmentNo	TotalLength	
117/S-W0250/S063447	147.02	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P Lakshman		0.00
PhoneNo	EmailId	
9916335298		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Concreting to road at 1st Main 'C' cross from BSG complex to anjana store in Ward No - 117	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	117-13-000007
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/40/2013-14	31/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0247	4th Crs	7th Cross 2nd main Vinayakanagara
SegmentNo	TotalLength	
117/S-W0247/S063800	41.45	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P Lakshman		0.00
PhoneNo	EmailId	
9916335298		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Concreting to 7th cross road at Vinayakanagara 2nd main road (adjacent to sacred heart burial ground) in Ward No - 117	1000000	2011
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	117-11-000005
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/39/2013-14	31/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0245	NA	7th Cross 2nd main Vinayakanagara
SegmentNo	TotalLength	
117/S-W0245/S064021	27.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P Lakshman		0.00
PhoneNo	EmailId	
9916335298		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Concreting to 7th cross road at Vinayakanagara 2nd main road (adjacent to sacred heart burial ground) in Ward No - 117	1000000	011
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	117-11-000005
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/39/2013-14	31/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0220	NA	Bethal Layout 1st Cross
SegmentNo	TotalLength	
117/S-W0220/S064233	146.96	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Concreting to road at Bethal Layout 1st cross in Ward No - 117	2000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	117-12-000066
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/12/2012-13	12/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0003	NA	Arab A Street
SegmentNo	TotalLength	
117/S-W0003/S064547	164.24	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945525730		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and concreting to roa at Arab lane, Imamia Manzil road, Aga Abdulla street in Ward No - 117	4990000	
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	117-13-000019
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/254/2012-13	06/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0010	NA	Imamia Manzil road
SegmentNo	TotalLength	
117/S-W0010/S064824	67.28	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945525730		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and concreting to roa at Arab lane, Imamia Manzil road, Aga Abdulla street in Ward No - 117	4990000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	117-13-000019
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/254/2012-13	06/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0020, W0013	NA	Aga Abdulla street
SegmentNo	TotalLength	
117/C-W0020/S065030	68.79	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945525730		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and concreting to roa at Arab lane, Imamia Manzil road, Aga Abdulla street in Ward No - 117	4990000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	117-13-000019
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/254/2012-13	06/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shaties
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0022, W0031	NA	Serpntin Street
SegmentNo	TotalLength	
117/C-W0022/S065257	79.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945525730		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and concreting to roa at Arab lane, Imamia Manzil road, Aga Abdulla street in Ward No - 117	4990000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	117-13-000019
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/254/2012-13	06/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shaties
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0184	NA	Police quarters A Street
SegmentNo	TotalLength	
117/S-W0184/S065523	156.28	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945525730		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Concreting to roads at Arablane B Street and Police quarters A Street and fencing to compound at Muslim Burial ground in Ward No - 117	4990000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
	0	117-13-000018
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/253/2012-13	06/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0262, W0248, W0252, W0203, W0264, W0258, W0250, W	Ambedkar Nagar Slum, NA	1st Main road of Vinayakanagara
SegmentNo	TotalLength	
117/C-W0262/S065813	144.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945525730		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and concreting to roads at 1st Main road of Vinayakanagara from BGS complex to old Laddy shops in Ward No - 117	4990000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	CC Road
Tender	WorkDetails	Job No Work Code
Not a Tender	0	117-13-000017
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/252/2012-13	06/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shamashakar
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0187	NA	BMTC Bus Stop
SegmentNo	TotalLength	
117/S-W0187/S070141	177.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945525730		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and concreting to roads at 1st Main road of Vinayakanagara from BGS complex to old Laddy shops in Ward No - 117	4990000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	117-13-000017
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/252/2012-13	06/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0239	NA	6th Cross 2nd Main Vinayakanagara
SegmentNo	TotalLength	
117/S-W0239/S070337	90.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MC Ramaiah		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain & concreting to road at 6th cross and construction of culverts at 2nd main road of Vinayakanagara in Ward No - 117	1800000	2012
Year	Type of Work	Other Work Type
2011 - 2012		Sanitary Line & CC Road
Tender	WorkDetails	Job No Work Code
Tender	0	117-12-000028
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/101/2011-12	20/07/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0241, W0234, W0243	NA, Chowdeshwari Temple Behind Rd	6th Cross 2nd Main Vinayakanagara
SegmentNo	TotalLength	
117/C-W0241/S070646	29.39	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MC Ramaiah		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain & concreting to road at 6th cross and construction of culverts at 2nd main road of Vinayakanagara in Ward No - 117	1800000	2012
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	117-12-000028
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/101/2011-12	20/07/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shaties
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0209	NA	6th Cross 2nd Main Vinayakanagara
SegmentNo	TotalLength	
117/S-W0209/S070827	65.57	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MC Ramaiah		0.00
PhoneNo	EmailId	
9492804401		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain & concreting to road at 6th cross and construction of culverts at 2nd main road of Vinayakanagara in Ward No - 117	1800000	2012
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	117-12-000028
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/101/2011-12	20/07/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0230	NA	JK Pura 2nd Cross
SegmentNo	TotalLength	
117/S-W0230/S071034	149.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Concreting to road at 1st cross JK Pura (Park Parallel road/DVK Factory) in Ward No - 117	2000000	2013
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	117-13-000004
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/31/2012-13	25/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0199, W0228, W0209	NA	JK Pura 2nd Cross
SegmentNo	TotalLength	
117/C-W0199/S071343	72.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Concreting to road at 1st cross JK Pura (Park Parallel road/DVK Factory) in Ward No - 117	2000000	2013
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	117-13-000004
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/31/2012-13	25/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shaties
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0199, W0228	NA	JK Pura 2nd Cross
SegmentNo	TotalLength	
117/C-W0199/S071602	71.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Concreting to road at 1st cross JK Pura (Park Parallel road/DVK Factory) in Ward No - 117	2000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	RCC Drain
Tender	WorkDetails	Job No Work Code
Tender	0	117-13-000004
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/31/2012-13	25/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
01/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0232, W0219, W0207, W0213, W0209	NA, Chowdeshwari Temple Rd	2nd main road vinayakanagara
SegmentNo	TotalLength	
117/C-W0232/S071842	82.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of culvert and RCC drain at 2nd Main road from Shakthivelunagara, in Ward No - 117	2000000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Others	CC Road
Tender	WorkDetails	Job No Work Code
Tender	0	117-11-000003
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/32/2012-13	25/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shaties
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0232, W0236, W0207	NA, 2nd Main Rd	2nd main road vinayakanagara
SegmentNo	TotalLength	
117/C-W0232/S072100	61.75	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of culvert and RCC drain at 2nd Main road from Shakhivelunagara, in Ward No - 117	2000000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	117-11-000003
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/32/2012-13	25/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shaties
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0219, W0228, W0230	Chowdeshwari Temple Rd, NA	2nd main road vinayakanagara
SegmentNo	TotalLength	
117/C-W0219/S072240	29.35	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of culvert and RCC drain at 2nd Main road from Shakthivelunagara, in Ward No - 117	2000000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	117-11-000003
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/32/2012-13	25/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shaties
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0219, W0225, W0234	Chowdeshwari Temple Rd, NA	2nd main road vinayakanagara
SegmentNo	TotalLength	
117/C-W0219/S072439	29.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of culvert and RCC drain at 2nd Main road from Shakthivelunagara, in Ward No - 117	2000000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	117-11-000003
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/32/2012-13	25/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shaties
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0159, W0192, W0198	NA	P Street
SegmentNo	TotalLength	
117/C-W0159/S072711	15.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Narayana		0.00
PhoneNo	EmailId	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of culvert and RCC drain at 2nd Main road from Shakhivelunagara, in Ward No - 117	2000000	2011
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	117-11-000003
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/32/2012-13	25/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		shaties
Date of Inspection	Remarks	
27/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 117	WardName Shanthi Nagara
StreetID W0164, W0162, W0154, W0158, W0133, W0150, W0123, W	StreetName NA, Vinayaka Lyt 4th Crs	Significant LandMark 8th Main
SegmentNo 117/C-W0164/S102022	TotalLength 980.26	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 8792589055	EmailId	

Work Details		
NameOfWork Asphalting of roads and construction of drain at Bangiyappa Garden and Lkshmi Road its surrounding area in Ward No.117 Shanthinagar	Sanctioned Amount 4000000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Road	Other Work Type
Tender Not a Tender	WorkDetails Asphalting to roads and Construction of RCC drains.	Job No Work Code 117-14-000027
Work OrderNo EE/SN/AE/WO/158/2013-14	Work Order Date 04/03/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
04/03/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Segment End



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 117	WardName Shanthi Nagara
StreetID W0232, W0219, W0228, W0230, W0250, W0211, W0249, W	StreetName NA, Chowdeshwari Temple Rd	Significant LandMark Vinayaka nagara
SegmentNo 117/C-W0232/S033952	TotalLength 182.04	

ContractorDetails		
NameofContractor S NARAYANA	ContractorRegNo	Expenditure 0.00
PhoneNo 9448070630	EmailId	

Work Details		
NameOfWork Re-Construction of Drain at 2nd main Road Vinayakanagara and its Cross roads in Ward No.117 Shanthinagara	Sanctioned Amount 1700000	Sanctioned Year 2016
Year 2015 - 2016	Type of Work Others	Other Work Type
Tender Tender	WorkDetails Reconstruction of Drain and concreting of road	Job No Work Code 117-16-000002
Work OrderNo EE/SN/AE/WO/34/2015-16	Work Order Date 26/02/2016	Period of Extention
Defect Liability Period From 20/10/2016	Defect Liability Period To 19/10/2017	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name Vijayanand
Date of Inspection 20/10/2016	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment End



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
I0022, W0031, I0029, W0020, W0013	NA	Aga Abdulla Street
SegmentNo	TotalLength	
117/C-I0022/S105848	348.14	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B SURESH		0.00
PhoneNo	EmailId	
9448073761		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain and Asphaltting of road at Aga Abdulla Street, Curley Street, Leonard lane and Serpentine Street in Ward No.117 Shanthinagara	2200000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Others	Drain & Asphalt
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drain and Asphaltting of roads	117-16-000001
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/34/2016-17	20/08/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/10/2016	27/10/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Vijayanand
Date of Inspection	Remarks	
28/10/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0218, W0128, W0138, W0177, W0133, W0134, W0140, W	NA, 2nd Crs, Vinayaka Lyt 4th Crs, 1st Crs, 3rd Crs	Lakshmi road 8th cross
SegmentNo	TotalLength	
117/C-W0218/S111730	208.24	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S NARAYANA		0.00
PhoneNo	Emailld	
9448070630		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Re Construction of Drain and Asphalting of Road at Lakshmi Road 8th cross in Ward No.117 Shanthinagara	2400000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Others	Drain & Asphalting
Tender	WorkDetails	Job No Work Code
Tender	Re construction of Drain and Asphalting to roads	117-16-000003
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/33/2016-17	20/08/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/10/2016	27/10/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Vijayanand
Date of Inspection	Remarks	
28/10/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0023, I0265, W0044, W0033, W0037	NA, Ambedkar Nagar Slum	Bride Street
SegmentNo	TotalLength	
117/C-W0023/S102324	393.11	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945525730		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and construcion of drain at biride street, Walker lane and norris road i Ward no.117 shanthinagara	3000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Removing refixing slabs, Earthwork, Construction of Drain and asphalting to roads, Providing covering slabs.	150-14-0000
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/160/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		C Murthy
Date of Inspection	Remarks	
04/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0164, W0117, W0123, W0121, W0130, W0128, W0132	NA	Basappa Road Cross
SegmentNo	TotalLength	
117/C-W0164/S025023	95.39	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
RAMARAJU PURUSHOTHAM		0.00
PhoneNo	EmailId	
9448090581		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Concreting of bad roads and Road cut portion in Ward No.117	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
Tender	Concreting of Roads	117-15-000013
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/06/2015-16	08/04/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/12/2015	30/12/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		D Murthy
Date of Inspection	Remarks	
04/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 117	WardName Shanthi Nagara
StreetID W0200, W0180, W0155, W0172, W0204, W0186, W0190, W	StreetName Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd, NA	Significant LandMark Nanjappa Circle
SegmentNo 117/C-W0200/S023825	TotalLength 396.23	
ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9448070630	EmailId	
Work Details		
NameOfWork Improvements and Asphaltting of Langford cross and from Nanjappa circle to N Street Shantinagara Ward No.117	Sanctioned Amount 5000000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Others	Other Work Type Asphaltting and Drain Improvement
Tender Not a Tender	WorkDetails Asphaltting to Roads and Improvements of Drains	Job No Work Code 117-14-000032
Work OrderNo EE/SN/AE/WO/47/2014-15	Work Order Date 19/12/2014	Period of Extention
Defect Liability Period From 31/05/2016	Defect Liability Period To 30/05/2018	Multiple Road Involved Yes
Field Inspection Details		
Number of Trees 0	Other Information	Name D Murthy
Date of Inspection 31/05/2016	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment End



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0026, W0028, W0031, I0029, W0027, W0035, W0032, W	NA, Ambedkar Nagar Slum, Vinayaka Lyt 4th Crs, Om Shakthi Lyt 4th Crs, Om Shakthi Lyt 2nd Crs, Veera	Near Ward office, Johnson market back side
SegmentNo	TotalLength	
117/C-W0026/S010820	3800.56	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
PRATHEEK K R		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Filling of Potholes in Ward No.117, Shanthinagara	1200000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Pothole filling	
Tender	WorkDetails	Job No Work Code
Tender	Filling of Pot holes	117-15-000004
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/18/2015-16	16/06/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
14/06/2016	13/06/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Somashekar
Date of Inspection	Remarks	
14/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	117	Shanthi Nagara
StreetID	StreetName	Significant LandMark
W0076, W0062, W0064, W0063, W0074, W0065, W0067, W	NA, Om Shakthi Lyt 6th Crs, Om Shakthi Lyt 5th Crs, 13th Crs, Subhash Chandra Bose Lyt	Circuler street
SegmentNo	TotalLength	
117/C-W0076/S044144	244.95	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
HANUMANTH G NAIK		0.00
PhoneNo	EmailId	
9481455797		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Concreting of circular street in ward No 117 Shanthinagara	1500000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
Tender	Concreting of roads	117-15-000007
Work OrderNo	Work Order Date	Period of Extention
EE/SN/AE/WO/15/2016-17	30/04/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
15/06/2016	14/06/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		D Murthy
Date of Inspection	Remarks	
15/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 117	WardName Shanthi Nagara
StreetID W0171, W0167, W0210, W0105, W0111, W0177, W0133, W	StreetName NA, Vinayaka Lyt 4th Crs, 1st Crs, Om Shakthi Lyt 2nd Crs, Veera Anjaneya Temple Rd	Significant LandMark Nanjappa road
SegmentNo 117/C-W0171/S125603	TotalLength 1036.22	

ContractorDetails		
NameofContractor B SURESH	ContractorRegNo	Expenditure 0.00
PhoneNo 9448073767	EmailId	

Work Details		
NameOfWork Desilting of Drains in ward no.117 Shanthinagara	Sanctioned Amount 850000	Sanctioned Year 2015
Year 2015 - 2016	Type of Work Others	Other Work Type Desilting
Tender Tender	WorkDetails Desilting of drains, removing and refixing of slabs	Job No Work Code 117-16-000005
Work OrderNo EE/SN/AE/WO/16/2016-17	Work Order Date 03/05/2016	Period of Extention
Defect Liability Period From 28/06/2016	Defect Liability Period To 27/06/2017	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name Vijayanand
Date of Inspection 29/06/2016	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start



Segment Start

