



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0144, W0245, W0243, W0247, W0142, W0241	3rd Crs, NA, Chowdeshwari Temple Behind Rd, 4th Crs	Sailayout
SegmentNo	TotalLength	
84/C-W0144/S043053	545.90	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Tam Tam Pedda Guruvareddy		0.00
PhoneNo	EmailId	
9845129495		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvementing roads and drains main road in sai layout in ward no 84, Hagadur	2000000	2016-17
Year	Type of Work	Other Work Type
2016 - 2017	Others	Roads and Drains
Tender	WorkDetails	Job No Work Code
Tender	Improvementing roads and drains main road in sai layout in ward no 84, Hagadur	084-16-000039
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/03- 08/WO/111/2016-17	04/06/2016	1 year
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
04/06/2016	03/06/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh kumar m
Date of Inspection	Remarks	
02/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W1107, W0608	NA, 2nd Crs	Siddapura
SegmentNo	TotalLength	
84/C-W1107/S044032	84.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Tam Tam Pedda Guruvareddy		0.00
PhoneNo	EmailId	
9845129495		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvementing roads and drains siddapura 2nd main and cross roads in ward no 84, Hagadur	2000000	2016-17
Year	Type of Work	Other Work Type
2016 - 2017	Road	
Tender	WorkDetails	Job No Work Code
Tender	Improvementing roads and drains siddapura 2nd main and cross roads in ward no 84, Hagadur	084-16-000037
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/01- 28/WO/112/2016-17	04/06/2016	1 Year
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
04/06/2016	03/06/2017	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh kumar M
Date of Inspection	Remarks	
02/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0165, W0169	NA	Borewell road
SegmentNo	TotalLength	
84/C-W0165/S045541	107.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Tam Tam Pedda Guruvareddy		0.00
PhoneNo	EmailId	
9845129495		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvementing roads of borewell road. Road cross in ward no 84, Hagadur	2000000	2016-17
Year	Type of Work	Other Work Type
2016 - 2017	Others	Roads and Drians
Tender	WorkDetails	Job No Work Code
Tender	Improvementing roads of borewell road. Road cross in ward no 84, Hagadur	084-16-000038
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/01- 29/WO/109/2016-17	04/06/2016	1 year
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
04/06/2016	03/06/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh kumar M
Date of Inspection	Remarks	
02/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0175, W0084, W0173	NA	Borewell Road
SegmentNo	TotalLength	
84/C-W0175/S050016	228.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Tam Tam Pedda Guruvareddy		0.00
PhoneNo	EmailId	
9845129495		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvementing roads of borewell road. Road cross in ward no 84, Hagadur	2000000	2016-17
Year	Type of Work	Other Work Type
2016 - 2017	Others	Roads and Drains
Tender	WorkDetails	Job No Work Code
Tender	Improvementing roads of borewell road. Road cross in ward no 84, Hagadur	084-16-000038
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/01- 29/WO/109/2016-17	04/06/2016	1 Year
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
04/06/2016	03/06/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh kumar m
Date of Inspection	Remarks	
02/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 84	WardName Hagadur
StreetID W0668, W0656, W0666, W0664, W1179, W0642, W1175, W	StreetName NA, 4th Crs	Significant LandMark Govt Shcool
SegmentNo 84/C-W0668/S064234	TotalLength 225.94	

ContractorDetails		
NameofContractor Sri Tam Tam Pedda Guruvareddy	ContractorRegNo	Expenditure 0.00
PhoneNo 9845129495	EmailId	

Work Details		
NameOfWork Construction of drains behind Govt school and cross roads at Ramgondanahalli in ward no 84, Hagadur	Sanctioned Amount 1500000	Sanctioned Year 2016-17
Year 2016 - 2017	Type of Work Others	Other Work Type Drains
Tender Tender	WorkDetails Construction of drains behind Govt school and cross roads at Ramgondanahalli in ward no 84, Hagadur	Job No Work Code 084-16-000009
Work OrderNo EE/MD/E-PMT/01- 09/WO/127/2016-17	Work Order Date 09/06/2016	Period of Extention 1 Year
Defect Liability Period From 09/06/2016	Defect Liability Period To 08/06/2017	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
02/11/2016	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W1127, W0640, W0642	NA, 4th Crs	Ramagondanahalli
SegmentNo	TotalLength	
84/C-W1127/S065427	129.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Tam Tam Pedda Guruvareddy		0.00
PhoneNo	EmailId	
9845129495		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement ofdrains and providing slabs in Ramagondanahalli cross roads in ward no 84, Hagadur	2000000	2016-17
Year	Type of Work	Other Work Type
2016 - 2017	Others	Drains
Tender	WorkDetails	Job No Work Code
Tender	Improvement ofdrains and providing slabs in Ramagondanahalli cross roads in ward no 84, Hagadur	084-16-000030
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/01- 22/WO/101/2016-17	02/06/2016	1 year
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
02/06/2016	01/06/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
02/11/2016	

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0063, W0032	Om Shakthi Lyt 6th Crs, NA	vijayanagara village
SegmentNo	TotalLength	
84/C-W0063/S050500	117.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N RAMESH		0.00
PhoneNo	EmailId	
7788990099		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS OF RCC DRAIN	950000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		084-12-000034
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/88/12-13	23/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	Remarks	
25/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 84	WardName Hagadur
StreetID W0253, W0641, W0639, W0314	StreetName NA, 2nd Crs	Significant LandMark nagondanahalli
SegmentNo 84/C-W0253/S054806	TotalLength 118.62	

ContractorDetails		
NameofContractor SRI M ANJINAPPA	ContractorRegNo	Expenditure 0.00
PhoneNo 8951120986	EmailId	

Work Details		
NameOfWork COnstrucation of Rcc drain with covering slabs one sides from Ramaswamy house to siddanna layout ,from choudappa house to Govidaraj house, from Venkat	Sanctioned Amount 1500000	Sanctioned Year 2013-14
Year 2013 - 2014	Type of Work Others	Other Work Type Drains
Tender Tender	WorkDetails COnstrucation of Rcc drain with covering slabs one sides from Ramaswamy house to siddanna layout ,from choudappa house to Govidaraj house, from Venkataramanappa house to Mariyappa house in Nagondanahalli village in ward no 84	Job No Work Code 082-13-000018
Work OrderNo EE/DM/E-TND/01- 35/WO/87/2013-14	Work Order Date 18/07/2013	Period of Extention 1 YEAR
Defect Liability Period From 18/07/2013	Defect Liability Period To 17/07/2014	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
05/11/2016	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0377	V S T Opposite, 5th Crs	Thimaiah Compound
SegmentNo	TotalLength	
84/S-W0377/S050143	112.21	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvementes to Roads and drains at Hagaduru Main and Cross Roads in Ward No.84	3737000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	CC Road,Covering slabs,Asphalting
Tender	WorkDetails	Job No Work Code
Not a Tender	Improvements to Roads and Drains at hagaduru main and Cross Roads in Ward No.84	084-12-000059
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/42/2014-15	31/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/10/2014	31/10/2015	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Narayanaswamy
Date of Inspection	Remarks	
03/01/2017	verified	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0604, W0606, W0610, W1107, W0608, W1111, W0602	1st Crs, NA, 2nd Crs	Siddapura Village
SegmentNo	TotalLength	
84/C-W0604/S105101	305.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Balance and Drains at SiddapVillage(2nd stage) at ward No:84	4500000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	CC Drain and Covering slab
Tender	WorkDetails	Job No Work Code
Not a Tender	CC Drain and Covering slab	84-13-000082
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/130/2012- 2013	20/03/2013	20/04/2013 To 3
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/01/2015	28/01/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh.M
Date of Inspection	Remarks	
03/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 84	WardName Hagadur
StreetID W0283, W0285, W0253, W0379, W0273	StreetName NA	Significant LandMark Hagadur Main road
SegmentNo 84/C-W0283/S110310	TotalLength 174.81	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9480828222	EmailId	

Work Details		
NameOfWork Improvements to roads and Drain at Hagadur main and cross roads in in ward No:84	Sanctioned Amount 3737000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Others	Other Work Type CC Roads and CC Drain and Covering Slaband Asphalt
Tender Not a Tender	WorkDetails CC Roads and CC Drain and Covering Slaband Asphaltting	Job No Work Code 084-12-000059
Work OrderNo BBMP/EE/MD/WO/42/2014-15	Work Order Date 31/10/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name Santhosh.M
Date of Inspection 03/01/2017	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0397	V S T Opposite, 3rd Crs	Gandhipura
SegmentNo	TotalLength	
84/S-W0397/S110911	85.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drains and Providing slabs in Gandhipura cross roads at ward No:84	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Others	Both sides RCC Drain and Covering slab
Tender	WorkDetails	Job No Work Code
Not a Tender	Both sides RCC Drain and Covering slab	84-14-000036
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/58/2014-15	06/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
12/02/2015	11/02/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh.M
Date of Inspection	Remarks	
04/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0367, W0345	NA, S Krishnappa Lyt	Vijayanagara
SegmentNo	TotalLength	
84/C-W0367/S112428	64.45	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drains and providing slabs inVijayanagara cross roads at ward No:84	500000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	CC Drains and Covering Slab
Tender	WorkDetails	Job No Work Code
Not a Tender	CC Drains and Covering Slab	84-14-000039
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/34/2014-15	31/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
12/02/2015	11/02/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh.M
Date of Inspection	Remarks	
04/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 84	WardName Hagadur
StreetID W0436, W0913, W0909, W0915, W0917, W0911	StreetName Mani Lyt 1st Crs, NA	Significant LandMark Vinayaka Nagara
SegmentNo 84/C-W0436/S113257	TotalLength 68.19	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9480828222	EmailId	

Work Details		
NameOfWork Improvements of road and Drains in Vinayaka Nagara Burrial Ground road at ward No-84	Sanctioned Amount 500000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Others	Other Work Type CC Drain and Covering Slab
Tender Not a Tender	WorkDetails CC Drain and Covering Slab	Job No Work Code 84-14-000041
Work OrderNo BBMP/EE/MD/WO/56/2014-15	Work Order Date 02/12/2014	Period of Extention
Defect Liability Period From 12/02/2015	Defect Liability Period To 11/02/2016	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name Santhosh.M
Date of Inspection 04/01/2017	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0539	NA	Vijayanagara
SegmentNo	TotalLength	
84/S-W0539/S104646	887.94	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and Improvements to road and drain from Vijayanagar to Nagondanahalli Road (Ch-305 to 2305 M) at ward No:84	30000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	Asphalting and SSM Drain and Flagging Coure drain
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphalting,SSM Drain and Flagging Coure OF drain and Covering salb	084-13-000076
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/03/2014-15	08/08/2014	08/11/2014 to 2
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/01/2016	28/01/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
04/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0561	NA	Vijaya Nagara
SegmentNo	TotalLength	
84/S-W0561/S110354	439.68	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and Improvements to road and drain from Vijayanagarato Nagondanahalli Road (Ch-305 to 2305 M) at ward No:84	30000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphalting,SSM Drain and Flagging Coure drain and Covering salb	084-13-000076
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/03/2014-15	08/08/2014	08/11/2014 to 2
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/01/2016	05/02/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh.M
Date of Inspection	Remarks	
04/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment End



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 84	WardName Hagadur
StreetID W0559	StreetName NA	Significant LandMark Vijaya Nagara
SegmentNo 84/S-W0559/S111141	TotalLength 401.64	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9480828222	EmailId	

Work Details		
NameOfWork Asphalting and Improvements to road and drain from Vijayanagar to Nagondanahalli Road (Ch-305 to 2305 M) at ward No:84	Sanctioned Amount 30000000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Others	Other Work Type Asphalting,SSM Drain and Flagging Coure drain and
Tender Not a Tender	WorkDetails Asphalting,SSM Drain and Flagging Coure drain and Covering salb	Job No Work Code 084-13-000076
Work OrderNo BBMP/EE/MD/WO/03/2014-15	Work Order Date 08/08/2014	Period of Extention 08/11/2014 to 2
Defect Liability Period From 29/01/2016	Defect Liability Period To 28/01/2017	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
04/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0339, W0351, W0204	NA, S Krishnappa Lyt	Gandhipura
SegmentNo	TotalLength	
84/C-W0339/S113011	292.11	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri A RaviKumar		0.00
PhoneNo	EmailId	
9880023958		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of drain at Gandhipura 1st main road in ward no-84	2500000	2015-16
Year	Type of Work	Other Work Type
2015 - 2016	Others	drains
Tender	WorkDetails	Job No Work Code
Tender	Improvements of drain at Gandhipura 1st main road in ward no-84	084-16-000017
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/04-56/WO/157/2015-16	28/03/2016	1 YEAR
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/03/2016	27/03/2017	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh Kumar M
Date of Inspection	Remarks	
16/09/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 84	WardName Hagadur
StreetID W0355, W0367, W0351, W0353, W0363, W0345, W0365	StreetName NA, S Krishnappa Lyt, R H B Colony 1st Main Rd, Chikka Muniswammappa Lyt, 2nd Crs	Significant LandMark Vinayanagara
SegmentNo 84/C-W0355/S051646	TotalLength 192.22	

ContractorDetails		
NameofContractor SRI Ramaiah	ContractorRegNo	Expenditure 0.00
PhoneNo 9448593413	EmailId	

Work Details		
NameOfWork Improvements of drain at vijayanagar main road left side portion area in ward no-84	Sanctioned Amount 2000000	Sanctioned Year 2016-17
Year 2015 - 2016	Type of Work Others	Other Work Type Drians
Tender Tender	WorkDetails Improvements of drain at vijayanagar main road left side portion area in ward no-84	Job No Work Code 084-16-000015
Work OrderNo EE/MD/E-PMT/06- 07/WO/134/2016-17	Work Order Date 24/06/2016	Period of Extention 1 YEAR
Defect Liability Period From 24/06/2016	Defect Liability Period To 23/06/2017	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0355, W0367, W0351, W0353, W0363, W0345, W0365	NA, S Krishnappa Lyt, R H B Colony 1st Main Rd, Chikka Muniswammappa Lyt, 2nd Crs	Vijayanagara
SegmentNo	TotalLength	
84/C-W0355/S053000	193.20	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI Ramaiah		0.00
PhoneNo	EmailId	
9448593413		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of drain at Vijayanagar main road left side portion area in ward no-84	2000000	2016-17
Year	Type of Work	Other Work Type
2016 - 2017	Others	Drains
Tender	WorkDetails	Job No Work Code
Tender	Improvements of drain at Vijayanagar main road left side portion area in ward no-84	084-16-000015
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/06- 07/WO/134/2016-17	24/06/2016	1 YEAR
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
24/06/2016	23/06/2017	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
21/10/2016	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0689, W0687	NA	ward office
SegmentNo	TotalLength	
84/C-W0689/S095029	103.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri. P. Narayanaswamy		0.00
PhoneNo	EmailId	
9448593413		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at Hagaduru ward office right sidde road in ward no-84	2500000	2015-16
Year	Type of Work	Other Work Type
2015 - 2016	Others	Drain
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drain at Hagaduru ward office right sidde road in ward no-84	084-16-000018
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/04-57/WO/165/2015-16	28/03/2016	1 YEAR
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/03/2016	27/03/2017	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh kumar m
Date of Inspection	Remarks	
26/10/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0148, W0146, W0150	NA	Byarappa lyt
SegmentNo	TotalLength	
84/C-W0148/S030412	180.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P Narayanaswamy		0.00
PhoneNo	EmailId	
9448593413		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC Drain in Byrappa layout roads and cross roads in ward N0-84 (Hagaduru)	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	Drains
Tender	WorkDetails	Job No Work Code
Tender	Drains	084-14-000009
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/21-40/WO/19/2014-15	24/05/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
25/06/2015	24/07/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0148, W0146, W0150	NA	Byrappa lyt
SegmentNo	TotalLength	
84/C-W0148/S081849	183.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P Narayanaswamy		0.00
PhoneNo	EmailId	
9448593413		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC Drain in Byrappa layout roads and cross roads in ward N0-84 (Hagaduru)	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	Drains
Tender	WorkDetails	Job No Work Code
	Drains	084-14-000009
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/21-40/WO/19/2014-15	24/05/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
25/07/2015	24/07/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh Kumar M
Date of Inspection	Remarks	
17/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0889, W0442, W0887, W0436	NA, Own Use Rd, Mani Lyt 1st Crs	HN Somshekar house
SegmentNo	TotalLength	
84/C-W0889/S083435	143.68	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P Narayanaswamy		0.00
PhoneNo	EmailId	
9448593413		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of CC road to H N Somshekar house and next roads in Hagaduru Main road at ward No.84 (Hagaduru)	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	Roads
Tender	WorkDetails	Job No Work Code
Tender	Roads	084-14-000014
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/21-46/WO/16/2014-15	24/05/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/10/2015	29/12/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh Kumar M
Date of Inspection	Remarks	
17/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0120, W0225, W0118, W0116, W0227	NA	Shanthi Avenue behind post office
SegmentNo	TotalLength	
84/C-W0120/S085316	171.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P Narayanaswamy		0.00
PhoneNo	EmailId	
9448593413		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and road in Shanthi Avenue behind post office, Whitefield at ward No.84 (Hagaduru)	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	drain and road
Tender	WorkDetails	Job No Work Code
Tender	drain and road	084-14-000010
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/21- 41/WO/18/2014-15	24/05/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/09/2015	28/09/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh Kumar M
Date of Inspection	Remarks	
17/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 84	WardName Hagadur
StreetID W0261, W0178, W0263, W0265, W0259, W0174, W0267	StreetName NA, Ambedkar Nagar Slum, Maheshwari Nagar Ambedkar Rd	Significant LandMark Vinayaka lyt
SegmentNo 84/C-W0261/S090913	TotalLength 242.81	

ContractorDetails		
NameofContractor P Narayanaswamy	ContractorRegNo	Expenditure 0.00
PhoneNo 9448593413	EmailId	

Work Details		
NameOfWork Construction of RCC Drain in Vinayaka layout roads and cross roads in ward N0-84	Sanctioned Amount 2000000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Others	Other Work Type Roads and Drains
Tender Tender	WorkDetails Roads and Drains	Job No Work Code 084-14-000008
Work OrderNo EE/MD/E-PMT/21- 39/WO/21/2014-15	Work Order Date 24/05/2014	Period of Extention
Defect Liability Period From 25/07/2015	Defect Liability Period To 24/07/2016	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name Santhosh Kumar M
Date of Inspection 17/12/2016	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0244, W0253, W0246, W0331	NA, Lakshmi Sagar Lyt 6th Crs	Sri rama temple
SegmentNo	TotalLength	
84/C-W0244/S123523	239.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9480828222		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing and Laying Asphaltting to Sri Rama Temple to Ratha beddi road in Hagaduru ward no:84	900000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphaltting	084-13-000049
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/75/2012-13	04/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/01/2015	27/01/2016	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
17/03/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0275, W0277, W0194, W0281, W0309, W0283, W0285	NA	Vinayaka lyt
SegmentNo	TotalLength	
84/S-W0275/S091943	139.93	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Ramaiah		0.00
PhoneNo	EmailId	
9980728302		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of Drain and Road in Vinayaka Layout at Whitefield in Ward no-84	2000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Others	Roads and Drains
Tender	WorkDetails	Job No Work Code
Tender	Roads and Drains	084-16-000025
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/06- 08/WO/135/2016-17	24/06/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/01/2017	29/01/2018	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Suresh
Date of Inspection	Remarks	
18/03/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0123, W0133, W0135	NA, Vinayaka Lyt 4th Crs	Victoria Layout
SegmentNo	TotalLength	
84/C-W0123/S090504	269.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anil Kumar		0.00
PhoneNo	EmailId	
9901652865		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement of Roads & drians at victoria Layout connecting Nalluahalli Main road	2500000	2015-16
Year	Type of Work	Other Work Type
2015 - 2016	Road	
Tender	WorkDetails	Job No Work Code
Tender	Improvement of Roads & drians at victoria Layout connecting Nalluahalli Main road	084-16-000023
Work OrderNo	Work Order Date	Period of Extention
EE/MD0E-PTM/04-62/WO/131/2015-16	23/03/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh Kumar
Date of Inspection	Remarks	
15/06/2016		




ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0851, W0418, W0855, W0849, W0847	NA, 7th Crs Gramatana	Narayanappa garden
SegmentNo	TotalLength	
84/C-W0851/S093057	336.26	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anil Kumar.G		0.00
PhoneNo	EmailId	
9901652865		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement of Roads at Narayanappa garden at Whitefiled road	2500000	2015-16
Year	Type of Work	Other Work Type
2015 - 2016	Road	
Tender	WorkDetails	Job No Work Code
Tender	Improvement of Roads at Narayanappa garden at Whitefiled road	084-16-000022
Work OrderNo	Work Order Date	Period of Extention
EE/MD0E-PMT/04- 61/WO/130/2015-16	23/03/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh Kumar
Date of Inspection	Remarks	
15/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0889, W0873, W0440	NA, Renuka Lyt, Mani Lyt 3rd Crs	Dhanamandi water tank road
SegmentNo	TotalLength	
84/C-W0889/S094620	249.89	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anil Kumar G		0.00
PhoneNo	EmailId	
9901652865		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement of Roads at Dhanamandi water tank road	1500000	2015-16
Year	Type of Work	Other Work Type
2015 - 2016	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvement of Roads at Dhanamandi water tank road	084-16-000026
Work OrderNo	Work Order Date	Period of Extention
EE/MD0E-PMT/04-65/WO/136/2015-16	28/03/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh Kumar
Date of Inspection	Remarks	
15/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0304, W0663, W0661, W0673	NA	Nagondanahalli Rama Mandira road
SegmentNo	TotalLength	
84/C-W0304/S100008	205.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anil Kumar G		0.00
PhoneNo	EmailId	
9901652865		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement of Roads & draid at Nagondanahalli Rama Mandira road	2000000	2015-16
Year	Type of Work	Other Work Type
2015 - 2016	Road	
Tender	WorkDetails	Job No Work Code
Tender	Improvement of Roads & draid at Nagondanahalli Rama Mandira road	084-16-000021
Work OrderNo	Work Order Date	Period of Extention
EE/MD0E-PMT/04-60/WO/128/2015-16	23/03/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh Kumar
Date of Inspection	Remarks	
15/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 84	WardName Hagadur
StreetID W0088, W0215, W0217, W0213	StreetName NA	Significant LandMark Karumariyamma temple
SegmentNo 84/C-W0088/S062822	TotalLength 350.74	

ContractorDetails		
NameofContractor M/S KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9901652865	EmailId	

Work Details		
NameOfWork Providing and laying Asphalting from Karumariyamma temple to Whitefield Main road in Hagaduru ward no-84	Sanctioned Amount 500000	Sanctioned Year 2012-13
Year 2012 - 2013	Type of Work Road	Other Work Type
Tender Not a Tender	WorkDetails Providing and laying Asphalting from Karumariyamma temple to Whitefield Main road in Hagaduru ward no-84	Job No Work Code 084-13-000044
Work OrderNo BBMP/EE/MD/WO/70/2012-13	Work Order Date 14/03/2013	Period of Extention 1 YEARS
Defect Liability Period From 30/05/2016	Defect Liability Period To 29/05/2017	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/11/2016	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 84	WardName Hagadur
StreetID W0436, W0889, W0887, W0885, W0881, W0879, W0883	StreetName Mani Lyt 1st Crs, NA	Significant LandMark Vinayaka temple
SegmentNo 84/C-W0436/S063747	TotalLength 233.65	

ContractorDetails		
NameofContractor M/s KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9901652865	EmailId	

Work Details		
NameOfWork Providing and laying Asphalting from Hagaduru vinayaka temple to ward office in Hagaduru ward no-84	Sanctioned Amount 500000	Sanctioned Year 2012-13
Year 2012 - 2013	Type of Work Road	Other Work Type
Tender Not a Tender	WorkDetails Providing and laying Asphalting from Hagaduru vinayaka temple to ward office in Hagaduru ward no-84	Job No Work Code 084-13-000040
Work OrderNo BBMP/EE/MD/WO/66/2012-13	Work Order Date 14/03/2013	Period of Extention 1 Year
Defect Liability Period From 30/05/2016	Defect Liability Period To 29/05/2017	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/11/2016	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0843, W0841	NA	HLRC Beside
SegmentNo	TotalLength	
84/S-W0843/S064621	227.79	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9901652865		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing and laying Asphalting from Whitefield main road – HLRC Beside road towards R Narayanapura in Hagaduru ward no-84	500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing and laying Asphalting from Whitefield main road – HLRC Beside road towards R Narayanapura in Hagaduru ward no-84	084-13-000054
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/ 80/2012-13	14/03/2013	1 Year
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/05/2016	29/05/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/11/2016	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 84	WardName Hagadur
StreetID W0253, W0274	StreetName NA, 2nd Crs, Maheshwari Nagar	Significant LandMark KEB Office
SegmentNo 84/C-W0253/S065348	TotalLength 82.26	

ContractorDetails		
NameofContractor M/S KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9901652865	EmailId	

Work Details		
NameOfWork Providing and laying Asphalting from Whitefield main road KEB Office Gandhipura in Hagaduru ward no-84	Sanctioned Amount 300000	Sanctioned Year 2012-13
Year 2012 - 2013	Type of Work Road	Other Work Type
Tender Not a Tender	WorkDetails Providing and laying Asphalting from Whitefield main road KEB Office Gandhipura in Hagaduru ward no-84	Job No Work Code 084-13-000043
Work OrderNo BBMP/EE/MD/WO/ 69/2012-13	Work Order Date 14/03/2013	Period of Extention 1 Years
Defect Liability Period From 30/05/2016	Defect Liability Period To 29/05/2017	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/11/2016	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0140, W0239, W0241	3rd Crs, NA	Nagondanahalli Main roads
SegmentNo	TotalLength	
84/C-W0140/S065904	176.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9901652865		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing and laying Asphalting to Nagondanahalli Main roads in Hagaduru ward no-84	500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing and laying Asphalting to Nagondanahalli Main roads in Hagaduru ward no-84	084-13-000041
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/ 67/2012-13	14/03/2013	1 Year
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/05/2016	29/05/2017	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh Kumar M
Date of Inspection	Remarks	
24/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0867, W0428, W0424	NA	VINAYAKA NAGARA VILLAGE
SegmentNo	TotalLength	
84/C-W0867/S110713	116.90	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P NARAYANA SWAMY		0.00
PhoneNo	EmailId	
9642190806		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC drain with covering slabs from HB Nagaraj house to Manjunath x menebr house construction off ssm drain form hallu Narayanappa vina	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		084-13-000010
Work OrderNo	Work Order Date	Period of Extention
EE/MD/ETND/29-67/WO/49/2013 -14	20/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		SANTHOSH
Date of Inspection	Remarks	
28/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W1065, W0562, W1051, W1077, W1069, W1063	NA, 2nd Crs	SIDDAPURA VILLAGE
SegmentNo	TotalLength	
84/C-W1065/S112005	291.63	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M ANJINAPPA		0.00
PhoneNo	EmailId	
9642190806		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC Drian with covering s;abs form chikkamuniyappa house both sidesdrain upto siddapura village	1800000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		084-13-00008
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/29- 65/WO/29/2013-14	24/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		SANTHOSH
Date of Inspection	Remarks	
28/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0549, W0264	NA	NAGONDANAHALLI VILLAGE
SegmentNo	TotalLength	
84/C-W0549/S112839	204.36	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
D H MELKAR		0.00
PhoneNo	EmailId	
9642190806		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Ip improvements to raods & drian at yallappa & Bytappa house cross roads at Nagaondanhalli	950000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	DRAIN AND ROAD
Tender	WorkDetails	Job No Work Code
Tender		084-12-000036
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/55-73/WO/13-2012-13	18/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		SANTHOSH
Date of Inspection	Remarks	
28/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0153	NA	HAGADUR
SegmentNo	TotalLength	
84/S-W0153/S114315	57.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
VENKATARAMAIAH		0.00
PhoneNo	EmailId	
9642190806		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
improvement to road and drian at cross roads of Boreweell road to nellurahalli	1000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	ROADS AND DRAIN
Tender	WorkDetails	Job No Work Code
Tender		084-11-000024
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/07/WO99/2010-11	15/02/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		SANTHOSH
Date of Inspection	Remarks	
28/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 84	WardName Hagadur
StreetID W0843, W0841	StreetName NA	Significant LandMark WHITEFIELD TZED
SegmentNo 84/C-W0843/S115027	TotalLength 176.08	

ContractorDetails		
NameofContractor K S NAGARAJA	ContractorRegNo	Expenditure 0.00
PhoneNo 9642190806	EmailId	

Work Details		
NameOfWork Asphatting to roads and construction of drian at whitewield Tzed area	Sanctioned Amount 600000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type ASPHALTING AND DRAIN
Tender Tender	WorkDetails	Job No Work Code 084-11-000002
Work OrderNo EE/MD/E-TND/12/WO/2011-12	Work Order Date 10/05/2011	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name SANTHOSH
Date of Inspection 29/02/2016	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0397	V S T Opposite, 3rd Crs	HAGADUR
SegmentNo	TotalLength	
84/S-W0397/S115759	78.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P NARAYANASWAMY		0.00
PhoneNo	EmailId	
9642190806		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement of roads and construction of drians at gandhipura main road	1050000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	ROAD AND DRAIN
Tender	WorkDetails	Job No Work Code
Tender		084-11-000058
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/10/WO/103-2011-12	02/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		SANTHOSH
Date of Inspection	Remarks	
29/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0579	5th Crs	KAI THOTA
SegmentNo	TotalLength	
84/S-W0579/S103239	146.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRISHNAMURTHY		0.00
PhoneNo	EmailId	
9642190806		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement to Roads and construction of drain in kai thota	1000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	ROAD AND DRAIN
Tender	WorkDetails	Job No Work Code
Tender		084-11-000012
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/07/WO/96/2010-11	09/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		SANTHOSH
Date of Inspection	Remarks	
29/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W1091	NA	SIDDAPURA
SegmentNo	TotalLength	
84/S-W1091/S104000	370.15	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N RAMESH		0.00
PhoneNo	EmailId	
9642190806		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing concrete & Asphaited roads & Construction of drains at Nanjappa road & lake road in siddpura	1000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	CONCRETE,ASPHALTING AND DRAIN
Tender	WorkDetails	Job No Work Code
Tender		084-11-000022
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/12/WO/2/2011-12	10/05/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		SANTHOSH
Date of Inspection	Remarks	
29/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 84	WardName Hagadur
StreetID W0022, W0018, W0028, W0012, W0053, W0026	StreetName NA	Significant LandMark NELLURHALLI VILLAGE
SegmentNo 84/C-W0022/S104653	TotalLength 207.41	

ContractorDetails		
NameofContractor D H MELKAR	ContractorRegNo	Expenditure 0.00
PhoneNo 9642190806	EmailId	

Work Details		
NameOfWork Construction of CC Roads & Drains at Pugasettepayaya 7th cross in nellurhalli village	Sanctioned Amount 950000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Others	Other Work Type road and drain
Tender Tender	WorkDetails	Job No Work Code 084-12-000035
Work OrderNo EE/MD/E-TND/55- 72/WO/12/2012-13	Work Order Date 18/06/2012	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name SANTHOSH
Date of Inspection 29/02/2016	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0537	NA	NAGONDAHALLI
SegmentNo	TotalLength	
84/S-W0537/S105204	24.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9642190806		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement to roads and drain at Dommarahalli in Nagaondahahalli	3000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	ROADS AND DRAIN
Tender	WorkDetails	Job No Work Code
Not a Tender		084-13-000075
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/134/2012-13	20/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		SANTHOSH
Date of Inspection	Remarks	
29/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0144, W0245, W0243, W0247, W0319	3rd Crs, NA, Chowdeshwari Temple Behind Rd, 4th Crs, 11th Crs Lakshmi Sagar Lyt	SAI LAYOUT
SegmentNo	TotalLength	
84/C-W0144/S105820	405.75	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G KRISHNAPPA		0.00
PhoneNo	EmailId	
9642190806		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement to Roads and drain in sai layout	1300000	2012
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
Tender	0	084-11-000066
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/52/WO/373/2011- 12	16/03/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		SANTHOSH
Date of Inspection	Remarks	
29/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0539, W0260	NA, Ambedkar Nagar Slum	Nagondanahalli
SegmentNo	TotalLength	
84/C-W0539/S091204	113.58	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P Narayanaswamy		0.00
PhoneNo	EmailId	
9448593413		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC drain and improvement of cross road from nagarajuse to srinivas house, from Rathnamma-Narayanappa house to Byrappa-Erappa house,	1200000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Others	RCC Drain
Tender	WorkDetails	Job No Work Code
Tender	RCC Drains	084-13-000019
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/29-75/WO/50/2013-14	26/06/2013	24/09/2013 to 3
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/11/2014	28/11/2015	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh Kumar M
Date of Inspection	Remarks	
04/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0088, W0215, W0217, W0213	NA	Karumariyamma temple road
SegmentNo	TotalLength	
84/C-W0088/S092810	318.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P Narayanaswamy		0.00
PhoneNo	EmailId	
9448593413		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of drain in Karumariyamma temple road upto chowdappa house in whitefield at ward no-84	1500000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Others	Drains
Tender	WorkDetails	Job No Work Code
Tender	Drains	084-14-000012
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/21-42/WO/17/2014-15	24/05/2014	24.08.2014 to 3
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/11/2014	28/11/2015	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh Kumar M
Date of Inspection	Remarks	
04/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0411, W0413	NA	Nagondanahalli colony
SegmentNo	TotalLength	
84/C-W0411/S093947	217.56	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P Narayanaswamy		0.00
PhoneNo	EmailId	
9448593413		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of drains and culverts and CC roads at Nagondanahalli colony cross roads in ward n0-84(Hagadur)	1500000	2015-16
Year	Type of Work	Other Work Type
2015 - 2016	Others	Roads ,culverts and drains
Tender	WorkDetails	Job No Work Code
Tender	Drains ,culverts and CC roads	084-16-000008
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/02-60/WO/64/2015-16	06/02/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/07/2016	27/07/2017	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Santhosh Kumar M
Date of Inspection	Remarks	
04/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W1091, W1153	NA	Siddapura
SegmentNo	TotalLength	
84/C-W1091/S114127	178.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri M Anjinappa		0.00
PhoneNo	EmailId	
9341034296		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of drains behind bakery and thota at Siddapura in ward no-84 (Hagaduru)	1500000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Others	Drain
Tender	WorkDetails	Job No Work Code
	Drain	084-16-000010
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/02-62/WO/103/2015-16	11/02/2016	11/05/2016 to 1
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
02/09/2016	01/09/2017	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Suresh
Date of Inspection	Remarks	
07/03/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 84	WardName Hagadur
StreetID W0149, W0145, W0157, W0078	StreetName NA	Significant LandMark Borewell road
SegmentNo 84/C-W0149/S115201	TotalLength 105.61	

ContractorDetails		
NameofContractor Sri M Anjinappa	ContractorRegNo	Expenditure 0.00
PhoneNo 9341034296	EmailId	

Work Details		
NameOfWork Construction of culverts and drains at ward no-84 (Hagaduru)	Sanctioned Amount 1450000	Sanctioned Year 2016
Year 2015 - 2016	Type of Work Others	Other Work Type Drains and Culverts
Tender Tender	WorkDetails Drains and Culverts	Job No Work Code 084-16-000012
Work OrderNo EE/MD/E-PMT/02-64/WO/70/2015-16	Work Order Date	Period of Extention 06/05/2016 to 1
Defect Liability Period From 30/06/2016	Defect Liability Period To 29/06/2017	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name Suresh
Date of Inspection 18/03/2017	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W1157, W0648, W0652, W1153	NA	Veeramadhakari school road
SegmentNo	TotalLength	
84/C-W1157/S120031	67.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri M Anjinappa		0.00
PhoneNo	EmailId	
9341034296		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain Veeramadhakari school road at Ramagondanahalli in at ward No.84	2000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Others	Drains
Tender	WorkDetails	Job No Work Code
Tender	Drains	084-16-000031
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/01-23/WO/123/2015-16	09/06/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/07/2016	27/07/2017	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Suresh
Date of Inspection	Remarks	
07/03/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0686, W1219, W1231, W1195	NA	Ramgondanahalli
SegmentNo	TotalLength	
84/C-W0686/S121312	162.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri M Anjinappa		0.00
PhoneNo	EmailId	
9341034296		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of CC Road from Venkataswamy house to Muniswamy house at Ramgondanahalli in ward no-84 (Hagaduru)	800000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
Tender	CC Road	84-14-000022
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/21-52/WO/69/2014-15	14/08/2014	14/08/2014 to 3
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/10/2015	30/10/2016	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Suresh
Date of Inspection	Remarks	
07/03/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	 
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0204, W0341	NA	VINAYAKA LAYOUT
SegmentNo	TotalLength	
84/C-W0204/S034820	98.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
7798567889		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TODRAINS AND SLABS	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		084-14-000037
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/32/14-15	31/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	Remarks	
25/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0416, W0845	5th Crs, NA	BHUVANESWARI ROAD
SegmentNo	TotalLength	
84/C-W0416/S035228	38.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9988996787		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TOO DRAINS AND SLABS	500000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		084-14-000038
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/35/14-15	31/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	Remarks	
25/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0559	NA	NAGONDANAHALLI
SegmentNo	TotalLength	
84/S-W0559/S035603	338.85	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
7788998800		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS AND SLABS	500000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		084-14-000010
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/29/14-15	31/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	Remarks	
25/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0082, W0163	NA	NELLURHALLI
SegmentNo	TotalLength	
84/C-W0082/S040015	70.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
8899007889		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO ROAD AND CC DRAINS	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	ROADS & DRAINS
Tender	WorkDetails	Job No Work Code
Not a Tender		084-14-000046
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/27/15-14	31/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	Remarks	
25/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0697	NA	VALEPURA VILLAGE
SegmentNo	TotalLength	
84/S-W0697/S040351	349.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER		0.00
PhoneNo	EmailId	
9978678756		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS OF ROADS & DRAINS	12000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		084-13-000073
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/06/14-15	08/08/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	Remarks	
25/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0867, W0424	NA	VINAYAKANAGARA
SegmentNo	TotalLength	
84/C-W0867/S040724	80.79	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
VENKATARAMANIAH		0.00
PhoneNo	EmailId	
7829475634		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS O CC ROADS	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Tender		084-13-000011
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/118/13-14	13/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	Remarks	
25/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 84	WardName Hagadur
StreetID W0384, W0396, W0811	StreetName Own Use Rd, Narayanaswamy Rd 4th Crs, NA	Significant LandMark RAMGONDANAHALLI
SegmentNo 84/C-W0384/S041023	TotalLength 327.45	

ContractorDetails		
NameofContractor GNANENDRA B REDDY	ContractorRegNo	Expenditure 0.00
PhoneNo 9988778989	EmailId	

Work Details		
NameOfWork IMPROVEMENTS OF RCC DRAIN FROM LAKSHMMA HOUSE	Sanctioned Amount 1000000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails	Job No Work Code 085-14-000023
Work OrderNo EE/MD/WO/159/14-15	Work Order Date 29/11/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name Ramesh
Date of Inspection 25/10/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0706	NA	ramgondanahalli
SegmentNo	TotalLength	
84/S-W0706/S042626	118.12	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
GNANENDRA B REDDY		0.00
PhoneNo	EmailId	
9978675645		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
improvements of rcc drain	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		084-14-000021
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/158/14-15	29/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	Remarks	
25/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 84	WardName Hagadur
StreetID W0277, W0194, W0186, W0192, W0180, W0281, W0190, W	StreetName NA, Ambedkar Nagar Slum, Maheshwari Nagar Ambedkar Rd	Significant LandMark VINAYAKA LAYOUT
SegmentNo 84/C-W0277/S043102	TotalLength 444.58	

ContractorDetails		
NameofContractor K.R.I.D.L	ContractorRegNo	Expenditure 0.00
PhoneNo 9988787898	EmailId	

Work Details		
NameOfWork IMPROVGEMENTS OF ROADS AND DRAINS	Sanctioned Amount 9900000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Others	Other Work Type ROADS & DRAINS
Tender Not a Tender	WorkDetails	Job No Work Code 084-13-000081
Work OrderNo EE/MD/WO/04/14-15	Work Order Date 08/08/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name Ramesh
Date of Inspection 25/10/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0428	NA	VINAYAKA NAGARA
SegmentNo	TotalLength	
84/S-W0428/S043624	172.25	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N V S VASANTHKUMAR		0.00
PhoneNo	EmailId	
9988778899		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS OF ROADS AND DRAINS	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Others	ROADS & DRAINS
Tender	WorkDetails	Job No Work Code
Tender		084-14-000053
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/167/14-15	05/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	Remarks	
25/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0517	NA	HAGADUR
SegmentNo	TotalLength	
84/S-W0517/S044104	100.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P.M NARAYASWAMY		0.00
PhoneNo	EmailId	
9898786778		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS OF RCC DRAIN	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Tender		084-13-000023
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/152/13-14	03/09/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	Remarks	
25/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0322, W0689	R H B Colony, 2nd Crs, NA	HAGADHUR
SegmentNo	TotalLength	
84/C-W0322/S044503	88.63	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P.NARAYANA SWAMY		0.00
PhoneNo	EmailId	
9988776767		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF CC ROAD IN KAI THOTA	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Tender		084-13-000022
Work OrderNo	Work Order Date	Period of Extention
EE/MD/WO/44/13-14	25/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	Remarks	
25/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0057, W0061, W0071	NA, Om Shakthi Lyt 7th Crs	NALLURHALLI
SegmentNo	TotalLength	
84/S-W0057/S050358	194.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9978678978		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO CROOSS RTOADS AND RCC DRAINS	4000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		084-13-000072
Work OrderNo	Work Order Date	Period of Extention
EE/DD/WO/135/13-12	20/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	Remarks	
25/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0561	NA	NAGONDANAHALLI
SegmentNo	TotalLength	
84/S-W0561/S054730	439.68	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9982273645		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS ROAD AND DRAINS AT NAGONDANAHALLI VILLAGE	5000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	ROAD AND DRAIN
Tender	WorkDetails	Job No Work Code
Not a Tender		084-13-000078
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/1132/12-13	20/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	Remarks	
25/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 84	WardName Hagadur
StreetID W0668, W0670, W1183, W1197, W1179, W1199, W0674	StreetName NA	Significant LandMark RAMAGONDANAHALLI VILLAGE
SegmentNo 84/C-W0668/S055150	TotalLength 159.25	

ContractorDetails		
NameofContractor GNANENDRA B REDDY	ContractorRegNo	Expenditure 0.00
PhoneNo 7866743677	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO DRAINS AT RAMAGONDANAHALLI	Sanctioned Amount 1900000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails	Job No Work Code 084-14-000047
Work OrderNo EE/MD/E-PMT/04-07/W0/157/14- 15	Work Order Date 29/12/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name Ramesh
Date of Inspection 25/10/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	84	Hagadur
StreetID	StreetName	Significant LandMark
W0363, W0403	R H B Colony 1st Main Rd, NA	ASWATKATTE
SegmentNo	TotalLength	
84/C-W0363/S055805	221.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NARAYANASWAMY		0.00
PhoneNo	EmailId	
6786745735		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN	1500000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		084-14-000017
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TEND/29-73/WO/43/13-14	04/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	Remarks	
28/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 84	WardName Hagadur
StreetID W0355, W0367, W0351, W0353, W0363, W0345, W0365	StreetName NA, S Krishnappa Lyt, R H B Colony 1st Main Rd, Chikka Muniswammappa Lyt, 2nd Crs	Significant LandMark Mariyamma temple
SegmentNo 84/C-W0355/S112736	TotalLength 195.26	

ContractorDetails		
NameofContractor P Narayanaswamy	ContractorRegNo	Expenditure 0.00
PhoneNo 9448593413	EmailId	

Work Details		
NameOfWork Improvements of drain at Vijayanagar main road right side in ward no-84	Sanctioned Amount 1500000	Sanctioned Year 2015-16
Year 2015 - 2016	Type of Work Others	Other Work Type Drain
Tender Tender	WorkDetails Improvements of drain at Vijayanagar main road right side in ward no-84	Job No Work Code 084-16-000016
Work OrderNo EE/MD/E-PMT/04- 55/WO/166/2015-16	Work Order Date 28/03/2016	Period of Extention 1 YEAR
Defect Liability Period From 28/03/2016	Defect Liability Period To 27/03/2017	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
27/07/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 84	WardName Hagadur
StreetID W1025, W0514, W1027	StreetName NA	Significant LandMark Near Anjaneyya Temple
SegmentNo 84/C-W1025/S114535	TotalLength 138.17	

ContractorDetails		
NameofContractor P Narayanaswamy	ContractorRegNo	Expenditure 0.00
PhoneNo 9448593413	EmailId	

Work Details		
NameOfWork Improvements of drains at Immadihalli 1st main road behind Puspamma land connecting rajakaluve in ward no-84	Sanctioned Amount 2000000	Sanctioned Year 2015-16
Year 2015 - 2016	Type of Work Others	Other Work Type Road and drains
Tender Tender	WorkDetails Improvements of drains at Immadihalli 1st main road behind Puspamma land connecting rajakaluve in ward no-84	Job No Work Code 084-16-000019
Work OrderNo EE/MD/E-PMT/04-58/WO/164/2015-16	Work Order Date 28/03/2016	Period of Extention 1 YEAR
Defect Liability Period From 28/03/2016	Defect Liability Period To 27/03/2017	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
27/07/2016	

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start

