



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	83	Kadugodi
StreetID	StreetName	Significant LandMark
W0405, W0407, W0324	8th A Crs, Mani Lyt 2nd Main Rd, R H B Colcny, 3rd Crs	Ganapathi Temple
SegmentNo	TotalLength	
83/C-W0405/S042759	99.80	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S R Ravindra		0.00
PhoneNo	EmailId	
9880818290		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC Drain at Ramegowda Nagar 3 rd Main (Anganavadi Road)	500000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC Drain at Ramegowda Nagar 3 rd Main (Anganavadi Road)	083-14-000056
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/06-51WO/52/2016-17	11/05/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramakrishna Reddy
Date of Inspection	Remarks	
08/08/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 83	WardName Kadugodi
StreetID W0512, W0595, W0524, W0589, W0587	StreetName NA, 5th Crs, 7th Crs, 2nd Crs	Significant LandMark AKG Colony
SegmentNo 83/C-W0512/S125544	TotalLength 124.14	



ContractorDetails		
NameofContractor Anil Kumar G	ContractorRegNo	Expenditure 0.00
PhoneNo 9901652865	EmailId	

Work Details		
NameOfWork Construction of RCC Drain in Main Road in AKG Colony ,Channasandra at ward no-83 (Kadugudi)	Sanctioned Amount 3000000	Sanctioned Year 2016-17
Year 2016 - 2017	Type of Work Others	Other Work Type RCC Drain
Tender Tender	WorkDetails Construction of RCC Drain in Main Road in AKG Colony ,Channasandra at ward no-83 (Kadugudi)	Job No Work Code 083-14-000060
Work OrderNo EE/MD/E-PMT/06- 53/WO/46/2016-17	Work Order Date 06/05/2016	Period of Extention 1 YEAR
Defect Liability Period From 06/05/2016	Defect Liability Period To 05/05/2017	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
16/08/2016	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 83	WardName Kadugodi
StreetID W0079, W0056, W0064, W0062, W0077, W0072, W0070, W	StreetName Om Shakthi Lyt 4th Crs, NA, Vinayaka Lyt 1st Crs, Chowdeshwari Temple Rd	Significant LandMark Vijaya Lakshmi Colony
SegmentNo 83/S-W0079/S125624	TotalLength 275.39	

ContractorDetails		
NameofContractor Kumar K	ContractorRegNo	Expenditure 0.00
PhoneNo 9448063457	EmailId	

Work Details		
NameOfWork Improvmnt to road and providing & Laying covering slab to existing drain at vijayalakshmi colony	Sanctioned Amount	Sanctioned Year
Year	Type of Work Road	Other Work Type
Tender Tender	WorkDetails Improvmnt to road and providing & Laying covering slab to existing drain at vijayalakshmi colony	Job No Work Code 083-16-000019
Work OrderNo EE/MD/E-PMT/04- 44/WO/03/2015-16	Work Order Date 02/04/2016	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
01/07/2016	

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	83	Kadugodi
StreetID	StreetName	Significant LandMark
W0432, W0479, W0422, W0481, W0477, W0426, W0430, W	NA, 1st Crs, Rama Anjaneya Lyt, 1st Crs, Doddenakundi Main Rd, Gosale Rd, Nagappa Lyt, 2nd Crs	Ambedkar Nagar Gutta
SegmentNo	TotalLength	
83/C-W0432/S045658	219.09	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A. Ashok Reddy		0.00
PhoneNo	EmailId	
7204663999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing and Laying CC Road To Janni House to Hulluramappa House,4th - Chalapathi House to Krishnappa House, &1st road Angasagiri house to Krishna Hoy	2000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Others	CC Road, Laying & Covering slab, RCC Drain
Tender	WorkDetails	Job No Work Code
Tender	Providing to CC Road, Laying & Covering slab, & RCC Drain	083-16-000028
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/04- 53/WO/132/2015-16	23/03/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/07/2016	

Category	Photo
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 83	WardName Kadugodi
StreetID W0444, W0463, W0454, W0422, W0440	StreetName Mani Lyt 4th Crs, Shetty Lyt, 1st Main Rd, 14th Crs, Rama Anjaneya Lyt, 1st Crs, Mani Lyt 3rd Crs	Significant LandMark Ambedhkarnagara
SegmentNo 83/S-W0444/S033348	TotalLength 286.30	

ContractorDetails		
NameofContractor J.V.Manjunatha Reddy	ContractorRegNo	Expenditure 0.00
PhoneNo 9964121710	EmailId	

Work Details		
NameOfWork Improvements and Asphaltting to Roads and Construction of Drains at Ambedkarnagar approch roads in ward no:83	Sanctioned Amount 2961677	Sanctioned Year 2016
Year 2015 - 2016	Type of Work Asphaltting	Other Work Type
Tender Tender	WorkDetails Asphaltting to Roads and Construction of Drains	Job No Work Code 083-16-000008
Work OrderNo EE/MD/E-PMT/02- 51/WO/110/2015-16	Work Order Date 26/02/2016	Period of Extention
Defect Liability Period From 08/07/2016	Defect Liability Period To 07/07/2017	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/12/2016	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	83	Kadugodi
StreetID	StreetName	Significant LandMark
W0028, W0023, W0034	NA	Gangamma temple (Bridge road)
SegmentNo	TotalLength	
83/C-W0028/S034922	568.51	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
J.V.Manjunatha Reddy		0.00
PhoneNo	EmailId	
9964121710		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing and Asphaltting Bridge road 1st 2nd & 3 rd Main roads from Wipro road in kadugodi planation	2994310	2016
Year	Type of Work	Other Work Type
2016 - 2017	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	Asphaltting	083-14-000058
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/06- 52/WO/119/2016-17	09/06/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
05/08/2016	04/08/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramakrishna Reddy
Date of Inspection	Remarks	
29/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	83	Kadugodi
StreetID	StreetName	Significant LandMark
W0616, W0566, W0550, W0665, W0546, W0558, W0602, W	NA, 4th Main Rd, 3rd Main Rd, 2nd Crs, 3rd Crs, Whitefield Rd	Sapathagiri Layout
SegmentNo	TotalLength	
83/C-W0616/S091418	445.47	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G.V.Anantha Narayana		0.00
PhoneNo	EmailId	
9902820502		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing and Laying covering slab to existing drain at Channasandra sapatagiri lyt in ward no:83	933064	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	CC Drain & Covering slab
Tender	WorkDetails	Job No Work Code
Tender	CC Drain & Covering slab	83-16-000024
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/04- 49/WO/20/2016-17	06/04/2017	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
11/11/2016	10/11/2017	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramakrishna Reddy
Date of Inspection	Remarks	
18/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	
Segment Start	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	83	Kadugodi
StreetID	StreetName	Significant LandMark
W0134, W0124, W0136, W0128, W0138, W0130, W0109	1st Crs, NA, 2nd Crs	POST OFFICE PARK
SegmentNo	TotalLength	
83/C-W0134/S090432	101.12	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V SRINIVAS		0.00
PhoneNo	EmailId	
9063735183		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC DRAIN INFROINT OF POST OFFICE PARK SIDE AT KADUGUDI	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		083-13-000011
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/01- 18/WO/116/2013-14	13/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramakrishnareddy
Date of Inspection	Remarks	
17/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	83	Kadugodi
StreetID	StreetName	Significant LandMark
W0507, W0509, W0505, W0488, W0517, W0484, W0521, W	I T P L Main Rd, NA, 3rd Crs	DR AMBEDKAR NAGAR
SegmentNo	TotalLength	
83/C-W0507/S092739	352.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
VENKATARAMAIAH		0.00
PhoneNo	EmailId	
9063735183		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO ROAD AND DRAIN AT AMBEDKARA ANAGAR	1900000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	IMPROVEMENTS TOROADS AND DRAINS
Tender	WorkDetails	Job No Work Code
Tender		083-11-000049
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT19/WO/91/2010- 2011	29/07/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramakrishnareddy
Date of Inspection	Remarks	
17/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	83	Kadugodi
StreetID	StreetName	Significant LandMark
W0315, W0228	NA	PATALAMMA LAYOUT
SegmentNo	TotalLength	
83/C-W0315/S094146	98.22	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
D H MELKAR		0.00
PhoneNo	EmailId	
8500621061		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO ROADS IN PATALAMMA LAYOUT IN KADUGUDI	2000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
Tender		083-12-000008
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-TND/31/WO/264/2011- 12	05/12/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramakrishnareddy
Date of Inspection	Remarks	
17/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	83	Kadugodi
StreetID	StreetName	Significant LandMark
W0439, W0431, W0366, W0441, W0368	NA, S Krishnappa Lyt	PRASANTHI EXTENSION
SegmentNo	TotalLength	
83/C-W0439/S095019	174.43	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C G CHANDRAPPA		0.00
PhoneNo	EmailId	
8500621061		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO ROADS AND DRAIN AT PRASANTHI LYT IN KADUGUDI	5000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	IMPROVEMENTS TO ROADS AND DRAINS
Tender	WorkDetails	Job No Work Code
Tender		083-11-000061
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/23/WO/314/2011- 12	16/12/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramakrishnareddy
Date of Inspection	Remarks	
17/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 83	WardName Kadugodi
StreetID W0432, W0489, W0422, W0488, W0513, W0496, W0487, W	StreetName NA, Rama Anjaneya Lyt, 1st Crs, 60 Feet Main Rd	Significant LandMark Ambedkar Nagara
SegmentNo 83/C-W0432/S075454	TotalLength 142.56	

ContractorDetails		
NameofContractor A.Ashok Reddy	ContractorRegNo	Expenditure 0.00
PhoneNo 9632502699	EmailId	

Work Details		
NameOfWork Construction of RCC Drain covering and Providing CC ROad gate to Ambedkar Nagar School	Sanctioned Amount	Sanctioned Year 2015-16
Year 2015 - 2016	Type of Work Others	Other Work Type Construction of RCC drain and CC Road
Tender Tender	WorkDetails Construction of RCC Drain covering and Providing CC ROad gate to Ambedkar Nagar School	Job No Work Code 083-16-000012
Work OrderNo EE0MD/E-PMT/04- 37/WO/13302015-16	Work Order Date 23/03/2016	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramkrishna Reddy
Date of Inspection	Remarks	
22/06/2016		
Category	Photo	
Drain Condition		
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	83	Kadugodi
StreetID	StreetName	Significant LandMark
W0077	NA	Vijaya Lakshmi Colony
SegmentNo	TotalLength	
83/S-W0077/S012738	147.58	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s Ajay Enterprises		592075.00
PhoneNo	EmailId	
7788995577		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construc antion of CC drain and Improvement to roads	1995000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender		08311000003
Work OrderNo	Work Order Date	Period of Extention
EE/MDDVNE-TEND/06/10-11		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramakrishnareddy
Date of Inspection	Remarks	
17/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	83	Kadugodi
StreetID	StreetName	Significant LandMark
W0500	NA	burrial ground
SegmentNo	TotalLength	
83/S-W0500/S014509	50.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sr.Ramanaiah		0.00
PhoneNo	EmailId	
8899567866		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrction of RCC drain and Providing CC	1900000	2013
Year	Type of Work	Other Work Type
2015 - 2016	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender		083-13-000026
Work OrderNo	Work Order Date	Period of Extention
ee/md/e-pmt/9-06wo/137/14-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramakrishnareddy
Date of Inspection	Remarks	
18/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	83	Kadugodi
StreetID	StreetName	Significant LandMark
W0581, W0512, W0591, W0585, W0595, W0593, W0583, W	6th Crs, NA, 3rd Crs, 1st Crs, 5th Crs, 2nd Crs	AK GOPALAN COLONY
SegmentNo	TotalLength	
83/C-W0581/S095819	242.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
RAMAIAH		0.00
PhoneNo	EmailId	
8500621061		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DESILTING OF DRAINS AND COVERING SLABS FROM KUNTAMMA HOUSE TO BHAGYAMMA HOUSE NEAR SCHOOL AT AKG COLONY	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		083-13-000022
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/4- 20/WO/317/2013-14	23/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramakrishnareddy
Date of Inspection	Remarks	
17/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	83	Kadugodi
StreetID	StreetName	Significant LandMark
W0397, W0332, W0326, W0322, W0330, W0334, W0328	V S T Opposite, 3rd Crs, NA, 1st Crs, R H B Colcny, 2nd Crs, R H B Colcny, 5th Crs, R H B Colcny, 4t	CHANNASANDRA
SegmentNo	TotalLength	
83/C-W0397/S101010	180.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M VENKATACHALAPATHI		0.00
PhoneNo	EmailId	
8500621061		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING ASPHALTING TO ROADS NEAR PILLARAJU,VEERABHADRAP PA,JAYASANKAR HOUSES AND AVANTHI ROADS IN NEW EXTENSION CHANNASANDRA	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
Tender		083-14-000049
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/03/WO/145/2014- 15	20/11/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramakrishnareddy
Date of Inspection	Remarks	
17/02/2016		
Category	Photo	
Road Condition		
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	83	Kadugodi
StreetID	StreetName	Significant LandMark
W0553, W0549, W0579, W0565, W0555	NA, 5th Crs, Basavanna Main Rd	AKG COLONY
SegmentNo	TotalLength	
83/C-W0553/S102554	180.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRISHNAMURTHY P.A		0.00
PhoneNo	EmailId	
8500621061		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC DRAIN FROM SCHOOL TO POLYTECHNIC COMPOUND AT AKG COLONY IN KADUGUDI	1500000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		083-14-000051
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/03/WO/199/2014- 15	20/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramakrishnareddy
Date of Inspection	Remarks	
17/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 83	WardName Kadugodi
StreetID W0293, W0315, W0305, W0234, W0319, W0313, W0303, W	StreetName Maheshwari Nagar Opp Police Station Rd, NA, Church Rd, 11th Crs Lakshmi Sagar Lyt	Significant LandMark PATALAMMA LAYOUT
SegmentNo 83/C-W0293/S103659	TotalLength 477.75	

ContractorDetails		
NameofContractor MOHAMMED ANSAR	ContractorRegNo	Expenditure 0.00
PhoneNo 8500621061	EmailId	

Work Details		
NameOfWork CONSTRUCTION OF CC DRAIN TO SEK CHOULTARY MAIN ROAD AT PATALAMMA LYT	Sanctioned Amount 1000000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails	Job No Work Code 083-12-000030
Work OrderNo EE/MD/E-TND/55/WO/15/2012- 13	Work Order Date 18/06/2012	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
17/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	83	Kadugodi
StreetID	StreetName	Significant LandMark
W0280, W0286, W0288, W0290, W0306, W0379	2nd Crs, Lakshmi Sagar Lyt, 4th Crs, Maheshwari Nagar, NA, Chikkanna Lyt 5th Crs	MUNESWARA LYT
SegmentNo	TotalLength	
83/S-W0280/S104806	375.35	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C G CHANDRAPPA		0.00
PhoneNo	EmailId	
8500621061		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO ROADS AND DRAINS ASPHALTING IN MUNESWARA LYT	5000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	ROADS AND DRAINS
Tender	WorkDetails	Job No Work Code
Tender		083-11-000058
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/23/WO/383/2011- 12	20/06/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramakrishnareddy
Date of Inspection	Remarks	
18/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	83	Kadugodi
StreetID	StreetName	Significant LandMark
W0530, W0541, W0536	NA	Upkar Layout
SegmentNo	TotalLength	
83/C-W0530/S113529	55.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvmnts of roads in Upkar Layout to ECC Road at ward No:83	2068562	2015
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Improvmnts of roads in Upkar Layout to ECC Road at ward No:83	083-15-000005
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/10-51/WO/21/2015-16	04/04/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		venkatesh
Date of Inspection	Remarks	
29/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	83	Kadugodi
StreetID	StreetName	Significant LandMark
W0516, W0541	Muniswamy Shetty Lyt Rd, NA	Whitefield Main Road
SegmentNo	TotalLength	
83/C-W0516/S114231	49.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Formation of Road from Whitfield Main Roadto ECC Road via Parshathi Layouy in ward No:83	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Formation of Road from Whitfield Main Roadto ECC Road via Parshathi Layouy in ward No:83	083-14-000047
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE/MD/WO/25/2014-15	31/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		venkatesh
Date of Inspection	Remarks	
29/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	83	Kadugodi
StreetID	StreetName	Significant LandMark
W0624	4th Crs	Prithvi Layout
SegmentNo	TotalLength	
83/S-W0624/S114902	201.93	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Ramaiah		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of Road and Construction of RCC Drain in Prithvi Layouy Channsandra in ward No:83	2096433	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	Asphalting & SMM Drain and Covering slab
Tender	WorkDetails	Job No Work Code
Tender	Asphalting & SMM Drain and Covering slab	083-14-000021
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/02-14/WO/121/2014-15	26/11/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramakrishna Reddy
Date of Inspection	Remarks	
29/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet



Zone MAHADEVAPURA	WardNo 83	WardName Kadugodi
StreetID W0223, W0168, W0219, W0180, W0182, W0174, W0172, W	StreetName NA, Chowdeshwari Temple Rd	Significant LandMark Maramma Temple
SegmentNo 83/C-W0223/S024253	TotalLength 204.66	

ContractorDetails		
NameofContractor Sri Srinivas V	ContractorRegNo	Expenditure 0.00
PhoneNo 9845726229	EmailId	

Work Details		
NameOfWork Improvements to Roads and Construction of Drain at Shankrapura colony in Ward no-83(Kadugudi) Improvements to Roads and Construction of Drain at bala	Sanctioned Amount 2000000	Sanctioned Year 2016
Year 2015 - 2016	Type of Work Others	Other Work Type CC Roads and Drain
Tender Tender	WorkDetails CC Roads and Drain	Job No Work Code 083-16-000007
Work OrderNo EE/MD/E-PMT/02- 50/WO/100/2015-16	Work Order Date 15/02/2016	Period of Extention
Defect Liability Period From 28/03/2016	Defect Liability Period To 27/03/2017	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
16/12/2016	
Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	83	Kadugodi
StreetID	StreetName	Significant LandMark
W0025, W0010, W0019, W0027, W0014	NA	Adjacent to govt School
SegmentNo	TotalLength	
83/C-W0025/S040307	209.43	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A.Ashok Reddy		0.00
PhoneNo	EmailId	
7204663999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of drain and CC Roads Adjacent to Govt school at Kadugudi planatation(dinnur) in ward No:83	1744918	2016
Year	Type of Work	Other Work Type
2015 - 2016	Others	CC Roads and Solid Block Drains
Tender	WorkDetails	Job No Work Code
Tender	CC Roads and Solid Block Drains	083-16-000032
Work OrderNo	Work Order Date	Period of Extention
EE/MD/E-PMT/09- 07/WO/196/2015-16	31/12/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/01/2017	19/01/2018	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ramakrishna reddy
Date of Inspection	Remarks	
13/03/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start

