



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|-------------------|--------------------------|----------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0356 | 80 Feet Rd Geddlalahalli | RAMAIAH CIRCLE GATE |
| SegmentNo | TotalLength | |
| 18/S-W0356/S42309 | 948.00 | |

| | | |
|----------------------|-----------------|-------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| N.S. RAJU GPA HOLDER | | 0.00 |
| PhoneNo | EmailId | |

| | | |
|--|----------------------------|------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| ROAD WIDENING & ASPHALTING IMPTS TO F/P AND DRAINAGES OF EITHER SIDE OF 80FEET ROAD INFRONT OF BEL ROAD FROM NOTRH CH:980.00 TO 114.00MTRS | 4600000 | 2008 |
| Year | Type of Work | Other Work Type |
| 2010 - 2011 | Asphalting | |
| Tender | WorkDetails | Job No Work Code |
| | | 033-10-MGER-ID-007 |
| Work OrderNo | Work Order Date | Period of Extention |
| | | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Field Inspection Details | |
|--------------------------|-------------------|
| Number of Trees | Other Information |
| 5 | Name |
| Date of Inspection | Remarks |
| 17/12/2014 | |

| Category | Photo |
|---------------|-------|
| Segment Start | |
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|----------------------------|---|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0303, W0288, W0299, W0286 | NA, Maheshwari Nagar Main Rd, 4th Crs, Maheshwari Nagar | HUVANAHALLI CLINIC |
| SegmentNo | TotalLength | |
| 18/C-W0303/S030212 | 447.17 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| K.N.SRINIVASA | | 0.00 |
| PhoneNo | EmailId | |
| 9938938929 | | |

| | | |
|---|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| ASPHATTING FOR SELECTED BAD ROADS IN KGS LAYOUT | 1000000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Asphalting | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-12-000027 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/92/12-14 | 27/06/2012 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | Yes |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|------------------------------|--|
| Zone EAST | WardNo 18 | WardName Radhakrishna Temple |
| StreetID W0044, W0031, W0056, W0050 | StreetName NA | Significant LandMark LK OFFICE |
| SegmentNo 18/C-W0044/S030205 | TotalLength 259.09 | |

| | | |
|---|------------------------|----------------------------|
| ContractorDetails | | |
| NameofContractor SKANDA ENTERPRISES | ContractorRegNo | Expenditure 0.00 |
| PhoneNo 9010572545 | EmailId | |

| | | |
|---|--|--|
| Work Details | | |
| NameOfWork RECTIFICATION TO FOOTPATH IN SANJAYA NAGAR MAIN ROAD | Sanctioned Amount 200000 | Sanctioned Year 12 |
| Year 2012 - 2013 | Type of Work Footpath Layering | Other Work Type |
| Tender Tender | WorkDetails | Job No Work Code 018-12-000036 |
| Work OrderNo EE/H/AE/WO/167/2012-13 | Work Order Date 27/09/2019 | Period of Extention |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved No |

| | | |
|---|--------------------------|-----------------------|
| Field Inspection Details | | |
| Number of Trees 0 | Other Information | Name Harish |
| Date of Inspection 06/08/2015 | Remarks | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|-------|
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0111, W0033 | NA | LIC OFFICE |
| SegmentNo | TotalLength | |
| 18/C-W0111/S031342 | 27.00 | |

| ContractorDetails | | |
|-------------------------|------------------------|--------------------|
| NameofContractor | ContractorRegNo | Expenditure |
| S.UMASHANKAR | | 0.00 |
| PhoneNo | EmailId | |
| 9010574737 | | |

| Work Details | | |
|--|-----------------------------------|-------------------------------|
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| RECTIFICATION TO FOOT PATH IN NEW BEL ROAD | 200000 | 2012 |
| Year | Type of Work | Other Work Type |
| 2012 - 2013 | Footpath Layering | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-12-000037 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/127/2012-13 | 01/09/2012 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| Field Inspection Details | | |
|---------------------------|--------------------------|----------------|
| Number of Trees | Other Information | Name |
| 0 | | Harish kumar D |
| Date of Inspection | Remarks | |
| 17/06/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|----------------|-------|
| Road Condition | |
| Road Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|---|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0320, W0318, W0329, W0308, W0331, W0306, W0289, W | Chikkanna Lyt 1st Crs, Lakshmi Sagar Lyt North Side, 1st Crs, NA, Lakshmi Sagar Lyt 6th Crs, Chikk | AJANEYA TEMPE |
| SegmentNo | TotalLength | |
| 18/C-W0320/S031347 | 250.40 | |

| ContractorDetails | | |
|-------------------------|------------------------|--------------------|
| NameofContractor | ContractorRegNo | Expenditure |
| T.NATARAJ | | 0.00 |
| PhoneNo | EmailId | |
| 9901223456 | | |

| Work Details | | |
|--|---------------------------------------|-------------------------------|
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| PROVIDING CC ROAS D TO CROSS ROADS OF GEDDALAHALLI AND BANDE COLONY | 1000000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Road | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-13-000004 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/392/2012-13 | 18/03/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | Yes |

| Field Inspection Details | | |
|---------------------------|--------------------------|-------------|
| Number of Trees | Other Information | Name |
| 0 | | harish |
| Date of Inspection | Remarks | |
| 07/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|----------------|-------|
| Road Condition | |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|----------------------------------|---|
| Zone EAST | WardNo 18 | WardName Radhakrishna Temple |
| StreetID W0111, W0033, W0113 | StreetName NA, 3rd Crs | Significant LandMark LIC OFFICE |
| SegmentNo 18/C-W0111/S033126 | TotalLength 70.94 | |

| | | |
|--|------------------------|----------------------------|
| ContractorDetails | | |
| NameofContractor THE GENERAL MANAGER | ContractorRegNo | Expenditure 0.00 |
| PhoneNo 9010654565 | EmailId | |

| | | |
|---|--------------------------------------|--|
| Work Details | | |
| NameOfWork DETAILED ESTIMATE FOR THE WORK OF ROAD WIDENING ASPHALTING IMPROVING TO FOOT PATH & DRAINAGE IN WESTERAN SIDE OF 80 FEET ROAD FROM BEL ROAD TO MS RAMA | Sanctioned Amount 5000000 | Sanctioned Year 2011 |
| Year 2011 - 2012 | Type of Work Others | Other Work Type FOOT PATH & DRAINAGE ASPHALT |
| Tender Tender | WorkDetails | Job No Work Code 018-11-000042 |
| Work OrderNo EE/H/AE/WO/87/2011-12 | Work Order Date 29/06/2014 | Period of Extention |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved No |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Field Inspection Details | | |
|--------------------------|-------------------|--------|
| Number of Trees | Other Information | Name |
| 0 | | harish |
| Date of Inspection | Remarks | |
| 07/08/2015 | | |

| Category | Photo |
|----------------|-------|
| Road Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|------------------------------|---|
| Zone EAST | WardNo 18 | WardName Radhakrishna Temple |
| StreetID W0126, W0020, W0016, W0008, W0010, W0018, W0014 | StreetName NA | Significant LandMark LIC OFFICE |
| SegmentNo 18/C-W0126/S040440 | TotalLength 236.38 | |

| | | |
|---|------------------------|----------------------------|
| ContractorDetails | | |
| NameofContractor THE GENERAL MANAGER (KRIDL) | ContractorRegNo | Expenditure 0.00 |
| PhoneNo 9010576788 | EmailId | |

| | | |
|--|---------------------------------------|---|
| Work Details | | |
| NameOfWork DETAILED ESTIMATION FOR THE WORK OF ROAD WILDNING ASPHALTING IMPROVEMENT TO FOOTPATH AND DRAINAGE ON THE WESTERN SIDE OF 80 FEET ROAD | Sanctioned Amount 5000000 | Sanctioned Year 2013 |
| Year 2013 - 2014 | Type of Work Others | Other Work Type DRAIN AND FOOTPATH AND ASPHALT |
| Tender Tender | WorkDetails | Job No Work Code 018-11-000043 |
| Work OrderNo EE/H/AE/WO/88/11-12 | Work Order Date 29/06/2011 | Period of Extention |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved No |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Field Inspection Details | |
|--------------------------|-------------------|
| Number of Trees | Other Information |
| 0 | Name |
| Date of Inspection | Remarks |
| 17/06/2015 | |

| Category | Photo |
|-----------------|-------|
| Drain Condition | |
| Drain Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0125 | Veera Anjaneya Temple Rd | Behind Sterling apartment |
| SegmentNo | TotalLength | |
| 18/S-W0125/S050247 | 239.52 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| SRI. GOPI REDDY | | 0.00 |
| PhoneNo | EmailId | |
| 7760405418 | | |

| | | |
|---|--|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| Construction of drain in MLA Layout Cross Behind Sterling Apartment in Ward No.18 | 1000000 | 2014-15 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | Construction of RCC drain with rcc covering slab and kerb stone on Eastern side of the road from dead end to Veeranjanya Temple street behind sterling apartment | 018-15-000016 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/272/2014-15 | 04/02/2015 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Field Inspection Details | |
|--------------------------|-------------------|
| Number of Trees | Other Information |
| 0 | Name |
| Date of Inspection | Remarks |
| 25/01/2016 | |

| Category | Photo |
|-----------------|-------|
| Drain Condition | |
| Segment End | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0174 | NA | Jyothi Bakery |
| SegmentNo | TotalLength | |
| 18/S-W0174/S051336 | 194.20 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| SRI. GOPI REDDY | | 0.00 |
| PhoneNo | EmailId | |
| 7760405418 | | |

| | | |
|---|---|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| Construction of ssm drain in gowdara colony main road in ward no.18 | 1500000 | 2014-15 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | Construction of size stone masonry drain providing rcc covering slab and kerb stone | 018-15-000019 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/271/14-15 | 04/02/2015 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|--------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | harish kumar |
| Date of Inspection | Remarks | |
| 25/01/2016 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |
| Segment End | |
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0288 | NA | Coffee day behind |
| SegmentNo | TotalLength | |
| 18/S-W0288/S052110 | 235.76 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| SRI. GOPI REDDY | | 0.00 |
| PhoneNo | EmailId | |
| 7760405418 | | |

| | | |
|--|--|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| Construction of drain in 2nd main and 3rd main in KGE Layout in Ward No.18 | 1500000 | 2014-15 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | Constrction of rcc drain with rcc covering slab and kerb stone | 018-15-000008 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/E/WO/270/14-15 | 04/02/2015 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|--------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | harish kumar |
| Date of Inspection | Remarks | |
| 25/01/2016 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |
| Segment End | |
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0195 | NA | BBMP Park |
| SegmentNo | TotalLength | |
| 18/S-W0195/S053111 | 161.75 | |




| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| SRI. GOPI REDDY | | 0.00 |
| PhoneNo | EmailId | |
| 7760405418 | | |

| | | |
|--|---|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| Construction of drain in RMV 2nd Stage 3rd block in Ward No.18 | 1000000 | 2014-15 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | Construcion of SSM drain with rcc covering slab and kerb stone | 018-15-000006 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/269/14-15 | 04/02/2015 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | Yes |

| | | |
|---------------------------------|--------------------------|--------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | harish kumar |
| Date of Inspection | Remarks | |
| 25/01/2016 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|--|
| Drain Condition |  |
| Segment End |  |
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0261 | NA | Behind Krishna Temple |
| SegmentNo | TotalLength | |
| 18/S-W0261/S115812 | 79.39 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| G. SATISH | | 0.00 |
| PhoneNo | EmailId | |
| 9880334400 | | |

| | | |
|---|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF DRAIN IN AECS LAYOUT BEHIND KRISHNA TEMPLE IN WARD NO.18 | 1500000 | 2014-15 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 18-15-000009 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/261/2014-15 | 04/02/2015 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-----------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | HARISH KUMAR. D |
| Date of Inspection | Remarks | |
| 02/03/2016 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |
| Segment End | |
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0214 | NA | Leela Interiors |
| SegmentNo | TotalLength | |
| 18/S-W0214/S120342 | 98.58 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| V. PONNUSWAMY | | 0.00 |
| PhoneNo | EmailId | |
| 9986457680 | | |

| | | |
|--|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF DRAIN IN KRISHNAPPA LAYOUT IN WARD NO.18 | 1000000 | 2014-15 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-15-000005 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/256/2014-15 | 04/02/2015 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-----------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | HARISH KUMAR. D |
| Date of Inspection | Remarks | |
| 02/03/2016 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |
| Segment End | |
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0060 | NA | BESIDE NEW BEL ROAD |
| SegmentNo | TotalLength | |
| 18/S-W0060/S120428 | 130.40 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| M/S. KRIDL LTD | | 0.00 |
| PhoneNo | EmailId | |
| 8023330515 | | |

| | | |
|---|-----------------------------------|--------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF RETAINING WALL TO THE ROAD CONNECTING NEW BEL ROAD AND VENKATACHARI NAGAR IN MLA LAYOUT IN WARD NO.18 | 3540000 | 2014-15 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Others | CONSTRUCTION OF RETAINING WALL |
| Tender | WorkDetails | Job No Work Code |
| Not a Tender | | 018-15-000004 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/254/2014-15 | 22/01/2015 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Field Inspection Details | |
|--------------------------|-------------------|
| Number of Trees | Other Information |
| 0 | |
| Date of Inspection | Name |
| 05/03/2016 | HARISH KUMAR D |
| | Remarks |
| | |
| Category | Photo |
| Segment End | |
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0113 | 3rd Crs | K K R VAJRA APARTMENT |
| SegmentNo | TotalLength | |
| 18/S-W0113/S121243 | 175.71 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| M/S. KRIDL LTD | | 0.00 |
| PhoneNo | EmailId | |
| 8023330515 | | |

| | | |
|--|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF RCC DRAIN AND PROVIDING COVERING SLABS TO 1ST CROSS AND 1ST MAIN ROADS IN MLA LAYOUT IN WARD NO.18 | 3680000 | 2014-15 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Others | CONSTRUCTION OF RCC DRAIN |
| Tender | WorkDetails | Job No Work Code |
| Not a Tender | | 018-15-000003 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/247/2014-15 | 07/01/2015 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Field Inspection Details | | |
|--------------------------|-------------------|----------------|
| Number of Trees | Other Information | Name |
| 0 | | HARISH KUMAR D |
| Date of Inspection | Remarks | |
| 05/03/2016 | | |

| Category | Photo |
|---------------|-------|
| Segment End | |
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0060 | NA | K K R VAJRA APARTMENT |
| SegmentNo | TotalLength | |
| 18/S-W0060/S121553 | 130.40 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| M/S. KRIDL LTD | | 0.00 |
| PhoneNo | EmailId | |
| 8023330515 | | |

| | | |
|--|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF RCC DRAIN AND PROVIDING COVERING SLABS TO 1ST CROSS AND 1ST MAIN ROADS IN MLA LAYOUT IN WARD NO.18 | 3680000 | 2014-15 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Others | CONSTRUCTION OF RCC DRAIN |
| Tender | WorkDetails | Job No Work Code |
| Not a Tender | | 018-15-000003 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/247/2014-15 | 07/01/2015 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Field Inspection Details | |
|--------------------------|-------------------|
| Number of Trees | Other Information |
| 0 | Name |
| Date of Inspection | Remarks |
| 05/03/2016 | |

| Category | Photo |
|-----------------|-------|
| Drain Condition | |
| Segment End | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|------------------------------|--|
| Zone EAST | WardNo 18 | WardName Radhakrishna Temple |
| StreetID W0055 | StreetName NA | Significant LandMark BBMP DRY WASTE COLLECTION CENTRE |
| SegmentNo 18/S-W0055/S121815 | TotalLength 814.91 | |

| | | |
|---|------------------------|----------------------------|
| ContractorDetails | | |
| NameofContractor M/S. KRIDL LTD | ContractorRegNo | Expenditure 0.00 |
| PhoneNo 8023330515 | EmailId | |

| | | |
|--|---------------------------------------|--|
| Work Details | | |
| NameOfWork CONSTRUCTION OF NEW ROAD AND IMPROVEMENT TO EXISTING SURFACE FROM 1ST MAIN ROAD RMV EXTENSION TO SOLID WASTE MANAGEMENT CENTRE (3RD CROSS) IN WARD NO. | Sanctioned Amount 4100000 | Sanctioned Year 2014-15 |
| Year 2014 - 2015 | Type of Work Resurfacing | Other Work Type |
| Tender Not a Tender | WorkDetails | Job No Work Code 018-15-000001 |
| Work OrderNo EE/H/AE/WO/215/2014-15 | Work Order Date 30/10/2014 | Period of Extention |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved No |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Field Inspection Details | |
|--------------------------|-------------------|
| Number of Trees | Other Information |
| 0 | Name |
| Date of Inspection | Remarks |
| 05/03/2016 | |

| Category | Photo |
|----------------|-------|
| Road Condition | |
| Segment End | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|--------------------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0159 | NA | PARALLAL TO SIHI NEERU BHAVI ROAD |
| SegmentNo | TotalLength | |
| 18/S-W0159/S124424 | 132.24 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| B.H.HARISH | | 0.00 |
| PhoneNo | EmailId | |
| 9341260169 | | |

| | | |
|---|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF DRAIN AND CULVERTS IN DODDAPPAIAH LAYOUT IN WARD NO.18 | 1000000 | 2013-14 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000009 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/178/2013-14 | 10/02/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|----------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | HARISH KUMAR D |
| Date of Inspection | Remarks | |
| 05/03/2016 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|-------|
| Segment End | |
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0021 | 8th Crs | MANJUNATHA MEDICALS |
| SegmentNo | TotalLength | |
| 18/S-W0021/S124821 | 83.69 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| B.H. HARISH | | 0.00 |
| PhoneNo | EmailId | |
| 9341260169 | | |

| | | |
|--|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF DRAIN IN BASAVESHWARA LAYOUT IN WARD NO.18 | 1000000 | 2013-14 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000008 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/177/2013-14 | 10/02/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|----------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | HARISH KUMAR D |
| Date of Inspection | Remarks | |
| 05/03/2016 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |
| Segment End | |
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0220 | NA | NEW BEL ROAD |
| SegmentNo | TotalLength | |
| 18/S-W0220/S125248 | 423.13 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| L. GANGADHAR | | 0.00 |
| PhoneNo | EmailId | |
| 9341260169 | | |

| | | |
|--|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF DRAIN 1ST AND 2ND MAIN RMV 2ND STAGE IN WARD NO.18 | 1500000 | 2014-15 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000006 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/100/2014-15 | 10/07/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|----------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | HARISH KUMAR D |
| Date of Inspection | Remarks | |
| 05/03/2016 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |
| Segment End | |
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|---------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0258 | Ambedkar Nagar Slum | SATYAMURTHY PARK |
| SegmentNo | TotalLength | |
| 18/S-W0258/S125725 | 558.20 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| B.H. HARISH | | 0.00 |
| PhoneNo | EmailId | |
| 9341260169 | | |

| | | |
|--|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF DRAIN AND CULVERTS IN NAIDU LAYOUT IN WARD NO.18 | 1000000 | 2013-14 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000004 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/179/2013-14 | 10/02/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|----------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | HARISH KUMAR D |
| Date of Inspection | Remarks | |
| 05/03/2016 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|--------------------|-------|
| Footpath Condition | |
| Segment End | |
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|----------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0193 | Vinayaka Lyt 2nd Crs | 2ND MAIN, NEAR PARK |
| SegmentNo | TotalLength | |
| 18/S-W0193/S010215 | 135.09 | |

| ContractorDetails | | |
|-------------------------|------------------------|--------------------|
| NameofContractor | ContractorRegNo | Expenditure |
| L. GANGADHAR | | 0.00 |
| PhoneNo | EmailId | |
| 9341260169 | | |

| Work Details | | |
|--|---------------------------------------|-------------------------------|
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF DRAIN 2ND AND 3RD MAIN RMV EXTENSION IN WARD NO.18 | 1500000 | 2014-15 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000007 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/101/2014-15 | 10/07/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| Field Inspection Details | | |
|---------------------------|--------------------------|----------------|
| Number of Trees | Other Information | Name |
| 0 | | HARISH KUMAR D |
| Date of Inspection | Remarks | |
| 05/03/2016 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |
| Segment End | |
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0157 | NA | FLORANCE SCHOOL |
| SegmentNo | TotalLength | |
| 18/S-W0157/S010540 | 215.66 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| B.H. HARISH | | 0.00 |
| PhoneNo | EmailId | |
| 9341260169 | | |

| | | |
|---|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF DRAIN IN FLORANCE SCHOOL ROAD IN WARD NO.18 | 1000000 | 2013-14 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000010 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/175/2013-14 | 10/02/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|----------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | HARISH KUMAR D |
| Date of Inspection | Remarks | |
| 05/03/2016 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |
| Segment End | |
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---|----------------------------------|---|
| Zone EAST | WardNo 18 | WardName Radhakrishna Temple |
| StreetID W0111, W0035, W0056, W0115, W0033, W0113, W0109, W | StreetName NA, 3rd Crs | Significant LandMark GANAPATHI TEMPLE |
| SegmentNo 18/C-W0111/S024800 | TotalLength 638.82 | |

| | | |
|---|------------------------|----------------------------|
| ContractorDetails | | |
| NameofContractor M V SURESH KUMAR | ContractorRegNo | Expenditure 0.00 |
| PhoneNo 9342839190 | EmailId | |

| | | |
|--|---------------------------------------|---|
| Work Details | | |
| NameOfWork REGARDING OF DRAINS AND RE-CONSTRUCTION OF CULVERTS AND PROVIDING COVERING SLABS TO 1ST,2ND,3RD,4TH ANJANAMURTHY LYT | Sanctioned Amount 1500000 | Sanctioned Year 2013 |
| Year 2013 - 2014 | Type of Work Others | Other Work Type DRAINS AND CULVERTS |
| Tender Tender | WorkDetails | Job No Work Code 018-11-000038 |
| Work OrderNo EE/H/AE/WO/432/2011-12 | Work Order Date 15/12/2013 | Period of Extention |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved Yes |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Field Inspection Details | |
|--------------------------|-------------------|
| Number of Trees | Other Information |
| 0 | Name |
| Date of Inspection | Remarks |
| 06/08/2015 | |

| Category | Photo |
|---------------|-------|
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0009, W0012, W0013, W0015, W0005, W0001, W0007, W | NA | IYANGAR BAKERY |
| SegmentNo | TotalLength | |
| 18/C-W0009/S030121 | 595.02 | |

| | | |
|------------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| TECHNICAL MANAGER (KRIDL) | | 0.00 |
| PhoneNo | EmailId | |
| 9342839190 | | |

| | | |
|---|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| DETAILED ESTIMATE FOR PROVIDING ASPHALTING TO MAIN AND CROSS ROAD OF PATELAPPA LYT | 1500000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Asphalting | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-13-000019 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE//H/AE/WO/256/12-13 | 01/03/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | Yes |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | harish |
| Date of Inspection | Remarks | |
| 07/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|----------------|-------|
| Road Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|---|---|
| Zone EAST | WardNo 18 | WardName Radhakrishna Temple |
| StreetID W0172, W0168, W0099, W0101, W0103, W0105 | StreetName NA, Om Shakthi Lyt 1st Crs | Significant LandMark BHOOP SANDRA MAIN ROAD |
| SegmentNo 18/C-W0172/S030825 | TotalLength 124.66 | |

| | | |
|--|------------------------|----------------------------|
| ContractorDetails | | |
| NameofContractor K L NISCHAL | ContractorRegNo | Expenditure 0.00 |
| PhoneNo 9878898965 | EmailId | |

| | | |
|---|---------------------------------------|--|
| Work Details | | |
| NameOfWork IMPROVEMENTS TO DRAIN AND FOOTPATH AT BHOVI COLONY | Sanctioned Amount 1000000 | Sanctioned Year 2012 |
| Year 2012 - 2013 | Type of Work Others | Other Work Type DRAIN AND FOOTPATH |
| Tender Tender | WorkDetails | Job No Work Code 018-12-000024 |
| Work OrderNo EE/H/AE/WO/111/12-13 | Work Order Date 16/08/2012 | Period of Extention |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved Yes |

| | | |
|---|--------------------------|-----------------------|
| Field Inspection Details | | |
| Number of Trees 0 | Other Information | Name Harish |
| Date of Inspection 06/08/2015 | Remarks | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0115, W0054, W0109, W0121, W0046, W0048 | NA | GANAPATHI TEMPLE |
| SegmentNo | TotalLength | |
| 18/C-W0115/S031530 | 274.12 | |

| | | |
|------------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| SRI SAPPHIRE CONSTRUCTION | | 0.00 |
| PhoneNo | EmailId | |
| 7768894121 | | |

| | | |
|---|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| IMPROVEMENT TO DRAIN AND FOOTPATH OF MLA LYT | 1900000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Others | DRAIN AND FOOTPATH |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-12-000033 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/62/12-13 | 29/04/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | Yes |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|-------|
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---|-------------------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0221, W0223, W0248, W0250, W0219, W0238, W0225 | NA, Chowdeshwari Temple Rd | GARDEN CITY LODGE |
| SegmentNo | TotalLength | |
| 18/S-W0221/S032311 | 549.59 | |

| | | |
|------------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| TECHNICAL MANAGER (KRIDL) | | 0.00 |
| PhoneNo | EmailId | |
| 9849281080 | | |

| | | |
|---|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| DETAILED ESTIMATE FOR PROVIDING ASPHALTING TO MAIN AND CROSS ROAD OF JALDARSHINI LYT | 1500000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Asphalting | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-13-000026 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE//WO/263/12-13 | 01/03/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | Yes |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|-------|
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|--|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0334, W0311, W0346, W0313, W0338, W0342, W0325, W | R H B Colony, 5th Crs, NA, R H B Colony, 6th Crs, R H B Colony, 7th Crs, Lakshmi Sagar Lyt North Si | 80 FEET ROAD |
| SegmentNo | TotalLength | |
| 18/C-W0334/S033435 | 766.33 | |

| ContractorDetails | | |
|----------------------------------|------------------------|--------------------|
| NameofContractor | ContractorRegNo | Expenditure |
| THE TECHNICAL MANAGER (KRIDL) | | 0.00 |
| PhoneNo | EmailId | |
| 8794446598 | | |

| Work Details | | |
|---|---------------------------------------|-------------------------------|
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| DETAILED ESTIMATE FOR PROVIDING ASPHALTING TO MAIN AND CROSS ROAD OF RMV 2ND STAGE | 1500000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Asphalting | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-13-000022 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/259/12-13 | 01/03/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | Yes |

| Field Inspection Details | | |
|---------------------------|--------------------------|-------------|
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---|------------------------------|---|
| Zone EAST | WardNo 18 | WardName Radhakrishna Temple |
| StreetID W0129, W0048, W0052, W0054, W0127, W0060, W0036, W | StreetName NA | Significant LandMark SATYA SAI HOSPITAL |
| SegmentNo 18/C-W0129/S034514 | TotalLength 697.08 | |

| | | |
|---|------------------------|----------------------------|
| ContractorDetails | | |
| NameofContractor THE TECHNICAL MANAGER (KRIDL) | ContractorRegNo | Expenditure 0.00 |
| PhoneNo 8556743778 | EmailId | |

| | | |
|---|---------------------------------------|--|
| Work Details | | |
| NameOfWork RESTORTION OF ROAD CUT PORTION DONE BY BWSSB FOR LAYING OF 1200 MM DIA NP 3 CLASS RCC TRUNK SEWER LINE UNDER PAKAGE 3 ALONG PARLLEL ROAD OF SWD FROM | Sanctioned Amount 6760000 | Sanctioned Year 2012 |
| Year 2012 - 2013 | Type of Work Road | Other Work Type |
| Tender Tender | WorkDetails | Job No Work Code 018-12-000018 |
| Work OrderNo EE/H/AE/WO/77/12-13 | Work Order Date 20/07/2012 | Period of Extention |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved Yes |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Field Inspection Details | |
|--------------------------|-------------------|
| Number of Trees | Other Information |
| 0 | Name |
| Date of Inspection | Remarks |
| 06/08/2015 | |

| Category | Photo |
|---------------|---|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|---|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0331, W0289, W0298, W0300, W0302, W0283, W0321, W | Lakshmi Sagar Lyt 6th Crs, Chikkanna Lyt, Manjunath Floor Mill Rd, 4th Crs Lakshmi Sagar Lyt, Vidy | ANJANEYA TEMPLE |
| SegmentNo | TotalLength | |
| 18/C-W0331/S040153 | 490.87 | |

| ContractorDetails | | |
|----------------------------------|------------------------|--------------------|
| NameofContractor | ContractorRegNo | Expenditure |
| THE TECHNICAL MANAGER (KRIDL) | | 0.00 |
| PhoneNo | EmailId | |
| 8987789872 | | |

| Work Details | | |
|--|---------------------------------------|-------------------------------|
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| DETAILED ESTIMATE FOR PROVIDING ASPHALTING TO MAIN AND CROSS ROAD OF GEDDALAHALLI | 2000000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Asphalting | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-13-000021 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/258/12-13 | 01/03/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | Yes |

| Field Inspection Details | | |
|---------------------------|--------------------------|-------------|
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0307, W0309 | NA | ST JOHNS MEDICALS |
| SegmentNo | TotalLength | |
| 18/S-W0307/S040927 | 576.97 | |

| | | |
|----------------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| THE TECHNICAL MANAGER (KRIDL) | | 0.00 |
| PhoneNo | EmailId | |
| 9849281080 | | |

| | | |
|---|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| DETAILED ESTIMATE FOR PROVIDING ASPHALTING TO 1ST TO 4TH CROSS ROAD OF RMV 2ND STAGE | 1500000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Asphalting | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-13-000023 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/260/12-13 | 01/03/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | Yes |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0151 | NA | HDFC BANK |
| SegmentNo | TotalLength | |
| 18/S-W0151/S041522 | 996.42 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| THE TECHNICAL MANAGER | | 0.00 |
| PhoneNo | EmailId | |
| 7689043567 | | |

| | | |
|---|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| RESTORATION OF ROAD CUT DONE BY BWSSB FOR LAYING OF 150MM AT 1ST MAIN ROAD HIG COLONY | 1950000 | 2012 |
| Year | Type of Work | Other Work Type |
| 2012 - 2013 | Road | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-13-000001 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/172/12-13 | 18/10/2012 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | Yes |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---|---|---|
| Zone EAST | WardNo 18 | WardName Radhakrishna Temple |
| StreetID W0072, W0059, W0082, W0076, W0074, W0084 | StreetName NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd | Significant LandMark GOVT HIGH SCHOOL |
| SegmentNo 18/C-W0072/S042338 | TotalLength 599.85 | |
| ContractorDetails | | |
| NameofContractor SRI N GOPALA KRISHNA | ContractorRegNo | Expenditure 0.00 |
| PhoneNo 8645891120 | EmailId | |
| Work Details | | |
| NameOfWork RECONSTRUCTION OF CULVERTS AND IMPROVEMENT TO DRAIN IN DOLLARS COLONY | Sanctioned Amount 1520000 | Sanctioned Year 2013 |
| Year 2013 - 2014 | Type of Work Others | Other Work Type CULVERTS AND DRAIN |
| Tender Tender | WorkDetails | Job No Work Code 018-11-000060 |
| Work OrderNo EE/H/AE/WO/313/11-12 | Work Order Date 26/06/2013 | Period of Extention |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved Yes |
| Field Inspection Details | | |
| Number of Trees 0 | Other Information | Name Harish |
| Date of Inspection 06/08/2015 | Remarks | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---|--|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0301, W0299, W0286, W0305, W0290, W0288 | Bimel Behind Rd, Maheshwari Nagar Main Rd, 4th Crs, Maheshwari Nagar, Church Rd, NA | HAVUNAHALLI CLINIC |
| SegmentNo | TotalLength | |
| 18/C-W0301/S044702 | 667.06 | |

| ContractorDetails | | |
|-------------------------|------------------------|--------------------|
| NameofContractor | ContractorRegNo | Expenditure |
| THE TECHNICAL MANAGER | | 0.00 |
| PhoneNo | EmailId | |
| 9342839190 | | |

| Work Details | | |
|---|---------------------------------------|-------------------------------|
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| DETAILED ESTIMATE FOR PROVIDING ASPHALTING TO MAIN AND CROSS ROAD OF KGS LYT | 1500000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Asphalting | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-13-000025 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/262/12-13 | 01/03/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | Yes |

| Field Inspection Details | | |
|---------------------------|--------------------------|-------------|
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|-------|
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---|---|---|
| Zone EAST | WardNo 18 | WardName Radhakrishna Temple |
| StreetID W0270, W0281, W0279, W0277, W0273, W0266, W0271, W | StreetName 2nd A Crs, Maheshwari Nagar, NA, Ambedkar Nagar Slum | Significant LandMark ACES LYT |
| SegmentNo 18/C-W0270/S045506 | TotalLength 1135.88 | |

| | | |
|--|------------------------|----------------------------|
| ContractorDetails | | |
| NameofContractor THE TECHNICAL MANAGER | ContractorRegNo | Expenditure 0.00 |
| PhoneNo 9342839190 | EmailId | |

| | | |
|---|---------------------------------------|--|
| Work Details | | |
| NameOfWork DETAILED ESTIMATE FOR PROVIDING ASPHALTING TO MAIN AND CROSS ROAD OF AECS LYT | Sanctioned Amount 2000000 | Sanctioned Year 2013 |
| Year 2013 - 2014 | Type of Work Asphalting | Other Work Type |
| Tender Tender | WorkDetails | Job No Work Code 018-13-000027 |
| Work OrderNo EE/H/AE/WO/264/12-13 | Work Order Date 01/03/2013 | Period of Extention |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved Yes |

| | | |
|---|--------------------------|-----------------------|
| Field Inspection Details | | |
| Number of Trees 0 | Other Information | Name Harish |
| Date of Inspection 06/08/2015 | Remarks | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0129 | NA | GANAPATHI TEMPLE |
| SegmentNo | TotalLength | |
| 18/S-W0129/S050213 | 203.32 | |


| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| THE TECHNICAL MANAGER | | 0.00 |
| PhoneNo | EmailId | |
| 9849281080 | | |

| | | |
|---|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF SSM DRAIN FROM ANJANAMURTHY CIRCLE TO NEW BEL ROAD | 2000000 | 2014 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000028 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/104/14-15 | 10/07/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|-----------------------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0251 | Maheshwaramma Temple Behind Rd | JUDICIAL COLONY |
| SegmentNo | TotalLength | |
| 18/S-W0251/S051007 | 57.16 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| B H HARISH | | 0.00 |
| PhoneNo | EmailId | |
| 8676881234 | | |

| | | |
|---------------------------------------|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF DRAIN AND CULVERTS | 1000000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Others | DRAIN AND CULVERTS |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000004 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/179/13-14 | 10/02/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|----------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish Kumar D |
| Date of Inspection | Remarks | |
| 18/06/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|--------------------|-------|
| Drain Condition | |
| Drain Condition | |
| Footpath Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0269 | NA | JALADARSHINI LYT |
| SegmentNo | TotalLength | |
| 18/S-W0269/S051549 | 372.73 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| M MURALI MOHAM | | 0.00 |
| PhoneNo | EmailId | |
| 9845671120 | | |

| | | |
|--|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF DRAINS 8TH CROSS AECS LYT | 1000000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000011 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/146/13-14 | 30/12/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|----------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish Kumar D |
| Date of Inspection | Remarks | |
| 19/06/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|--------------------|-------|
| Drain Condition | |
| Drain Condition | |
| Footpath Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0179 | NA | 50 FEET ROAD |
| SegmentNo | TotalLength | |
| 18/S-W0179/S052552 | 224.72 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| M MURALI MOHAN | | 0.00 |
| PhoneNo | EmailId | |
| 8912009818 | | |

| | | |
|---|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF RCC DRAIN AND CULVERTS IN AECS LYT 2ND MAIN | 1000000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Others | DRAIN AND CULVERTS |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000003 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/144/13-14 | 30/12/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|----------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish Kumar D |
| Date of Inspection | Remarks | |
| 19/06/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |
| Drain Condition | |
| Drain Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0008, W0027, W0002, W0021, W0023, W0006 | NA, 8th Crs | MANJUNATHA MEDICAL STORE |
| SegmentNo | TotalLength | |
| 18/C-W0008/S053521 | 193.35 | |

| | | |
|----------------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| THE TECHNICAL MANAGER (KRIDL) | | 0.00 |
| PhoneNo | EmailId | |
| 8876100961 | | |

| | | |
|---|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF CEMENT PAVEMENTS ROADS TO CROSS ROADS IN BASAWESWARA LYT | 2000000 | 2014 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Road | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000029 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/105/14-15 | 10/07/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | Yes |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|-------|
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0053 | NA | MUNESWARA TEMPLE |
| SegmentNo | TotalLength | |
| 18/S-W0053/S054047 | 395.44 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| R RAJENDRA | | 0.00 |
| PhoneNo | EmailId | |
| 7687700981 | | |

| | | |
|--|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF DRAIN LOTTEGOLLAHALLI | 1000000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000005 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/196/2013-14 | 17/02/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|----------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish Kumar D |
| Date of Inspection | Remarks | |
| 19/06/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |
| Drain Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0185 | NA | KPTCL |
| SegmentNo | TotalLength | |
| 18/S-W0185/S054605 | 139.64 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| L GANGADHAR | | 0.00 |
| PhoneNo | EmailId | |
| 9823490098 | | |

| | | |
|---|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF RCC DRAIN AND CULVERTS IN CHIKKAMARANAHALLI LYT | 1500000 | 2014 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Others | DRAIN AND CULVERTS |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000002 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/174/14-15 | 04/08/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|----------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish Kumar D |
| Date of Inspection | Remarks | |
| 19/06/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |
| Drain Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0231 | NA | HOTEL NANDINI |
| SegmentNo | TotalLength | |
| 18/S-W0231/S104725 | 157.20 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| L GANGADHAR | | 0.00 |
| PhoneNo | EmailId | |
| 8904593061 | | |

| | | |
|--|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF RCC DRAIN AND CULVERTS IN JALADARSHINI LYT | 1500000 | 2014 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Others | DRAIN AND CULVERT |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000001 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/186/14-15 | 23/08/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|-------|
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|--------------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0220, W0193, W0191, W0185, W0189, W0187, W0195, W | NA, Vinayaka Lyt 2nd Crs | RAJMAHAL VILAS 3RD BLOCK |
| SegmentNo | TotalLength | |
| 18/C-W0220/S105718 | 499.77 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| L GANGADHAR | | 0.00 |
| PhoneNo | EmailId | |
| 8976554680 | | |

| | | |
|--|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF DRAIN IN 2ND AND 3RD RMV EXTENSION | 1500000 | 2014 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000007 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/101/14-15 | 10/07/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | Yes |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|-------|
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|--|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0116, W0118, W0120, W0098, W0112, W0122, W0102, W | NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd | GANAPATHI TEMPLE |
| SegmentNo | TotalLength | |
| 18/C-W0116/S111813 | 853.99 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| V.PONNUSWAMY | | 0.00 |
| PhoneNo | EmailId | |
| 9704436699 | | |

| | | |
|--|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| IMPROVEMENT TO DRAIN AND PROVIDING FOOT PATH OF CROSS ROAD BETWEEN 5TH TO 7TH MAIN ROAD HIG COLONY | 1900000 | 2012 |
| Year | Type of Work | Other Work Type |
| 2012 - 2013 | Others | DRAIN AND FOOTPATH |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-12-000028 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/105/2012-13 | 16/08/2012 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|-------|
| Segment Start | |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|------------------------------|---|
| Zone EAST | WardNo 18 | WardName Radhakrishna Temple |
| StreetID W0195 | StreetName NA | Significant LandMark 13TH MAIN ROAD |
| SegmentNo 18/S-W0195/S112505 | TotalLength 161.75 | |

| | | |
|---------------------------------------|------------------------|----------------------------|
| ContractorDetails | | |
| NameofContractor B H HARISH | ContractorRegNo | Expenditure 0.00 |
| PhoneNo 8890667542 | EmailId | |

| | | |
|--|--|--|
| Work Details | | |
| NameOfWork CONSTRUCTION OF DRAIN IN FLORANCE SCHOOL ROAD | Sanctioned Amount 1000000 | Sanctioned Year 2013 |
| Year 2013 - 2014 | Type of Work Drain Maintenance | Other Work Type |
| Tender Tender | WorkDetails | Job No Work Code 018-14-000010 |
| Work OrderNo EE/H/AE/WO/175/13-14 | Work Order Date 10/02/2014 | Period of Extention |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved No |

| | | |
|---|--------------------------|-----------------------|
| Field Inspection Details | | |
| Number of Trees 0 | Other Information | Name Harish |
| Date of Inspection 06/08/2015 | Remarks | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0021 | 8th Crs | MANJUNATHA MEDICAL STORE |
| SegmentNo | TotalLength | |
| 18/S-W0021/S113000 | 83.69 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| B H HARISH | | 0.00 |
| PhoneNo | EmailId | |
| 9887866780 | | |

| | | |
|---|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF DRAIN IN BASAWESWARA LYT | 1000000 | 2014 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000008 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/177/13-14 | 10/02/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0220 | NA | NEW BEL MAIN ROAD |
| SegmentNo | TotalLength | |
| 18/S-W0220/S113338 | 423.13 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| L GANGADHAR | | 0.00 |
| PhoneNo | EmailId | |
| 7668809003 | | |

| | | |
|---|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF DRAIN IN RMV 2ND STAGE | 1500000 | 2014 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000006 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/100/14-15 | 10/07/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0071 | NA | HDFC BANK |
| SegmentNo | TotalLength | |
| 18/S-W0071/S113722 | 236.82 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| B H HARISH | | 0.00 |
| PhoneNo | EmailId | |
| 9849786004 | | |

| | | |
|--|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF DRAIN AND CULVERTS IN DODDAPPIAH LYT | 1000000 | 2014 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Others | DRAIN AND CULVERTS |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000009 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/178/13-14 | 10/02/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|-------|
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|----------------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0036, W0053, W0034, W0028 | NA | MUNESWARA TEMPLE |
| SegmentNo | TotalLength | |
| 18/C-W0036/S114354 | 88.36 | |

| | | |
|-------------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| THE TECHNICAL MANAGER (KRIDL) | | 0.00 |
| PhoneNo | EmailId | |
| 8244561120 | | |

| | | |
|--|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF SSM DRAIN FROM 7TH CROSS TO SOLID WASTE MANAGEMENT CENTER IN PARELLEL ROAD | 2000000 | 2014 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000027 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/103/14-15 | 10/07/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|-------|
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|---|---|
| Zone EAST | WardNo 18 | WardName Radhakrishna Temple |
| StreetID W0066, W0057, W0070, W0072, W0059, W0147, W0076 | StreetName NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd | Significant LandMark GOVT HIGH SCHOOL |
| SegmentNo 18/C-W0066/S114525 | TotalLength 562.69 | |

| | | |
|---|------------------------|----------------------------|
| ContractorDetails | | |
| NameofContractor S.UMASHANKAR | ContractorRegNo | Expenditure 0.00 |
| PhoneNo 8904593069 | EmailId | |

| | | |
|--|--|--|
| Work Details | | |
| NameOfWork IMPROVEMENTS TO FOOT PATH OF 3RD ,4TH,5TH,& 6TH CROSS ROAD RMV 2ND STAGE | Sanctioned Amount 200000 | Sanctioned Year 2012 |
| Year 2012 - 2013 | Type of Work Footpath Layering | Other Work Type |
| Tender Tender | WorkDetails | Job No Work Code 018-12-000039 |
| Work OrderNo EE/H/AE/WO/128/2012-13 | Work Order Date 01/09/2012 | Period of Extention |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved Yes |

| | | |
|---|--------------------------|-----------------------|
| Field Inspection Details | | |
| Number of Trees 0 | Other Information | Name Harish |
| Date of Inspection 06/08/2015 | Remarks | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0053 | NA | MUNESWARA TEMPLE |
| SegmentNo | TotalLength | |
| 18/S-W0053/S115358 | 182.08 | |

| | | |
|----------------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| THE TECHNICAL MANAGER (KRIDL) | | 0.00 |
| PhoneNo | EmailId | |
| 9848657120 | | |

| | | |
|--|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF SSM DRAIN FROM 1ST MAIN TO SOLOID WASTE MANAGEMENT CENTER IN PARELLEL ROAD | 2000000 | 2014 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000026 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/102/14-15 | 10/07/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | Yes |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|------------------------------|--|
| Zone EAST | WardNo 18 | WardName Radhakrishna Temple |
| StreetID W0017, W0014 | StreetName NA | Significant LandMark YANGAR BAKERY |
| SegmentNo 18/C-W0017/S115602 | TotalLength 113.18 | |

| | | |
|---|------------------------|----------------------------|
| ContractorDetails | | |
| NameofContractor ANAND ASSOCIATES | ContractorRegNo | Expenditure 0.00 |
| PhoneNo 9735510352 | EmailId | |

| | | |
|--|--|--|
| Work Details | | |
| NameOfWork IMPROVEMENTS TO DRAIN AT CROSS ROADS OF BASAVESHWARA LAYOUT | Sanctioned Amount 1000000 | Sanctioned Year 2013 |
| Year 2013 - 2014 | Type of Work Drain Maintenance | Other Work Type |
| Tender Tender | WorkDetails | Job No Work Code 018-13-000005 |
| Work OrderNo EE/H/AE/WO/396/2012-13 | Work Order Date 19/03/2013 | Period of Extention |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved No |

| | | |
|---|--------------------------|-----------------------|
| Field Inspection Details | | |
| Number of Trees 0 | Other Information | Name Harish |
| Date of Inspection 06/08/2015 | Remarks | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0062 | NA | RAHEJA APPARTMENTS |
| SegmentNo | TotalLength | |
| 18/S-W0062/S120442 | 139.81 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| MURALI MOHAN | | 0.00 |
| PhoneNo | EmailId | |
| 8904593064 | | |

| | | |
|---|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF DRIAN IN HIG COLONY 1ST 'A' CROSS | 1000000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000012 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/145/2013-14 | 30/12/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|-------|
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0196, W0157, W0155, W0202, W0161 | NA | KRISHNAPPA LYT |
| SegmentNo | TotalLength | |
| 18/C-W0196/S120709 | 408.74 | |

| | | |
|----------------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| THE TECHNICAL MANAGER (KRIDL) | | 0.00 |
| PhoneNo | EmailId | |
| 8873332245 | | |

| | | |
|---|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| DETAILED ESTIMATION FOR PROVIDING ASPHALTING AND IMPROVEMENTS TO DRAIN AT MAIN AND CROSS ROADS AT NIT LYT | 3000000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Others | ASPHALTING AND DRAIN |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-13-000041 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/341/12-13 | 08/03/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | Yes |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0068, W0082, W0072, W0084, W0076, W0074, W0078, W | NA | B0VLEYVARD PARK |
| SegmentNo | TotalLength | |
| 18/C-W0068/S121219 | 526.60 | |

| | | |
|---------------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| THE TECHNICAL MANAGER (EAST) | | 0.00 |
| PhoneNo | EmailId | |
| 9012280122 | | |

| | | |
|---|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| DETAILED ESTIMATE FOR PROVIDING METALLING & ASPHALLING TO 3RD MAIN ROAD FROM 1ST CROSS TO 7TH CROSS | 1000000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2012 - 2013 | Asphalting | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-13-000042 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/343/2012-13 | 08/03/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|--------------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0172, W0201, W0205, W0106, W0182, W0099, W0197, W | NA, Vinayaka Lyt 1st Crs | LIC OFFICE |
| SegmentNo | TotalLength | |
| 18/C-W0172/S122127 | 307.85 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| G M SUBRAMANYAM | | 0.00 |
| PhoneNo | EmailId | |
| 8892541212 | | |

| | | |
|--|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF RCC DRAIN AND CULVERTS IN MANJUNATHA LYT | 1500000 | 2014 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Others | RCC DRAIN AND CULVERTS |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000013 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/220/14-15 | 21/11/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0211 | NA | RADHAKRISHNA TEMPLE |
| SegmentNo | TotalLength | |
| 18/S-W0211/S122240 | 288.78 | |

| | | |
|---------------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| THE TECHNICAL MANAGER (EAST) | | 0.00 |
| PhoneNo | EmailId | |
| 9012280122 | | |

| | | |
|--|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| IMPROVEMENT TO DRAIN AT 1ST CROSS OF CIL LAYOUT FROM SANJAYA NAGARA MAIN TO DOLLARS COLONY MAIN ROAD | 900000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2012 - 2013 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-13-000043 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/342/12-13 | 08/03/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|-------|
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|---|---|
| Zone EAST | WardNo 18 | WardName Radhakrishna Temple |
| StreetID W0282 | StreetName 3rd A Crs Maheshwari Nagar | Significant LandMark HOTEL NADINI |
| SegmentNo 18/S-W0282/S123040 | TotalLength 60.50 | |

| | | |
|--|------------------------|----------------------------|
| ContractorDetails | | |
| NameofContractor ABIVRUDH NIRMAN | ContractorRegNo | Expenditure 0.00 |
| PhoneNo 8904563060 | EmailId | |

| | | |
|---|---------------------------------------|--|
| Work Details | | |
| NameOfWork ASPHALT OF 6TH MAIN ROAD KGES LAYOUT FROM 8TH CROSS TO END | Sanctioned Amount 900000 | Sanctioned Year 2013 |
| Year 2013 - 2014 | Type of Work Asphalting | Other Work Type |
| Tender Tender | WorkDetails | Job No Work Code 018-12-000040 |
| Work OrderNo EE/H/AE/WO/129/2013-14 | Work Order Date 25/10/2013 | Period of Extention |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved No |

| | | |
|---|--------------------------|-----------------------|
| Field Inspection Details | | |
| Number of Trees 0 | Other Information | Name Harish |
| Date of Inspection 06/08/2015 | Remarks | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0254 | NA | naidu layout |
| SegmentNo | TotalLength | |
| 18/S-W0254/S021849 | 135.47 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| c.b vanaraju | | 0.00 |
| PhoneNo | EmailId | |
| 9618117154 | | |

| | | |
|---|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| improvements to drain and providing foot path | 800000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2012 - 2013 | Others | drain and footpath |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-12-000026 |
| Work OrderNo | Work Order Date | Period of Extention |
| ee/h/ae/wo/217/12-13 | 03/01/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| 03/01/2013 | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|-------|
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---|---|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0301, W0299, W0286, W0284, W0290, W0288 | Bimel Behind Rd, Maheshwari Nagar Main Rd, 4th Crs, Maheshwari Nagar, NA | HUVANHALLI CLINIC |
| SegmentNo | TotalLength | |
| 18/C-W0301/S022644 | 392.67 | |

| ContractorDetails | | |
|-------------------------|------------------------|--------------------|
| NameofContractor | ContractorRegNo | Expenditure |
| R.RAJENDRA | | 0.00 |
| PhoneNo | EmailId | |
| 8904596302 | | |

| Work Details | | |
|---|---------------------------------------|-------------------------------|
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| IMPROVEMENTS TO DRAIN AND PROVIDING FOOT PATH OF 1ST MAIN ROAD OF KGS LAYOUT | 1000000 | 2012 |
| Year | Type of Work | Other Work Type |
| 2012 - 2013 | Others | FOOT PATH AND DRAIN |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-12-000029 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/126/12-13 | 01/09/2012 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| Field Inspection Details | | |
|---------------------------|--------------------------|-------------|
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0225, W0238 | NA | MAYURI RESTARENT |
| SegmentNo | TotalLength | |
| 18/C-W0225/S023627 | 148.24 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| N.B NAGARAJ | | 0.00 |
| PhoneNo | EmailId | |
| 9704590365 | | |

| | | |
|---|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| IMPROVEMENTS TO DRAIN & PROVIDING FOOT PATH OF ISRO MAIN ROAD | 1900000 | 2012 |
| Year | Type of Work | Other Work Type |
| 2012 - 2013 | Others | FOOT PATH AND DRAIN |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-12-000032 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/210/2012-13 | 07/12/2012 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|----------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish Kumar D |
| Date of Inspection | Remarks | |
| 19/06/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |
| Drain Condition | |
| Drain Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Footpath Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---|---|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0201, W0225, W0203, W0219, W0197, W0238 | NA, Chowdeshwari Temple Rd, Vinayaka Lyt 1st Crs | MAYURI RESTARENT |
| SegmentNo | TotalLength | |
| 18/C-W0201/S024440 | 176.01 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| PUTTARAJU | | 0.00 |
| PhoneNo | EmailId | |
| 8904563050 | | |

| | | |
|---|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| RECTIFICATION TO FOOT PATH ON ISRO MAIN ROAD | 200000 | 2012 |
| Year | Type of Work | Other Work Type |
| 2012 - 2013 | Footpath Layering | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-12-000038 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/W0/136/2012-13 | 05/09/2012 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|----------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish Kumar D |
| Date of Inspection | Remarks | |
| 19/06/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|--------------------|-------|
| Drain Condition | |
| Drain Condition | |
| Footpath Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|----------------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0143, W0112, W0120, W0141 | NA | HIG COLONY |
| SegmentNo | TotalLength | |
| 18/C-W0143/S024602 | 366.75 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| SKANDA ENTERPRICES | | 0.00 |
| PhoneNo | EmailId | |
| 9618117151 | | |

| | | |
|---|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| IMPROVEMENTS TO DRAIN AT 15TH TO 17TH CROSS ROAD OF HIG COLONY NEAR MASJID ROAD | 600000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-13-000012 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/01/12-13 | 15/05/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | Yes |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | Harish |
| Date of Inspection | Remarks | |
| 06/08/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|--|
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|------------------------------|--|
| Zone EAST | WardNo 18 | WardName Radhakrishna Temple |
| StreetID W0175, W0208, W0173, W0212 | StreetName NA | Significant LandMark KRISHNAPPA LAYOUT |
| SegmentNo 18/C-W0175/S024951 | TotalLength 169.60 | |

| | | |
|--------------------------------------|------------------------|----------------------------|
| ContractorDetails | | |
| NameofContractor T.NATARAJ | ContractorRegNo | Expenditure 0.00 |
| PhoneNo 9848221106 | EmailId | |

| | | |
|---|---------------------------------------|---|
| Work Details | | |
| NameOfWork IMPROVEMENT DRAIN AND PROVIDING THE FOOT PATH OF KRISHNAPPA LAYOUT | Sanctioned Amount 1700000 | Sanctioned Year 2012 |
| Year 2012 - 2013 | Type of Work Others | Other Work Type DRAIN AND FOOT PATH |
| Tender | WorkDetails | Job No Work Code 018-12-000031 |
| Work OrderNo EE/H/AE/WO/129/2012-13 | Work Order Date 05/09/2017 | Period of Extention |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved No |

| | | |
|---|--------------------------|--------------------------|
| Field Inspection Details | | |
| Number of Trees 0 | Other Information | Name harish .d |
| Date of Inspection 27/07/2015 | Remarks | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|--|
| Drain Condition |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0129 | NA | ANJANAMURTHY CIRCLE |
| SegmentNo | TotalLength | |
| 18/S-W0129/S115530 | 203.32 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| M/S. KRIDL | | 0.00 |
| PhoneNo | EmailId | |
| 9341260169 | | |

| | | |
|--|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF SSM DRAIN FROM ANJANAMURTHY CIRCLE TO NEW BEL ROAD IN WARD NO.18 | 2000000 | 2014-15 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Others | NEW DRAIN CONSTRUCTION |
| Tender | WorkDetails | Job No Work Code |
| Not a Tender | | 018-14-000028 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/104/2014-15 | 10/07/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-----------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | HARISH KUMAR. D |
| Date of Inspection | Remarks | |
| 10/03/2016 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|-------|
| Segment End | |
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|------------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0051 | Om Shakthi Lyt 8th Crs | 7TH CROSS |
| SegmentNo | TotalLength | |
| 18/S-W0051/S115937 | 105.19 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| M/S. KRIDL LTD | | 0.00 |
| PhoneNo | EmailId | |
| 9341260169 | | |

| | | |
|--|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF SSM DRAIN FROM 7TH CROSS ROAD TO SOLID WASTE MANAGEMENT CENTER IN PARALLEL ROAD TO SWD IN WARD NO.18 | 2000000 | 2014-15 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Others | CONSTRUCTION OF NEW DRAIN |
| Tender | WorkDetails | Job No Work Code |
| Not a Tender | | 018-14-000027 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/103/2014-15 | 10/07/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Field Inspection Details | | |
|--------------------------|-------------------|-----------------|
| Number of Trees | Other Information | Name |
| 0 | | HARISH KUMAR. D |
| Date of Inspection | Remarks | |
| 10/03/2016 | | |

| Category | Photo |
|---------------|--|
| Segment End |  |
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0021 | 8th Crs | MANJUNATHA MEDICALS |
| SegmentNo | TotalLength | |
| 18/S-W0021/S120314 | 83.69 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| M/S. KRIDL LTD | | 0.00 |
| PhoneNo | EmailId | |
| 9341260169 | | |

| | | |
|--|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF CEMENT CONCRETE PAVEMENT ROADS TO CROSS ROADS IN BASAVESHWARA LAYOUT IN WARD NO.18 | 2000000 | 2014-15 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Others | CONSTRUCTION OF RCC PAVEMENT |
| Tender | WorkDetails | Job No Work Code |
| Not a Tender | | 018-14-000029 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/105/2014-15 | 10/07/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Field Inspection Details | | |
|--------------------------|-------------------|-----------------|
| Number of Trees | Other Information | Name |
| 0 | | HARISH KUMAR. D |
| Date of Inspection | Remarks | |
| 10/03/2016 | | |

| Category | Photo |
|---------------|-------|
| Segment End | |
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0055 | NA | ANRIYA APARTMENT |
| SegmentNo | TotalLength | |
| 18/S-W0055/S120555 | 814.91 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| M/S. KRIDL LTD | | 0.00 |
| PhoneNo | EmailId | |
| 9341260169 | | |

| | | |
|---|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF SSM DRAIN FROM 1ST MAIN ROAD TO SOLID WASTE MANAGEMENT CENTRE IN PARALLEL ROAD OF SWD IN WARD NO.18 | 2000000 | 2014-15 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Others | CONSTRUCTION OF NEW DRAIN |
| Tender | WorkDetails | Job No Work Code |
| Not a Tender | | 018-14-000026 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/102/2014-15 | 10/07/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Field Inspection Details | | |
|--------------------------|-------------------|-----------------|
| Number of Trees | Other Information | Name |
| 0 | | HARISH KUMAR. D |
| Date of Inspection | Remarks | |
| 10/03/2016 | | |

| Category | Photo |
|---------------|--|
| Segment End |  |
| Segment Start |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0237 | NA | REVA COLLEGE |
| SegmentNo | TotalLength | |
| 18/S-W0237/S010233 | 120.09 | |

| ContractorDetails | | |
|-------------------------|------------------------|--------------------|
| NameofContractor | ContractorRegNo | Expenditure |
| L. GANGADHAR | | 0.00 |
| PhoneNo | EmailId | |
| 9341260169 | | |

| Work Details | | |
|---|-----------------------------------|-------------------------------|
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF RCC DRAIN AND CULVERTS IN JALADARSHINI LAYOUT IN WARD NO.18 | 1500000 | 2014-15 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Others | CONSTRUCTION OF RCC DRAIN |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000001 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/186/2014-15 | 23/08/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| Field Inspection Details | | |
|---------------------------|--------------------------|-----------------|
| Number of Trees | Other Information | Name |
| 0 | | HARISH KUMAR. D |
| Date of Inspection | Remarks | |
| 10/03/2016 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|-------|
| Segment End | |
| Segment Start | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| EAST | 18 | Radhakrishna Temple |
| StreetID | StreetName | Significant LandMark |
| W0220 | NA | STORM WATER DRAIN |
| SegmentNo | TotalLength | |
| 18/S-W0220/S010624 | 423.13 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| L. GANGADHAR | | 0.00 |
| PhoneNo | EmailId | |
| 9341260169 | | |

| | | |
|--|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| CONSTRUCTION OF RCC DRAIN AND CULVERTS IN CHIKKAMARANAHALLI LAYOUT MAIN ROAD AND CROSS ROADS IN WARD NO.18 | 1000000 | 2013-14 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 018-14-000002 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/H/AE/WO/174/2013-14 | 04/08/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-----------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | HARISH KUMAR. D |
| Date of Inspection | Remarks | |
| 10/03/2016 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|---------------|-------|
| Segment End | |
| Segment Start | |