



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0150, W0179, W0185, W0138, W0162, W0154	NA, 2nd Crs	Near SWD
SegmentNo	TotalLength	
183/C-W0150/S043355	239.12	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.R. Ravi		0.00
PhoneNo	EmailId	
9535326585		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing B.S Covering slabs to 2nd C Cross road and cross road at 9th cross of ittamadu in ward no. 183	1655000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drain and providing B.S Covering slabs to 2nd C Cross road and cross road at 9th cross of ittamadu in ward no. 183	183-14-000009
Work OrderNo	Work Order Date	Period of Extention
EE/PN/AE/Wo No/281/13-14	18/02/2014	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/02/2014	18/02/2015	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/03/2016	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0149, W0092, W0157	NA	Maramma temple
SegmentNo	TotalLength	
183/C-W0149/S092738	80.39	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Harish. N		0.00
PhoneNo	EmailId	
9740808031		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and Providing BS Covering slabs to 7th A cross road between 7th to 8th cross of Bhuvaneshwarinagar in Ward no. 183	670000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drain and Providing BS Covering slabs to 7th A cross road between 7th to 8th cross of Bhuvaneshwarinagar in Ward no. 183	183-15-000005
Work OrderNo	Work Order Date	Period of Extention
EE/PN/AE/Wo No/127/14-15	07/01/2015	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
07/01/2015	07/01/2016	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/03/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0149, W0094, W0157	NA	Maramma temple
SegmentNo	TotalLength	
183/C-W0149/S094808	76.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Harisha. N		0.00
PhoneNo	EmailId	
9740808031		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and Providing BS Covering slabs to 7th B cross road between 7th to 8th cross of Bhuvaneshwarinagar in Ward No. 183	875000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	drain and culvert
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drain and Providing BS Covering slabs to 7th B cross road between 7th to 8th cross of Bhuvaneshwarinagar in Ward No. 183	183-15-000006
Work OrderNo	Work Order Date	Period of Extention
EE/PN/AE/Wo No/126/14-15	07/01/2015	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
07/01/2015	07/01/2016	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/03/2016	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0050, W0048, W0043, W0049	8th Main Rd, 7th Main Rd, 7th Crs Bhuvaneshwarinagar, 5th Crs Dr Vishnuvardhana Rd	Kumarswamy loyut
SegmentNo	TotalLength	
183/S-W0050/S69856	138.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.D Anand Naidu,		885160.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Flagging course and Covering Slab to Road side drains to 1st and 7th main Road Rangappa layout.	970000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Providing Flagging course and Covering Slab to Road side drains to 1st and 7th main Road Rangappa layout.	183-11-000029
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/160/11-12		60 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Linge Gowda
Date of Inspection	Remarks	
31/10/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0037, W0008	NA, 1st Main Rd	Kumarswamy layout
SegmentNo	TotalLength	
183/S-W0037/S69857	69.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.D Anand Naidu		885160.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Flagging course and Covering Slab to Road side drains to 1st and 7th main Road Rangappa layout.	970000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Providing Flagging course and Covering Slab to Road side drains to 1st and 7th main Road Rangappa layout.	181-11-000029
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/160/11-12	13/10/2011	60 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
13/10/2011	13/10/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
2		lingegowda
Date of Inspection	Remarks	
11/02/2015	complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 183	WardName Chikkalsandra
StreetID W0010, W0043, W0041	StreetName 2nd Main Rd, 7th Crs Bhuvaneshwarinagar, NA	Significant LandMark Kumarswamy loyut
SegmentNo 183/S-W0010/S69858	TotalLength 99.00	

ContractorDetails		
NameofContractor Sri .Harshitha Construction,	ContractorRegNo	Expenditure 918976.00
PhoneNo	EmailId	

Work Details		
NameOfWork Providing Flagging course and Covering Slab to Road side drains to 2nd main and 7th A cross road of Rangappa layout bhuvaneshwari nagar	Sanctioned Amount 990000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Providing Flagging course and Covering Slab to Road side drains to 2nd main and 7th A cross road of Rangappa layout bhuvaneshwari nagar	Job No Work Code 183-11-000030
Work OrderNo EE/PN/JE/WO NO/232/11-12	Work Order Date 23/12/2011	Period of Extention 90 days
Defect Liability Period From 23/12/2011	Defect Liability Period To 23/12/2012	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		Linge Gowda
Date of Inspection	Remarks	
31/10/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 183	WardName Chikkalsandra
StreetID W0022, W0010, W0041, W0020	StreetName 4th Main Rd Bhuvaneshwari Nagar, 2nd Main Rd, NA, 3rd Main Rd	Significant LandMark Kumarswamy loyut
SegmentNo 183/S-W0022/S69861	TotalLength 77.00	

ContractorDetails		
NameofContractor Sri .Harshitha Construction	ContractorRegNo	Expenditure 918976.00
PhoneNo	Emailld	

Work Details		
NameOfWork Providing Flagging course and Covering Slab to Road side drains to 2nd main and 7th A cross road of Rangappa layout bhuvaneshwari nagar	Sanctioned Amount 990000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Providing Flagging course and Covering Slab to Road side drains to 2nd main and 7th A cross road of Rangappa layout bhuvaneshwari nagar	Job No Work Code 183-11-000030
Work OrderNo EE/PN/JE/WO NO/232/11-12	Work Order Date 23/12/2011	Period of Extention 90 days
Defect Liability Period From 23/12/2011	Defect Liability Period To 23/12/2012	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		lingegowda
Date of Inspection	Remarks	
18/02/2015	complet	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0188, W0051, W0194	2nd Main Rd, 4th C Crs, 3rd Main 5th Block	Kumar swamy Layuot
SegmentNo	TotalLength	
183/S-W0188/S69863	110.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Keshavmurthy,		725500.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC Culvert, improvements to Road side Drains and Providing covering slabs to 4th cross road of Bhuvanewarinagar.	800000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC Culvert, improvements to Road side Drains and Providing covering slabs to 4th cross road of Bhuvanewarinagar.	183-11-000043
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/140/11-12	13/09/2011	60 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
13/09/2011	13/09/2012	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		Linge Gowda
Date of Inspection	Remarks	
29/10/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0019, W0033, W0026, W0025	NA, 2nd Main Rd K E B Rd, 3rd C Crs, NA	Kumar Swamy layout
SegmentNo	TotalLength	
183/S-W0019/S69868	125.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.H.N Manjegowda		842470.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC Culvert, improvements to Road side Drains and Providing covering slabs to 3rd cross road of Ittamadu BDA layout	930000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC Culvert, improvements to Road side Drains and Providing covering slabs to 3rd cross road of Ittamadu BDA layout	183-11-000039
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/104/11-12	08/08/2011	60 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
08/08/2011	08/08/2012	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		Linge Gowda
Date of Inspection	Remarks	
29/10/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0136	10th C Crs	Ittamadu
SegmentNo	TotalLength	
183/S-W0136/S69901	90.00	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri T srinivas		743330.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement to drains and Providing covering slabs to 10th cross of Kuvempunagar in Ittamadu	800000	2012
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvement to drains and Providing covering slabs to 10th cross of Kuvempunagar in Ittamadu	183-12-000008
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/236/11-12	24/12/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
24/12/2011	24/12/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Linge Gowda
Date of Inspection	Remarks	
29/10/2014	complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0127, W0104, W0137, W0135	2nd Main Rd Ittmadu, 8th A Crs Ittmadu, 10th A Crs Bhuvaneshwari Nagar, NA	Padmanabhanagar
SegmentNo	TotalLength	
183/S-W0127/S71086	165.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri C.krishnaiah		990000.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC deck culverts and improvements to drain and providing covering slabs to 18th Cross road of Ittmadu BDA layout	1075000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC deck culverts and improvements to drain and providing covering slabs to 18th Cross road of Ittmadu BDA layout	183-11-000047
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/NO NO/51/11-12	23/07/2011	60 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
12/07/2011	23/07/2012	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Linge Gowda
Date of Inspection	Remarks	
31/10/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 183	WardName Chikkalsandra
StreetID W0192, W0073, W0186, W0196	StreetName 2nd A Main, 1st A Crs Banashankari 3rd Stage, 1st A Main Rd, 2nd Main Rd	Significant LandMark Chikkalasandra
SegmentNo 183/C-W0192/S115927	TotalLength 101.55	

ContractorDetails		
NameofContractor Sri D Ananda naidu	ContractorRegNo	Expenditure 886090.00
PhoneNo	Emailld	

Work Details		
NameOfWork Providing flagging course and covering slabs to road side drain to 1stB cross road in Krishnaiah layout Bhuvaneswari nagar	Sanctioned Amount 970000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Providing flagging course and covering slabs to road side drain to 1stB cross road in Krishnaiah layout Bhuvaneswari nagar	Job No Work Code 183-11-000026
Work OrderNo EE/PN/JE/WO NO/161/11-12	Work Order Date 13/10/2011	Period of Extention 60 days
Defect Liability Period From 13/10/2011	Defect Liability Period To 13/10/2012	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		Linge Gowda
Date of Inspection	Remarks	
29/10/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0171, W0073, W0075, W0208, W0071	1st C Crs Banashankari 3rd Stage, 1st A Crs Banashankari 3rd Stage, 1st Crs Banashankari 3rd Stage,	Chikkalasandra
SegmentNo	TotalLength	
183/C-W0171/S031800	118.90	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Gowthami Constructions		881893.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing flagging course and covering slabs to road side drain to 3rd main and Balance cross road of Krishnaiah layout in Bhuvaneswari nagar	950000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Providing flagging course and covering slabs to road side drain to 3rd main and Balance cross road of Krishnaiah layout in Bhuvaneswari nagar	183-11-000031
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/235/11-12	23/12/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
19/12/2011	23/12/2012	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		Linge Gowda
Date of Inspection	Remarks	
31/10/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0142	11th Crs	Chikkalasandra
SegmentNo	TotalLength	
183/S-W0142/S033245	161.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.Harshitha Construction		1064950.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement of Drain and providing covering slabs to 11th cross road of Kuvempunagar in Ittamadu	1150000	2012
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvement of Drain and providing covering slabs to 11th cross road of Kuvempunagar in Ittamadu	183-12-000009
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/212/11-12	15/11/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
15/11/2011	15/11/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
2		Linge Gowda
Date of Inspection	Remarks	
31/10/2014	complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0046, W0309, W0307, M0191	4th Crs, 2nd Crs, 7th Crs, Ittmadu Main Rd	Govt School
SegmentNo	TotalLength	
183/S-W0046/S63998	119.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N S Constructions		1415360.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC desk Slabs Culvert, improvements to road side drain and providing B.S slabs to 7th cross road N/S of 50 feet main road Thimmarayag	1550000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC desk Slabs Culvert, improvements to road side drain and providing B.S slabs to 7th cross road N/S of 50 feet main road Thimmarayagowda layout	161-11-000032
Work OrderNo	Work Order Date	Period of Extention
EE(PN)WO/60/11-12	27/07/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/07/2011	27/07/2012	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		Venkatesh
Date of Inspection	Remarks	
05/11/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0056, W0190, W0309, M0191	4th Crs, 6th Crs, 2nd Crs, Ittmadu Main Rd	Thimmarayagowda Layout
SegmentNo	TotalLength	
183/S-W0056/S64090	138.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Teacnical Manager		1685965.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC desk Slabs Culvert, improvements to drains and covering slab to 6th and 7th cross road at S/side of 50 ft main road Thimmarayagowd	1605000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC desk Slabs Culvert, improvements to drains and covering slab to 6th and 7th cross road at S/side of 50 ft main road Thimmarayagowda layout	161-11-000017
Work OrderNo	Work Order Date	Period of Extention
EE(PN)WO/16/10-11	24/02/2011	120days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
24/02/2011	24/02/2012	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		venkatesh
Date of Inspection	Remarks	
03/02/2015	complete	
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet



Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0046, W0309, W0307, M0191	4th Crs, 2nd Crs, 7th Crs, Ittmadu Main Rd	Thimmarayagowda Layout
SegmentNo	TotalLength	
183/S-W0046/S64096	133.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Teacnical Manager		1658965.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC desk Slabs Culvert, improvements to drains and covering slab to 6th and 7th cross road at S/side of 50 ft main road Thimmarayagowd	1605000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC desk Slabs Culvert, improvements to drains and covering slab to 6th and 7th cross road at S/side of 50 ft main road Thimmarayagowda layout .	161-11-000017
Work OrderNo	Work Order Date	Period of Extention
EE(PN)WO/16/10-11	24/02/2011	120 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
24/02/2011	24/02/2012	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
4		venkatesh
Date of Inspection	Remarks	
03/02/2015	complete	
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet


Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0002, W0090, M0191, W0148	NA, 1st Crs Aanjeneya Hbcs, Ittmadu Main Rd, 2nd Crs Aanjeneya Hbcs	Hoskerehalli
SegmentNo	TotalLength	
183/S-W0002/S67568	121.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.S.Innasappa		929765.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC desk Slabs Culvert, improvements to Road side drains and providing covering Slabs to 5th main road of Anjaneyanagara	1000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC desk Slabs Culvert, improvements to Road side drains and providing covering Slabs to 5th main road of Anjaneyanagara	161-11-000061
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/292/11-12	13/01/2012	60 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
13/01/2012	13/01/2013	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		Venkatesh
Date of Inspection	Remarks	
31/10/2014	complete	
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0164, W0199, W0135, W0195, W0166, W0174, I0159, I	NA, 3rd Crs, Vinayaka Lyt 3rd Crs, Vinayaka Lyt 2nd Crs	Kakathi ngar
SegmentNo	TotalLength	
183/C-W0164/S023141	1047.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9986697126		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of culverts and improvements to drains with providing covering slabs to Kakathinagar 2nd main 3rd main, 5th main and 3rd to 6th cross in	8055000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	Drain and Culvert
Tender	WorkDetails	Job No Work Code
Not a Tender	Construction of culverts and improvements to drains with providing covering slabs to Kakathinagar 2nd main 3rd main, 5th main and 3rd to 6th cross in ward No.183	183-14-000026
Work OrderNo	Work Order Date	Period of Extention
EE/PN/AE/WoNo/36/14-15	05/11/2014	180 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
05/11/2014	05/11/2015	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
	Umesh V
Date of Inspection	Remarks
11/03/2016	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 183	WardName Chikkalsandra
StreetID W0138, W0127, W0133, W0129, W0179, W0175, W0185	StreetName 9th Crs, 2nd Main Rd Ittmadu, 10th D Crs, NA, 2nd C Crs, 2nd D Crs, 2nd B Crs	Significant LandMark Chikkalasandra
SegmentNo 183/C-W0138/S113444	TotalLength 196.58	

ContractorDetails		
NameofContractor M/S Sai construction,	ContractorRegNo	Expenditure 825630.00
PhoneNo	EmailId	

Work Details		
NameOfWork Construction of RCC culvert and improvements to drain providing Covering Slab to 9 th of Ittamadu BDA Layout Ward no 183	Sanctioned Amount 900000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Construction of RCC culvert and improvements to drain providing Covering Slab to 9 th of Ittamadu BDA Layout Ward no 183	Job No Work Code 183-11-000048
Work OrderNo EE/PN/JE/WO NO/43/11-12	Work Order Date 22/07/2011	Period of Extention 60days
Defect Liability Period From 22/07/2011	Defect Liability Period To 22/07/2012	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Linge Gowda
Date of Inspection	Remarks	
31/10/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 183	WardName Chikkalsandra
StreetID W0127, W0096, W0098, W0135	StreetName 2nd Main Rd Ittmadu, NA, 7th A Crs	Significant LandMark Chikkalasandra
SegmentNo 183/C-W0127/S115232	TotalLength 183.60	

ContractorDetails		
NameofContractor Sri A.N Narasimhaiah	ContractorRegNo	Expenditure 907130.00
PhoneNo	EmailId	

Work Details		
NameOfWork Providing Flagging course and covering Slabs to road side drains 7th cross of ittamadu BDA Layout	Sanctioned Amount 900000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Providing Flagging course and covering Slabs to road side drains 7th cross of ittamadu BDA Layout	Job No Work Code 183-11-000034
Work OrderNo EE/PN/JE/WO NO/239/11-12	Work Order Date 27/12/2011	Period of Extention 90 days
Defect Liability Period From 02/01/2012	Defect Liability Period To 27/12/2012	Multiple Road Involved No

Field Inspection Details		
Number of Trees 2	Other Information	Name Linge Gowda
Date of Inspection 31/10/2014	Remarks complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0075	1st Crs Banashankari 3rd Stage	Chikkalasandra
SegmentNo	TotalLength	
183/S-W0075/S120845	73.05	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.Ananda Naidu		904590.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Flagging course and covering Slabs to road side drains 1st cross road in Krishnaiah Layout and 2nd main road of Bhuvaneswara nagar	990000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Providing Flagging course and covering Slabs to road side drains 1st cross road in Krishnaiah Layout and 2nd main road of Bhuvaneswara nagar	183-11000028
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/163/11-12	13/10/2011	60 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
13/10/2011	13/10/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
1		Linge Gowda
Date of Inspection	Remarks	
31/10/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0192, W0073, W0075, W0077	2nd A Main, 1st A Crs Banashankari 3rd Stage, 1st Crs Banashankari 3rd Stage, 1st Crs Revenue Lyt 5	Chikkalasandra
SegmentNo	TotalLength	
183/C-W0192/S122233	43.97	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.Ananda Naidu		904590.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Flagging course and covering Slabs to road side drains 1st cross road in Krishnaiah Layout and 2nd main road of Bhuvanewara nagar	990000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Providing Flagging course and covering Slabs to road side drains 1st cross road in Krishnaiah Layout and 2nd main road of Bhuvanewara nagar	183-11000028
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/163/11-12	13/10/2011	60 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
13/10/2011	13/10/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet


Field Inspection Details		
Number of Trees	Other Information	Name
2		lingegowda
Date of Inspection	Remarks	
18/02/2015	complet	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 183	WardName Chikkalsandra
StreetID W0059	StreetName 4th A Crs	Significant LandMark Chikkalasandra
SegmentNo 183/S-W0059/S012411	TotalLength 55.73	

ContractorDetails		
NameofContractor M/S Vijay Associates	ContractorRegNo	Expenditure 1476290.00
PhoneNo	EmailId	

Work Details		
NameOfWork Constrictions of RCC Culvert and Improvements and providing Covering Slabs 4th A and 4th B Cross road of Bhuvanewarinagar	Sanctioned Amount 1600000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Constrictions of RCC Culvert and Improvements and providing Covering Slabs 4th A and 4th B Cross road of Bhuvanewarinagar	Job No Work Code 183-11--000041
Work OrderNo EE/PN/JE/WO NO/47/11-12	Work Order Date 23/07/2011	Period of Extention 90 DAYS
Defect Liability Period From 23/07/2011	Defect Liability Period To 23/07/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		Linge Gowda
Date of Inspection	Remarks	
31/10/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0055	4th B Crs	Chikkalasandra
SegmentNo	TotalLength	
183/S-W0055/S015255	58.42	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S Vijay Associates		1476290.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrictions of RCC Culvert and Improvements and providing Covering Slabs 4th A and 4th B Cross road of Bhuvanewarinagar	1600000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrictions of RCC Culvert and Improvements and providing Covering Slabs 4th A and 4th B Cross road of Bhuvanewarinagar	183-11--000041
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/47/11-12	23/07/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/07/2011	23/07/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		lingegowda
Date of Inspection	Remarks	
18/02/2015	comolet	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0073	1st A Crs Banashankari 3rd Stage	Chikkalasandra
SegmentNo	TotalLength	
183/S-W0073/S033019	141.55	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri A.N Narasimhaiah		882880.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Flagging course and covering Slabs to road side drains to 1st A cross road of Krishnaiah Layout in Bhuvaneswara nagar	970000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Providing Flagging course and covering Slabs to road side drains to 1st A cross road of Krishnaiah Layout in Bhuvaneswara nagar	183-11-000025
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/237//11-12	24/12/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
24/12/2011	24/12/2012	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		Linge Gowda
Date of Inspection	Remarks	
31/10/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0056	4th Crs	Chikkalasandra
SegmentNo	TotalLength	
183/S-W0056/S034043	184.79	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager (west),		2062900.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC deck slab culvert, Improvements to drain and providing Covering Slabs to 4th and 5th cross road of Sriram nagar Ittamadu	1997000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC deck slab culvert, Improvements to drain and providing Covering Slabs to 4th and 5th cross road of Sriram nagar Ittamadu	183-11-000020
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/13/10-11	23/02/2011	180 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
21/02/2011	23/02/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		Linge Gowda
Date of Inspection	Remarks	
31/10/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 183	WardName Chikkalsandra
StreetID W0119, W0066, M0191, W0113	StreetName 6th Main Rd, 5th Crs, Ittmadu Main Rd, 8th Main	Significant LandMark Chikkalasandra
SegmentNo 183/C-W0119/S035027	TotalLength 149.89	

ContractorDetails		
NameofContractor Technical Manager (west)	ContractorRegNo	Expenditure 2062900.00
PhoneNo	EmailId	

Work Details		
NameOfWork Construction of RCC deck slab culvert, Improvements to drain and providing Covering Slabs to 4th and 5th cross road of Sriram nagar Ittamadu	Sanctioned Amount 1997000	Sanctioned Year 2011
Year 2010 - 2011	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Construction of RCC deck slab culvert, Improvements to drain and providing Covering Slabs to 4th and 5th cross road of Sriram nagar Ittamadu	Job No Work Code 183-11-000020
Work OrderNo EE/PN/JE/WO NO/13/10-11	Work Order Date 23/02/2011	Period of Extention 180 days
Defect Liability Period From 23/02/2011	Defect Liability Period To 23/02/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		linegowda
Date of Inspection	Remarks	
18/02/2015	completa	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0127, W0056, W0066, W0011, W0058, W0054	2nd Main Rd Ittmadu, 4th Crs, 5th Crs, 2nd Main Rd, 3rd B Crs, 4th Crs Ittmadu	Chikkalasandra
SegmentNo	TotalLength	
183/C-W0127/S035623	13.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager (west)		2062900.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC deck slab culvert, Improvements to drain and providing Covering Slabs to 4th and 5th cross road of Sriram nagar Ittamadu	1997000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC deck slab culvert, Improvements to drain and providing Covering Slabs to 4th and 5th cross road of Sriram nagar Ittamadu	183-11-000020
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/13/10-11	23/02/2011	180 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/02/2011	23/02/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		P.Prasad
Date of Inspection	Remarks	
31/10/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0109, W0115, W0119, W0100, W0111, W0309, M0191, W	NA, 8th Main Rd, 6th Main Rd, 7th Crs, 6th A Crs Ittmadu, 2nd Crs, Ittmadu Main Rd, 7th Main Rd	Chikkalasandra
SegmentNo	TotalLength	
183/C-W0109/S041207	121.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager (west)		1868860.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC deck slab culvert, Improvements to drain and providing Covering Slabs 7th main and 7th cross road Sriramanagar Ittamadu	1851000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC deck slab culvert, Improvements to drain and providing Covering Slabs 7th main and 7th cross road Sriramanagar Ittamadu	183-11-000018
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/14/10-11	23/02/2011	180 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/02/2011	23/02/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		P.Prasad
Date of Inspection	Remarks	
29/10/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0117	7th Main Rd	Chikkalasandra
SegmentNo	TotalLength	
183/S-W0117/S041734	52.28	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager (west)		1868860.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC deck slab culvert, Improvements to drain and providing Covering Slabs 7th main and 7th cross road Sriramanagar Ittamadu	1851000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC deck slab culvert, Improvements to drain and providing Covering Slabs 7th main and 7th cross road Sriramanagar Ittamadu	183-11-000018
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/14/10-11	23/02/2011	180 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/02/2011	23/02/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		P.Prasad
Date of Inspection	Remarks	
29/10/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0158	14th Crs	Chikkalasandra
SegmentNo	TotalLength	
183/S-W0158/S115809	130.48	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Harish Construction		1391920.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and Providing covering slab to 14th and 15th cross road of Kuvempunagar in Ittamadu in ward No-183	1500000	2012
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drain and Providing covering slab to 14th and 15th cross road of Kuvempunagar in Ittamadu in ward No-183	183-12-000012
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/227/10-11	22/11/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
22/11/2011	22/11/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		linegowda
Date of Inspection	Remarks	
18/02/2015	complet	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Footpath Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0172	15th Crs	Chikkalasandra
SegmentNo	TotalLength	
183/S-W0172/S120240	146.68	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Harish Construction		1391920.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and Providing covering slab to 14th and 15th cross road of Kuvempunagar in Ittamadu in ward No-183	1500000	2012
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drain and Providing covering slab to 14th and 15th cross road of Kuvempunagar in Ittamadu in ward No-183	183-12-000012
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/227/10-11	22/11/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
22/11/2011	22/11/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		linegowda
Date of Inspection	Remarks	
18/02/2015	complet	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0138, W0146, W0132, W0156, W0140, W0150, W0175, W	9th Crs, 12th Crs, 8th B Crs, NA, 10th Crs, 2nd D Crs, 11th Crs, 2nd A Main Rd, 13th Crs Ittmadagu	Ghikkalasandra
SegmentNo	TotalLength	
183/C-W0138/S122002	59.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri A.N Narasimhaiah		1475860.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and Providing covering slab to 13th B cross road of Kuvempunagar in Ittamadu in ward No 183	1600000	2012
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drain and Providing covering slab to 13th B cross road of Kuvempunagar in Ittamadu in ward No 183	183-12-000013
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/WO NO/210/10-11	15/11/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
15/11/2011	15/11/2012	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		linegowd
Date of Inspection	Remarks	
18/02/2015	complet	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet



Zone SOUTH	WardNo 183	WardName Chikkalsandra
StreetID W0127, W0029, W0064, W0031, W0011, W0033, W0027, W	StreetName NA	Significant LandMark Sri Rameswara Temple
SegmentNo 183/C-W0127/S084859	TotalLength 300.93	

ContractorDetails		
NameofContractor Shivalingegowda	ContractorRegNo	Expenditure 0.00
PhoneNo 9341228174	EmailId	

Work Details		
NameOfWork Improvements to Drain and Providing B S Covering Slabs to 5th and 4th A Crs of Ittamadu in Ward No 183.	Sanctioned Amount 1937000	Sanctioned Year 2014
Year 2013 - 2014	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Improvements to Drain and Providing B S Covering Slabs to 5th and 4th A Crs of Ittamadu in Ward No 183.	Job No Work Code 183-14-000007
Work OrderNo EE/PN/AE/Wo/no/269/13-14	Work Order Date 04/02/2014	Period of Extention 90 Days
Defect Liability Period From 04/02/2014	Defect Liability Period To 04/02/2015	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Umesh
Date of Inspection	Remarks	
10/03/2016		
Category	Photo	
Drain Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 183	WardName Chikkalsandra
StreetID W0146, W0173, W0148, W0150, W0175	StreetName NA	Significant LandMark V.V Bakari
SegmentNo 183/C-W0146/S113848	TotalLength 181.45	

ContractorDetails		
NameofContractor A.N.Narasimhaiah	ContractorRegNo	Expenditure 0.00
PhoneNo 9742773817	EmailId	

Work Details		
NameOfWork Improvements to drain and providing covering slabs to 13th Cross of Kuvempunagar ittamadu in Ward No-183	Sanctioned Amount 1100000	Sanctioned Year 2012
Year 2013 - 2014	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Improvements to drain and providing covering slabs to 13th Cross of Kuvempunagar ittamadu in Ward No-183	Job No Work Code 183-12-000011
Work OrderNo EE/PN/AE/WoNo/99/13-14	Work Order Date 23/10/2013	Period of Extention 90 Days
Defect Liability Period From 23/10/2013	Defect Liability Period To 23/10/2014	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name Umesh V
Date of Inspection 11/03/2016	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0171, W0224, W0220, W0069, W0198, W0208, W0214, W	NA	Mahalakshmi Temple
SegmentNo	TotalLength	
183/C-W0171/S114802	273.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9986697126		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and foothpath to 8o feet road Bhuvaneshwarinagar to Chikkalasandra Main Road, in Ward No-183.	1997000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender	Improvements to drain and foothpath to 8o feet road Bhuvaneshwarinagar to Chikkalasandra Main Road, in Ward No-183.	183-13-000022
Work OrderNo	Work Order Date	Period of Extention
EE/PN/AE/WoNo/258/12-13	18/02/2014	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/02/2014	18/02/2015	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/03/2016	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 183	WardName Chikkalsandra
StreetID W0310, W0085, W0079, W0077, W0308	StreetName Chikkanna Lyt 4th Crs, NA, Om Shakthi Lyt 4th Crs	Significant LandMark 183 Ward Office
SegmentNo 183/C-W0310/S115752	TotalLength 226.03	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9986697126	EmailId	

Work Details		
NameOfWork Emergency work in ward No.183, Re-construction of secondary drain in 8th cross and 9th A cross dena bank colony in ward 183	Sanctioned Amount 1250000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Drain Maintenance	Other Work Type
Tender Not a Tender	WorkDetails Emergency work in ward No.183, Re-construction of secondary drain in 8th cross and 9th A cross dena bank colony in ward 183	Job No Work Code 183-14-000016
Work OrderNo EE/PN/AE/WoNo/29/14-15	Work Order Date 02/09/2014	Period of Extention 90 Days
Defect Liability Period From 02/09/2014	Defect Liability Period To 30/08/2015	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/03/2016	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 183	WardName Chikkalsandra
StreetID W0039, W0022, W0050, W0032, W0104, W0141, W0090, W	StreetName NA	Significant LandMark Satyanarayana Temple
SegmentNo 183/C-W0039/S123154	TotalLength 1269.96	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9986697126	EmailId	

Work Details		
NameOfWork Improvements to drain with covering slab and deck slab to 2nd, 8th, 10th, 11th Main and 9th A Cross, 10th Cross, 7th A Cross, 8th Cross, 9th Cross and	Sanctioned Amount 10000000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Others	Other Work Type Drain, Cullverts and CC Pavaing
Tender Not a Tender	WorkDetails Improvements to drain with covering slab and deck slab to 2nd, 8th, 10th, 11th Main and 9th A Cross, 10th Cross, 7th A Cross, 8th Cross, 9th Cross and cross roads BSK 2nd Stage, Bhuvaneswara nagara, in Ward No-183	Job No Work Code 183-13-000020
Work OrderNo EE/PN/AE/Wo/No/355/12-13	Work Order Date 20/02/2014	Period of Extention 180 Days
Defect Liability Period From 20/02/2014	Defect Liability Period To 20/02/2015	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/03/2016	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 183	WardName Chikkalsandra
StreetID W0019, W0028, W0033, W0021	StreetName NA, 1st Crs, 2nd Main Rd K E B Rd	Significant LandMark Hamadu layout
SegmentNo 183/C-W0019/S091817	TotalLength 108.05	

ContractorDetails		
NameofContractor Sri.S.R.Vikram	ContractorRegNo	Expenditure 1477510.00
PhoneNo	EmailId	

Work Details		
NameOfWork Improvements to drain and providing covering Slab to 2nd cross and 1th main road and Hamadu layout in Wo no 183	Sanctioned Amount 1732000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Improvements to drain and providing covering Slab to 2nd cross and 1th main road and Hamadu layout in Wo no 183	Job No Work Code 183-12-000034
Work OrderNo EE/PN/JE/Wo No/128/12-13	Work Order Date 17/08/2013	Period of Extention 90days
Defect Liability Period From 17/08/2013	Defect Liability Period To 17/08/2014	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 2	Other Information	Name umesha
Date of Inspection 19/02/2015	Remarks complet	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 183	WardName Chikkalsandra
StreetID W0030, W0033, W0021, W0017	StreetName 2nd Crs, 2nd Main Rd K E B Rd, NA	Significant LandMark Hamadu layout
SegmentNo 183/C-W0030/S093437	TotalLength 124.32	

ContractorDetails		
NameofContractor Sri.S.R.Vikram	ContractorRegNo	Expenditure 1477510.00
PhoneNo	EmailId	

Work Details		
NameOfWork Improvements to drain and providing covering Slab to 2nd cross and 1th main road and Hamadu layout in Wo no 183	Sanctioned Amount 1732000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Improvements to drain and providing covering Slab to 2nd cross and 1th main road and Hamadu layout in Wo no 183	Job No Work Code 183-12-000034
Work OrderNo EE/PN/JE/Wo No/128/12-13	Work Order Date 17/08/2013	Period of Extention 90days
Defect Liability Period From 17/08/2013	Defect Liability Period To 17/08/2014	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 3	Other Information	Name umesha
Date of Inspection 19/02/2015	Remarks complet	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0003	4th Main Rd	Rajahamsa road
SegmentNo	TotalLength	
183/S-W0003/S094202	75.47	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.Gajanana Construction		1602560.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing covering Slab to 4th main road and Rajahamsa road in Wo no 183	1800000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drain and providing covering Slab to 4th main road and Rajahamsa road in Wo no 183	183-12-000034
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/Wo No/128/12-13	26/09/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
26/09/2012	26/09/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		lingegowda
Date of Inspection	Remarks	
04/02/2015	complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0001	5th Main Rd	Rajahamsa road
SegmentNo	TotalLength	
183/S-W0001/S094854	69.03	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.Gajanana Construction		1602560.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing covering Slab to 4th main road and Rajahamsa road in Wo no 183	1800000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drain and providing covering Slab to 4th main road and Rajahamsa road in Wo no 183	183-12-000034
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/Wo No/128/12-13	26/09/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/10/2012	26/09/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Linge Gowda
Date of Inspection	Remarks	
31/10/2014	complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0138, W0136, W0127, W0193, W0133, W0104, W0128, W	9th Crs, 10th C Crs, 2nd Main Rd Ittmadu, 10th Crs, 10th D Crs, 8th A Crs Ittmadu, 10th B Crs, NA,	Anjanaya temple road
SegmentNo	TotalLength	
183/C-W0138/S095608	124.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.T.S .Mahadeva		1188100.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing covering Slab to Anjanaya temple road in Wo no 183	1320000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drain and providing covering Slab to Anjanaya temple road in Wo no 183	183-12-000027
Work OrderNo	Work Order Date	Period of Extention
EE/PN/JE/Wo No/98/12-13	27/08/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/08/2012	27/08/2013	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		Linge Gowda
Date of Inspection	Remarks	
31/10/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0096	NA	SWD Drain
SegmentNo	TotalLength	
183/S-W0096/S032225	87.11	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9343722108		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Cement Concrete Roads to Conservancy Roads and bad Stretches in Wards No-183.	1700000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	Cemente Concrete Road
Tender	WorkDetails	Job No Work Code
Tender	Providing Cement Concrete Roads to Conservancy Roads and bad Stretches in Wards No-183.	183-14-000023
Work OrderNo	Work Order Date	Period of Extention
EE/PN/AE/WO No/34/2014-15	05/11/2014	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
05/11/2014	05/11/2015	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Umesh
Date of Inspection	Remarks	
28/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0186	NA	Kamakaya Tharater
SegmentNo	TotalLength	
183/S-W0186/S114016	146.98	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Harish constructions		0.00
PhoneNo	EmailId	
9448068702		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain and Providing B.S covering slabs to 1st A main road(From Kamakya Main road to 2nd cross Bhuvaneshwarinagar) in Ward No-183.	1347000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Drain and Providing B.S covering slabs to 1st A main road(From Kamakya Main road to 2nd cross Bhuvaneshwarinagar) in Ward No-183.	183-14-000005
Work OrderNo	Work Order Date	Period of Extention
EE/PN/AW/WoNo/314/13-14	04/03/2014	90
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
04/03/2014	06/03/2015	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
05/03/2016	Completed

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	183	Chikkalsandra
StreetID	StreetName	Significant LandMark
W0310, W0192, W0292, W0077, W0208, W0300, W0186, W	Chikkanna Lyt 4th Crs, NA, 3rd Crs Lakshmi Sagar Lyt, 4th Crs Lakshmi Sagar Lyt, 1st Crs, Vidya Nu	Khamakya Thetare
SegmentNo	TotalLength	
183/C-W0310/S014042	315.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9986697126		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Removing resetting and deselting to Khamakya Mn Rd (1st Crs Khamakya Lyt) in Ward No 183.	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	Deselting
Tender	WorkDetails	Job No Work Code
Not a Tender	Removing resetting and deselting to Khamakya Mn Rd (1st Crs Khamakya Lyt) in Ward No 183.	183-14-000025
Work OrderNo	Work Order Date	Period of Extention
EE/PN/AE/Wo No/35/14-15	05/11/2014	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
05/11/2014	05/11/2015	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
	Umesh
Date of Inspection	Remarks
01/04/2016	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 183	WardName Chikkalsandra
StreetID W0065, W0061, W0184	StreetName Om Shakthi Lyt 5th Crs, Om Shakthi Lyt 7th Crs, NA	Significant LandMark Kathriguppe signal
SegmentNo 183/C-W0065/S052218	TotalLength 205.88	

ContractorDetails		
NameofContractor R.C. Enterprises(R. Chandra)	ContractorRegNo	Expenditure 0.00
PhoneNo 9880212349	EmailId	

Work Details		
NameOfWork Improvements to Drain and Providing B.S covering slabs to 1st main road(from 5th to 3rd cross) of Bhuvaneshwarinagar in Ward No-183.	Sanctioned Amount 1690000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Others	Other Work Type drain and culvert
Tender Tender	WorkDetails Improvements to Drain and Providing B.S covering slabs to 1st main road(from 5th to 3rd cross) of Bhuvaneshwarinagar in Ward No-183.	Job No Work Code 183-14-000006
Work OrderNo EE/PN/AE/Wo No/11/14-15	Work Order Date 25/06/2014	Period of Extention 90 Days
Defect Liability Period From 25/06/2014	Defect Liability Period To 25/06/2015	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Umesha.V
Date of Inspection	Remarks	
07/04/2016		

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start

