



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0083	NA	biny mill road
SegmentNo	TotalLength	
34/S-W0083/S082244	386.58	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sri.b.s.guru babu		1350000.00
PhoneNo	EmailId	
9448541055		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of rcc drain and covering slabs and kerb paiting shoulder drain grills in 4th, 5th main ganaganagara extension in ward 34	1353709.83	11-12
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	construction of rcc drian with rcc slabs covering and culvert with rcc deck slab	034-12-000028
Work OrderNo	Work Order Date	Period of Extention
034-12-000028	23/02/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
15		pushpalatha n.d
Date of Inspection	Remarks	
19/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0110	NA	1ST C MAIN ROAD
SegmentNo	TotalLength	
34/S-W0110/S083649	103.29	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448115105		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDNG CONCRETING TO 1 ST E MAIN ROAD, BEHIND BINNY MILL, GANGENAHALLI IN WARD NO.34	1000000	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	1. PROVIDING AND LAYING CC ROAD .	034-14-000021
Work OrderNo	Work Order Date	Period of Extention
NO.EE/AE/WO/179/14-15	08/08/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pushpalatha n. d
Date of Inspection	Remarks	
19/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0106	NA	lakshmi devamma apartment
SegmentNo	TotalLength	
34/S-W0106/S084557	114.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448115105		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
providing concreting to 1st e main road, behind binn ymill road in ward no.34	1000000	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	1. providing and laying cc road .	034-14-000021
Work OrderNo	Work Order Date	Period of Extention
no/EE/H/AE/WO/179/14-15	08/08/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pushpalatha n.d
Date of Inspection	Remarks	
19/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0117	NA	min veerappa moily house
SegmentNo	TotalLength	
34/S-W0117/S094513	210.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.N.SUDHAKAR REDDY	CBS/10289/CIVIL/2010	942000.00
PhoneNo	EmailId	
9448619840		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
providing and concreting roads RCC culverts in muthappa block in ward no.34	1000000	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	1. providing and laying 40mm and 20 mm concrete (RMC) to road cut portion and contruction of rcc culverts	034-13-000010
Work OrderNo	Work Order Date	Period of Extention
no.ee/h/ae/wo/55/13-14	02/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
10		pushpalatha n. d
Date of Inspection	Remarks	
19/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0024	NA	BBMP PARK
SegmentNo	TotalLength	
34/S-W0024/S043724	174.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		1939577.00
PhoneNo	EmailId	
9880858969		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN IN LEFT AND RIGHT SIDE OF KHM BLOCK MAIN ROAD AND CROSS ROADS IN WARD NO.34	2000000	12-13
Year	Type of Work	Other Work Type
2015 - 2016	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender	1. Earth work excavation2. Providing and laying 40mm3. palcing TMT Steel4. providing side wall (20mm)5. Placing pre cast slab RCC	034-13-000020
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/336/12-13	01/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
10/09/2015		
Category	Photo	
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0083	NA	binny mill road
SegmentNo	TotalLength	
34/S-W0083/S095543	386.58	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.M.V.Suresh Kumar		992353.55
PhoneNo	EmailId	
9341285087		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting and lane paiting at 4th main and cross Ganganagara extension in ward 34	1025585.9	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. Providing and laying WMM2.Providing and laying and compacting SDBC 25mm th	034-14-000004
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/252/14-15	21/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
10		pushpalatha n. d
Date of Inspection	Remarks	
23/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0090	NA	3RD MAIN AND 5TH MAIN KRISHNAPPA BLOCK
SegmentNo	TotalLength	
34/S-W0090/S030641	161.09	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.M.V.Suresh Kumar		992353.55
PhoneNo	EmailId	
9341285087		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Aphlating and Lane painting at 4th main and cross Ganganagara extension in ward 34	1025585.9	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. Providing and Laying WMM 2. Provding and laying SDBC 25mm thick	034-14-000004
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/252/14-15	21/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha . n.d
Date of Inspection	Remarks	
21/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0125	Veera Anjaneya Temple Rd	Min Dinesh Gundurao House
SegmentNo	TotalLength	
34/S-W0125/S071853	327.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.M.V.Suresh Kumar		1027277.10
PhoneNo	EmailId	
9341285087		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing and asphaltting to 1st main and crosses MLA layout in ward no.34	1028417.5	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. Providing and laying WMM2. Providing and laying SDBC 25mm thick	034-14-000007
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/253/14-15	21/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		pushpalatha . d
Date of Inspection	Remarks	
23/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0041	Om Shakthi Lyt, 9th Crs	Hotel Emirates
SegmentNo	TotalLength	
34/S-W0041/S072856	66.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.Ashok G		573900.00
PhoneNo	EmailId	
9036136305		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Concrete road to 5th cross, Dena Bank colony behind hotel emirates in ward No.34	574022.96	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Tender	1.0 Providing and laying 40mm cocnrete 2. Providing and laying 20mm (RMC)	034-14-00005
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE.WO.63/2014-15	24/06/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pushpalatha n. d
Date of Inspection	Remarks	
24/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0114, W0121, W0119, W0125, W0117, W0123	NA, Veera Anjaneya Temple Rd	milk booth
SegmentNo	TotalLength	
34/C-W0114/S073928	129.26	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.K.Srinivasa		0.00
PhoneNo	EmailId	
9844476080		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS OF EXISTING DRAIN IN mla aLAYOUT IN WARD NO.34	484072.03	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	1. Desilting of drain2. Covering with drain with tiles	034-14-000008
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/139/14-15	25/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		pushpalatha n. d
Date of Inspection	Remarks	
24/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0114	NA	SWD
SegmentNo	TotalLength	
34/S-W0114/S075710	589.89	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.V.Babu		1839297.24
PhoneNo	EmailId	
9844663999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
asphalting and lane painting 1st,2nd,3rd 4th 5th main road and cross roads in cpv block	1795000	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	providing and laying sdbc 25m th	034-14-000012
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/ /14-15	14/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
8		pushpalatha n. d
Date of Inspection	Remarks	
21/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0108	Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	SWD
SegmentNo	TotalLength	
34/S-W0108/S080035	230.34	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.C.RAJU		780000.00
PhoneNo	EmailId	
9448354105		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDNG CONCRETING TO 6TH,7TH,8TH,9TH,10TH CROSS ROADS IN KRISHNAPPA BLOCK IN WARD NO.34	782896	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDNG 40MM CONCRETE2.PROVIDING 20MM (RMC) TO CONCRETE PORTION OF THE ROAD.	034-14-000011
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/202-13-14	17/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
5	Name
Date of Inspection	Remarks
19/06/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0088	NA	SWD
SegmentNo	TotalLength	
34/S-W0088/S080954	223.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.C.RAJU		782000.00
PhoneNo	EmailId	
9448354105		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CONCRETING TO 6TH,7TH,8TH,9TH,10TH CROSS ROADS IN KRISHNAPPA BLOCK IN WARD 34	782896	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDING 40MM CONCRTE2. PROVIDING 20MM (RMC) TO CONCRETE PORTION OF THE ROAD	034-14-000011
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/202/13-14	17/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		pushpalatha . n. d
Date of Inspection	Remarks	
19/06/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet


Zone EAST	WardNo 34	WardName Gangenahalli
StreetID W0086	StreetName NA	Significant LandMark SWD
SegmentNo 34/S-W0086/S081354	TotalLength 215.39	

ContractorDetails		
NameofContractor SRI.C.RAJU	ContractorRegNo	Expenditure 782800.00
PhoneNo 9448354105	EmailId	

Work Details		
NameOfWork PROVIDING CONCRETING TO 6TH,7TH,8TH,9TH AND 10TH CROSS ROADS OF KRISHNAPPA BLOCK IN WARD 34	Sanctioned Amount 782896	Sanctioned Year 13-14
Year 2013 - 2014	Type of Work Resurfacing	Other Work Type
Tender Tender	WorkDetails 1. PROVIDING 40MM CONCRETE 2.PROVIDING 20MM (RMC) CONCRETE TO CONCRETE PORTION OF THE ROAD	Job No Work Code 034-14-000011
Work OrderNo NO.EE/H/AE/WO/202/14-15	Work Order Date 17/02/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
19/06/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 34	WardName Gangenahalli
StreetID W0084	StreetName NA	Significant LandMark FATHIMA MASJID
SegmentNo 34/S-W0084/S081746	TotalLength 198.33	

ContractorDetails		
NameofContractor SRI.C.RAJU	ContractorRegNo	Expenditure 782000.00
PhoneNo 9448354105	EmailId	

Work Details		
NameOfWork PROVIDING CONCRETING TO 6TH, 7TH,8TH,9TH, 10TH CROSS ROADS IN KRISHNAPPA BLOCK IN WARD NO.34	Sanctioned Amount 782896	Sanctioned Year 13-14
Year 2013 - 2014	Type of Work Resurfacing	Other Work Type
Tender Tender	WorkDetails 1.PROVIDING 40MM CONCRETE 2.PROVIDING 20MM RMC CONCRTE TO CONCRETE PORTION OF THE ROAD	Job No Work Code 034-14-000011
Work OrderNo NO.EE/H/AE/WO/202/13-14	Work Order Date 17/02/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
19/06/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0025	NA	5TH MAIN KRISHNAPPA BLOCK MAIN ROAD
SegmentNo	TotalLength	
34/S-W0025/S082439	74.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.C.RAJU		7829000.00
PhoneNo	EmailId	
9448354105		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CONCRETING TO 6HT,7TH,8H,9TH AND 10TH CROSS KRISHNAPPA BLOCK IN WARD 34	782896.2	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDING 40MM CONRETE 2. PROVIDING 20MM CONCRETE (RMC) CONSIDERED LENGTH	034-14-000011
Work OrderNo	Work Order Date	Period of Extention
NO.EE/AE/WO/202/14-15	17/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
1		pushpalatha n. d
Date of Inspection	Remarks	
25/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0080	NA	5TH MAIN KRISHNAPPA BLOCK
SegmentNo	TotalLength	
34/S-W0080/S083025	186.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.C.RAJU		782000.00
PhoneNo	EmailId	
9448354105		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDNG CONCRETING TO 6TH,7TH,8TH,9TH,10TH CROSS ROADS IN KRISHNAPPA BLCOK IN WARD 34	782896	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDING 40MM CONCRETE2. PROVIDING 20MM RMC TO CONCRETE PORTION OF THE ROAD	034-14-000011
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/202/13-14	17/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
19/06/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0076	NA	All pine apartment
SegmentNo	TotalLength	
34/S-W0076/S102410	141.12	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.M.S.Raju		1417633.65
PhoneNo	EmailId	
9845167879		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provding RCC Drain and covering slab Market Road up to Ambedhkar Slum in ward 34	144009.65	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	1. Construction of RCC drain with RCC covering slabs (Right side of the road: from binny mill road entrance)	No.34-13-000005
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/57/2013-14	02/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
2		pushpalatha n. d
Date of Inspection	Remarks	
25/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0049	NA	Ambedhkar Slum
SegmentNo	TotalLength	
34/S-W0049/S102924	105.80	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.M.S.Raju		1417633.65
PhoneNo	EmailId	
9845167879		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providin RCC Drain and covering slab Market Road upto Ambedhkar slum in ward 34	1440097.65	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender	1. Construction of RCC drain with RCC coverig slabs (Right side of the road) from water tank to dead end)	034-13-000005
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/57/13-14	02/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
2		pushpalatha n. d
Date of Inspection	Remarks	
25/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0136	NA	Bellary main road
SegmentNo	TotalLength	
34/S-W0136/S103730	628.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		1740000.00
PhoneNo	EmailId	
9341285087		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provding Asphaltting at binny mill road (road sunk portion from Binny mill road entrance to vani school) in Ward 34	2000000	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Resurfacing	
Tender	WorkDetails	Job No Work Code
Not a Tender	1. Providing and laying GSB2. Providing and laying WMM3. Providing and laying BM4. Providing and laying BC 40MM COMPACTED THICKNESS	034-14-000017
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/31/12-13	17/05/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
1	Name
Date of Inspection	Remarks
25/06/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0013	NA	BBMP PARK
SegmentNo	TotalLength	
34/S-W0013/S122116	239.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.M.V.SURESH KUMAR		2093270.00
PhoneNo	EmailId	
9341285087		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVDING AND ASPHALTING TO ROADS 1ST, 2ND ND 3RD CROSS AND MAIN ROADS IN KHM BLOCK IN WARD NO.34	2095272.8	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDING AND LAYING BM 50MM THICK2. PROVIDING AND LAYING SDBC (50MM THICK)	034-13-000002
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/251/14-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
2	Name
Date of Inspection	Remarks
23/06/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0004	NA	BBMP PARK
SegmentNo	TotalLength	
34/S-W0004/S015413	140.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.N.V.SURESH KUMAR		2082272.80
PhoneNo	EmailId	
9341285087		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING ASPHALTING TO ROADS 1ST, 2ND AND 3RD CROSS AND MAIN ROADS IN KHM BLOCK IN WARD NO.34	2095272.8	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDING ASPHALTING TO ROAD BY SDBC 25MM THICK	034-13-000002
Work OrderNo	Work Order Date	Period of Extention
NO.EE/AE/WO/251/14-15	21/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
23/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0011	NA	BBMP SCHOOL
SegmentNo	TotalLength	
34/S-W0011/S015747	101.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.M.V.SURESH KUMAR		2082272.80
PhoneNo	EmailId	
9341285087		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING AND ASPHALTING TO ROADS 1ST,2ND, AND 3RD CROSS AND MAIN ROADS IN KHM BLOCK IN WARD NO.34	2095272.8	
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDING AND LAYING SDBC 25MM THICK.	034-13-000002
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/251/2014-15	21/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
2		pushpalatha n. d
Date of Inspection	Remarks	
23/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0009	NA	BBMP SCHOOL
SegmentNo	TotalLength	
34/S-W0009/S020526	106.18	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.M.V.SURESH KUMAR		2093270.00
PhoneNo	EmailId	
9341285087		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING ASPHALTIG TO 1ST, 2ND AND 3RD CROSS AND MAIN ROADS IN KHM BLOCK IN WARD NO.34	2095272.8	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDING AND LAYING SDBC 25MM TH	034-13-000002
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/251/14-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
2		pushpalatha . n. d
Date of Inspection	Remarks	
23/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0007	NA	BBMP SCHOOL
SegmentNo	TotalLength	
34/S-W0007/S021123	110.81	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.M.V.SURESH KUMAR		2093270.00
PhoneNo	EmailId	
9341285087		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING AND ASPHALTING TO 1ST, 2ND AND 3RD CROSS AND MAIN IN KHM BLOCK IN WARD NO.34	2095272.8	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDING AND ASPHALTING SDBC 25MM THICK	034-13-000002
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/251/14-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
23/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0067	13th Crs	Lakshmi devamma block parking side
SegmentNo	TotalLength	
34/S-W0067/S020635	72.44	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.sudhakar Reddy		1900000.00
PhoneNo	EmailId	
9448619840		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing concrete to roads in lakshmi devamma block in ward no.34	1925505.59	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1.Providing and laying 40mm cocnrete to road cut portion.2. Providing ad laying 20mm cocnrete to entire width	034-15-000003
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/307/14-15	26/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
25/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0092	NA	woo67
SegmentNo	TotalLength	
34/S-W0092/S021225	67.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.Sudhakar Reddy		1900000.00
PhoneNo	EmailId	
9448619840		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing concrete to roads in lakshmi devamma block in ward 34	1925505.59	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1.Providing and laying 40mm concret to road cut portion.2. Providing an dlaying 20mm concrete to entire road width	034-15-000003
Work OrderNo	Work Order Date	Period of Extention
No./EE/H/AE/WO/307/14-15	26/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
25/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0059	Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	w0106
SegmentNo	TotalLength	
34/S-W0059/S021712	71.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.sudhakar Reddy		1900000.00
PhoneNo	EmailId	
9448619840		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing concrete to roads in Lakshmi Devamma Block in ward No.34	1925505.55	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1.Providng and laying 40mm concrete to road cut portion.2. Providing and laying 20mm RMC to entire road width.	034-15-000003
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/307/14-15	26/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
25/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0076	NA	Allpine Apartement
SegmentNo	TotalLength	
34/S-W0076/S025134	141.12	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.sudhakar Reddy		1198701.33
PhoneNo	EmailId	
9448619840		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing concrete to main road in dena bank colony in ward no.34	1483742.01	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1.Providing and laying 40mm concrete to Road cut portion 2. Providng and laying 20mm (RMC) to entire road width	034-15-000002
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/306/14-15	26/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
1		pushpalatha n. d
Date of Inspection	Remarks	
25/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0108	Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	V.Anand house
SegmentNo	TotalLength	
34/S-W0108/S030802	230.34	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.V.Babu		1970000.00
PhoneNo	EmailId	
9844663999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 6th, 7th, 8th, 9th and 10th crss in Krishnappa Block in ward 34	1973858.33	14-15
Year	Type of Work	Other Work Type
	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. Providing and Laying WMM.2. Providing and Laying and compacting SDBC	034-14-000002
Work OrderNo	Work Order Date	Period of Extention
No. EE/H/AE/WO/ /14-15	14/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha . d
Date of Inspection	Remarks	
21/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0088	NA	Storm water drain
SegmentNo	TotalLength	
34/S-W0088/S031709	223.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.V.Babu		1970000.00
PhoneNo	EmailId	
9844663999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing and laying Asphalting to 6th, 7th, 8th, 9th and 10th cross in Krishnappa Block in work in ward 34	1973858.33	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1.Providing and laying WMM 2. Providing and laying and rolling SDBC 40mm.	034-14-000002
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/ /14-15	14/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha .d
Date of Inspection	Remarks	
21/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0086	NA	Storm water drain
SegmentNo	TotalLength	
34/S-W0086/S032519	215.39	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.V.babu		1973019.84
PhoneNo	EmailId	
9844663999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 6th, th, 8th, 9th and 10th cross in Krishnappa Block in ward 34	1973858.33	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1.Providing and laying, rolling WMM2. Provding asphaltting SDBC 40mm th	034-14-000002
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/ 14-15	14/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha . d
Date of Inspection	Remarks	
21/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0084	NA	Ftahima Masjid
SegmentNo	TotalLength	
34/S-W0084/S033002	198.33	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.V.Babu		0.00
PhoneNo	EmailId	
9844663999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provding Asphaltting to 6th,7th,8th, 9th and 10th cross Krishnappa Block in ward no.34	1973858.33	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1.Providing and laying WMM 2. Asphaltting the road surface by SDBC 40mm	034-14-000002
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/14-15	14/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
25/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0080	NA	SWD
SegmentNo	TotalLength	
34/S-W0080/S033432	186.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.V.Babu		0.00
PhoneNo	EmailId	
9844663999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting roads 6th,7th,8th, 9th and 10th cross roads of rISHNAPPA Block in ward 34	1973858.33	
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1.Providing and laying WMM 2. Providing and laying SDBC compacted thickness of 25mm	034-14-000002
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE.WO/ 14-15	14/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha . d
Date of Inspection	Remarks	
21/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0101	Om Shakthi Lyt 1st Crs	swd
SegmentNo	TotalLength	
34/S-W0101/S034536	148.29	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.V.Babu		1973019.84
PhoneNo	EmailId	
9844663999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to roads 6th,7th,8th, 9th and 10th cross roads of Krishnappa Block in ward 34	1973858.33	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. Providng and laying WMM2. Providing and laying SDBC of thickness 25mm	034-14-000002
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/ / 14-15	14/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha . d
Date of Inspection	Remarks	
21/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0077	NA	Binny mill road
SegmentNo	TotalLength	
34/S-W0077/S040219	526.63	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.V.Babu		1973019.84
PhoneNo	EmailId	
9844663999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to 1st, 2nd, 3rd main ganganagara extension in ward 34	1536561.32	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1.Providing and laying WMM 2. Providing asphaltting to road surface by SDBC 25mm th	034-14-000002
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/ / 14-15	14/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n.d
Date of Inspection	Remarks	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0079	Om Shakthi Lyt 4th Crs	Binny Mill road
SegmentNo	TotalLength	
34/S-W0079/S040805	541.71	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.V.Babu		1528905.89
PhoneNo	EmailId	
9844663999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting 1st, 2nd, 3rd main Ganganagara Extension in ward 34	1536561.32	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. Providing and laying WMM 2. Providing asphaltting to road surface by SDBC 25mm th	034-14-000003
Work OrderNo	Work Order Date	Period of Extention
No. EE/H/AE/WO/ / 14-15	14/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
21/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0077, W0114, W0075, W0085, W0069, W0083, W0079	NA, Om Shakthi Lyt 4th Crs	GE
SegmentNo	TotalLength	
34/C-W0077/S042721	181.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.V.Babu		1973019.84
PhoneNo	Emailld	
9844663999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 1st2nd,3rd main ganganagara extension in ward 34	1536561.32	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. Providing and laying WMM2. Providing Asphaltting to surface by SDBC by 25mm thNo	034-14-000002
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/ / 14-15	14/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
10		pushpalatha n. d
Date of Inspection	Remarks	
24/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0077, W0075, W0090, W0088, W0085, W0083, W0079	NA, Om Shakthi Lyt 4th Crs	All win school
SegmentNo	TotalLength	
34/C-W0077/S043315	154.29	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.V.Babu		0.00
PhoneNo	EmailId	
9844663999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Apsphalting to 1st, 2nd, 3rd main Ganganagara Extnsion in ward 34	1536561.32	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. Providing and Laying compacting WMM2. Provding asphalting to road surface by SDBC 25mm thick	034-14-000002
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/14-15	14/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
1		pushpalatha n. d
Date of Inspection	Remarks	
25/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0113	3rd Crs	water tank
SegmentNo	TotalLength	
34/S-W0113/S114621	81.50	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri. Venkatesh Narayana Reddy		1433392.72
PhoneNo	EmailId	
9035158247		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
constuction of ssm drain in binny mil road and cross roads in ward no.34	1500000	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	1. construction of ssm drain with rcc slab covering in binny mill road and cros road	034-15-000009
Work OrderNo	Work Order Date	Period of Extention
no.ee/h/ae/wo/268/2014-15	04/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
21/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0112	NA	Kodanda rama swamy temple
SegmentNo	TotalLength	
34/S-W0112/S114753	212.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.V.Babu		1839297.24
PhoneNo	EmailId	
9844663999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 1st, 2nd, 3rd, 4th, 5th main road and cross roads in CPV Block in ward 34	1839297.24	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. Providing and laying WMM2. Providing and laying compacting SDBC 25mm thick	034-14-000012
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/ /14-15	14/01/2015	0
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
10		pushpalatha n. d
Date of Inspection	Remarks	
21/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0124	NA	Ganesha Temple
SegmentNo	TotalLength	
34/S-W0124/S120232	105.59	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.V.Babu		1973019.84
PhoneNo	EmailId	
9844663999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provding and Asphalting and lane painting 1st,2nd,3rd,4th,5th main road and crosses in CPV block in ward 34	1839297.24	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. Provding and laying WMM2. Providing and laying SDBC 25mm thick	034-14-000002
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/ / 14-15	14/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
21/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0085	NA	V.Anand House
SegmentNo	TotalLength	
34/S-W0085/S121655	497.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI. V.BABU		1839297.24
PhoneNo	EmailId	
9844663999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting and lane painting 1st,2nd,3rd,4th,5th main road and crosses in CPV block in ward 34	1839297.24	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. Providing and laying WMM 2. Providing and laying SDBC 25mm thick	034-14-000012
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/ / 14-15	14/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
24/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0082	NA	BURIAL GROUND
SegmentNo	TotalLength	
34/S-W0082/S031514	160.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.SUDHAKAR REDDY	CBS/10289/CIVIL/2010	1848000.00
PhoneNo	EmailId	
9448619840		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING AND CONCRETING TO ROAD AND RCC DRAIN COVERING SLABS 3RD CROSS AND 1ST MAIN IN NRUPATHUNGA BADAVANE	1851344.95	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	1. CONSTRUCTION OF RCC DRAIN WITH RCC COVERING SLABS AND PROVIDING TILE STO LEFT SIDE OF RT NAGARA MAIN ROAD2. DESILTING OF DRAIN (ADJ TO BURAIL GROUND) 3. PROVIDING AND LAYING CC ROAD	034-13-000003
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/54/13-14	02/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha. n. d
Date of Inspection	Remarks	
24/06/2015		

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0031	NA	SWD
SegmentNo	TotalLength	
34/S-W0031/S032127	90.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.SUDHAKAR REDDY	CBS/10289/CIVIL/2010	1848000.00
PhoneNo	EmailId	
9448619840		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING AND CONCRETEING TO ROAD AND RCC DRAIN COVERING SLABS 3RD CROSS AND 1ST MAIN IN NRUPATHUNGA BADAVANE IN WARD 34	1851344.95	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	1. CONSTRUCTION OF RCC DRAIN WITH RCC COVERING SLABS AND PROVIDING TILE STO LEFT SIDE OF RT NAGARA MAIN ROAD2. DESILTING OF DRAIN (ADJ TO BURAIL GROUND) 3. PROVIDING AND LAYING CC ROAD	034-13-000003
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/54/13-14	02/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		pushpalatha n. d
Date of Inspection	Remarks	
24/06/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0079	Om Shakthi Lyt 4th Crs	WARD OFFICE
SegmentNo	TotalLength	
34/S-W0079/S032609	541.71	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.SUDHAKAR REDDY	CBS/10289/CIVIL/2010	932581.00
PhoneNo	EmailId	
9448619840		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVDING AND CONSTRUCTING RCC DRAIN AND COVERING SLABS IN 4TH MAIN ROAD IN GANAGANAGARA EXTENSION IN WARD 34	933041.1	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	1. CONSTRUCTION OF RCC DRAIN WITH RCC SLAB COVERING AND CULVERT. (LEFT AND RIGHT SIDE ONLY 145M)	034-13-000006
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/56/13-14	02/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
20		pushpalatha n. d
Date of Inspection	Remarks	
19/06/2015		

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0125	Veera Anjaneya Temple Rd	MIN DINSH GUNDURAO HOUSE
SegmentNo	TotalLength	
34/S-W0125/S033555	327.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.GANESH M.S		933436.00
PhoneNo	EmailId	
9611042358		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING AND CONSTRUCTING RCC CULVERTS AND IMPROVEMENTS OF DRAINS MAIN ROAD IN MLA LAYOUT IN WARD 34	933436.09	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	1. DESILTING AND CONCRUTION OF SSM DRAIN (DAMAGED PORTION)	034-13-000007
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/208/14-15	27/09/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
19/06/2015		
Category	Photo	
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 34	WardName Gangenahalli
StreetID W0123	StreetName NA	Significant LandMark MIN BOMMAI HOUSE
SegmentNo 34/S-W0123/S034210	TotalLength 137.47	

ContractorDetails		
NameofContractor SRI.GANESH M.S	ContractorRegNo	Expenditure 933436.00
PhoneNo 9611042358	EmailId	

Work Details		
NameOfWork PROVIDING AND CONSTRUCTION OF RCC CULVERTS AND IMPROVEMENTS OF DRAINS MAIN ROADS IN MLA LAYOUT IN WARD 34	Sanctioned Amount 933436	Sanctioned Year 12-13
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails 1. DESILTING OF DRAINS AND CONSTRUCTION OF DRAIN DAMAGED PORTION AND PROVIDING MISSING SLABS.	Job No Work Code 034-13-000007
Work OrderNo NO.EE/H/AE/WO/208/14-15	Work Order Date 27/09/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
5	Name
Date of Inspection	Remarks
19/06/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0121	NA	MIN BOOMAI HOUSE
SegmentNo	TotalLength	
34/S-W0121/S034528	135.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.GANESH M.S		933436.00
PhoneNo	EmailId	
9611042358		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING AND CONSTRUCTING RCC DRAIN CULVERTS AND IMPROVEMENTS OF DRAINS MAIN ROADS IN MLA LAAYOUT IN WARD 34	933436.09	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
	1. DESILTING OF DRAINS AND CONSTRUCTION OF DRAIN DAMAGED PORTION AND PROVIDING MISSING SLABS.	034-13-000007
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/208/14-15	27/09/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha . n.d
Date of Inspection	Remarks	
19/06/2015		

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0109	NA	SWD
SegmentNo	TotalLength	
34/S-W0109/S071424	47.28	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.N.SUDHAKAR REDDY	CBS/10289/CIVIL/2010	942000.00
PhoneNo	EmailId	
9448619840		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING AND CONCRETING ROADS RCC CULVERTS IN MUTHAPPA BLOCK IN WARD NO.34	944881.74	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDING AND LAYING 0MM CONCRETE AND 20MM (RMC) CONCRETE TO ROAD CUT PORTION.2.CONTRUCTION OF RCC CULVERTS WITH RCC DECK SLAB	034-13-000010
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/55/13-14	02/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		pushpalatha n.d
Date of Inspection	Remarks	
19/06/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0116	NA	1ST C MAIN ROAD
SegmentNo	TotalLength	
34/S-W0116/S071914	98.71	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.N.SUDHAKAR REDDY	CBS/10289/CIVIL/2010	942000.00
PhoneNo	EmailId	
9448619840		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING AND CONCRETING ROADS RCC CULVERTS IN MUTHAPPA BLCOK IN WARD 34	944881.74	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDING AND LAYING 40 MM AND 20MM (RMC) CONCRETE TO ROAD CUT PORTION2.0 CONSTRUCTION OF RCC CULVERTS WITH RCC DECK SLABS	034-13-000010
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/55/13-14	02/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
1		pushpalatha n. d
Date of Inspection	Remarks	
24/06/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0138	2nd Crs	GANESHA TEMPLE
SegmentNo	TotalLength	
34/S-W0138/S072349	142.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.N.SUDHAKAR REDDY	CBS/10289/CIVIL/2010	942000.00
PhoneNo	EmailId	
9448619840		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING AND CONSTRUCTION ROADS RCC CULVERTS MUTHAPPA BLOCK IN WARD NO.34	944881.74	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDING AND LAYING 40 MM AND 20MM (RMC) CONCRETE TO ROAD CUT PORTION2.0 CONSTRUCTION OF RCC CULVERTS WITH RCC DECK SLABS	034-13-000010
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/55/13-14	02/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		pushpalatha n. d
Date of Inspection	Remarks	
19/06/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0130	NA	GANESHA TEMPLE
SegmentNo	TotalLength	
34/S-W0130/S072803	169.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.N.SUDHAKAR REDDY	CBS/10289/CIVIL/2010	942000.00
PhoneNo	EmailId	
9448619840		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING AND CONCRETING ROADS RCC CULVERTS IN MUTHAPPA BLOCK IN WARD NO.34	944881.74	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDING AND LAYING 40 MM AND 20MM (RMC) CONCRETE TO ROAD CUT PORTION2.0 CONSTRUCTION OF RCC CULVERTS WITH RCC DECK SLABS	034-13-000010
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/55/13-14	02/08/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/06/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0142	NA	TEMPLE
SegmentNo	TotalLength	
34/S-W0142/S073259	201.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.M.S.GANESH		940000.00
PhoneNo	EmailId	
9611042358		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC CULVERTS AND IMPROVEMENTS OF DRAINS IN GIDAPPA BLOCK AND MUTHAPPA BLOCK IN WARD NO.34	943295.58	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	1. CONSTRUCTION OF RCC DRAIN WITH RCC SLAB COVERING	034-13-000011
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/207/14-15	27/09/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		pushpalatha n. d
Date of Inspection	Remarks	
19/06/2015		
Category	Photo	
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 34	WardName Gangenahalli
StreetID W0038	StreetName NA	Significant LandMark SWD
SegmentNo 34/S-W0038/S090148	TotalLength 61.51	

ContractorDetails		
NameofContractor SRI.M.S.GANESH	ContractorRegNo	Expenditure 940000.00
PhoneNo 9611042358	EmailId	

Work Details		
NameOfWork CONSTRUCTION OF RCC CULVERTS AND IMPROVEMENTS OF DRAINS IN GIDAPPA BLOCK AND MUTHAPPA BLOCK IN WARD NO.34	Sanctioned Amount 943295.58	Sanctioned Year 12-13
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails 1. CONSTRUTCION OF RCC DRAIN WITH RCC COVERING SLABS	Job No Work Code 034-13-000011
Work OrderNo NO.EE/H/AE/WO/207/14-15	Work Order Date 27/09/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		pushpalatha n.d
Date of Inspection	Remarks	
19/06/2015		
Category	Photo	
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 34	WardName Gangenahalli
StreetID W0080	StreetName NA	Significant LandMark SWD
SegmentNo 34/S-W0080/S090552	TotalLength 186.78	

ContractorDetails		
NameofContractor SRI.R.JAGANATH	ContractorRegNo	Expenditure 886142.00
PhoneNo 9844476080	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO DRAINS AND CONSTRUCTION OF RCC CULVERTS IN KRISHNAPPA BLOCK IN WARD NO.34	Sanctioned Amount 8865515.47	Sanctioned Year 12-13
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails 1. DESILTING OF RAINS AND CONSTRUCTION OF RCC CULVERTS WITH RCC DECK SLAB	Job No Work Code 034-13-000012
Work OrderNo NO.EE/H/AE/WO/148/13-14	Work Order Date 31/12/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/06/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0007	NA	BBMP SCHOOL
SegmentNo	TotalLength	
34/S-W0007/S092115	110.81	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.SHASHI KIRAN		970208.73
PhoneNo	EmailId	
9916134545		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC DRAIN AND COVERING SLABS, SHOULDER DRAINS GRILLS IN 3RD MAIN AND CROSS ROADS, KHM BLOCK IN WARD 34	996208.73	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	1. CONSTRUCTION OF RCC DRAIN WITH RCC SLABS. (LEFT SIDE ONLY)	034-12-000026
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/389/2012-13	18/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/06/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0018	NA	BBMP PARK
SegmentNo	TotalLength	
34/S-W0018/S092655	213.41	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.SHASHI KIRAN		970208.73
PhoneNo	EmailId	
9916134545		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC DRAIN AND COVERING SLABS, SHOULDER DRAIN GRILLS IN 3RD MAIN AND CROSS ROADS IN KHM BLCOK IN WARD 34	996208.73	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	1. CONSTRUCTION OF RCC DRAIN WITH RCC COVERING SLABS (LEFT SIDE ONLY)	034-12-000026
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/389/12-13	18/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
19/06/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0013	NA	BBMP PARK
SegmentNo	TotalLength	
34/S-W0013/S093318	239.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.K.SRINIVAS		879000.00
PhoneNo	EmailId	
9844476080		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS OF DRAINS AND RESETING OF COVERING SLABS AND KERB STONES IN KHM BLOCK IN WARD 34	879633.58	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	1. DESILTING OF DRAINS AND CONSTRUCION OF CULVERTS WITH RCC DECK SLAB.	034-13-000013
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/16/13-14	15/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
10	Name
Date of Inspection	Remarks
19/06/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 34	WardName Gangenahalli
StreetID W0018	StreetName NA	Significant LandMark PARK BBMP
SegmentNo 34/S-W0018/S093801	TotalLength 213.41	

ContractorDetails		
NameofContractor SRI.K.SRINIVAS	ContractorRegNo	Expenditure 879000.00
PhoneNo 9844476080	EmailId	

Work Details		
NameOfWork IMPROVEMENTS OF DRAINS AND RESETING OF COVERING SLABS AND KERB STONES IN KHM BLOCK IN WARD NO.34	Sanctioned Amount 879633.58	Sanctioned Year 12-13
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender	WorkDetails 1. DESILTING OF DRAINS AND CONSTRUCION OF CULVERTS WITH RCC DECK SLAB.	Job No Work Code 034-13-000013
Work OrderNo NO.EE/H/AE/WO/16/13-14	Work Order Date 15/06/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
10	Name
Date of Inspection	Remarks
19/06/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0081	14th Crs	EX MIN KRISHNAPPA HOUSE
SegmentNo	TotalLength	
34/S-W0081/S094402	181.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.B.S.GURUBABU		1348655.85
PhoneNo	EmailId	
9448055110		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUTCION OF RCC DRAIN AND COVERING SLABS AND KERB STONE PAITING SHOULDER DRAINS GRILLS IN 4 TH MAIN,5TH MAIN GANAGNAGARA EXTENSION IN WARD 34	1353709.83	10-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	1. CONSTRUCTION OF RCC DRAIN WITH RCC COVERING SLABS AND CULVERT WITH RCC DECK SLAB.	034-12-000028
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/ / 2012-13	26/02/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
10	Name
Date of Inspection	Remarks
24/06/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0099	NA	MUNESHWARA TEMPLE
SegmentNo	TotalLength	
34/S-W0099/S095550	93.23	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.C.RAJU		995000.00
PhoneNo	EmailId	
9448354105		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS OF EXISTING CONCRETE ROADS IN LD BLOCK GANGAPPA BLOCK AND GIDAPPA BLOCK IN WARD 34	996591.5	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PAROVINDING AN DLAYING 40MM AND 20 MM (RMC)	034-13-000015
Work OrderNo	Work Order Date	Period of Extention
NO,EE/H/AE/WO/125/13-14	03/11/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pushpalatha n.d
Date of Inspection	Remarks	
19/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0066	NA	swd
SegmentNo	TotalLength	
34/S-W0066/S102800	78.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.C.RAJU		994000.00
PhoneNo	EmailId	
9448354105		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMNETS OF EXISTING CONCRETE ROADS IN LD BLOCK GANGAPPA BLOCK AND GIDAPPA BLOCK IN WARD NO.34	996591.5	12+13
Year	Type of Work	Other Work Type
2012 - 2013	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. providing and laying 40mm and 20mm (rmc)	034-13-000015
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/125/13-14	03/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		pushpalatha n.d
Date of Inspection	Remarks	
19/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0072	NA	SWD
SegmentNo	TotalLength	
34/S-W0072/S103101	77.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.C.RAJU		994000.00
PhoneNo	EmailId	
9448354105		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMNETS OF EXISTING CONCRETE ROADS IN LD BLOCK GANGAPPA BLOCK AND GIDAPPA BLOCK IN WARD NO.34	996591.05	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDING AN DLAYING 40MM AND 20MM (RMC)	034-13-000015
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/125/13-14	03/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pushpalatha n.d
Date of Inspection	Remarks	
19/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0065	Om Shakthi Lyt 5th Crs	KEMPEGOWDA COLONY
SegmentNo	TotalLength	
34/S-W0065/S103259	88.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.C.RAJU		994000.00
PhoneNo	EmailId	
9448354105		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMNETS OF EXISTING CONCRETE ROADS IN LD BLOCK GANGAPPA BLOCK AND GIDAPPA BLOCK IN WARD NO.34	996591.5	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDING AND LAING 40MM AND 20 MM(RMC)	034-13-000015
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/125/13-14	03/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pushpalatha n.d
Date of Inspection	Remarks	
19/06/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0050	NA	TEMPLE
SegmentNo	TotalLength	
34/S-W0050/S103530	54.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.C.RAJU		994000.00
PhoneNo	EmailId	
9448354105		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMNETS OF EXISTING CONCRETE ROADS IN LD BLOCK GANGAPPA BLOCK AND GIDAPPA BLOCK IN WARD NO.34	996591.5	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDING NA DLAYING 40MM AND 20MM (RMC)	034-13-000015
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/125/13-14	03/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
2		pushpalatha n. d
Date of Inspection	Remarks	
24/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0039	NA	RT NAGAR MAIN ROAD
SegmentNo	TotalLength	
34/S-W0039/S103936	99.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.SANTHOSH KUMAR		0.00
PhoneNo	EmailId	
9845882355		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS OF DRAIN AND LAYING OF COVERING SLAB IN NRUPATHUNGA BADAVANE IN WARD NO.34	1044215.75	10-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	1. CONSTRUCTION OF RCC DRAIN WITH RCC COVERING SLAB	034-12-000025
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/164/2012-13	14/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n.d
Date of Inspection	Remarks	
19/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0095	Om Shakthi Lyt 2nd Crs	KODANDA RAMA SWAMY TEMPLE
SegmentNo	TotalLength	
34/S-W0095/S025643	47.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sHARANAPPA PRABHANAVAR		969225.38
PhoneNo	EmailId	
9448961045		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains in CPV Block in ward 34	988036.44	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	construction of ssm drain and covering with rcc slabs	034-15-000005
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/AO/321/14-15	28/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
02/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0103	NA	kodandaramaswamy temple
SegmentNo	TotalLength	
34/S-W0103/S034701	41.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.Sharanappa Prabhanavar		969225.38
PhoneNo	EmailId	
9448961045		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains in CPV Block in ward 34	988036.44	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	1. constrction of ssm drain and covering with RCC drain	034-15-000005
Work OrderNo	Work Order Date	Period of Extention
no.ee/h/ae/wo/321/14-15	28/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
02/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0112	NA	kodandaramaswamy temple
SegmentNo	TotalLength	
34/S-W0112/S034954	212.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.Sharanappa Prabhanavar		969225.38
PhoneNo	EmailId	
9448961045		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
improvements to drains in CPV Blcok in ward 34	988036.44	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	1. construction of SSM drain in cpv block in ward 34.	034-15-000005
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/321/14-15	28/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
02/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0109	NA	Kondandaramaswamy temple
SegmentNo	TotalLength	
34/S-W0109/S124647	47.28	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri. Sharanappa Prabhanavar		969225.38
PhoneNo	EmailId	
9448961045		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains in CPV Block in ward 34	988036.44	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Others	Construction of drain and Improvements to road
Tender	WorkDetails	Job No Work Code
Tender	1.Covering of open drain with RCC slabs2.Construction of new SSM DRAIN.3.Laying 20 mm (RMC) to damaged road	034-15-000005
Work OrderNo	Work Order Date	Period of Extention
N.EE/H/AE/WO/321/2014-15	28/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
1		pushpalatha n. d
Date of Inspection	Remarks	
25/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0136	NA	Bellary main road
SegmentNo	TotalLength	
34/S-W0136/S011147	628.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri. Venkatesh Narayana Reddy		1433392.72
PhoneNo	EmailId	
9035158247		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of SSM drain in Binny mill road and cross roads in ward 34	1435910.48	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Others	constrcution of New SSM drain
Tender	WorkDetails	Job No Work Code
Tender	1.Construction of SSM drain	034-15-000009
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/268/2014-15	04/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
2		pushpalatha n. d
Date of Inspection	Remarks	
25/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0065	Om Shakthi Lyt 5th Crs	Kempegowda Slum
SegmentNo	TotalLength	
34/S-W0065/S012720	88.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.Sudhakar Reddy		1900000.00
PhoneNo	EmailId	
9448619840		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing concrete to roads in Lakshmi devamma Block in ward no.34	1925505.09	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
Tender	1.Providing and Laying 40mm concrete to road cut portion2. Providing and ;aying 20mm (RMC) to entire road width of the road 3. Floatering the new surface.	034-15-000003
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/307/2014-15	26/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
1		pushpalatha n. d
Date of Inspection	Remarks	
25/06/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0078	NA	Kempegowda Slum
SegmentNo	TotalLength	
34/S-W0078/S013337	142.29	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.sudhakar Reddy		1900000.00
PhoneNo	EmailId	
9448619840		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing concrete to roads in Lakshmi devamma block in ward no.34	1025505.09	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. Provding 40mm concrete to road cut portion.1. Provding and laying 20mm (RMC) concrete to entire road width.	034-15-000003
Work OrderNo	Work Order Date	Period of Extention
No.EE/H/AE/WO/307/14-15	26/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
1		pushpalatha n. d
Date of Inspection	Remarks	
25/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0144	3rd Crs	euro kids
SegmentNo	TotalLength	
34/S-W0144/S053033	151.59	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.ASHOK.G	CBSEI/CIVIL/1258/2015	1458000.00
PhoneNo	EmailId	
9844742550		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Detailed estimate for providing asphaltting and lane painting to 2nd, 3rd,4th mian roads and cross roads in mla layout in ward no.34	1468093.69	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. Providing and laying WMM2. Provosing and laying BM (50mm thick)3.Provosing and laying SDBC (25mm thick)4. Providing with lane painting.	034-14-000006
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/310/14-15	26/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
6		pushpalatha n. d
Date of Inspection	Remarks	
04/09/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0119	NA	pUBLIC TV RAGNATH HOUSE
SegmentNo	TotalLength	
34/S-W0119/S053720	136.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.ASHOK.G	CBSEI/CIVIL/1258/2015	1458000.00
PhoneNo	EmailId	
9844742550		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DETAILED ESTIMATION FOR PROVIDING ASPHALTING AND LANE PAITING TO 2ND,3RD,4TH AMIN ROAD AND CROSS ROADS IN MLA LAYOUT IN WARD NO.34	1468093.69	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. Providing and laying WMM2. Provosing and laying BM (50mm thick)3.Provosing and laying SDBC (25mm thick)4. Providing with lane painting.	034-14-000006
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/310/14-15	26/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
8	Name
Date of Inspection	Remarks
04/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0121	NA	MLA LAYOUT
SegmentNo	TotalLength	
34/S-W0121/S053952	135.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.ASHOK.G	CBSEI/CIVIL/1258/2015	1458000.00
PhoneNo	EmailId	
9844742550		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DETAILED ESTIMATION FOR PROVIDING ASPHALTING AND LANE PAIING TO 2ND,3RD, 4TH MAIN ROADS AND CROSS ROADS IN MLA LAYOUT IN WARD NO.34	1468093.69	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. Providing and laying WMM2. Provosing and laying BM (50mm thick)3.Provosing and laying SDBC (25mm thick)4. Providing with lane painting.	034-14-000006
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/310/14-15	26/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
6		pushpalatha n. d
Date of Inspection	Remarks	
04/09/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0123	NA	MLA LAYOUT
SegmentNo	TotalLength	
34/S-W0123/S054201	137.47	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.ASHOK.G	CBSEI/CIVIL/1258/2015	1458000.00
PhoneNo	EmailId	
9844742550		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DETAILED ESTIMATION FOR PROVIDNG ASPHALTING AND LANE PAITING TO 2ND,3RD,4TH MAIN ROADS AND CROSS ROADS IN MLA LAYOUT IN WARD NO.34	1468093.69	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. Providing and laying WMM2. Provosing and laying BM (50mm thick)3.Provosing and laying SDBC (25mm thick)4. Providing with lane painting.	034-14-000006
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/310/14-15	26/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
6		pushpalatha n. d
Date of Inspection	Remarks	
04/09/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0114	NA	RT NAGARA MAIN ROAD
SegmentNo	TotalLength	
34/S-W0114/S054414	589.89	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.ASHOK.G	CBSEI/CIVIL/1258/2015	1458000.00
PhoneNo	EmailId	
9844742550		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DETAILED ESTIMATION FOR PROVIDING ASPHALTING AND LANE PAITING TO 2ND,3RD, 4TH MAIN ROADS AND CROSS ROADS IN MLA LAYOUT IN WARD NO.34	1468093.69	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDING AND LAYING WMM2. PROVIDING AND LAYING BM (50MM THICK)3. PROVIDING AND LAYING SDBC (25MM THIVK)4. PROVIDING LANE PAINTING	034-14-000006
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/310/14-15	26/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
04/09/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0075	NA	ALL WIN PUBLIC SCHOOL
SegmentNo	TotalLength	
34/S-W0075/S055355	458.22	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.ASHOK G	CBSEI/CIVIL1258/2015	1948000.00
PhoneNo	EmailId	
9844742550		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DETAILED ESTIMATION FOR PROVIDING ASPHALTING AND LANE PAITING BEHIND BINNY MILL ROAD 1ST A,B,C,D,F ROADS IN WARD NO.34	1951626.49	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1.PROVIDING AND LAYING WMM2. PROVIDING AND LAYING BM 3. PROVIDING AND LAYING SDBC (25MM THICK)4. PROVIDING LANE PAITING	034-14-000010
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/309/14-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
9	Name
Date of Inspection	Remarks
04/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0063	Om Shakthi Lyt 6th Crs	SREE VANI SCHOOL
SegmentNo	TotalLength	
34/S-W0063/S060201	114.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.ASHOK.G	CBSEI/CIVIL/1258/2015	1948000.00
PhoneNo	EmailId	
9844742550		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DETAILED ESTIMAT EFOR PROVIDING ASPHALTING AND LAE PAITING TO 1ST, A,B,C,F ROAD IN WARD NO.34	1951626.49	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1.PROVIDING AND LAYING WMM2. PROVIDING AND LAYING BM 3. PROVIDING AND LAYING SDBC (25MM THICK)4. PROVIDING LANE PAITING	034-14-000010
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/309/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
1		pushpalatha n. d
Date of Inspection	Remarks	
04/09/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0134	1st Crs	SREE VANI SCHOOL
SegmentNo	TotalLength	
34/S-W0134/S060524	45.93	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.ASHOK.G	CBSEI/CIVIL/1258/2015	1948000.00
PhoneNo	EmailId	
9844742550		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DETAILED ESTIMATION FOR PROVIDING ASPHALTING AND LANE PAITING BEHIND BINNY MILL ROAD 1ST A, B, C, D, F ROAD IN WARD NO.34	1951626.49	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1.PROVIDING AND LAYING WMM2. PROVIDING AND LAYING BM 3. PROVIDING AND LAYING SDBC (25MM THICK)4. PROVIDING LANE PAITING	034-14-000010
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/309/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
3	Name
Date of Inspection	Remarks
04/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0061	Om Shakthi Lyt 7th Crs	SREE VANI SCHOOL
SegmentNo	TotalLength	
34/S-W0061/S060733	139.75	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.ASHOK G	CBSEI/CIVIL1258/2015	1948000.00
PhoneNo	EmailId	
9844742550		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DETAILED ESTIMATION FOR PROVIDING ASPHALTING AND LANE PAITINGBEHIMD BINNY MILL ROAD 1ST A,B,C,D,F ROADS IN WARD NO.34	1951626.49	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1.PROVIDING AND LAYING WMM2. PROVIDING AND LAYING BM 3. PROVIDING AND LAYING SDBC (25MM THICK)4. PROVIDING LANE PAITING	034-14-000010
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/309/14-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0132	NA	EX MIN MUMTAZ ALI KHAN HOUSE
SegmentNo	TotalLength	
34/S-W0132/S060957	40.68	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.ASHOK G	CBSEI/CIVIL1258/2015	1948000.00
PhoneNo	EmailId	
9844742550		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DETAILE DESTIMATE FOR PROVIDING ASPHALTING AND LANE PAINTING BEHIND BINNY MILL ROAD 1ST A,B,C,D, F ROADS IN WARD NO.34	1951626.49	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1.PROVIDING AND LAYING WMM2. PROVIDING AND LAYING BM 3. PROVIDING AND LAYING SDBC (25MM THICK)4. PROVIDING LANE PAITING	034-14-000010
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/309/14-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha n. d
Date of Inspection	Remarks	
04/09/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0118	NA	SREE VANI SCHOOL
SegmentNo	TotalLength	
34/S-W0118/S061229	80.81	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.ASHOK G	CBSEI/CIVIL1258/2015	1948000.00
PhoneNo	EmailId	
9844742550		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DETAILED ESTIMATE FOR PROVIDING ASPHALTING AND LANE PAITING TO ROADS BEHINF BINNY MILL 1ST A,B,C,D,F ROAD IN WARD 34	1951626.49	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1.PROVIDING AND LAYING WMM2. PROVIDING AND LAYING BM 3. PROVIDING AND LAYING SDBC (25MM THICK)4. PROVIDING LANE PAITING	034-14-000010
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/309/14-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet


Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0110	NA	SREE VANI SCHOOL
SegmentNo	TotalLength	
34/S-W0110/S061553	103.29	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.ASHOK G	CBSEI/CIVIL1258/2015	1948000.00
PhoneNo	EmailId	
9844742550		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DETAILED ESTIMATION FR ROVIDING ASPHALTING AND LANE PAITIG TO ROADS BEHIND BINNY MILL 1ST A,B,C,D,F ROAD IN WARD NO.34	1951626.49	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1.PROVIDING AND LAYING WMM2. PROVIDING AND LAYING BM 3. PROVIDING AND LAYING SDBC (25MM THICK)4. PROVIDING LANE PAITING	034-14-000010
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/309/14-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		pushpalatha n. d
Date of Inspection	Remarks	
04/09/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0057	NA	SREE VANI SCHOOL
SegmentNo	TotalLength	
34/S-W0057/S061818	457.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.ASHOK.G	CBSEI/CIVIL/1258/2015	1948000.00
PhoneNo	EmailId	
9844742550		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DETAILED ESTIMATION FOR PROVIDING ASPHALTING AND LANE PAINTING BEHIND BINNY MILL ROAD 1ST, A,B,C,D F MAIN ROADS IN WARD NO.34	1951626.49	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1.PROVIDING AND LAYING WMM2. PROVIDING AND LAYING BM 3. PROVIDING AND LAYING SDBC (25MM THICK)4. PROVIDING LANE PAITING	034-14-000010
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/WO/309/14-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
10		pushpalatha n. d
Date of Inspection	Remarks	
04/09/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0017	NA	MASJID
SegmentNo	TotalLength	
34/S-W0017/S045733	194.08	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI SAI CONSTRUCTIONS		2040000.00
PhoneNo	EmailId	
9845567111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING ASPHALTING AND LANE PSITING AT 2ND AND 3RD CROSS IN GANGAPPA BLOCK IN WARD 34	2044215.91	12-13
Year	Type of Work	Other Work Type
2012 - 2013	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDING APHALTING BD 40MM THICK	034-12-000017
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/112/2012-13	16/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
15		pushpalatha n.d
Date of Inspection	Remarks	
19/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0045	NA	market
SegmentNo	TotalLength	
34/S-W0045/S075649	114.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.V.BABU		1876014.60
PhoneNo	EmailId	
9844636669		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to roads in dena bank colony in ward no.34	1880014.6	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. Providing and laying SDBC 25mm thick	034-15-000001
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/03/15-16	10/04/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha.n.d
Date of Inspection	Remarks	
05/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0043	NA	Karnataka choultry
SegmentNo	TotalLength	
34/S-W0043/S080121	277.76	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.V.BABU		1876014.60
PhoneNo	EmailId	
9844636669		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
providing and asphalting to roads in dena bank colony in ward no.34	1880014.6	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. providig and laying SDBC 25mm thick .	034-15-000001
Work OrderNo	Work Order Date	Period of Extention
no.ee/h/ae/wo/03/15-16	10/04/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		pushpalatha.n.d
Date of Inspection	Remarks	
05/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0102	NA	shell petrol bunk
SegmentNo	TotalLength	
34/S-W0102/S080415	74.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.V.BABU		1876014.60
PhoneNo	EmailId	
9844636669		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
providing asphaltting to roads in dena bank colony in ward no.34	1880014.6	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. providing and laying SDBC 25mm thick	034-15-000001
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/03/15-16	10/04/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
2		pushpalatha.n.d
Date of Inspection	Remarks	
05/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	34	Gangenahalli
StreetID	StreetName	Significant LandMark
W0082	NA	BURIAL GROUND
SegmentNo	TotalLength	
34/S-W0082/S080719	160.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.V.BABU		1876014.60
PhoneNo	EmailId	
9844636669		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING ASPHALTING TO ROADS IN DENA BANK COLONY IN WARD NO.34	1880014.6	14-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender	1. PROVIDING AND LAYING SDBC 25MM THICK	034-15-000001
Work OrderNo	Work Order Date	Period of Extention
NO.EE/H/AE/WO/03/15-16	10/04/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
2		pushpalatha.n.d
Date of Inspection	Remarks	
05/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	