



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0020	15th Crs	11TH MAIN
SegmentNo	TotalLength	
65/S-W0020/S45893	270.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.H.PURUSHOTHAM		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
ROAD WIDENING & ASPHALTING TO IMPTS TO DRAIN & F/P AT 15TH CROSS N/S FROM 11TH MAIN MES COLLEGE TO 8TH MAIN CH:0.00 TO 270MTRS	4990000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
		004-09-IGER-IM-004
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
20		parashuram
Date of Inspection	Remarks	
16/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0020	15th Crs	8TH MAIN
SegmentNo	TotalLength	
65/S-W0020/S45896	270.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NARAYANA CONSTRUCTION		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
ROAD WIDENING ASPHALTING IMPTS TO DRAIN & F/P AT 15TH CROSS N/S FROM 8TH MAIN TO 6TH MAIN MLM CH:270.00 TO 540.00MTRS	4990000	2009
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
		004-09-IGER-IM-009
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
15		parashuram
Date of Inspection	Remarks	
16/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0020	15th Crs	6th main
SegmentNo	TotalLength	
65/S-W0020/S45899	270.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
L.N.PRABHU		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
ROAD WIDENING ASPHALTING TO IMPTS DRAIN & F/P AT 15TH CROSS N/S FROM 6TH MAIN MARGOSA ROAD MLM CH:540.00 TO 810.00MTRS	4990000	2010
Year	Type of Work	Other Work Type
2009 - 2010	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
		004-09-IGER-IM-005
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
12		parashuram
Date of Inspection	Remarks	
16/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0239	10th Main Vyalikaval	12th B cross
SegmentNo	TotalLength	
65/S-W0239/S054125	33.76	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Jairam		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to 12th B cross, 12th C cross and 13th Cross road in vyalikaval in ward No.5	4113575	2009-10
Year	Type of Work	Other Work Type
2009 - 2010	Road	
Tender	WorkDetails	Job No Work Code
Tender		005-09-M-E-E-R-IM-003
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sushma
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0004	12th Crs	12th Cross
SegmentNo	TotalLength	
65/S-W0004/S064603	511.48	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Munirathna		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphlting to 12th Cross of road of Vyalikaval in ward No.5	3159317	
Year	Type of Work	Other Work Type
2009 - 2010	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		032-10-N-G-E-R-AS-008
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sushma
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0209	3rd Temple Rd	Kodandarampura
SegmentNo	TotalLength	
65/S-W0209/S065229	12.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Munirathna		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphlting to Kodandarampura roads and temple roads in ward No.5	3018009	
Year	Type of Work	Other Work Type
2009 - 2010	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		032-10-N-G-E-R-AS-002
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sushma
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0263	NA	2nd Main
SegmentNo	TotalLength	
65/S-W0263/S071548	77.11	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P. Hemanth		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impt to Footpath and Drain in 2nd Main of Vyalikaval road from 11th Cross to 16th Cross from Ch:85 to 170mtrs in ward No.5	1068341	
Year	Type of Work	Other Work Type
2009 - 2010	Others	Improvements Footpath and Drain
Tender	WorkDetails	Job No Work Code
Tender		032-10-M-G-E-D-IM-025
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sushma
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 65	WardName Kadu Malleshwara Ward
StreetID W0006	StreetName Pipeline Rd	Significant LandMark SIDDASHRAMA
SegmentNo 65/S-W0006/S42303	TotalLength 300.00	

ContractorDetails		
NameofContractor C.K.ANAND	ContractorRegNo	Expenditure 0.00
PhoneNo	EmailId	

Work Details		
NameOfWork PROVIDING SSM DRAIN AT RANGANATHPURA IN WARD NO.35	Sanctioned Amount 2500000	Sanctioned Year 2008
Year 2010 - 2011	Type of Work Drain Maintenance	Other Work Type
Tender	WorkDetails	Job No Work Code 099-09-NGED-FO-005
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 2	Other Information	Name keshavmurthy
Date of Inspection 17/12/2014	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0025	1st Main Rd Gdp Extn	SIDDASHRAMA
SegmentNo	TotalLength	
65/S-W0025/S41942	60.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K.ANAND		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING SSM DRAIN AT RANGANATHPURA IN WARD NO.35	2500000	2008
Year	Type of Work	Other Work Type
2010 - 2011	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
		099-09-NGED-EO-005
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		keshavmurthy
Date of Inspection	Remarks	
17/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0282	6th Crs	BJP office
SegmentNo	TotalLength	
65/S-W0282/S035814	277.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9843161122		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Removal debries near old BJP office & Venkatrangapura	1000000	
Year	Type of Work	Other Work Type
2013 - 2014	Others	Debries
Tender	WorkDetails	Job No Work Code
Tender		065-14-000007
Work OrderNo	Work Order Date	Period of Extention
060		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
7		k.s.sushma
Date of Inspection	Remarks	
19/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 65	WardName Kadu Malleshwara Ward
StreetID W0242	StreetName 8th Crs	Significant LandMark Sampige road
SegmentNo 65/S-W0242/S041250	TotalLength 708.66	

ContractorDetails		
NameofContractor J.H. Rudrappa	ContractorRegNo	Expenditure 0.00
PhoneNo 9845202792	EmailId	

Work Details		
NameOfWork Impts to Drain & Footpath of 8th cross roads from Smpige road to Margosa road	Sanctioned Amount 2000000	Sanctioned Year
Year 2012 - 2013	Type of Work Others	Other Work Type Drain & Footpath
Tender Tender	WorkDetails	Job No Work Code 065-12-000045
Work OrderNo 145/12-13	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 2	Other Information	Name k.s.sushma
Date of Inspection 20/12/2014	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0013	NA	Ward Jurisdiction
SegmentNo	TotalLength	
65/S-W0013/S041723	98.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B.S. Dhananjaya		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Cement pavement to damaged conservancy roads	2000000	
Year	Type of Work	Other Work Type
2012 - 2013	Others	Cement pavement
Tender	WorkDetails	Job No Work Code
Tender		065-12-000051
Work OrderNo	Work Order Date	Period of Extention
303/12-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
20/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0123	8th Main Rd	7th Cross
SegmentNo	TotalLength	
65/S-W0123/S042027	816.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.S. bharath		0.00
PhoneNo	EmailId	
9686200428		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Filling of potholes, wornout portion, & Road cut portion @ MLM b/w 7th to 15th Cross	200000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		065-12-000040
Work OrderNo	Work Order Date	Period of Extention
75/12-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
23/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0092	NA	Gayathrinagara
SegmentNo	TotalLength	
65/S-W0092/S042344	83.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.S. Bharath		0.00
PhoneNo	EmailId	
9686200428		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Filling of potholes, wornout portion, & Road cut portion @ Gayathrinagara & Subramanyanagara	200000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		065-12-000038
Work OrderNo	Work Order Date	Period of Extention
099/12-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
22/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0302	NA	Vyalikaval
SegmentNo	TotalLength	
65/S-W0302/S042728	28.26	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.S. Bharath		0.00
PhoneNo	EmailId	
9686200428		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Filling of potholes, wornout portion, & Road cut portion @ Vyalikaval area	200000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		065-12-000041
Work OrderNo	Work Order Date	Period of Extention
82/12-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
23/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 65	WardName Kadu Malleshwara Ward
StreetID W0209	StreetName 3rd Temple Rd	Significant LandMark Kodandarampura
SegmentNo 65/S-W0209/S042856	TotalLength 58.11	

ContractorDetails		
NameofContractor Bharath	ContractorRegNo	Expenditure 0.00
PhoneNo 9686200428	EmailId	

Work Details		
NameOfWork Filling of potholes, wornout portion, & Road cut portion @ Kodanrampura area	Sanctioned Amount 200000	Sanctioned Year
Year 2012 - 2013	Type of Work Asphalting	Other Work Type
Tender Tender	WorkDetails	Job No Work Code 065-12-000039
Work OrderNo 86/12-13	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name k.s.sushma
Date of Inspection 23/12/2014	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0032	2nd Crs	gayathrinagar
SegmentNo	TotalLength	
65/S-W0032/S043214	167.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9843161122		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to bad reaches in Gayathrinagara	2000000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		065-13-000030
Work OrderNo	Work Order Date	Period of Extention
416/12-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
22/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0020	15th Crs	Sampige road
SegmentNo	TotalLength	
65/S-W0020/S043429	1759.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9843161122		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 15th cross from Sampige road road to 6th main	5000000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		065-13-000015
Work OrderNo	Work Order Date	Period of Extention
382/12-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
47		k.s.sushma
Date of Inspection	Remarks	
19/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0026	5th Crs	Law college
SegmentNo	TotalLength	
65/S-W0026/S043853	161.11	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Jai maruthi Constructio		0.00
PhoneNo	Emailld	
9900022110		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to Drain & F/P to 5th C block Vivekananda law college	2000000	
Year	Type of Work	Other Work Type
2012 - 2013	Others	Drain & F/P
Tender	WorkDetails	Job No Work Code
Tender		065-12-000045
Work OrderNo	Work Order Date	Period of Extention
182/12-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		k.s.sushma
Date of Inspection	Remarks	
20/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0230	9th Crs	11th Main
SegmentNo	TotalLength	
65/S-W0230/S044613	624.80	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.S. Sidde gowda		0.00
PhoneNo	EmailId	
9844643692		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing modern F/P to 9th cross from 11th main to West park road from Ch:440 to 550	2000000	
Year	Type of Work	Other Work Type
2011 - 2012	Others	Footpath
Tender	WorkDetails	Job No Work Code
Tender		065-11-000037
Work OrderNo	Work Order Date	Period of Extention
230/11-12		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
22/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0166	NA	11th Cross
SegmentNo	TotalLength	
65/S-W0166/S075423	855.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B.S. DHANAJAYA		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING ASPHALTING 10, 11TH CROSS AND SURROUNDING AREA IN WARD NO.65	2000000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		065-15-000021
Work OrderNo	Work Order Date	Period of Extention
EE/MLM/AE/WO/112/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sushma. K. S
Date of Inspection	Remarks	
08/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
I0004	NA	kabaddi ground
SegmentNo	TotalLength	
65/S-I0004/S075629	497.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER (WEST) KRIDL		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING ASPHALTING TO BALANCE ROADS IN VYALIKAVAL AND GAYATHRINGARA IN WARD NO.65	2000000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
		065-15-000023
Work OrderNo	Work Order Date	Period of Extention
EE/MLM/AE/WO/110/2014-15	20/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sushma. K.S
Date of Inspection	Remarks	
08/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0326	1st Crs	AYYAPPA TEMPLE
SegmentNo	TotalLength	
65/S-W0326/S075930	239.76	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER (WEST) KRIDL		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING ASPHALTING 12, 13 AND 14TH CROSS MALLESHWARAM AND SURROUNDING AREA IN WARD NO.65	2000000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		065-15-000022
Work OrderNo	Work Order Date	Period of Extention
EE/MLM/AE/WO/111/2014-15	20/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sushma.K.S
Date of Inspection	Remarks	
08/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0116	NA	14TH CROSS
SegmentNo	TotalLength	
65/S-W0116/S080240	215.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER (WEST) KRIDL		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CC TO DAMAGED ROAD AND IMPROVEMENTS DRAIN AND FOOTPATH 14TH A CROSS AND 14TH CROSS AND SURROUDING AREA IN WARD NO.65	2000000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
		065-15-000024
Work OrderNo	Work Order Date	Period of Extention
EE/MLM/AE/WO/109/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
08/11/2016	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0166	NA	11TH CROSS
SegmentNo	TotalLength	
65/S-W0166/S080725	855.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER (WEST) KRIDL		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Maintenance of footpath like desilting, painting to kerbs & Replacing of broken slabs 11th cross malleshwaram from sampige road to 6th main & Surro	1000000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		065-15-000031
Work OrderNo	Work Order Date	Period of Extention
EE/MLM/AE/WO/1069/2014-15	20/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma. K. S
Date of Inspection	Remarks	
08/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0024	NA	3rd cross
SegmentNo	TotalLength	
65/S-W0024/S081504	133.68	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B.S. DHANAJAYA		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AND FOOTPATH AT 3RD CROSS SUBRAMANYANAGARA B BLOCK AND SURROUNDING AREA IN WARD NO.65	2000000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Footpath Layering	
Tender	WorkDetails	Job No Work Code
Tender		065-15-000011
Work OrderNo	Work Order Date	Period of Extention
EE/MLM/AE/WO/115/2014-15	26/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma. K. S
Date of Inspection	Remarks	
08/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0242	NA	8TH CROSS
SegmentNo	TotalLength	
65/S-W0242/S082058	708.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER (WEST) KRIDL		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING ASPHALTING 7TH AND 8TH MALLESHWARAM AND SURROUNDING AREA IN WARD NO.65	2000000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		065-15-000020
Work OrderNo	Work Order Date	Period of Extention
EE/MLM/AE/WO/113/2014-15	20/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma. K.S
Date of Inspection	Remarks	
08/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
I0020	NA	CHOWDAIAH HALL
SegmentNo	TotalLength	
65/S-I0020/S082405	1759.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER (WEST) KRIDL		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Maintenance of footpath like desilting, painting to kerbs & Replacing of broken slabs at temple street & Surrounding area in ward No.65	1000000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		065-15-000026
Work OrderNo	Work Order Date	Period of Extention
EE/MLM/AE/WO/107/2014-15	20/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma. K. S
Date of Inspection	Remarks	
08/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0300	4th Crs Lakshmi Sagar Lyt	GD PARK
SegmentNo	TotalLength	
65/S-W0300/S082835	242.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER (WEST) KRIDL		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Maintenance of footpath like desilting, painting to kerbs & Replacing of broken slabs @ GD PARK EXTN & Surrounding area in ward No.65	1000000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	065-15-000025
Work OrderNo	Work Order Date	Period of Extention
EE/MLM/AE/WO/101/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma. K. S
Date of Inspection	Remarks	
08/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0193	Vinayaka Lyt 2nd Crs	BEHIND LIBRARY
SegmentNo	TotalLength	
65/S-W0193/S114152	786.50	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER (WEST)		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
REMOVING OF TREE ROOTS AND RESTORING THE FOOTPATH AT WARD JURIDCTION IN WARD NO.65	500000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Footpath Layering	
Tender	WorkDetails	Job No Work Code
Tender		065-15-000027
Work OrderNo	Work Order Date	Period of Extention
EE/MLM/AE/WO/102/2014-15	20/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma
Date of Inspection	Remarks	
09/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0261	NA	9TH MAIN
SegmentNo	TotalLength	
65/S-W0261/S114610	272.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER (WEST)		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Maintenance of footpath like desilting, painting to kerbs & Replacing of broken slabs @ 9TH main , Vyalikaval, From 14th Cross To 16th Cross & Sur	500000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Resurfacing	
Tender	WorkDetails	Job No Work Code
Tender		065-15-000030
Work OrderNo	Work Order Date	Period of Extention
EE/MLM/AE/WO/105/2014-15	20/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma
Date of Inspection	Remarks	
09/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
I0020	NA	13TH B CROSS
SegmentNo	TotalLength	
65/S-I0020/S115058	1759.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B.S. DHANAJAYA		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AND FOOTPATH AT 13TH B CROSS FROM 10TH MAIN TO AYYAPPA TEMPLE AND SURROUNDING AREA IN WARD NO.65	2000000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Others	DRAIN AND FOOTPATH
Tender	WorkDetails	Job No Work Code
Tender		065-15-000010
Work OrderNo	Work Order Date	Period of Extention
EE/MLM/AE/WO/119/2014-15	26/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma
Date of Inspection	Remarks	
09/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0004, W0010, W0008, W0006, W0015, W0016	12th Crs, 11th Crs, NA, 1st Main Rd Malleshwara(temple Rd)	Kabaddi Ground
SegmentNo	TotalLength	
65/C-W0004/S110039	89.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.V. Subramani		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and footpath at 2nd Temple Road from Kabadi ground to 10th Cross& Surrounding area in ward No.64	1376848	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Others	footpath & Drain
Tender	WorkDetails	Job No Work Code
Tender		064-14-000022
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
15		jayashankar
Date of Inspection	Remarks	
23/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Footpath Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0261	3rd Main Rd Vyalikaval	3rd Main
SegmentNo	TotalLength	
65/S-W0261/S010523	59.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G.K. Jayaram		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain & Footpath of 13th Cross to 15th Cross of 3rd Main Vyalikaval in ward No.65	1957408	2012-13
Year	Type of Work	Other Work Type
2013 - 2014	Others	Footpath & Drain
Tender	WorkDetails	Job No Work Code
Tender		065-12-000093
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
18		k.s.sushma
Date of Inspection	Remarks	
20/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0161, W0041, W0043, W0055, W0040, W0031, W0096, W	Tha Ra Su Rd Gayatri Nagar, B Block, NA, 1st Crs, 1st Crs C Block, 6th C Main C Block, 12th Crs, 6t	Subramnyanagara and Gayathrinagara
SegmentNo	TotalLength	
65/C-W0161/S011831	302.59	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S. Anil Kumar		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Maintenance of footpath like desilting to kerbs & replacing of broken slabs @ Gayathrinagara in ward No.65	498482.37	2012-13
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
		065-12-000047
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		k.s.sushma
Date of Inspection	Remarks	
20/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0004	12th Crs	Kodandarampura School
SegmentNo	TotalLength	
65/S-W0004/S012558	511.48	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Maruthi Engineering		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain and Footpath of 12th Cross from Kodandarampura School to 6th Main in ward No.65	1991953	2012-13
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
		065-12-000043
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
20		k.s.sushma
Date of Inspection	Remarks	
19/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0304	14th Crs	Rammandira
SegmentNo	TotalLength	
65/S-W0304/S013051	327.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
H.S. Chaluve Gowda		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to footpath & Drain of 14th Cross 9th Mian Rammandira to 2nd Main in ward No.65	1990161	2012-13
Year	Type of Work	Other Work Type
2013 - 2014	Others	Footpath and Drain
Tender	WorkDetails	Job No Work Code
		065-12-000080
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
20/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0304	14th Crs	Rammandir
SegmentNo	TotalLength	
65/S-W0304/S013558	327.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.C. Chandra Shekar		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to footpath & Drain of 14th Cross 9th main Rammandira to 2nd Main Northern side in ward No.65	1992080.1	2012-13
Year	Type of Work	Other Work Type
2013 - 2014	Others	Footpath & Drain
Tender	WorkDetails	Job No Work Code
Tender		065-12-00078
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
20/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0304	14th Crs	Rammandir
SegmentNo	TotalLength	
65/S-W0304/S013727	327.95	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.S. Sidde Gowda		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to footpath & Drain of 14th Cross 9th main Rammandira to 2nd Main Southern side Ch:149 to 298in ward No.65	1989893.51	2012-13
Year	Type of Work	Other Work Type
2013 - 2014	Others	Footpath and Drain
Tender	WorkDetails	Job No Work Code
Tender		065-12-000081
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
8		k.s.sushma
Date of Inspection	Remarks	
20/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0304	14th Crs	Rammandira
SegmentNo	TotalLength	
65/S-W0304/S014211	327.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K. Anand		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to footpath & Drain of 14th Cross from 9th Main rammandira to 2nd Main Southern Side 149 to 298 in w No.65	1991334.1	2012-13
Year	Type of Work	Other Work Type
2013 - 2014	Others	Footpath & Drain
Tender	WorkDetails	Job No Work Code
Tender		065-12-000079
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
7		k.s.sushma
Date of Inspection	Remarks	
20/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0161	Tha Ra Su Rd Gayatri Nagar, B Block	gayathringara
SegmentNo	TotalLength	
65/S-W0161/S041952	124.27	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Dinesh		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
filling of potholes, wornout roads & road cut portion @ Gayathrinagara & Subramanyanagara in ward No.66	209486.42	2012-13
Year	Type of Work	Other Work Type
2013 - 2014	Pothole filling	
Tender	WorkDetails	Job No Work Code
Tender		066-12-000030
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		devaraj
Date of Inspection	Remarks	
25/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0268	7th Crs	Sampige Road
SegmentNo	TotalLength	
65/S-W0268/S094810	455.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. vijaya Kumar		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain & Footpath @ 7th Cross from Sampige road to Margosa road in ward No.65	2078569.06	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & Drain
Tender	WorkDetails	Job No Work Code
Tender		065-12-000025
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
22/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0282	6th Crs	Railway parallel road
SegmentNo	TotalLength	
65/S-W0282/S095027	283.91	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K. Anand		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain & Footpath @ 6th Cross from 11th Main to 4th Main of South Side in ward No.65	2091836.22	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & Drain
Tender	WorkDetails	Job No Work Code
		065-12-000027
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
22/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0282	6th Crs	Railway Parallel
SegmentNo	TotalLength	
65/S-W0282/S095250	283.91	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K. Anand		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain & Footpath @ 6th Cross from 11th Main to 4th Main of North Side in ward No.65	2089532.85	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & Drain
Tender	WorkDetails	Job No Work Code
Tender		065-12-000027
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
22/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0030	3rd Crs	Gayathrinagara
SegmentNo	TotalLength	
65/S-W0030/S095541	164.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K. Anand		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain & Footpath @ 3rd Cross Gayathrinagara C block in ward No.65	2082357	2011-12
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & Drain
Tender	WorkDetails	Job No Work Code
Tender		065-11-000040
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		m.j. yogesh
Date of Inspection	Remarks	
18/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0268	7th Crs	Railway Parallel Road
SegmentNo	TotalLength	
65/S-W0268/S095947	455.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K. Anand		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain & Footpath @ 7th Cross from Sampige road to Margosa road Northern Side in ward No.65	2095812.81	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & drain
Tender	WorkDetails	Job No Work Code
Tender		065-12-000024
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
23/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0128	13th Crs	Gangamma temple
SegmentNo	TotalLength	
65/S-W0128/S100349	1133.60	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K. Anand		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain & Footpath From Gangamma temple to 13th Cross in ward No.65	2096801.87	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P 7 Drain
Tender	WorkDetails	Job No Work Code
Tender		065-12-000028
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
22/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0030	3rd Crs	Rajkumar Statue
SegmentNo	TotalLength	
65/S-W0030/S100552	164.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
H.S. Chaluve Gowda		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Repairs to F/P of 1st Main Eastern side from Rajkumar Statue to 3rd Cross gayathrinagara in ward No.65	524386	2011-12
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & Drain
Tender	WorkDetails	Job No Work Code
Tender		065-11-000018
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		m.j. yogesh
Date of Inspection	Remarks	
18/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0230	9th Crs	West Park
SegmentNo	TotalLength	
65/S-W0230/S101737	642.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.S. Raju		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Modern F/P to 9th Cross road from 11th Main to West Park Road from North Ch:110 to 220mtrs in ward No.65	2074646.02	2011-12
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & Drain
Tender	WorkDetails	Job No Work Code
Tender		065-11-000029
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		H.R.Giridhar
Date of Inspection	Remarks	
19/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0230	9th Crs	West Park road
SegmentNo	TotalLength	
65/S-W0230/S102029	642.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.S. Raju		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Modern F/P to 9th Cross road from 11th Main to West Park Road from North Ch:0.00 to 110.00mtrs in ward No.65	2074646.02	2011-12
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & Drain
Tender	WorkDetails	Job No Work Code
Tender		065-11-000028
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		H.R.Giridhar
Date of Inspection	Remarks	
19/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0230	9th Crs	West Park road
SegmentNo	TotalLength	
65/S-W0230/S102224	642.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.S. Raju		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Modern F/P to 9th Cross road from 11th Main to West Park Road from North Ch:220 to 330.00mtrs in ward No.65	2074646.02	2011-12
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & Drain
Tender	WorkDetails	Job No Work Code
Tender		065-11-000030
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		h.r.giridhar
Date of Inspection	Remarks	
19/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0230	9th Crs	West Park road
SegmentNo	TotalLength	
65/S-W0230/S102405	642.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.S. Raju		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Modern F/P to 9th Cross road from 11th Main to West Park Road from North Ch:330 to 440.00mtrs in ward No.65	2074646.02	2011-12
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & Drain
Tender	WorkDetails	Job No Work Code
Tender		065-11-000031
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		giridhar
Date of Inspection	Remarks	
19/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0230	9th Crs	West Park road
SegmentNo	TotalLength	
65/S-W0230/S102542	642.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sidde Gowda		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Modern F/P to 9th Cross road from 11th Main to West Park Road from South Ch:0.00 to 110.00mtrs in ward No.65	2074646.02	2011-12
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & Drain
Tender	WorkDetails	Job No Work Code
Tender		065-11-000033
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		giridhar
Date of Inspection	Remarks	
19/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0155	5th Main Rd	5th Cross
SegmentNo	TotalLength	
65/S-W0155/S102930	215.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Vijaya Kumar		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain & Footpath from 5th Cross to 13th Cross of Western side from ch:0.00 to 140.00mtrs in ward No.65	2098640.85	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & drain
Tender	WorkDetails	Job No Work Code
Tender		065-12-000002
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
22/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0230	9th Crs	West Park road
SegmentNo	TotalLength	
65/S-W0230/S103238	642.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sidde Gowda		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Modern F/P to 9th Cross road from 11th Main to West Park Road from South Ch:330.00 to 440.00mtrs in ward No.65	2074646.02	2011-12
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & drian
Tender	WorkDetails	Job No Work Code
Tender		065-11-000036
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		giridhar
Date of Inspection	Remarks	
19/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0230	9th Crs	West Park road
SegmentNo	TotalLength	
65/S-W0230/S103506	642.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sidde Gowda		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Modern F/P to 9th Cross road from 11th Main to West Park Road from South Ch:220.00 to 330.00mtrs in ward No.65	2074646.02	2011-12
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & drain
Tender	WorkDetails	Job No Work Code
Tender		065-11-0000
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
22/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0230	9th Crs	West Park road
SegmentNo	TotalLength	
65/S-W0230/S103653	642.86	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sidde Gowda		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Modern F/P to 9th Cross road from 11th Main to West Park Road from South Ch:110.00 to 220.00mtrs in ward No.65	2074646.02	2011-12
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & drain
Tender	WorkDetails	Job No Work Code
Tender		065-11-000034
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
22/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0230	9th Crs	West Park road
SegmentNo	TotalLength	
65/S-W0230/S103853	642.86	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.S. Raju		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Modern F/P to 9th Cross road from 11th Main to West Park Road from North Ch:440.00 to 550.00mtrs in ward No.65	1479146.07	2011-12
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & Drain
Tender	WorkDetails	Job No Work Code
Tender		065-11-000032
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
22/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0155	5th Main Rd	5th Cross
SegmentNo	TotalLength	
65/S-W0155/S105017	215.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Vijaya Kumar		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain & Footpath from 5th Cross to 13th Cross of Western side from ch:420.00 to 560.00mtrs in ward No.65	20996475.77	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & Drain
Tender	WorkDetails	Job No Work Code
Tender		065-12-000005
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
22/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0155	5th Main Rd	5th Cross
SegmentNo	TotalLength	
65/S-W0155/S105359	215.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Vijaya Kumar		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain & Footpath from 5th Cross to 13th Cross of Western side from ch:280.00 to 420.00mtrs in ward No.65	2099675.99	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & Drain
Tender	WorkDetails	Job No Work Code
Tender		065-12-000004
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
22/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0155	5th Main Rd	5th Cross
SegmentNo	TotalLength	
65/S-W0155/S105539	215.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Vijaya Kumar		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain & Footpath from 5th Cross to 13th Cross of Western side from ch:140.00 to 280.00mtrs in ward No.65	2096727	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & Drain
Tender	WorkDetails	Job No Work Code
Tender		065-12-000003
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
22/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0155	5th Main Rd	5th Cross
SegmentNo	TotalLength	
65/S-W0155/S105731	215.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Vijaya Kumar		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain & Footpath from 5th Cross to 13th Cross of Western side from ch:5600.00 to 700.00mtrs in ward No.65	2099675.97	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Others	F/P & Drain
Tender	WorkDetails	Job No Work Code
Tender		065-12-000003
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
22/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0230	NA	Narayana Hospital
SegmentNo	TotalLength	
65/S-W0230/S093640	624.80	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B.S. DHANANJAYA		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing covering slab and drain in Maruthi Extension and surrounding area in ward No.65	1000000	2015-16
Year	Type of Work	Other Work Type
2015 - 2016	Others	Drain
Tender	WorkDetails	Job No Work Code
Tender		065-16-000008
Work OrderNo	Work Order Date	Period of Extention
EE/MLM/AE/WO/37/2015-16	30/01/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma
Date of Inspection	Remarks	
11/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0193	Vinayaka Lyt 2nd Crs	12TH CROSS
SegmentNo	TotalLength	
65/S-W0193/S094003	786.50	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER (WEST)		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
MAINTENANCE OF FOOTPATH LIKE DESILTING PAINTING T KERB AND REPLACING OF BROKEN SLABS AT 9TH MAIN VYALIKAVAl FROM 12TH CROSS TO 14TH CROSS SURROUNDING	500000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Others	FOOTPATH
Tender	WorkDetails	Job No Work Code
Tender		065-15-000029
Work OrderNo	Work Order Date	Period of Extention
EE/MLM/AE/WO/104/2014-15	20/08/2016	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/11/2016	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0131	13th Crs	13th Cross
SegmentNo	TotalLength	
65/S-W0131/S081443	115.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anil Kumar		0.00
PhoneNo	EmailId	
9448974686		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain & Footpath @ 13th Cross & neighbour cross roads in ward No.65	500000	
Year	Type of Work	Other Work Type
2010 - 2011	Others	Drain & Footpath
Tender	WorkDetails	Job No Work Code
Tender		065-11-000007
Work OrderNo	Work Order Date	Period of Extention
042/10-11		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		M.J. Yogesh
Date of Inspection	Remarks	
18/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0197	NA	Malleshwaram
SegmentNo	TotalLength	
65/S-W0197/S081826	214.99	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Hanumantha Naik		0.00
PhoneNo	EmailId	
9916879265		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Culverts at Malleshwaram in ward No.65	500000	
Year	Type of Work	Other Work Type
2010 - 2011	Others	Culverts
Tender	WorkDetails	Job No Work Code
Tender		065-11-000012
Work OrderNo	Work Order Date	Period of Extention
399/10-11		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		M.J.Yogesh
Date of Inspection	Remarks	
18/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0225	Swimming Pool Avenue Rd	Malleshwaram
SegmentNo	TotalLength	
65/S-W0225/S082153	283.91	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G. Vasu		0.00
PhoneNo	EmailId	
9686422977		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providng Asphaltng to roads Cut portion by BWSSB department in Ward No.65	2000000	
Year	Type of Work	Other Work Type
2010 - 2011	Asphaltng	
Tender	WorkDetails	Job No Work Code
Tender		065-11-000017
Work OrderNo	Work Order Date	Period of Extention
043/10-11		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		M.J.Yogesh
Date of Inspection	Remarks	
18/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 65	WardName Kadu Malleshwara Ward
StreetID W0154	StreetName NA	Significant LandMark Malleshwaram
SegmentNo 65/S-W0154/S082431	TotalLength 78.96	

ContractorDetails		
NameofContractor Dhananjaya	ContractorRegNo	Expenditure 0.00
PhoneNo 9448151443	EmailId	

Work Details		
NameOfWork Providing Concrete pavement to damaged conservancy roads in ward no.65	Sanctioned Amount 2000000	Sanctioned Year
Year 2010 - 2011	Type of Work Others	Other Work Type Concrete Pavment
Tender Tender	WorkDetails	Job No Work Code 065-11-000003
Work OrderNo 025/10-11	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name M.J.Yogesh
Date of Inspection 18/12/2014	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0243	NA	Dhobi ghatt
SegmentNo	TotalLength	
65/S-W0243/S082612	102.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sheshadri Reddy		0.00
PhoneNo	EmailId	
9739368795		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to dhobi ghatt area and providing roofing to generator room at Kadumalleshwara in Ward No.65	2000000	
Year	Type of Work	Other Work Type
2009 - 2010	Others	Drain
Tender	WorkDetails	Job No Work Code
Tender		065-11-000004
Work OrderNo	Work Order Date	Period of Extention
25/09-10		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		m.j. yogesh
Date of Inspection	Remarks	
18/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0054	5th Crs Maruthi Extension	Railway Bridge
SegmentNo	TotalLength	
65/S-W0054/S082902	118.24	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
L. Dilip		0.00
PhoneNo	EmailId	
9686844679		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain & Footpath at 5th Cross to Railway Bridge in M.K.K Road in Ward No.65. Kadu Malleshwara.	500000	
Year	Type of Work	Other Work Type
2010 - 2011	Others	Drain & footpah
Tender	WorkDetails	Job No Work Code
		065-11-000011
Work OrderNo	Work Order Date	Period of Extention
44/10-11		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		m.j. yogesh
Date of Inspection	Remarks	
18/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0217	NA	Kodandarampura
SegmentNo	TotalLength	
65/S-W0217/S083304	46.48	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Naveen Kumar		0.00
PhoneNo	EmailId	
9036994126		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain & footpath at Kodandarampura Extension in Ward No.65. Kadu Malleshwara.	500000	
Year	Type of Work	Other Work Type
2010 - 2011	Others	Drain & Footpath
Tender	WorkDetails	Job No Work Code
Tender		065-11-000008
Work OrderNo	Work Order Date	Period of Extention
043/10		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		m.j. yogesh
Date of Inspection	Remarks	
18/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0025	1st Main Rd Gdp Extn	TTD Temple
SegmentNo	TotalLength	
65/S-W0025/S083608	237.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Damodara raju		0.00
PhoneNo	EmailId	
8165789524		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Prvd MS grill to ffootpath infront of TTD temple & Impts to Drain & F/p to Surrounding area of temple @ Vyalikaval	1500000	
Year	Type of Work	Other Work Type
2010 - 2011	Others	Drain 7 Footpath
Tender	WorkDetails	Job No Work Code
Tender		065-11-000015
Work OrderNo	Work Order Date	Period of Extention
083/10-11		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		m.j. yogesh
Date of Inspection	Remarks	
18/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0026	5th Crs	C block
SegmentNo	TotalLength	
65/S-W0026/S083942	161.11	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K. Anand		0.00
PhoneNo	EmailId	
9845015736		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to Drain & Footpath @ 5th cross of gayathrinagara C block	2000000	
Year	Type of Work	Other Work Type
2010 - 2011	Others	Drain & Footpath
Tender	WorkDetails	Job No Work Code
Tender		065-11-000041
Work OrderNo	Work Order Date	Period of Extention
42/10-11		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		m.j. yogesh
Date of Inspection	Remarks	
18/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0213	4th Temple St	4th Temple Raod
SegmentNo	TotalLength	
65/S-W0213/S084218	164.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S. builders		0.00
PhoneNo	Emailld	
8105605796		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to Drain & Footpath @ 4th Temple Raod from 15th cross towards South Side @ kodandarampura	2000000	
Year	Type of Work	Other Work Type
2010 - 2011	Others	Drain & Footpath
Tender	WorkDetails	Job No Work Code
Tender		065-11-000046
Work OrderNo	Work Order Date	Period of Extention
069/10-11		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		m.j. yogesh
Date of Inspection	Remarks	
18/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0245	9th Main Rd Vyalikaval	9th Main
SegmentNo	TotalLength	
65/S-W0245/S084915	285.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Jagadish		0.00
PhoneNo	EmailId	
9900022110		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to Drain & Footpath to 9th main from 12th cross to 15th cross western side of Kodandarampura	2000000	
Year	Type of Work	Other Work Type
2010 - 2011	Others	Drain & Footpath
Tender	WorkDetails	Job No Work Code
Tender		065-11-000044
Work OrderNo	Work Order Date	Period of Extention
0325		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		m.j. yogesh
Date of Inspection	Remarks	
18/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0245	9th Main Rd Vyalikaval	9th main
SegmentNo	TotalLength	
65/S-W0245/S085734	285.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Krishna Murthy		0.00
PhoneNo	EmailId	
9845067895		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to Drain & Footpath from 9th main from 12th cross to 15th cross of Kodandarampura	2000000	
Year	Type of Work	Other Work Type
2011 - 2012	Others	Drain & Footpath
Tender	WorkDetails	Job No Work Code
Tender		065-11-000043
Work OrderNo	Work Order Date	Period of Extention
269/11-12		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		m.j. yogesh
Date of Inspection	Remarks	
18/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0255	6th Main Rd Vyalikaval	Ayyappa Swamy temple
SegmentNo	TotalLength	
65/S-W0255/S090023	470.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Ashok babu		0.00
PhoneNo	EmailId	
9480689758		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to Drain & Footpath @ 13th cross from 6th main to Ayyappa Swamy temple of southern side of Vyalikaval	2000000	
Year	Type of Work	Other Work Type
2010 - 2011	Others	Drain & Footpath
Tender	WorkDetails	Job No Work Code
Tender		065-11-000038
Work OrderNo	Work Order Date	Period of Extention
185/10-11		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		m.j. yogesh
Date of Inspection	Remarks	
18/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0073	NA	Maruthi Extnsion
SegmentNo	TotalLength	
65/S-W0073/S090436	220.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Samasundar		0.00
PhoneNo	EmailId	
9448975698		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to drain & Footpath @ 1st main of Mauthi Extn gayathrinagara	2000000	
Year	Type of Work	Other Work Type
2010 - 2011	Others	Drain & Footpath
Tender	WorkDetails	Job No Work Code
Tender		065-11-000039
Work OrderNo	Work Order Date	Period of Extention
163/11-12		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		m.j. yogesh
Date of Inspection	Remarks	
18/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0308	13th A Crs Vyalikaval	Ayyappa swamy temple
SegmentNo	TotalLength	
65/S-W0308/S090714	241.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Prasanna Kumar		0.00
PhoneNo	EmailId	
9036978254		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to Drain & footpath @ 13th A cross from 6th main to Ayyappa swamy temple of Northern side of Vyalikavak	2000000	
Year	Type of Work	Other Work Type
2011 - 2012	Others	Drain & Footapath
Tender	WorkDetails	Job No Work Code
Tender		065-11-000045
Work OrderNo	Work Order Date	Period of Extention
0161/11-12		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		m.j. yogesh
Date of Inspection	Remarks	
18/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 65	WardName Kadu Malleshwara Ward
StreetID W0249	StreetName 7th Main Rd	Significant LandMark 7th Main
SegmentNo 65/S-W0249/S091014	TotalLength 62.95	

ContractorDetails		
NameofContractor Dhananjaya	ContractorRegNo	Expenditure 0.00
PhoneNo 9448151443	EmailId	

Work Details		
NameOfWork Impts to Drain & Footpath @ 7th, 8th & 9th main B/w 13th A 7 14th Cross of Vyalikaval	Sanctioned Amount 2000000	Sanctioned Year
Year 2010 - 2011	Type of Work Others	Other Work Type Drain & Footpath
Tender Tender	WorkDetails	Job No Work Code 065-11-000042
Work OrderNo 157/11-12	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name m.j. yogesh
Date of Inspection 18/12/2014	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0166	11th Crs	Sampige road
SegmentNo	TotalLength	
65/S-W0166/S092104	855.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Vasanth Kumar		0.00
PhoneNo	EmailId	
9686200428		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to Footapath & Drain @ 11th Main margosa road to Sampige road of MLM	3000000	
Year	Type of Work	Other Work Type
2009 - 2010	Others	Footapath & Drain
Tender	WorkDetails	Job No Work Code
Tender		031-10-MGEDIm-017
Work OrderNo	Work Order Date	Period of Extention
24/09-10		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		M. J. Yogesh
Date of Inspection	Remarks	
18/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0222	10th Crs	Margosa road
SegmentNo	TotalLength	
65/S-W0222/S092416	214.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A. Raghavendra		0.00
PhoneNo	EmailId	
9448756892		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to Footapath & Drain @ 10th cross road to Sampige road of MLM	3000000	
Year	Type of Work	Other Work Type
2009 - 2010	Others	Footapath & Drain
Tender	WorkDetails	Job No Work Code
Tender		031-10-MGER-IM-016
Work OrderNo	Work Order Date	Period of Extention
149/09-10		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		M.J.Yogesh
Date of Inspection	Remarks	
18/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Footpath Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0044	6th Crs Maruthi Extension	Maruthi Extn
SegmentNo	TotalLength	
65/S-W0044/S092935	113.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Dhananjaya		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to L Drain & footpath @ 3rd Subramanyanagara & Impts to drain @ 6th cross Maruthi Extn	2000000	
Year	Type of Work	Other Work Type
2013 - 2014	Others	Footapath & Drain
Tender	WorkDetails	Job No Work Code
Tender		065-14-000020
Work OrderNo	Work Order Date	Period of Extention
141/13-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
7		k.s.sushma
Date of Inspection	Remarks	
20/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment Start	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0005	5th Temple Rd	Subbamma Choutry
SegmentNo	TotalLength	
65/S-W0005/S093219	158.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.C. Sreedhar		0.00
PhoneNo	EmailId	
9845015968		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to Drain & Footapath to 5th temple road from 12th A cross to 13th cross (Subbamma Choutry) & other roads	2000000	
Year	Type of Work	Other Work Type
2012 - 2013	Others	Drain & Footapath
Tender	WorkDetails	Job No Work Code
Tender		065-12-000046
Work OrderNo	Work Order Date	Period of Extention
219/12-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
20/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0128	13th Crs	13th Cross
SegmentNo	TotalLength	
65/S-W0128/S093633	1107.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9843161122		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to Drain & Footapath @ 13th cross from West park road to 6th main MLM	2000000	
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
		065-13-000021
Work OrderNo	Work Order Date	Period of Extention
350/12-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
22		k.s.sushma
Date of Inspection	Remarks	
19/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0005	5th Temple Rd	IPP building
SegmentNo	TotalLength	
65/S-W0005/S093848	158.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9843161122		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to Drain & Footapath @ 16th cross from IPP to 5th temle road MLM	1500000	
Year	Type of Work	Other Work Type
2013 - 2014	Others	Drain & Footapath
Tender	WorkDetails	Job No Work Code
Tender		065-13-000020
Work OrderNo	Work Order Date	Period of Extention
373/12-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
7		k.s.sushma
Date of Inspection	Remarks	
20/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0042	7th Crs Maruthi Extension	Railway Parallel road
SegmentNo	TotalLength	
65/S-W0042/S094215	123.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDI		0.00
PhoneNo	EmailId	
9843161122		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to Drain & Footpath @Railway Parallel road east side attached to Railway compound Veer sourkar road Gayathrinagara	2000000	
Year	Type of Work	Other Work Type
2012 - 2013	Others	Drain & Footpath
Tender	WorkDetails	Job No Work Code
Tender		065-13-000023
Work OrderNo	Work Order Date	Period of Extention
369/12-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
6		k.s.sushma
Date of Inspection	Remarks	
20/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0128	13th Crs	11th main
SegmentNo	TotalLength	
65/S-W0128/S094430	1107.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9843161122		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to Drain & footpath @ 13th cross from 6th main to 11th main MLM	2000000	
Year	Type of Work	Other Work Type
2012 - 2013	Others	Drain & footpath
Tender	WorkDetails	Job No Work Code
Tender		065-13-000026
Work OrderNo	Work Order Date	Period of Extention
370/12-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
46		k.s.sushma
Date of Inspection	Remarks	
19/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0128	13th Crs	Margosa road
SegmentNo	TotalLength	
65/S-W0128/S094806	1107.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Puttaswamy gowda		0.00
PhoneNo	EmailId	
9448697589		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to Drain & footpath to 13th cross from Margosa road to 11th main	4000000	
Year	Type of Work	Other Work Type
2009 - 2010	Others	Drain & footpath
Tender	WorkDetails	Job No Work Code
Tender		007-09-MGER-AS-005
Work OrderNo	Work Order Date	Period of Extention
841/09-10		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
22/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0123	8th Main Rd	8th main
SegmentNo	TotalLength	
65/S-W0123/S091438	816.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R. Ramchandra		0.00
PhoneNo	EmailId	
9900022110		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Maintenance of Footpath @ 8th main MLM	500000	
Year	Type of Work	Other Work Type
2013 - 2014	Others	Footpath
Tender	WorkDetails	Job No Work Code
Tender		065-14-000025
Work OrderNo	Work Order Date	Period of Extention
127/13-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
19/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0004	12th Crs	12th Cross
SegmentNo	TotalLength	
65/S-W0004/S091646	497.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Jayaprakash		0.00
PhoneNo	EmailId	
9448704869		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to Footpath @ 12th cross Kodandarampura	2000000	
Year	Type of Work	Other Work Type
2013 - 2014	Others	Footpath
Tender	WorkDetails	Job No Work Code
Tender		065-14-000016
Work OrderNo	Work Order Date	Period of Extention
174/13-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
10		k.s.sushma
Date of Inspection	Remarks	
19/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0217	NA	Kodandarampura
SegmentNo	TotalLength	
65/S-W0217/S091934	46.48	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Dhananjaya		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing CC to bad roads @ kodandarampura	2000000	
Year	Type of Work	Other Work Type
2012 - 2013	Others	Cement concrete
Tender	WorkDetails	Job No Work Code
Tender		065-12-000050
Work OrderNo	Work Order Date	Period of Extention
512/12-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
20/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0193	13th East Park Rd	Post office
SegmentNo	TotalLength	
65/S-W0193/S092449	235.93	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Arvind		0.00
PhoneNo	EmailId	
9845762852		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to drain Footpath & Cc to damaged road @ 9th cross old market road	2000000	
Year	Type of Work	Other Work Type
2013 - 2014	Others	Drain & Footpath, CC
Tender	WorkDetails	Job No Work Code
Tender		065-14-000018
Work OrderNo	Work Order Date	Period of Extention
11/13-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
19/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0314	13th Crs Vyalikaval	Kodanadrampura
SegmentNo	TotalLength	
65/S-W0314/S092814	241.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9843161122		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to drain & Footpath @ 13th cross Kodanrampura	2000000	
Year	Type of Work	Other Work Type
2013 - 2014	Others	drain & Footpath
Tender	WorkDetails	Job No Work Code
Tender		065-13-000037
Work OrderNo	Work Order Date	Period of Extention
500/14-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
19/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0154	NA	Malleshwaram
SegmentNo	TotalLength	
65/S-W0154/S093201	78.96	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Vasanth Kumar		0.00
PhoneNo	EmailId	
9448769583		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing CC to road cut portion & pot hole & cement concrete to bad roads	1500000	
Year	Type of Work	Other Work Type
2012 - 2013	Others	Cement concrete
Tender	WorkDetails	Job No Work Code
Tender		065-13-000012
Work OrderNo	Work Order Date	Period of Extention
17/13-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		k.s.sushma
Date of Inspection	Remarks	
20/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 65	WardName Kadu Malleshwara Ward
StreetID W0242, W0268, W0230, W0282, W0141	StreetName 8th Crs, 7th Crs, 9th Crs, 6th Crs, 7th Main Rd	Significant LandMark MLM
SegmentNo 65/C-W0242/S093617	TotalLength 284.44	

ContractorDetails		
NameofContractor T. Jayaprakash	ContractorRegNo	Expenditure 0.00
PhoneNo 9448704869	EmailId	

Work Details		
NameOfWork Impts to drain & Footpath @ 7th main from 6th to 9th cross & Surrounding area	Sanctioned Amount 2000000	Sanctioned Year
Year 2013 - 2014	Type of Work Others	Other Work Type drain & Footpath
Tender Tender	WorkDetails	Job No Work Code 065-14-000017
Work OrderNo 80/13-14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 27	Other Information	Name k.s.sushma
Date of Inspection 19/12/2014	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0222, M0089, W0116, W0154, W0166, W0230, W0128	10th Crs, Margosa Rd, 14th A Crs Malleshwara, NA, 11th Crs, 9th Crs, 13th Crs	Margosa road
SegmentNo	TotalLength	
65/C-W0222/S100113	581.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P. Arvind		0.00
PhoneNo	EmailId	
9845677598		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Maintenance of footpath & improvements of drain 3rd main Margosa road MLM	1000000	
Year	Type of Work	Other Work Type
2013 - 2014	Others	drain & Footpath
Tender	WorkDetails	Job No Work Code
Tender		065-14-000024
Work OrderNo	Work Order Date	Period of Extention
163/13-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
19/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0243	NA	Vyalikval
SegmentNo	TotalLength	
65/S-W0243/S100455	102.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
L. Mahesh		0.00
PhoneNo	EmailId	
9686200428		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to bad road @ Vyalikaval & Surouning area	2000000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		065-13-000008
Work OrderNo	Work Order Date	Period of Extention
462/12-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		k.s.sushma
Date of Inspection	Remarks	
23/12/2014		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0155	NA	ganesha Temple
SegmentNo	TotalLength	
65/S-W0155/S023909	709.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B.S. Dhananjaya		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to drain and footpath at 5th main from 5th cross to 6th cross and maintenance of footpath at 5th main and surrounding area in ward no.65	1000000	2011-12
Year	Type of Work	Other Work Type
2012 - 2013	Others	Drain and footpath
Tender	WorkDetails	Job No Work Code
Tender		065-10-000012
Work OrderNo	Work Order Date	Period of Extention
73/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma
Date of Inspection	Remarks	
19/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0006	NA	Segregation point
SegmentNo	TotalLength	
65/S-W0006/S024603	600.76	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448151443		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to drain and footpath at 2nd main road, vyalikaval west isde 15th cross and surrounding area in ward no.65	1500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Others	Drain and footpath
Tender	WorkDetails	Job No Work Code
Tender		065-13-000019
Work OrderNo	Work Order Date	Period of Extention
564/14-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma
Date of Inspection	Remarks	
19/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0116	NA	MLA College
SegmentNo	TotalLength	
65/S-W0116/S120734	215.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.S. Sidde Gowda		0.00
PhoneNo	EmailId	
9686200428		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting patch work to road cut portion by BWSSB at 14th A cross, 14th B cross, 3rd main and surrounding area in w No.65	1900000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		065-12-000077
Work OrderNo	Work Order Date	Period of Extention
118/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma
Date of Inspection	Remarks	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0087	NA	Cluny convent school
SegmentNo	TotalLength	
65/S-W0087/S121131	1099.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager, KRIDL		0.00
PhoneNo	EmailId	
9686200428		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provd Asphaltting to 11th main Railway parallel road from 15th cross to 9th cross in W No.65	2000000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender		065-13-000039
Work OrderNo	Work Order Date	Period of Extention
501/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma
Date of Inspection	Remarks	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0014	NA	2nd Main Vyalikaval
SegmentNo	TotalLength	
65/S-W0014/S122607	176.48	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager, KRIDL		0.00
PhoneNo	EmailId	
9686200428		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provd asphaltting to 15th cross, from Sampige road to 2nd Main Vyalikaval in w No.65	2000000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender		065-13-000031
Work OrderNo	Work Order Date	Period of Extention
417/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma
Date of Inspection	Remarks	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0314	NA	Dhobi Ghatt
SegmentNo	TotalLength	
65/S-W0314/S125632	241.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager, KRIDL		0.00
PhoneNo	EmailId	
9686200428		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 13th Cross Vyalikaval ward No.65	2000000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender		65-13-000033
Work OrderNo	Work Order Date	Period of Extention
415/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma
Date of Inspection	Remarks	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
I0020	NA	MES College
SegmentNo	TotalLength	
65/S-I0020/S032941	1759.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manger, KRIDL		0.00
PhoneNo	EmailId	
9686200428		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provd Asphaltting to 15th cross from 6th to 11th main & Surrounding area in ward No.65	4990000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender		065-13-000016
Work OrderNo	Work Order Date	Period of Extention
368/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma
Date of Inspection	Remarks	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0268	NA	Malleshwaram Club
SegmentNo	TotalLength	
65/S-W0268/S033238	442.47	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Nagesh		0.00
PhoneNo	EmailId	
9686200428		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Bad roads at Kadu Malleshwaram in ward No.65	2000000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender		065-13-000007
Work OrderNo	Work Order Date	Period of Extention
463/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma
Date of Inspection	Remarks	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0087	NA	Railway Parallel Road
SegmentNo	TotalLength	
65/S-W0087/S033500	1099.38	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager, KRIDL		0.00
PhoneNo	EmailId	
9686200428		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 11th main Railwayparallel road from 9th to 5th cross in Malleshwaram in ward No.65	2000000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender		065-13-000040
Work OrderNo	Work Order Date	Period of Extention
502/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma
Date of Inspection	Remarks	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0219	Chowdeshwari Temple Rd	Dhobi Ghatt
SegmentNo	TotalLength	
65/S-W0219/S034535	118.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager, KRIDL		0.00
PhoneNo	EmailId	
9686200428		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 16th cross 2nd main Vyalikaval to 5th temple road in ward No.65	2000000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender		065-13-000032
Work OrderNo	Work Order Date	Period of Extention
419/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma
Date of Inspection	Remarks	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
I0255	Mahadevapura Village Rd	Vyalikaval
SegmentNo	TotalLength	
65/S-I0255/S035053	470.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Nagesh		0.00
PhoneNo	EmailId	
9686200428		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to roads BWSSB road cut portion at Vyalikaval in ward No.65	2000000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender		065-13-000011
Work OrderNo	Work Order Date	Period of Extention
461/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma
Date of Inspection	Remarks	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0030	NA	Raj kumar Statue
SegmentNo	TotalLength	
65/S-W0030/S035624	161.11	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager, KRIDL		0.00
PhoneNo	EmailId	
9686200042		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to railway parallel road from 3rd main to Rajkumar Statue Veersourkar road Gayathrinagara in ward No.65	2000000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender		065-13-000034
Work OrderNo	Work Order Date	Period of Extention
418/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma
Date of Inspection	Remarks	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0028	NA	Gayathrinagara
SegmentNo	TotalLength	
65/S-W0028/S035903	162.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Manjunath		0.00
PhoneNo	EmailId	
9686200428		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to roads BWSSB road cut portion at Gayathrinagara in ward No.65	2000000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender		065-13-000009
Work OrderNo	Work Order Date	Period of Extention
521/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma
Date of Inspection	Remarks	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	65	Kadu Malleshwara Ward
StreetID	StreetName	Significant LandMark
W0097	16th Crs	MES Kisore Kendra
SegmentNo	TotalLength	
65/S-W0097/S114029	432.97	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manger, KRIDL		0.00
PhoneNo	EmailId	
9686200428		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Filling of potholes wornout roads and road cut portion in ward No.65	500000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Pothole filling	
Tender	WorkDetails	Job No Work Code
Tender		065-13-000048
Work OrderNo	Work Order Date	Period of Extention
30/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sushma
Date of Inspection	Remarks	
22/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	